Scheduling Constrained-Deadline Parallel Tasks on Two-type Heterogeneous Multiprocessors

Björn Andersson Carnegie Mellon University Gurulingesh Raravi Xerox Research Centre India

Abstract-Consider the problem of scheduling a taskset on a multiprocessor to meet all deadlines. Assume (i) constraineddeadline sporadic tasks, i.e., a task generates a sequence of jobs and the deadline of a job is no greater than the minimum inter-arrival time of the task that generates the job, (ii) stageparallelism, i.e., a task comprises one or more stages with a stage comprising one or many segments so that segments in the same stage are allowed to execute in parallel and a segment is allowed to execute only if all segments of the previous stage have finished, (iii) two-type heterogeneous multiprocessor platform, i.e., there are processors of two types, type-1 and type-2, and for each task, there is a specification of its execution speed on a type-1 processor and on a type-2 processor, and (iv) intratype migration, i.e., a job can migrate between processors of the same type but for a task, all jobs of this task must execute on the same processor type. We present an algorithm for this problem; it assigns each task to a processor type and then schedules tasks on processors of each type with global-Earliest-Deadline-First. Its has pseudo-polynomial time complexity and in our evaluation with randomly-generated tasksets with systems up to 256 tasks and 256 processors, the algorithm never took more than 2.5 seconds to finish. We show that the speedup factor of the algorithm is most 5. This is the first algorithm for scheduling parallel real-time tasks on a heterogeneous multiprocessor with provably good performance.

I. Introduction

Software systems are expected to do more with less, i.e., providing more functionality and greater performance with lower size, weight, and power consumption. The research community has taken a great interest in developing methods that provide foundations for doing so while ensuring, before run-time, that the software system can respond, at run-time, to certain events within pre-specified time constraints (deadlines). Such foundations include algorithms for scheduling tasks on heterogeneous multiprocessors. These algorithms are useful because heterogeneous multiprocessors typically provide more processing power per watt. Other foundations include algorithms for scheduling tasks that can execute in parallel on multiprocessors. These algorithms are relevant for computations responding to events that have so tight deadlines that even if a computation is executed on a system with no other computations present, the only way for the computation to meet its deadline is to perform execution in parallel.

A computer platform is a *homogeneous multiprocessor* (sometimes called *identical multiprocessor*) if the execution speed of all tasks is the same on all processors. Conversely, a computer platform is a *heterogeneous multiprocessor* (sometimes called *unrelated multiprocessor*) if the execution speed of a task depends on both the processor and the task. A

heterogeneous multiprocessor is *two-type* if it has two types of processors (a.k.a. *two-type platform*). Analogously, a heterogeneous multiprocessor is *t-type* if it has t types of processors (a.k.a. *t-type platform*). For two-type platforms, the problem of assigning tasks to processors is NP-hard in the strong sense and the problem of assigning tasks to processor types is NP-hard [1]. For t-type platforms, both the problems are NP-Hard in the strong sense [2], [3]. Consequently, the research community has developed approximation algorithms (i.e., algorithms with finite speedup factors) for assigning tasks to processors and to processor types [1]–[14] on such platforms.

Related work. The algorithms for assigning implicitdeadline sporadic tasks (i.e., a task generates a sequence of jobs and a job has a deadline that is equal to the minimum inter-arrival time of the task that generates the job) to processors and to processor types for two-type platforms [1], [4]-[7] have lower time complexity than the algorithms for t-type platforms [2], [3], [8]-[13] while maintaining their performance bound. In addition, an algorithm for scheduling arbitrary-deadline sporadic tasks (i.e., a task generates a sequence of jobs and a job has a deadline that may be less than or greater than or equal to the minimum inter-arrival time of the task that generates the job) on t-type platforms is known as well [14]. However, none of them [1]-[14] support parallel tasks. The research community has also presented algorithms with proven speedup factor for scheduling parallel tasks on homogeneous multiprocessors [15]-[21]. Further, there are other algorithms [22]-[31] with no proven speedup factor for scheduling parallel tasks on homogeneous multiprocessors some of them [22]–[27] are for constrained-deadline sporadic tasks (i.e., a task generates a sequence of jobs and a job has a deadline that may be less than or equal to the minimum inter-arrival time of the task that generates the job) and the others [28]-[31] are for implicit-deadline sporadic tasks. Unfortunately, none of these works [15]-[31] support heterogeneous multiprocessors (and moreover most of these algorithms [22]-[31] have no proven speedup factors). A work by Holenderski et. al. [32] comes closest to ours as it also deals with the problem of scheduling parallel tasks on heterogeneous multiprocessors. However, the approach presented in [32] has no proven speedup factor.

This research. In this paper, we present an algorithm for scheduling tasks on a two-type heterogeneous multiprocessor with a finite speedup factor. Our approach assigns each task to a processor type and then uses global-Earliest-Deadline-First (gEDF) on the processors of each type to schedule the




Fig. 1: The parallel task model studied in this paper.

respective tasks. We show that our algorithm has pseudo-polynomial time complexity and a speedup factor at most 5. We study the *constrained-deadline sporadic task model* and consider *parallelism with stages* (i.e., a task is described with one or more stages with each stage comprising one or many segments such that segments in the same stage are allowed to execute in parallel but a segment is only allowed to execute if all segments of the previous stage have finished execution). This work makes the following contribution: it presents the *first algorithm for scheduling parallel real-time tasks on a heterogeneous multiprocessor with a proven speedup factor*.

Organization of the paper. The rest of this paper is organized as follows. Section II states the system model. Section III lists previous results for parallel scheduling on homogeneous multiprocessors and also proves new lemmas that we use later in the paper. Section IV presents our new algorithm for two-type heterogeneous multiprocessors and proves its speedup factor and time complexity. Section V presents evaluation. Section VI concludes.

II. SYSTEM MODEL

We consider the problem of scheduling a set τ of constrained-deadline sporadic tasks on a two-type heterogeneous multiprocessor platform Π comprising m_1 processors of type-1 and m_2 processors of type-2. A task $\tau_i \in \tau$ is characterized by a minimum inter-arrival time T_i and a deadline D_i such that $D_i \leq T_i$. Each task τ_i generates a sequence of jobs, with the first job arriving at any time and subsequent jobs arriving at least T_i time units apart.

The execution of a task τ_i is described by ns_i , $\mathrm{nseg}_{i,j}$, and $C_{i,j}$ with the interpretation that a job of τ_i has ns_i stages with stage j comprising $\mathrm{nseg}_{i,j}$ segments with each segment of stage j having execution requirement at most $C_{i,j}$ — see Fig. 1. A segment finishes when it performs a number of units of execution equal to its execution requirement. A segment executing contiguously for L time units on a processor of speed s performs $L \times s$ units of execution. A segment of a job is allowed to execute only if all segments of its previous stage have finished. A job finishes when all segments of its last stage have finished. If a job of τ_i finishes at most D_i time units after its arrival, then it meets its deadline.

On a two-type platform, the execution speed of a job depends on the type of processor on which it executes. Let r_i^1

and r_i^2 denote the execution speeds of a job of task τ_i when it executes on a processor of type-1 and type-2 respectively.

We now define terms that we use in the rest of the paper.

Definition 1 (**Legal jobset**). If, for each task in the taskset τ , the task is assigned the number of jobs it generates and each job is assigned an arrival time such that the minimum interarrival time constraint is satisfied and each segment of a job is assigned an execution requirement such that the upper bound on execution requirement of a segment is respected, then we say that the resulting jobset is a legal jobset with respect to τ .

Definition 2 (Intra-migrative schedule). A schedule is intramigrative if both of the following conditions are true: (i) jobs are allowed to migrate between processors of the same type and (ii) for each task, it holds that, if a job executes on a processor of one type then all other jobs of this task execute on processors of the same type.

Definition 3 (Intra-migrative feasible taskset). A taskset τ is intra-migrative feasible on a two-type platform Π if for each jobset that is legal with respect to τ there exists an intra-migrative schedule in which all deadlines are met.

Definition 4 (S-Schedulable task set). A taskset τ is S-schedulable on a two-type platform Π if for each jobset that is legal with respect to τ , for each schedule that S can generate from the jobset, it holds that the schedule is intra-migrative and all deadlines are met.

Definition 5 (Speed of the computing platform). If Π is a two-type platform then let $\Pi \times x$ denote a two-type platform where the speed of each processor is multiplied by x.

Definition 6 (Speedup factor). A scheduler S has a speedup factor SF_S if, for each taskset τ , for each two-type platform Π , it holds that: if τ is intra-migrative feasible on Π then τ is S-schedulable on $\Pi \times SF_S$.

In order to simplify our discussion in the rest of the paper, we rewrite our model to an equivalent formulation as follows. Instead of using $C_{i,j}, \, r_i^1$, and r_i^2 , we use parameters $C_{i,j}^1, \, C_{i,j}^2$, and s selected as follows: $C_{i,j}^1/s = C_{i,j}/r_i^1$ and $C_{i,j}^2/s = C_{i,j}/r_i^2$. We let s.t. mean such that and : mean it holds that. We let $\{x|f(x)\}$ denote a set of elements so that an element x is in the set if and only if f(x) is true. For convenience, we write the predicate $(\forall t>0:x)$ to mean the predicate $(\forall t \text{ s.t. } t>0:x)$. For convenience, we also define $\text{DMAX} = \max_{\tau_i \in \tau} D_i$, $\text{DMIN} = \min_{\tau_i \in \tau} D_i$, and $\text{TMAX} = \max_{\tau_i \in \tau} T_i$.

III. SCHEDULABILITY ANALYSIS OF PARALLEL TASKS ON A HOMOGENEOUS MULTIPROCESSOR

There is no optimal online algorithm for scheduling sporadic tasks on a homogeneous multiprocessor (even for tasks without parallelism) [33]. Therefore, we use global-Earliest-Deadline-First (gEDF) scheduling as it has good speedup factor [34]. An exact schedulability test exists for gEDF [35] but it has high time-complexity, does not support parallel tasks, and requires

$$C_i \stackrel{\text{def}}{=} \sum_{j=1}^{\text{ns}_i} \left(\text{nseg}_{i,j} \times C_{i,j} \right) \qquad \qquad \eta_i \stackrel{\text{def}}{=} \sum_{j=1}^{\text{ns}_i} \left(\left\lceil \frac{\text{nseg}_{i,j}}{m} \right\rceil \times C_{i,j} \right)$$
 (1)

$$WJ(\tau_{i}, t, s) \stackrel{\text{def}}{=} \left\{ \begin{array}{ccc} 0 & \text{if } t < 0 \\ WJS(i, t, 1, s) & \text{if } 0 \leq t < \frac{\eta_{i}}{s} & \text{bsp}_{i, j} \stackrel{\text{def}}{=} \frac{C_{i, j}}{s} \times \left\lfloor \frac{\text{nseg}_{i, j}}{m} \right\rfloor & \text{sp}_{i, j} \stackrel{\text{def}}{=} \frac{C_{i, j}}{s} \times \left\lceil \frac{\text{nseg}_{i, j}}{m} \right\rceil \end{array} \right.$$
(2)

$$\text{WJS}\left(i,t,j,s\right) \overset{\text{def}}{=} \left\{ \begin{array}{c} t \times m \times s & \text{if } 0 \leq t < \text{bsp}_{i,j} \\ \text{bsp}_{i,j} \times m \times s + \left(t - \text{bsp}_{i,j}\right) \times \left(\text{nseg}_{i,j} \bmod m\right) \times s & \text{if } \text{bsp}_{i,j} \leq t < \text{sp}_{i,j} \\ C_{i,j} \times \text{nseg}_{i,j} + \text{WJS}\left(i,t - \text{sp}_{i,j},j + 1,s\right) & \text{if } \text{sp}_{i,j} \leq t \end{array} \right.$$
 (3)

$$\operatorname{ffdbf}\left(\tau_{i}, t, v, s\right) \stackrel{\text{def}}{=} \left| \frac{t}{T_{i}} \right| \times C_{i} + C_{i} - \operatorname{WJ}\left(\tau_{i}, \left(D_{i} - \left(t \bmod T_{i}\right)\right) \times v, s\right)$$

$$\tag{4}$$

$$h\left(\tau, m, s, \sigma, t\right) \stackrel{\text{def}}{=} \left(\left(\sum_{\tau_i \in \tau} \text{ffdbf}\left(\tau_i, t, \frac{\sigma}{s}, s\right) \right) \le \left(\left(m - (m - 1) \times \frac{\sigma}{s} \right) \times t \times s \right) \right)$$
 (5)

$$\left(\exists \sigma \text{ s.t. } \left(\sigma \geq \max_{\tau_i \in \tau} \frac{\eta_i}{D_i}\right) \land (\forall t \text{ s.t. } t \geq 0 : h\left(\tau, m, s, \sigma, t\right))\right) \Rightarrow \tau \text{ is gEDF-schedulable on } m \text{ processors of speed } s$$
 (6)

$$\tau$$
 is feasible on m processors of speed $s \Rightarrow \left(\forall t > 0 : \sum_{\tau_i \in \tau} \text{ffdbf}(\tau_i, t, 1, s) \le m \times t \times s \right)$ (7)

Fig. 2: Previously known [17] schedulability analysis for gEDF scheduling of parallel tasks on a homogeneous multiprocessor.

$$\Delta\left(\tau\right) \stackrel{\text{def}}{=} 2^{\left\lfloor \log_2\left(\max_{\tau_i \in \tau} (T_i + D_i)\right) \right\rfloor + 1} \tag{8}$$

$$\Delta(\tau) \stackrel{\text{def}}{=} 2^{\lfloor \log_2(\max_{\tau_i \in \tau}(T_i + D_i)) \rfloor + 1}$$

$$\text{ffdbf}^*(\tau_i, t, v, s, \tau) \stackrel{\text{def}}{=} \begin{cases} \text{ffdbf}(\tau_i, 2^{\lfloor \log_2 t \rfloor + 1}, v, s) & \text{if } t \leq \Delta(\tau) \\ \text{ffdbf}(\tau_i, \Delta(\tau), v, s) + \left(C_i + \frac{C_i}{T_i} \times (t - \Delta(\tau))\right) & \text{if } t > \Delta(\tau) \end{cases}$$

$$(9)$$

Fig. 3: New expressions we will use.

task parameters be integers. Therefore, in this work, we use a sufficient (not exact) schedulability test for parallel tasks.

The literature offers many sufficient schedulability tests for gEDF for tasks that are not parallel — see for example [36]-[38]. Of particular interest is [38] which offers a schedulability test with a speedup factor two. The key to its good performance is the use of ffdbf — forced-forward demand-bound function — for describing the maximum amount of execution a task can demand in a time interval, rather than using the traditional dbf — demand-bound function. This schedulability test [38] states that if there exists a σ such that σ is at least as large as the density of each task and for each value of t the sum of ffdbf of tasks is at most a certain value then the taskset is gEDF-schedulable. Later work [17] extended this for parallel tasks by defining ffdbf for parallel tasks. Fig. 2 shows this schedulability test (see Eq. (6)) for parallel tasks on a homogeneous multiprocessor [17] comprising m processors. See (4). It shows the definition of ffdbf. We define ffdbf using WJ where WJ should be read as: Work-performed-by-a-single-Job-of-task- τ_i . WJ is defined using WJS where WJS should be read as: Work-performed-by-Stage-j-and-later-of-a-single-Job-of-task- τ_i . WJS is defined using $bsp_{i,j}$ and $sp_{i,j}$ where $bsp_{i,j}$ should be read as: the-SPan-of-time-during-whichstage-j-of-task- τ_i -can-keep-all-processors-Busy-for-the-casethat-there-is-no-contention-from-other-jobs and $sp_{i,j}$ should be read as: the-SPan-of-time-during-which-stage-j-of-task- τ_i can-keep-at-least-one-processor-busy-for-the-case-that-there-

is-no-contention-from-other-jobs. C_i denotes an upper bound on the total execution requirement of a job of τ_i , that is, if a job of τ_i executes with no contention from other jobs on a computer system with a single processor then it takes C_i/s time units to finish. η_i denotes an upper bound on the number of elapsed units of execution performed by a job of task τ_i , that is, if a job of τ_i executes with no contention from other jobs on a computer system with an infinite number of processors then it takes η_i/s time units to finish.

Fig. 2 also shows a feasibility test (see Eq. (7)) for parallel tasks on a homogeneous multiprocessor. Since this formulation is for homogeneous multiprocessors, we do not have the ¹ and ² on $C_{i,j}$. Basic properties of ffdbf are shown below.

Lemma 1. $\forall t_0 > 0, \forall t > t_0$: ffdbf $(\tau_i, t_0, v, s) \leq$ ffdbf (τ_i, t, v, s)

Lemma 2. $\forall l \in \mathbb{N}$: ffdbf $(\tau_i, t + l \times T_i, v, s)$ ffdbf $(\tau_i, t, v, s) + l \times C_i$

Proof: Follows from Eq. (4). Let $\Delta(\tau)$, in Fig. 3, be a duration of a time interval.

Lemma 3. ffdbf
$$(\tau_i, \Delta(\tau), v, s)$$
 + $C_i \leq$ ffdbf $(\tau_i, 2 \times \Delta(\tau), v, s)$

Proof: Applying Lemma 2 with $t = \Delta(\tau)$ and l = 1, yields ffdbf $(\tau_i, \Delta(\tau), v, s) + C_i = \text{ffdbf}(\tau_i, \Delta(\tau) + T_i, v, s)$. From the definition of $\Delta(\tau)$, it follows that $T_i \leq \Delta(\tau)$.

```
C1. \exists \sigma^1 \text{ s.t. } (\forall \tau_i \in \tau \text{ s.t. } x_i^1 = 1 : \frac{\eta_i^1}{D_i} \leq \sigma^1) \land (\forall t \geq 0 : (\sum_{\tau_i \in \tau} \text{ffdbf}^1(\tau_i, t, \frac{\sigma^1}{s}, s) \times x_i^1) \leq ((m_1 - (m_1 - 1) \times \frac{\sigma^1}{s}) \times t \times s))

C2. \exists \sigma^2 \text{ s.t. } (\forall \tau_i \in \tau \text{ s.t. } x_i^2 = 1 : \frac{\eta_i^2}{D_i} \leq \sigma^2) \land (\forall t \geq 0 : (\sum_{\tau_i \in \tau} \text{ffdbf}^2(\tau_i, t, \frac{\sigma^2}{s}, s) \times x_i^2) \leq ((m_2 - (m_2 - 1) \times \frac{\sigma^2}{s}) \times t \times s))

C3. \forall \tau_i \in \tau : x_i^1 + x_i^2 = 1

C4. \forall \tau_i \in \tau : x_i^1 \in \{0, 1\} \text{ and } x_i^2 \in \{0, 1\}
```

Fig. 4: A naive formulation of constraints for task-to-processor-type assignment.

Applying this on the above and using Lemma 1 yields ffdbf $(\tau_i, \Delta(\tau), v, s) + C_i \leq \text{ffdbf}(\tau_i, 2 \times \Delta(\tau), v, s)$.

Previous works [39], [40] have approximated the demand-bound function and used it for schedulability analysis on a single processor and a homogeneous multiprocessor. We now define a function ffdbf^* (an approximation of ffdbf) that is fit for our purpose. For inputs where t is at most $\Delta(\tau)$, ffdbf^* (τ_i, t, v, s, τ) is a staircase function and for t greater than $\Delta(\tau)$, ffdbf^* (τ_i, t, v, s, τ) increases linearly with t. Formally, Eq. (9) shows the definition of ffdbf^* (τ_i, t, v, s, τ).

Lemma 4.
$$\forall t \geq 0$$
: ffdbf $(\tau_i, t, v, s) \leq \text{ffdbf}^* (\tau_i, t, v, s, \tau)$

Proof: See Appendix.

Definition 7.
$$TS(\tau, \theta) \stackrel{\text{def}}{=} \{t | (2^{\lfloor \log_2 t \rfloor} = t) \land (\text{DMIN} \times (1 - \theta) \le t \le \Delta(\tau))\} \cup \{2^{\lfloor \log_2(\text{DMIN} \times (1 - \theta)) \rfloor}\}$$

Lemma 5.
$$\forall t \in TS(\tau, \theta)$$
 : $ffdbf^*(\tau_i, t, v, s, \tau)$ $ffdbf(\tau_i, 2 \times t, v, s)$

IV. NEW ALGORITHM AND ITS SPEEDUP FACTOR

In this section, we discuss scheduling on a two-type heterogeneous multiprocessor. We will use notations in Fig. 2 and Fig. 3 but with 1 as superscript; this superscript indicates that the quantity is based on $C^1_{i,j}$. Ditto for type-2. For example, from Eq. (1) we obtain: $C^1_i \stackrel{\mathrm{def}}{=} \sum_{j=1}^{\mathrm{ns}_i} \left(\mathrm{nseg}_{i,j} \times C^1_{i,j} \right)$ and $C^2_i \stackrel{\mathrm{def}}{=} \sum_{j=1}^{\mathrm{ns}_i} \left(\mathrm{nseg}_{i,j} \times C^2_{i,j} \right)$.

A. Developing the new algorithm

The problem of intra-migrative scheduling of constrained-deadline parallel sporadic tasks on a two-type heterogeneous multiprocessor can be solved in two steps. Step 1: Before runtime, assign tasks to processor types so that (i) tasks assigned to type-1 are gEDF-schedulable on the processors of type-1 and (ii) tasks assigned to type-2 are gEDF-schedulable on the processors of type-2. Step 2: At run-time, schedule all tasks assigned to type-1 with gEDF on processors of type-1 and schedule all tasks assigned to type-2 with gEDF on processors of type-2. Since Step 2 is trivial, we only discuss Step 1.

Step 1 could be solved as follows. Let $x_i^1=1$ indicate that task τ_i is assigned to type-1 processors and let $x_i^2=1$ indicate that task τ_i is assigned to type-2 processors. Let X denote the matrix of x_i values for all tasks in τ . Then, by using Eq. (6), one could solve Step 1 by assigning values to x_i variables such that all the constraints in Fig. 4 are satisfied. Intuitively, C1 in Fig. 4 states that according to the schedulability test of Eq. (6), the tasks assigned to type-1 processors are gEDF-schedulable

on type-1 processors. C2 is analogous for type-2 processors. C3 combined with C4 states that a task is either assigned to type-1 or type-2. C4 states that x_i -variables are integers. Unfortunately, creating an algorithm that assigns values to X such that all the constraints in Fig. 4 are satisfied is challenging because (i) it involves an exists-quantifier ($\exists \sigma^1$ in C1 and $\exists \sigma^2$ in C2) and (ii) it involves a forall-quantifier ($\forall t$ in C1 and $\forall t$ in C2) and (iii) it has integer variables (see C4). Hence, we now present other constraints so that if these other constraints are satisfied then the constraints in Fig. 4 are satisfied as well.

Let θ^1 and θ^2 be non-negative parameters that we can choose. Then, instead of asking if there exists a σ^1 in C1 in Fig. 4 with certain properties, let us only consider the σ^1 such that $\sigma^1/s = \theta^1$. Then it follows that if there is a task τ_i with $x_i^1 = 1$ and $\frac{\eta_i^1}{D_i} > \theta^1 \times s(\Pi)$ then C1 is violated. Hence, if θ^1 is given and $\sigma^1/s = \theta^1$ and $\frac{\eta_i^1}{D_i} > \theta^1 \times s(\Pi)$ then it is necessary that $x_i^1 = 0$. We can reason analogously for θ^2 and C2. For this reason, we introduce the following sets.

$$\begin{split} & \text{H}12 \stackrel{\text{def}}{=} \left\{ \tau_i \in \tau \mid (\frac{\eta_i^1}{D_i} > \theta^1 \times s(\Pi)) \wedge (\frac{\eta_i^2}{D_i} > \theta^2 \times s(\Pi)) \right\} \\ & \text{H}1 \stackrel{\text{def}}{=} \left\{ \tau_i \in \tau \mid (\frac{\eta_i^1}{D_i} \leq \theta^1 \times s(\Pi)) \wedge (\frac{\eta_i^2}{D_i} > \theta^2 \times s(\Pi)) \right\} \\ & \text{H}2 \stackrel{\text{def}}{=} \left\{ \tau_i \in \tau \mid (\frac{\eta_i^1}{D_i} > \theta^1 \times s(\Pi)) \wedge (\frac{\eta_i^2}{D_i} \leq \theta^2 \times s(\Pi)) \right\} \\ & \text{L} \stackrel{\text{def}}{=} \left\{ \tau_i \in \tau \mid (\frac{\eta_i^1}{D_i} \leq \theta^1 \times s(\Pi)) \wedge (\frac{\eta_i^2}{D_i} \leq \theta^2 \times s(\Pi)) \right\} \end{split}$$

Observe that $\tau = \text{H}12 \cup \text{H}1 \cup \text{H}2 \cup \text{L}$. Let $\text{H}12(\theta^1, \theta^2, \tau, \Pi)$ denote H12 for the parameters $\theta^1, \theta^2, \tau, \Pi$. Analogously for H1,H2, and L.

Clearly, if θ^1 and θ^2 are given and $\sigma^1/s = \theta^1$ and $\sigma^2/s = \theta^2$ and there is a task in H12 then it is impossible to satisfy Fig. 4. Also, if θ^1 is given and $\sigma^1/s = \theta^1$ then it is necessary that, for each task $\tau_i \in \text{H1}$, $x_i^1 = 1$. Analogously, if θ^2 is given and $\sigma^2/s = \theta^2$ then it is necessary that, for each task $\tau_i \in \text{H2}$, $x_i^2 = 1$. This yields Fig. 5. It can be seen that if θ^1 and θ^2 are given and X satisfies Fig. 5 then X satisfies Fig. 4.

Note that there is still a $\forall t$ in C1 and C2 in Fig. 5. We now present constraints with a finite number of t — see Fig. 6.

Lemma 6. if X satisfies Fig. 6 then X satisfies Fig. 5.

Proof: Suppose that the lemma was false. Then there exists $\tau, \Pi, \theta^1, \theta^2, X$ such that X satisfies Fig. 6 and X does not satisfy Fig. 5. Note that it can only be that either C1 or C2 (or both) are violated in Fig. 5.

If it is C1 then we can reason as follows: There must be a t that violated C1 in Fig. 5. Hence,

```
C1. \forall t \geq 0 : (\sum_{\tau_i \in \tau} \text{ffdbf}^1(\tau_i, t, \theta^1, s) \times x_i^1) \leq ((m_1 - (m_1 - 1) \times \theta^1) \times t \times s)

C2. \forall t \geq 0 : (\sum_{\tau_i \in \tau} \text{ffdbf}^2(\tau_i, t, \theta^2, s) \times x_i^2) \leq ((m_2 - (m_2 - 1) \times \theta^2) \times t \times s)

C3. \forall \tau_i \in \tau : x_i^1 + x_i^2 = 1

C4. \forall \tau_i \in \tau : x_i^1 \in \{0, 1\} \text{ and } x_i^2 \in \{0, 1\}

C5. \forall \tau_i \in H1 : x_i^1 = 1

C6. \forall \tau_i \in H2 : x_i^2 = 1

C7. H12 = \emptyset
```

Fig. 5: A slightly less naive formulation of constraints for task-to-processor-type assignment.

```
C1. \forall \in TS(\tau, \theta^1) : (\sum_{\tau_i \in \tau} \text{ffdbf}^{*1}(\tau_i, t, \theta^1, s, \tau) \times x_i^1) \leq ((m_1 - (m_1 - 1) \times \theta^1) \times t \times s)

C2. \forall \in TS(\tau, \theta^2) : (\sum_{\tau_i \in \tau} \text{ffdbf}^{*2}(\tau_i, t, \theta^2, s, \tau) \times x_i^2) \leq ((m_2 - (m_2 - 1) \times \theta^2) \times t \times s)

C3-C7. Same as C3-C7 in Figure 5

C8. (\sum_{\tau_i \in \tau} (C_i^1/T_i) \times x_i^1) \leq ((m_1 - (m_1 - 1) \times \theta^1) \times s)

C9. (\sum_{\tau_i \in \tau} (C_i^2/T_i) \times x_i^2) \leq ((m_2 - (m_2 - 1) \times \theta^2) \times s)
```

Fig. 6: Constraints for task-to-processor-type assignment.

```
C1. \forall t \in TS(\tau, \theta^1) : (\sum_{\tau_i \in \tau} \text{ffdbf}^{*1}(\tau_i, t, \theta^1, s, \tau) \times x_i^1) \leq ((m_1 - (m_1 - 1) \times \theta^1) \times t \times s \times 1/2)
C2. \forall t \in TS(\tau, \theta^2) : (\sum_{\tau_i \in \tau} \text{ffdbf}^{*2}(\tau_i, t, \theta^2, s, \tau) \times x_i^2) \leq ((m_2 - (m_2 - 1) \times \theta^2) \times t \times s \times 1/2)
C3. Same as C3 in Figure 6
C4. \forall \tau_i \in \tau : x_i^1 \geq 0 \text{ and } x_i^2 \geq 0
C5-C7. Same as C5-C7 in Figure 6
C8. (\sum_{\tau_i \in \tau} (C_i^1/T_i) \times x_i^1) \leq ((m_1 - (m_1 - 1) \times \theta^1) \times s \times 1/2)
C9. (\sum_{\tau_i \in \tau} (C_i^2/T_i) \times x_i^2) \leq ((m_2 - (m_2 - 1) \times \theta^2) \times s \times 1/2)
```

Fig. 7: Constraints for task-to-processor-type assignment — relaxed to LP.

```
C1-C9. Same as C1-C9 in Figure 6
C10. \forall \tau_i \in \tau \text{ s.t. } ((x'_i^1 = 1) \lor (x'_i^2 = 1)) : x_i^1 = x'_i^1
C11. \forall \tau_i \in \tau \text{ s.t. } ((x'_i^1 = 1) \lor (x'_i^2 = 1)) : x_i^2 = x'_i^2
C12. X' is the solution to the problem in Fig. 7 and X' is a vertex solution
```

Fig. 8: Constraints for task-to-processor-type assignment; we will show this can be computed in pseudo-polynomial time.

$$\left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, \theta^1, s\right) \times x_i^1\right) > \left(m_1 - (m_1 - 1) \times \theta^1\right) \times t \times s \tag{10}$$

For this t, let us explore three possibilities:

Case 1: $t > \Delta(\tau)$. Note that $\Delta(\tau)$ is an element in $TS(\tau, \theta^1)$. Then, C1 in Fig. 6 yields:

$$\left(\sum_{\tau_{i} \in \tau} \operatorname{ffdbf}^{*1}\left(\tau_{i}, \Delta(\tau), \theta^{1}, s, \tau\right) \times x_{i}^{1}\right) \leq \left(m_{1} - (m_{1} - 1) \times \theta^{1}\right) \times \Delta(\tau) \times s \tag{11}$$

Then, C8 in Fig. 6 yields:

$$\left(\sum_{\tau_i \in \tau} \frac{C_i}{T_i} \times x_i^1\right) \le \left(m_1 - (m_1 - 1) \times \theta^1\right) \times s \tag{12}$$

Multiplying Eq. (12) by $(t - \Delta(\tau))$ and adding to Eq. (11) and then combining with Eq. (10) yields:

$$\begin{split} &(\sum_{\tau_i \in \tau} (\mathrm{ffdbf}^{*\,1}\left(\tau_i, \Delta(\tau), \theta^1, s, \tau\right) + \frac{C_i}{T_i} \times (t - \Delta(\tau))) \times x_i^1) \\ &< (\sum_{\tau_i \in \tau} \mathrm{ffdbf}^1\left(\tau_i, t, \theta^1, s\right) \times x_i^1) \end{split}$$

Since $\Delta(\tau) \in TS(\tau, \theta^1)$, Lemma 5 can be applied on the left-most term. Doing so and then applying Lemma 3 yields:

$$\begin{split} &(\sum_{\tau_i \in \tau} (\mathrm{ffdbf}^1\left(\tau_i, \Delta(\tau), \theta^1, s\right) + C_i + \frac{C_i}{T_i} \times (t - \Delta(\tau))) \times x_i^1) \\ &< (\sum_{\tau_i \in \tau} \mathrm{ffdbf}^1\left(\tau_i, t, \theta^1, s\right) \times x_i^1) \end{split}$$

Note that the left-hand side is the expression of ffdbf^{*1} (the second case of Eq. (9)). Hence:

$$\sum_{\tau_{i} \in \tau} \operatorname{ffdbf}^{*1}\left(\tau_{i}, t, \theta^{1}, s, \tau\right) \times x_{i}^{1} < \sum_{\tau_{i} \in \tau} \operatorname{ffdbf}^{1}\left(\tau_{i}, t, \theta^{1}, s\right) \times x_{i}^{1}$$

But this contradicts Lemma 4.

Case 2: $t < \text{DMIN} \times (1 - \theta^1)$. For such a t, it holds that $\text{ffdbf}^1(\tau_i, t, \theta^1, s)$ is zero. But this violates Eq. (10).

Case 3: DMIN \times $(1-\theta^1) \le t \le \Delta(\tau)$. Let us define t_1 as $t_1 = 2^{\lfloor \log_2 t \rfloor + 1}$ and let t_0 be $t_1/2$. It is easy to see that $t_0 \le t < t_1$. Note that t_0 is an element in $TS(\tau, \theta^1)$. This gives us from Fig. 6:

$$\left(\sum_{\tau_i \in \tau} \text{ffdbf}^{*1} \left(\tau_i, t_0, \theta^1, s, \tau\right) \times x_i^1\right) \le \left(m_1 - (m_1 - 1) \times \theta^1\right) \times t_0 \times s$$
(13)

Since $t_0 \le t$, it clearly holds that:

$$(m_1 - (m_1 - 1) \times \theta^1) \times t_0 \times s \le (m_1 - (m_1 - 1) \times \theta^1) \times t \times s$$
 (14)

Lemma 5 yields: $\operatorname{ffdbf}^{*1}\left(\tau_{i},t_{0},\theta^{1},s,\tau\right)=\operatorname{ffdbf}^{1}\left(\tau_{i},t_{1},\theta^{1},s\right)$. Combining this with Eq. (10), Eq. (13), and Eq. (14) yields:

$$\sum_{\tau_{i} \in \tau} \operatorname{ffdbf}^{1}\left(\tau_{i}, t_{1}, \theta^{1}, s\right) \times x_{i}^{1} < \sum_{\tau_{i} \in \tau} \operatorname{ffdbf}^{1}\left(\tau_{i}, t, \theta^{1}, s\right) \times x_{i}^{1}$$

Using this and $t < t_1$ and Lemma 1 yields a contradiction.

If C2 is violated then we can reason analogously to the case when C1 is violated.

It can be seen that if the lemma is false then each case results in contradiction. Hence, the lemma is true.

Note that in Fig. 6, there is a finite number of constraints and this is what we want. However, the X variables are integers and this makes the problem a Mixed-Integer Linear Program (MILP); the research literature currently neither offers a polynomial time algorithm for solving general MILP nor for solving MILP with the special structure of Fig. 6. For Linear Programming (LP), polynomial time algorithms are known though (see [41], for example). It is also known that if there is a solution to an LP then there is also a vertex solution to the LP. We now discuss how to exploit this. Fig. 7 shows an LP; it differs from Fig. 6 in that X variables are real numbers instead of integers and it is also more constrained s/2 instead of s in C1,C2,C8 and C9. With the solution to this LP, we obtain a new optimization problem — see Fig. 8. This optimization problem is as follows. First, we solve the LP (specified by Fig. 7) and obtain a solution X' that is a vertex solution. With this solution X', we consider the MILP (specified by Fig. 6) and require that for those i such that $x_i^{\prime 1} = 1$ or $x_i^{\prime 2} = 1$, the value of x_i^1 should be equal to $x_i^{\prime 1}$ and the value of x_i^2 should be equal to $x_i'^2$. There may be some x_i s that remain; these will be assigned values by solving an MILP (as specified by Fig. 8).

Lemma 7. If θ^1 and θ^2 are given and X satisfies Fig. 8 then X satisfies Fig. 4.

Proof: Follows from the discussion in this subsection. ■ Hence, solving Fig. 8 yields an assignment of tasks to processor types.

B. Stating the new algorithm

We let solvePTMILP $(\tau, \Pi, \theta^1, \theta^2)$ denote a function which takes as input a taskset τ and a computer platform Π and θ^1 and θ^2 and returns a tuple $\langle f, X \rangle$ where f is a boolean and X is a matrix with the following interpretation: if Fig. 8 is feasible then f is true and X is the solution; if Fig. 8 is infeasible then f is false and X is undefined.

Theorem 1. If $\langle f, X \rangle = \text{solvePTMILP}(\tau, \Pi, \theta^1, \theta^2)$ and f is true and tasks are assigned to processor types according to the X-matrix and tasks are scheduled with gEDF on each processor type **then** all deadlines will be met at run-time.

Proof: Follows from Lemma 7 and the fact that Eq. (6) is a schedulability test.

Algorithm 1: An algorithm for evaluating the function solvePTMILP $(\tau, \Pi, \theta^1, \theta^2)$.

```
Input: A taskset \tau and a two-type platform \Pi and \theta^1 and \theta^2
    Output: A tuple \langle f, X \rangle where f is a boolean and X is a matrix
   Partition \tau into H12, H1, H2 and L
   if (H12 = \emptyset) then
          Solve the LP in Fig. 7 and obtain a vertex solution
          if (this LP is feasible) then
               Let X' denote this solution.
               Let F denote a set of indices of tasks in L such that
               (x'_i^1 \neq 1) \lor (x'_i^2 \neq 1). Let us introduce \chi^{\text{found}} which is an assignment of values to
               the x_i-variables whose subscript index is in F; this
               assignment is initialized to be undefined.
               Let us introduce a local variable foundPTMILP that is
               boolean and initialize it to false.
               foreach assignment of 0-1 to the x_i-variables whose subscript
               index is in F do
10
                     Evaluate if Fig. 8 is satisfied for this assignment
                     if (the above evaluation yields true) then
11
                          Let \chi denote the assignment of 0-1 to the
                           x_i-variables whose subscript index is in F
                           if (foundPTMILP = false) then
13
                                 Set foundPTMILP to true
14
                                Set \chi^{\text{found}} to \chi
15
                           end
16
17
                     end
18
               end
               if (foundPTMILP = true) then
19
20
                     Form the matrix X as follows:
                     \forall i \in F: Assign x_i^1 and x_i^2 according to \chi^{\text{found}}
21
                     \forall i \in L \setminus F \text{: Assign } x_i^1 \text{ and } x_i^2 \text{ according to } X'.
22
                     \forall i \in H1: Assign x_i^1 = 1 and x_i^2 = 0
\forall i \in H2: Assign x_i^1 = 0 and x_i^2 = 1
23
                     return \langle \text{true}, X \rangle
25
               else
                     return \langle \text{false}, X' \rangle
27
28
               end
29
30
              return \langle \text{false}, X \rangle, where X is undefined.
31
32 else
         return \langle \text{false}, X \rangle, where X is undefined.
33
```

Algorithm 2: The new intra-migrative task assignment algorithm for two-type heterogeneous multiprocessors.

```
Input: A taskset \tau and a two-type platform \Pi
Output: Assignment of tasks to processor types indicated by matrix X

1 \langle f, X \rangle \coloneqq \text{solvePTMILP}(\tau, \Pi, 1/R(\Pi), 1/R(\Pi))

2 if (f = \text{true}) then

3 | declare SUCCESS and stop

4 else

5 | declare FAILURE and stop

6 end
```

We now define a term used in the rest of the paper.

Definition 8.
$$R(\Pi) = 4 + \max\left(1 - \frac{1}{m_1}, 1 - \frac{1}{m_2}\right)$$

Algorithm 1 lists the pseudo-code for evaluating the function solvePTMILP $(\tau, \Pi, \theta^1, \theta^2)$. Algorithm 2 shows how to assign tasks to processor types.

Theorem 2. If Algorithm 2 declares SUCCESS and tasks are assigned to processor types according to the X-matrix and

tasks are scheduled with gEDF on each processor type then all deadlines will be met at run-time.

C. Proving the time complexity of the new algorithm

Lemma 8.
$$|TS(\tau, \theta^1)| = \lfloor \log_2 \frac{\Delta(\tau)}{DMIN \times (1 - \theta^1)} \rfloor + 2$$
 and $|TS(\tau, \theta^2)| = \lfloor \log_2 \frac{\Delta(\tau)}{DMIN \times (1 - \theta^2)} \rfloor + 2$

Proof: Follows from the definition of TS.

Lemma 9. After line 6 of Algorithm 1 has executed, it holds that: $|F| \leq \lfloor \log_2 \frac{\Delta(\tau)}{\text{DMIN} \times (1-\theta^1)} \rfloor + \lfloor \log_2 \frac{\Delta(\tau)}{\text{DMIN} \times (1-\theta^2)} \rfloor + 6$.

Proof: In the LP on line 3 of Algorithm 1, there are

- 1) $2 \times |L|$ variables
- 2) $\lfloor \log_2 \frac{\Delta(\tau)}{\text{DMIN} \times (1-\theta^1)} \rfloor + \lfloor \log_2 \frac{\Delta(\tau)}{\text{DMIN} \times (1-\theta^2)} \rfloor + 6 + |L|$

The former follows from the fact that there are no tasks in H12 and for the tasks in H1 and H2 there are no X-variables (they are constants, as stated by C5 and C6). The latter can be seen from the following: There are $\lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN}\times(1-\theta^1)} \rfloor + 2$ constraints of C1 and $\lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN}\times(1-\theta^2)} \rfloor + 2$ constraints of C2 (follows from Lemma 8); one constraint of C8; one constraint of C9; |L| constraints of C3.

Let X' denote the solution of the LP in Fig. 7. Since for each vertex solution of LP, it holds that the number of non-zero variables is at most the number of constraints, it follows that there are at most $\lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^1)} \rfloor + \lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^2)} \rfloor + 6 + |L|$ non-zero values of the X' variables. For each task in $L \setminus F$, it holds that there is exactly one non-zero value in X'. For each task in F, it holds that there is exactly two non-zero values in X'. Hence, there are $1 \times (|L| - |F|) + 2 \times |F|$ non-zero values of the X' variables. Consequently: $1 \times (|L| - |F|) + 2 \times |F| \le \lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^1)} \rfloor + \lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^2)} \rfloor + 6 + |L|$. Rewriting yields: $|F| \le \lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^1)} \rfloor + \lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^2)} \rfloor + 6$. This states the lemma.

Lemma 10. The number of iterations of the for-loop on line 9 of Algorithm 1 is at most: $\left(\frac{\mathrm{TMAX} + \mathrm{DMAX}}{\mathrm{DMIN}}\right)^2 \times \frac{256}{(1-\theta^1)\times(1-\theta^2)}$

Proof: The number of iterations is at most $2^{|F|}$. Using Lemma 9 yields that the number of iterations is at most:

$$2^{\lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^1)} \rfloor + \lfloor \log_2 \frac{\Delta(\tau)}{\mathrm{DMIN} \times (1-\theta^2)} \rfloor + 6}$$

Eq. (8) yields $\Delta(\tau) \leq 2 \times (\text{TMAX} + \text{DMAX})$. Using it and and rewriting yields: the number of iterations is at most

$$2^{\left\lfloor \log_2 \frac{2 \times (\text{TMAX} + \text{DMAX})}{\text{DMIN} \times (1-\theta^1)} \right\rfloor} \times 2^{\left\lfloor \log_2 \frac{2 \times (\text{TMAX} + \text{DMAX})}{\text{DMIN} \times (1-\theta^2)} \right\rfloor} \times 2^6$$

Further rewriting yields the lemma.

Lemma 11. The time complexity of Algorithm 1 is $O\left(poly + \left(\frac{\text{TMAX} + \text{DMAX}}{\text{DMIN}}\right)^2 \times \frac{1}{(1-\theta^1)\times(1-\theta^2)}\right)$.

Proof: Follows from the facts that (i) line 3 of Algorithm 1 can be executed in polynomial time because LPs can be solved in polynomial time [41] and a solution can be

converted to a vertex solution in polynomial time and (ii) the number of combinations iterated through in the for-loop of line 9 is at most $\left(\frac{\text{TMAX} + \text{DMAX}}{\text{DMIN}}\right)^2 \times \frac{256}{(1-\theta^1)\times(1-\theta^2)}$ (follows from Lemma 10).

Theorem 3. The time complexity of Algorithm 2 is $O\left(poly + \left(\frac{\text{TMAX} + \text{DMAX}}{\text{DMIN}}\right)^2\right)$.

 $\begin{array}{lll} \textit{Proof:} & \text{Since Algorithm 2 calls solvePTMILP once} \\ \text{with } \theta^1 &= \theta^2 &= 1/R(\Pi) \text{ it follows that (using Lemma 11) the time complexity of Algorithm 2 is} \\ O\left(poly + \left(\frac{\text{TMAX} + \text{DMAX}}{\text{DMIN}}\right)^2 \times \frac{1}{(1-1/R(\Pi))\times(1-1/R(\Pi))}\right). & \text{Observing that } 4 \leq R(\Pi) \text{ yields that the time complexity of Algorithm 2 is} & O\left(poly + \left(\frac{\text{TMAX} + \text{DMAX}}{\text{DMIN}}\right)^2\right). & \blacksquare \end{array}$

D. Proving the speedup factor of the new algorithm

Lemma 12. Consider a taskset τ and a computer platform Π . If τ is intra-migrative feasible on Π then there exists a matrix X such that all constraints in Fig. 9 are satisfied.

Proof: Follows from the fact that Eq. (7) is a necessary condition for feasibility.

Lemma 13. Consider a taskset τ and a computer platform Π . If τ is intra-migrative feasible on $\Pi \times 1/R(\Pi)$ then there exists a matrix X such that all constraints in Fig. 10 are satisfied.

Proof: Follows from applying Lemma 12 on $\Pi \times (1/R(\Pi))$ and then considering $t \to \infty$ on C1 and C2 yields C8 and C9 respectively.

Lemma 14. $\forall Q \geq 0$: $(\forall t \geq 0: \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, \theta^1, s\right)\right) \leq m_1 \times t \times Q)$ $\Rightarrow (\forall t \in TS(\tau, \theta^1): \left(\sum_{\tau_i \in \tau} \text{ffdbf}^{*1}\left(\tau_i, t, \theta^1, s, \tau\right)\right) \leq m_1 \times t \times Q \times 2)$

Proof: See Appendix.

Lemma 15. $\forall Q \geq 0$: $(\forall t \geq 0 : (\sum_{\tau_i \in \tau} \text{ffdbf}^2(\tau_i, t, \theta^2, s)) \leq m_2 \times t \times Q)$ $\Rightarrow (\forall t \in TS(\tau, \theta^2) : (\sum_{\tau_i \in \tau} \text{ffdbf}^{*2}(\tau_i, t, \theta^2, s, \tau)) \leq m_2 \times t \times Q \times 2)$

Proof: See Appendix.

Lemma 16. Consider a taskset τ and a computer platform Π . If X satisfies Fig. 10 then X satisfies Fig. 11.

Proof: Follows from applying Lemma 14 on C1 in Fig. 10 and applying Lemma 15 on C2 in Fig. 10. ■

Lemma 17. Consider a taskset τ and a computer platform Π . If τ is intra-migrative feasible on $\Pi \times 1/R(\Pi)$ then there exists a matrix X such that all constraints in Fig. 11 are satisfied.

Proof: Follows Lemma 13 and Lemma 16.

Lemma 18. Consider a taskset τ and a computer platform Π . If τ is intra-migrative feasible on $\Pi \times 1/R(\Pi)$ then there exists a matrix X such that all constraints in Fig. 12 are satisfied.

Proof: Algebraic manipulations of $R(\Pi)$ yields:

```
 \begin{array}{ll} \text{C1.} & \forall t \geq 0: \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, 1, s\right) \times x_i^1\right) \leq m_1 \times t \times s \\ \text{C2.} & \forall t \geq 0: \left(\sum_{\tau_i \in \tau} \text{ffdbf}^2\left(\tau_i, t, 1, s\right) \times x_i^2\right) \leq m_2 \times t \times s \\ \text{C3.} & \forall \tau_i \in \tau: x_i^1 + x_i^2 = 1 \\ \text{C4.} & \forall \tau_i \in \tau: x_i^1 \in \{0, 1\} \text{ and } x_i^2 \in \{0, 1\} \\ \text{C5.} & \forall \tau_i \in \text{H1}(1, 1, \tau): x_i^1 = 1 \\ \text{C6.} & \forall \tau_i \in \text{H2}(1, 1, \tau): x_i^2 = 1 \\ \text{C7.} & \text{H12}(1, 1, \tau) = \emptyset \end{array}
```

Fig. 9: Constraints expressing a necessary intra-migrative feasibility condition.

```
\begin{array}{ll} \text{C1.} & \forall t \geq 0: \left( \sum_{\tau_i \in \tau} \operatorname{ffdbf}^1 \left( \tau_i, t, 1/R \left( \Pi \right), s \right) \times x_i^1 \right) \leq m_1 \times t \times (s/R \left( \Pi \right)) \\ \text{C2.} & \forall t \geq 0: \left( \sum_{\tau_i \in \tau} \operatorname{ffdbf}^2 \left( \tau_i, t, 1/R \left( \Pi \right), s \right) \times x_i^2 \right) \leq m_2 \times t \times (s/R \left( \Pi \right)) \\ \text{C3-C4.} & \text{Same as C3-C4 in Figure 9} \\ \text{C5.} & \forall \tau_i \in \operatorname{H1}(1/R \left( \Pi \right), 1/R \left( \Pi \right), \tau ): x_i^1 = 1 \\ \text{C6.} & \forall \tau_i \in \operatorname{H2}(1/R \left( \Pi \right), 1/R \left( \Pi \right), \tau ): x_i^2 = 1 \\ \text{C7.} & \operatorname{H12}(1/R \left( \Pi \right), 1/R \left( \Pi \right), \tau ) = \emptyset \\ \text{C8.} & \sum_{\tau_i \in \tau} (C_i^1/T_i) \times x_i^1 \leq m_1 \times (s/R \left( \Pi \right)) \\ \text{C9.} & \sum_{\tau_i \in \tau} (C_i^2/T_i) \times x_i^2 \leq m_2 \times (s/R \left( \Pi \right)) \end{array}
```

Fig. 10: Constraints expressing a necessary intra-migrative feasibility condition; rewritten.

```
C1. \forall t \in TS(\tau, 1/R(\Pi)) : \left(\sum_{\tau_i \in \tau} \operatorname{ffdbf}^{*1}\left(\tau_i, t, 1/R(\Pi), s, \tau\right) \times x_i^1\right) \leq m_1 \times t \times (s/R(\Pi)) \times 2
C2. \forall t \in TS(\tau, 1/R(\Pi)) : \left(\sum_{\tau_i \in \tau} \operatorname{ffdbf}^{*2}\left(\tau_i, t, 1/R(\Pi), s, \tau\right) \times x_i^2\right) \leq m_2 \times t \times (s/R(\Pi)) \times 2
C3–C9. Same as C3–C9 in Figure 10
```

Fig. 11: Constraints expressing a necessary intra-migrative feasibility condition; rewritten further.

```
\begin{array}{ll} \text{C1.} & \forall t \in TS(\tau, 1/R\left(\Pi\right)) : \left(\sum_{\tau_i \in \tau} \operatorname{ffdbf}^{*1}\left(\tau_i, t, 1/R\left(\Pi\right), s, \tau\right) \times x_i^1\right) \leq \left(m_1 - (m_1 - 1) \times 1/R\left(\Pi\right)\right) \times t \times s \times 1/2 \\ \text{C2.} & \forall t \in TS(\tau, 1/R\left(\Pi\right)) : \left(\sum_{\tau_i \in \tau} \operatorname{ffdbf}^{*2}\left(\tau_i, t, 1/R\left(\Pi\right), s, \tau\right) \times x_i^2\right) \leq \left(m_2 - (m_2 - 1) \times 1/R\left(\Pi\right)\right) \times t \times s \times 1/2 \\ \text{C3-C7.} & \text{Same as C3-C7 in Figure 11} \\ \text{C8.} & \sum_{\tau_i \in \tau} (C_i^1/T_i) \times x_i^1 \leq \left(\left(m_1 - (m_1 - 1) \times 1/R\left(\Pi\right)\right) \times s \times 1/2\right) \\ \text{C9.} & \sum_{\tau_i \in \tau} (C_i^2/T_i) \times x_i^2 \leq \left(\left(m_2 - (m_2 - 1) \times 1/R\left(\Pi\right)\right) \times s \times 1/2\right) \end{array}
```

Fig. 12: Constraints expressing a necessary intra-migrative feasibility condition; rewritten even more.

```
C1–C3. Same as C1–C3 in Figure 12
C4. \forall \tau_i \in \tau : x_i^1 \geq 0 \text{ and } x_i^2 \geq 0
C5–C9. Same as C5–C9 in Figure 12
```

Fig. 13: Constraints expressing a necessary intra-migrative feasibility condition; rewritten to LP.

```
\begin{split} m_1 \times t \times \frac{s}{R(\Pi)} \times 2 &\leq (m_1 - \frac{m_1 - 1}{R(\Pi)}) \times t \times \frac{s}{2} \\ m_2 \times t \times \frac{s}{R(\Pi)} \times 2 &\leq (m_2 - \frac{m_2 - 1}{R(\Pi)}) \times t \times \frac{s}{2} \\ m_1 \times \frac{s}{R(\Pi)} &\leq (m_1 - \frac{m_1 - 1}{R(\Pi)}) \times \frac{s}{2} \\ m_2 \times \frac{s}{R(\Pi)} &\leq (m_2 - \frac{m_2 - 1}{R(\Pi)}) \times \frac{s}{2} \end{split}
```

Hence, if X satisfies Fig. 11 then it also satisfies Fig. 12. Combining this with Lemma 17 yields the lemma.

Lemma 19. Consider a taskset τ and a computer platform Π . If there exists a matrix X such that all constraints in Fig. 12 are satisfied then Algorithm 2 declares SUCCESS.

Proof: Let us suppose that the lemma was false. Then there is a taskset τ and a computer platform Π such that

there exists a matrix X such that all constraints in Fig. 12 are satisfied (15)

and Algorithm 2 declares FAILURE.

Relaxing C4 in Fig. 12 yields:

there exists a matrix X such that all constraints in Fig. 13 are satisfied (16)

Eq. (15) yields

$$H12(1/R(\Pi), 1/R(\Pi), \tau) = \emptyset$$
(17)

Consider Fig. 7 with $\theta^1 = \theta^2 = 1/R(\Pi)$ and compare with Fig. 13. They are identical. Hence:

there is a matrix
$$X$$
 such that all constraints
in Fig. 7 are satisfied for $\theta^1 = \theta^2 = 1/R(\Pi)$ (18)

From the statement that Algorithm 2 declares FAILURE it follows that Algorithm 1 returns a tuple with the first element in the tuple being false. Let us explore the possibilities at which Algorithm 1 can return a tuple with the first element in the tuple being false.

Case 1. Algorithm 1 returns on line 33.

The condition of the case yields $H12(1/R(\Pi), 1/R(\Pi), \tau) \neq \emptyset$. But this contradicts Eq. (17).

Case 2. Algorithm 1 returns on line 30.

From the condition of the case, it follows that

there exists no matrix X such that all constraints in Fig. 7 are satisfied for $\theta^1 = \theta^2 = 1/R(\Pi)$

But this contradicts Eq. (18).

Case 3. Algorithm 1 returns on line 27.

From the condition of the case, it follows that foundPTMILP is false when the Algorithm 1 returns on line 27. Let us partition τ into F and $\tau \setminus F$. Note that for $\tau \setminus F$ it holds that X' satisfies Fig. 7 and since this set of tasks have x_i^1 and x_i^2 being integers (follows from the fact that it does not contain the tasks in F), it follows that X' also satisfies the following constraints: Fig. 8 where in the expression on the right-hand side of C1,C2,C8,C9, the symbol s is replaced by s/2. Note that $F \subseteq \tau$ and hence from Eq. (15), it follows that for F, there is an S that satisfies the following constraints: Fig. 8 where in the expression on the right-hand side of C1,C2,C8,C9, the symbol s is replaced by s/2. Adding S and S gives us a new matrix that satisfies Fig. 8 and this yields that foundPTMILP is true. This is a contradiction.

It can be seen that if the lemma is false then each case results in contradiction. Hence, the lemma is true.

Theorem 4. Consider a taskset τ and a computer platform Π . If τ is intra-migrative feasible on $\Pi \times 1/R(\Pi)$ then Algorithm 2 declares SUCCESS.

Proof: Follows from Lemma 18 and Lemma 19.

Theorem 5. Algorithm 2 has speedup factor $R(\Pi) < 5$.

Proof: Follows from Theorem 4 and Definition 8.

V. EVALUATION

Recall (from Theorem 3) that the time-complexity of our new algorithm (Algorithm 2) is pseudo-polynomial and this gives us knowledge about its worst-case running time. We would like, however, to also know its average-case running time. Therefore, we developed a tool that performs the assignment as specified by Algorithm 2 and ran experiments on randomly generated tasksets and measured the running time.

m_1	m_2	$ \tau $	TR	DTR	maxt
1	16	16	0.0100	1.0000	0.001
1	16	16	0.0100	0.0100	0.005
1	16	256	0.0100	1.0000	0.026
1	16	256	0.0100	0.0100	0.053
1	256	16	0.0100	1.0000	0.001
1	256	16	0.0100	0.0100	0.006
1	256	256	0.0100	1.0000	0.017
1	256	256	0.0100	0.0100	0.080
16	16	16	0.0100	1.0000	0.001
16	16	16	0.0100	0.0100	0.004
16	16	256	0.0100	1.0000	0.026
16	16	256	0.0100	0.0100	0.079
16	256	16	0.0100	1.0000	0.001
16	256	16	0.0100	0.0100	0.005
16	256	256	0.0100	1.0000	0.018
16	256	256	0.0100	0.0100	0.055
256	256	16	0.0100	1.0000	0.001
256	256	16	0.0100	0.0100	0.006
256	256	256	0.0100	1.0000	0.001
256	256	256	0.0100	0.0100	0.050

Fig. 14: Execution time of our new algorithm.

We generated systems as follows. We let m_1 be in the set $\{1, 16, 256\}$ and m_2 be in the set $\{1, 16, 256\}$ and $|\tau|$ be in the set $\{1, 16, 256\}$. We let TR be a parameter which specifies that $TR \leq \frac{\min T_i}{\max T_i} \leq 1$ and DTR specify that for each task τ_i , it holds that $D_i \in [DTR \times T_i, T_i]$. We let TR be 0.01 and DTR be in the set $\{0.01, 1\}$. All combinations of these were explored and 6 tasksets for each combination was generated. The number of stages of a task is a uniformly distributed random number in $\{1..5\}$ and the number of segments of a stage is a uniformly distributed random number in $\{1.. \max(m_1, m_2)\}$. Recall that Eq. (7) expresses a necessary feasibility test for parallel tasks on a homogeneous multiprocessor. This can be used to obtain an MILP which is a necessary condition for intra-migrative feasibility on a two-type heterogeneous platform. We scale the execution time parameters so that this condition is true but increasing all execution times by an arbitrarily small number makes the condition false. The intuition behind this scaling is that it makes the tasksets as challenging as possible. Generating tasksets this way is very time-consuming though; this is the reason why we only generated 6 tasksets per combination.

For each combination, the maximum time required by the algorithm was obtained and this is referred to as maxt; it is measured in seconds. The results are shown Fig. 14.

It can be seen that for these combinations, the algorithm required at most 0.079 seconds. We have conducted more extensive experiments with a wider variation of parameters and found that for these experiments, the algorithm required at most 2.44 seconds. See [42] for details and also see [42] for an algorithm that improves the performance further.

VI. CONCLUSIONS

Scheduling real-time tasks on a heterogeneous multiprocessor has received increasing attention from researchers during recent years but no solution was available for parallel tasks with a proven speedup factor. Therefore, in this paper, we have presented the first algorithm for scheduling parallel tasks on a heterogeneous multiprocessor with proven speedup factor. We did so by focusing on constrained-deadline sporadic tasks and a heterogeneous multiprocessor where processors are of two types and we presented a new algorithm that assigns tasks to processor types and then apply global-Earliest-Deadline-First on each type of processors. Our new algorithm has pseudo-polynomial time complexity and a speedup factor at most 5.

ACKNOWLEDGMENT

Copyright 2015 Carnegie Mellon University and IEEE This material is based upon work funded and supported by the Department of Defense under Contract No. FA8721-05-C-0003 with Carnegie Mellon University for the operation of the Software Engineering Institute, a federally funded research and development center. Any opinions, findings and conclusions or recommendations expressed in this material are those of the author(s) and do not necessarily reflect the views of the United States Department of Defense. NO WARRANTY. THIS CARNEGIE MELLON UNIVERSITY AND SOFT-WARE ENGINEERING INSTITUTE MATERIAL IS FUR-NISHED ON AN "AS-IS" BASIS. CARNEGIE MELLON UNIVERSITY MAKES NO WARRANTIES OF ANY KIND, EITHER EXPRESSED OR IMPLIED, AS TO ANY MAT-TER INCLUDING, BUT NOT LIMITED TO, WARRANTY OF FITNESS FOR PURPOSE OR MERCHANTABILITY, EXCLUSIVITY, OR RESULTS OBTAINED FROM USE OF THE MATERIAL. CARNEGIE MELLON UNIVERSITY DOES NOT MAKE ANY WARRANTY OF ANY KIND WITH RESPECT TO FREEDOM FROM PATENT, TRADE-MARK, OR COPYRIGHT INFRINGEMENT. This material has been approved for public release and unlimited distribution. DM-0002407

REFERENCES

- G. Raravi, B. Andersson, V. Nélis, and K. Bletsas, "Task assignment algorithms for two-type heterogeneous multiprocessors," *Real-Time Sys*tems, 2014.
- [2] S. Baruah, "Partitioning real-time tasks among heterogeneous multiprocessors," in *ICPP*, 2004.
- [3] G. Raravi and V. Nélis, "Task assignment algorithms for heterogeneous multiprocessors," TECS, 2014.
- [4] G. Raravi, B. Andersson, and K. Bletsas, "Assigning real-time tasks on heterogeneous multiprocessors with two unrelated types of processors," *Real-Time Systems*, 2013.
- [5] G. Raravi and V. Nélis, "A PTAS for assigning sporadic tasks on twotype heterogeneous multiprocessors," in RTSS, 2012.
- [6] B. Andersson and G. Raravi, "Provably good task assignment for twotype heterogeneous multiprocessors using cutting planes," TECS, 2014.

- [7] S. Kedad-Sidhoum, F. Monna, G. Mouni, and D. Trystram, "Scheduling independent tasks on multi-cores with GPU accelerators," in *Euro-Par*, ser. Springer Lecture Notes in Computer Science, 2014.
- [8] A. Wiese, V. Bonifaci, and S. Baruah, "Partitioned EDF scheduling on a few types of unrelated multiprocessors," *Real-Time Systems*, 2013.
- [9] J. Lenstra, D. Shmoys, and E. Tardos, "Approximation algorithms for scheduling unrelated parallel machines," *Math. Program.*, 1990.
- [10] J. Correa, M. Skutella, and J. Verschae, "The power of preemption on unrelated machines and applications to scheduling orders," *Mathematics* of Operations Research, 2012.
- [11] E. Horowitz and S. Sahni, "Exact and Approximate Algorithms for Scheduling Nonidentical Processors," *Journal of the ACM*, 1976.
- [12] K. Jansen and L. Porkolab, "Improved approximation schemes for scheduling unrelated parallel machines," in STOC, 1999.
- [13] M. Niemeier, A. Wiese, and S. Baruah, "Partitioned real-time scheduling on heterogeneous shared-memory multiprocessors," in ECRTS, 2011.
- [14] A. Marchetti-Spaccamela, C. Rutten, S. van der Ster, and A. Wiese, "Assigning sporadic tasks to unrelated parallel machines," in *ICALP*, 2012.
- [15] K. Lakshmanan, S. Kato, and R. Rajkumar, "Scheduling parallel realtime tasks on multi-core processors," in RTSS, 2010.
- [16] A. Saifullah, K. Agrawal, C. Lu, and C. Gill, "Multi-core real-time scheduling for generalized parallel task models," in RTSS, 2011.
- [17] B. Andersson and D. de Niz, "Analyzing Global-EDF for multiprocessor scheduling of parallel tasks," in *OPODIS*, 2012.
- [18] V. Bonifaci, A. Marchetti-Spaccamela, S. Stiller, and A. Wiese, "Feasibility analysis in the sporadic DAG model," in *ECRTS*, 2013.
- [19] S. Baruah, V. Bonifaci, A. Marchetti-Spaccamela, L. Stougie, and A. Wiese, "A generalized parallel task model for recurrent real-time processes," in RTSS, 2012.
- [20] J. Kim, H. Kim, K. Lakshmanan, and R. R. Rajkumar, "Parallel scheduling for cyber physical systems: Analysis and case study on a self-driving car," in RTAS, 2013.
- [21] J. Li, K. Agrawal, C. Lu, and C. Gill, "Analysis of global EDF for parallel tasks," in ECRTS, 2013.
- [22] L. Cong and J. H. Anderson, "Supporting soft real-time DAG-based systems on multiprocessors with no utilization loss," in RTSS, 2010.
- [23] S. Kato and Y. Ishikawa, "Gang EDF scheduling of parallel task systems," in *RTSS*, 2009.
- [24] P. Jayachandran and T. Abdelzaher, "Reduction-based schedulability analysis of distributed systems with cycles in the task graph," *Real-Time* Systems, 2010.
- [25] M. Qamhieh, F. Fauberteau, G. Laurent, and S. Midonnet, "Global EDF scheduling of directed acyclic graphs on multiprocessor systems," in RTNS, 2013.
- [26] D. Ferry, J. Li, M. Mahadevan, K. Agrawal, C. Gill, and C. Lu, "A real-time scheduling service for parallel tasks," in RTAS, 2013.
- [27] H. S. Chwa, J. Lee, K.-M. Phan, A. Easwaran, and I. Shin, "Global EDF schedulability analysis for synchronous parallel tasks on multicore platforms," in *ECRTS*, 2013.
- [28] S. Collette, L. Cucu, and J. Goossens, "Integrating job parallelism in real-time scheduling theory," *Information Processing Letters*, 2008.
- [29] L. Nogueira and L. P. Pinho, "Server-based scheduling of parallel realtime tasks," in EMSOFT, 2012.
- [30] P. Axer, S. Quinton, M. Neukirchner, R. Ernest, B. Döbel, and H. Härtig, "Response-time analysis of parallel fork-join workloads with real-time constraints," in *ECRTS*, 2013.
- [31] Q. Wang and G. Parmer, "FJOS: Practical, predictable, and efficient system support for fork-join parallelism," in *RTAS*, 2014.
- [32] M. Holenderski, R. J. Bril, and J. J. Lukkien, "Parallel-task scheduling on multiple resources," in ECRTS, 2012.
- [33] N. Fisher, J. Goossens, and S. K. Baruah, "Optimal online multiprocessor scheduling of sporadic real-time tasks is impossible," *Real-Time* Systems, 2010.
- [34] C. A. Phillips, C. Stein, E. Torng, and J. Wein, "Optimal time-critical scheduling via resource augmentation," in *STOC*, 1997.
- [35] T. P. Baker and M. Cirinei, "Brute-force determination of multiprocessor schedulability for sets of sporadic hard-deadline tasks," in *OPODIS*, 2007
- [36] T. P. Baker, "Multiprocessor EDF and deadline monotonic schedulability analysis," in RTSS, 2003.
- [37] M. Bertogna, M. Cirinei, and G. Lipari, "Improved schedulability analysis of EDF on multiprocessor platforms," in ECRTS, 2005.

- [38] S. K. Baruah, V. Bonifaci, A. Marchetti-Spaccamela, and S. Stiller, "Implementation of a speedup-optimal global EDF schedulability test," in *ECRTS*, 2009.
- [39] S. Chakraborty, S. Kunzli, and L. Thiele, "Approximate schedulability analysis," in RTSS, 2002.
- [40] S. Baruah and N. Fisher, "The partitioned multiprocessor scheduling of sporadic task systems," in RTSS, 2005.
- [41] N. Karmarkar, "A new polynomial time algorithm for linear programming," Combinatorica, 1984.
- [42] "www.andrew.cmu.edu/user/banderss/papers/parhet2/parhet2.pdf."

APPENDIX

A. Proof of Lemma 4

In this section, we prove Lemma 4 and we do this incrementally, i.e., by proving some basic results and then merging them to obtain the desired result.

Lemma 20.
$$\forall t>0,t\leq \Delta(\tau)$$
 : $\mathrm{ffdbf}\left(\tau_{i},t,v,s\right)\leq \mathrm{ffdbf}\left(\tau_{i},2^{\lfloor\log_{2}t\rfloor+1},v,s\right)$

Proof: Follows from Lemma 1 (monotonicity) and observing that $t \leq 2^{\lfloor \log_2 t \rfloor + 1}$.

$$\begin{array}{lll} \textbf{Lemma} & \textbf{21.} & \forall t > \Delta(\tau) & : & \text{ffdbf} \left(\tau_i, t, v, s\right) & \leq \\ \text{ffdbf} \left(\tau_i, \Delta(\tau), v, s\right) + \left(C_i + \frac{C_i}{T_i} \times (t - \Delta(\tau))\right) \\ \end{array}$$

Proof: Algebraic manipulations yield:

$$\begin{array}{ll} t & = & \Delta(\tau) + (t - \Delta(\tau)) \\ & = & \Delta(\tau) + \left\lfloor \frac{t - \Delta(\tau)}{T_i} \right\rfloor \times T_i + (t - \Delta(\tau)) \mod T_i \\ & \leq & \Delta(\tau) + \left\lfloor \frac{t - \Delta(\tau)}{T_i} \right\rfloor \times T_i + T_i \\ & \leq & \Delta(\tau) + \left(\left\lfloor \frac{t - \Delta(\tau)}{T_i} \right\rfloor + 1 \right) \times T_i \end{array}$$

Using this on Lemma 1 yields:

ffdbf
$$(\tau_i, t, v, s) \le$$
 ffdbf $\left(\tau_i, \Delta(\tau) + \left(\left\lfloor \frac{t - \Delta(\tau)}{T_i} \right\rfloor + 1\right) \times T_i, v, s\right)$

Using Lemma 2 yields:

ffdbf
$$(\tau_i, t, v, s) \le$$
 ffdbf $(\tau_i, \Delta(\tau), v, s) + \left(\left\lfloor \frac{t - \Delta(\tau)}{T_i} \right\rfloor + 1 \right) \times C_i$

Relaxing the bound on the right-hand side and rewriting yields:

ffdbf
$$(\tau_i, t, v, s) \le$$
 ffdbf $(\tau_i, \Delta(\tau), v, s) + (t - \Delta(\tau)) \times \frac{C_i}{T_i} + C_i$

This states the lemma.

We now restate Lemma 4 and prove it.

Lemma 4. ffdbf
$$(\tau_i, t, v, s) \leq \text{ffdbf}^* (\tau_i, t, v, s, \tau)$$

Proof: We need to consider two cases.

Case 1. $t \leq \Delta(\tau)$: For this case Lemma 20 along with the definition of ffdbf* in Eq. (9) proves the lemma.

Case 2. $t > \Delta(\tau)$: For this case Lemma 21 along with the definition of ffdbf* in Eq. (9) proves the lemma.

B. Proof of Lemma 14 and Lemma 15

In this section, we prove Lemma 14 and Lemma 15 and once again we do this incrementally, i.e., by proving some basic results and then merging them to obtain the desired result.

Lemma 22.
$$\forall t \in (\Delta(\tau), \Delta(\tau) + T_i]$$
 : ffdbf* $(\tau_i, t, v, s, \tau) \leq$ ffdbf $(\tau_i, t, v, s) + 2 \times C_i$

Proof: Since $t > \Delta(\tau)$ and because of Lemma 1 (monotonicity), we have:

ffdbf
$$(\tau_i, \Delta(\tau), v, s) < \text{ffdbf } (\tau_i, t, v, s)$$
 (19)

Rewriting yields:

ffdbf
$$(\tau_i, \Delta(\tau), v, s) + C_i + \frac{C_i}{T_i} \times T_i \le \text{ffdbf}(\tau_i, t, v, s) + 2 \times C_i$$
 (20)

From $t \in (\Delta(\tau), \Delta(\tau) + T_i]$, we obtain that: $t - \Delta(\tau) \le T_i$. Applying this on Eq. (20) yields: $\forall t \in (\Delta(\tau), \Delta(\tau) + T_i]$:

ffdbf
$$(\tau_i, \Delta(\tau), v, s) + C_i + \frac{C_i}{T_i} \times (t - \Delta(\tau)) \le \text{ffdbf } (\tau_i, t, v, s) + 2 \times C_i$$
(21)

Using the definition of ffdbf* yields: $\forall t \in (\Delta(\tau), \Delta(\tau) + T_i]$: ffdbf* $(\tau_i, t, v, s, \tau) \leq$ ffdbf $(\tau_i, t, v, s) + 2 \times C_i$

Hence the proof.

Lemma 23.
$$\forall t > \Delta(\tau)$$
 : $\text{ffdbf}^*(\tau_i, t, v, s, \tau) \leq \text{ffdbf}(\tau_i, t, v, s) + 2 \times C_i$

Proof: We prove this by contradiction. If the lemma was false then there exist a t such that $t>\Delta(\tau)$ and

$$\operatorname{ffdbf}^*\left(\tau_i,t,v,s,\tau\right) > \operatorname{ffdbf}\left(\tau_i,t,v,s\right) + 2 \times C_i$$

If $t > \Delta(\tau) + T_i$ then decreasing t by T_i decreases the left-hand side and the right-hand side of the above inequality by the same amount (C_i) . Hence, we can decrease t by T_i until it holds that $t \in (\Delta(\tau), \Delta(\tau) + T_i]$. And this gives us that there exists a t such that $t \in (\Delta(\tau), \Delta(\tau) + T_i]$ and

$$ffdbf^*(\tau_i, t, v, s, \tau) > ffdbf(\tau_i, t, v, s) + 2 \times C_i$$

But this contradicts Lemma 22 and hence it is not possible that lemma under discussion is false. Hence the proof.

Lemma 24.
$$\forall t > \Delta(\tau)$$
 : $\text{ffdbf}^*(\tau_i, t, v, s, \tau) \leq \text{ffdbf}(\tau_i, t, v, s) \times 2$

Proof: Since $t > \Delta(\tau)$, it follows that t > TMAX + DMAX and then it follows that:

ffdbf
$$(\tau_i, t, v, s) > 2 \times C_i$$
 (22)

Using Lemma 23 and Eq. (22) yields: $\forall t > \Delta(\tau)$:

$$\frac{\text{ffdbf}^* (\tau_i, t, v, s, \tau)}{\text{ffdbf} (\tau_i, t, v, s)} \leq \frac{\text{ffdbf} (\tau_i, t, v, s) + 2 \times C_i}{\text{ffdbf} (\tau_i, t, v, s)} \\
\leq 1 + \frac{2 \times C_i}{\text{ffdbf} (\tau_i, t, v, s)} \\
\leq 1 + \frac{2 \times C_i}{2 \times C_i} = 2$$
(23)

Rewriting yields: $\forall t > \Delta(\tau)$:

$$ffdbf^*(\tau_i, t, v, s, \tau) \leq ffdbf(\tau_i, t, v, s) \times 2$$

This states the lemma.

Lemma 14. $\forall Q \geq 0$:

$$(\forall t \geq 0 : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, \theta^1, s\right)\right) \leq m_1 \times t \times Q) \Rightarrow (\forall t \in TS(\tau, \theta^1) : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^{*1}\left(\tau_i, t, \theta^1, s, \tau\right)\right) \leq m_1 \times t \times Q \times 2)$$

Proof: Suppose that the lemma was false. Then it holds that there exists a Q such that $Q \ge 0$ and

$$\left(\forall t \geq 0 : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, \theta^1, s\right)\right) \leq m_1 \times t \times Q\right)$$

$$\left(\exists t \in TS(\tau, \theta^1) : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^{*1}\left(\tau_i, t, \theta^1, s, \tau\right)\right) > m_1 \times t \times Q \times 2\right)$$

Since there exists a t in $TS(\tau, \theta^1)$ such that the last constraint is true, let us choose one of them and call it t_0 . This gives us:

$$\left(\forall t \geq 0 : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, \theta^1, s\right)\right) \leq m_1 \times t \times Q\right) \land \left(\left(\sum_{\tau_i \in \tau} \text{ffdbf}^{*1}\left(\tau_i, t_0, \theta^1, s, \tau\right)\right) > m_1 \times t_0 \times Q \times 2\right) \tag{24}$$

Let us consider two cases:

Case 1: $t_0 \le \Delta(\tau)$. Applying $2 \times t_0$ on the 1st constraint in Eq. (24) yields:

$$\left(\left(\sum_{\tau_i \in \tau} \text{ffdbf}^1 \left(\tau_i, 2 \times t_0, \theta^1, s \right) \right) \leq m_1 \times 2 \times t_0 \times Q \right) \wedge \left(\left(\sum_{\tau_i \in \tau} \text{ffdbf}^{*1} \left(\tau_i, t_0, \theta^1, s, \tau \right) \right) > m_1 \times t_0 \times Q \times 2 \right) \right)$$

Since $t_0 \in TS(\tau, \theta^1)$, it follows from the definition of ffdbf^{*1} that ffdbf^{*1} $(\tau_i, t_0, \theta^1, s, \tau) = \text{ffdbf}^1(\tau_i, 2 \times t_0, \theta^1, s)$. Applying this on the last constraint yields:

$$\left(\left(\sum_{\tau_i \in \tau} \text{ffdbf}^1 \left(\tau_i, 2 \times t_0, \theta^1, s \right) \right) \leq m_1 \times 2 \times t_0 \times Q \right) \wedge \left(\left(\sum_{\tau_i \in \tau} \text{ffdbf}^1 \left(\tau_i, 2 \times t_0, \theta^1, s \right) \right) > m_1 \times t_0 \times Q \times 2 \right) \right)$$

This is a contradiction. End of Case 1.

Case 2: $t_0 > \Delta(\tau)$. Applying Lemma 24 on the last constraint in Eq. (24) yields:

$$\left(\forall \geq 0 : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, \theta^1, s\right)\right) \leq m_1 \times t \times Q\right) \wedge \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t_0, \theta^1, s\right) \times 2 > m_1 \times t_0 \times Q \times 2\right)$$

Dividing the last constraint by 2 yields:

$$\left(\forall t \geq 0 : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t, \theta^1, s\right)\right) \leq m_1 \times t \times Q\right) \land \left(\sum_{\tau_i \in \tau} \text{ffdbf}^1\left(\tau_i, t_0, \theta^1, s\right) > m_1 \times t_0 \times Q\right)$$

This is a contradiction. End of Case 2.

It can be seen that if the lemma is false then for each case, we obtain a contradiction. Hence, the lemma is true.

Lemma 15. $\forall Q \geq 0$: $(\forall t \geq 0 : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^2\left(\tau_i, t, \theta^2, s\right)\right) \leq m_2 \times t \times Q) \Rightarrow (\forall t \in TS(\tau, \theta^2) : \left(\sum_{\tau_i \in \tau} \text{ffdbf}^{*2}\left(\tau_i, t, \theta^2, s\right)\right) \leq m_2 \times t \times Q \times 2)$

Proof: Analogous to the proof of Lemma 14.

Algorithm 3: Another new intra-migrative task assignment algorithm for two-type heterogeneous multiprocessors.

```
Input : A taskset \tau and a two-type platform \Pi
   Output: Assignment of tasks to processor types indicated by matrix X
   K := 4
1
2 foreach k_1 \in \{0..K-1\} do
         foreach k_2 \in \{0..K - 1\} do
3
              \theta_1 := \frac{1}{R(\Pi)} + \frac{1 - \frac{2}{R(\Pi)}}{K - \frac{1}{2}} \times k_1
               \langle f, X \rangle := \text{solvePTMILP}(\tau, \Pi, \theta_1, \theta_2)
6
               if (f = true) then
7
                    declare SUCCESS and stop
8
               end
         end
10
11 end
12 declare FAILURE and stop
```

C. Better average-case performance

So far, we have discussed how to create an algorithm with a proven speedup factor and with pseudo polynomial timecomplexity and Algorithm 2 offers this. But Algorithm 2 uses $\theta^1 = \theta^2 = 1/R(\Pi)$ and can result in poor performance for some tasksets — one such taskset is the following: $m_1 = m_2 = \infty$ and $\tau = \{\tau_1\}$ and $T_1 = 1$ and $\mathrm{ns}_i = 1$ and $\operatorname{nseg}_{1,1} = 1$ and $C_{1,1} = 0.21$ and s = 1. We can improve the performance by also exploring other values of θ^1 and θ^2 . Note that doing so gives us an algorithm that will succeed whenever Algorithm 2 succeeds but may suceed also in cases when Algorithm 2 fails. Also, note that as long as we choose a finite number of combinations of θ^1 and θ^2 and as long as for choices of θ^1 and θ^2 it holds that $\theta^1 < 1$ and $\theta^2 < 1$ then the resulting algorithm has pseudo-polynomial time-complexity (can be seen from Lemma 11). Hence, we introduce Algorithm 3 based on this idea.

D. Extensive evaluation

Recall that Fig. 14 presented an evaluation of Algorithm 2 but only for a small number of configurations and it did not evaluate Algorithm 3. Therefore, in this section, we perform an evaluation of running time with more configurations and also include Algorithm 3. The results are shown below. We also report the sucess ratio (SR) for each configuration of experiments. (We define success ratio of a configuration as the number of tasksets for which the algorithm succeeded in finding a task assignment divided by the number of tasksets evaluated for this configuration.) It can be seen that Algorithm 3 offers a significant performance improvement (in terms of success ratio) at a minor increase in running time. The maximum time is 5.5 seconds.

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.10	1	1	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	1	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	1	1	1.0000	0.0001	3	1.00	0.002	0.003
0.10	1	1	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	1	1	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	1	1	1	0.0100	0.0100	2	1.00	0.002	0.003
0.10	1	1	1	0.0100	0.0100	2	1.00	0.002	0.003
0.10	1	1	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	1	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	1	1	1	0.0001	1.0000	3	1.00	0.002	0.003
0.10	1	1	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	1	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	1	1	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	1	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	1	1	4	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	1	4	1.0000	0.0100	3	1.00	0.003	0.003
0.10	1	1	4	1.0000	0.0001	3	1.00	0.003	0.003
0.10	1	1	4	0.0100	1.0000	2	1.00	0.003	0.003
0.10	1	1	4	0.0100	1.0000	3	1.00	0.003	0.003
0.10	1	1	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	1	1	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	1	1	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	1	1	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	1	1	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	1	1	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	1	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	1	1	4	0.0001	0.0001	3	1.00	0.003	0.004
0.10	1	1	16	1.0000	1.0000	2	1.00	0.003	0.004
0.10	1	1	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	1	1	16	1.0000	0.0100	2	1.00	0.004	0.004
0.10	1	1	16 16	1.0000	0.0100	3 2	1.00	0.004	0.004
0.10	1	1	16	1.0000	0.0001	3	1.00	0.004	0.006
0.10	1	1	16	0.0100	1.0000	2	1.00	0.004	0.004
0.10	1	1	16	0.0100	1.0000	3	1.00	0.004	0.004
0.10	1	1	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	1	1	16 16	0.0100	0.0100	3	1.00	0.004	0.005
0.10	1	1	16	0.0100	0.0001	3	1.00	0.004	0.005
0.10	1	1	16	0.0001	1.0000	2	1.00	0.004	0.005
0.10	1	1	16	0.0001	1.0000	3	1.00	0.004	0.005
0.10	1	1	16	0.0001	0.0100	2	1.00	0.004	0.006
0.10	1	1	16 16	0.0001	0.0100	3 2	1.00	0.004	0.005
0.10	1	1	16	0.0001	0.0001	3	1.00	0.005	0.005
0.10	1	1	64	1.0000	1.0000	2	1.00	0.006	0.007
0.10	1	1	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10	1	1	64	1.0000	0.0100	2	1.00	0.007	0.011
0.10	1	1	64	1.0000	0.0100	3	1.00	0.007	0.010
0.10	1	1	64	1.0000	0.0001	3	1.00	0.009	0.011
0.10	1	1	64	0.0100	1.0000	2	1.00	0.008	0.010
0.10	1	1	64	0.0100	1.0000	3	1.00	0.008	0.009
0.10	1	1	64	0.0100	0.0100	2	1.00	0.009	0.010
0.10	1	1	64	0.0100	0.0100	3	1.00	0.009	0.011
0.10	1	1	64	0.0100	0.0001	3	1.00	0.011	0.012
0.10	1	1	64	0.0001	1.0000	2	1.00	0.010	0.012
0.10	1	1	64	0.0001	1.0000	3	1.00	0.010	0.012
0.10	1	1	64	0.0001	0.0100	2	1.00	0.011	0.013
0.10	1	1	64	0.0001	0.0100	3	1.00	0.011	0.014
0.10	1	1	64	0.0001	0.0001	3	1.00	0.013	0.016
0.10	1	1	256	1.0000	1.0000	2	1.00	0.021	0.023
0.10	1	1	256	1.0000	1.0000	3	1.00	0.021	0.023
0.10	1	1	256	1.0000	0.0100	2	1.00	0.033	0.036
0.10	1	1	256	1.0000	0.0100	3	1.00	0.032	0.074

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	1	1	256	1.0000	0.0001	2	1.00	0.045	0.046
0.10	1	1	256	1.0000	0.0001	3	1.00	0.046	0.047
0.10	1	1	256	0.0100	1.0000	2	1.00	0.034	0.050
0.10	1	1	256	0.0100	1.0000	3	1.00	0.034	0.051
0.10	1	1	256	0.0100	0.0100	2	1.00	0.049	0.052
0.10	1	1	256	0.0100	0.0100	3	1.00	0.049	0.053
0.10	1	1	256 256	0.0100	0.0001	3	1.00	0.064	0.075 0.069
0.10	1	1	256	0.0100	1.0000	2	1.00	0.051	0.009
0.10	1	1	256	0.0001	1.0000	3	1.00	0.051	0.053
0.10	1	1	256	0.0001	0.0100	2	1.00	0.062	0.069
0.10	1	1	256	0.0001	0.0100	3	1.00	0.062	0.066
0.10	1	1	256	0.0001	0.0001	2	1.00	0.068	0.098
0.10	1	1	256	0.0001	0.0001	3	1.00	0.067	0.090
0.10	1	4	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	1	4	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	1	4	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	1	4	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	1	4	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	1	4	1	0.0100	1.0000	3	1.00	0.003	0.003
0.10	1	4	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	1	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	1	4	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	1	4	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	1	4	1	0.0001	1.0000	2	1.00	0.002	0.003
0.10	1	4	1	0.0001	1.0000	3	1.00	0.002	0.003
0.10	1	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	1	4	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	1	4	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	1	4	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	4	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	1	4	4	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	4	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	1	4	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	1	4	4	1.0000	0.0001	3	1.00	0.003	0.004
0.10	1	4	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	1	4	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	1	4	4	0.0100	0.0100	3	1.00	0.003	0.003
0.10	1	4	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	1	4	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	1	4	4	0.0001	1.0000	2	1.00	0.004	0.004
0.10	1	4	4	0.0001	1.0000	3	1.00	0.004	0.004
0.10	1	4	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	1	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	1	4	4	0.0001	0.0001	2	1.00	0.003	0.004
0.10	1	4	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00	0.003	0.004
0.10	1	4	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	1	4	16	1.0000	0.0100	2	1.00	0.003	0.004
0.10	1	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	1	4	16	1.0000	0.0001	2	1.00	0.004	0.005
0.10	1	4	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	1	4	16	0.0100	1.0000	2	1.00	0.004	0.005
0.10	1	4	16	0.0100	1.0000	3	1.00	0.004	0.005
0.10	1	4	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	1	4	16	0.0100	0.0100	3	1.00	0.004	0.006
0.10	1	4	16 16	0.0100	0.0001	3	1.00	0.004	0.006
0.10	1	4	16	0.0100	1.00001	2	1.00	0.004	0.006
0.10	1	4	16	0.0001	1.0000	3	1.00	0.004	0.006
0.10	1	4	16	0.0001	0.0100	2	1.00	0.006	0.006
0.10	1	4	16	0.0001	0.0100	3	1.00	0.006	0.007
0.10	1	4	16	0.0001	0.0001	2	1.00	0.005	0.007
0.10	1	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.10	1	4	64	1.0000	1.0000	2	1.00	0.006	0.007
0.10	1	4	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10	1	4	64	1.0000	0.0100	2	1.00	0.008	0.011
0.10	1	4	64	1.0000	0.0100	3	1.00	0.007	0.010
0.10	1	4	64	1.0000	0.0001	3	1.00	0.009	0.011
0.10	1	4	64	0.0100	1.00001	2	1.00	0.009	0.011
0.10	1	4	64	0.0100	1.0000	3	1.00	0.008	0.009
0.10	1	-	04	0.0100	1.0000		1.00	0.000	0.009

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.10	1	4	64	0.0100	0.0100	2	1.00	0.009	0.014
0.10	1	4	64	0.0100	0.0100	3	1.00	0.009	0.014
0.10	1	4	64	0.0100	0.0001	2	1.00	0.011	0.018
0.10	1	4	64	0.0100	0.0001	3	1.00	0.011	0.017
0.10	1	4	64	0.0001	1.0000	2	1.00	0.010	0.016
0.10	1	4	64	0.0001	1.0000 0.0100	3	1.00	0.010 0.012	0.016 0.018
0.10	1	4	64	0.0001	0.0100	3	1.00	0.012	0.018
0.10	1	4	64	0.0001	0.0001	2	1.00	0.014	0.018
0.10	1	4	64	0.0001	0.0001	3	1.00	0.014	0.021
0.10	1	4	256	1.0000	1.0000	2	1.00	0.020	0.022
0.10	1	4	256	1.0000	1.0000	3	1.00	0.021	0.022
0.10	1	4	256	1.0000	0.0100	3	1.00	0.032	0.033
0.10	1	4	256 256	1.0000	0.0100	2	1.00	0.032	0.033
0.10	1	4	256	1.0000	0.0001	3	1.00	0.046	0.075
0.10	1	4	256	0.0100	1.0000	2	1.00	0.035	0.069
0.10	1	4	256	0.0100	1.0000	3	1.00	0.034	0.073
0.10	1	4	256	0.0100	0.0100	2	1.00	0.049	0.075
0.10	1	4	256	0.0100	0.0100	3	1.00	0.049	0.076
0.10	1	4	256	0.0100	0.0001	2	1.00	0.094	0.101
0.10	1	4	256 256	0.0100	0.0001 1.0000	3	1.00	0.095	0.099
0.10	1	4	256	0.0001	1.0000	3	1.00	0.049	0.080
0.10	1	4	256	0.0001	0.0100	2	1.00	0.062	0.067
0.10	1	4	256	0.0001	0.0100	3	1.00	0.059	0.068
0.10	1	4	256	0.0001	0.0001	2	1.00	0.074	0.114
0.10	1	4	256	0.0001	0.0001	3	1.00	0.075	0.115
0.10	1	16 16	1	1.0000	1.0000	2	1.00	0.002	0.003
0.10	1	16	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	1	16	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	1	16	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	1	16 16	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	1	16	1	0.0100	0.0100	3	1.00	0.002	0.003
0.10	1	16	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	1	16	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	1	16	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	1	16	1	0.0001	1.0000	2	1.00	0.002	0.003
0.10	1	16 16	1	0.0001	1.0000 0.0100	3	1.00	0.002	0.003
0.10	1	16	1	0.0001	0.0100	3	1.00	0.002	0.003
0.10	1	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	1	16	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	1	16	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	16	4	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.10	1	16 16	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	1	16	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	1	16	4	1.0000	0.0001	3	1.00	0.003	0.003
0.10	1	16	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	1	16	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	1	16 16	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	1	16	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	1	16	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	1	16	4	0.0001	1.0000	2	1.00	0.003	0.003
0.10	1	16	4	0.0001	1.0000	3	1.00	0.003	0.003
0.10	1	16 16	4	0.0001	0.0100	3	1.00	0.003	0.003
0.10	1	16	4	0.0001	0.0100	2	1.00	0.003	0.003
0.10	1	16	4	0.0001	0.0001	3	1.00	0.003	0.003
0.10	1	16	16	1.0000	1.0000	2	1.00	0.003	0.004
0.10	1	16	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	1	16 16	16 16	1.0000	0.0100	2	1.00	0.004	0.004
0.10	1	16	16	1.0000	0.0100	2	1.00	0.004	0.004
0.10	1	16	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	1	16	16	0.0100	1.0000	2	1.00	0.004	0.004
0.10	1	16	16	0.0100	1.0000	3	1.00	0.004	0.004
0.10	1	16	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	1	16 16	16 16	0.0100	0.0100	3	1.00	0.004	0.004
0.10	1	16	16	0.0100	0.0001	3	1.00	0.004	0.005
	-	10	- 10	1 2.2100			00		

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	1	16	16	0.0001	1.0000	2	1.00	0.004	0.005
0.10	1	16	16	0.0001	1.0000	3	1.00	0.004	0.005
0.10	1	16 16	16 16	0.0001	0.0100	3	1.00	0.004	0.005
0.10	1	16	16	0.0001	0.0001	2	1.00	0.004	0.003
0.10	1	16	16	0.0001	0.0001	3	1.00	0.005	0.005
0.10	1	16	64	1.0000	1.0000	2	1.00	0.006	0.006
0.10	1	16	64	1.0000	1.0000	3	1.00	0.006	0.006
0.10	1	16	64	1.0000	0.0100	2	1.00	0.007	0.008
0.10	1	16	64	1.0000	0.0100	2	1.00	0.007	0.009
0.10	1	16	64	1.0000	0.0001	3	1.00	0.009	0.014
0.10	1	16	64	0.0100	1.0000	2	1.00	0.008	0.011
0.10	1	16	64	0.0100	1.0000	3	1.00	0.008	0.011
0.10	1	16	64	0.0100	0.0100	2	1.00	0.009	0.014
0.10	1	16	64	0.0100	0.0100	3	1.00	0.009	0.014
0.10	1	16 16	64	0.0100	0.0001	2	1.00	0.014	0.017
0.10	1	16	64	0.0100	1.0000	2	1.00	0.011	0.020
0.10	1	16	64	0.0001	1.0000	3	1.00	0.010	0.015
0.10	1	16	64	0.0001	0.0100	2	1.00	0.012	0.018
0.10	1	16	64	0.0001	0.0100	3	1.00	0.011	0.018
0.10	1	16	64	0.0001	0.0001	2	1.00	0.013	0.022
0.10	1	16	64	0.0001	0.0001	3	1.00	0.017	0.022
0.10	1	16 16	256 256	1.0000	1.0000	2	1.00	0.025 0.026	0.033
0.10	1	16	256	1.0000	0.0100	2	1.00	0.026	0.055
0.10	1	16	256	1.0000	0.0100	3	1.00	0.040	0.051
0.10	1	16	256	1.0000	0.0001	2	1.00	0.055	0.067
0.10	1	16	256	1.0000	0.0001	3	1.00	0.053	0.069
0.10	1	16	256	0.0100	1.0000	2	1.00	0.033	0.047
0.10	1	16 16	256 256	0.0100	1.0000 0.0100	3	1.00	0.033	0.073
0.10	1	16	256	0.0100	0.0100	3	1.00	0.047	0.076 0.075
0.10	1	16	256	0.0100	0.0001	2	1.00	0.090	0.098
0.10	1	16	256	0.0100	0.0001	3	1.00	0.094	0.098
0.10	1	16	256	0.0001	1.0000	2	1.00	0.062	0.080
0.10	1	16	256	0.0001	1.0000	3	1.00	0.077	0.080
0.10	1	16	256	0.0001	0.0100	2	1.00	0.060	0.095
0.10	1	16 16	256 256	0.0001	0.0100	2	1.00	0.060	0.097
0.10	1	16	256	0.0001	0.0001	3	1.00	0.070	0.124
0.10	1	64	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	64	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	1	64	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	64	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	1	64	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	1	64	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	1	64	1	0.0100	1.0000	3	1.00	0.003	0.003
0.10	1	64	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	1	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	1	64	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	1	64	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	1	64	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	1	64	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	1	64	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	1	64	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	1	64	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	1	64	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	64	4	1.0000	1.0000 0.0100	3	1.00	0.003	0.003
0.10	1	64	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	1	64	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	1	64	4	1.0000	0.0001	3	1.00	0.004	0.004
0.10	1	64	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	1	64	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	1	64	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	1	64	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	1	64	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	1	64	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	1	64	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	1	64	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	1	64	4	0.0001	0.0100	3	1.00	0.003	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	1	64	4	0.0001	0.0001	2	1.00	0.003	0.004
0.10	1	64	4	0.0001	0.0001	3	1.00	0.003	0.004
0.10	1	64	16 16	1.0000	1.0000	3	1.00	0.004	0.004
0.10	1	64	16	1.0000	0.0100	2	1.00	0.005	0.005
0.10	1	64	16	1.0000	0.0100	3	1.00	0.005	0.005
0.10	1	64	16	1.0000	0.0001	2	1.00	0.005	0.006
0.10	1	64	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00	0.005	0.006
0.10	1	64	16	0.0100	1.0000	3	1.00	0.004	0.005
0.10	1	64	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	1	64	16	0.0100	0.0100	3	1.00	0.004	0.005
0.10	1	64	16 16	0.0100	0.0001	3	1.00	0.006	0.006
0.10	1	64	16	0.0001	1.0000	2	1.00	0.006	0.006
0.10	1	64	16	0.0001	1.0000	3	1.00	0.006	0.006
0.10	1	64	16	0.0001	0.0100	2	1.00	0.006	0.006
0.10	1	64	16 16	0.0001	0.0100	3	1.00	0.006	0.007
0.10	1	64	16	0.0001	0.0001	3	1.00	0.005	0.008
0.10	1	64	64	1.0000	1.0000	2	1.00	0.008	0.008
0.10	1	64	64 64	1.0000	1.0000 0.0100	3	1.00	0.008	0.008
0.10	1	64	64	1.0000	0.0100	3	1.00	0.011	0.012
0.10	1	64	64	1.0000	0.0001	2	1.00	0.014	0.015
0.10	1	64	64	1.0000	0.0001	3	1.00	0.011	0.014
0.10	1	64	64	0.0100	1.0000	3	1.00	0.008	0.009
0.10	1	64	64	0.0100	0.0100	2	1.00	0.008	0.008
0.10	1	64	64	0.0100	0.0100	3	1.00	0.009	0.010
0.10	1	64	64	0.0100	0.0001	2	1.00	0.011	0.012
0.10	1	64	64	0.0100	0.0001 1.0000	3	1.00	0.012	0.012
0.10	1	64	64	0.0001	1.0000	3	1.00	0.010	0.011
0.10	1	64	64	0.0001	0.0100	2	1.00	0.011	0.012
0.10	1	64	64	0.0001	0.0100	3	1.00	0.011	0.012
0.10	1	64	64	0.0001	0.0001	2	1.00	0.014	0.021
0.10	1	64	256	1.0000	1.0000	2	1.00	0.013	0.022
0.10	1	64	256	1.0000	1.0000	3	1.00	0.021	0.033
0.10	1	64	256	1.0000	0.0100	2	1.00	0.036	0.053
0.10	1	64	256 256	1.0000	0.0100	3	1.00	0.035	0.053
0.10	1	64	256	1.0000	0.0001	3	1.00	0.072	0.096
0.10	1	64	256	0.0100	1.0000	2	1.00	0.033	0.049
0.10	1	64	256	0.0100	1.0000	3	1.00	0.032	0.051
0.10	1	64	256 256	0.0100	0.0100	3	1.00	0.046	0.078
0.10	1	64	256	0.0100	0.0001	2	1.00	0.093	0.100
0.10	1	64	256	0.0100	0.0001	3	1.00	0.075	0.097
0.10	1	64 64	256 256	0.0001	1.0000	3	1.00	0.057	0.080
0.10	1	64	256	0.0001	0.0100	2	1.00	0.059	0.096
0.10	1	64	256	0.0001	0.0100	3	1.00	0.060	0.096
0.10	1	64	256	0.0001	0.0001	2	1.00	0.079	0.103
0.10	1	64 256	256 1	0.0001 1.0000	0.0001 1.0000	3	1.00	0.079	0.093
0.10	1	256	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	1	256	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	256	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	1	256 256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	1	256	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	1	256	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	1	256	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	1	256 256	1	0.0100	0.0100	3	1.00	0.003 0.002	0.003
0.10	1	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	1	256	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	1	256 256	1	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.10	1	256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	1	256	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	1	256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	1	256 256	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	1	230	4	1.0000	1.0000	3	1.00	0.003	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	1	256	4	1.0000	0.0100	2	1.00	0.003	0.003
0.10	1	256	4	1.0000	0.0100	3	1.00	0.003	0.015
0.10	1	256	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	1	256	4	1.0000 0.0100	0.0001	3	1.00	0.003	0.004
0.10	1	256 256	4	0.0100	1.0000	3	1.00	0.003	0.003
0.10	1	256	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	1	256	4	0.0100	0.0100	3	1.00	0.003	0.003
0.10	1	256	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	1	256	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	1	256	4	0.0001	1.0000	2	1.00	0.003	0.003
0.10	1	256	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	1	256	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	1	256 256	4	0.0001	0.0100	3	1.00	0.003	0.003
0.10	1	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.10	1	256	16	1.0000	1.0000	2	1.00	0.003	0.004
0.10	1	256	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	1	256	16	1.0000	0.0100	2	1.00	0.004	0.005
0.10	1	256	16	1.0000	0.0100	3	1.00	0.004	0.004
0.10	1	256	16	1.0000	0.0001	2	1.00	0.004	0.005
0.10	1	256	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	1	256	16	0.0100	1.0000	2	1.00	0.004	0.005
0.10	1	256 256	16 16	0.0100	1.0000 0.0100	3	1.00	0.004	0.005
0.10	1	256	16	0.0100	0.0100	3	1.00	0.004	0.005
0.10	1	256	16	0.0100	0.0001	2	1.00	0.004	0.005
0.10	1	256	16	0.0100	0.0001	3	1.00	0.004	0.006
0.10	1	256	16	0.0001	1.0000	2	1.00	0.004	0.006
0.10	1	256	16	0.0001	1.0000	3	1.00	0.004	0.006
0.10	1	256	16	0.0001	0.0100	2	1.00	0.004	0.006
0.10	1	256	16	0.0001	0.0100	3	1.00	0.005	0.005
0.10	1	256	16	0.0001	0.0001	2	1.00	0.005	0.006
0.10	1	256 256	16 64	0.0001 1.0000	1.0000	3	1.00	0.005	0.007
0.10	1	256	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10	1	256	64	1.0000	0.0100	2	1.00	0.008	0.009
0.10	1	256	64	1.0000	0.0100	3	1.00	0.008	0.009
0.10	1	256	64	1.0000	0.0001	2	1.00	0.009	0.014
0.10	1	256	64	1.0000	0.0001	3	1.00	0.010	0.015
0.10	1	256	64	0.0100	1.0000	2	1.00	0.008	0.012
0.10	1	256	64	0.0100	1.0000	3	1.00	0.008	0.011
0.10	1	256	64	0.0100	0.0100	2	1.00	0.014	0.015
0.10	1	256 256	64 64	0.0100	0.0100	3	1.00	0.015	0.015
0.10	1	256	64	0.0100	0.0001	3	1.00	0.011	0.017
0.10	1	256	64	0.0001	1.0000	2	1.00	0.011	0.012
0.10	1	256	64	0.0001	1.0000	3	1.00	0.011	0.011
0.10	1	256	64	0.0001	0.0100	2	1.00	0.011	0.012
0.10	1	256	64	0.0001	0.0100	3	1.00	0.011	0.012
0.10	1	256	64	0.0001	0.0001	2	1.00	0.013	0.015
0.10	1	256	64	0.0001	0.0001	3	1.00	0.013	0.015
0.10	1	256 256	256 256	1.0000	1.0000	3	1.00	0.020	0.022
0.10	1	256	256	1.0000	0.0100	2	1.00	0.021	0.021
0.10	1	256	256	1.0000	0.0100	3	1.00	0.035	0.042
0.10	1	256	256	1.0000	0.0001	2	1.00	0.048	0.075
0.10	1	256	256	1.0000	0.0001	3	1.00	0.045	0.074
0.10	1	256	256	0.0100	1.0000	2	1.00	0.033	0.053
0.10	1	256	256	0.0100	1.0000	3	1.00	0.035	0.053
0.10	1	256	256	0.0100	0.0100	2	1.00	0.052	0.080
0.10	1	256 256	256 256	0.0100	0.0100	3	1.00	0.051	0.080
0.10	1	256	256	0.0100	0.0001	3	1.00	0.060	0.067
0.10	1	256	256	0.0100	1.0000	2	1.00	0.050	0.073
0.10	1	256	256	0.0001	1.0000	3	1.00	0.051	0.074
0.10	1	256	256	0.0001	0.0100	2	1.00	0.063	0.092
0.10	1	256	256	0.0001	0.0100	3	1.00	0.064	0.071
0.10	1	256	256	0.0001	0.0001	2	1.00	0.080	0.123
0.10	1	256	256	0.0001	0.0001	3	1.00	0.080	0.123
0.10	4	1	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	4	1	1	1.0000	1.0000 0.0100	3	1.00	0.003	0.003
0.10	4	1	1	1.0000	0.0100	3	1.00	0.002	0.003
0.10	4	1	1	1.0000	0.0001	2	1.00	0.002	0.003
0.10	4	1	1	1.0000	0.0001	3	1.00	0.003	0.003
				- 1	1				

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	4	1	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	4	1	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	4	1	1	0.0100	0.0100	3	1.00	0.002	0.003
0.10	4	1	1	0.0100	0.0100	2	1.00	0.002	0.003
0.10	4	1	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	4	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	4	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	4	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	4	1	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	4	1	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	4	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	4	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	4	1	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	4	1	4	1.0000	0.0001	2	1.00	0.003	0.020
0.10	4	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.10	4	1	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	4	1	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	4	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	4	1	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	4	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	4	1	4	0.0001	1.0000	2	1.00	0.003	0.003
0.10	4	1	4	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.10	4	1	4	0.0001	0.0100	3	1.00	0.003	0.003
0.10	4	1	4	0.0001	0.0001	2	1.00	0.003	0.004
0.10	4	1	4	0.0001	0.0001	3	1.00	0.003	0.003
0.10	4	1	16	1.0000	1.0000	2	1.00	0.003	0.003
0.10	4	1	16 16	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.10	4	1	16	1.0000	0.0100	3	1.00	0.004	0.004
0.10	4	1	16	1.0000	0.0001	2	1.00	0.004	0.004
0.10	4	1	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	4	1	16 16	0.0100	1.0000	2	1.00	0.004	0.004
0.10	4	1	16	0.0100	0.0100	2	1.00	0.004	0.004
0.10	4	1	16	0.0100	0.0100	3	1.00	0.004	0.004
0.10	4	1	16	0.0100	0.0001	2	1.00	0.004	0.005
0.10	4	1	16 16	0.0100	0.0001 1.0000	3	1.00	0.004	0.005
0.10	4	1	16	0.0001	1.0000	3	1.00	0.004	0.005
0.10	4	1	16	0.0001	0.0100	2	1.00	0.004	0.005
0.10	4	1	16	0.0001	0.0100	3	1.00	0.004	0.005
0.10	4	1	16	0.0001	0.0001	2	1.00	0.004	0.006
0.10	4	1	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00	0.004	0.005
0.10	4	1	64	1.0000	1.0000	3	1.00	0.006	0.006
0.10	4	1	64	1.0000	0.0100	2	1.00	0.007	0.008
0.10	4	1	64	1.0000	0.0100	3	1.00	0.007	0.009
0.10	4	1	64 64	1.0000	0.0001	3	1.00	0.009	0.012
0.10	4	1	64	0.0100	1.0000	2	1.00	0.009	0.011
0.10	4	1	64	0.0100	1.0000	3	1.00	0.008	0.011
0.10	4	1	64	0.0100	0.0100	2	1.00	0.009	0.014
0.10	4	1	64	0.0100	0.0100	3	1.00	0.009	0.014
0.10	4	1	64	0.0100	0.0001	3	1.00	0.016	0.018
0.10	4	1	64	0.0001	1.0000	2	1.00	0.011	0.015
0.10	4	1	64	0.0001	1.0000	3	1.00	0.015	0.015
0.10	4	1	64	0.0001	0.0100	2	1.00	0.017	0.018
0.10	4	1	64	0.0001	0.0100	3	1.00	0.016	0.018
0.10	4	1	64	0.0001	0.0001	3	1.00	0.020	0.022
0.10	4	1	256	1.0000	1.0000	2	1.00	0.022	0.033
0.10	4	1	256	1.0000	1.0000	3	1.00	0.023	0.032
0.10	4	1	256 256	1.0000	0.0100	3	1.00	0.033	0.078
0.10	4	1	256	1.0000	0.0100	2	1.00	0.034	0.030
0.10	4	1	256	1.0000	0.0001	3	1.00	0.044	0.046
0.10	4	1	256	0.0100	1.0000	2	1.00	0.031	0.051
0.10	4	1	256	0.0100	1.0000	3	1.00	0.032	0.052
0.10	4	1	256 256	0.0100	0.0100	3	1.00	0.051	0.074
0.10	7	1	230	0.0100	0.0100		1.00	0.077	0.015

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	4	1	256	0.0100	0.0001	2	1.00	0.086	0.101
0.10	4	1	256	0.0100	0.0001	3	1.00	0.084	0.102
0.10	4	1	256	0.0001	1.0000	2	1.00	0.049	0.072
0.10	4	1	256 256	0.0001	1.0000 0.0100	3	1.00	0.048	0.067
0.10	4	1	256	0.0001	0.0100	3	1.00	0.058	0.097 0.083
0.10	4	1	256	0.0001	0.0001	2	1.00	0.039	0.003
0.10	4	1	256	0.0001	0.0001	3	1.00	0.076	0.102
0.10	4	4	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	4	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	4	4	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	4	4	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	4	4	1	1.0000	0.0001	2	1.00	0.002	0.003
0.10	4	4	1	1.0000	0.0001	3	1.00	0.002	0.003
0.10	4	4	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	4	4	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	4	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	4	4	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	4	4	1	0.0100	0.0001	3	1.00	0.003	0.004
0.10	4	4	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	4	4	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	4	4	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	4	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	4	4	1	0.0001	0.0001	2	1.00	0.003	0.004
0.10	4	4	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	4	4	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	4	4	4	1.0000	1.0000	3	1.00	0.003	0.004
0.10	4	4	4	1.0000	0.0100	2	1.00	0.003	0.042
0.10	4	4	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	4	4	4	1.0000	0.0001	3	1.00	0.003	0.003
0.10	4	4	4	0.0100	1.0000	2	1.00	0.003	0.003
0.10	4	4	4	0.0100	1.0000	3	1.00	0.003	0.003
0.10	4	4	4	0.0100	0.0100	2	1.00	0.003	0.006
0.10	4	4	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	4	4	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	4	4	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	4	4	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	4	4	4	0.0001	1.0000	3	1.00	0.003	0.003
0.10	4	4	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	4	4	4	0.0001	0.0100	3	1.00	0.003	0.003
0.10	4	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.10	4	4	16	1.0000	1.0000	2	1.00	0.003	0.004
0.10	4	4	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	4	4	16	1.0000	0.0100	2	1.00	0.005	0.005
0.10	4	4	16	1.0000	0.0100	3	1.00	0.005	0.005
0.10	4	4	16	1.0000	0.0001	2	1.00	0.005	0.006
0.10	4	4	16	1.0000	0.0001	3	1.00	0.005	0.006
0.10	4	4	16	0.0100	1.0000	2	1.00	0.005	0.005
0.10	4	4	16	0.0100	1.0000	3	1.00	0.004	0.005
0.10	4	4	16	0.0100	0.0100	2	1.00	0.004	0.006
0.10	4	4	16	0.0100	0.0100	3	1.00	0.004	0.006
0.10	4	4	16	0.0100	0.0001	3	1.00	0.006	0.006
0.10	4	4	16 16	0.0100	1.0000	2	1.00	0.005	0.007
0.10	4	4	16	0.0001	1.0000	3	1.00	0.006	0.006
0.10	4	4	16	0.0001	0.0100	2	1.00	0.004	0.006
0.10	4	4	16	0.0001	0.0100	3	1.00	0.004	0.007
0.10	4	4	16	0.0001	0.0001	2	1.00	0.005	0.006
0.10	4	4	16	0.0001	0.0001	3	1.00	0.004	0.007
0.10	4	4	64	1.0000	1.0000	2	1.00	0.006	0.007
0.10	4	4	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10	4	4	64	1.0000	0.0100	2	1.00	0.008	0.011
0.10	4	4	64	1.0000	0.0100	3	1.00	0.008	0.011
0.10	4	4	64	1.0000	0.0001	2	1.00	0.014	0.015
0.10	4	4	64	1.0000	0.0001	3	1.00	0.014	0.014
0.10	4	4	64	0.0100	1.0000	2	1.00	0.008	0.012
0.10	4	4	64 64	0.0100	1.0000	2	1.00	0.008	0.012
0.10	4	4	64	0.0100	0.0100	3	1.00	0.009	0.010
0.10	4	4	64	0.0100	0.0100	2	1.00	0.009	0.010
0.10	4	4	64	0.0100	0.0001	3	1.00	0.012	0.018
0.10	4	4	64	0.0001	1.0000	2	1.00	0.012	0.016
0.10	4	4	64	0.0001	1.0000	3	1.00	0.010	0.016

0.10	mul	m_1	m_2	\tau	TR	DTR	alg	SR	mint	maxt
0.10								1.00		
0.10		4	4							
O.10	0.10				0.0001	0.0001			0.014	0.016
O.10										
O.10										
0.10										
0.10										
0.10										
0.10										
0.10										
0.10										
0.10										
O.10										
O.10		4	4							
O.10					0.0001	1.0000			0.053	0.080
O.10										
O.10										
0.10										
O.10										
O.10										
O.10	0.10	4			1.0000	1.0000	3	1.00	0.003	0.003
O.10										
O.10										
O.10										
O.10										
O.10										
0.10		4								
O.10										
O.10										
0.10										
0.10										
O.10										
0.10		4					3			
O.10										
0.10										
0.10										
0.10										
0.10										
0.10										
0.10	0.10	4	16	4	1.0000	0.0001	3	1.00	0.003	0.003
0.10										
0.10 4 16 4 0.0100 0.0100 3 1.00 0.003 0.003 0.10 4 16 4 0.0100 0.0001 2 1.00 0.003 0.003 0.10 4 16 4 0.0100 0.0001 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 1.0000 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 1.0000 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 0.0100 2 1.00 0.004 0.004 0.10 4 16 4 0.0001 0.0100 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 0.0001 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 0.0001 3 1.00										
0.10 4 16 4 0.0100 0.0001 2 1.00 0.003 0.003 0.10 4 16 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 4 16 4 0.0001 1.0000 2 1.00 0.003 0.004 0.10 4 16 4 0.0001 1.0000 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 0.0100 2 1.00 0.004 0.004 0.10 4 16 4 0.0001 0.0100 3 1.00 0.004 0.004 0.10 4 16 4 0.0001 0.0001 3 1.00 0.003 0.005 0.10 4 16 4 0.0001 0.0001 3 1.00 0.003 0.004 0.10 4 16 16 1.0000 1.0000 3 1.0										
0.10 4 16 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 4 16 4 0.0001 1.0000 2 1.00 0.003 0.004 0.10 4 16 4 0.0001 1.0000 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 0.0100 2 1.00 0.004 0.004 0.10 4 16 4 0.0001 0.0100 3 1.00 0.004 0.004 0.10 4 16 4 0.0001 0.0001 2 1.00 0.003 0.005 0.10 4 16 4 0.0001 0.0001 3 1.00 0.003 0.004 0.10 4 16 16 1.0000 1.0000 2 1.00 0.003 0.004 0.10 4 16 16 1.0000 1.0000 3 1.										
0.10 4 16 4 0.0001 1.0000 2 1.00 0.003 0.004 0.10 4 16 4 0.0001 1.0000 3 1.00 0.003 0.004 0.10 4 16 4 0.0001 0.0100 2 1.00 0.004 0.004 0.10 4 16 4 0.0001 0.0100 3 1.00 0.004 0.004 0.10 4 16 4 0.0001 0.0001 2 1.00 0.003 0.005 0.10 4 16 4 0.0001 0.0001 3 1.00 0.003 0.004 0.10 4 16 16 1.0000 1.0000 2 1.00 0.003 0.004 0.10 4 16 16 1.0000 0.0100 3 1.00 0.003 0.004 0.10 4 16 16 1.0000 0.0100 3 1										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$					0.0001		-			0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.10		16	16	1.0000	0.0100	2	1.00	0.004	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.10 4 16 16 0.0001 1.0000 2 1.00 0.004 0.005 0.10 4 16 16 0.0001 1.0000 3 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0100 2 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0100 3 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0001 2 1.00 0.005 0.007										
0.10 4 16 16 0.0001 1.0000 3 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0100 2 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0100 3 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0001 2 1.00 0.005 0.007										
0.10 4 16 16 0.0001 0.0100 2 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0100 3 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0001 2 1.00 0.005 0.007										
0.10 4 16 16 0.0001 0.0100 3 1.00 0.004 0.006 0.10 4 16 16 0.0001 0.0001 2 1.00 0.005 0.007										
0.10 4 16 16 0.0001 0.0001 2 1.00 0.005 0.007										
0.10 4 16 16 0.0001 0.0001 3 1.00 0.005 0.006										
		4								

0.10	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	0.10	4	16	64	1.0000	1.0000	2	1.00	0.006	0.007
0.10	0.10	4	16	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10										0.008
O.10										0.010
O.10										
0.10										
0.10										
0.10										
O.10										
O.10		4								0.014
0.10	0.10	4	16	64	0.0100	0.0001	3	1.00	0.012	0.017
O.10										0.016
0.10										
0.10										
0.10										
0.10										
0.10										
0.10										
0.10										0.036
0.10		4	16	256			3		0.035	0.035
0.10										0.083
0.10										0.147
0.10										
0.10 4 16 256 0.0100 0.0100 3 1.00 0.049 0.051 0.10 4 16 256 0.0100 0.0001 2 1.00 0.058 0.065 0.10 4 16 256 0.0001 1.0000 2 1.00 0.048 0.053 0.10 4 16 256 0.0001 1.0000 3 1.00 0.048 0.053 0.10 4 16 256 0.0001 1.0000 3 1.00 0.059 0.097 0.10 4 16 256 0.0001 0.0100 3 1.00 0.059 0.109 0.10 4 16 256 0.0001 0.0001 3 1.00 0.059 0.122 0.10 4 64 1 1.0000 1.0000 3 1.00 0.003 0.003 0.10 4 64 1 1.0000 1.0000 3										
0.10										
0.10										
O.10										
0.10										0.053
0.10										0.053
0.10 4 16 256 0.0001 0.0001 2 1.00 0.080 0.123 0.10 4 16 256 0.0001 0.0001 3 1.00 0.079 0.122 0.10 4 64 1 1.0000 1.0000 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0100 1.0000 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 1.0000 3	0.10	4	16	256	0.0001	0.0100	2	1.00	0.059	0.097
0.10	0.10	4	16	256	0.0001	0.0100	3	1.00	0.059	0.100
0.10										0.123
0.10 4 64 1 1.0000 1.0000 3 1.00 0.003 0.004 0.10 4 64 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0100 1.0000 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 1.0000 3 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00										
0.10 4 64 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0100 1.0000 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 1.0000 3 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00										
0.10 4 64 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0100 1.0000 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 1.0000 3 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00										
0.10 4 64 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0100 1.0000 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 1.0000 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0100 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0100 3 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 1.0000 2 1.00										
0.10 4 64 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0100 1.0000 2 1.00 0.002 0.003 0.10 4 64 1 0.0100 1.0000 3 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 1.0000 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 1.0000 3 1.00										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.10	4	64	1	0.0100	1.0000		1.00	0.002	0.003
0.10 4 64 1 0.0100 0.0100 3 1.00 0.002 0.003 0.10 4 64 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 1.0000 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0100 2 1.00 0.002 0.003 0.10 4 64 1 0.0001 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0100 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0001 3 1.00	0.10	4	64	1	0.0100	1.0000	3	1.00	0.002	0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.003
0.10 4 64 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 1.0000 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 1.0000 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0100 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0100 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0001 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 1.0000 1.00 0.003 0.003 0.10 4 64 4 1.0000 1.0000 2 1.00 0										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.10 4 64 1 0.0001 1.0000 3 1.00 0.002 0.003 0.10 4 64 1 0.0001 0.0100 2 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0100 3 1.00 0.003 0.003 0.10 4 64 1 0.0001 0.0001 2 1.00 0.003 0.004 0.10 4 64 1 0.0001 0.0001 3 1.00 0.003 0.003 0.10 4 64 4 1.0000 1.0000 2 1.00 0.003 0.003 0.10 4 64 4 1.0000 1.0000 3 1.00 0.003 0.003 0.10 4 64 4 1.0000 1.0000 3 1.00 0.003 0.003 0.10 4 64 4 1.0000 0.0100 2 1.00										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.004
0.10 4 64 4 1.0000 1.0000 3 1.00 0.003 0.003 0.10 4 64 4 1.0000 0.0100 2 1.00 0.003 0.004 0.10 4 64 4 1.0000 0.0100 3 1.00 0.003 0.004 0.10 4 64 4 1.0000 0.0001 2 1.00 0.004 0.004 0.10 4 64 4 1.0000 0.0001 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 1.0000 2 1.00 0.003 0.004 0.10 4 64 4 0.0100 1.0000 3 1.00 0.003 0.004 0.10 4 64 4 0.0100 1.0000 3 1.00 0.003 0.004 0.10 4 64 4 0.0100 0.0100 2 1.00										0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.003
0.10 4 64 4 1.0000 0.0100 3 1.00 0.003 0.004 0.10 4 64 4 1.0000 0.0001 2 1.00 0.004 0.004 0.10 4 64 4 1.0000 0.0001 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 1.0000 2 1.00 0.003 0.004 0.10 4 64 4 0.0100 1.0000 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 2 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 2 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004										
0.10 4 64 4 1.0000 0.0001 2 1.00 0.004 0.004 0.10 4 64 4 1.0000 0.0001 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 1.0000 2 1.00 0.003 0.004 0.10 4 64 4 0.0100 1.0000 3 1.00 0.003 0.004 0.10 4 64 4 0.0100 0.0100 2 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004										
0.10 4 64 4 1.0000 0.0001 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 1.0000 2 1.00 0.003 0.004 0.10 4 64 4 0.0100 1.0000 3 1.00 0.003 0.004 0.10 4 64 4 0.0100 0.0100 2 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004										
0.10 4 64 4 0.0100 1.0000 2 1.00 0.003 0.004 0.10 4 64 4 0.0100 1.0000 3 1.00 0.003 0.004 0.10 4 64 4 0.0100 0.0100 2 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004										
0.10 4 64 4 0.0100 1.0000 3 1.00 0.003 0.004 0.10 4 64 4 0.0100 0.0100 2 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004 0.10 6 6 0.0100 0.0100 3 1.00 0.004 0.004										
0.10 4 64 4 0.0100 0.0100 2 1.00 0.004 0.004 0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004										0.004
0.10 4 64 4 0.0100 0.0100 3 1.00 0.004 0.004								1.00		0.004
0.10 4 64 4 0.0100 0.0001 2 1.00 0.004 0.004										0.004
	0.10	4	64	4	0.0100	0.0001	2	1.00	0.004	0.004
										0.004
										0.003
										0.003
										0.003
										0.004
										0.004
										0.003
										0.004
										0.004
0.10 4 64 16 1.0000 0.0100 3 1.00 0.004 0.004	0.10	4	64	16	1.0000	0.0100	3	1.00	0.004	0.004

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.10	4	64	16	1.0000	0.0001	2	1.00	0.004	0.005
0.10	4	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	4	64	16	0.0100	1.0000	2	1.00	0.004	0.004
0.10	4	64	16	0.0100	1.0000	3	1.00	0.004	0.004
0.10	4	64	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	4	64 64	16 16	0.0100	0.0100	3	1.00	0.004	0.005
0.10	4	64	16	0.0100	0.0001	3	1.00	0.004	0.004
0.10	4	64	16	0.0001	1.0000	2	1.00	0.004	0.003
0.10	4	64	16	0.0001	1.0000	3	1.00	0.004	0.005
0.10	4	64	16	0.0001	0.0100	2	1.00	0.004	0.005
0.10	4	64	16	0.0001	0.0100	3	1.00	0.004	0.005
0.10	4	64	16	0.0001	0.0001	2	1.00	0.005	0.006
0.10	4	64	16 64	1.0000	1.0000	3	1.00	0.005	0.005
0.10	4	64	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10	4	64	64	1.0000	0.0100	2	1.00	0.007	0.008
0.10	4	64	64	1.0000	0.0100	3	1.00	0.007	0.009
0.10	4	64	64	1.0000	0.0001	2	1.00	0.010	0.014
0.10	4	64	64	1.0000	0.0001	3	1.00	0.009	0.014
0.10	4	64	64	0.0100	1.0000	2	1.00	0.008	0.011
0.10	4	64 64	64 64	0.0100	1.0000 0.0100	3	1.00	0.008	0.012
0.10	4	64	64	0.0100	0.0100	3	1.00	0.012	0.015
0.10	4	64	64	0.0100	0.0001	2	1.00	0.011	0.017
0.10	4	64	64	0.0100	0.0001	3	1.00	0.012	0.017
0.10	4	64	64	0.0001	1.0000	2	1.00	0.010	0.012
0.10	4	64	64	0.0001	1.0000	3	1.00	0.010	0.012
0.10	4	64	64	0.0001	0.0100	2	1.00	0.011	0.017 0.018
0.10	4	64	64	0.0001	0.0001	2	1.00	0.011	0.013
0.10	4	64	64	0.0001	0.0001	3	1.00	0.013	0.020
0.10	4	64	256	1.0000	1.0000	2	1.00	0.022	0.033
0.10	4	64	256	1.0000	1.0000	3	1.00	0.023	0.033
0.10	4	64	256	1.0000	0.0100	2	1.00	0.039	0.050
0.10	4	64	256 256	1.0000	0.0100	3	1.00	0.043	0.051
0.10	4	64	256	1.0000	0.0001	3	1.00	0.048	0.100
0.10	4	64	256	0.0100	1.0000	2	1.00	0.032	0.038
0.10	4	64	256	0.0100	1.0000	3	1.00	0.032	0.034
0.10	4	64	256	0.0100	0.0100	2	1.00	0.047	0.074
0.10	4	64	256	0.0100	0.0100	3	1.00	0.048	0.077
0.10	4	64	256	0.0100	0.0001	2	1.00	0.095	0.101
0.10	4	64 64	256 256	0.0100	0.0001 1.0000	3	1.00	0.087	0.101
0.10	4	64	256	0.0001	1.0000	3	1.00	0.056	0.080
0.10	4	64	256	0.0001	0.0100	2	1.00	0.061	0.097
0.10	4	64	256	0.0001	0.0100	3	1.00	0.060	0.097
0.10	4	64	256	0.0001	0.0001	2	1.00	0.080	0.126
0.10	4	64	256	0.0001	0.0001	3	1.00	0.092	0.127
0.10	4	256 256	1	1.0000	1.0000	3	1.00	0.003	0.004
0.10	4	256	1	1.0000	0.0100	2	1.00	0.002	0.004
0.10	4	256	1	1.0000	0.0100	3	1.00	0.002	0.003
0.10	4	256	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	4	256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	4	256	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	4	256 256	1	0.0100	1.0000 0.0100	3	1.00	0.003	0.003 0.003
0.10	4	256	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	4	256	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	4	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	4	256	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	4	256	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	4	256	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	4	256 256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	4	256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	4	256	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	4	256	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	4	256	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	4	256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	4	256	4	1.0000	0.0001	2	1.00	0.004	0.004
0.10	4	256 256	4	1.0000 0.0100	1.00001	3	1.00	0.004	0.004
0.10	4	256	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10		250		0.0100	1.0000		1.00	5.505	0.001

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	4	256	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	4	256	4	0.0100	0.0100	3	1.00	0.004	0.004
0.10	4	256	4	0.0100	0.0001	2	1.00	0.004	0.004
0.10	4	256	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	4	256	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	4	256	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	4	256	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	4	256	4	0.0001	0.0100	3	1.00	0.004	0.004
0.10	4	256	4	0.0001	0.0001	2	1.00	0.003	0.004
0.10	4	256 256	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00	0.003	0.004
0.10	4	256	16	1.0000	1.0000	3	1.00	0.003	0.003
0.10	4	256	16	1.0000	0.0100	2	1.00	0.005	0.005
0.10	4	256	16	1.0000	0.0100	3	1.00	0.005	0.005
0.10	4	256	16	1.0000	0.0001	2	1.00	0.005	0.006
0.10	4	256	16	1.0000	0.0001	3	1.00	0.006	0.006
0.10	4	256	16	0.0100	1.0000	2	1.00	0.005	0.005
0.10	4	256	16	0.0100	1.0000	3	1.00	0.005	0.005
0.10	4	256	16	0.0100	0.0100	2	1.00	0.005	0.006
0.10	4	256	16	0.0100	0.0100	3	1.00	0.005	0.006
0.10	4	256	16	0.0100	0.0001	2	1.00	0.006	0.006
0.10	4	256 256	16 16	0.0100	1.00001	2	1.00	0.006	0.006
0.10	4	256	16	0.0001	1.0000	3	1.00	0.006	0.007
0.10	4	256	16	0.0001	0.0100	2	1.00	0.004	0.006
0.10	4	256	16	0.0001	0.0100	3	1.00	0.004	0.007
0.10	4	256	16	0.0001	0.0001	2	1.00	0.005	0.006
0.10	4	256	16	0.0001	0.0001	3	1.00	0.005	0.005
0.10	4	256	64	1.0000	1.0000	2	1.00	0.006	0.006
0.10	4	256	64	1.0000	1.0000	3	1.00	0.006	0.006
0.10	4	256	64	1.0000	0.0100	2	1.00	0.008	0.009
0.10	4	256	64	1.0000	0.0100	3	1.00	0.008	0.008
0.10	4	256	64	1.0000	0.0001	2	1.00	0.009	0.011
0.10	4	256	64	1.0000	0.0001	3	1.00	0.009	0.010
0.10	4	256 256	64 64	0.0100	1.0000	3	1.00	0.007	0.009
0.10	4	256	64	0.0100	1.0000 0.0100	2	1.00	0.007	0.008
0.10	4	256	64	0.0100	0.0100	3	1.00	0.010	0.011
0.10	4	256	64	0.0100	0.0001	2	1.00	0.010	0.011
0.10	4	256	64	0.0100	0.0001	3	1.00	0.011	0.017
0.10	4	256	64	0.0001	1.0000	2	1.00	0.012	0.016
0.10	4	256	64	0.0001	1.0000	3	1.00	0.015	0.016
0.10	4	256	64	0.0001	0.0100	2	1.00	0.016	0.018
0.10	4	256	64	0.0001	0.0100	3	1.00	0.012	0.018
0.10	4	256	64	0.0001	0.0001	2	1.00	0.020	0.022
0.10	4	256	64	0.0001	0.0001	3	1.00	0.015	0.022
0.10	4	256	256	1.0000	1.0000	2	1.00	0.021	0.033
0.10	4	256	256	1.0000	1.0000	3	1.00	0.021	0.033
0.10	4	256 256	256 256	1.0000	0.0100	3	1.00	0.043	0.053
0.10	4	256	256	1.0000	0.0100	2	1.00	0.038	0.053
0.10	4	256	256	1.0000	0.0001	3	1.00	0.007	0.074
0.10	4	256	256	0.0100	1.0000	2	1.00	0.033	0.053
0.10	4	256	256	0.0100	1.0000	3	1.00	0.033	0.053
0.10	4	256	256	0.0100	0.0100	2	1.00	0.059	0.078
0.10	4	256	256	0.0100	0.0100	3	1.00	0.063	0.078
0.10	4	256	256	0.0100	0.0001	2	1.00	0.086	0.097
0.10	4	256	256	0.0100	0.0001	3	1.00	0.087	0.098
0.10	4	256	256	0.0001	1.0000	2	1.00	0.052	0.079
0.10	4	256	256	0.0001	1.0000	3	1.00	0.054	0.078
0.10	4	256 256	256 256	0.0001	0.0100	3	1.00	0.059	0.071
0.10	4	256	256	0.0001	0.0100	2	1.00	0.059	0.064
0.10	4	256	256	0.0001	0.0001	3	1.00	0.077	0.095
0.10	16	1	1	1.0000	1.0000	2	1.00	0.003	0.104
0.10	16	1	1	1.0000	1.0000	3	1.00	0.003	0.004
0.10	16	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	16	1	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	16	1	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	16	1	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	16	1	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	16	1	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	16	1	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	16	1	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	16	1	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	16	1	1	0.0100	0.0001	3	1.00	0.003	0.003

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.10	16	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	16	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	16	1	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	16	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	16	1	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	16 16	1	1 4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	16	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	16	1	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	16	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	16	1	4	1.0000	0.0001	2	1.00	0.004	0.004
0.10	16	1	4	1.0000	1.0000	3	1.00	0.004	0.004
0.10	16 16	1	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	16	1	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	16	1	4	0.0100	0.0100	3	1.00	0.003	0.003
0.10	16	1	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	16	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	16	1	4	0.0001	1.0000	2	1.00	0.003	0.003
0.10	16 16	1	4	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.10	16	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	16	1	4	0.0001	0.0001	2	1.00	0.003	0.004
0.10	16	1	4	0.0001	0.0001	3	1.00	0.003	0.004
0.10	16	1	16	1.0000	1.0000	2	1.00	0.003	0.005
0.10	16	1	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	16	1	16	1.0000	0.0100	2	1.00	0.004	0.004
0.10	16 16	1	16 16	1.0000	0.0100	3 2	1.00	0.004	0.005
0.10	16	1	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	16	1	16	0.0100	1.0000	2	1.00	0.004	0.005
0.10	16	1	16	0.0100	1.0000	3	1.00	0.004	0.009
0.10	16	1	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	16	1	16	0.0100	0.0100	3	1.00	0.004	0.004
0.10	16 16	1	16 16	0.0100	0.0001	3	1.00	0.004	0.006
0.10	16	1	16	0.0100	1.0000	2	1.00	0.004	0.005
0.10	16	1	16	0.0001	1.0000	3	1.00	0.004	0.005
0.10	16	1	16	0.0001	0.0100	2	1.00	0.005	0.006
0.10	16	1	16	0.0001	0.0100	3	1.00	0.006	0.006
0.10	16	1	16	0.0001	0.0001	2	1.00	0.006	0.008
0.10	16 16	1	16 64	0.0001 1.0000	1.0000	3	1.00	0.006	0.008
0.10	16	1	64	1.0000	1.0000	3	1.00	0.007	0.008
0.10	16	1	64	1.0000	0.0100	2	1.00	0.007	0.009
0.10	16	1	64	1.0000	0.0100	3	1.00	0.007	0.008
0.10	16	1	64	1.0000	0.0001	2	1.00	0.009	0.010
0.10	16	1	64	1.0000	0.0001	3	1.00	0.009	0.010
0.10	16	1	64	0.0100	1.0000	2	1.00	0.007	0.008
0.10	16 16	1	64	0.0100	1.0000 0.0100	3	1.00	0.007	0.009
0.10	16	1	64	0.0100	0.0100	3	1.00	0.009	0.010
0.10	16	1	64	0.0100	0.0001	2	1.00	0.011	0.018
0.10	16	1	64	0.0100	0.0001	3	1.00	0.011	0.017
0.10	16	1	64	0.0001	1.0000	2	1.00	0.010	0.015
0.10	16	1	64	0.0001	1.0000	3	1.00	0.010	0.013
0.10	16 16	1	64 64	0.0001	0.0100	3	1.00	0.012 0.012	0.014
0.10	16	1	64	0.0001	0.0100	2	1.00	0.012	0.013
0.10	16	1	64	0.0001	0.0001	3	1.00	0.013	0.015
0.10	16	1	256	1.0000	1.0000	2	1.00	0.021	0.024
0.10	16	1	256	1.0000	1.0000	3	1.00	0.021	0.027
0.10	16	1	256	1.0000	0.0100	2	1.00	0.034	0.038
0.10	16 16	1	256 256	1.0000	0.0100	3	1.00	0.034	0.035
0.10	16	1	256	1.0000	0.0001	3	1.00	0.047	0.050
0.10	16	1	256	0.0100	1.0000	2	1.00	0.034	0.035
0.10	16	1	256	0.0100	1.0000	3	1.00	0.035	0.036
0.10	16	1	256	0.0100	0.0100	2	1.00	0.047	0.056
0.10	16	1	256	0.0100	0.0100	3	1.00	0.048	0.075
0.10	16	1	256	0.0100	0.0001	2	1.00	0.064	0.068
0.10	16	1	256	0.0100	0.0001 1.0000	3 2	1.00	0.064	0.068
	16						1.00	0.030	0.000
0.10	16 16	1	256 256		1.0000		1.00	0.049	
	16 16		256 256 256	0.0001 0.0001 0.0001		3	1.00	0.049 0.060	0.080 0.098

$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.121 0.107 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.003 0.003 0.003 0.003 0.003 0.003 0.003 0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.003 0.003 0.003 0.003 0.003 0.003 0.003
0.10 16 4 1 1.0000 0.0001 2 1.00 0.003 0.10 16 4 1 1.0000 0.0001 3 1.00 0.003 0.10 16 4 1 0.0100 1.0000 2 1.00 0.003 0.10 16 4 1 0.0100 1.0000 3 1.00 0.003 0.10 16 4 1 0.0100 0.0100 2 1.00 0.003 0.10 16 4 1 0.0100 0.0100 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001	0.003 0.003 0.003 0.003 0.003 0.003 0.003
0.10 16 4 1 1.0000 0.0001 3 1.00 0.003 0.10 16 4 1 0.0100 1.0000 2 1.00 0.003 0.10 16 4 1 0.0100 1.0000 3 1.00 0.003 0.10 16 4 1 0.0100 0.0100 2 1.00 0.003 0.10 16 4 1 0.0100 0.0100 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003	0.003 0.003 0.003 0.003 0.003 0.003
0.10 16 4 1 0.0100 1.0000 2 1.00 0.003 0.10 16 4 1 0.0100 1.0000 3 1.00 0.003 0.10 16 4 1 0.0100 0.0100 2 1.00 0.003 0.10 16 4 1 0.0100 0.0100 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003	0.003 0.003 0.003 0.003 0.003
0.10 16 4 1 0.0100 0.0100 2 1.00 0.003 0.10 16 4 1 0.0100 0.0100 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003	0.003 0.003 0.003
0.10 16 4 1 0.0100 0.0100 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003	0.003 0.003
0.10 16 4 1 0.0100 0.0001 2 1.00 0.003 0.10 16 4 1 0.0100 0.0001 3 1.00 0.003	0.003
0.10 16 4 1 0.0100 0.0001 3 1.00 0.003	1
	1 ().()()4
1 0 10 1 16 1 1 1 1 0 0 0 0 1 1 0 0 0 0	
0.10 16 4 1 0.0001 1.0000 2 1.00 0.003 0.10 16 4 1 0.0001 1.0000 3 1.00 0.003	0.003
0.10 16 4 1 0.0001 1.0000 3 1.00 0.003	0.003
0.10 16 4 1 0.0001 0.0100 2 1.00 0.003	0.003
0.10 16 4 1 0.0001 0.0001 2 1.00 0.003	0.003
0.10 16 4 1 0.0001 0.0001 3 1.00 0.003	0.003
0.10 16 4 4 1.0000 1.0000 2 1.00 0.003	0.003
0.10 16 4 4 1.0000 1.0000 3 1.00 0.003	0.003
0.10 16 4 4 1.0000 0.0100 2 1.00 0.003	0.004
0.10 16 4 4 1.0000 0.0100 3 1.00 0.003	0.004
0.10 16 4 4 1.0000 0.0001 2 1.00 0.004	0.004
0.10 16 4 4 1.0000 0.0001 3 1.00 0.004 0.10 16 4 4 0.0100 1.0000 2 1.00 0.003	0.004
0.10 16 4 4 0.0100 1.0000 2 1.00 0.003	0.004
0.10 16 4 4 0.0100 1.0000 3 1.00 0.003	0.003
0.10 16 4 4 0.0100 0.0100 3 1.00 0.003	0.004
0.10 16 4 4 0.0100 0.0001 2 1.00 0.004	0.004
0.10 16 4 4 0.0100 0.0001 3 1.00 0.004	0.004
0.10 16 4 4 0.0001 1.0000 2 1.00 0.004	0.004
0.10 16 4 4 0.0001 1.0000 3 1.00 0.004	0.004
0.10 16 4 4 0.0001 0.0100 2 1.00 0.003	0.004
0.10 16 4 4 0.0001 0.0100 3 1.00 0.003	0.004
0.10 16 4 4 0.0001 0.0001 2 1.00 0.003 0.10 16 4 4 0.0001 0.0001 3 1.00 0.004	0.004
0.10 16 4 4 0.0001 0.0001 3 1.00 0.004 0.10 16 4 16 1.0000 1.0000 2 1.00 0.003	0.007
0.10 16 4 16 1.0000 1.0000 2 1.00 0.003	0.004
0.10 16 4 16 1.0000 0.0100 2 1.00 0.004	0.005
0.10 16 4 16 1.0000 0.0100 3 1.00 0.004	0.005
0.10 16 4 16 1.0000 0.0001 2 1.00 0.004	0.006
0.10 16 4 16 1.0000 0.0001 3 1.00 0.004	0.006
0.10 16 4 16 0.0100 1.0000 2 1.00 0.004	0.005
0.10 16 4 16 0.0100 1.0000 3 1.00 0.004	0.005
0.10 16 4 16 0.0100 0.0100 2 1.00 0.004	0.006
0.10 16 4 16 0.0100 0.0100 3 1.00 0.004 0.10 16 4 16 0.0100 0.0001 2 1.00 0.005	0.005
0.10 16 4 16 0.0100 0.0001 2 1.00 0.005 0.10 16 4 16 0.0100 0.0001 3 1.00 0.004	0.006
0.10 16 4 16 0.0100 0.0001 3 1.00 0.004	0.006
0.10 16 4 16 0.0001 1.0000 2 1.00 0.004	0.006
0.10 16 4 16 0.0001 0.0100 2 1.00 0.004	0.006
0.10 16 4 16 0.0001 0.0100 3 1.00 0.004	0.007
0.10 16 4 16 0.0001 0.0001 2 1.00 0.006	0.007
0.10	0.008
0.10 16 4 64 1.0000 1.0000 2 1.00 0.006	0.008
0.10 16 4 64 1.0000 1.0000 3 1.00 0.006 0.10 16 4 64 1.0000 0.0100 2 1.00 0.007	0.008
0.10 16 4 64 1.0000 0.0100 2 1.00 0.007 0.10 16 4 64 1.0000 0.0100 3 1.00 0.008	0.009
0.10 16 4 64 1.0000 0.0100 3 1.00 0.008	0.009
0.10 16 4 64 1.0000 0.0001 2 1.00 0.009	0.010
0.10 16 4 64 0.0100 1.0000 2 1.00 0.007	0.009
0.10 16 4 64 0.0100 1.0000 3 1.00 0.007	0.009
0.10 16 4 64 0.0100 0.0100 2 1.00 0.009	0.011
0.10 16 4 64 0.0100 0.0100 3 1.00 0.009	0.011
0.10 16 4 64 0.0100 0.0001 2 1.00 0.012	0.018
0.10 16 4 64 0.0100 0.0001 3 1.00 0.011	0.017
0.10 16 4 64 0.0001 1.0000 2 1.00 0.012	0.016
0.10 16 4 64 0.0001 1.0000 3 1.00 0.011 0.10 16 4 64 0.0001 0.0100 2 1.00 0.017	0.016
0.10 16 4 64 0.0001 0.0100 2 1.00 0.017	0.018
0.10 16 4 64 0.0001 0.0001 2 1.00 0.020	0.018
0.10 16 4 64 0.0001 0.0001 3 1.00 0.021	0.021
0.10 16 4 256 1.0000 1.0000 2 1.00 0.031	0.032
0.10 16 4 256 1.0000 1.0000 3 1.00 0.031	0.033

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	16	4	256	1.0000	0.0100	2	1.00	0.042	0.050
0.10	16	4	256	1.0000	0.0100	3	1.00	0.045	0.051
0.10	16 16	4	256 256	1.0000	0.0001	3	1.00	0.052	0.072 0.073
0.10	16	4	256	0.0100	1.0000	2	1.00	0.033	0.050
0.10	16	4	256	0.0100	1.0000	3	1.00	0.033	0.040
0.10	16	4	256	0.0100	0.0100	2	1.00	0.047	0.078
0.10	16 16	4	256 256	0.0100	0.0100	3	1.00	0.046	0.077
0.10	16	4	256	0.0100	0.0001	3	1.00	0.083	0.101
0.10	16	4	256	0.0001	1.0000	2	1.00	0.067	0.080
0.10	16	4	256	0.0001	1.0000	3	1.00	0.078	0.080
0.10	16 16	4	256 256	0.0001	0.0100	3	1.00	0.057	0.097
0.10	16	4	256	0.0001	0.0001	2	1.00	0.038	0.108
0.10	16	4	256	0.0001	0.0001	3	1.00	0.073	0.106
0.10	16	16	1	1.0000	1.0000	2	1.00	0.003	0.004
0.10	16 16	16 16	1	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.10	16	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	16	16	1	1.0000	0.0001	2	1.00	0.003	0.004
0.10	16	16	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	16 16	16 16	1	0.0100	1.0000	3	1.00	0.003	0.003
0.10	16	16	1	0.0100	1.0000 0.0100	2	1.00	0.003	0.003
0.10	16	16	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	16	16	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	16	16	1	0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.10	16 16	16 16	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	16	16	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	16	16	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	16	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	16 16	16 16	1 4	0.0001 1.0000	0.0001 1.0000	3 2	1.00	0.003	0.003
0.10	16	16	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	16	16	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	16	16	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	16 16	16 16	4	1.0000	0.0001	3	1.00	0.003	0.004
0.10	16	16	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	16	16	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	16	16	4	0.0100	0.0100	2	1.00	0.004	0.004
0.10	16 16	16 16	4	0.0100	0.0100	3	1.00	0.004	0.004
0.10	16	16	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	16	16	4	0.0001	1.0000	2	1.00	0.004	0.004
0.10	16	16	4	0.0001	1.0000	3	1.00	0.004	0.004
0.10	16	16	4	0.0001	0.0100	2	1.00	0.004	0.004
0.10	16 16	16 16	4	0.0001	0.0100	3	1.00	0.004	0.004
0.10	16	16	4	0.0001	0.0001	3	1.00	0.004	0.004
0.10	16	16	16	1.0000	1.0000	2	1.00	0.004	0.004
0.10	16	16	16	1.0000	1.0000	3	1.00	0.004	0.004
0.10	16 16	16 16	16 16	1.0000 1.0000	0.0100	3	1.00	0.004	0.005 0.005
0.10	16	16	16	1.0000	0.0001	2	1.00	0.004	0.005
0.10	16	16	16	1.0000	0.0001	3	1.00	0.004	0.006
0.10	16	16	16	0.0100	1.0000	2	1.00	0.005	0.005
0.10	16 16	16 16	16 16	0.0100	1.0000 0.0100	2	1.00	0.005	0.005 0.006
0.10	16	16	16	0.0100	0.0100	3	1.00	0.005	0.006
0.10	16	16	16	0.0100	0.0001	2	1.00	0.004	0.006
0.10	16	16	16	0.0100	0.0001	3	1.00	0.004	0.006
0.10	16 16	16	16	0.0001	1.0000	2	1.00	0.004	0.005 0.005
0.10	16	16 16	16 16	0.0001	0.0100	2	1.00	0.004	0.005
0.10	16	16	16	0.0001	0.0100	3	1.00	0.004	0.005
0.10	16	16	16	0.0001	0.0001	2	1.00	0.005	0.005
0.10	16	16	16 64	0.0001	0.0001	3	1.00	0.005	0.005
0.10	16 16	16 16	64	1.0000	1.0000	2	1.00	0.006	0.006 0.007
0.10	16	16	64	1.0000	0.0100	2	1.00	0.007	0.007
0.10	16	16	64	1.0000	0.0100	3	1.00	0.008	0.008
0.10	16	16	64	1.0000	0.0001	2	1.00	0.009	0.010
0.10	16	16	64	1.0000	0.0001	3	1.00	0.009	0.010

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	16	16	64	0.0100	1.0000	2	1.00	0.008	0.009
0.10	16	16	64	0.0100	1.0000	3	1.00	0.008	0.008
0.10	16	16	64	0.0100	0.0100	2	1.00	0.009	0.011
0.10	16	16	64	0.0100	0.0100	3	1.00	0.009	0.010
0.10	16 16	16 16	64	0.0100	0.0001	3	1.00	0.011	0.017
0.10	16	16	64	0.0100	1.0000	2	1.00	0.011	0.017
0.10	16	16	64	0.0001	1.0000	3	1.00	0.010	0.016
0.10	16	16	64	0.0001	0.0100	2	1.00	0.012	0.018
0.10	16	16	64	0.0001	0.0100	3	1.00	0.012	0.018
0.10	16	16	64	0.0001	0.0001	2	1.00	0.015	0.023
0.10	16	16	64	0.0001	0.0001	3	1.00	0.014	0.023
0.10	16	16	256	1.0000	1.0000	2	1.00	0.026	0.034
0.10	16 16	16 16	256 256	1.0000	1.0000 0.0100	3	1.00	0.027	0.034 0.075
0.10	16	16	256	1.0000	0.0100	3	1.00	0.040	0.073
0.10	16	16	256	1.0000	0.0001	2	1.00	0.048	0.071
0.10	16	16	256	1.0000	0.0001	3	1.00	0.048	0.070
0.10	16	16	256	0.0100	1.0000	2	1.00	0.034	0.037
0.10	16	16	256	0.0100	1.0000	3	1.00	0.033	0.037
0.10	16	16	256	0.0100	0.0100	2	1.00	0.045	0.048
0.10	16	16	256	0.0100	0.0100	3	1.00	0.044	0.047
0.10	16 16	16	256 256	0.0100	0.0001	2	1.00	0.063	0.076
0.10	16	16 16	256	0.0100	1.0000	2	1.00	0.064	0.086
0.10	16	16	256	0.0001	1.0000	3	1.00	0.053	0.056
0.10	16	16	256	0.0001	0.0100	2	1.00	0.064	0.067
0.10	16	16	256	0.0001	0.0100	3	1.00	0.064	0.067
0.10	16	16	256	0.0001	0.0001	2	1.00	0.073	0.093
0.10	16	16	256	0.0001	0.0001	3	1.00	0.074	0.086
0.10	16	64	1	1.0000	1.0000	2	1.00	0.002	0.003
0.10	16	64	1	1.0000	1.0000	3	1.00	0.002	0.003
0.10	16 16	64	1	1.0000	0.0100	2	1.00	0.002	0.003
0.10	16	64	1	1.0000	0.0001	2	1.00	0.002	0.003
0.10	16	64	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	16	64	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	16	64	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	16	64	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	16	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	16	64	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	16 16	64	1	0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.10	16	64	1	0.0001	1.0000	3	1.00	0.002	0.003
0.10	16	64	1	0.0001	0.0100	2	1.00	0.002	0.003
0.10	16	64	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	16	64	1	0.0001	0.0001	2	1.00	0.002	0.003
0.10	16	64	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	16	64	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	16	64	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	16	64	4	1.0000	0.0100	2	1.00	0.003	0.006
0.10	16 16	64	4	1.0000	0.0100	3	1.00	0.003	0.006
0.10	16	64	4	1.0000	0.0001	3	1.00	0.004	0.004
0.10	16	64	4	0.0100	1.0000	2	1.00	0.004	0.004
0.10	16	64	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	16	64	4	0.0100	0.0100	2	1.00	0.004	0.004
0.10	16	64	4	0.0100	0.0100	3	1.00	0.004	0.004
0.10	16	64	4	0.0100	0.0001	2	1.00	0.004	0.004
0.10	16	64	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	16 16	64	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	16	64	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	16	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	16	64	4	0.0001	0.0001	2	1.00	0.004	0.004
0.10	16	64	4	0.0001	0.0001	3	1.00	0.004	0.004
0.10	16	64	16	1.0000	1.0000	2	1.00	0.004	0.004
0.10	16	64	16	1.0000	1.0000	3	1.00	0.004	0.004
0.10	16	64	16	1.0000	0.0100	2	1.00	0.004	0.005
0.10	16 16	64	16 16	1.0000	0.0100	2	1.00	0.004	0.005
0.10	16	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	16	64	16	0.0100	1.0000	2	1.00	0.004	0.005
							1.00	0.005	
0.10	16	64	16	0.0100	1.0000	3	1.00	0.005	0.005
0.10	16 16	64	16 16	0.0100	0.0100	2 3	1.00	0.003	0.003

O.10	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10										
O.10										
O.10										
O.10										
O.10										
O.10										
O.10										
O.10										
No. 10							2		0.008	
No. 10										
0.10										
Description Color Color										
O.10										
Description Color Color										
O.10										
December 2										
O 10										
0.10	0.10	16	64	64	0.0001	1.0000	3	1.00	0.012	0.016
0.10										
0.10										
0.10										
0.10	0.10	16	64	256	1.0000	1.0000	2	1.00	0.021	0.033
0.10										
0.10										
0.10										
0.10										
0.10										
0.10										
0.10										
0.10 16 64 256 0.0001 1.0000 2 1.00 0.049 0.078 0.10 16 64 256 0.0001 1.0000 3 1.00 0.050 0.077 0.10 16 64 256 0.0001 0.0100 2 1.00 0.058 0.066 0.10 16 64 256 0.0001 0.0001 2 1.00 0.078 0.083 0.10 16 64 256 0.0001 0.0001 3 1.00 0.076 0.104 0.10 16 256 1 1.0000 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001										
0.10 16 64 256 0.0001 1.0000 3 1.00 0.050 0.077 0.10 16 64 256 0.0001 0.0100 2 1.00 0.058 0.065 0.10 16 64 256 0.0001 0.0010 3 1.00 0.059 0.066 0.10 16 64 256 0.0001 0.0001 2 1.00 0.076 0.104 0.10 16 64 256 0.0001 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001										
0.10 16 64 256 0.0001 0.0100 2 1.00 0.058 0.065 0.10 16 64 256 0.0001 0.0100 3 1.00 0.059 0.066 0.10 16 64 256 0.0001 0.0001 2 1.00 0.078 0.083 0.10 16 64 256 0.0001 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3										
0.10 16 64 256 0.0001 0.0100 3 1.00 0.059 0.066 0.10 16 64 256 0.0001 0.0001 2 1.00 0.078 0.083 0.10 16 64 256 0.0001 0.0001 3 1.00 0.076 0.104 0.10 16 256 1 1.0000 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3<										
0.10 16 64 256 0.0001 0.0001 3 1.00 0.076 0.104 0.10 16 256 1 1.0000 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 3 <td></td>										
0.10 16 256 1 1.0000 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 3 <td></td> <td></td> <td></td> <td></td> <td>0.0001</td> <td>0.0001</td> <td></td> <td></td> <td></td> <td></td>					0.0001	0.0001				
0.10 16 256 1 1.0000 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 3 <td></td>										
0.10 16 256 1 1.0000 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 1.00100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0001 1.0000 2 <td></td>										
0.10 16 256 1 1.0000 0.0100 3 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 0.0001 1.0000 3 <td></td>										
0.10 16 256 1 1.0000 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0001 1.0000 3 1.00 0.002 0.003 0.10 16 256 1 0.0001 0.0100 2 <td></td> <td></td> <td></td> <td></td> <td></td> <td>0.0100</td> <td></td> <td></td> <td></td> <td></td>						0.0100				
0.10 16 256 1 0.0100 1.0000 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 1.0000 3 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0100 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 2 1.00 0.003 0.003 0.10 16 256 1 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 1 0.0001 1.0000 2 1.00 0.002 0.003 0.10 16 256 1 0.0001 0.0100 2 1.00 0.002 0.003 0.10 16 256 1 0.0001 0.0100 3 <td></td>										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.10	16	256	1	0.0001	0.0100	2	1.00	0.002	0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$				4						0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.10 16 256 4 0.0100 1.0000 3 1.00 0.003 0.004 0.10 16 256 4 0.0100 0.0100 2 1.00 0.003 0.003 0.10 16 256 4 0.0100 0.0100 3 1.00 0.003 0.003 0.10 16 256 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 16 256 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 4 0.0001 1.0000 2 1.00 0.003 0.004										
0.10 16 256 4 0.0100 0.0100 3 1.00 0.003 0.003 0.10 16 256 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 16 256 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 4 0.0001 1.0000 2 1.00 0.003 0.004	0.10	16	256	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10 16 256 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 16 256 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 4 0.0001 1.0000 2 1.00 0.003 0.004										
0.10 16 256 4 0.0100 0.0001 3 1.00 0.003 0.003 0.10 16 256 4 0.0001 1.0000 2 1.00 0.003 0.004										
0.10 16 256 4 0.0001 1.0000 2 1.00 0.003 0.004										
0.10 16 256 4 0.0001 1.0000 3 1.00 0.003 0.004										
	0.10	16	256	4	0.0001	1.0000	3	1.00	0.003	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	16	256	4	0.0001	0.0100	2	1.00	0.003	0.003
0.10	16	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	16	256	4	0.0001	0.0001	2	1.00	0.003	0.004
0.10	16	256 256	4	0.0001 1.0000	0.0001	3	1.00	0.003	0.004
0.10	16 16	256	16 16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	16	256	16	1.0000	0.0100	2	1.00	0.003	0.004
0.10	16	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	16	256	16	1.0000	0.0001	2	1.00	0.006	0.006
0.10	16	256	16	1.0000	0.0001	3	1.00	0.004	0.006
0.10	16	256	16	0.0100	1.0000	2	1.00	0.004	0.005
0.10	16	256	16	0.0100	1.0000	3	1.00	0.004	0.005
0.10	16	256	16	0.0100	0.0100	2	1.00	0.004	0.007
0.10	16	256 256	16	0.0100	0.0100	3	1.00	0.004	0.008
0.10	16 16	256	16 16	0.0100	0.0001	3	1.00	0.005	0.006
0.10	16	256	16	0.0100	1.0000	2	1.00	0.005	0.006
0.10	16	256	16	0.0001	1.0000	3	1.00	0.005	0.006
0.10	16	256	16	0.0001	0.0100	2	1.00	0.006	0.006
0.10	16	256	16	0.0001	0.0100	3	1.00	0.006	0.007
0.10	16	256	16	0.0001	0.0001	2	1.00	0.005	0.007
0.10	16	256	16	0.0001	0.0001	3	1.00	0.005	0.007
0.10	16	256	64	1.0000	1.0000	2	1.00	0.006	0.007
0.10	16	256	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10	16 16	256 256	64 64	1.0000	0.0100 0.0100	2	1.00	0.008	0.009
0.10	16	256	64	1.0000	0.0100	3	1.00	0.008	0.009
0.10	16	256	64	1.0000	0.0001	3	1.00	0.009	0.011
0.10	16	256	64	0.0100	1.0000	2	1.00	0.010	0.012
0.10	16	256	64	0.0100	1.0000	3	1.00	0.008	0.009
0.10	16	256	64	0.0100	0.0100	2	1.00	0.010	0.012
0.10	16	256	64	0.0100	0.0100	3	1.00	0.010	0.012
0.10	16	256	64	0.0100	0.0001	2	1.00	0.011	0.014
0.10	16	256	64	0.0100	0.0001	3	1.00	0.011	0.014
0.10	16	256	64	0.0001	1.0000	2	1.00	0.010	0.016
0.10	16	256 256	64	0.0001	1.0000 0.0100	3	1.00	0.010	0.012
0.10	16	256	64	0.0001	0.0100	3	1.00	0.011	0.014
0.10	16	256	64	0.0001	0.0001	2	1.00	0.011	0.014
0.10	16	256	64	0.0001	0.0001	3	1.00	0.014	0.016
0.10	16	256	256	1.0000	1.0000	2	1.00	0.021	0.023
0.10	16	256	256	1.0000	1.0000	3	1.00	0.022	0.024
0.10	16	256	256	1.0000	0.0100	2	1.00	0.032	0.075
0.10	16	256	256	1.0000	0.0100	3	1.00	0.032	0.034
0.10	16	256	256	1.0000	0.0001	2	1.00	0.045	0.069
0.10	16	256 256	256 256	1.0000	0.0001	3	1.00	0.046	0.058
0.10	16 16	256	256	0.0100	1.0000	3	1.00	0.036	0.048
0.10	16	256	256	0.0100	0.0100	2	1.00	0.050	0.043
0.10	16	256	256	0.0100	0.0100	3	1.00	0.050	0.060
0.10	16	256	256	0.0100	0.0001	2	1.00	0.064	0.096
0.10	16	256	256	0.0100	0.0001	3	1.00	0.064	0.118
0.10	16	256	256	0.0001	1.0000	2	1.00	0.049	0.078
0.10	16	256	256	0.0001	1.0000	3	1.00	0.049	0.076
0.10	16	256	256	0.0001	0.0100	2	1.00	0.061	0.098
0.10	16 16	256 256	256 256	0.0001	0.0100	3	1.00	0.060 0.118	0.098 0.128
0.10	16	256	256	0.0001	0.0001	3	1.00	0.118	0.128
0.10	64	1	1	1.0000	1.0000	2	1.00	0.104	0.003
0.10	64	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	64	1	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	64	1	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	64	1	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	64	1	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	64	1	1	0.0100	1.0000 0.0100	3	1.00	0.003	0.003
0.10	64	1	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	64	1	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	64	1	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	64	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	64	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	64	1	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	64	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	64	1	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	64	1	1	0.0001	0.0001	3	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	64	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	64	1	4	1.0000	1.0000	3	1.00	0.003	0.004
0.10	64	1	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	64	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	64	1	4	1.0000	0.0001	3	1.00	0.004	0.004
0.10	64	1	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	64	1	4	0.0100	1.0000	3	1.00	0.003	0.003
0.10	64	1	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	64	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	64	1	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	64	1	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	64	1	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	64	1	4	0.0001	0.0100	2	1.00	0.004	0.004
0.10	64	1	4	0.0001	0.0100	3	1.00	0.004	0.004
0.10	64	1	4	0.0001	0.0001	3	1.00	0.003	0.016
0.10	64	1	16	1.0000	1.0000	2	1.00	0.003	0.004
0.10	64	1	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	64	1	16	1.0000	0.0100	2	1.00	0.004	0.005
0.10	64	1	16 16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	64	1	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	64	1	16	0.0100	1.0000	2	1.00	0.004	0.004
0.10	64	1	16	0.0100	1.0000	3	1.00	0.004	0.004
0.10	64	1	16 16	0.0100	0.0100	3	1.00	0.004	0.005
0.10	64	1	16	0.0100	0.0100	2	1.00	0.004	0.004
0.10	64	1	16	0.0100	0.0001	3	1.00	0.004	0.005
0.10	64	1	16	0.0001	1.0000	2	1.00	0.004	0.005
0.10	64	1	16	0.0001	1.0000	3	1.00	0.004	0.008
0.10	64	1	16 16	0.0001	0.0100	3	1.00	0.004	0.005
0.10	64	1	16	0.0001	0.0001	2	1.00	0.005	0.005
0.10	64	1	16	0.0001	0.0001	3	1.00	0.005	0.006
0.10	64	1	64	1.0000	1.0000	2	1.00	0.008	0.008
0.10	64	1	64	1.0000	1.0000 0.0100	3	1.00	0.008	0.008
0.10	64	1	64	1.0000	0.0100	3	1.00	0.011	0.011
0.10	64	1	64	1.0000	0.0001	2	1.00	0.009	0.014
0.10	64	1	64	1.0000	0.0001	3	1.00	0.009	0.014
0.10	64	1	64	0.0100	1.0000	2	1.00	0.008	0.011
0.10	64	1	64	0.0100	0.0100	2	1.00	0.009	0.011
0.10	64	1	64	0.0100	0.0100	3	1.00	0.014	0.014
0.10	64	1	64	0.0100	0.0001	2	1.00	0.013	0.018
0.10	64	1	64 64	0.0100	0.0001	3	1.00	0.011	0.018
0.10	64	1	64	0.0001	1.0000	3	1.00	0.014	0.024
0.10	64	1	64	0.0001	0.0100	2	1.00	0.011	0.018
0.10	64	1	64	0.0001	0.0100	3	1.00	0.015	0.018
0.10	64	1	64	0.0001	0.0001	2	1.00	0.014	0.017
0.10	64	1	64 256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.014	0.017
0.10	64	1	256	1.0000	1.0000	3	1.00	0.022	0.067
0.10	64	1	256	1.0000	0.0100	2	1.00	0.039	0.053
0.10	64	1	256	1.0000	0.0100	3	1.00	0.034	0.052
0.10	64	1	256	1.0000	0.0001	2	1.00	0.045	0.052
0.10	64	1	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00	0.046 0.033	0.053
0.10	64	1	256	0.0100	1.0000	3	1.00	0.033	0.034
0.10	64	1	256	0.0100	0.0100	2	1.00	0.046	0.077
0.10	64	1	256	0.0100	0.0100	3	1.00	0.046	0.077
0.10	64	1	256 256	0.0100	0.0001	3	1.00	0.077	0.120
0.10	64	1	256	0.0100	1.0000	2	1.00	0.063	0.097
0.10	64	1	256	0.0001	1.0000	3	1.00	0.075	0.079
0.10	64	1	256	0.0001	0.0100	2	1.00	0.057	0.082
0.10	64	1	256	0.0001	0.0100	3	1.00	0.058	0.062
0.10	64	1	256 256	0.0001	0.0001	3	1.00	0.078	0.119
0.10	64	4	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	64	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	4	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	64	4	1	1.0000	0.0100	3	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	64	4	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	64	4	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	64	4	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	64	4	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	64	4	1	0.0100	0.0100	2	1.00	0.003	0.015
0.10	64	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	64	4	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	64	4	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	64	4	1	0.0001	1.0000	2	1.00	0.002	0.003
0.10	64	4	1	0.0001	1.0000	3	1.00	0.002	0.003
0.10	64	4	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	64	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	64	4	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	64	4	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	64	4	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	64	4	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	4	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	64		4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	64	4	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	64	4	4	1.0000	0.0001	3	1.00	0.003	0.004
0.10			4	0.0100	1.0000			0.003	0.004
0.10	64	4	4	0.0100	1.0000 0.0100	3	1.00	0.003	0.004
		4	4	0.0100					
0.10	64	4	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	64	4	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	64	4	4	0.0100	1.00001	2	1.00	0.004	0.004
0.10	64	4	4	0.0001	1.0000	3	1.00	0.004	0.004
0.10	64	4	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	64	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	64	4	4	0.0001	0.0001	2	1.00	0.003	0.004
0.10	64	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.10	64	4	16	1.0000	1.0000	2	1.00	0.003	0.004
0.10	64	4	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	64	4	16	1.0000	0.0100	2	1.00	0.003	0.004
0.10	64	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	64	4	16	1.0000	0.0001	2	1.00	0.004	0.005
0.10	64	4	16	1.0000	0.0001	3	1.00	0.004	0.005
0.10	64	4	16	0.0100	1.0000	2	1.00	0.004	0.015
0.10	64	4	16	0.0100	1.0000	3	1.00	0.004	0.003
0.10	64	4	16	0.0100	0.0100	2	1.00	0.004	0.004
0.10	64	4	16	0.0100	0.0100	3	1.00	0.004	0.006
0.10	64	4	16	0.0100	0.0001	2	1.00	0.004	0.005
0.10	64	4	16	0.0100	0.0001	3	1.00	0.004	0.006
0.10	64	4	16	0.0001	1.0000	2	1.00	0.004	0.006
0.10	64	4	16	0.0001	1.0000	3	1.00	0.004	0.006
0.10	64	4	16	0.0001	0.0100	2	1.00	0.004	0.007
0.10	64	4	16	0.0001	0.0100	3	1.00	0.004	0.006
0.10	64	4	16	0.0001	0.0001	2	1.00	0.005	0.007
0.10	64	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.10	64	4	64	1.0000	1.0000	2	1.00	0.006	0.007
0.10	64	4	64	1.0000	1.0000	3	1.00	0.006	0.008
0.10	64	4	64	1.0000	0.0100	2	1.00	0.008	0.013
0.10	64	4	64	1.0000	0.0100	3	1.00	0.008	0.008
0.10	64	4	64	1.0000	0.0001	2	1.00	0.009	0.010
0.10	64	4	64	1.0000	0.0001	3	1.00	0.009	0.010
0.10	64	4	64	0.0100	1.0000	2	1.00	0.007	0.008
0.10	64	4	64	0.0100	1.0000	3	1.00	0.008	0.009
0.10	64	4	64	0.0100	0.0100	2	1.00	0.009	0.015
0.10	64	4	64	0.0100	0.0100	3	1.00	0.009	0.015
0.10	64	4	64	0.0100	0.0001	2	1.00	0.014	0.018
0.10	64	4	64	0.0100	0.0001	3	1.00	0.011	0.019
0.10	64	4	64	0.0001	1.0000	2	1.00	0.012	0.016
0.10	64	4	64	0.0001	1.0000	3	1.00	0.010	0.058
0.10	64	4	64	0.0001	0.0100	2	1.00	0.012	0.018
0.10	64	4	64	0.0001	0.0100	3	1.00	0.014	0.018
0.10	64	4	64	0.0001	0.0001	2	1.00	0.014	0.023
0.10	64	4	64	0.0001	0.0001	3	1.00	0.016	0.023
0.10	64	4	256	1.0000	1.0000	2	1.00	0.032	0.033
0.10	64	4	256	1.0000	1.0000	3	1.00	0.025	0.048
0.10	64	4	256	1.0000	0.0100	2	1.00	0.041	0.052
0.10	64	4	256	1.0000	0.0100	3	1.00	0.046	0.051
0.10	64	4	256	1.0000	0.0001	2	1.00	0.071	0.072
	64	4	256	1.0000	0.0001	3	1.00	0.067	0.072
0.10	01								
0.10	64	4	256	0.0100	1.0000	2	1.00	0.032	0.051

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	64	4	256	0.0100	0.0100	2	1.00	0.046	0.051
0.10	64	4	256	0.0100	0.0100	3	1.00	0.046	0.077
0.10	64	4	256	0.0100	0.0001	2	1.00	0.068	0.090
0.10	64	4	256 256	0.0100	0.0001 1.0000	3	1.00	0.065	0.097
0.10	64	4	256	0.0001	1.0000	3	1.00	0.053	0.007
0.10	64	4	256	0.0001	0.0100	2	1.00	0.071	0.101
0.10	64	4	256	0.0001	0.0100	3	1.00	0.060	0.100
0.10	64	4	256	0.0001	0.0001	2	1.00	0.070	0.113
0.10	64	4 16	256 1	0.0001 1.0000	0.0001 1.0000	3	1.00	0.069	0.118
0.10	64	16	1	1.0000	1.0000	3	1.00	0.002	0.003
0.10	64	16	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	64	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	64	16	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	64	16 16	1	1.0000 0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.10	64	16	1	0.0100	1.0000	3	1.00	0.003	0.003
0.10	64	16	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	64	16	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	64	16	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	64	16 16	1	0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.10	64	16	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	64	16	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	64	16	1	0.0001	0.0100	3	1.00	0.003	0.013
0.10	64	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	64	16 16	1 4	0.0001 1.0000	0.0001 1.0000	3	1.00	0.003	0.003
0.10	64	16	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	16	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	64	16	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	64	16	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	64	16 16	4	1.0000 0.0100	0.0001 1.0000	3	1.00	0.004	0.004
0.10	64	16	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	64	16	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	64	16	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	64	16	4	0.0100	0.0001	2	1.00	0.004	0.004
0.10	64	16 16	4	0.0100	0.0001 1.0000	3	1.00	0.003	0.004
0.10	64	16	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	64	16	4	0.0001	0.0100	2	1.00	0.004	0.004
0.10	64	16	4	0.0001	0.0100	3	1.00	0.004	0.004
0.10	64	16	4	0.0001	0.0001	3	1.00	0.004	0.004
0.10	64	16 16	16	1.0000	0.0001 1.0000	2	1.00	0.004	0.004
0.10	64	16	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	64	16	16	1.0000	0.0100	2	1.00	0.004	0.005
0.10	64	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	64	16 16	16 16	1.0000	0.0001	3	1.00	0.006	0.006
0.10	64	16	16	0.0100	1.0000	2	1.00	0.006	0.006
0.10	64	16	16	0.0100	1.0000	3	1.00	0.005	0.005
0.10	64	16	16	0.0100	0.0100	2	1.00	0.005	0.006
0.10	64	16	16	0.0100	0.0100	3	1.00	0.005	0.006
0.10	64	16 16	16 16	0.0100	0.0001	2	1.00	0.004	0.006
0.10	64	16	16	0.0100	1.0000	2	1.00	0.004	0.012
0.10	64	16	16	0.0001	1.0000	3	1.00	0.004	0.006
0.10	64	16	16	0.0001	0.0100	2	1.00	0.006	0.006
0.10	64	16	16	0.0001	0.0100	3	1.00	0.006	0.007
0.10	64	16 16	16 16	0.0001	0.0001	3	1.00	0.005	0.326
0.10	64	16	64	1.0000	1.0000	2	1.00	0.006	0.007
0.10	64	16	64	1.0000	1.0000	3	1.00	0.006	0.007
0.10	64	16	64	1.0000	0.0100	2	1.00	0.007	0.009
0.10	64	16 16	64	1.0000	0.0100	3	1.00	0.007	0.008
0.10	64	16	64	1.0000	0.0001	3	1.00	0.009	0.010
0.10	64	16	64	0.0100	1.0000	2	1.00	0.007	0.008
0.10	64	16	64	0.0100	1.0000	3	1.00	0.007	0.008
0.10	64	16	64	0.0100	0.0100	2	1.00	0.009	0.010
0.10	64	16 16	64	0.0100	0.0100	3	1.00	0.009	0.010
0.10	64	16	64	0.0100	0.0001	3	1.00	0.011	0.012

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	64	16	64	0.0001	1.0000	2	1.00	0.010	0.011
0.10	64	16	64	0.0001	1.0000	3	1.00	0.010	0.011
0.10	64	16	64	0.0001	0.0100	2	1.00	0.011	0.017
0.10	64	16 16	64	0.0001	0.0100	3	1.00	0.012	0.018
0.10	64	16	64	0.0001	0.0001	3	1.00	0.014	0.023
0.10	64	16	256	1.0000	1.0000	2	1.00	0.032	0.033
0.10	64	16	256	1.0000	1.0000	3	1.00	0.025	0.033
0.10	64	16	256	1.0000	0.0100	2	1.00	0.051	0.052
0.10	64	16	256	1.0000	0.0100	3	1.00	0.051	0.053
0.10	64	16	256 256	1.0000	0.0001	2	1.00	0.068	0.074
0.10	64	16 16	256	1.0000 0.0100	1.0000	3 2	1.00	0.073	0.074
0.10	64	16	256	0.0100	1.0000	3	1.00	0.046	0.032
0.10	64	16	256	0.0100	0.0100	2	1.00	0.045	0.053
0.10	64	16	256	0.0100	0.0100	3	1.00	0.045	0.082
0.10	64	16	256	0.0100	0.0001	2	1.00	0.066	0.070
0.10	64	16	256	0.0100	0.0001	3	1.00	0.064	0.079
0.10	64	16	256	0.0001	1.0000	2	1.00	0.067	0.080
0.10	64	16 16	256 256	0.0001	1.0000 0.0100	3	1.00	0.063	0.078
0.10	64	16	256	0.0001	0.0100	3	1.00	0.073	0.097
0.10	64	16	256	0.0001	0.0001	2	1.00	0.083	0.090
0.10	64	16	256	0.0001	0.0001	3	1.00	0.076	0.103
0.10	64	64	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	64	64	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	64	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	64	64	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	64	64	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	64	64	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	64	64	1	0.0100	1.0000	3	1.00	0.003	0.003
0.10	64	64	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	64	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	64	64	1	0.0100	0.0001	2	1.00	0.003	0.004
0.10	64	64	1	0.0100	0.0001	3	1.00	0.003	0.004
0.10	64	64	1	0.0001	1.0000	2	1.00	0.002	0.003
0.10	64	64	1	0.0001	1.0000	3	1.00	0.002	0.003
0.10	64	64	1	0.0001	0.0100	3	1.00	0.003	0.090
0.10	64	64	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	64	64	1	0.0001	0.0001	3	1.00	0.002	0.003
0.10	64	64	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	64	64	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	64	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	64	64	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	64	64	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	64	64	4	1.0000	0.0001	3	1.00	0.003	0.004
0.10	64 64	64	4	0.0100	1.0000	3	1.00	0.003	0.003
0.10	64	64	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	64	64	4	0.0100	0.0100	3	1.00	0.004	0.004
0.10	64	64	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	64	64	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	64	64	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	64	64	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	64	64	4	0.0001	0.0100	2	1.00	0.003	0.003
0.10	64	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	64	64	4	0.0001	0.0001	3	1.00	0.003	0.004
0.10	64	64	16	1.0000	1.0000	2	1.00	0.003	0.003
0.10	64	64	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	64	64	16	1.0000	0.0100	2	1.00	0.004	0.005
0.10	64	64	16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	64	64	16	1.0000	0.0001	2	1.00	0.004	0.006
0.10	64	64	16	1.0000	1.0000	3	1.00	0.004	0.005
0.10	64	64	16 16	0.0100	1.0000	3	1.00	0.004	0.005
0.10	64	64	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	64	64	16	0.0100	0.0100	3	1.00	0.004	0.005
0.10	64	64	16	0.0100	0.0001	2	1.00	0.005	0.007
0.10	64	64	16	0.0100	0.0001	3	1.00	0.005	0.006
0.10	64	64	16	0.0001	1.0000	2	1.00	0.004	0.006
0.10	64	64	16	0.0001	1.0000	3	1.00	0.004	0.006
0.10	64	64	16	0.0001	0.0100	2	1.00	0.005	0.006
0.10	64	64	16	0.0001	0.0100	3	1.00	0.004	0.006

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	64	64	16	0.0001	0.0001	2	1.00	0.005	0.007
0.10	64	64	16	0.0001	0.0001	3	1.00	0.005	0.007
0.10	64	64	64 64	1.0000	1.0000	2	1.00	0.006	0.008
0.10	64	64	64	1.0000	0.0100	3	1.00	0.006	0.006
0.10	64	64	64	1.0000	0.0100	3	1.00	0.011	0.012
0.10	64	64	64	1.0000	0.0001	2	1.00	0.011	0.014
0.10	64	64	64	1.0000	0.0001	3	1.00	0.010	0.015
0.10	64	64 64	64 64	0.0100	1.0000	2	1.00	0.008	0.012
0.10	64	64	64	0.0100	0.0100	3	1.00	0.008	0.011
0.10	64	64	64	0.0100	0.0100	3	1.00	0.009	0.011
0.10	64	64	64	0.0100	0.0001	2	1.00	0.011	0.012
0.10	64	64	64	0.0100	0.0001	3	1.00	0.011	0.012
0.10	64 64	64	64 64	0.0001	1.0000	2	1.00	0.010	0.011
0.10	64	64	64	0.0001	0.0100	2	1.00	0.010	0.011
0.10	64	64	64	0.0001	0.0100	3	1.00	0.011	0.013
0.10	64	64	64	0.0001	0.0001	2	1.00	0.013	0.014
0.10	64	64	64	0.0001	0.0001	3	1.00	0.013	0.016
0.10	64	64	256 256	1.0000	1.0000	2	1.00	0.021	0.034
0.10	64	64	256	1.0000	0.0100	2	1.00	0.022	0.054
0.10	64	64	256	1.0000	0.0100	3	1.00	0.033	0.051
0.10	64	64	256	1.0000	0.0001	2	1.00	0.057	0.073
0.10	64	64	256	1.0000	0.0001	3	1.00	0.058	0.072
0.10	64	64	256 256	0.0100	1.0000	3	1.00	0.038	0.054
0.10	64	64	256	0.0100	0.0100	2	1.00	0.037	0.033
0.10	64	64	256	0.0100	0.0100	3	1.00	0.046	0.060
0.10	64	64	256	0.0100	0.0001	2	1.00	0.058	0.098
0.10	64	64	256	0.0100	0.0001	3	1.00	0.058	0.098
0.10	64	64	256 256	0.0001	1.0000	2	1.00	0.063	0.083
0.10	64	64	256	0.0001	0.0100	2	1.00	0.069	0.082
0.10	64	64	256	0.0001	0.0100	3	1.00	0.067	0.098
0.10	64	64	256	0.0001	0.0001	2	1.00	0.086	0.194
0.10	64	64 256	256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.085	0.122
0.10	64	256	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	256	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	64	256	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	64	256	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	64	256 256	1	1.0000 0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.10	64	256	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	64	256	1	0.0100	0.0100	2	1.00	0.002	0.003
0.10	64	256	1	0.0100	0.0100	3	1.00	0.002	0.003
0.10	64	256	1	0.0100	0.0001	2	1.00	0.002	0.003
0.10	64	256 256	1	0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.10	64	256	1	0.0001	1.0000	3	1.00	0.002	0.003
0.10	64	256	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	64	256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	64	256 256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	64	256	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	64	256	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	64	256	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	64	256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	64	256 256	4	1.0000	0.0001	3	1.00	0.004	0.004
0.10	64	256	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	64	256	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	64	256	4	0.0100	0.0100	2	1.00	0.004	0.004
0.10	64	256 256	4	0.0100	0.0100	3	1.00	0.004	0.004
0.10	64	256	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	64	256	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	64	256	4	0.0001	1.0000	3	1.00	0.004	0.004
0.10	64	256 256	4	0.0001	0.0100	2	1.00	0.004	0.004
0.10	64	256	4	0.0001	0.0100	2	1.00	0.004	0.004
0.10	64	256	4	0.0001	0.0001	3	1.00	0.004	0.004
0.10	64	256	16	1.0000	1.0000	2	1.00	0.004	0.004
0.10	64	256	16	1.0000	1.0000	3	1.00	0.004	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	64	256	16	1.0000	0.0100	2	1.00	0.005	0.005
0.10	64	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	64	256	16	1.0000	0.0001	2	1.00	0.006	0.006
0.10	64	256 256	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00	0.005	0.006
0.10	64	256	16	0.0100	1.0000	3	1.00	0.005	0.005
0.10	64	256	16	0.0100	0.0100	2	1.00	0.005	0.006
0.10	64	256	16	0.0100	0.0100	3	1.00	0.005	0.006
0.10	64	256	16	0.0100	0.0001	2	1.00	0.006	0.006
0.10	64	256	16	0.0100	0.0001	3	1.00	0.006	0.006
0.10	64 64	256 256	16 16	0.0001	1.0000	2	1.00	0.006	0.006
0.10	64	256	16	0.0001	0.0100	2	1.00	0.003	0.006
0.10	64	256	16	0.0001	0.0100	3	1.00	0.004	0.006
0.10	64	256	16	0.0001	0.0001	2	1.00	0.005	0.006
0.10	64	256	16	0.0001	0.0001	3	1.00	0.005	0.006
0.10	64	256	64	1.0000	1.0000	2	1.00	0.006	0.006
0.10	64	256	64	1.0000	1.0000	3	1.00	0.006	0.006
0.10	64	256 256	64 64	1.0000	0.0100	3	1.00	0.007	0.009
0.10	64	256	64	1.0000	0.0001	2	1.00	0.007	0.009
0.10	64	256	64	1.0000	0.0001	3	1.00	0.010	0.012
0.10	64	256	64	0.0100	1.0000	2	1.00	0.008	0.009
0.10	64	256	64	0.0100	1.0000	3	1.00	0.008	0.008
0.10	64	256	64	0.0100	0.0100	2	1.00	0.010	0.011
0.10	64	256	64	0.0100	0.0100	3	1.00	0.010	0.011
0.10	64	256	64	0.0100	0.0001	2	1.00	0.011	0.018
0.10	64	256 256	64 64	0.0100	1.00001	3	1.00	0.011	0.018 0.016
0.10	64	256	64	0.0001	1.0000	3	1.00	0.011	0.016
0.10	64	256	64	0.0001	0.0100	2	1.00	0.012	0.019
0.10	64	256	64	0.0001	0.0100	3	1.00	0.013	0.019
0.10	64	256	64	0.0001	0.0001	2	1.00	0.014	0.022
0.10	64	256	64	0.0001	0.0001	3	1.00	0.015	0.021
0.10	64	256 256	256 256	1.0000	1.0000	3	1.00	0.023	0.033
0.10	64	256	256	1.0000	0.0100	2	1.00	0.024	0.053
0.10	64	256	256	1.0000	0.0100	3	1.00	0.034	0.052
0.10	64	256	256	1.0000	0.0001	2	1.00	0.045	0.075
0.10	64	256	256	1.0000	0.0001	3	1.00	0.045	0.415
0.10	64	256	256	0.0100	1.0000	2	1.00	0.032	0.033
0.10	64	256	256	0.0100	1.0000	3	1.00	0.031	0.034
0.10	64	256 256	256 256	0.0100	0.0100	2	1.00	0.049	0.078
0.10	64	256	256	0.0100	0.0100	3	1.00	0.048	0.077
0.10	64	256	256	0.0100	0.0001	3	1.00	0.077	0.090
0.10	64	256	256	0.0001	1.0000	2	1.00	0.055	0.073
0.10	64	256	256	0.0001	1.0000	3	1.00	0.056	0.075
0.10	64	256	256	0.0001	0.0100	2	1.00	0.059	0.095
0.10	64	256	256	0.0001	0.0100	3	1.00	0.060	0.093
0.10	64	256	256	0.0001	0.0001	3	1.00	0.075	0.106
0.10	256	256	256	0.0001 1.0000	0.0001 1.0000	2	1.00	0.075	0.122
0.10	256	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	256	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	256	1	1	1.0000	0.0100	3	1.00	0.003	0.013
0.10	256	1	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	256	1	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	256	1	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	256 256	1	1	0.0100	1.0000 0.0100	2	1.00	0.003	0.003
0.10	256	1	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	256	1	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	256	1	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	256	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	256	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.10	256	1	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	256 256	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	256	1	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	256	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	256	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	256	1	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	256	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	256	1	4	1.0000	0.0001	2	1.00	0.004	0.004
0.10	256	1	4	1.0000	0.0001	3	1.00	0.004	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	256	1	4	0.0100	1.0000	2	1.00	0.003	0.004
0.10	256 256	1	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	256	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	256	1	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	256	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.10	256	1	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	256	1	4	0.0001	1.0000 0.0100	3	1.00	0.003	0.004
0.10	256 256	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	256	1	4	0.0001	0.0001	2	1.00	0.004	0.004
0.10	256	1	4	0.0001	0.0001	3	1.00	0.004	0.004
0.10	256	1	16	1.0000	1.0000	2	1.00	0.004	0.005
0.10	256 256	1	16 16	1.0000	1.0000 0.0100	3	1.00	0.004	0.004 0.005
0.10	256	1	16	1.0000	0.0100	3	1.00	0.005	0.005
0.10	256	1	16	1.0000	0.0001	2	1.00	0.006	0.006
0.10	256	1	16	1.0000	0.0001	3	1.00	0.006	0.006
0.10	256	1	16	0.0100	1.0000	2	1.00	0.005	0.005
0.10	256 256	1	16 16	0.0100	1.0000 0.0100	3	1.00	0.005	0.005
0.10	256	1	16	0.0100	0.0100	3	1.00	0.004	0.005
0.10	256	1	16	0.0100	0.0001	2	1.00	0.005	0.006
0.10	256	1	16	0.0100	0.0001	3	1.00	0.005	0.006
0.10	256	1	16	0.0001	1.0000	2	1.00	0.004	0.006
0.10	256 256	1	16 16	0.0001	1.0000 0.0100	3	1.00	0.004	0.005
0.10	256	1	16	0.0001	0.0100	3	1.00	0.004	0.006
0.10	256	1	16	0.0001	0.0001	2	1.00	0.005	0.007
0.10	256	1	16	0.0001	0.0001	3	1.00	0.005	0.007
0.10	256	1	64	1.0000	1.0000	2	1.00	0.006	0.008
0.10	256 256	1	64 64	1.0000	1.0000 0.0100	3	1.00	0.006	0.007
0.10	256	1	64	1.0000	0.0100	3	1.00	0.008	0.009
0.10	256	1	64	1.0000	0.0001	2	1.00	0.010	0.016
0.10	256	1	64	1.0000	0.0001	3	1.00	0.010	0.011
0.10	256 256	1	64 64	0.0100	1.0000	2	1.00	0.008	0.009
0.10	256	1	64	0.0100	0.0100	2	1.00	0.008	0.009
0.10	256	1	64	0.0100	0.0100	3	1.00	0.010	0.011
0.10	256	1	64	0.0100	0.0001	2	1.00	0.011	0.012
0.10	256	1	64	0.0100	0.0001	3	1.00	0.011	0.013
0.10	256 256	1	64 64	0.0001	1.0000	2	1.00	0.011	0.017 0.017
0.10	256	1	64	0.0001	0.0100	2	1.00	0.011	0.017
0.10	256	1	64	0.0001	0.0100	3	1.00	0.011	0.018
0.10	256	1	64	0.0001	0.0001	2	1.00	0.014	0.021
0.10	256	1	64	0.0001	0.0001	3	1.00	0.014	0.022
0.10	256 256	1	256 256	1.0000	1.0000	2	1.00	0.031	0.033
0.10	256	1	256	1.0000	0.0100	2	1.00	0.024	0.033
0.10	256	1	256	1.0000	0.0100	3	1.00	0.036	0.052
0.10	256	1	256	1.0000	0.0001	2	1.00	0.052	0.072
0.10	256 256	1	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00	0.048	0.097 0.051
0.10	256	1	256	0.0100	1.0000	3	1.00	0.049	0.051
0.10	256	1	256	0.0100	0.0100	2	1.00	0.066	0.077
0.10	256	1	256	0.0100	0.0100	3	1.00	0.050	0.077
0.10	256	1	256 256	0.0100	0.0001	2	1.00	0.093	0.098
0.10	256 256	1	256	0.0100	0.0001 1.0000	2	1.00	0.086	0.098
0.10	256	1	256	0.0001	1.0000	3	1.00	0.054	0.080
0.10	256	1	256	0.0001	0.0100	2	1.00	0.062	0.095
0.10	256	1	256	0.0001	0.0100	3	1.00	0.060	0.099
0.10	256 256	1	256 256	0.0001	0.0001	3	1.00	0.081	0.125 0.128
0.10	256	4	230	1.0000	1.00001	2	1.00	0.079	0.128
0.10	256	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	256	4	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	256	4	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	256 256	4	1	1.0000 1.0000	0.0001	2	1.00	0.003	0.003
0.10	256	4	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	256	4	1	0.0100	1.0000	3	1.00	0.003	0.003
0.10	256	4	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	256	4	1	0.0100	0.0100	3	1.00	0.003	0.003

0.10 256 4	mul	m_1	m_2	au	TR	DTR	alg	SR	mint	maxt
0.10 256	0.10	256		1	0.0100	0.0001		1.00	0.003	0.004
0.10 256 4										
0.10 256 4 1 0.0001 0.0100 2 1.00 0.003 0.003 0.003 0.010 256 4 1 0.0001 0.0001 2 1.00 0.003 0.003 0.003 0.010 256 4 1 0.0001 0.0001 3 1.00 0.003 0.003 0.003 0.010 256 4 4 1.0000 1.0000 3 1.00 0.003 0.003 0.010 256 4 4 1.0000 1.0000 3 1.00 0.003 0.003 0.010 256 4 4 1.0000 1.0000 3 1.00 0.003 0.003 0.003 0.010 256 4 4 1.0000 0.0100 2 1.00 0.003 0.003 0.003 0.010 256 4 4 1.0000 0.0100 2 1.00 0.003 0.004 0.010 2 0.00 0.003 0.004 0.005 0.	$\overline{}$									
0.10 256 4 1 0.0001 0.0001 3 1.00 0.003 0.003 0.003 0.010 256 4 1 0.0001 0.0001 3 1.00 0.003 0.003 0.003 0.010 256 4 4 1.0000 1.0000 2 1.00 0.003 0.003 0.003 0.010 256 4 4 1.0000 1.0000 2 1.00 0.003 0.003 0.010 256 4 4 1.0000 1.0000 2 1.00 0.003 0.003 0.010 256 4 4 1.0000 0.0100 2 1.00 0.003 0.003 0.003 0.010 256 4 4 1.0000 0.0100 2 1.00 0.003 0.003 0.004 0.010 256 4 4 1.0000 0.0010 2 1.00 0.003 0.004 0.010 256 4 4 1.0000 0.0001 2 1.00 0.003 0.004 0.010 256 4 4 1.0000 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 1.0000 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0000 3 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.003 0.003 0.004 0.10 256 4 4 0.0001 0.0000 2 1.00 0.003 0.003 0.004 0.10 2 2 2 2 2 2 2 2 2										
0.10 256 4 1 0.0001 0.0001 2 1.00 0.003 0.003 0.003 0.10 256 4 4 1.0000 1.0000 3 1.00 0.003 0.003 0.003 0.10 256 4 4 1.0000 0.1000 3 1.00 0.003 0.003 0.003 0.10 256 4 4 1.0000 0.1000 3 1.00 0.003 0.004 0.10 256 4 4 1.0000 0.0100 3 1.00 0.003 0.004 0.10 256 4 4 1.0000 0.0100 3 1.00 0.003 0.004 0.10 256 4 4 1.0000 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 1.0000 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 1.0000 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 1.0000 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0000 3 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0010 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 1.0000 2 1.00 0.003 0.003 0.004 0.10 256 4 4 0.0001 1.0000 3 1.00 0.003 0.003 0.10 256 4 4 0.0001 0.0100 3 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0000 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.003 0.004 0.10 256 4 4 0.0001 0.0001 2 1.00 0.004 0.006 0.10 256 4 4 0.0001 0.0001 2 1.00 0.004 0.006 0.10 256 4 16 1.0000 0.0001 2 1.00 0.004 0.006 0.10 256 4 16 1.0000										
0.10 256 4 4 1.0000 1.0000 2 1.00 0.003 0.004 0.005 0.										
0.10 256 4 4 1.0000 1.0000 2 1.00 0.003 0.003 0.003 0.010 256 4 4 1.0000 0.0100 2 1.00 0.003 0.003 0.003 0.010 0.100 256 4 4 1.0000 0.0100 3 1.00 0.003 0.003 0.003 0.004 0.101 256 4 4 1.0000 0.0001 3 1.00 0.003 0.004 0.101 256 4 4 1.0000 0.0001 3 1.00 0.003 0.004 0.101 256 4 4 0.0100 1.0000 3 1.00 0.003 0.004 0.101 256 4 4 0.0100 1.0000 3 1.00 0.003 0.004 0.101 256 4 4 0.0100 1.0000 3 1.00 0.003 0.004 0.101 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.101 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.101 256 4 4 0.0100 0.0100 2 1.00 0.003 0.004 0.101 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.101 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.101 256 4 4 0.0100 0.0001 2 1.00 0.003 0.004 0.101 256 4 4 0.0001 0.0001 2 1.00 0.003 0.003 0.004 0.101 256 4 4 0.0001 0.0001 2 1.00 0.003 0.003 0.004 0.101 256 4 4 0.0001 0.0000 2 1.00 0.003 0.003 0.004 0.101 256 4 4 0.0001 0.0000 2 1.00 0.003 0.004 0.101 256 4 4 0.0001 0.0100 2 1.00 0.003 0.004 0.101 256 4 4 0.0001 0.0100 3 1.00 0.003 0.004 0.101 256 4 4 0.0001 0.0001 3 1.00 0.003 0.004 0.101 256 4 4 0.0001 0.0001 3 1.00 0.003 0.004 0.101 256 4 16 1.0000 0.0000 3 1.00 0.003 0.004 0.101 256 4 16 1.0000 0.0000 3 1.00 0.003 0.005 0.101 256 4 16 1.0000 0.0000 3 1.00 0.004 0.005 0.101 256 4 16 1.0000 0.0000 3 1.00 0.004 0.005 0.101 256 4 16 1.0000 0.0100 3 1.00 0.004 0.005 0.101 256 4 16 1.0000 0.0100 3 1.00 0.004 0.005 0.101 256 4 16 1.0000 0.0000 3 1.00 0.004 0.005 0.101 256 4 16 1.0000										
0.10 256			4	4						
0.10 256	0.10	256	4	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10 256										
0.10 256										
0.10 256										
0.10 256										
0.10 256										
0.10 256	$\overline{}$									
0.10 256			4	4						
O.10 256	0.10	256	4	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10										
O.10										
0.10 256	$\overline{}$									
0.10 256										
O.10 256										
O.10										
O.10										
O.10 256										
O.10	0.10	256	4	16		0.0100	2		0.004	0.005
0.10 256										
O.10 256										
O.10 256										
O.10 256										
0.10 256										
0.10 256	$\overline{}$									
0.10 256										
0.10 256		256	4	16			3		0.004	
0.10 256 4 16 0.0001 0.0100 2 1.00 0.004 0.005 0.10 256 4 16 0.0001 0.0100 3 1.00 0.004 0.005 0.10 256 4 16 0.0001 0.0001 2 1.00 0.005 0.006 0.10 256 4 16 1.0000 1.0000 2 1.00 0.005 0.006 0.10 256 4 64 1.0000 1.0000 3 1.00 0.007 0.008 0.10 256 4 64 1.0000 0.0100 2 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0100 3 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0001 3 1.00 0.010 0.015 0.10 256 4 64 1.0000 0.001 3	0.10	256		16	0.0001	1.0000		1.00	0.004	0.005
0.10 256 4 16 0.0001 0.0100 3 1.00 0.004 0.005 0.10 256 4 16 0.0001 0.0001 2 1.00 0.005 0.006 0.10 256 4 16 0.0001 0.0001 3 1.00 0.005 0.006 0.10 256 4 64 1.0000 1.0000 3 1.00 0.006 0.008 0.10 256 4 64 1.0000 0.0100 2 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0100 3 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0001 2 1.00 0.010 0.011 0.012 0.10 256 4 64 1.0000 0.0001 3 1.00 0.010 0.015 0.10 256 4 64 0.0100 1.0000										
O.10 256	$\overline{}$									
0.10 256 4 16 0.0001 0.0001 3 1.00 0.005 0.006 0.10 256 4 64 1.0000 1.0000 2 1.00 0.006 0.008 0.10 256 4 64 1.0000 0.0100 3 1.00 0.007 0.008 0.10 256 4 64 1.0000 0.0100 3 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0001 3 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0001 3 1.00 0.010 0.015 0.10 256 4 64 1.0000 0.0001 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 1.0000 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0100 3 <td></td>										
0.10 256										
0.10 256 4 64 1.0000 1.0000 3 1.00 0.007 0.008 0.10 256 4 64 1.0000 0.0100 2 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0100 3 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0001 3 1.00 0.010 0.016 0.10 256 4 64 1.0000 0.0001 3 1.00 0.010 0.016 0.10 256 4 64 0.0100 1.0000 2 1.00 0.011 0.012 0.10 256 4 64 0.0100 1.0000 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0100 3 1.00 0.010 0.015 0.10 256 4 64 0.0100 0.0001 3 <td></td>										
0.10 256 4 64 1.0000 0.0100 2 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0100 3 1.00 0.011 0.012 0.10 256 4 64 1.0000 0.0001 2 1.00 0.010 0.015 0.10 256 4 64 1.0000 1.000 2 1.00 0.011 0.012 0.10 256 4 64 0.0100 1.0000 2 1.00 0.011 0.012 0.10 256 4 64 0.0100 1.0000 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0100 2 1.00 0.010 0.015 0.10 256 4 64 0.0100 0.0100 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0001 3										
0.10 256 4 64 1.0000 0.0001 2 1.00 0.010 0.015 0.10 256 4 64 1.0000 0.0001 3 1.00 0.010 0.016 0.10 256 4 64 0.0100 1.0000 2 1.00 0.011 0.012 0.10 256 4 64 0.0100 1.0000 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0100 2 1.00 0.010 0.015 0.10 256 4 64 0.0100 0.0100 3 1.00 0.010 0.014 0.10 256 4 64 0.0100 0.0001 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0001 3 1.00 0.011 0.012 0.10 256 4 64 0.0001 1.0000 3 <td></td> <td></td> <td>4</td> <td>64</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>			4	64						
0.10 256 4 64 1.0000 0.0001 3 1.00 0.010 0.016 0.10 256 4 64 0.0100 1.0000 2 1.00 0.011 0.012 0.10 256 4 64 0.0100 1.0000 3 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0100 3 1.00 0.010 0.015 0.10 256 4 64 0.0100 0.0100 3 1.00 0.010 0.014 0.10 256 4 64 0.0100 0.0001 2 1.00 0.011 0.012 0.10 256 4 64 0.0100 0.0001 3 1.00 0.011 0.012 0.10 256 4 64 0.0001 1.0000 3 1.00 0.010 0.011 0.10 256 4 64 0.0001 1.0000 3 <td>0.10</td> <td>256</td> <td>4</td> <td>64</td> <td>1.0000</td> <td>0.0100</td> <td>3</td> <td>1.00</td> <td>0.011</td> <td>0.012</td>	0.10	256	4	64	1.0000	0.0100	3	1.00	0.011	0.012
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\overline{}$									
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	$\overline{}$									
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.035
0.10 256 4 256 0.0100 1.0000 2 1.00 0.034 0.035 0.10 256 4 256 0.0100 1.0000 3 1.00 0.034 0.035 0.10 256 4 256 0.0100 0.0100 2 1.00 0.049 0.053 0.10 256 4 256 0.0100 0.0100 3 1.00 0.050 0.052 0.10 256 4 256 0.0100 0.0001 2 1.00 0.060 0.064 0.10 256 4 256 0.0100 0.0001 3 1.00 0.059 0.064 0.10 256 4 256 0.0100 0.0001 3 1.00 0.059 0.064 0.10 256 4 256 0.0001 1.0000 2 1.00 0.048 0.068										
0.10 256 4 256 0.0100 1.0000 3 1.00 0.034 0.035 0.10 256 4 256 0.0100 0.0100 2 1.00 0.049 0.053 0.10 256 4 256 0.0100 0.0100 3 1.00 0.050 0.052 0.10 256 4 256 0.0100 0.0001 2 1.00 0.060 0.064 0.10 256 4 256 0.0100 0.0001 3 1.00 0.059 0.064 0.10 256 4 256 0.0001 1.0000 2 1.00 0.048 0.068										
0.10 256 4 256 0.0100 0.0100 2 1.00 0.049 0.053 0.10 256 4 256 0.0100 0.0100 3 1.00 0.050 0.052 0.10 256 4 256 0.0100 0.0001 2 1.00 0.060 0.064 0.10 256 4 256 0.0100 0.0001 3 1.00 0.059 0.064 0.10 256 4 256 0.0001 1.0000 2 1.00 0.048 0.068										
0.10 256 4 256 0.0100 0.0100 3 1.00 0.050 0.052 0.10 256 4 256 0.0100 0.0001 2 1.00 0.060 0.064 0.10 256 4 256 0.0100 0.0001 3 1.00 0.059 0.064 0.10 256 4 256 0.0001 1.0000 2 1.00 0.048 0.068										
0.10 256 4 256 0.0100 0.0001 2 1.00 0.060 0.064 0.10 256 4 256 0.0100 0.0001 3 1.00 0.059 0.064 0.10 256 4 256 0.0001 1.0000 2 1.00 0.048 0.068										
0.10 256 4 256 0.0100 0.0001 3 1.00 0.059 0.064 0.10 256 4 256 0.0001 1.0000 2 1.00 0.048 0.068										
0.10 256 4 256 0.0001 1.0000 2 1.00 0.048 0.068	$\overline{}$									
0.10 256 4 256 0.0001 1.0000 3 1.00 0.049 0.072	0.10	256	4	256	0.0001	1.0000	3	1.00	0.049	0.072

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	256	4	256	0.0001	0.0100	2	1.00	0.065	0.068
0.10	256	4	256	0.0001	0.0100	3	1.00	0.064	0.068
0.10	256 256	4	256 256	0.0001	0.0001	3	1.00	0.076 0.077	0.084
0.10	256	16	1	1.0000	1.0000	2	1.00	0.002	0.003
0.10	256	16	1	1.0000	1.0000	3	1.00	0.002	0.003
0.10	256	16	1	1.0000	0.0100	2	1.00	0.002	0.003
0.10	256 256	16 16	1	1.0000	0.0100	3	1.00	0.002	0.003
0.10	256	16	1	1.0000	0.0001	3	1.00	0.002	0.003
0.10	256	16	1	0.0100	1.0000	2	1.00	0.002	0.003
0.10	256	16	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	256 256	16 16	1	0.0100	0.0100	3	1.00	0.002	0.003
0.10	256	16	1	0.0100	0.0001	2	1.00	0.002	0.003
0.10	256	16	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	256	16	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	256 256	16 16	1	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.10	256	16	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	256	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	256	16	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	256	16 16	4	1.0000	1.0000	3	1.00	0.003	0.010
0.10	256 256	16	4	1.0000	1.0000 0.0100	2	1.00	0.003	0.004
0.10	256	16	4	1.0000	0.0100	3	1.00	0.003	0.003
0.10	256	16	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	256	16	4	1.0000	0.0001 1.0000	3	1.00	0.003	0.004
0.10	256 256	16 16	4	0.0100	1.0000	3	1.00	0.003	0.003
0.10	256	16	4	0.0100	0.0100	2	1.00	0.003	0.003
0.10	256	16	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	256	16	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	256 256	16 16	4	0.0100	0.0001 1.0000	3 2	1.00	0.003	0.004
0.10	256	16	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	256	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	256	16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	256 256	16 16	4	0.0001	0.0001	3	1.00	0.003	0.003
0.10	256	16	16	1.0000	1.0000	2	1.00	0.003	0.003
0.10	256	16	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	256	16	16	1.0000	0.0100	2	1.00	0.004	0.004
0.10	256 256	16 16	16 16	1.0000	0.0100	3	1.00	0.004	0.004
0.10	256	16	16	1.0000	0.0001	3	1.00	0.004	0.004
0.10	256	16	16	0.0100	1.0000	2	1.00	0.004	0.004
0.10	256	16	16	0.0100	1.0000	3	1.00	0.004	0.004
0.10	256	16	16	0.0100	0.0100	2	1.00	0.004	0.005
0.10	256 256	16 16	16 16	0.0100	0.0100	3	1.00	0.004	0.004
0.10	256	16	16	0.0100	0.0001	3	1.00	0.004	0.006
0.10	256	16	16	0.0001	1.0000	2	1.00	0.004	0.005
0.10	256	16	16	0.0001	1.0000	3	1.00	0.004	0.005
0.10	256 256	16 16	16 16	0.0001	0.0100	3	1.00	0.004	0.005 0.005
0.10	256	16	16	0.0001	0.0001	2	1.00	0.004	0.005
0.10	256	16	16	0.0001	0.0001	3	1.00	0.005	0.006
0.10	256	16	64	1.0000	1.0000	2	1.00	0.006	0.006
0.10	256 256	16 16	64 64	1.0000	1.0000 0.0100	2	1.00	0.006 0.007	0.007 0.008
0.10	256	16	64	1.0000	0.0100	3	1.00	0.007	0.008
0.10	256	16	64	1.0000	0.0001	2	1.00	0.009	0.011
0.10	256	16	64	1.0000	0.0001	3	1.00	0.010	0.010
0.10	256 256	16 16	64 64	0.0100	1.0000	2	1.00	0.007	0.008
0.10	256	16	64	0.0100	0.0100	2	1.00	0.007	0.008
0.10	256	16	64	0.0100	0.0100	3	1.00	0.009	0.011
0.10	256	16	64	0.0100	0.0001	2	1.00	0.011	0.017
0.10	256	16	64	0.0100	0.0001 1.0000	3	1.00	0.011	0.017
0.10	256 256	16 16	64	0.0001	1.0000	2	1.00	0.010	0.016 0.015
0.10	256	16	64	0.0001	0.0100	2	1.00	0.011	0.013
0.10	256	16	64	0.0001	0.0100	3	1.00	0.011	0.013
0.10	256	16	64	0.0001	0.0001	2	1.00	0.014	0.015
0.10	256	16	64	0.0001	0.0001	3	1.00	0.014	0.017

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	256	16	256	1.0000	1.0000	2	1.00	0.022	0.023
0.10	256	16	256	1.0000	1.0000	3	1.00	0.021	0.024
0.10	256	16	256	1.0000	0.0100	2	1.00	0.033	0.035
0.10	256 256	16	256 256	1.0000	0.0100	3	1.00	0.033	0.035
0.10	256	16 16	256	1.0000	0.0001	3	1.00	0.048	0.050
0.10	256	16	256	0.0100	1.0000	2	1.00	0.048	0.036
0.10	256	16	256	0.0100	1.0000	3	1.00	0.034	0.082
0.10	256	16	256	0.0100	0.0100	2	1.00	0.050	0.055
0.10	256	16	256	0.0100	0.0100	3	1.00	0.048	0.054
0.10	256	16	256	0.0100	0.0001	2	1.00	0.060	0.079
0.10	256	16	256	0.0100	0.0001	3	1.00	0.060	0.078
0.10	256	16	256 256	0.0001	1.0000	2	1.00	0.053	0.057
0.10	256 256	16 16	256	0.0001	1.0000 0.0100	3	1.00	0.053	0.056
0.10	256	16	256	0.0001	0.0100	3	1.00	0.064	0.099
0.10	256	16	256	0.0001	0.0001	2	1.00	0.081	0.086
0.10	256	16	256	0.0001	0.0001	3	1.00	0.081	0.084
0.10	256	64	1	1.0000	1.0000	2	1.00	0.003	0.003
0.10	256	64	1	1.0000	1.0000	3	1.00	0.003	0.003
0.10	256	64	1	1.0000	0.0100	2	1.00	0.002	0.003
0.10	256	64	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	256 256	64	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	256	64	1	1.0000 0.0100	0.0001 1.0000	2	1.00	0.003	0.003
0.10	256	64	1	0.0100	1.0000	3	1.00	0.002	0.003
0.10	256	64	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	256	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	256	64	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	256	64	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	256	64	1	0.0001	1.0000	2	1.00	0.003	0.003
0.10	256	64	1	0.0001	1.0000	3 2	1.00	0.003	0.003
0.10	256 256	64	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	256	64	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	256	64	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	256	64	4	1.0000	1.0000	2	1.00	0.003	0.003
0.10	256	64	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	256	64	4	1.0000	0.0100	2	1.00	0.003	0.004
0.10	256	64	4	1.0000	0.0100	3	1.00	0.003	0.004
0.10	256 256	64	4	1.0000	0.0001	2	1.00	0.004	0.004
0.10	256	64	4	1.0000 0.0100	0.0001 1.0000	3	1.00	0.004	0.004
0.10	256	64	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	256	64	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	256	64	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	256	64	4	0.0100	0.0001	2	1.00	0.004	0.004
0.10	256	64	4	0.0100	0.0001	3	1.00	0.004	0.004
0.10	256	64	4	0.0001	1.0000	2	1.00	0.003	0.004
0.10	256	64	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	256 256	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	256	64	4	0.0001	0.0001	2	1.00	0.004	0.004
0.10	256	64	4	0.0001	0.0001	3	1.00	0.004	0.004
0.10	256	64	16	1.0000	1.0000	2	1.00	0.004	0.004
0.10	256	64	16	1.0000	1.0000	3	1.00	0.004	0.004
0.10	256	64	16	1.0000	0.0100	2	1.00	0.005	0.005
0.10	256	64	16	1.0000	0.0100	3	1.00	0.005	0.005
0.10	256	64	16	1.0000	0.0001	2	1.00	0.006	0.006
0.10	256 256	64 64	16 16	1.0000 0.0100	0.0001 1.0000	2	1.00	0.005	0.006
0.10	256	64	16	0.0100	1.0000	3	1.00	0.003	0.005
0.10	256	64	16	0.0100	0.0100	2	1.00	0.004	0.006
0.10	256	64	16	0.0100	0.0100	3	1.00	0.005	0.006
0.10	256	64	16	0.0100	0.0001	2	1.00	0.006	0.006
0.10	256	64	16	0.0100	0.0001	3	1.00	0.006	0.006
0.10	256	64	16	0.0001	1.0000	2	1.00	0.006	0.006
0.10	256	64	16	0.0001	1.0000	3	1.00	0.006	0.006
0.10	256 256	64 64	16 16	0.0001	0.0100	3	1.00	0.006	0.007
0.10	256	64	16	0.0001	0.0001	2	1.00	0.006	0.007
0.10	256	64	16	0.0001	0.0001	3	1.00	0.006	0.007
0.10					1.0000	2	1.00	0.008	0.016
	256	64	64	1.0000	1.00001	_			
0.10	256	64	64	1.0000	1.0000	3	1.00	0.008	0.014
0.10 0.10 0.10									

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	256	64	64	1.0000	0.0001	2	1.00	0.015	0.015
0.10	256	64	64	1.0000	0.0001	3	1.00	0.014	0.015
0.10	256 256	64	64 64	0.0100	1.0000	3	1.00	0.007	0.011
0.10	256	64	64	0.0100	0.0100	2	1.00	0.007	0.011
0.10	256	64	64	0.0100	0.0100	3	1.00	0.014	0.015
0.10	256	64	64	0.0100	0.0001	2	1.00	0.011	0.017
0.10	256	64	64	0.0100	0.0001	3	1.00	0.011	0.017
0.10	256	64	64	0.0001	1.0000	2	1.00	0.010	0.015
0.10	256 256	64	64	0.0001	1.0000 0.0100	3	1.00	0.011	0.015 0.018
0.10	256	64	64	0.0001	0.0100	3	1.00	0.017	0.018
0.10	256	64	64	0.0001	0.0001	2	1.00	0.014	0.015
0.10	256	64	64	0.0001	0.0001	3	1.00	0.014	0.015
0.10	256 256	64	256 256	1.0000	1.0000	2	1.00	0.021	0.021
0.10	256	64	256	1.0000	0.0100	2	1.00	0.020	0.021
0.10	256	64	256	1.0000	0.0100	3	1.00	0.032	0.051
0.10	256	64	256	1.0000	0.0001	2	1.00	0.054	0.074
0.10	256	64	256	1.0000	0.0001	3	1.00	0.049	0.074
0.10	256 256	64	256 256	0.0100	1.0000	2	1.00	0.034	0.052
0.10	256	64	256	0.0100	0.0100	2	1.00	0.037	0.083
0.10	256	64	256	0.0100	0.0100	3	1.00	0.051	0.074
0.10	256	64	256	0.0100	0.0001	2	1.00	0.064	0.088
0.10	256	64	256	0.0100	0.0001	3	1.00	0.060	0.086
0.10	256 256	64	256 256	0.0001	1.0000	3	1.00	0.062	0.080
0.10	256	64	256	0.0001	0.0100	2	1.00	0.063	0.079
0.10	256	64	256	0.0001	0.0100	3	1.00	0.096	0.098
0.10	256	64	256	0.0001	0.0001	2	1.00	0.076	0.127
0.10	256	64	256	0.0001	0.0001	3	1.00	0.076	0.124
0.10	256 256	256 256	1	1.0000	1.0000 1.0000	2	1.00	0.003 0.003	0.003
0.10	256	256	1	1.0000	0.0100	2	1.00	0.003	0.003
0.10	256	256	1	1.0000	0.0100	3	1.00	0.003	0.003
0.10	256	256	1	1.0000	0.0001	2	1.00	0.003	0.003
0.10	256	256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.10	256 256	256 256	1	0.0100	1.0000	2	1.00	0.003	0.003
0.10	256	256	1	0.0100	0.0100	2	1.00	0.003	0.003
0.10	256	256	1	0.0100	0.0100	3	1.00	0.003	0.003
0.10	256	256	1	0.0100	0.0001	2	1.00	0.003	0.003
0.10	256	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.10	256 256	256 256	1	0.0001	1.0000	3	1.00	0.002	0.003
0.10	256	256	1	0.0001	0.0100	2	1.00	0.003	0.003
0.10	256	256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.10	256	256	1	0.0001	0.0001	2	1.00	0.003	0.003
0.10	256	256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.10	256 256	256 256	4	1.0000	1.0000	3	1.00	0.003	0.003
0.10	256	256	4	1.0000	0.0100	2	1.00	0.003	0.003
0.10	256	256	4	1.0000	0.0100	3	1.00	0.003	0.003
0.10	256	256	4	1.0000	0.0001	2	1.00	0.003	0.004
0.10	256 256	256 256	4	1.0000 0.0100	0.0001 1.0000	3	1.00	0.003	0.004
0.10	256	256	4	0.0100	1.0000	3	1.00	0.003	0.004
0.10	256	256	4	0.0100	0.0100	2	1.00	0.003	0.004
0.10	256	256	4	0.0100	0.0100	3	1.00	0.003	0.004
0.10	256	256	4	0.0100	0.0001	2	1.00	0.003	0.004
0.10	256 256	256 256	4	0.0100	0.0001 1.0000	3	1.00	0.003	0.004
0.10	256	256	4	0.0001	1.0000	3	1.00	0.003	0.004
0.10	256	256	4	0.0001	0.0100	2	1.00	0.003	0.004
0.10	256	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.10	256	256	4	0.0001	0.0001	2	1.00	0.003	0.015
0.10	256 256	256 256	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00	0.003	0.004
0.10	256	256	16	1.0000	1.0000	3	1.00	0.003	0.004
0.10	256	256	16	1.0000	0.0100	2	1.00	0.004	0.005
0.10	256	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.10	256	256	16	1.0000	0.0001	2	1.00	0.005	0.006
0.10	256 256	256 256	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00	0.005	0.006
0.10	256	256	16	0.0100	1.0000	3	1.00	0.004	0.005

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.10	256	256	16	0.0100	0.0100	2	1.00	0.004	0.006
0.10	256	256	16	0.0100	0.0100	3	1.00	0.005	0.006
0.10	256	256	16	0.0100	0.0001	2	1.00	0.005	0.006
0.10	256 256	256 256	16 16	0.0100	0.0001 1.0000	3	1.00	0.005	0.007
0.10	256	256	16	0.0001	1.0000	3	1.00	0.005	0.006
0.10	256	256	16	0.0001	0.0100	2	1.00	0.006	0.007
0.10	256	256	16	0.0001	0.0100	3	1.00	0.006	0.007
0.10	256	256	16	0.0001	0.0001	2	1.00	0.007	0.008
0.10	256	256	16	0.0001	0.0001	3	1.00	0.007	0.007
0.10	256	256	64	1.0000	1.0000	2	1.00	0.007	0.014
0.10	256	256	64	1.0000	1.0000	3	1.00	0.006	0.008
0.10	256 256	256	64	1.0000	0.0100	2	1.00	0.008	0.011
0.10	256	256 256	64	1.0000	0.0100	3	1.00	0.008	0.011
0.10	256	256	64	1.0000	0.0001	3	1.00	0.014	0.015
0.10	256	256	64	0.0100	1.0000	2	1.00	0.008	0.013
0.10	256	256	64	0.0100	1.0000	3	1.00	0.007	0.011
0.10	256	256	64	0.0100	0.0100	2	1.00	0.010	0.014
0.10	256	256	64	0.0100	0.0100	3	1.00	0.010	0.012
0.10	256	256	64	0.0100	0.0001	2	1.00	0.011	0.015
0.10	256	256	64	0.0100	0.0001	3	1.00	0.011	0.016
0.10	256 256	256	64	0.0001	1.0000	3	1.00	0.010	0.015
0.10	256	256 256	64	0.0001	1.0000 0.0100	2	1.00	0.010	0.016
0.10	256	256	64	0.0001	0.0100	3	1.00	0.012	0.019
0.10	256	256	64	0.0001	0.0001	2	1.00	0.011	0.022
0.10	256	256	64	0.0001	0.0001	3	1.00	0.014	0.021
0.10	256	256	256	1.0000	1.0000	2	1.00	0.021	0.026
0.10	256	256	256	1.0000	1.0000	3	1.00	0.021	0.029
0.10	256	256	256	1.0000	0.0100	2	1.00	0.032	0.034
0.10	256	256	256	1.0000	0.0100	3	1.00	0.032	0.035
0.10	256 256	256 256	256 256	1.0000	0.0001	2	1.00	0.047	0.075 0.075
0.10	256	256	256	0.0100	1.0000	2	1.00	0.049	0.073
0.10	256	256	256	0.0100	1.0000	3	1.00	0.039	0.052
0.10	256	256	256	0.0100	0.0100	2	1.00	0.047	0.079
0.10	256	256	256	0.0100	0.0100	3	1.00	0.047	0.078
0.10	256	256	256	0.0100	0.0001	2	1.00	0.069	0.095
0.10	256	256	256	0.0100	0.0001	3	1.00	0.085	0.100
0.10	256	256	256	0.0001	1.0000	2	1.00	0.057	0.079
0.10	256	256	256	0.0001	1.0000	3	1.00	0.050	0.083
0.10	256 256	256 256	256 256	0.0001	0.0100	3	1.00	0.067	0.101
0.10	256	256	256	0.0001	0.0001	2	1.00	0.071	0.101
0.10	256	256	256	0.0001	0.0001	3	1.00	0.084	0.102
0.20	1	1	1	1.0000	1.0000	2	1.00	0.002	0.003
0.20	1	1	1	1.0000	1.0000	3	1.00	0.002	0.003
0.20	1	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	1	1	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	1	1	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	1	1	1	1.0000 0.0100	0.0001 1.0000	3	1.00	0.002	0.003
0.20	1	1	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	1	1	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	1	1	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	1	1	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	1	1	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	1	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	1	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	1	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	1	1	1	0.0001	0.0001	2	1.00	0.003	0.004
0.20	1	1	1	0.0001	0.0001	3	1.00	0.002	0.003
0.20	1	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	1	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	1	1	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	1	1	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	1	1	4	1.0000	0.0001	2	1.00	0.003	0.003
0.20	1	1	4	1.0000 0.0100	0.0001 1.0000	2	1.00	0.003	0.003
0.20	1	1	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	1	1	4	0.0100	0.0100	2	1.00	0.003	0.003
									0.003
0.20	1	1	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	1	1	4 4 4	0.0100	0.0100	2	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	1	1	4	0.0001	1.0000	2	1.00	0.003	0.003
0.20	1	1	4	0.0001	1.0000	3	1.00	0.003	0.003
0.20	1	1	4	0.0001	0.0100	3	1.00	0.003	0.003
0.20	1	1	4	0.0001	0.0100	2	1.00	0.003	0.003
0.20	1	1	4	0.0001	0.0001	3	1.00	0.003	0.003
0.20	1	1	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	1	1	16 16	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.20	1	1	16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	1	1	16	1.0000	0.0001	2	1.00	0.004	0.004
0.20	1	1	16	1.0000	0.0001	3	1.00	0.004	0.004
0.20	1	1	16 16	0.0100	1.0000	3	1.00	0.004	0.004
0.20	1	1	16	0.0100	0.0100	2	1.00	0.004	0.004
0.20	1	1	16	0.0100	0.0100	3	1.00	0.004	0.004
0.20	1	1	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	1	1	16 16	0.0100	0.0001 1.0000	3	1.00	0.004	0.005
0.20	1	1	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	1	1	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	1	1	16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	1	1	16 16	0.0001	0.0001	3	1.00	0.005	0.005
0.20	1	1	64	1.0000	1.0000	2	1.00	0.005	0.003
0.20	1	1	64	1.0000	1.0000	3	1.00	0.007	0.010
0.20	1	1	64	1.0000	0.0100	2	1.00	0.008	0.011
0.20	1	1	64 64	1.0000	0.0100	3	1.00	0.008	0.011
0.20	1	1	64	1.0000	0.0001	3	1.00	0.009	0.013
0.20	1	1	64	0.0100	1.0000	2	1.00	0.008	0.012
0.20	1	1	64	0.0100	1.0000	3	1.00	0.008	0.012
0.20	1	1	64	0.0100	0.0100	3	1.00	0.008	0.014
0.20	1	1	64	0.0100	0.0100	2	1.00	0.008	0.013
0.20	1	1	64	0.0100	0.0001	3	1.00	0.016	0.018
0.20	1	1	64	0.0001	1.0000	2	1.00	0.011	0.016
0.20	1	1	64 64	0.0001	1.0000 0.0100	3	1.00	0.011	0.017
0.20	1	1	64	0.0001	0.0100	3	1.00	0.016	0.017
0.20	1	1	64	0.0001	0.0001	2	1.00	0.017	0.022
0.20	1	1	64	0.0001	0.0001	3	1.00	0.015	0.022
0.20	1	1	256 256	1.0000	1.0000	3	1.00	0.023	0.075
0.20	1	1	256	1.0000	0.0100	2	1.00	0.024	0.055
0.20	1	1	256	1.0000	0.0100	3	1.00	0.046	0.055
0.20	1	1	256	1.0000	0.0001	2	1.00	0.045	0.046
0.20	1	1	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00	0.045	0.047
0.20	1	1	256	0.0100	1.0000	3	1.00	0.035	0.057
0.20	1	1	256	0.0100	0.0100	2	1.00	0.052	0.077
0.20	1	1	256	0.0100	0.0100	3	1.00	0.053	0.078
0.20	1	1	256 256	0.0100	0.0001	3	1.00	0.073	0.086
0.20	1	1	256	0.0001	1.0000	2	1.00	0.052	0.082
0.20	1	1	256	0.0001	1.0000	3	1.00	0.051	0.082
0.20	1	1	256 256	0.0001	0.0100	3	1.00	0.063	0.076 0.087
0.20	1	1	256	0.0001	0.0100	2	1.00	0.065	0.087
0.20	1	1	256	0.0001	0.0001	3	1.00	0.073	0.084
0.20	1	4	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	1	4	1	1.0000	1.0000 0.0100	3	1.00	0.003	0.003
0.20	1	4	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	1	4	1	1.0000	0.0001	2	1.00	0.002	0.003
0.20	1	4	1	1.0000	0.0001	3	1.00	0.002	0.003
0.20	1	4	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	1	4	1	0.0100	0.0100	2	1.00	0.002	0.003
0.20	1	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	1	4	1	0.0100	0.0001	2	1.00	0.002	0.003
0.20	1	4	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	1	4	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	1	4	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	1	4	1	0.0001	0.0100	3	1.00	0.003	0.003

0.20	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	0.20	1	4	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	0.20	1	4	1	0.0001	0.0001	3	1.00	0.003	0.004
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20	0.20	1	4	4	0.0100	0.0100		1.00	0.003	0.004
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20		1	4	4			3			
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20	0.20	1	4	16	0.0100	0.0100	3	1.00	0.005	0.006
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20 1 4 64 1.0000 0.0100 2 1.00 0.007 0.008 0.20 1 4 64 1.0000 0.0100 3 1.00 0.007 0.009 0.20 1 4 64 1.0000 0.0001 2 1.00 0.009 0.010 0.20 1 4 64 1.0000 0.0001 3 1.00 0.008 0.008 0.20 1 4 64 0.0100 1.0000 3 1.00 0.008 0.008 0.20 1 4 64 0.0100 0.0100 2 1.00 0.008 0.008 0.20 1 4 64 0.0100 0.0100 3 1.00 0.009 0.011 0.20 1 4 64 0.0100 0.0001 3 1.00 0.010 0.012 0.20 1 4 64 0.0001 1.0000 2 1.00	0.20	1	4	64	1.0000	1.0000		1.00	0.006	0.013
0.20 1 4 64 1.0000 0.0100 3 1.00 0.007 0.009 0.20 1 4 64 1.0000 0.0001 2 1.00 0.009 0.010 0.20 1 4 64 1.0000 0.0001 3 1.00 0.009 0.010 0.20 1 4 64 0.0100 1.0000 3 1.00 0.008 0.008 0.20 1 4 64 0.0100 0.0100 3 1.00 0.009 0.010 0.20 1 4 64 0.0100 0.0100 3 1.00 0.009 0.011 0.20 1 4 64 0.0100 0.0100 3 1.00 0.010 0.012 0.20 1 4 64 0.0010 0.0001 3 1.00 0.011 0.012 0.20 1 4 64 0.0001 1.0000 3 1.00	0.20	1	4	64	1.0000	1.0000		1.00	0.006	0.011
0.20										
0.20 1 4 64 1.0000 0.0001 3 1.00 0.009 0.010 0.20 1 4 64 0.0100 1.0000 2 1.00 0.008 0.008 0.20 1 4 64 0.0100 1.0000 3 1.00 0.009 0.018 0.20 1 4 64 0.0100 0.0100 2 1.00 0.009 0.011 0.20 1 4 64 0.0100 0.0001 3 1.00 0.009 0.011 0.20 1 4 64 0.0100 0.0001 3 1.00 0.010 0.012 0.20 1 4 64 0.0100 1.0000 3 1.00 0.010 0.012 0.20 1 4 64 0.0001 1.0000 3 1.00 0.010 0.015 0.20 1 4 64 0.0001 0.0100 3 1.00										
0.20										
0.20 1 4 64 0.0100 1.0000 3 1.00 0.008 0.008 0.20 1 4 64 0.0100 0.0100 2 1.00 0.009 0.010 0.20 1 4 64 0.0100 0.0001 3 1.00 0.009 0.011 0.20 1 4 64 0.0100 0.0001 2 1.00 0.010 0.011 0.20 1 4 64 0.0010 1.0000 2 1.00 0.010 0.015 0.20 1 4 64 0.0001 1.0000 3 1.00 0.010 0.015 0.20 1 4 64 0.0001 1.0000 3 1.00 0.010 0.016 0.20 1 4 64 0.0001 0.0100 3 1.00 0.017 0.018 0.20 1 4 64 0.0001 0.0001 3 1.00										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.20 1 4 64 0.0100 0.0001 3 1.00 0.011 0.012 0.20 1 4 64 0.0001 1.0000 2 1.00 0.010 0.015 0.20 1 4 64 0.0001 1.0000 3 1.00 0.010 0.015 0.20 1 4 64 0.0001 0.0100 2 1.00 0.013 0.018 0.20 1 4 64 0.0001 0.0001 2 1.00 0.017 0.018 0.20 1 4 64 0.0001 0.0001 2 1.00 0.021 0.023 0.20 1 4 64 0.0001 0.0001 3 1.00 0.021 0.023 0.20 1 4 256 1.0000 1.0000 2 1.00 0.024 0.080 0.20 1 4 256 1.0000 0.0100 3 1.	0.20	1	4		0.0100	0.0100	3	1.00	0.009	0.011
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$				64	0.0100	0.0001		1.00	0.010	0.012
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.20 1 4 64 0.0001 0.0100 2 1.00 0.013 0.018 0.20 1 4 64 0.0001 0.0100 3 1.00 0.017 0.018 0.20 1 4 64 0.0001 0.0001 2 1.00 0.021 0.023 0.20 1 4 64 0.0001 1.0000 2 1.00 0.024 0.080 0.20 1 4 256 1.0000 1.0000 3 1.00 0.023 0.036 0.20 1 4 256 1.0000 0.0100 2 1.00 0.035 0.039 0.20 1 4 256 1.0000 0.0100 3 1.00 0.035 0.036 0.20 1 4 256 1.0000 0.0001 3 1.00 0.048 0.059 0.20 1 4 256 1.0000 0.0001 3 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.20 1 4 64 0.0001 0.0001 3 1.00 0.020 0.023 0.20 1 4 256 1.0000 1.0000 2 1.00 0.024 0.080 0.20 1 4 256 1.0000 1.0000 3 1.00 0.023 0.036 0.20 1 4 256 1.0000 0.0100 2 1.00 0.035 0.039 0.20 1 4 256 1.0000 0.0100 3 1.00 0.035 0.036 0.20 1 4 256 1.0000 0.0001 2 1.00 0.035 0.036 0.20 1 4 256 1.0000 0.0001 3 1.00 0.046 0.049 0.20 1 4 256 0.0100 1.0000 2 1.00 0.036 0.038 0.20 1 4 256 0.0100 1.0000 3										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.20	1		256		1.0000	2	1.00	0.024	0.080
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.20 1 4 256 0.0100 0.0001 3 1.00 0.059 0.089 0.20 1 4 256 0.0001 1.0000 2 1.00 0.053 0.070 0.20 1 4 256 0.0001 1.0000 3 1.00 0.053 0.057 0.20 1 4 256 0.0001 0.0100 2 1.00 0.064 0.069 0.20 1 4 256 0.0001 0.0100 3 1.00 0.064 0.067 0.20 1 4 256 0.0001 0.0001 2 1.00 0.064 0.067 0.20 1 4 256 0.0001 0.0001 2 1.00 0.075 0.080 0.20 1 4 256 0.0001 0.0001 3 1.00 0.076 0.082 0.20 1 4 256 0.0001 0.0001 3	0.20			256	0.0100	0.0100		1.00	0.048	0.058
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.20 1 4 256 0.0001 0.0100 2 1.00 0.064 0.069 0.20 1 4 256 0.0001 0.0100 3 1.00 0.064 0.067 0.20 1 4 256 0.0001 0.0001 2 1.00 0.075 0.080 0.20 1 4 256 0.0001 0.0001 3 1.00 0.076 0.082 0.20 1 16 1 1.0000 1.0000 2 1.00 0.003 0.003										
0.20 1 4 256 0.0001 0.0100 3 1.00 0.064 0.067 0.20 1 4 256 0.0001 0.0001 2 1.00 0.075 0.080 0.20 1 4 256 0.0001 0.0001 3 1.00 0.076 0.082 0.20 1 16 1 1.0000 1.0000 2 1.00 0.003 0.003										
0.20 1 4 256 0.0001 0.0001 2 1.00 0.075 0.080 0.20 1 4 256 0.0001 0.0001 3 1.00 0.076 0.082 0.20 1 16 1 1.0000 1.0000 2 1.00 0.003 0.003										
0.20 1 4 256 0.0001 0.0001 3 1.00 0.076 0.082 0.20 1 16 1 1.0000 1.0000 2 1.00 0.003 0.003										
0.20 1 16 1 1.0000 1.0000 2 1.00 0.003 0.003										
0.20 1 10 1 1.0000 1.0000 3 1.00 0.002 0.003	0.20	1	16	1	1.0000	1.0000	3	1.00	0.002	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	1	16	1	1.0000	0.0100	2	1.00	0.002	0.003
0.20	1	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	1	16	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	1	16 16	1	1.0000 0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.20	1	16	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	1	16	1	0.0100	0.0100	2	1.00	0.002	0.003
0.20	1	16	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	1	16	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	1	16	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	1	16	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	1	16 16	1	0.0001	1.0000 0.0100	3	1.00	0.002	0.003
0.20	1	16	1	0.0001	0.0100	3	1.00	0.002	0.003
0.20	1	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	1	16	1	0.0001	0.0001	3	1.00	0.002	0.003
0.20	1	16	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	1	16	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	1	16 16	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	1	16	4	1.0000	0.0001	2	1.00	0.003	0.003
0.20	1	16	4	1.0000	0.0001	3	1.00	0.003	0.003
0.20	1	16	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	1	16	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	1	16	4	0.0100	0.0100	2	1.00	0.003	0.003
0.20	1	16	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	1	16 16	4	0.0100	0.0001	3	1.00	0.003	0.004
0.20	1	16	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	1	16	4	0.0001	1.0000	3	1.00	0.003	0.003
0.20	1	16	4	0.0001	0.0100	2	1.00	0.003	0.003
0.20	1	16	4	0.0001	0.0100	3	1.00	0.003	0.003
0.20	1	16	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	1	16 16	4 16	0.0001 1.0000	0.0001 1.0000	3 2	1.00	0.003	0.003
0.20	1	16	16	1.0000	1.0000	3	1.00	0.003	0.003
0.20	1	16	16	1.0000	0.0100	2	1.00	0.004	0.004
0.20	1	16	16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	1	16	16	1.0000	0.0001	2	1.00	0.004	0.004
0.20	1	16	16	1.0000	0.0001	3	1.00	0.004	0.004
0.20	1	16	16	0.0100	1.0000	2	1.00	0.004	0.004
0.20	1	16 16	16 16	0.0100	1.0000 0.0100	3	1.00	0.004	0.004
0.20	1	16	16	0.0100	0.0100	3	1.00	0.004	0.004
0.20	1	16	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	1	16	16	0.0100	0.0001	3	1.00	0.004	0.005
0.20	1	16	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	1	16	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	1	16 16	16 16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	1	16	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	1	16	16	0.0001	0.0001	3	1.00	0.004	0.005
0.20	1	16	64	1.0000	1.0000	2	1.00	0.006	0.009
0.20	1	16	64	1.0000	1.0000	3	1.00	0.006	0.009
0.20	1	16	64	1.0000	0.0100	2	1.00	0.008	0.011
0.20	1	16	64 64	1.0000	0.0100	3	1.00	0.008	0.011
0.20	1	16 16	64	1.0000 1.0000	0.0001	3	1.00	0.009	0.010 0.009
0.20	1	16	64	0.0100	1.0000	2	1.00	0.009	0.009
0.20	1	16	64	0.0100	1.0000	3	1.00	0.008	0.011
0.20	1	16	64	0.0100	0.0100	2	1.00	0.009	0.013
0.20	1	16	64	0.0100	0.0100	3	1.00	0.010	0.012
0.20	1	16	64	0.0100	0.0001	2	1.00	0.011	0.014
0.20	1	16 16	64	0.0100	0.0001 1.0000	3	1.00	0.011	0.015
0.20	1	16	64	0.0001	1.0000	3	1.00	0.011	0.013
0.20	1	16	64	0.0001	0.0100	2	1.00	0.010	0.012
0.20	1	16	64	0.0001	0.0100	3	1.00	0.011	0.013
0.20	1	16	64	0.0001	0.0001	2	1.00	0.016	0.022
0.20	1	16	64	0.0001	0.0001	3	1.00	0.014	0.021
0.20	1	16	256	1.0000	1.0000	2	1.00	0.025	0.058
0.20	1	16 16	256 256	1.0000	1.0000 0.0100	3	1.00	0.023	0.041
0.20	1	16	256	1.0000	0.0100	3	1.00	0.033	0.059
0.20	1	16	256	1.0000	0.0001	2	1.00	0.046	0.037
0.20	1	16	256	1.0000	0.0001	3	1.00	0.046	0.058

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	1	16	256	0.0100	1.0000	2	1.00	0.036	0.051
0.20	1	16	256	0.0100	1.0000	3	1.00	0.036	0.049
0.20	1	16	256	0.0100	0.0100	2	1.00	0.047	0.053
0.20	1	16	256	0.0100	0.0100	3	1.00	0.049	0.051
0.20	1	16	256	0.0100	0.0001	2	1.00	0.058	0.067
0.20	1	16 16	256 256	0.0100	1.0000	2	1.00	0.060	0.067 0.067
0.20	1	16	256	0.0001	1.0000	3	1.00	0.053	0.065
0.20	1	16	256	0.0001	0.0100	2	1.00	0.057	0.064
0.20	1	16	256	0.0001	0.0100	3	1.00	0.057	0.065
0.20	1	16	256	0.0001	0.0001	2	1.00	0.073	0.107
0.20	1	16	256	0.0001	0.0001	3	1.00	0.075	0.103
0.20	1	64	1	1.0000	1.0000	3	1.00	0.002	0.003
0.20	1	64	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	1	64	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	1	64	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	1	64	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	1	64	1	0.0100	1.0000	2	1.00	0.002	0.003
0.20	1	64	1	0.0100	1.0000	2	1.00	0.002	0.003
0.20	1	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	1	64	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	1	64	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	1	64	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	1	64	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	1	64	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	1	64	1	0.0001	0.0100	2	1.00	0.003	0.003 0.003
0.20	1	64	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	1	64	4	1.0000	1.0000	2	1.00	0.003	0.004
0.20	1	64	4	1.0000	1.0000	3	1.00	0.003	0.004
0.20	1	64	4	1.0000	0.0100	2	1.00	0.003	0.004
0.20	1	64	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	1	64	4	1.0000	0.0001	3	1.00	0.003	0.004 0.004
0.20	1	64	4	0.0100	1.0000	2	1.00	0.003	0.004
0.20	1	64	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	1	64	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	1	64	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	1	64	4	0.0100	0.0001	2	1.00	0.004	0.004
0.20	1	64	4	0.0100	1.0000	2	1.00 0.83	0.004	0.004
0.20	1	64	4	0.0001	1.0000	3	0.83	0.002	0.004
0.20	1	64	4	0.0001	0.0100	2	1.00	0.004	0.004
0.20	1	64	4	0.0001	0.0100	3	1.00	0.004	0.004
0.20	1	64	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	1	64	4	0.0001	0.0001	3	1.00	0.003	0.004
0.20	1	64	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	1	64	16 16	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.20	1	64	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	1	64	16	1.0000	0.0001	2	1.00	0.004	0.006
0.20	1	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.20	1	64	16	0.0100	1.0000	2	1.00	0.004	0.004
0.20	1	64	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	1	64	16 16	0.0100	0.0100	3	1.00	0.004	0.005 0.005
0.20	1	64	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	1	64	16	0.0100	0.0001	3	1.00	0.004	0.007
0.20	1	64	16	0.0001	1.0000	2	1.00	0.004	0.006
0.20	1	64	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	1	64	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	1	64	16 16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	1	64	16	0.0001	0.0001	3	1.00	0.005	0.006
0.20	1	64	64	1.0000	1.0000	2	1.00	0.005	0.009
0.20	1	64	64	1.0000	1.0000	3	1.00	0.006	0.009
0.20	1	64	64	1.0000	0.0100	2	1.00	0.009	0.012
0.20	1	64	64	1.0000	0.0100	3	1.00	0.011	0.012
0.20	1	64	64	1.0000	0.0001	2	1.00	0.010	0.015
0.20	1	64	64	1.0000 0.0100	1.0000	3	1.00	0.010	0.014
0.20	1	64	64	0.0100	1.0000	3	1.00	0.008	0.010 0.010
0.20	1	64	64	0.0100	0.0100	2	1.00	0.008	0.010
0.20	1	64	64	0.0100	0.0100	3	1.00	0.010	0.012
					. "	-			-

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	1	64	64	0.0100	0.0001	2	1.00	0.011	0.013
0.20	1	64	64	0.0100	0.0001	3	1.00	0.011	0.014
0.20	1	64	64	0.0001	1.0000	3	1.00	0.011	0.017 0.017
0.20	1	64	64	0.0001	0.0100	2	1.00	0.011	0.017
0.20	1	64	64	0.0001	0.0100	3	1.00	0.011	0.019
0.20	1	64	64	0.0001	0.0001	2	1.00	0.013	0.014
0.20	1	64	64	0.0001	0.0001	3	1.00	0.013	0.015
0.20	1	64	256	1.0000	1.0000	2	1.00	0.023	0.024
0.20	1	64	256 256	1.0000	1.0000 0.0100	2	1.00	0.023	0.024
0.20	1	64	256	1.0000	0.0100	3	1.00	0.033	0.054
0.20	1	64	256	1.0000	0.0001	2	1.00	0.044	0.069
0.20	1	64	256	1.0000	0.0001	3	1.00	0.044	0.072
0.20	1	64	256	0.0100	1.0000	2	1.00	0.032	0.049
0.20	1	64	256 256	0.0100	1.0000 0.0100	3	1.00	0.035	0.087
0.20	1	64	256	0.0100	0.0100	3	1.00	0.052	0.078
0.20	1	64	256	0.0100	0.0001	2	1.00	0.058	0.064
0.20	1	64	256	0.0100	0.0001	3	1.00	0.057	0.064
0.20	1	64	256	0.0001	1.0000	2	1.00	0.050	0.083
0.20	1	64	256 256	0.0001 0.0001	1.0000 0.0100	3	1.00	0.051 0.062	0.082
0.20	1	64	256	0.0001	0.0100	3	1.00	0.062	0.065
0.20	1	64	256	0.0001	0.0001	2	1.00	0.080	0.100
0.20	1	64	256	0.0001	0.0001	3	1.00	0.081	0.124
0.20	1	256	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	1	256 256	1	1.0000	1.0000 0.0100	3	1.00	0.003	0.003
0.20	1	256	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	1	256	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	1	256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	1	256	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	1	256 256	1	0.0100	1.0000 0.0100	3	1.00	0.003	0.003
0.20	1	256	1	0.0100	0.0100	3	1.00	0.002	0.003
0.20	1	256	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	1	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	1	256	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	1	256 256	1	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.20	1	256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	1	256	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	1	256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	1	256	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	1	256 256	4	1.0000	1.0000 0.0100	3	1.00	0.003	0.003
0.20	1	256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	1	256	4	1.0000	0.0001	2	1.00	0.003	0.003
0.20	1	256	4	1.0000	0.0001	3	1.00	0.003	0.023
0.20	1	256	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	1	256 256	4	0.0100	1.0000 0.0100	3 2	1.00	0.003	0.003 0.003
0.20	1	256	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	1	256	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	1	256	4	0.0100	0.0001	3	1.00	0.003	0.004
0.20	1	256	4	0.0001	1.0000	2	1.00	0.003	0.003
0.20	1	256 256	4	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.20	1	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	1	256	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	1	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.20	1	256	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	1	256 256	16 16	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.20	1	256	16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	1	256	16	1.0000	0.0001	2	1.00	0.004	0.005
0.20	1	256	16	1.0000	0.0001	3	1.00	0.004	0.006
0.20	1	256	16	0.0100	1.0000	2	1.00	0.004	0.004
0.20	1	256 256	16 16	0.0100	1.0000 0.0100	2	1.00	0.004	0.004
0.20	1	256	16	0.0100	0.0100	3	1.00	0.004	0.005
0.20	1	256	16	0.0100	0.0001	2	1.00	0.005	0.005
0.20	1	256	16	0.0100	0.0001	3	1.00	0.004	0.005
0.20	1	256	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	1	256	16	0.0001	1.0000	3	1.00	0.004	0.005

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	1	256	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	1	256	16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	1	256	16	0.0001	0.0001	2	1.00	0.005	0.006
0.20	1	256	16	0.0001 1.0000	0.0001	3	1.00	0.005	0.005
0.20	1	256 256	64 64	1.0000	1.0000	3	1.00	0.006	0.007
0.20	1	256	64	1.0000	0.0100	2	1.00	0.008	0.007
0.20	1	256	64	1.0000	0.0100	3	1.00	0.008	0.012
0.20	1	256	64	1.0000	0.0001	2	1.00	0.010	0.015
0.20	1	256	64	1.0000	0.0001	3	1.00	0.010	0.016
0.20	1	256	64	0.0100	1.0000	2	1.00	0.008	0.010
0.20	1	256	64	0.0100	1.0000	3	1.00	0.008	0.010
0.20	1	256	64	0.0100	0.0100	2	1.00	0.010	0.013
0.20	1	256 256	64	0.0100	0.0100	3	1.00	0.010	0.013 0.015
0.20	1	256	64	0.0100	0.0001	3	1.00	0.012	0.015
0.20	1	256	64	0.0001	1.0000	2	1.00	0.011	0.013
0.20	1	256	64	0.0001	1.0000	3	1.00	0.011	0.014
0.20	1	256	64	0.0001	0.0100	2	1.00	0.011	0.018
0.20	1	256	64	0.0001	0.0100	3	1.00	0.011	0.018
0.20	1	256	64	0.0001	0.0001	2	1.00	0.015	0.023
0.20	1	256	64	0.0001	0.0001	3	1.00	0.018	0.022
0.20	1	256	256	1.0000	1.0000	2	1.00	0.034	0.035
0.20	1	256	256	1.0000	1.0000	3	1.00	0.032	0.035
0.20	1	256 256	256 256	1.0000	0.0100	3	1.00	0.051	0.053
0.20	1	256	256	1.0000	0.0001	2	1.00	0.037	0.033
0.20	1	256	256	1.0000	0.0001	3	1.00	0.074	0.075
0.20	1	256	256	0.0100	1.0000	2	1.00	0.051	0.079
0.20	1	256	256	0.0100	1.0000	3	1.00	0.051	0.078
0.20	1	256	256	0.0100	0.0100	2	1.00	0.053	0.077
0.20	1	256	256	0.0100	0.0100	3	1.00	0.075	0.078
0.20	1	256	256	0.0100	0.0001	2	1.00	0.061	0.094
0.20	1	256	256	0.0100	0.0001	3	1.00	0.061	0.095
0.20	1	256 256	256 256	0.0001	1.0000	3	1.00	0.051	0.054
0.20	1	256	256	0.0001	0.0100	2	1.00	0.051	0.098
0.20	1	256	256	0.0001	0.0100	3	1.00	0.074	0.098
0.20	1	256	256	0.0001	0.0001	2	1.00	0.093	0.115
0.20	1	256	256	0.0001	0.0001	3	1.00	0.096	0.119
0.20	4	1	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	4	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	4	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	4	1	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	4	1	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	4	1	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	4	1	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	4	1	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	4	1	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	4	1	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	4	1	1	0.0100	0.0001	3	1.00	0.003	0.004
0.20	4	1	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	4	1	1	0.0001	0.0100	2	1.00	0.002	0.003
0.20	4	1	1	0.0001	0.0100	3	1.00	0.002	0.003
0.20	4	1	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	4	1	1	0.0001	0.0001	3	1.00	0.002	0.003
0.20	4	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	4	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	4	1	4	1.0000	0.0100	2	1.00	0.003	0.004
0.20	4	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	4	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	4	1	4	0.0100	1.0000	2	1.00	0.003	0.004
0.20	4	1	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	4	1	4	0.0100	0.0100	2	1.00	0.003	0.003
0.20	4	1	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	4	1	4	0.0100	0.0001	2	1.00	0.003	0.003
0.20	4	1	4	0.0100	0.0001	3	1.00	0.003	0.003
0.20	4	1	4	0.0001	1.0000	2	1.00	0.003	0.003
0.20	4	1	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	4	1	4	0.0001	0.0100	2	1.00	0.003	0.003
0.20	4	1	4	0.0001	0.0100	3	1.00	0.003	0.003
0.20	4	1	4	0.0001	0.0001	3	1.00	0.003	0.003
5.20	+	1	-	0.0001	0.0001	,	1.00	0.003	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	4	1	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	4	1	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	4	1	16 16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	4	1	16	1.0000	0.0100	2	1.00	0.004	0.004
0.20	4	1	16	1.0000	0.0001	3	1.00	0.004	0.004
0.20	4	1	16	0.0100	1.0000	2	1.00	0.004	0.004
0.20	4	1	16	0.0100	1.0000	3	1.00	0.004	0.004
0.20	4	1	16 16	0.0100	0.0100	3	1.00	0.004	0.004
0.20	4	1	16	0.0100	0.0100	2	1.00	0.004	0.004
0.20	4	1	16	0.0100	0.0001	3	1.00	0.004	0.005
0.20	4	1	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	4	1	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	4	1	16 16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	4	1	16	0.0001	0.0001	2	1.00	0.004	0.005
0.20	4	1	16	0.0001	0.0001	3	1.00	0.005	0.006
0.20	4	1	64	1.0000	1.0000	2	1.00	0.006	0.007
0.20	4	1	64	1.0000	1.0000	3	1.00	0.006	0.007
0.20	4	1	64 64	1.0000	0.0100	3	1.00	0.007	0.008
0.20	4	1	64	1.0000	0.0001	2	1.00	0.007	0.014
0.20	4	1	64	1.0000	0.0001	3	1.00	0.009	0.014
0.20	4	1	64	0.0100	1.0000	2	1.00	0.008	0.011
0.20	4	1	64 64	0.0100	1.0000 0.0100	3	1.00	0.008	0.011
0.20	4	1	64	0.0100	0.0100	3	1.00	0.009	0.014
0.20	4	1	64	0.0100	0.0001	2	1.00	0.016	0.018
0.20	4	1	64	0.0100	0.0001	3	1.00	0.016	0.018
0.20	4	1	64	0.0001	1.0000	2	1.00	0.013	0.017
0.20	4	1	64	0.0001	1.0000 0.0100	3	1.00	0.013	0.016
0.20	4	1	64	0.0001	0.0100	3	1.00	0.016	0.018
0.20	4	1	64	0.0001	0.0001	2	1.00	0.022	0.022
0.20	4	1	64	0.0001	0.0001	3	1.00	0.022	0.022
0.20	4	1	256	1.0000	1.0000	2	1.00	0.025	0.035
0.20	4	1	256 256	1.0000	1.0000 0.0100	3	1.00	0.024	0.035
0.20	4	1	256	1.0000	0.0100	3	1.00	0.034	0.037
0.20	4	1	256	1.0000	0.0001	2	1.00	0.049	0.072
0.20	4	1	256	1.0000	0.0001	3	1.00	0.049	0.072
0.20	4	1	256 256	0.0100	1.0000	2	1.00	0.034	0.077
0.20	4	1	256	0.0100	0.0100	2	1.00	0.034	0.030
0.20	4	1	256	0.0100	0.0100	3	1.00	0.048	0.079
0.20	4	1	256	0.0100	0.0001	2	1.00	0.088	0.102
0.20	4	1	256	0.0100	0.0001	3	1.00	0.098	0.102
0.20	4	1	256 256	0.0001	1.0000	3	1.00	0.080	0.083
0.20	4	1	256	0.0001	0.0100	2	1.00	0.059	0.089
0.20	4	1	256	0.0001	0.0100	3	1.00	0.059	0.099
0.20	4	1	256	0.0001	0.0001	2	1.00	0.076	0.116
0.20	4	1 4	256 1	0.0001 1.0000	0.0001 1.0000	3	1.00	0.076	0.680
0.20	4	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	4	4	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	4	4	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	4	4	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	4	4	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	4	4	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	4	4	1	0.0100	0.0100	2	1.00	0.002	0.004
0.20	4	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	4	4	1	0.0100	0.0001	3	1.00	0.003	0.004
0.20	4	4	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	4	4	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	4	4	1	0.0001	0.0100	2	1.00	0.002	0.003
0.20	4	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	4	4	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	4	4	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	4	4	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	4	4	4	1.0000	0.0100	2	1.00	0.003	0.004
0.20	4	4	4	1.0000	0.0100	3	1.00	0.003	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	4	4	4	1.0000	0.0001	2	1.00	0.004	0.004
0.20	4	4	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	4	4	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	4	4	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	4	4	4	0.0100	0.0100	2	1.00	0.004	0.004
0.20	4	4	4	0.0100	0.0100	3	1.00	0.004	0.004
0.20	4	4	4	0.0100	0.0001	3	1.00	0.004	0.004
0.20	4	4	4	0.0001	1.0000	2	1.00	0.004	0.004
0.20	4	4	4	0.0001	1.0000	3	1.00	0.004	0.004
0.20	4	4	4	0.0001	0.0100	2	1.00	0.004	0.004
0.20	4	4	4	0.0001	0.0100	3	1.00	0.004	0.004
0.20	4	4	4	0.0001	0.0001	2	1.00	0.004	0.004
0.20	4	4	4	0.0001	0.0001	3	1.00	0.004	0.004
0.20	4	4	16	1.0000	1.0000	2	1.00	0.004	0.004
0.20	4	4	16 16	1.0000	1.0000 0.0100	3	1.00	0.004	0.005
0.20	4	4	16	1.0000	0.0100	3	1.00	0.005	0.005
0.20	4	4	16	1.0000	0.0001	2	1.00	0.003	0.006
0.20	4	4	16	1.0000	0.0001	3	1.00	0.004	0.005
0.20	4	4	16	0.0100	1.0000	2	1.00	0.004	0.004
0.20	4	4	16	0.0100	1.0000	3	1.00	0.004	0.004
0.20	4	4	16	0.0100	0.0100	2	1.00	0.004	0.004
0.20	4	4	16	0.0100	0.0100	3	1.00	0.004	0.004
0.20	4	4	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	4	4	16 16	0.0100	0.0001 1.0000	3	1.00	0.004	0.005
0.20	4	4	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	4	4	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	4	4	16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	4	4	16	0.0001	0.0001	2	1.00	0.005	0.006
0.20	4	4	16	0.0001	0.0001	3	1.00	0.005	0.006
0.20	4	4	64	1.0000	1.0000	2	1.00	0.006	0.007
0.20	4	4	64	1.0000	1.0000	3	1.00	0.006	0.006
0.20	4	4	64	1.0000	0.0100	2	1.00	0.007	0.008
0.20	4	4	64	1.0000	0.0100	3	1.00	0.007	0.008
0.20	4	4	64	1.0000	0.0001	3	1.00	0.009	0.010
0.20	4	4	64	0.0100	1.0000	2	1.00	0.009	0.010
0.20	4	4	64	0.0100	1.0000	3	1.00	0.008	0.009
0.20	4	4	64	0.0100	0.0100	2	1.00	0.010	0.014
0.20	4	4	64	0.0100	0.0100	3	1.00	0.009	0.015
0.20	4	4	64	0.0100	0.0001	2	1.00	0.014	0.017
0.20	4	4	64	0.0100	0.0001	3	1.00	0.011	0.018
0.20	4	4	64	0.0001	1.0000	2	1.00	0.016	0.017
0.20	4	4	64	0.0001	1.0000 0.0100	3	1.00	0.016	0.017 0.018
0.20	4	4	64	0.0001	0.0100	3	1.00	0.017	0.018
0.20	4	4	64	0.0001	0.0001	2	1.00	0.017	0.023
0.20	4	4	64	0.0001	0.0001	3	1.00	0.020	0.022
0.20	4	4	256	1.0000	1.0000	2	1.00	0.028	0.036
0.20	4	4	256	1.0000	1.0000	3	1.00	0.033	0.036
0.20	4	4	256	1.0000	0.0100	2	1.00	0.045	0.070
0.20	4	4	256	1.0000	0.0100	3	1.00	0.045	0.380
0.20	4	4	256 256	1.0000	0.0001	3	1.00	0.045	0.052
0.20	4	4	256	0.0100	1.00001	2	1.00	0.045	0.056
0.20	4	4	256	0.0100	1.0000	3	1.00	0.036	0.050
0.20	4	4	256	0.0100	0.0100	2	1.00	0.047	0.075
0.20	4	4	256	0.0100	0.0100	3	1.00	0.048	0.076
0.20	4	4	256	0.0100	0.0001	2	1.00	0.088	0.098
0.20	4	4	256	0.0100	0.0001	3	1.00	0.084	0.095
0.20	4	4	256	0.0001	1.0000	2	1.00	0.071	0.084
0.20	4	4	256	0.0001	1.0000	3	1.00	0.068	0.097
0.20	4	4	256 256	0.0001	0.0100	3	1.00	0.063	0.197 0.138
0.20	4	4	256	0.0001	0.0100	2	1.00	0.061	0.138
0.20	4	4	256	0.0001	0.0001	3	1.00	0.079	0.123
0.20	4	16	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	4	16	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	4	16	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	4	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	4	16	1	1.0000	0.0001	2	1.00	0.003	0.003
	4	16	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20				0 01	4 0000				
0.20 0.20 0.20	4	16 16	1	0.0100 0.0100	1.0000	2	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	4	16	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	4	16	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	4	16	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	4	16 16	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	4	16	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	4	16	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	4	16	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	4	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	4	16 16	1 4	0.0001 1.0000	0.0001 1.0000	2	1.00	0.003	0.003
0.20	4	16	4	1.0000	1.0000	3	1.00	0.003	0.004
0.20	4	16	4	1.0000	0.0100	2	1.00	0.003	0.004
0.20	4	16	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	4	16	4	1.0000	0.0001	2	1.00	0.003	0.004
0.20	4	16 16	4	0.0100	1.0000	2	1.00	0.003	0.004
0.20	4	16	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	4	16	4	0.0100	0.0100	2	1.00	0.003	0.003
0.20	4	16	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	4	16	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	4	16 16	4	0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.20	4	16	4	0.0001	1.0000	3	1.00	0.003	0.003
0.20	4	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.20	4	16	4	0.0001	0.0100	3	1.00	0.003	0.003
0.20	4	16	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	4	16 16	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00	0.003	0.004
0.20	4	16	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	4	16	16	1.0000	0.0100	2	1.00	0.004	0.004
0.20	4	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	4	16	16	1.0000	0.0001	2	1.00	0.004	0.006
0.20	4	16 16	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00	0.004	0.005 0.005
0.20	4	16	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	4	16	16	0.0100	0.0100	2	1.00	0.004	0.005
0.20	4	16	16	0.0100	0.0100	3	1.00	0.004	0.006
0.20	4	16 16	16 16	0.0100	0.0001	3	1.00	0.004	0.006
0.20	4	16	16	0.0100	0.0001 1.0000	2	1.00	0.004	0.003
0.20	4	16	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	4	16	16	0.0001	0.0100	2	1.00	0.004	0.006
0.20	4	16	16	0.0001	0.0100	3	1.00	0.004	0.006
0.20	4	16 16	16 16	0.0001	0.0001	3	1.00	0.005	0.005
0.20	4	16	64	1.0000	1.0000	2	1.00	0.005	0.007
0.20	4	16	64	1.0000	1.0000	3	1.00	0.006	0.007
0.20	4	16	64	1.0000	0.0100	2	1.00	0.008	0.010
0.20	4	16	64	1.0000	0.0100	3	1.00	0.007	0.008
0.20	4	16 16	64 64	1.0000	0.0001	3	1.00	0.009	0.012
0.20	4	16	64	0.0100	1.0000	2	1.00	0.009	0.011
0.20	4	16	64	0.0100	1.0000	3	1.00	0.008	0.010
0.20	4	16	64	0.0100	0.0100	2	1.00	0.010	0.012
0.20	4	16	64	0.0100	0.0100	3	1.00	0.010	0.011
0.20	4	16 16	64 64	0.0100 0.0100	0.0001	3	1.00	0.011	0.013
0.20	4	16	64	0.0100	1.0000	2	1.00	0.011	0.014
0.20	4	16	64	0.0001	1.0000	3	1.00	0.011	0.013
0.20	4	16	64	0.0001	0.0100	2	1.00	0.011	0.013
0.20	4	16	64	0.0001	0.0100	3	1.00	0.011	0.084
0.20	4	16 16	64 64	0.0001	0.0001	3	1.00	0.013 0.014	0.023
0.20	4	16	256	1.0000	1.0000	2	1.00	0.014	0.022
0.20	4	16	256	1.0000	1.0000	3	1.00	0.034	0.036
0.20	4	16	256	1.0000	0.0100	2	1.00	0.051	0.053
0.20	4	16	256	1.0000	0.0100	3	1.00	0.051	0.053
0.20	4	16 16	256 256	1.0000	0.0001 0.0001	2	1.00	0.045	0.072 0.074
0.20	4	16	256	0.0100	1.0000	2	1.00	0.043	0.074
0.20	4	16	256	0.0100	1.0000	3	1.00	0.037	0.045
0.20	4	16	256	0.0100	0.0100	2	1.00	0.048	0.051
0.20	4	16	256	0.0100	0.0100	3	1.00	0.047	0.077
0.20	4	16 16	256	0.0100	0.0001	2	1.00	0.061	0.101
0.20	4	10	256	0.0100	0.0001	3	1.00	0.002	0.101

0.20		maxt
0.20 4 16 256 0.0001 1.0000 2 1.00	0.052	0.083
0.20 4 16 256 0.0001 1.0000 3 1.00	0.052	0.082
0.20 4 16 256 0.0001 0.0100 2 1.00	0.057	0.061
0.20 4 16 256 0.0001 0.0100 3 1.00 0.20 4 16 256 0.0001 0.0001 2 1.00	0.058	0.085
0.20 4 16 256 0.0001 0.0001 2 1.00 0.20 4 16 256 0.0001 0.0001 3 1.00	0.104	0.128 0.128
0.20 4 64 1 1.0000 1.0000 2 1.00	0.093	0.128
0.20 4 64 1 1.0000 1.0000 3 1.00	0.003	0.003
0.20 4 64 1 1.0000 0.0100 2 1.00	0.003	0.003
0.20 4 64 1 1.0000 0.0100 3 1.00	0.003	0.003
0.20 4 64 1 1.0000 0.0001 2 1.00	0.003	0.003
0.20 4 64 1 1.0000 0.0001 3 1.00	0.003	0.003
0.20 4 64 1 0.0100 1.0000 2 1.00	0.003	0.003
0.20 4 64 1 0.0100 1.0000 3 1.00 0.20 4 64 1 0.0100 0.0100 2 1.00	0.003	0.003
0.20 4 64 1 0.0100 0.0100 2 1.00	0.003	0.003
0.20 4 64 1 0.0100 0.0001 2 1.00	0.003	0.003
0.20 4 64 1 0.0100 0.0001 3 1.00	0.003	0.003
0.20 4 64 1 0.0001 1.0000 2 1.00	0.003	0.003
0.20 4 64 1 0.0001 1.0000 3 1.00	0.003	0.003
0.20 4 64 1 0.0001 0.0100 2 1.00	0.003	0.003
0.20 4 64 1 0.0001 0.0100 3 1.00	0.003	0.003
0.20 4 64 1 0.0001 0.0001 2 1.00 0.20 4 64 1 0.0001 0.0001 3 1.00	0.003	0.003
0.20 4 64 1 0.0001 0.0001 3 1.00	0.003	0.003
0.20 4 64 4 1.0000 1.0000 2 1.00	0.003	0.003
0.20 4 64 4 1.0000 0.0100 2 1.00	0.003	0.003
0.20 4 64 4 1.0000 0.0100 3 1.00	0.003	0.004
0.20 4 64 4 1.0000 0.0001 2 1.00	0.004	0.004
0.20 4 64 4 1.0000 0.0001 3 1.00	0.004	0.004
0.20 4 64 4 0.0100 1.0000 2 1.00	0.003	0.004
0.20 4 64 4 0.0100 1.0000 3 1.00 0.20 4 64 4 0.0100 0.0100 2 1.00	0.003	0.004
0.20 4 64 4 0.0100 0.0100 2 1.00 0.20 4 64 4 0.0100 0.0100 3 1.00	0.004	0.004
0.20 4 64 4 0.0100 0.0001 2 1.00	0.004	0.004
0.20 4 64 4 0.0100 0.0001 3 1.00	0.004	0.004
0.20 4 64 4 0.0001 1.0000 2 1.00	0.004	0.004
0.20 4 64 4 0.0001 1.0000 3 1.00	0.004	0.004
0.20 4 64 4 0.0001 0.0100 2 1.00	0.004	0.004
0.20 4 64 4 0.0001 0.0100 3 1.00	0.004	0.004
0.20 4 64 4 0.0001 0.0001 2 1.00	0.004	0.004
0.20 4 64 4 0.0001 0.0001 3 1.00 0.20 4 64 16 1.0000 1.0000 2 1.00	0.004	0.004
0.20 4 64 16 1.0000 1.0000 3 1.00	0.004	0.004
0.20 4 64 16 1.0000 0.0100 2 1.00	0.005	0.005
0.20 4 64 16 1.0000 0.0100 3 1.00	0.005	0.005
0.20 4 64 16 1.0000 0.0001 2 1.00	0.005	0.006
0.20 4 64 16 1.0000 0.0001 3 1.00	0.005	0.006
0.20 4 64 16 0.0100 1.0000 2 1.00	0.005	0.005
0.20 4 64 16 0.0100 1.0000 3 1.00	0.005	0.005
0.20 4 64 16 0.0100 0.0100 2 1.00 0.20 4 64 16 0.0100 0.0100 3 1.00	0.005	0.006
0.20 4 64 16 0.0100 0.0100 3 1.00	0.003	0.006
0.20 4 64 16 0.0100 0.0001 3 1.00	0.004	0.006
0.20 4 64 16 0.0001 1.0000 2 1.00	0.004	0.006
0.20 4 64 16 0.0001 1.0000 3 1.00	0.004	0.006
0.20 4 64 16 0.0001 0.0100 2 1.00	0.005	0.006
0.20 4 64 16 0.0001 0.0100 3 1.00	0.005	0.007
0.20 4 64 16 0.0001 0.0001 2 1.00	0.005	0.007
0.20 4 64 16 0.0001 0.0001 3 1.00 0.20 4 64 64 1.0000 1.0000 2 1.00	0.004	0.007
0.20 4 64 64 1.0000 1.0000 2 1.00	0.008	0.009
0.20 4 64 64 1.0000 0.0100 2 1.00	0.008	0.003
0.20 4 64 64 1.0000 0.0100 3 1.00	0.008	0.011
0.20 4 64 64 1.0000 0.0001 2 1.00	0.009	0.012
0.20 4 64 64 1.0000 0.0001 3 1.00	0.009	0.010
0.20 4 64 64 0.0100 1.0000 2 1.00	0.008	0.009
0.20 4 64 64 0.0100 1.0000 3 1.00	0.008	0.009
0.20 4 64 64 0.0100 0.0100 2 1.00 0.20 4 64 64 0.0100 0.0100 3 1.00	0.010	0.011
0.20 4 64 64 0.0100 0.0100 3 1.00 0.20 4 64 64 0.0100 0.0001 2 1.00	0.010	0.010
0.20 4 64 64 0.0100 0.0001 2 1.00	0.012	0.110
0.20 4 64 64 0.0001 1.0000 2 1.00	0.011	0.023
0.20 4 64 64 0.0001 1.0000 3 1.00	0.011	0.016
0.20 4 64 64 0.0001 0.0100 2 1.00	0.011	0.018
0.20 4 64 64 0.0001 0.0100 3 1.00	0.011	0.018

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	4	64	64	0.0001	0.0001	2	1.00	0.015	0.022
0.20	4	64	64	0.0001	0.0001	3	1.00	0.014	0.022
0.20	4	64	256	1.0000	1.0000	2	1.00	0.036	0.036
0.20	4	64	256 256	1.0000	1.0000 0.0100	3	1.00	0.025	0.036 0.052
0.20	4	64	256	1.0000	0.0100	3	1.00	0.032	0.052
0.20	4	64	256	1.0000	0.0001	2	1.00	0.048	0.074
0.20	4	64	256	1.0000	0.0001	3	1.00	0.045	0.074
0.20	4	64	256	0.0100	1.0000	2	1.00	0.034	0.036
0.20	4	64	256	0.0100	1.0000	3	1.00	0.034	0.036
0.20	4	64	256	0.0100	0.0100	2	1.00	0.047	0.073
0.20	4	64 64	256 256	0.0100	0.0100	3	1.00	0.046	0.074
0.20	4	64	256	0.0100	0.0001	3	1.00	0.005	0.092
0.20	4	64	256	0.0001	1.0000	2	1.00	0.055	0.079
0.20	4	64	256	0.0001	1.0000	3	1.00	0.056	0.082
0.20	4	64	256	0.0001	0.0100	2	1.00	0.060	0.091
0.20	4	64	256	0.0001	0.0100	3	1.00	0.059	0.090
0.20	4	64	256 256	0.0001	0.0001	2	1.00	0.078	0.128 0.128
0.20	4	256	230	1.0000	1.0000	2	1.00	0.079	0.128
0.20	4	256	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	4	256	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	4	256	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	4	256	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	4	256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	4	256	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	4	256 256	1	0.0100	1.0000 0.0100	3	1.00	0.003	0.003
0.20	4	256	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	4	256	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	4	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	4	256	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	4	256	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	4	256	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	4	256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	4	256 256	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	4	256	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	4	256	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	4	256	4	1.0000	0.0100	2	1.00	0.003	0.004
0.20	4	256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	4	256	4	1.0000	0.0001	2	1.00	0.004	0.004
0.20	4	256	4	1.0000	0.0001	3	1.00	0.004	0.004
0.20	4	256 256	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	4	256	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	4	256	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	4	256	4	0.0100	0.0001	2	1.00	0.004	0.004
0.20	4	256	4	0.0100	0.0001	3	1.00	0.004	0.004
0.20	4	256	4	0.0001	1.0000	2	1.00	0.004	0.004
0.20	4	256	4	0.0001	1.0000	3	1.00	0.004	0.004
0.20	4	256	4	0.0001	0.0100	2	1.00	0.003	0.004
0.20	4	256 256	4	0.0001	0.0100	3	1.00	0.003 0.004	0.004
0.20	4	256	4	0.0001	0.0001	3	1.00	0.004	0.004
0.20	4	256	16	1.0000	1.0000	2	1.00	0.004	0.004
0.20	4	256	16	1.0000	1.0000	3	1.00	0.004	0.004
0.20	4	256	16	1.0000	0.0100	2	1.00	0.005	0.005
0.20	4	256	16	1.0000	0.0100	3	1.00	0.005	0.005
0.20	4	256	16	1.0000	0.0001	2	1.00	0.004	0.006
0.20	4	256	16	1.0000	0.0001	3	1.00	0.004	0.006
0.20	4	256 256	16 16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	4	256	16	0.0100	0.0100	2	1.00	0.004	0.003
0.20	4	256	16	0.0100	0.0100	3	1.00	0.005	0.006
0.20	4	256	16	0.0100	0.0001	2	1.00	0.006	0.006
0.20	4	256	16	0.0100	0.0001	3	1.00	0.004	0.006
0.20	4	256	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	4	256	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	4	256	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	4	256 256	16 16	0.0001	0.0100	3 2	1.00	0.004	0.005 0.005
0.20	4	256	16	0.0001	0.0001	3	1.00	0.005	0.005
0.20	4	256	64	1.0000	1.0000	2	1.00	0.005	0.003
0.20	4	256	64	1.0000	1.0000	3	1.00	0.006	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	4	256	64	1.0000	0.0100	2	1.00	0.008	0.008
0.20	4	256	64	1.0000	0.0100	3	1.00	0.008	0.009
0.20	4	256	64	1.0000	0.0001	2	1.00	0.010	0.015
0.20	4	256	64	1.0000	0.0001	3	1.00	0.009	0.015
0.20	4	256 256	64 64	0.0100	1.0000	3	1.00	0.008	0.012
0.20	4	256	64	0.0100	0.0100	2	1.00	0.008	0.013
0.20	4	256	64	0.0100	0.0100	3	1.00	0.010	0.015
0.20	4	256	64	0.0100	0.0001	2	1.00	0.011	0.018
0.20	4	256	64	0.0100	0.0001	3	1.00	0.011	0.017
0.20	4	256	64	0.0001	1.0000	2	1.00	0.012	0.017
0.20	4	256	64	0.0001	1.0000	3	1.00	0.011	0.017
0.20	4	256 256	64	0.0001	0.0100	2	1.00	0.012	0.019
0.20	4	256	64	0.0001	0.0100	3	1.00	0.014	0.018
0.20	4	256	64	0.0001	0.0001	3	1.00	0.013	0.022
0.20	4	256	256	1.0000	1.0000	2	1.00	0.025	0.035
0.20	4	256	256	1.0000	1.0000	3	1.00	0.024	0.035
0.20	4	256	256	1.0000	0.0100	2	1.00	0.041	0.052
0.20	4	256	256	1.0000	0.0100	3	1.00	0.035	0.049
0.20	4	256	256	1.0000	0.0001	2	1.00	0.051	0.075
0.20	4	256	256	1.0000	0.0001	3	1.00	0.053	0.074
0.20	4	256	256 256	0.0100	1.0000	3	1.00	0.032	0.052
0.20	4	256 256	256	0.0100	1.0000 0.0100	2	1.00	0.032	0.040
0.20	4	256	256	0.0100	0.0100	3	1.00	0.048	0.093
0.20	4	256	256	0.0100	0.0001	2	1.00	0.061	0.067
0.20	4	256	256	0.0100	0.0001	3	1.00	0.062	0.066
0.20	4	256	256	0.0001	1.0000	2	1.00	0.054	0.056
0.20	4	256	256	0.0001	1.0000	3	1.00	0.054	0.055
0.20	4	256	256	0.0001	0.0100	2	1.00	0.064	0.100
0.20	4	256	256	0.0001	0.0100	3	1.00	0.065	0.099
0.20	4	256 256	256 256	0.0001	0.0001	3	1.00	0.075 0.076	0.107
0.20	16	1	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	16	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	16	1	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	16	1	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	16	1	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	16	1	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	16 16	1	1	0.0100	1.0000 0.0100	2	1.00	0.003	0.003
0.20	16	1	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	16	1	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	16	1	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	16	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	16	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	16	1	1	0.0001	0.0100	2	1.00	0.002	0.003
0.20	16	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	16 16	1	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	16	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	16	1	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	16	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	16	1	4	1.0000	0.0001	2	1.00	0.003	0.003
0.20	16	1	4	1.0000	0.0001	3	1.00	0.003	0.003
0.20	16	1	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	16 16	1	4	0.0100	1.0000 0.0100	2	1.00	0.003	0.003
0.20	16	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	16	1	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	16	1	4	0.0100	0.0001	3	1.00	0.003	0.003
0.20	16	1	4	0.0001	1.0000	2	1.00	0.003	0.004
0.20	16	1	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	16	1	4	0.0001	0.0100	2	1.00	0.003	0.003
0.20	16	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	16 16	1	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	16	1	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	16	1	16	1.0000	1.0000	3	1.00	0.004	0.003
0.20	16	1	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	16	1	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	16	1	16	1.0000	0.0001	2	1.00	0.004	0.006
0.20	16	1	16	1.0000	0.0001	3	1.00	0.004	0.006

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	16	1	16	0.0100	1.0000	2	1.00	0.004	0.005
0.20	16	1	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	16	1	16	0.0100	0.0100	2	1.00	0.005	0.006
0.20	16 16	1	16 16	0.0100	0.0100	3	1.00	0.005	0.006
0.20	16	1	16	0.0100	0.0001	3	1.00	0.006	0.006
0.20	16	1	16	0.0001	1.0000	2	1.00	0.005	0.034
0.20	16	1	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	16	1	16	0.0001	0.0100	2	1.00	0.005	0.005
0.20	16	1	16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	16	1	16	0.0001	0.0001	2	1.00	0.005	0.006
0.20	16 16	1	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00	0.005	0.006
0.20	16	1	64	1.0000	1.0000	3	1.00	0.006	0.008
0.20	16	1	64	1.0000	0.0100	2	1.00	0.008	0.010
0.20	16	1	64	1.0000	0.0100	3	1.00	0.008	0.009
0.20	16	1	64	1.0000	0.0001	2	1.00	0.009	0.011
0.20	16	1	64	1.0000	0.0001	3	1.00	0.009	0.010
0.20	16	1	64	0.0100	1.0000	2	1.00	0.008	0.010
0.20	16 16	1	64	0.0100	1.0000 0.0100	3	1.00	0.008	0.010
0.20	16	1	64	0.0100	0.0100	3	1.00	0.010	0.012
0.20	16	1	64	0.0100	0.0001	2	1.00	0.010	0.012
0.20	16	1	64	0.0100	0.0001	3	1.00	0.011	0.013
0.20	16	1	64	0.0001	1.0000	2	1.00	0.010	0.013
0.20	16	1	64	0.0001	1.0000	3	1.00	0.010	0.013
0.20	16	1	64	0.0001	0.0100	2	1.00	0.010	0.013
0.20	16	1	64	0.0001	0.0100	3	1.00	0.011	0.012
0.20	16 16	1	64	0.0001	0.0001	3	1.00	0.014	0.016 0.015
0.20	16	1	256	1.0000	1.0000	2	1.00	0.014	0.013
0.20	16	1	256	1.0000	1.0000	3	1.00	0.022	0.025
0.20	16	1	256	1.0000	0.0100	2	1.00	0.033	0.049
0.20	16	1	256	1.0000	0.0100	3	1.00	0.033	0.048
0.20	16	1	256	1.0000	0.0001	2	1.00	0.047	0.058
0.20	16	1	256	1.0000	0.0001	3	1.00	0.048	0.055
0.20	16 16	1	256 256	0.0100	1.0000	2	1.00	0.036	0.037
0.20	16	1	256	0.0100	0.0100	2	1.00	0.050	0.037
0.20	16	1	256	0.0100	0.0100	3	1.00	0.048	0.077
0.20	16	1	256	0.0100	0.0001	2	1.00	0.059	0.079
0.20	16	1	256	0.0100	0.0001	3	1.00	0.060	0.065
0.20	16	1	256	0.0001	1.0000	2	1.00	0.050	0.052
0.20	16 16	1	256 256	0.0001	1.0000 0.0100	3	1.00	0.051	0.072
0.20	16	1	256	0.0001	0.0100	3	1.00	0.064	0.086
0.20	16	1	256	0.0001	0.0001	2	1.00	0.079	0.100
0.20	16	1	256	0.0001	0.0001	3	1.00	0.079	0.086
0.20	16	4	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	16	4	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	16 16	4	1	1.0000	0.0100	3 2	1.00	0.003	0.003
0.20	16	4	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	16	4	1	0.0100	1.0000	2	1.00	0.002	0.003
0.20	16	4	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	16	4	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	16	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	16 16	4	1	0.0100	0.0001 0.0001	2	1.00	0.003	0.003 0.003
0.20	16	4	1	0.0100	1.00001	2	1.00	0.003	0.003
0.20	16	4	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	16	4	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	16	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	16	4	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	16	4	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	16 16	4	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	4	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	16	4	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	16	4	4	1.0000	0.0001	2	1.00	0.003	0.004
0.20	16	4	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	16	4	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	16	4	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	16 16	4	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	10	4	4	0.0100	0.0100	3	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	16	4	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	16	4	4	0.0100	0.0001	3	1.00	0.003	0.004
0.20	16	4	4	0.0001	1.0000	2	1.00	0.003	0.004
0.20	16	4	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	16 16	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	16	4	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	16	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.20	16	4	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	16	4	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	16	4	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	16	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	16	4	16	1.0000	0.0001	2	1.00	0.004	0.006
0.20	16 16	4	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00	0.004	0.004
0.20	16	4	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	16	4	16	0.0100	0.0100	2	1.00	0.004	0.005
0.20	16	4	16	0.0100	0.0100	3	1.00	0.004	0.005
0.20	16	4	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	16	4	16	0.0100	0.0001	3	1.00	0.004	0.005
0.20	16	4	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	16	4	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	16	4	16	0.0001	0.0100	2	1.00	0.004	0.006
0.20	16	4	16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	16 16	4	16 16	0.0001	0.0001	3	1.00	0.005	0.006
0.20	16	4	64	1.0000	1.0000	2	1.00	0.003	0.006
0.20	16	4	64	1.0000	1.0000	3	1.00	0.006	0.007
0.20	16	4	64	1.0000	0.0100	2	1.00	0.008	0.008
0.20	16	4	64	1.0000	0.0100	3	1.00	0.008	0.009
0.20	16	4	64	1.0000	0.0001	2	1.00	0.009	0.010
0.20	16	4	64	1.0000	0.0001	3	1.00	0.009	0.011
0.20	16	4	64	0.0100	1.0000	2	1.00	0.008	0.009
0.20	16	4	64	0.0100	1.0000	3	1.00	0.008	0.009
0.20	16 16	4	64	0.0100	0.0100	3	1.00	0.009	0.079
0.20	16	4	64	0.0100	0.0001	2	1.00	0.003	0.013
0.20	16	4	64	0.0100	0.0001	3	1.00	0.012	0.012
0.20	16	4	64	0.0001	1.0000	2	1.00	0.012	0.016
0.20	16	4	64	0.0001	1.0000	3	1.00	0.011	0.017
0.20	16	4	64	0.0001	0.0100	2	1.00	0.014	0.018
0.20	16	4	64	0.0001	0.0100	3	1.00	0.011	0.018
0.20	16	4	64	0.0001	0.0001	2	1.00	0.014	0.016
0.20	16 16	4	64 256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.014	0.015
0.20	16	4	256	1.0000	1.0000	3	1.00	0.023	0.026
0.20	16	4	256	1.0000	0.0100	2	1.00	0.025	0.025
0.20	16	4	256	1.0000	0.0100	3	1.00	0.035	0.035
0.20	16	4	256	1.0000	0.0001	2	1.00	0.049	0.049
0.20	16	4	256	1.0000	0.0001	3	1.00	0.047	0.048
0.20	16	4	256	0.0100	1.0000	2	1.00	0.035	0.038
0.20	16	4	256	0.0100	1.0000	3	1.00	0.035	0.037
0.20	16	4	256	0.0100	0.0100	2	1.00	0.045	0.049
0.20	16 16	4	256 256	0.0100	0.0100	3	1.00	0.047	0.049
0.20	16	4	256	0.0100	0.0001	3	1.00	0.063	0.083
0.20	16	4	256	0.0100	1.0000	2	1.00	0.056	0.070
0.20	16	4	256	0.0001	1.0000	3	1.00	0.054	0.084
0.20	16	4	256	0.0001	0.0100	2	1.00	0.064	0.101
0.20	16	4	256	0.0001	0.0100	3	1.00	0.064	0.069
0.20	16	4	256	0.0001	0.0001	2	1.00	0.074	0.100
0.20	16	4	256	0.0001	0.0001	3	1.00	0.075	0.096
0.20	16	16	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16 16	16 16	1	1.0000	1.0000 0.0100	3	1.00	0.003	0.003
0.20	16	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	16	16	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	16	16	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	16	16	1	0.0100	1.0000	2	1.00	0.002	0.003
0.20	16	16	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	16	16	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	16	16	1	0.0100	0.0100	3	1.00	0.002	0.003
0.20	16	16	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	16 16	16 16	1	0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.20	16	16	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	10	10	1	0.0001	1.0000	,	1.00	0.002	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	16	16	1	0.0001	0.0100	2	1.00	0.002	0.003
0.20	16	16	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	16	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	16 16	16 16	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	16	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	16	16	4	1.0000	0.0100	2	1.00	0.003	0.004
0.20	16	16	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	16 16	16 16	4	1.0000	0.0001	2	1.00	0.004	0.004
0.20	16	16	4	0.0100	1.0000	2	1.00	0.004	0.004
0.20	16	16	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	16	16	4	0.0100	0.0100	2	1.00	0.004	0.004
0.20	16	16	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	16 16	16 16	4	0.0100	0.0001	2	1.00	0.003	0.003
0.20	16	16	4	0.0001	1.0000	2	1.00	0.003	0.004
0.20	16	16	4	0.0001	1.0000	3	1.00	0.003	0.003
0.20	16	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.20	16	16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	16 16	16 16	4	0.0001	0.0001	2	1.00	0.003	0.003
0.20	16	16	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	16	16	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	16	16	16	1.0000	0.0100	2	1.00	0.004	0.004
0.20	16	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	16 16	16 16	16 16	1.0000	0.0001	3	1.00	0.004	0.005
0.20	16	16	16	0.0100	1.0000	2	1.00	0.004	0.003
0.20	16	16	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	16	16	16	0.0100	0.0100	2	1.00	0.004	0.005
0.20	16	16	16	0.0100	0.0100	3	1.00	0.004	0.005
0.20	16 16	16 16	16 16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	16	16	16	0.0001	1.0000	2	1.00	0.005	0.006
0.20	16	16	16	0.0001	1.0000	3	1.00	0.005	0.006
0.20	16	16	16	0.0001	0.0100	2	1.00	0.004	0.006
0.20	16	16	16	0.0001	0.0100	3	1.00	0.004	0.006
0.20	16 16	16 16	16 16	0.0001	0.0001	3	1.00	0.004	0.006
0.20	16	16	64	1.0000	1.0000	2	1.00	0.006	0.009
0.20	16	16	64	1.0000	1.0000	3	1.00	0.006	0.009
0.20	16	16	64	1.0000	0.0100	2	1.00	0.011	0.012
0.20	16	16	64	1.0000	0.0100	3	1.00	0.011	0.011
0.20	16 16	16 16	64 64	1.0000	0.0001	3	1.00	0.014	0.015
0.20	16	16	64	0.0100	1.0000	2	1.00	0.008	0.012
0.20	16	16	64	0.0100	1.0000	3	1.00	0.008	0.012
0.20	16	16	64	0.0100	0.0100	2	1.00	0.009	0.011
0.20	16 16	16 16	64 64	0.0100	0.0100	3	1.00	0.010	0.011
0.20	16	16	64	0.0100	0.0001	3	1.00	0.011	0.013
0.20	16	16	64	0.0001	1.0000	2	1.00	0.011	0.013
0.20	16	16	64	0.0001	1.0000	3	1.00	0.011	0.052
0.20	16	16	64	0.0001	0.0100	2	1.00	0.011	0.014
0.20	16 16	16 16	64 64	0.0001	0.0100 0.0001	3	1.00	0.011	0.014
0.20	16	16	64	0.0001	0.0001	3	1.00	0.014	0.043
0.20	16	16	256	1.0000	1.0000	2	1.00	0.023	0.033
0.20	16	16	256	1.0000	1.0000	3	1.00	0.024	0.035
0.20	16	16	256	1.0000	0.0100	2	1.00	0.035	0.041
0.20	16 16	16 16	256 256	1.0000	0.0100	3	1.00	0.035	0.036 0.066
0.20	16	16	256	1.0000	0.0001	3	1.00	0.047	0.000
0.20	16	16	256	0.0100	1.0000	2	1.00	0.037	0.057
0.20	16	16	256	0.0100	1.0000	3	1.00	0.036	0.057
0.20	16	16	256	0.0100	0.0100	2	1.00	0.050	0.077
0.20	16 16	16 16	256 256	0.0100	0.0100	3	1.00	0.050	0.077
0.20	16	16	256	0.0100	0.0001	3	1.00	0.060	0.064
0.20	16	16	256	0.0001	1.0000	2	1.00	0.053	0.085
0.20	16	16	256	0.0001	1.0000	3	1.00	0.053	0.085
0.20	16	16	256	0.0001	0.0100	2	1.00	0.084	0.128
0.20	16 16	16 16	256 256	0.0001	0.0100	3	1.00	0.064	0.127 0.124
0.20	16	16	256	0.0001	0.0001	3	1.00	0.076	0.124
0.20	10	10	250	5.5001	5.5001		1.00	5.570	V.111

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	16	64	1	1.0000	1.0000	2	1.00	0.002	0.003
0.20	16	64	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	16	64	1	1.0000	0.0100	2	1.00	0.002	0.003
0.20	16	64	1	1.0000	0.0100	3	1.00	0.002	0.003
0.20	16 16	64	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	16	64	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	16	64	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	16	64	1	0.0100	0.0100	2	1.00	0.002	0.003
0.20	16	64	1	0.0100	0.0100	3	1.00	0.002	0.003
0.20	16	64	1	0.0100	0.0001	2	1.00	0.002	0.003
0.20	16	64	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	16	64	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	16 16	64	1	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.20	16	64	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	16	64	1	0.0001	0.0001	2	1.00	0.002	0.003
0.20	16	64	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	16	64	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	64	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	16	64	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	16	64	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	16 16	64	4	1.0000	0.0001	2	1.00	0.003	0.003
0.20	16	64	4	1.0000 0.0100	1.0000	2	1.00	0.003	0.003
0.20	16	64	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	16	64	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	16	64	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	16	64	4	0.0100	0.0001	2	1.00	0.004	0.004
0.20	16	64	4	0.0100	0.0001	3	1.00	0.004	0.004
0.20	16	64	4	0.0001	1.0000	2	1.00	0.003	0.003
0.20	16	64	4	0.0001	1.0000 0.0100	3	1.00	0.003	0.004
0.20	16 16	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	16	64	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	16	64	4	0.0001	0.0001	3	1.00	0.004	0.004
0.20	16	64	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	16	64	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	16	64	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	16	64	16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	16	64	16	1.0000	0.0001	3	1.00	0.004	0.006
0.20	16	64	16 16	1.0000 0.0100	0.0001 1.0000	2	1.00	0.004	0.005
0.20	16	64	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	16	64	16	0.0100	0.0100	2	1.00	0.004	0.006
0.20	16	64	16	0.0100	0.0100	3	1.00	0.004	0.006
0.20	16	64	16	0.0100	0.0001	2	1.00	0.006	0.006
0.20	16	64	16	0.0100	0.0001	3	1.00	0.006	0.006
0.20	16	64	16	0.0001	1.0000	2	1.00	0.006	0.006
0.20	16	64	16	0.0001	1.0000	3	1.00	0.005	0.006
0.20	16 16	64	16 16	0.0001	0.0100	3	1.00	0.006	0.006
0.20	16	64	16	0.0001	0.0001	2	1.00	0.007	0.039
0.20	16	64	16	0.0001	0.0001	3	1.00	0.005	0.007
0.20	16	64	64	1.0000	1.0000	2	1.00	0.008	0.009
0.20	16	64	64	1.0000	1.0000	3	1.00	0.008	0.009
0.20	16	64	64	1.0000	0.0100	2	1.00	0.011	0.011
0.20	16	64	64	1.0000	0.0100	3	1.00	0.008	0.011
0.20	16 16	64 64	64 64	1.0000	0.0001	2	1.00	0.013 0.012	0.014
0.20	16	64	64	0.0100	1.00001	2	1.00	0.012	0.014
0.20	16	64	64	0.0100	1.0000	3	1.00	0.011	0.012
0.20	16	64	64	0.0100	0.0100	2	1.00	0.010	0.015
0.20	16	64	64	0.0100	0.0100	3	1.00	0.010	0.015
0.20	16	64	64	0.0100	0.0001	2	1.00	0.012	0.016
0.20	16	64	64	0.0100	0.0001	3	1.00	0.011	0.017
0.20	16	64	64	0.0001	1.0000	2	1.00	0.011	0.016
0.20	16 16	64	64	0.0001	1.0000 0.0100	3 2	1.00	0.011 0.012	0.016 0.018
0.20	16	64	64	0.0001	0.0100	3	1.00	0.012	0.018
0.20	16	64	64	0.0001	0.0001	2	1.00	0.014	0.017
0.20	16	64	64	0.0001	0.0001	3	1.00	0.014	0.022
0.20	16	64	256	1.0000	1.0000	2	1.00	0.025	0.036
0.20	16	64	256	1.0000	1.0000	3	1.00	0.025	0.035
0.20	16	64	256	1.0000	0.0100	2	1.00	0.032	0.052
0.20	16	64	256	1.0000	0.0100	3	1.00	0.032	0.073

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	16	64	256	1.0000	0.0001	2	1.00	0.046	0.074
0.20	16	64	256	1.0000	0.0001	3	1.00	0.047	0.074
0.20	16	64	256	0.0100	1.0000	2	1.00	0.054	0.056
0.20	16 16	64	256 256	0.0100	1.0000 0.0100	3	1.00	0.054 0.051	0.056 0.088
0.20	16	64	256	0.0100	0.0100	3	1.00	0.051	0.088
0.20	16	64	256	0.0100	0.0001	2	1.00	0.063	0.073
0.20	16	64	256	0.0100	0.0001	3	1.00	0.065	0.077
0.20	16	64	256	0.0001	1.0000	2	1.00	0.052	0.053
0.20	16	64	256	0.0001	1.0000	3	1.00	0.052	0.054
0.20	16	64	256	0.0001	0.0100	2	1.00	0.060	0.086
0.20	16 16	64 64	256 256	0.0001	0.0100	3	1.00	0.060	0.088
0.20	16	64	256	0.0001	0.0001	3	1.00	0.078	0.084
0.20	16	256	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	256	1	1.0000	1.0000	3	1.00	0.002	0.003
0.20	16	256	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	16	256	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	16 16	256 256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	16	256	1	0.0100	1.0000	2	1.00	0.002	0.003
0.20	16	256	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	16	256	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	16	256	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	16	256	1	0.0100	0.0001	2	1.00	0.003	0.004
0.20	16	256	1	0.0100	0.0001	3	1.00	0.003	0.004
0.20	16 16	256 256	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	16	256	1	0.0001	0.0100	2	1.00	0.002	0.003
0.20	16	256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	16	256	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	16	256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	16	256	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	16	256	4	1.0000	1.0000	3	1.00	0.003	0.004
0.20	16 16	256 256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	16	256	4	1.0000	0.0001	2	1.00	0.003	0.003
0.20	16	256	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	16	256	4	0.0100	1.0000	2	1.00	0.003	0.004
0.20	16	256	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	16	256	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	16 16	256 256	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	16	256	4	0.0100	0.0001	3	1.00	0.004	0.004
0.20	16	256	4	0.0001	1.0000	2	1.00	0.004	0.004
0.20	16	256	4	0.0001	1.0000	3	1.00	0.004	0.004
0.20	16	256	4	0.0001	0.0100	2	1.00	0.004	0.004
0.20	16	256	4	0.0001	0.0100	3	1.00	0.004	0.004
0.20	16	256	4	0.0001	0.0001	2	1.00	0.004	0.004
0.20	16 16	256 256	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00	0.004	0.004
0.20	16	256	16	1.0000	1.0000	3	1.00	0.004	0.005
0.20	16	256	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	16	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	16	256	16	1.0000	0.0001	2	1.00	0.006	0.006
0.20	16	256	16	1.0000	0.0001	3	1.00	0.006	0.006
0.20	16 16	256 256	16 16	0.0100 0.0100	1.0000	3	1.00	0.005 0.005	0.005 0.006
0.20	16	256	16	0.0100	0.0100	2	1.00	0.003	0.006
0.20	16	256	16	0.0100	0.0100	3	1.00	0.004	0.005
0.20	16	256	16	0.0100	0.0001	2	1.00	0.004	0.035
0.20	16	256	16	0.0100	0.0001	3	1.00	0.005	0.006
0.20	16	256	16	0.0001	1.0000	2	1.00	0.004	0.006
0.20	16	256	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	16 16	256 256	16 16	0.0001	0.0100	2	1.00	0.005	0.005 0.005
0.20	16	256	16	0.0001	0.0100	2	1.00	0.005	0.005
0.20	16	256	16	0.0001	0.0001	3	1.00	0.005	0.006
0.20	16	256	64	1.0000	1.0000	2	1.00	0.006	0.007
0.20	16	256	64	1.0000	1.0000	3	1.00	0.006	0.006
0.20	16	256	64	1.0000	0.0100	2	1.00	0.008	0.008
0.20	16	256	64	1.0000	0.0100	3	1.00	0.007	0.009
0.20	16	256	64	1.0000	0.0001	2	1.00	0.010	0.011
0.20	16 16	256 256	64	1.0000 0.0100	0.0001 1.0000	3	1.00	0.010	0.011
0.20	16	256	64	0.0100	1.0000	3	1.00	0.007	0.011
0.20	10	230	04	0.0100	1.0000		1.00	0.006	0.011

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	16	256	64	0.0100	0.0100	2	1.00	0.014	0.016
0.20	16	256	64	0.0100	0.0100	3	1.00	0.010	0.016
0.20	16	256	64	0.0100	0.0001	2	1.00	0.012	0.018
0.20	16 16	256 256	64	0.0100	1.0000	3	1.00	0.012	0.018
0.20	16	256	64	0.0001	1.0000	3	1.00	0.014	0.016
0.20	16	256	64	0.0001	0.0100	2	1.00	0.017	0.018
0.20	16	256	64	0.0001	0.0100	3	1.00	0.013	0.018
0.20	16	256	64	0.0001	0.0001	2	1.00	0.014	0.022
0.20	16	256	64	0.0001	0.0001	3	1.00	0.016	0.022
0.20	16	256	256	1.0000	1.0000	2	1.00	0.024	0.026
0.20	16	256	256	1.0000	1.0000	3	1.00	0.024	0.026
0.20	16	256	256	1.0000	0.0100	2	1.00	0.035	0.052
0.20	16 16	256 256	256 256	1.0000	0.0100	3	1.00	0.035	0.053
0.20	16	256	256	1.0000	0.0001	3	1.00	0.046	0.091
0.20	16	256	256	0.0100	1.0000	2	1.00	0.040	0.035
0.20	16	256	256	0.0100	1.0000	3	1.00	0.034	0.036
0.20	16	256	256	0.0100	0.0100	2	1.00	0.051	0.063
0.20	16	256	256	0.0100	0.0100	3	1.00	0.051	0.082
0.20	16	256	256	0.0100	0.0001	2	1.00	0.066	0.081
0.20	16	256	256	0.0100	0.0001	3	1.00	0.068	0.086
0.20	16	256	256	0.0001	1.0000	2	1.00	0.057	0.070
0.20	16	256	256	0.0001	1.0000	3	1.00	0.055	0.077
0.20	16	256 256	256	0.0001	0.0100	2	1.00	0.059	0.082
0.20	16 16	256	256 256	0.0001	0.0100	3	1.00	0.059	0.090
0.20	16	256	256	0.0001	0.0001	3	1.00	0.074	0.108
0.20	64	1	1	1.0000	1.0000	2	1.00	0.070	0.003
0.20	64	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	64	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	64	1	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	64	1	1	1.0000	0.0001	2	1.00	0.003	0.004
0.20	64	1	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	64	1	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	64	1	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	64	1	1	0.0100	0.0100	3	1.00	0.002	0.003
0.20	64	1	1	0.0100	0.0001	2	1.00	0.002	0.003
0.20	64	1	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	64	1	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	64	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	64	1	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	64	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	64	1	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	64	1	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	64	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	64	1	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	64	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	64	1	4	1.0000	0.0001	2	1.00	0.003	0.004
0.20	64	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	64	1	4	0.0100	1.0000	2	1.00	0.003	0.004
0.20	64	1	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	64	1	4	0.0100	0.0100	2	1.00	0.004	0.004
0.20	64	1	4	0.0100	0.0100	3	1.00	0.004	0.004
0.20	64	1	4	0.0100	0.0001	2	1.00	0.004	0.004
0.20	64	1	4	0.0100	0.0001 1.0000	3	1.00	0.003	0.004
0.20	64	1	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	64	1	4	0.0001	0.0100	2	1.00	0.003	0.004
0.20	64	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	64	1	4	0.0001	0.0001	2	1.00	0.004	0.004
0.20	64	1	4	0.0001	0.0001	3	1.00	0.004	0.004
0.20	64	1	16	1.0000	1.0000	2	1.00	0.004	0.004
0.20	64	1	16	1.0000	1.0000	3	1.00	0.004	0.004
0.20	64	1	16	1.0000	0.0100	2	1.00	0.005	0.005
0.20	64	1	16	1.0000	0.0100	3	1.00	0.005	0.005
0.20	64	1	16 16	1.0000	0.0001	2	1.00	0.006	0.006
0.20	64	1	16	0.0100	1.0000	2	1.00	0.006	0.005
0.20	64	1	16	0.0100	1.0000	3	1.00	0.005	0.005
0.20	64	1	16	0.0100	0.0100	2	1.00	0.005	0.006
	64	1	16	0.0100	0.0100	3	1.00	0.006	0.042
0.20	0-	-							
0.20	64	1	16	0.0100	0.0001	2	1.00	0.006	0.006

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	64	1	16	0.0001	1.0000	2	1.00	0.005	0.006
0.20	64	1	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	64	1	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	64	1	16	0.0001	0.0100	3	1.00	0.004	0.006
0.20	64	1	16 16	0.0001	0.0001	3	1.00	0.004	0.007
0.20	64	1	64	1.0000	1.0000	2	1.00	0.004	0.000
0.20	64	1	64	1.0000	1.0000	3	1.00	0.007	0.009
0.20	64	1	64	1.0000	0.0100	2	1.00	0.011	0.012
0.20	64	1	64	1.0000	0.0100	3	1.00	0.011	0.012
0.20	64	1	64	1.0000	0.0001	2	1.00	0.013	0.014
0.20	64	1	64	1.0000	0.0001	3	1.00	0.014	0.015
0.20	64	1	64	0.0100	1.0000	3	1.00	0.012	0.012
0.20	64	1	64	0.0100	0.0100	2	1.00	0.012	0.012
0.20	64	1	64	0.0100	0.0100	3	1.00	0.013	0.015
0.20	64	1	64	0.0100	0.0001	2	1.00	0.015	0.017
0.20	64	1	64	0.0100	0.0001	3	1.00	0.016	0.018
0.20	64	1	64	0.0001	1.0000	2	1.00	0.011	0.018
0.20	64	1	64	0.0001	1.0000 0.0100	3	1.00	0.011	0.012
0.20	64	1	64	0.0001	0.0100	3	1.00	0.011	0.012
0.20	64	1	64	0.0001	0.0001	2	1.00	0.011	0.013
0.20	64	1	64	0.0001	0.0001	3	1.00	0.014	0.017
0.20	64	1	256	1.0000	1.0000	2	1.00	0.021	0.022
0.20	64	1	256	1.0000	1.0000	3	1.00	0.021	0.022
0.20	64	1	256	1.0000	0.0100	2	1.00	0.036	0.052
0.20	64 64	1	256 256	1.0000	0.0100	3	1.00	0.036	0.052
0.20	64	1	256	1.0000	0.0001	3	1.00	0.059	0.074
0.20	64	1	256	0.0100	1.0000	2	1.00	0.035	0.049
0.20	64	1	256	0.0100	1.0000	3	1.00	0.035	0.046
0.20	64	1	256	0.0100	0.0100	2	1.00	0.051	0.078
0.20	64	1	256	0.0100	0.0100	3	1.00	0.056	0.076
0.20	64	1	256 256	0.0100	0.0001	3	1.00	0.060	0.094
0.20	64	1	256	0.0001	1.0000	2	1.00	0.052	0.079
0.20	64	1	256	0.0001	1.0000	3	1.00	0.063	0.079
0.20	64	1	256	0.0001	0.0100	2	1.00	0.066	0.095
0.20	64	1	256	0.0001	0.0100	3	1.00	0.063	0.092
0.20	64	1	256 256	0.0001	0.0001	3	1.00	0.089	0.125 0.121
0.20	64	4	1	1.0000	1.0000	2	1.00	0.093	0.008
0.20	64	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	64	4	1	1.0000	0.0100	2	1.00	0.003	0.191
0.20	64	4	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	64	4	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	64	4	1	1.0000 0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.20	64	4	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	64	4	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	64	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	64	4	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	64	4	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	64	4	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	64	4	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	64	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	64	4	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	64	4	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	64	4	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	64	4	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	64	4	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	64	4	4	1.0000	0.0001	2	1.00	0.004	0.004
0.20	64	4	4	1.0000	0.0001	3	1.00	0.004	0.004
0.20	64	4	4	0.0100	1.0000	2	1.00	0.003	0.004
0.20	64 64	4	4	0.0100	1.0000 0.0100	3	1.00	0.003	0.004
0.20	64	4	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	64	4	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	64	4	4	0.0100	0.0001	3	1.00	0.003	0.004
0.20	64	4	4	0.0001	1.0000	2	1.00	0.003	0.004
0.20	64	4	4	0.0001	1.0000 0.0100	3	1.00	0.003	0.004
0.20	64	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	JŦ			0.0001	0.0100	J	1.00	0.005	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	$_{ m mint}$	maxt
0.20	64	4	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	64	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.20	64	4	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	64	4	16 16	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.20	64	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	64	4	16	1.0000	0.0001	2	1.00	0.004	0.006
0.20	64	4	16	1.0000	0.0001	3	1.00	0.004	0.006
0.20	64	4	16	0.0100	1.0000	2	1.00	0.004	0.005
0.20	64	4	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	64	4	16 16	0.0100	0.0100	2	1.00	0.004	0.006
0.20	64	4	16	0.0100	0.0001	2	1.00	0.004	0.006
0.20	64	4	16	0.0100	0.0001	3	1.00	0.005	0.006
0.20	64	4	16	0.0001	1.0000	2	1.00	0.004	0.006
0.20	64	4	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	64	4	16	0.0001	0.0100	2	1.00	0.004	0.007
0.20	64	4	16	0.0001	0.0100	3	1.00	0.004	0.006
0.20	64	4	16 16	0.0001	0.0001	3	1.00	0.005	0.007
0.20	64	4	64	1.0000	1.0000	2	1.00	0.006	0.007
0.20	64	4	64	1.0000	1.0000	3	1.00	0.006	0.009
0.20	64	4	64	1.0000	0.0100	2	1.00	0.008	0.012
0.20	64	4	64	1.0000	0.0100	3	1.00	0.008	0.011
0.20	64	4	64	1.0000	0.0001	2	1.00	0.009	0.014
0.20	64	4	64	1.0000	0.0001	3	1.00	0.009	0.015
0.20	64	4	64	0.0100	1.0000	2	1.00	0.008	0.012
0.20	64	4	64	0.0100	1.0000	3	1.00	0.008	0.012
0.20	64	4	64	0.0100	0.0100	2	1.00	0.009	0.012
0.20	64	4	64	0.0100	0.0001	2	1.00	0.003	0.012
0.20	64	4	64	0.0100	0.0001	3	1.00	0.011	0.012
0.20	64	4	64	0.0001	1.0000	2	1.00	0.010	0.011
0.20	64	4	64	0.0001	1.0000	3	1.00	0.010	0.011
0.20	64	4	64	0.0001	0.0100	2	1.00	0.011	0.012
0.20	64	4	64	0.0001	0.0100	3	1.00	0.011	0.012
0.20	64	4	64	0.0001	0.0001	2	1.00	0.014	0.015
0.20	64 64	4	64 256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.013	0.015
0.20	64	4	256	1.0000	1.0000	3	1.00	0.022	0.035
0.20	64	4	256	1.0000	0.0100	2	1.00	0.038	0.052
0.20	64	4	256	1.0000	0.0100	3	1.00	0.044	0.051
0.20	64	4	256	1.0000	0.0001	2	1.00	0.055	0.075
0.20	64	4	256	1.0000	0.0001	3	1.00	0.051	0.074
0.20	64	4	256	0.0100	1.0000	2	1.00	0.036	0.055
0.20	64	4	256	0.0100	1.0000	3	1.00	0.036	0.055
0.20	64	4	256	0.0100	0.0100	2	1.00	0.047	0.080
0.20	64	4	256 256	0.0100	0.0100	2	1.00	0.048	0.079
0.20	64	4	256	0.0100	0.0001	3	1.00	0.057	0.098
0.20	64	4	256	0.0001	1.0000	2	1.00	0.054	0.082
0.20	64	4	256	0.0001	1.0000	3	1.00	0.056	0.083
0.20	64	4	256	0.0001	0.0100	2	1.00	0.064	0.067
0.20	64	4	256	0.0001	0.0100	3	1.00	0.064	0.068
0.20	64	4	256	0.0001	0.0001	2	1.00	0.081	0.084
0.20	64	4	256	0.0001 1.0000	1.0000	3	1.00	0.076	0.085
0.20	64	16 16	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	64	16	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	64	16	1	1.0000	0.0100	3	1.00	0.002	0.003
0.20	64	16	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	64	16	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	64	16	1	0.0100	1.0000	2	1.00	0.002	0.003
0.20	64	16	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	64	16	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	64	16 16	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	64	16	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	64	16	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	64	16	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	64	16	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	64	16	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	64	16	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	64	16	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	64	16	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	64	16	4	1.0000	1.0000	3	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	64	16	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	64	16	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	64	16	4	1.0000	0.0001	2	1.00	0.003	0.021
0.20	64	16 16	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	64	16	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	64	16	4	0.0100	0.0100	2	1.00	0.003	0.003
0.20	64	16	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	64	16	4	0.0100	0.0001	2	1.00	0.003	0.003
0.20	64	16 16	4	0.0100	0.0001 1.0000	2	1.00	0.003	0.004
0.20	64	16	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	64	16	4	0.0001	0.0100	2	1.00	0.003	0.003
0.20	64	16	4	0.0001	0.0100	3	1.00	0.003	0.003
0.20	64	16	4	0.0001	0.0001	2	1.00	0.003	0.003
0.20	64	16 16	16	1.0000	1.0000	2	1.00	0.003	0.003
0.20	64	16	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	64	16	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	64	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	64	16	16	1.0000	0.0001	2	1.00	0.004	0.005
0.20	64	16 16	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00	0.004	0.006
0.20	64	16	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	64	16	16	0.0100	0.0100	2	1.00	0.004	0.005
0.20	64	16	16	0.0100	0.0100	3	1.00	0.004	0.005
0.20	64	16	16 16	0.0100	0.0001	2	1.00	0.004	0.007
0.20	64	16 16	16	0.0100	0.0001 1.0000	3	1.00	0.004	0.007
0.20	64	16	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	64	16	16	0.0001	0.0100	2	1.00	0.004	0.006
0.20	64	16	16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	64	16	16	0.0001	0.0001	2	1.00	0.005	0.007
0.20	64	16 16	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00	0.005	0.007 0.008
0.20	64	16	64	1.0000	1.0000	3	1.00	0.006	0.007
0.20	64	16	64	1.0000	0.0100	2	1.00	0.008	0.009
0.20	64	16	64	1.0000	0.0100	3	1.00	0.008	0.010
0.20	64	16 16	64	1.0000	0.0001	3	1.00	0.009	0.013
0.20	64	16	64	1.0000 0.0100	0.0001 1.0000	2	1.00	0.009	0.012
0.20	64	16	64	0.0100	1.0000	3	1.00	0.008	0.009
0.20	64	16	64	0.0100	0.0100	2	1.00	0.010	0.011
0.20	64	16	64	0.0100	0.0100	3	1.00	0.010	0.012
0.20	64	16 16	64	0.0100	0.0001	3	1.00	0.011	0.015
0.20	64	16	64	0.0100	1.0000	2	1.00	0.011	0.013
0.20	64	16	64	0.0001	1.0000	3	1.00	0.011	0.013
0.20	64	16	64	0.0001	0.0100	2	1.00	0.011	0.013
0.20	64	16	64	0.0001	0.0100	3	1.00	0.011	0.014
0.20	64	16	64 64	0.0001	0.0001	3	1.00	0.013	0.017 0.017
0.20	64	16 16	256	0.0001 1.0000	1.0000	2	1.00	0.014	0.017
0.20	64	16	256	1.0000	1.0000	3	1.00	0.022	0.024
0.20	64	16	256	1.0000	0.0100	2	1.00	0.034	0.035
0.20	64	16	256	1.0000	0.0100	3	1.00	0.035	0.036
0.20	64	16 16	256 256	1.0000	0.0001	3	1.00	0.045	0.049
0.20	64	16	256	0.0100	1.0000	2	1.00	0.035	0.051
0.20	64	16	256	0.0100	1.0000	3	1.00	0.035	0.051
0.20	64	16	256	0.0100	0.0100	2	1.00	0.050	0.064
0.20	64	16	256	0.0100	0.0100	3	1.00	0.049	0.084
0.20	64	16 16	256 256	0.0100 0.0100	0.0001	3	1.00	0.073	0.090
0.20	64	16	256	0.0001	1.0000	2	1.00	0.055	0.098
0.20	64	16	256	0.0001	1.0000	3	1.00	0.052	0.076
0.20	64	16	256	0.0001	0.0100	2	1.00	0.058	0.083
0.20	64	16	256	0.0001	0.0100	3	1.00	0.058	0.072
0.20	64 64	16 16	256 256	0.0001	0.0001	2	1.00	0.076 0.092	0.129 0.129
0.20	64	64	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	64	64	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	64	64	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	64	64	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	64 64	64	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	0-1	L 04	1	1.0000	0.0001	3	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	64	64	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	64	64	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	64	64	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	64	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	64	64	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	64	64	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	64	64	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	64	64	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	64	64	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	64	64	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	64	64	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	64	64	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	64	64	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	64	64	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	64	64	4	1.0000	0.0001	2	1.00	0.003	0.004
0.20	64	64	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	64	64	4	0.0100	1.0000	2	1.00	0.003	0.004
0.20	64	64	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	64	64	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	64	64	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	64	64	4	0.0100	0.0001	3	1.00	0.003	0.004
0.20	64	64	4	0.0001	1.0000	2	1.00	0.003	0.004
0.20	64	64	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	64	64	4	0.0001	0.0100	2	1.00	0.003	0.004
0.20	64	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	64	64	4	0.0001	0.0001	3	1.00	0.003	0.004
0.20	64	64	16	1.0000	1.0000	2	1.00	0.003	0.032
0.20	64	64	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	64	64	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	64	64	16	1.0000	0.0100	3	1.00	0.004	0.005
0.20	64	64	16 16	1.0000	0.0001	3	1.00	0.005	0.006
0.20	64	64	16	0.0100	1.0000	2	1.00	0.005	0.005
0.20	64	64	16	0.0100	1.0000	3	1.00	0.005	0.005
0.20	64	64	16	0.0100	0.0100	2	1.00	0.005	0.006
0.20	64	64	16	0.0100	0.0100	3	1.00	0.005	0.006
0.20	64	64	16	0.0100	0.0001	2	1.00	0.006	0.006
0.20	64	64	16 16	0.0100	1.0000	3	1.00	0.006	0.006
0.20	64	64	16	0.0001	1.0000	3	1.00	0.003	0.006
0.20	64	64	16	0.0001	0.0100	2	1.00	0.006	0.006
0.20	64	64	16	0.0001	0.0100	3	1.00	0.006	0.006
0.20	64	64	16	0.0001	0.0001	2	1.00	0.006	0.007
0.20	64	64	16	0.0001	0.0001	3	1.00	0.006	0.007
0.20	64	64	64	1.0000	1.0000	2	1.00	0.008	0.009
0.20	64	64	64 64	1.0000	1.0000 0.0100	3	1.00	0.008	0.009
0.20	64	64	64	1.0000	0.0100	3	1.00	0.011	0.011
0.20	64	64	64	1.0000	0.0001	2	1.00	0.010	0.015
0.20	64	64	64	1.0000	0.0001	3	1.00	0.010	0.017
0.20	64	64	64	0.0100	1.0000	2	1.00	0.008	0.012
0.20	64	64	64	0.0100	1.0000	3	1.00	0.008	0.011
0.20	64	64	64 64	0.0100	0.0100	3	1.00	0.010	0.015 0.015
0.20	64	64	64	0.0100	0.0001	2	1.00	0.010	0.013
0.20	64	64	64	0.0100	0.0001	3	1.00	0.012	0.018
0.20	64	64	64	0.0001	1.0000	2	1.00	0.011	0.017
0.20	64	64	64	0.0001	1.0000	3	1.00	0.011	0.017
0.20	64	64	64	0.0001	0.0100	2	1.00	0.012	0.018
0.20	64	64 64	64 64	0.0001	0.0100	3	1.00	0.012	0.017 0.022
0.20	64	64	64	0.0001	0.0001	3	1.00	0.017	0.022
0.20	64	64	256	1.0000	1.0000	2	1.00	0.014	0.022
0.20	64	64	256	1.0000	1.0000	3	1.00	0.026	0.035
0.20	64	64	256	1.0000	0.0100	2	1.00	0.039	0.051
0.20	64	64	256	1.0000	0.0100	3	1.00	0.041	0.051
0.20	64	64	256	1.0000	0.0001	2	1.00	0.048	0.073
0.20	64 64	64 64	256 256	1.0000 0.0100	0.0001 1.0000	3 2	1.00	0.053	0.074 0.088
0.20	64	64	256	0.0100	1.0000	3	1.00	0.036	0.088
0.20	64	64	256	0.0100	0.0100	2	1.00	0.048	0.071
0.20	64	64	256	0.0100	0.0100	3	1.00	0.046	0.077

0.20	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	0.20	64	64	256	0.0100			1.00	0.065	0.084
0.20										
0.20										
0.20										
0.20										
0.20										
0.20				256			3			
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20	0.20	64	256	1		1.0000	3	1.00	0.003	0.003
0.20										
0.20										
0.20										
0.20										
0.20										
0.20							2			
0.20										
0.20										
0.20										
0.20										
0.20										
0.20										
0.20	0.20	64	256	4		0.0001	2	1.00	0.004	0.004
0.20										
0.20										
0.20 64 256 4 0.0100 0.0100 3 1.00 0.003 0.004 0.20 64 256 4 0.0100 0.0001 2 1.00 0.004 0.004 0.20 64 256 4 0.0001 1.000 0.003 0.004 0.20 64 256 4 0.0001 1.000 0.003 0.004 0.20 64 256 4 0.0001 1.000 0.003 0.004 0.20 64 256 4 0.0001 0.0100 2 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0100 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64										
0.20 64 256 4 0.0100 0.0001 2 1.00 0.004 0.004 0.20 64 256 4 0.0100 0.0001 3 1.00 0.004 0.004 0.20 64 256 4 0.0001 1.0000 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 1.0000 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0100 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 3 </td <td></td>										
0.20 64 256 4 0.0001 1.0000 2 1.00 0.003 0.004 0.20 64 256 4 0.0001 1.0000 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0100 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2										
0.20 64 256 4 0.0001 1.0000 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0100 2 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 2 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 2 1.00 0.003 0.005 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001	0.20	64	256	4		0.0001	3	1.00	0.004	0.004
0.20 64 256 4 0.0001 0.0100 2 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0100 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 2 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 2 1.00 0.003 0.005 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 2 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 1.0000 <th< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th<>										
0.20 64 256 4 0.0001 0.0100 3 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 2 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 2 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0100 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 1.0000 3 1.00 0.006 0.006 0.20 64 256 16 0.0100 1.0000 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>										
0.20 64 256 4 0.0001 0.0001 2 1.00 0.003 0.004 0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 2 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0100 2 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 3 1.00 0.006 0.006 0.20 64 256 16 0.0100 1.0000 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 1.0000 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>										
0.20 64 256 4 0.0001 0.0001 3 1.00 0.003 0.004 0.20 64 256 16 1.0000 1.0000 2 1.00 0.003 0.005 0.20 64 256 16 1.0000 1.0000 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0100 2 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 1.0000 0.0001 3 1.00 0.006 0.006 0.20 64 256 16 0.0100 1.0000 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 <										
0.20 64 256 16 1.0000 1.0000 2 1.00 0.003 0.005 0.20 64 256 16 1.0000 1.0000 3 1.00 0.003 0.005 0.20 64 256 16 1.0000 0.0100 2 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 1.0000 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 1.0000 0.0001 3 1.00 0.006 0.006 0.20 64 256 16 0.0100 1.0000 2 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0010										
0.20 64 256 16 1.0000 0.0100 2 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0100 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2 1.00 0.006 0.006 0.20 64 256 16 0.0100 1.0000 2 1.00 0.004 0.005 0.20 64 256 16 0.0100 1.0000 2 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 2 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000										
0.20 64 256 16 1.0000 0.0100 3 1.00 0.005 0.005 0.20 64 256 16 1.0000 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 1.0000 0.0001 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 1.0000 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0100 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000										
0.20 64 256 16 1.0000 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 1.0000 0.0001 3 1.00 0.006 0.006 0.20 64 256 16 0.0100 1.0000 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 2 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0100 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000										
0.20 64 256 16 1.0000 0.0001 3 1.00 0.006 0.006 0.20 64 256 16 0.0100 1.0000 2 1.00 0.004 0.005 0.20 64 256 16 0.0100 1.0000 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.004 0.006 0.20 64 256 16 0.0001 1.0000										
0.20 64 256 16 0.0100 1.0000 2 1.00 0.004 0.005 0.20 64 256 16 0.0100 1.0000 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.004 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0100										
0.20 64 256 16 0.0100 1.0000 3 1.00 0.004 0.005 0.20 64 256 16 0.0100 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000 2 1.00 0.004 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.004 0.006 0.20 64 256 16 0.0001 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0001										
0.20 64 256 16 0.0100 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0100 3 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0100 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000 2 1.00 0.004 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.004 0.006 0.20 64 256 16 0.0001 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0001										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.20	64	256	16	0.0100	0.0100	2	1.00	0.005	0.006
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.20 64 256 16 0.0001 1.0000 2 1.00 0.004 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.004 0.006 0.20 64 256 16 0.0001 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0001 2 1.00 0.005 0.007 0.20 64 256 16 0.0001 0.0001 2 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.005 0.006 0.20 64 256 64 1.0000 1.0000 3 1.00 0.006 0.010 0.20 64 256 64 1.0000 0.0100										
0.20 64 256 16 0.0001 1.0000 3 1.00 0.004 0.006 0.20 64 256 16 0.0001 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0001 2 1.00 0.005 0.007 0.20 64 256 16 0.0001 0.0001 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 1.0000 3 1.00 0.005 0.006 0.20 64 256 64 1.0000 1.0000 2 1.00 0.006 0.010 0.20 64 256 64 1.0000 1.0000 3 1.00 0.006 0.013 0.20 64 256 64 1.0000 0.0100 2 1.00 0.007 0.011 0.20 64 256 64 1.0000 0.0001										
0.20 64 256 16 0.0001 0.0100 2 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0100 3 1.00 0.005 0.006 0.20 64 256 16 0.0001 0.0001 2 1.00 0.005 0.007 0.20 64 256 16 0.0001 0.0001 3 1.00 0.005 0.006 0.20 64 256 64 1.0000 1.0000 2 1.00 0.006 0.010 0.20 64 256 64 1.0000 1.0000 3 1.00 0.006 0.013 0.20 64 256 64 1.0000 0.0100 2 1.00 0.007 0.011 0.20 64 256 64 1.0000 0.0100 3 1.00 0.007 0.011 0.20 64 256 64 1.0000 0.0001										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.20	64	256	16	0.0001	0.0100	3	1.00		0.006
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.20 64 256 64 1.0000 1.0000 3 1.00 0.006 0.013 0.20 64 256 64 1.0000 0.0100 2 1.00 0.007 0.011 0.20 64 256 64 1.0000 0.0001 3 1.00 0.007 0.011 0.20 64 256 64 1.0000 0.0001 2 1.00 0.010 0.016 0.20 64 256 64 1.0000 0.0001 3 1.00 0.010 0.016 0.20 64 256 64 1.0000 1.0000 2 1.00 0.008 0.012 0.20 64 256 64 0.0100 1.0000 3 1.00 0.008 0.012 0.20 64 256 64 0.0100 1.0000 3 1.00 0.010 0.015 0.20 64 256 64 0.0100 0.0100										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$										
0.20 64 256 64 1.0000 0.0001 2 1.00 0.010 0.016 0.20 64 256 64 1.0000 0.0001 3 1.00 0.010 0.016 0.20 64 256 64 0.0100 1.0000 2 1.00 0.008 0.012 0.20 64 256 64 0.0100 0.0100 3 1.00 0.008 0.012 0.20 64 256 64 0.0100 0.0100 2 1.00 0.010 0.012 0.20 64 256 64 0.0100 0.0100 3 1.00 0.011 0.015 0.20 64 256 64 0.0100 0.0001 2 1.00 0.011 0.015 0.20 64 256 64 0.0100 0.0001 2 1.00 0.012 0.022 0.20 64 256 64 0.0100 0.0001										
0.20 64 256 64 0.0100 1.0000 2 1.00 0.008 0.012 0.20 64 256 64 0.0100 1.0000 3 1.00 0.008 0.012 0.20 64 256 64 0.0100 0.0100 2 1.00 0.010 0.015 0.20 64 256 64 0.0100 0.0001 2 1.00 0.011 0.015 0.20 64 256 64 0.0100 0.0001 2 1.00 0.012 0.022 0.20 64 256 64 0.0100 0.0001 3 1.00 0.012 0.019 0.20 64 256 64 0.0100 0.0001 3 1.00 0.012 0.019 0.20 64 256 64 0.0001 1.0000 2 1.00 0.016 0.017	0.20	64		64	1.0000	0.0001	2	1.00	0.010	0.016
0.20 64 256 64 0.0100 1.0000 3 1.00 0.008 0.012 0.20 64 256 64 0.0100 0.0100 2 1.00 0.010 0.015 0.20 64 256 64 0.0100 0.0001 3 1.00 0.011 0.015 0.20 64 256 64 0.0100 0.0001 2 1.00 0.012 0.022 0.20 64 256 64 0.0100 0.0001 3 1.00 0.012 0.019 0.20 64 256 64 0.0001 1.0000 2 1.00 0.016 0.017										
0.20 64 256 64 0.0100 0.0100 2 1.00 0.010 0.015 0.20 64 256 64 0.0100 0.0100 3 1.00 0.011 0.015 0.20 64 256 64 0.0100 0.0001 2 1.00 0.012 0.022 0.20 64 256 64 0.0100 0.0001 3 1.00 0.012 0.019 0.20 64 256 64 0.0001 1.0000 2 1.00 0.016 0.017										
0.20 64 256 64 0.0100 0.0100 3 1.00 0.011 0.015 0.20 64 256 64 0.0100 0.0001 2 1.00 0.012 0.022 0.20 64 256 64 0.0100 0.0001 3 1.00 0.012 0.019 0.20 64 256 64 0.0001 1.0000 2 1.00 0.016 0.017										
0.20 64 256 64 0.0100 0.0001 2 1.00 0.012 0.022 0.20 64 256 64 0.0100 0.0001 3 1.00 0.012 0.019 0.20 64 256 64 0.0001 1.0000 2 1.00 0.016 0.017										
0.20 64 256 64 0.0100 0.0001 3 1.00 0.012 0.019 0.20 64 256 64 0.0001 1.0000 2 1.00 0.016 0.017										
0.20 64 256 64 0.0001 1.0000 2 1.00 0.016 0.017										
0.20 64 256 64 0.0001 1.0000 3 1.00 0.014 0.017	0.20		256	64	0.0001	1.0000		1.00	0.016	0.017
	0.20	64	256	64	0.0001	1.0000	3	1.00	0.014	0.017

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	64	256	64	0.0001	0.0100	2	1.00	0.012	0.018
0.20	64	256	64	0.0001	0.0100	3	1.00	0.012	0.018
0.20	64	256	64	0.0001	0.0001	2	1.00	0.014	0.023
0.20	64	256	64	0.0001 1.0000	0.0001	3	1.00	0.014	0.023
0.20	64	256 256	256 256	1.0000	1.0000	3	1.00	0.026	0.036
0.20	64	256	256	1.0000	0.0100	2	1.00	0.034	0.079
0.20	64	256	256	1.0000	0.0100	3	1.00	0.035	0.053
0.20	64	256	256	1.0000	0.0001	2	1.00	0.049	0.075
0.20	64	256	256	1.0000	0.0001	3	1.00	0.052	0.075
0.20	64	256	256	0.0100	1.0000	2	1.00	0.054	0.055
0.20	64	256	256	0.0100	1.0000	3	1.00	0.054	0.056
0.20	64	256	256	0.0100	0.0100	2	1.00	0.074	0.080
0.20	64	256 256	256 256	0.0100	0.0100	3	1.00	0.053	0.079 0.100
0.20	64	256	256	0.0100	0.0001	3	1.00	0.094	0.100
0.20	64	256	256	0.0100	1.0000	2	1.00	0.051	0.100
0.20	64	256	256	0.0001	1.0000	3	1.00	0.050	0.083
0.20	64	256	256	0.0001	0.0100	2	1.00	0.060	0.099
0.20	64	256	256	0.0001	0.0100	3	1.00	0.061	0.099
0.20	64	256	256	0.0001	0.0001	2	1.00	0.090	0.127
0.20	64	256	256	0.0001	0.0001	3	1.00	0.119	0.126
0.20	256	1	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	256 256	1	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256	1	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	1	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	256	1	1	0.0100	1.0000	2	1.00	0.003	0.005
0.20	256	1	1	0.0100	1.0000	3	1.00	0.003	0.004
0.20	256	1	1	0.0100	0.0100	2	1.00	0.002	0.003
0.20	256	1	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	256	1	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	256	1	1	0.0100	0.0001	3	1.00	0.003	0.014
0.20	256 256	1	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	256	1	1	0.0001	0.0100	2	1.00	0.002	0.003
0.20	256	1	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	256	1	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	256	1	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	256	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	256	1	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	1	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256 256	1	4	1.0000	0.0001	3	1.00	0.003	0.003
0.20	256	1	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	256	1	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	256	1	4	0.0100	0.0100	2	1.00	0.003	0.003
0.20	256	1	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	256	1	4	0.0100	0.0001	2	1.00	0.003	0.003
0.20	256	1	4	0.0100	0.0001	3	1.00	0.003	0.003
0.20	256	1	4	0.0001	1.0000	2	1.00	0.003	0.003
0.20	256	1	4	0.0001	1.0000 0.0100	3	1.00	0.003	0.003
0.20	256 256	1	4	0.0001	0.0100	3	1.00	0.003	0.003
0.20	256	1	4	0.0001	0.0001	2	1.00	0.003	0.003
0.20	256	1	4	0.0001	0.0001	3	1.00	0.003	0.003
0.20	256	1	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	256	1	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	256	1	16	1.0000	0.0100	2	1.00	0.004	0.004
0.20	256	1	16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	256	1	16	1.0000	0.0001	2	1.00	0.004	0.005
0.20	256 256	1	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00	0.004	0.005
0.20	256	1	16	0.0100	1.0000	3	1.00	0.004	0.004
0.20	256	1	16	0.0100	0.0100	2	1.00	0.004	0.004
0.20	256	1	16	0.0100	0.0100	3	1.00	0.004	0.005
0.20	256	1	16	0.0100	0.0001	2	1.00	0.005	0.005
0.20	256	1	16	0.0100	0.0001	3	1.00	0.004	0.016
0.20	256	1	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	256	1	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	256	1	16	0.0001	0.0100	2	1.00	0.006	0.007
0.20	256	1	16	0.0001	0.0100	3	1.00	0.006	0.007
0.20	256 256	1	16 16	0.0001	0.0001	3	1.00	0.005	0.007
0.20	230	1	10	0.0001	0.0001	3	1.00	0.003	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	256	1	64	1.0000	1.0000	2	1.00	0.006	0.009
0.20	256	1	64	1.0000	1.0000	3	1.00	0.008	0.009
0.20	256 256	1	64 64	1.0000	0.0100	3	1.00	0.009	0.062
0.20	256	1	64	1.0000	0.0100	2	1.00	0.008	0.012
0.20	256	1	64	1.0000	0.0001	3	1.00	0.011	0.012
0.20	256	1	64	0.0100	1.0000	2	1.00	0.008	0.012
0.20	256	1	64	0.0100	1.0000	3	1.00	0.012	0.012
0.20	256 256	1	64 64	0.0100	0.0100	2	1.00	0.015	0.015 0.016
0.20	256	1	64	0.0100	0.0001	2	1.00	0.013	0.018
0.20	256	1	64	0.0100	0.0001	3	1.00	0.017	0.018
0.20	256	1	64	0.0001	1.0000	2	1.00	0.013	0.017
0.20	256	1	64	0.0001	1.0000	3	1.00	0.010	0.017
0.20	256 256	1	64	0.0001	0.0100	2	1.00	0.012	0.014 0.014
0.20	256	1	64	0.0001	0.0001	2	1.00	0.012	0.014
0.20	256	1	64	0.0001	0.0001	3	1.00	0.013	0.016
0.20	256	1	256	1.0000	1.0000	2	1.00	0.022	0.025
0.20	256	1	256	1.0000	1.0000	3	1.00	0.024	0.024
0.20	256 256	1	256 256	1.0000	0.0100	2	1.00	0.035	0.037
0.20	256	1	256	1.0000	0.0001	2	1.00	0.035	0.057
0.20	256	1	256	1.0000	0.0001	3	1.00	0.045	0.051
0.20	256	1	256	0.0100	1.0000	2	1.00	0.033	0.036
0.20	256	1	256	0.0100	1.0000	3	1.00	0.033	0.036
0.20	256 256	1	256 256	0.0100	0.0100	3	1.00	0.049	0.061
0.20	256	1	256	0.0100	0.0001	2	1.00	0.060	0.034
0.20	256	1	256	0.0100	0.0001	3	1.00	0.061	0.066
0.20	256	1	256	0.0001	1.0000	2	1.00	0.054	0.060
0.20	256 256	1	256 256	0.0001	1.0000 0.0100	2	1.00	0.054	0.060
0.20	256	1	256	0.0001	0.0100	3	1.00	0.063	0.068
0.20	256	1	256	0.0001	0.0001	2	1.00	0.076	0.098
0.20	256	1	256	0.0001	0.0001	3	1.00	0.076	0.095
0.20	256	4	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256 256	4	1	1.0000	1.0000 0.0100	2	1.00	0.003	0.003
0.20	256	4	1	1.0000	0.0100	3	1.00	0.002	0.003
0.20	256	4	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	256	4	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	256	4	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	256 256	4	1	0.0100	1.0000 0.0100	3	1.00	0.002 0.003	0.003
0.20	256	4	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	256	4	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	256	4	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	256 256	4	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	256	4	1	0.0001	0.0100	2	1.00	0.002	0.003
0.20	256	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	256	4	1	0.0001	0.0001	2	1.00	0.003	0.003
0.20	256	4	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	256 256	4	4	1.0000	1.0000	3	1.00	0.003	0.004
0.20	256	4	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	4	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256	4	4	1.0000	0.0001	2	1.00	0.003	0.004
0.20	256 256	4	4	1.0000 0.0100	0.0001 1.0000	3	1.00	0.003	0.004 0.004
0.20	256	4	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	256	4	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	256	4	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	256	4	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	256 256	4	4	0.0100	0.0001 1.0000	2	1.00	0.003	0.004
0.20	256	4	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	256	4	4	0.0001	0.0100	2	1.00	0.003	0.004
0.20	256	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.20	256	4	4	0.0001	0.0001	2	1.00	0.003	0.003
0.20	256 256	4	4 16	0.0001 1.0000	0.0001 1.0000	3 2	1.00	0.003	0.004
0.20	256	4	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	256	4	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	256	4	16	1.0000	0.0100	3	1.00	0.004	0.005

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	$_{ m mint}$	maxt
0.20	256	4	16	1.0000	0.0001	2	1.00	0.004	0.005
0.20	256	4	16	1.0000	0.0001	3	1.00	0.004	0.006
0.20	256	4	16	0.0100	1.0000	2	1.00	0.004	0.005
0.20	256 256	4	16 16	0.0100	1.0000 0.0100	3	1.00	0.004	0.005
0.20	256	4	16	0.0100	0.0100	3	1.00	0.004	0.005
0.20	256	4	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	256	4	16	0.0100	0.0001	3	1.00	0.004	0.006
0.20	256	4	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	256	4	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	256	4	16	0.0001	0.0100	2	1.00	0.004	0.006
0.20	256	4	16	0.0001	0.0100	3	1.00	0.004	0.006
0.20	256	4	16	0.0001	0.0001	2	1.00	0.005	0.007
0.20	256 256	4	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00	0.005	0.007 0.014
0.20	256	4	64	1.0000	1.0000	3	1.00	0.006	0.014
0.20	256	4	64	1.0000	0.0100	2	1.00	0.008	0.010
0.20	256	4	64	1.0000	0.0100	3	1.00	0.008	0.009
0.20	256	4	64	1.0000	0.0001	2	1.00	0.010	0.013
0.20	256	4	64	1.0000	0.0001	3	1.00	0.010	0.013
0.20	256	4	64	0.0100	1.0000	2	1.00	0.008	0.010
0.20	256	4	64	0.0100	1.0000	3	1.00	0.008	0.012
0.20	256	4	64	0.0100	0.0100	2	1.00	0.015	0.015
0.20	256	4	64	0.0100	0.0100	3	1.00	0.015	0.015
0.20	256 256	4	64	0.0100	0.0001	3	1.00	0.017 0.015	0.060
0.20	256	4	64	0.0100	1.00001	2	1.00	0.013	0.018
0.20	256	4	64	0.0001	1.0000	3	1.00	0.010	0.015
0.20	256	4	64	0.0001	0.0100	2	1.00	0.012	0.013
0.20	256	4	64	0.0001	0.0100	3	1.00	0.011	0.018
0.20	256	4	64	0.0001	0.0001	2	1.00	0.014	0.015
0.20	256	4	64	0.0001	0.0001	3	1.00	0.013	0.015
0.20	256	4	256	1.0000	1.0000	2	1.00	0.021	0.022
0.20	256	4	256	1.0000	1.0000	3	1.00	0.021	0.022
0.20	256 256	4	256 256	1.0000	0.0100	3	1.00	0.033	0.052
0.20	256	4	256	1.0000	0.0001	2	1.00	0.032	0.030
0.20	256	4	256	1.0000	0.0001	3	1.00	0.049	0.075
0.20	256	4	256	0.0100	1.0000	2	1.00	0.043	0.052
0.20	256	4	256	0.0100	1.0000	3	1.00	0.039	0.053
0.20	256	4	256	0.0100	0.0100	2	1.00	0.053	0.079
0.20	256	4	256	0.0100	0.0100	3	1.00	0.068	0.078
0.20	256	4	256	0.0100	0.0001	2	1.00	0.060	0.098
0.20	256	4	256	0.0100	0.0001	3	1.00	0.059	0.099
0.20	256 256	4	256 256	0.0001	1.0000	3	1.00	0.052	0.079
0.20	256	4	256	0.0001	0.0100	2	1.00	0.031	0.077
0.20	256	4	256	0.0001	0.0100	3	1.00	0.076	0.093
0.20	256	4	256	0.0001	0.0001	2	1.00	0.092	0.114
0.20	256	4	256	0.0001	0.0001	3	1.00	0.093	0.116
0.20	256	16	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256	16	1	1.0000	1.0000	3	1.00	0.002	0.003
0.20	256	16	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256 256	16 16	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	256	16	1	0.0100	1.00001	2	1.00	0.003	0.003
0.20	256	16	1	0.0100	1.0000	3	1.00	0.002	0.003
0.20	256	16	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	256	16	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	256	16	1	0.0100	0.0001	2	1.00	0.002	0.003
0.20	256	16	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	256	16	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	256	16	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	256	16	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	256 256	16 16	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	256	16	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	256	16	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256	16	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	256	16	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	16	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256	16	4	1.0000	0.0001	2	1.00	0.003	0.003
0.20	256	16	4	1.0000	0.0001	3	1.00	0.003	0.003
0.20	256	16	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	256	16	4	0.0100	1.0000	3	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	256	16	4	0.0100	0.0100	2	1.00	0.003	0.003
0.20	256	16	4	0.0100	0.0100	3	1.00	0.003	0.003
0.20	256	16	4	0.0100	0.0001	2	1.00	0.003	0.004
0.20	256 256	16 16	4	0.0100	0.0001 1.0000	3	1.00	0.003	0.003
0.20	256	16	4	0.0001	1.0000	3	1.00	0.003	0.003
0.20	256	16	4	0.0001	0.0100	2	1.00	0.003	0.003
0.20	256	16	4	0.0001	0.0100	3	1.00	0.003	0.003
0.20	256	16	4	0.0001	0.0001	2	1.00	0.003	0.004
0.20	256	16	4	0.0001	0.0001	3	1.00	0.003	0.004
0.20	256	16	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	256 256	16 16	16 16	1.0000	1.0000 0.0100	3	1.00	0.003	0.004
0.20	256	16	16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	256	16	16	1.0000	0.0001	2	1.00	0.004	0.006
0.20	256	16	16	1.0000	0.0001	3	1.00	0.004	0.006
0.20	256	16	16	0.0100	1.0000	2	1.00	0.005	0.005
0.20	256	16	16	0.0100	1.0000	3	1.00	0.005	0.005
0.20	256	16 16	16 16	0.0100	0.0100	3	1.00	0.005	0.006
0.20	256 256	16	16	0.0100	0.0001	2	1.00	0.005	0.006
0.20	256	16	16	0.0100	0.0001	3	1.00	0.005	0.006
0.20	256	16	16	0.0001	1.0000	2	1.00	0.004	0.006
0.20	256	16	16	0.0001	1.0000	3	1.00	0.004	0.006
0.20	256	16	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	256	16	16	0.0001	0.0100	3	1.00	0.004	0.006
0.20	256	16	16	0.0001	0.0001	2	1.00	0.005	0.007
0.20	256	16	16	0.0001	0.0001	3	1.00	0.005	0.007
0.20	256 256	16 16	64	1.0000	1.0000	2	1.00	0.006	0.008
0.20	256	16	64	1.0000	0.0100	2	1.00	0.008	0.008
0.20	256	16	64	1.0000	0.0100	3	1.00	0.007	0.057
0.20	256	16	64	1.0000	0.0001	2	1.00	0.015	0.016
0.20	256	16	64	1.0000	0.0001	3	1.00	0.016	0.016
0.20	256	16	64	0.0100	1.0000	2	1.00	0.011	0.012
0.20	256	16	64	0.0100	1.0000	3	1.00	0.008	0.012
0.20	256	16	64	0.0100	0.0100	2	1.00	0.010	0.015
0.20	256 256	16 16	64	0.0100	0.0100	2	1.00	0.010	0.015 0.014
0.20	256	16	64	0.0100	0.0001	3	1.00	0.011	0.014
0.20	256	16	64	0.0001	1.0000	2	1.00	0.011	0.012
0.20	256	16	64	0.0001	1.0000	3	1.00	0.010	0.013
0.20	256	16	64	0.0001	0.0100	2	1.00	0.011	0.013
0.20	256	16	64	0.0001	0.0100	3	1.00	0.011	0.014
0.20	256	16	64	0.0001	0.0001	2	1.00	0.014	0.016
0.20	256 256	16 16	64 256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.015	0.016 0.024
0.20	256	16	256	1.0000	1.0000	3	1.00	0.022	0.024
0.20	256	16	256	1.0000	0.0100	2	1.00	0.032	0.035
0.20	256	16	256	1.0000	0.0100	3	1.00	0.032	0.036
0.20	256	16	256	1.0000	0.0001	2	1.00	0.045	0.047
0.20	256	16	256	1.0000	0.0001	3	1.00	0.046	0.048
0.20	256	16	256	0.0100	1.0000	2	1.00	0.035	0.052
0.20	256	16	256	0.0100	1.0000	3	1.00	0.034	0.049
0.20	256 256	16 16	256 256	0.0100	0.0100	2	1.00	0.051	0.054 0.055
0.20	256	16	256	0.0100	0.0100	2	1.00	0.049	0.055
0.20	256	16	256	0.0100	0.0001	3	1.00	0.063	0.065
0.20	256	16	256	0.0001	1.0000	2	1.00	0.051	0.056
0.20	256	16	256	0.0001	1.0000	3	1.00	0.051	0.068
0.20	256	16	256	0.0001	0.0100	2	1.00	0.064	0.107
0.20	256	16	256	0.0001	0.0100	3	1.00	0.064	0.097
0.20	256	16	256	0.0001	0.0001	2	1.00	0.078	0.128
0.20	256 256	16 64	256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.076	0.124
0.20	256	64	1	1.0000	1.0000	3	1.00	0.003	0.003
0.20	256	64	1	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	64	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256	64	1	1.0000	0.0001	2	1.00	0.003	0.004
0.20	256	64	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	256	64	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	256	64	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	256	64	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	256 256	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.20	256	64	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	200	L 04	1	0.0100	0.0001	ی	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	256	64	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	256	64	1	0.0001	1.0000	3	1.00	0.003	0.003
0.20	256	64	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	256 256	64	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	256	64	1	0.0001	0.0001	3	1.00	0.003	0.003
0.20	256	64	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256	64	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	256	64	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	64	4	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256	64	4	1.0000	0.0001	2	1.00	0.003	0.004
0.20	256	64	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	256	64	4	0.0100	1.0000	2	1.00	0.003	0.003
0.20	256	64	4	0.0100	1.0000	3	1.00	0.003	0.003
0.20	256 256	64	4	0.0100	0.0100	2	1.00	0.004	0.004
0.20	256	64	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	256	64	4	0.0100	0.0001	3	1.00	0.003	0.004
0.20	256	64	4	0.0001	1.0000	2	1.00	0.003	0.004
0.20	256	64	4	0.0001	1.0000	3	1.00	0.003	0.004
0.20	256	64	4	0.0001	0.0100	2	1.00	0.004	0.013
0.20	256	64	4	0.0001	0.0100	3	1.00	0.004	0.004
0.20	256	64	4	0.0001	0.0001	2	1.00	0.004	0.004
0.20	256	64	4	0.0001	0.0001	3	1.00	0.004	0.004
0.20	256	64	16	1.0000	1.0000	2	1.00	0.003	0.004
0.20	256	64	16	1.0000	1.0000	3	1.00	0.003	0.004
0.20	256 256	64	16 16	1.0000	0.0100	3	1.00	0.004	0.004
0.20	256	64	16	1.0000	0.0100	2	1.00	0.004	0.005
0.20	256	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.20	256	64	16	0.0100	1.0000	2	1.00	0.004	0.005
0.20	256	64	16	0.0100	1.0000	3	1.00	0.004	0.004
0.20	256	64	16	0.0100	0.0100	2	1.00	0.004	0.004
0.20	256	64	16	0.0100	0.0100	3	1.00	0.004	0.004
0.20	256	64	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	256	64	16	0.0100	0.0001	3	1.00	0.004	0.005
0.20	256	64	16	0.0001	1.0000	2	1.00	0.004	0.005
0.20	256	64	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	256 256	64	16 16	0.0001	0.0100	3	1.00	0.004	0.005
0.20	256	64	16	0.0001	0.0100	2	1.00	0.004	0.005
0.20	256	64	16	0.0001	0.0001	3	1.00	0.005	0.005
0.20	256	64	64	1.0000	1.0000	2	1.00	0.006	0.007
0.20	256	64	64	1.0000	1.0000	3	1.00	0.006	0.007
0.20	256	64	64	1.0000	0.0100	2	1.00	0.007	0.009
0.20	256	64	64	1.0000	0.0100	3	1.00	0.007	0.008
0.20	256	64	64	1.0000	0.0001	2	1.00	0.010	0.012
0.20	256	64	64	1.0000	0.0001	3	1.00	0.010	0.044
0.20	256	64	64	0.0100	1.0000	2	1.00	0.008	0.011
0.20	256	64	64	0.0100	1.0000	3	1.00	0.008	0.012
0.20	256 256	64	64	0.0100	0.0100	3	1.00	0.011	0.015
0.20	256	64	64	0.0100	0.0001	2	1.00	0.010	0.013
0.20	256	64	64	0.0100	0.0001	3	1.00	0.013	0.020
0.20	256	64	64	0.0001	1.0000	2	1.00	0.011	0.017
0.20	256	64	64	0.0001	1.0000	3	1.00	0.012	0.017
0.20	256	64	64	0.0001	0.0100	2	1.00	0.012	0.014
0.20	256	64	64	0.0001	0.0100	3	1.00	0.012	0.017
0.20	256	64	64	0.0001	0.0001	2	1.00	0.014	0.018
0.20	256	64	64	0.0001	0.0001	3	1.00	0.015	0.017
0.20	256	64	256	1.0000	1.0000	2	1.00	0.022	0.025
0.20	256 256	64 64	256 256	1.0000	1.0000 0.0100	3	1.00	0.022	0.025
0.20	256	64	256	1.0000	0.0100	3	1.00	0.034	0.036
0.20	256	64	256	1.0000	0.0001	2	1.00	0.034	0.036
0.20	256	64	256	1.0000	0.0001	3	1.00	0.046	0.075
0.20	256	64	256	0.0100	1.0000	2	1.00	0.033	0.036
0.20	256	64	256	0.0100	1.0000	3	1.00	0.033	0.036
0.20	256	64	256	0.0100	0.0100	2	1.00	0.050	0.064
0.20	256	64	256	0.0100	0.0100	3	1.00	0.050	0.074
0.20	256	64	256	0.0100	0.0001	2	1.00	0.064	0.085
0.20	256	64	256	0.0100	0.0001	3	1.00	0.064	0.066
0.20	256	64	256	0.0001	1.0000	3	1.00	0.053	0.057
0.20	256 256	64	256 256	0.0001	1.0000 0.0100	2	1.00	0.053	0.085
0.20	256	64	256	0.0001	0.0100	3	1.00	0.062	0.067
0.20	250	U-T	250	0.0001	0.0100		1.00	0.002	0.000

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	256	64	256	0.0001	0.0001	2	1.00	0.075	0.128
0.20	256	64	256	0.0001	0.0001	3	1.00	0.076	0.125
0.20	256	256	1	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256 256	256 256	1	1.0000	1.0000 0.0100	3	1.00	0.003	0.003
0.20	256	256	1	1.0000	0.0100	3	1.00	0.003	0.003
0.20	256	256	1	1.0000	0.0001	2	1.00	0.003	0.003
0.20	256	256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.20	256	256	1	0.0100	1.0000	2	1.00	0.003	0.003
0.20	256	256	1	0.0100	1.0000	3	1.00	0.003	0.003
0.20	256 256	256 256	1	0.0100	0.0100	2	1.00	0.003	0.003
0.20	256	256	1	0.0100	0.0001	2	1.00	0.003	0.003
0.20	256	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.20	256	256	1	0.0001	1.0000	2	1.00	0.003	0.003
0.20	256	256	1	0.0001	1.0000	3	1.00	0.002	0.003
0.20	256	256	1	0.0001	0.0100	2	1.00	0.003	0.003
0.20	256 256	256 256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.20	256	256	1	0.0001	0.0001	3	1.00	0.002	0.003
0.20	256	256	4	1.0000	1.0000	2	1.00	0.003	0.003
0.20	256	256	4	1.0000	1.0000	3	1.00	0.003	0.003
0.20	256	256	4	1.0000	0.0100	2	1.00	0.003	0.003
0.20	256	256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.20	256 256	256 256	4	1.0000	0.0001	3	1.00	0.003	0.004
0.20	256	256	4	0.0100	1.00001	2	1.00	0.003	0.004
0.20	256	256	4	0.0100	1.0000	3	1.00	0.003	0.004
0.20	256	256	4	0.0100	0.0100	2	1.00	0.003	0.004
0.20	256	256	4	0.0100	0.0100	3	1.00	0.003	0.004
0.20	256	256	4	0.0100	0.0001	2	1.00	0.004	0.004
0.20	256 256	256 256	4	0.0100	1.0000	3	1.00	0.004	0.004
0.20	256	256	4	0.0001	1.0000	3	1.00	0.004	0.004
0.20	256	256	4	0.0001	0.0100	2	1.00	0.004	0.004
0.20	256	256	4	0.0001	0.0100	3	1.00	0.004	0.004
0.20	256	256	4	0.0001	0.0001	2	1.00	0.004	0.004
0.20	256	256	4	0.0001	0.0001	3	1.00	0.004	0.004
0.20	256 256	256 256	16 16	1.0000	1.0000	3	1.00	0.004	0.004
0.20	256	256	16	1.0000	0.0100	2	1.00	0.004	0.004
0.20	256	256	16	1.0000	0.0100	3	1.00	0.005	0.005
0.20	256	256	16	1.0000	0.0001	2	1.00	0.006	0.006
0.20	256	256	16	1.0000	0.0001	3	1.00	0.006	0.006
0.20	256	256	16	0.0100	1.0000	2	1.00	0.005	0.006
0.20	256	256	16	0.0100	1.0000	3	1.00	0.004	0.005
0.20	256 256	256 256	16 16	0.0100	0.0100 0.0100	2	1.00	0.004	0.006 0.005
0.20	256	256	16	0.0100	0.0001	2	1.00	0.004	0.005
0.20	256	256	16	0.0100	0.0001	3	1.00	0.004	0.005
0.20	256	256	16	0.0001	1.0000	2	1.00	0.004	0.006
0.20	256	256	16	0.0001	1.0000	3	1.00	0.004	0.005
0.20	256	256	16	0.0001	0.0100	2	1.00	0.005	0.006
0.20	256 256	256 256	16 16	0.0001	0.0100	3	1.00	0.005	0.006
0.20	256	256	16	0.0001	0.0001	3	1.00	0.005	0.007
0.20	256	256	64	1.0000	1.0000	2	1.00	0.006	0.009
0.20	256	256	64	1.0000	1.0000	3	1.00	0.006	0.009
0.20	256	256	64	1.0000	0.0100	2	1.00	0.007	0.011
0.20	256	256	64	1.0000	0.0100	3	1.00	0.007	0.011
0.20	256 256	256 256	64	1.0000	0.0001	3	1.00	0.010	0.016
0.20	256	256	64	0.0100	1.0000	2	1.00	0.010	0.010
0.20	256	256	64	0.0100	1.0000	3	1.00	0.008	0.010
0.20	256	256	64	0.0100	0.0100	2	1.00	0.010	0.015
0.20	256	256	64	0.0100	0.0100	3	1.00	0.010	0.014
0.20	256	256	64	0.0100	0.0001	2	1.00	0.012	0.017
0.20	256	256	64	0.0100	0.0001	3	1.00	0.011	0.017
0.20	256 256	256 256	64 64	0.0001	1.0000	2	1.00	0.015	0.017 0.017
0.20	256	256	64	0.0001	0.0100	2	1.00	0.013	0.017
0.20	256	256	64	0.0001	0.0100	3	1.00	0.012	0.012
0.20	256	256	64	0.0001	0.0001	2	1.00	0.014	0.015
0.20	256	256	64	0.0001	0.0001	3	1.00	0.015	0.015
0.20	256	256	256	1.0000	1.0000	2	1.00	0.022	0.038
0.20	256	256	256	1.0000	1.0000	3	1.00	0.022	0.036

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.20	256	256	256	1.0000	0.0100	2	1.00	0.045	0.052
0.20	256	256	256	1.0000	0.0100	3	1.00	0.037	0.053
0.20	256	256	256	1.0000	0.0001	2	1.00	0.050	0.078
0.20	256	256	256	1.0000	0.0001	3	1.00	0.051	0.068
0.20	256	256	256	0.0100	1.0000	2	1.00	0.034	0.055
0.20	256	256	256	0.0100	1.0000	3	1.00	0.032	0.054
0.20	256	256	256	0.0100	0.0100	2	1.00	0.056	0.079
0.20	256	256	256	0.0100	0.0100	3	1.00	0.054	0.079
0.20	256	256	256	0.0100	0.0001	2	1.00	0.058	0.098
0.20	256 256	256	256 256	0.0100	0.0001	3	1.00	0.058	0.094
0.20	256	256 256	256	0.0001	1.0000	3	1.00	0.070	0.078
0.20	256	256	256	0.0001	0.0100	2	1.00	0.003	0.101
0.20	256	256	256	0.0001	0.0100	3	1.00	0.065	0.101
0.20	256	256	256	0.0001	0.0001	2	1.00	0.076	0.124
0.20	256	256	256	0.0001	0.0001	3	1.00	0.077	0.124
0.25	1	1	1	1.0000	1.0000	2	0.67	0.001	0.003
0.25	1	1	1	1.0000	1.0000	3	1.00	0.003	0.003
0.25	1	1	1	1.0000	0.0100	2	0.33	0.001	0.003
0.25	1	1	1	1.0000	0.0100	3	1.00	0.003	0.005
0.25	1	1	1	1.0000	0.0001	2	0.33	0.001	0.003
0.25	1	1	1	1.0000	0.0001	3	1.00	0.003	0.006
0.25	1	1	1	0.0100	1.0000	3	1.00	0.002	0.003
0.25	1	1	1	0.0100	0.0100	2	0.33	0.002	0.003
0.25	1	1	1	0.0100	0.0100	3	1.00	0.001	0.003
0.25	1	1	1	0.0100	0.0001	2	0.33	0.003	0.003
0.25	1	1	1	0.0100	0.0001	3	1.00	0.001	0.006
0.25	1	1	1	0.0001	1.0000	2	1.00	0.002	0.003
0.25	1	1	1	0.0001	1.0000	3	1.00	0.002	0.003
0.25	1	1	1	0.0001	0.0100	2	0.17	0.001	0.003
0.25	1	1	1	0.0001	0.0100	3	1.00	0.003	0.007
0.25	1	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	1	1	1	0.0001	0.0001	3	1.00	0.003	0.008
0.25	1	1	4	1.0000	1.0000	2	1.00	0.003	0.003
0.25	1	1	4	1.0000	1.0000	3	1.00	0.003	0.003
0.25	1	1	4	1.0000	0.0100	2	1.00	0.003	0.004
0.25	1	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.25	1	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.25	1	1	4	0.0100	1.0000	2	1.00	0.003	0.004
0.25	1	1	4	0.0100	1.0000	3	1.00	0.003	0.004
0.25	1	1	4	0.0100	0.0100	2	0.67	0.001	0.003
0.25	1	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.25	1	1	4	0.0100	0.0001	2	1.00	0.003	0.004
0.25	1	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.25	1	1	4	0.0001	1.0000	2	1.00	0.003	0.004
0.25	1	1	4	0.0001	1.0000	3	1.00	0.003	0.004
0.25	1	1	4	0.0001	0.0100	2	1.00	0.003	0.003
0.25	1	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	1	1	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	1	1	16	0.0001 1.0000	0.0001 1.0000	2	1.00	0.003	0.003
0.25	1	1	16	1.0000	1.0000	3	1.00	0.004	0.003
0.25	1	1	16	1.0000	0.0100	2	1.00	0.004	0.005
0.25	1	1	16	1.0000	0.0100	3	1.00	0.005	0.005
0.25	1	1	16	1.0000	0.0001	2	1.00	0.005	0.006
0.25	1	1	16	1.0000	0.0001	3	1.00	0.005	0.006
0.25	1	1	16	0.0100	1.0000	2	1.00	0.005	0.005
0.25	1	1	16	0.0100	1.0000	3	1.00	0.005	0.005
0.25	1	1	16	0.0100	0.0100	2	1.00	0.005	0.005
0.25	1	1	16	0.0100	0.0100	3	1.00	0.005	0.006
0.25	1	1	16	0.0100	0.0001	2	1.00	0.006	0.006
0.25	1	1	16	0.0100	0.0001	3	1.00	0.006	0.033
0.25	1	1	16 16	0.0001	1.0000	3	1.00	0.006	0.006
0.25	1	1	16	0.0001	0.0100	2	1.00	0.006	0.006
0.25	1	1	16	0.0001	0.0100	3	1.00	0.006	0.007
0.25	1	1	16	0.0001	0.0001	2	1.00	0.007	0.007
0.25	1	1	16	0.0001	0.0001	3	1.00	0.007	0.008
0.25	1	1	64	1.0000	1.0000	2	1.00	0.007	0.009
0.25	1	1	64	1.0000	1.0000	3	1.00	0.006	0.009
0.25	1	1	64	1.0000	0.0100	2	1.00	0.008	0.010
0.25	1	1	64	1.0000	0.0100	3	1.00	0.008	0.008
	- 1	1	64	1.0000	0.0001	2	1.00	0.009	0.011
0.25	1	1	64	1.0000	0.0001	3	1.00	0.009	0.011

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	1	1	64	0.0100	1.0000	2	1.00	0.008	0.009
0.25		1		0.0100		3	1.00		0.010
0.25	1	1	64	0.0100	0.0100	3	1.00	0.009	0.012
0.25	1	1	64	0.0100	0.0001	2	1.00	0.009	0.011
0.25	1	1	64	0.0100	0.0001	3	1.00	0.011	0.014
0.25	1	1	64	0.0100	1.0000	2	1.00	0.012	0.014
0.25	1	1	64	0.0001	1.0000	3	1.00	0.011	0.013
0.25	1	1	64	0.0001	0.0100	2	1.00	0.011	0.013
0.25	1	1	64	0.0001	0.0100	3	1.00	0.011	0.013
0.25	1	1	64	0.0001	0.0001	2	1.00	0.016	0.021
0.25	1	1	64	0.0001	0.0001	3	1.00	0.014	0.023
0.25	1	1	256	1.0000	1.0000	2	1.00	0.024	0.025
0.25	1	1	256	1.0000	1.0000	3	1.00	0.024	0.025
0.25	1	1	256	1.0000	0.0100	2	1.00	0.035	0.041
0.25	1	1	256	1.0000	0.0100	3	1.00	0.035	0.049
0.25	1	1	256	1.0000	0.0001	2	1.00	0.045	0.058
0.25	1	1	256	1.0000	0.0001	3	1.00	0.046	0.055
0.25	1	1	256	0.0100	1.0000	2	1.00	0.040	0.042
0.25	1	1	256	0.0100	1.0000	3	1.00	0.040	0.042
0.25	1	1	256	0.0100	0.0100	2	1.00	0.051	0.057
0.25	1	1	256	0.0100	0.0100	3	1.00	0.051	0.055
0.25	1	1	256	0.0100	0.0001	2	1.00	0.062	0.078
0.25	1	1	256	0.0100	0.0001	3	1.00	0.062	0.080
0.25	1	1	256	0.0001	1.0000	2	1.00	0.054	0.058
0.25	1	1	256	0.0001	1.0000	3	1.00	0.053	0.058
0.25	1	1	256	0.0001	0.0100	2	1.00	0.060	0.066
0.25	1	1	256	0.0001	0.0100	3	1.00	0.061	0.094
0.25	1	1	256	0.0001	0.0001	2	1.00	0.075	0.134
0.25	1	1	256	0.0001	0.0001	3	1.00	0.075	0.118
0.25	1	4	1	1.0000	1.0000	2	0.17	0.001	0.003
0.25	1	4	1	1.0000	1.0000	3	1.00	0.003	0.003
0.25	1	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	1	4	1	1.0000	0.0100	3	1.00	0.003	0.003
0.25	1	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	1	4	1	1.0000	0.0001	3	1.00	0.003	0.003
0.25	1	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	1	4	1	0.0100	1.0000	3	1.00	0.003	0.003
0.25	1	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	1	4	1	0.0100	0.0100	3	1.00	0.003	0.014
0.25	1	4	1	0.0100	0.0001	3	0.00	0.001	0.001
0.25	1	4	1	0.0100	0.0001 1.0000	2	1.00 0.33	0.003	0.003
0.25	1	4	1	0.0001	1.0000	3	0.83	0.001	0.003
0.25	1	4	1	0.0001	0.0100	2	0.00	0.003	0.001
0.25	1	4	1	0.0001	0.0100	3	1.00	0.001	0.001
0.25	1	4	1	0.0001	0.0001	2	0.00	0.003	0.001
0.25	1	4	1	0.0001	0.0001	3	0.83	0.001	0.001
0.25	1	4	4	1.0000	1.0000	2	0.00	0.003	0.002
0.25	1	4	4	1.0000	1.0000	3	0.83	0.001	0.002
0.25	1	4	4	1.0000	0.0100	2	0.50	0.001	0.004
0.25	1	4	4	1.0000	0.0100	3	1.00	0.003	0.004
0.25	1	4	4	1.0000	0.0001	2	0.83	0.001	0.004
0.25	1	4	4	1.0000	0.0001	3	1.00	0.003	0.004
0.25	1	4	4	0.0100	1.0000	2	0.33	0.001	0.003
0.25	1	4	4	0.0100	1.0000	3	0.83	0.003	0.020
0.25	1	4	4	0.0100	0.0100	2	0.67	0.001	0.003
0.25	1	4	4	0.0100	0.0100	3	1.00	0.003	0.008
0.25	1	4	4	0.0100	0.0001	2	0.67	0.001	0.004
0.25	1	4	4	0.0100	0.0001	3	1.00	0.003	0.004
0.25	1	4	4	0.0001	1.0000	2	0.33	0.001	0.003
0.25	1	4	4	0.0001	1.0000	3	0.67	0.003	0.020
0.25	1	4	4	0.0001	0.0100	2	0.83	0.001	0.003
0.25	1	4	4	0.0001	0.0100	3	1.00	0.003	0.003
0.25	1	4	4	0.0001	0.0001	2	0.67	0.001	0.003
0.25	1	4	4	0.0001	0.0001	3	1.00	0.003	0.005
0.25	1	4	16	1.0000	1.0000	2	0.00	0.002	0.002
0.25	1	4	16	1.0000	1.0000	3	0.00	0.024	0.026
0.25	1	4	16	1.0000	0.0100	2	0.83	0.001	0.005
0.25	1	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	1	4	16	1.0000	0.0001	2	1.00	0.004	0.005
0.25	1	4	16	1.0000	0.0001	3	1.00	0.004	0.005
0.25	1	4	16	0.0100	1.0000	2	0.00	0.002	0.003
0.25	1	4	16	0.0100	1.0000	3	0.00	0.028	0.058
0.25	1	4	16	0.0100	0.0100	2	1.00	0.004	0.005
0.25	1	4	16	0.0100	0.0100	3	1.00	0.004	0.005

0.25	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25										0.000
0.25										
0.25										
0.25										
0.25										
0.25		1	4							0.006
0.25										
0.25										
0.25										
0.25										
0.25										
0.25										
0.25	0.25	1	4	64			2		0.004	0.006
0.25										
0.25										
0.25										
0.25										
0.25 1 4 64 0.0001 1.0000 3 0.00 0.089 0.093 0.25 1 4 64 0.0001 0.0100 2 1.00 0.012 0.013 0.25 1 4 64 0.0001 0.0001 2 1.00 0.014 0.015 0.25 1 4 64 0.0001 0.0001 3 1.00 0.016 0.016 0.016 0.016 0.016 0.016 0.016 0.016 0.016 0.016 0.016 0.016 0.010 0.010 0.011 0.025 1 4 256 1.0000 1.000 0.035 0.068 0.025 1 4 256 1.0000 0.0100 2 1.00 0.034 0.036 0.025 1 4 256 1.0000 0.0001 2 1.00 0.048 0.073 0.025 1 4 256 0.0100 1.0000 3 0.00 0.016 0.02										
0.25										
0.25								1.00		
0.25										
0.25 1 4 256 1.0000 1.0000 2 0.00 0.011 0.020 0.25 1 4 256 1.0000 0.0000 2 1.00 0.035 0.068 0.25 1 4 256 1.0000 0.0100 3 1.00 0.034 0.036 0.25 1 4 256 1.0000 0.0001 2 1.00 0.048 0.073 0.25 1 4 256 1.0000 0.0001 3 1.00 0.048 0.074 0.25 1 4 256 0.0100 1.0000 2 0.00 0.016 0.027 0.25 1 4 256 0.0100 0.0100 3 1.00 0.049 0.075 0.25 1 4 256 0.0100 0.0001 2 1.00 0.064 0.01 0.25 1 4 256 0.0001 1.0000 2										
0.25 1 4 256 1.0000 1.0000 3 0.00 0.185 0.963 0.25 1 4 256 1.0000 0.0100 3 1.00 0.034 0.036 0.25 1 4 256 1.0000 0.0001 2 1.00 0.034 0.036 0.25 1 4 256 1.0000 0.0001 3 1.00 0.048 0.073 0.25 1 4 256 0.0100 1.0000 2 0.00 0.016 0.074 0.25 1 4 256 0.0100 1.0000 3 0.00 0.285 0.445 0.25 1 4 256 0.0100 0.0100 3 1.00 0.064 0.055 0.25 1 4 256 0.0100 0.0001 3 1.00 0.064 0.101 0.25 1 4 256 0.0001 1.0000 3										
0.25 1 4 256 1.0000 0.0100 2 1.00 0.035 0.066 0.25 1 4 256 1.0000 0.0001 2 1.00 0.048 0.073 0.25 1 4 256 1.0000 0.0001 3 1.00 0.048 0.073 0.25 1 4 256 0.0100 1.0000 3 0.00 0.016 0.027 0.25 1 4 256 0.0100 1.0000 3 0.00 0.285 0.445 0.25 1 4 256 0.0100 0.0100 3 1.00 0.049 0.075 0.25 1 4 256 0.0100 0.0001 3 1.00 0.064 0.101 0.25 1 4 256 0.0001 1.0000 3 1.00 0.064 0.101 0.25 1 4 256 0.0001 1.0000 2										
0.25 1 4 256 1.0000 0.0100 3 1.00 0.034 0.036 0.25 1 4 256 1.0000 0.0001 2 1.00 0.048 0.073 0.25 1 4 256 1.0000 0.0001 3 1.00 0.048 0.074 0.25 1 4 256 0.0100 1.0000 3 0.00 0.016 0.027 0.25 1 4 256 0.0100 0.0100 2 1.00 0.049 0.055 0.25 1 4 256 0.0100 0.0100 3 1.00 0.049 0.055 0.25 1 4 256 0.0100 0.0001 3 1.00 0.064 0.101 0.25 1 4 256 0.0001 1.0000 2 1.00 0.062 0.001 0.25 1 4 256 0.0001 1.0000 3										
0.25										
0.25 1 4 256 0.0100 1.0000 2 0.00 0.016 0.027 0.25 1 4 256 0.0100 1.000 3 0.00 0.285 0.445 0.25 1 4 256 0.0100 0.0100 3 1.00 0.049 0.055 0.25 1 4 256 0.0100 0.0001 2 1.00 0.064 0.101 0.25 1 4 256 0.0100 0.0001 3 1.00 0.064 0.101 0.25 1 4 256 0.0001 1.0000 2 0.00 0.025 0.041 0.25 1 4 256 0.0001 0.0100 2 1.00 0.062 0.091 0.25 1 4 256 0.0001 0.0001 2 1.00 0.062 0.070 0.25 1 4 256 0.0001 0.0001 3		1					2			
0.25										
0.25 1 4 256 0.0100 0.0100 2 1.00 0.049 0.075 0.25 1 4 256 0.0100 0.0001 2 1.00 0.049 0.055 0.25 1 4 256 0.0100 0.0001 2 1.00 0.064 0.101 0.25 1 4 256 0.0001 1.0000 2 0.00 0.025 0.041 0.25 1 4 256 0.0001 1.0000 3 0.00 0.406 0.500 0.25 1 4 256 0.0001 0.0100 3 1.00 0.062 0.091 0.25 1 4 256 0.0001 0.0100 3 1.00 0.062 0.070 0.25 1 4 256 0.0001 0.0001 3 1.00 0.072 0.117 0.25 1 16 1 1.0000 1.0001 3										
0.25										
0.25										
0.25										
0.25 1 4 256 0.0001 1.0000 3 0.00 0.406 0.500 0.25 1 4 256 0.0001 0.0100 2 1.00 0.062 0.091 0.25 1 4 256 0.0001 0.0100 3 1.00 0.062 0.091 0.25 1 4 256 0.0001 0.0001 2 1.00 0.072 0.117 0.25 1 4 256 0.0001 0.0001 3 1.00 0.072 0.117 0.25 1 16 1 1.0000 1.0000 3 0.83 0.003 0.013 0.25 1 16 1 1.0000 0.0100 3 1.00 0.001 0.001 0.25 1 16 1 1.0000 0.0100 3 1.00 0.003 0.003 0.25 1 16 1 1.0000 0.0001 3 <td< td=""><td></td><td>1</td><td>4</td><td>256</td><td></td><td></td><td>3</td><td></td><td></td><td></td></td<>		1	4	256			3			
0.25 1 4 256 0.0001 0.0100 2 1.00 0.062 0.091 0.25 1 4 256 0.0001 0.0100 3 1.00 0.062 0.070 0.25 1 4 256 0.0001 0.0001 2 1.00 0.072 0.117 0.25 1 16 1 1.0000 1.0000 2 0.00 0.001 0.001 0.25 1 16 1 1.0000 1.0000 2 0.00 0.001 0.001 0.25 1 16 1 1.0000 0.0100 2 0.00 0.001 0.001 0.25 1 16 1 1.0000 0.0100 3 1.00 0.003 0.003 0.25 1 16 1 1.0000 0.0001 3 1.00 0.001 0.001 0.25 1 16 1 0.0100 1.0000 3 1										
0.25										
0.25										
0.25										
0.25										
0.25										
0.25	0.25	1	16	1	1.0000	1.0000	3	0.83	0.003	0.013
0.25		1		1						
0.25 1 16 1 1.0000 0.0001 3 1.00 0.003 0.003 0.25 1 16 1 0.0100 1.0000 2 0.17 0.001 0.003 0.25 1 16 1 0.0100 1.0000 3 1.00 0.003 0.003 0.25 1 16 1 0.0100 0.0100 2 0.00 0.001 0.001 0.25 1 16 1 0.0100 0.0100 3 0.83 0.003 0.012 0.25 1 16 1 0.0100 0.0001 2 0.00 0.001 0.001 0.25 1 16 1 0.0100 0.0001 3 1.00 0.003 0.003 0.25 1 16 1 0.0001 1.0000 2 0.00 0.001 0.003 0.25 1 16 1 0.0001 1.0000 2 0.00										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.25	1	16		0.0100	0.0100		0.83	0.003	0.012
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		1			0.0001	0.0001			0.003	0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.25 1 16 4 0.0100 0.0100 2 1.00 0.003 0.003 0.25 1 16 4 0.0100 0.0100 3 1.00 0.003 0.003 0.25 1 16 4 0.0100 0.0001 2 0.67 0.001 0.004 0.25 1 16 4 0.0100 0.0001 3 1.00 0.003 0.004 0.25 1 16 4 0.0001 1.0000 2 0.17 0.001 0.003										
0.25 1 16 4 0.0100 0.0100 3 1.00 0.003 0.003 0.25 1 16 4 0.0100 0.0001 2 0.67 0.001 0.004 0.25 1 16 4 0.0100 0.0001 3 1.00 0.003 0.004 0.25 1 16 4 0.0001 1.0000 2 0.17 0.001 0.003	0.25	1	16		0.0100	1.0000	3	0.83	0.003	0.019
0.25 1 16 4 0.0100 0.0001 2 0.67 0.001 0.004 0.25 1 16 4 0.0100 0.0001 3 1.00 0.003 0.004 0.25 1 16 4 0.0001 1.0000 2 0.17 0.001 0.003										
0.25 1 16 4 0.0100 0.0001 3 1.00 0.003 0.004 0.25 1 16 4 0.0001 1.0000 2 0.17 0.001 0.003										
0.25 1 16 4 0.0001 1.0000 2 0.17 0.001 0.003										
	0.25	1	16	4	0.0001	1.0000	3	0.17	0.001	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	1	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.25	1	16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	1	16	4	0.0001	0.0001	2	0.83	0.001	0.004
0.25	1	16 16	4 16	0.0001 1.0000	0.0001 1.0000	3	0.00	0.003	0.004
0.25	1	16	16	1.0000	1.0000	3	0.00	0.001	0.002
0.25	1	16	16	1.0000	0.0100	2	0.67	0.001	0.005
0.25	1	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	1	16	16	1.0000	0.0001	2	0.83	0.001	0.006
0.25	1	16	16	1.0000	0.0001	3	1.00	0.006	0.006
0.25	1	16	16	0.0100	1.0000	2	0.00	0.001	0.003
0.25	1	16 16	16 16	0.0100	1.0000 0.0100	3	0.00 1.00	0.027 0.004	0.038
0.25	1	16	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	1	16	16	0.0100	0.0001	2	1.00	0.004	0.005
0.25	1	16	16	0.0100	0.0001	3	1.00	0.004	0.005
0.25	1	16	16	0.0001	1.0000	2	0.17	0.001	0.005
0.25	1	16	16	0.0001	1.0000	3	0.17	0.005	0.035
0.25	1	16 16	16 16	0.0001	0.0100	2	1.00	0.004	0.005
0.25	1	16	16	0.0001	0.0100	2	1.00	0.004	0.006
0.25	1	16	16	0.0001	0.0001	3	1.00	0.005	0.007
0.25	1	16	64	1.0000	1.0000	2	0.00	0.003	0.005
0.25	1	16	64	1.0000	1.0000	3	0.00	0.049	0.059
0.25	1	16	64	1.0000	0.0100	2	0.83	0.001	0.011
0.25	1	16	64	1.0000	0.0100	3	1.00	0.008	0.012
0.25	1	16 16	64 64	1.0000	0.0001	3	1.00	0.009	0.011
0.25	1	16	64	0.0100	1.0000	2	0.00	0.004	0.006
0.25	1	16	64	0.0100	1.0000	3	0.00	0.064	0.090
0.25	1	16	64	0.0100	0.0100	2	1.00	0.014	0.015
0.25	1	16	64	0.0100	0.0100	3	1.00	0.014	0.015
0.25	1	16	64	0.0100	0.0001	2	1.00	0.015	0.018
0.25	1	16 16	64	0.0100	0.0001 1.0000	3 2	1.00 0.00	0.017	0.018
0.25	1	16	64	0.0001	1.0000	3	0.00	0.000	0.791
0.25	1	16	64	0.0001	0.0100	2	1.00	0.016	0.018
0.25	1	16	64	0.0001	0.0100	3	1.00	0.011	0.018
0.25	1	16	64	0.0001	0.0001	2	1.00	0.019	0.022
0.25	1	16	64	0.0001	0.0001	3	1.00	0.019	0.022
0.25	1	16	256	1.0000	1.0000	2	0.00	0.011	0.017
0.25	1	16 16	256 256	1.0000	1.0000 0.0100	3	1.00	0.239	0.277
0.25	1	16	256	1.0000	0.0100	3	1.00	0.033	0.051
0.25	1	16	256	1.0000	0.0001	2	1.00	0.045	0.046
0.25	1	16	256	1.0000	0.0001	3	1.00	0.045	0.047
0.25	1	16	256	0.0100	1.0000	2	0.00	0.017	0.025
0.25	1	16	256	0.0100	1.0000	3	0.00	0.285	1.226
0.25	1	16 16	256 256	0.0100	0.0100	2	1.00	0.045	0.048
0.25	1	16	256	0.0100	0.0100	2	1.00	0.046	0.049
0.25	1	16	256	0.0100	0.0001	3	1.00	0.066	0.003
0.25	1	16	256	0.0001	1.0000	2	0.00	0.024	0.041
0.25	1	16	256	0.0001	1.0000	3	0.00	0.406	1.019
0.25	1	16	256	0.0001	0.0100	2	1.00	0.060	0.081
0.25	1	16	256	0.0001	0.0100	3	1.00	0.058	0.066
0.25	1	16 16	256 256	0.0001	0.0001	3	1.00	0.077	0.083
0.25	1	64	1	1.0000	1.0000	2	0.00	0.001	0.003
0.25	1	64	1	1.0000	1.0000	3	0.83	0.003	0.014
0.25	1	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	1	64	1	1.0000	0.0100	3	0.67	0.003	0.014
0.25	1	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	1	64	1	1.0000 0.0100	0.0001 1.0000	3	0.83	0.003	0.013
0.25	1	64	1	0.0100	1.0000	3	0.50	0.001	0.001
0.25	1	64	1	0.0100	0.0100	2	0.00	0.003	0.001
0.25	1	64	1	0.0100	0.0100	3	1.00	0.003	0.003
0.25	1	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.25	1	64	1	0.0100	0.0001	3	1.00	0.003	0.003
0.25	1	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	1	64	1	0.0001	1.0000 0.0100	3	0.83	0.003	0.013
0.25	1	64	1	0.0001	0.0100	3	0.83	0.001	0.001
0.25	1	64	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	1	64	1	0.0001	0.0001	3	1.00	0.003	0.003
							-		

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	1	64	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	1	64	4	1.0000	1.0000	3	0.33	0.003	0.014
0.25	1	64	4	1.0000	0.0100	2	0.50	0.001	0.003
0.25	1	64	4	1.0000	0.0100	3	1.00	0.003	0.003
0.25	1	64	4	1.0000	0.0001	2	0.67	0.001	0.003
0.25	1	64	4	1.0000	0.0001	3	1.00	0.003	0.003
0.25	1	64	4	0.0100	1.0000	3	0.33	0.001	0.003
0.25	1	64	4	0.0100	0.0100	2	0.50	0.003	0.018
0.25	1	64	4	0.0100	0.0100	3	1.00	0.001	0.003
0.25	1	64	4	0.0100	0.0001	2	0.50	0.003	0.003
0.25	1	64	4	0.0100	0.0001	3	1.00	0.003	0.003
0.25	1	64	4	0.0001	1.0000	2	0.33	0.001	0.003
0.25	1	64	4	0.0001	1.0000	3	0.67	0.003	0.021
0.25	1	64	4	0.0001	0.0100	2	1.00	0.003	0.003
0.25	1	64	4	0.0001	0.0100	3	1.00	0.003	0.003
0.25	1	64	4	0.0001	0.0001	2	0.83	0.001	0.003
0.25	1	64	4	0.0001	0.0001	3	1.00	0.003	0.003
0.25	1	64	16 16	1.0000	1.0000	3	0.00	0.001	0.002
0.25	1	64	16	1.0000	0.0100	2	0.67	0.003	0.023
0.25	1	64	16	1.0000	0.0100	3	1.00	0.001	0.004
0.25	1	64	16	1.0000	0.0001	2	0.83	0.004	0.005
0.25	1	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.25	1	64	16	0.0100	1.0000	2	0.00	0.001	0.002
0.25	1	64	16	0.0100	1.0000	3	0.33	0.004	0.027
0.25	1	64	16	0.0100	0.0100	2	0.83	0.001	0.005
0.25	1	64	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	1	64	16	0.0100	0.0001	2	1.00	0.004	0.005
0.25	1	64	16	0.0100	0.0001	3	1.00	0.004	0.005
0.25	1	64	16	0.0001	1.0000	2	0.33	0.001	0.005
0.25	1	64	16 16	0.0001	1.0000 0.0100	2	0.33 1.00	0.005	1.551 0.007
0.25	1	64	16	0.0001	0.0100	3	1.00	0.005	0.007
0.25	1	64	16	0.0001	0.0001	2	1.00	0.003	0.008
0.25	1	64	16	0.0001	0.0001	3	1.00	0.007	0.008
0.25	1	64	64	1.0000	1.0000	2	0.00	0.001	0.004
0.25	1	64	64	1.0000	1.0000	3	0.00	0.056	0.066
0.25	1	64	64	1.0000	0.0100	2	0.33	0.001	0.010
0.25	1	64	64	1.0000	0.0100	3	1.00	0.008	0.010
0.25	1	64	64	1.0000	0.0001	2	0.83	0.001	0.011
0.25	1	64	64	1.0000	0.0001	3	1.00	0.010	0.012
0.25	1	64	64	0.0100	1.0000	2	0.00	0.004	0.005
0.25	1	64	64	0.0100	1.0000	3	0.00	0.064	0.070
0.25	1	64	64	0.0100	0.0100	2	1.00	0.010	0.012
0.25	1	64	64	0.0100	0.0100	3	1.00	0.010	0.011
0.25	1	64	64	0.0100	0.0001	3	1.00	0.010	0.012
0.25	1	64	64	0.0100	1.0000	2	0.00	0.010	0.006
0.25	1	64	64	0.0001	1.0000	3	0.00	0.083	0.087
0.25	1	64	64	0.0001	0.0100	2	1.00	0.011	0.013
0.25	1	64	64	0.0001	0.0100	3	1.00	0.011	0.012
0.25	1	64	64	0.0001	0.0001	2	1.00	0.014	0.023
0.25	1	64	64	0.0001	0.0001	3	1.00	0.014	0.023
0.25	1	64	256	1.0000	1.0000	2	0.00	0.011	0.015
0.25	1	64	256	1.0000	1.0000	3	0.00	0.192	0.202
0.25	1	64	256	1.0000	0.0100	2	0.67	0.001	0.052
0.25	1	64	256 256	1.0000	0.0100	3	0.83	0.033	0.361
0.25	1	64	256	1.0000	0.0001	3	1.00	0.045	0.073 0.063
0.25	1	64	256	0.0100	1.00001	2	0.00	0.043	0.063
0.25	1	64	256	0.0100	1.0000	3	0.00	0.019	0.027
0.25	1	64	256	0.0100	0.0100	2	1.00	0.049	0.080
0.25	1	64	256	0.0100	0.0100	3	1.00	0.049	0.079
0.25	1	64	256	0.0100	0.0001	2	1.00	0.060	0.092
0.25	1	64	256	0.0100	0.0001	3	1.00	0.060	0.097
0.25	1	64	256	0.0001	1.0000	2	0.00	0.026	0.040
0.25	1	64	256	0.0001	1.0000	3	0.00	0.412	0.602
0.25	1	64	256	0.0001	0.0100	2	1.00	0.085	0.132
0.25	1	64	256	0.0001	0.0100	3	1.00	0.074	0.099
0.25	1	64	256	0.0001	0.0001	2	1.00	0.103	0.125
		64	256	0.0001	0.0001	3	1.00	0.081	0.123
0.25	1		- 1	1 0000					
0.25	1	256	1	1.0000	1.0000	2	0.00	0.001	0.001
			1 1 1	1.0000 1.0000 1.0000	1.0000 1.0000 0.0100	3 2	0.00	0.001 0.003 0.001	0.001 0.013 0.001

mul	m_1	m_2	τ	TR	DTR	alg	SR	mint	maxt
			- ' '						
0.25	1	256 256	1	1.0000	0.0001	3	0.00	0.001	0.001
0.25	1	256	1	0.0100	1.00001	2	0.00	0.003	0.013
0.25	1	256	1	0.0100	1.0000	3	1.00	0.001	0.001
0.25	1	256	1	0.0100	0.0100	2	0.00	0.002	0.003
0.25	1	256	1	0.0100	0.0100	3	1.00	0.003	0.003
0.25	1	256	1	0.0100	0.0001	2	0.00	0.003	0.003
0.25	1	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.25	1	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	1	256	1	0.0001	1.0000	3	0.83	0.003	0.013
0.25	1	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	1	256	1	0.0001	0.0100	3	1.00	0.003	0.003
0.25	1	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	1	256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.25	1	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	1	256	4	1.0000	1.0000	3	0.67	0.003	0.014
0.25	1	256	4	1.0000	0.0100	2	0.33	0.001	0.003
0.25	1	256	4	1.0000	0.0100	3	1.00	0.003	0.003
0.25	1	256	4	1.0000	0.0001	2	0.17	0.001	0.003
0.25	1	256	4	1.0000	0.0001	3	1.00	0.003	0.003
0.25	1	256	4	0.0100	1.0000	2	0.50	0.001	0.003
0.25	1	256	4	0.0100	1.0000	3	0.83	0.003	0.018
0.25	1	256	4	0.0100	0.0100	2	0.67	0.001	0.003
0.25	1	256	4	0.0100	0.0100	3	1.00	0.003	0.003
0.25	1	256	4	0.0100	0.0001	2	0.67	0.001	0.003
0.25	1	256	4	0.0100	0.0001	3	1.00	0.003	0.003
0.25	1	256	4	0.0001	1.0000	2	0.00	0.001	0.002
0.25	1	256	4	0.0001	1.0000	3	0.50	0.003	0.020
0.25	1	256	4	0.0001	0.0100	2	1.00	0.003	0.003
0.25	1	256	4	0.0001	0.0100	3	1.00	0.003	0.003
0.25	1	256	4	0.0001	0.0001	2	0.83	0.001	0.004
0.25	1	256	4	0.0001	0.0001	3	1.00	0.003	0.003
0.25	1	256	16	1.0000	1.0000	2	0.00	0.001	0.001
0.25	1	256	16	1.0000	1.0000	3	0.67	0.003	0.018
0.25	1	256 256	16 16	1.0000	0.0100	2	0.33 1.00	0.001	0.004
0.25	1	256	16	1.0000	0.0100	3	0.67	0.004	0.004
0.25	1	256	16	1.0000	0.0001	3	1.00	0.001	0.005
0.25	1	256	16	0.0100	1.0000	2	0.00	0.004	0.003
0.25	1	256	16	0.0100	1.0000	3	0.50	0.004	0.002
0.25	1	256	16	0.0100	0.0100	2	1.00	0.004	0.004
0.25	1	256	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	1	256	16	0.0100	0.0001	2	1.00	0.006	0.007
0.25	1	256	16	0.0100	0.0001	3	1.00	0.006	0.007
0.25	1	256	16	0.0001	1.0000	2	0.33	0.001	0.006
0.25	1	256	16	0.0001	1.0000	3	0.83	0.006	0.046
0.25	1	256	16	0.0001	0.0100	2	1.00	0.006	0.006
0.25	1	256	16	0.0001	0.0100	3	1.00	0.006	0.006
0.25	1	256	16	0.0001	0.0001	2	1.00	0.006	0.007
0.25	1	256	16	0.0001	0.0001	3	1.00	0.006	0.007
0.25	1	256	64	1.0000	1.0000	2	0.00	0.001	0.004
0.25	1	256	64	1.0000	1.0000	3	0.17	0.009	0.062
0.25	1	256	64	1.0000	0.0100	2	0.33	0.001	0.012
0.25	1	256	64	1.0000	0.0100	3	1.00	0.012	0.012
0.25	1	256	64	1.0000	0.0001	2	0.83	0.001	0.016
0.25	1	256	64	1.0000	0.0001	3	1.00	0.010	0.016
0.25	1	256	64	0.0100	1.0000	2	0.00	0.001	0.006
0.25	1	256	64	0.0100	1.0000	3	0.00	0.042	0.088
0.25	1	256		0.0100	0.0100	2	1.00	0.010	0.010
0.25	1	256 256	64 64	0.0100	0.0100	2	1.00	0.010 0.017	0.015 0.018
0.25	1	256	64	0.0100	0.0001	3	1.00	0.017	0.018
0.25	1	256	64	0.0100	1.00001	2	0.17	0.017	0.009
0.25	1	256	64	0.0001	1.0000	3	0.17	0.001	0.647
0.25	1	256	64	0.0001	0.0100	2	1.00	0.012	0.047
0.25	1	256	64	0.0001	0.0100	3	1.00	0.012	0.017
0.25	1	256	64	0.0001	0.0001	2	1.00	0.014	0.021
0.25	1	256	64	0.0001	0.0001	3	1.00	0.013	0.022
0.25	1	256	256	1.0000	1.0000	2	0.00	0.001	0.010
0.25	1	256	256	1.0000	1.0000	3	0.00	0.174	0.254
0.25	1	256	256	1.0000	0.0100	2	0.33	0.001	0.054
0.25	1	256	256	1.0000	0.0100	3	0.83	0.053	0.313
0.25	1	256	256	1.0000	0.0001	2	1.00	0.049	0.076
0.25	1	256	256	1.0000	0.0001	3	1.00	0.049	0.075
0.25	1	256	256	0.0100	1.0000	2	0.00	0.001	0.026
0.25	1	256	256	0.0100	1.0000	3	0.00	0.271	0.999

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	1	256	256	0.0100	0.0100	2	1.00	0.052	0.054
0.25	1	256	256	0.0100	0.0100	3	1.00	0.052	0.055
0.25	1	256	256	0.0100	0.0001	2	1.00	0.062	0.074
0.25	1	256	256	0.0100	0.0001	3	1.00	0.063	0.065
0.25	1	256	256	0.0001	1.0000	2	0.00	0.001	0.033
0.25	1	256	256	0.0001	1.0000	3	0.00	0.407	1.538
0.25	1	256	256	0.0001	0.0100	2	1.00	0.059	0.103
0.25	1	256	256	0.0001	0.0100	3	1.00	0.059	0.103
0.25	1	256	256	0.0001	0.0001	2	1.00	0.075	0.124
0.25	1	256	256	0.0001	0.0001	2	1.00	0.076	0.124
0.25	4	1	1	1.0000	1.0000	3	0.17 1.00	0.001	0.003
0.25	4	1	1	1.0000	0.0100	2	0.00	0.003	0.003
0.25	4	1	1	1.0000	0.0100	3	1.00	0.003	0.001
0.25	4	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	4	1	1	1.0000	0.0001	3	1.00	0.003	0.006
0.25	4	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	4	1	1	0.0100	1.0000	3	0.83	0.003	0.015
0.25	4	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	4	1	1	0.0100	0.0100	3	1.00	0.003	0.007
0.25	4	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.25	4	1	1	0.0100	0.0001	3	1.00 0.00	0.003	0.012
0.25	4	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	4	1	1	0.0001	0.0100	2	0.00	0.004	0.001
0.25	4	1	1	0.0001	0.0100	3	1.00	0.001	0.007
0.25	4	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	4	1	1	0.0001	0.0001	3	0.83	0.004	0.013
0.25	4	1	4	1.0000	1.0000	2	0.17	0.001	0.003
0.25	4	1	4	1.0000	1.0000	3	0.33	0.003	0.018
0.25	4	1	4	1.0000	0.0100	2	0.67	0.001	0.003
0.25	4	1	4	1.0000	0.0100	3	1.00	0.003	0.006
0.25	4	1	4	1.0000	0.0001	2	0.67	0.001	0.003
0.25	4	1	4	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.003	0.004
0.25	4	1	4	0.0100	1.0000	3	0.50	0.001	0.002
0.25	4	1	4	0.0100	0.0100	2	0.83	0.003	0.020
0.25	4	1	4	0.0100	0.0100	3	1.00	0.003	0.003
0.25	4	1	4	0.0100	0.0001	2	0.67	0.003	0.004
0.25	4	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.25	4	1	4	0.0001	1.0000	2	0.17	0.001	0.003
0.25	4	1	4	0.0001	1.0000	3	0.50	0.004	0.041
0.25	4	1	4	0.0001	0.0100	2	1.00	0.003	0.004
0.25	4	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	4	1	4	0.0001	0.0001	2	0.83	0.001	0.004
0.25	4	1	4	0.0001	0.0001	3	1.00	0.003	0.007
0.25	4	1	16 16	1.0000	1.0000	3	0.00	0.002	0.002
0.25	4	1	16	1.0000	0.0100	2	1.00	0.023	0.025
0.25	4	1	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	4	1	16	1.0000	0.0001	2	1.00	0.004	0.005
0.25	4	1	16	1.0000	0.0001	3	1.00	0.004	0.005
0.25	4	1	16	0.0100	1.0000	2	0.00	0.002	0.002
0.25	4	1	16	0.0100	1.0000	3	0.00	0.029	0.030
0.25	4	1	16	0.0100	0.0100	2	1.00	0.004	0.005
0.25	4	1	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	4	1	16	0.0100	0.0001	2	1.00	0.004	0.005
0.25	4	1	16	0.0100	0.0001	3	1.00	0.004	0.006
0.25	4	1	16	0.0001	1.0000	2	0.00	0.002	0.003
0.25	4	1	16 16	0.0001	0.0100	2	0.00 1.00	0.033	0.048
0.25	4	1	16	0.0001	0.0100	3	1.00	0.004	0.005
0.25	4	1	16	0.0001	0.0001	2	1.00	0.004	0.005
0.25	4	1	16	0.0001	0.0001	3	1.00	0.005	0.006
0.25	4	1	64	1.0000	1.0000	2	0.00	0.003	0.004
0.25	4	1	64	1.0000	1.0000	3	0.00	0.045	0.819
0.25	4	1	64	1.0000	0.0100	2	1.00	0.008	0.009
0.25	4	1	64	1.0000	0.0100	3	1.00	0.007	0.009
0.25	4	1	64	1.0000	0.0001	2	1.00	0.009	0.010
0.25	4	1	64	1.0000	0.0001	3	1.00	0.009	0.010
0.25	4	1	64	0.0100	1.0000	2	0.00	0.004	0.006
0.25	4	1	64	0.0100	1.0000	3	0.00	0.063	0.079
0.25	4	1	64	0.0100	0.0100	2	1.00	0.010	0.011
0.25	4	1	64	0.0100	0.0100	3	1.00	0.010	0.011
0.25	4	1	64	0.0100	0.0001	3	1.00	0.011	0.013
0.23	7	1	04	0.0100	0.0001	3	1.00	0.011	0.014

1.025	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.025										
0.25										
0.25										
0.25										
0.25		4	1							
0.25										
0.25										
0.25										
0.25										
0.25										
0.25										
0.25										
0.25										
0.25			1		0.0100	0.0001	2	1.00	0.060	
0.25 4 1 256 0.0001 1.0000 3 0.00 0.428 0.975 0.25 4 1 256 0.0001 0.0100 2 1.00 0.062 0.068 0.25 4 1 256 0.0001 0.0001 3 1.00 0.076 0.124 0.25 4 1 256 0.0001 0.0001 3 1.00 0.076 0.124 0.25 4 4 1 1.0000 1.0000 2 0.00 0.001 0.000 0.25 4 4 1 1.0000 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 1.0000 0.0001 3 1.00 0.003 0.008 0.25 4 4 1 1.0000 0.0001 2 0.00 0.001 0.000 0.25 4 4 1 0.0100 0.0000 3 1.00<										
0.25 4 1 256 0.0001 0.0100 2 1.00 0.062 0.068 0.25 4 1 256 0.0001 0.0001 2 1.00 0.076 0.124 0.25 4 1 256 0.0001 0.0001 3 1.00 0.076 0.124 0.25 4 4 1 1.0000 1.0000 3 1.00 0.003 0.696 0.25 4 4 1 1.0000 0.0100 3 1.00 0.001 0.001 0.25 4 4 1 1.0000 0.0100 3 1.00 0.003 0.008 0.25 4 4 1 1.0000 0.0001 2 0.00 0.001 0.003 0.008 0.25 4 4 1 0.0100 1 1.00 0.003 0.008 0.25 4 4 1 0.0100 1 1.00 0.001										
0.25 4 1 256 0.0001 0.0100 3 1.00 0.076 0.028 0.25 4 1 256 0.0001 0.0001 2 1.00 0.076 0.124 0.25 4 4 1 1.0000 1.0000 2 0.00 0.001 0.001 0.25 4 4 1 1.0000 0.0000 3 1.00 0.003 0.006 0.25 4 4 1 1.0000 0.0100 2 0.00 0.001 0.001 0.001 0.001 0.001 0.001 0.000 0.001 0.000 0.001 0.000 0.001 0.000 0.000 0.001 0.000 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>										
0.25 4 1 256 0.0001 0.0001 3 1.00 0.076 0.124 0.25 4 4 1 1.0000 1.0000 3 1.00 0.003 0.696 0.25 4 4 1 1.0000 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 1.0000 0.0010 2 0.00 0.001 0.001 0.25 4 4 1 1.0000 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 0.0100 1.0000 2 0.00 0.001 0.003 0.25 4 4 1 0.0100 1.0000 3 1.00 0.003 0.001 0.25 4 4 1 0.0100 0.001 2 0.00 0.001 0.001 0.25 4 4 1 0.0100 0.001 2 0.00		4								
0.25										
0.25										
0.25 4 4 1 1.0000 0.0100 2 0.00 0.001 0.003 0.008 0.25 4 4 1 1.0000 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 1.0000 0.0001 3 1.00 0.003 0.008 0.25 4 4 1 0.0100 1.0000 2 0.17 0.001 0.003 0.25 4 4 1 0.0100 1.0000 3 1.00 0.003 0.010 0.25 4 4 1 0.0100 0.0100 3 1.00 0.003 0.001 0.25 4 4 1 0.0100 0.0001 3 1.00 0.003 0.005 0.25 4 4 1 0.0100 0.0001 3 1.00 0.003 0.005 0.25 4 4 1 0.0001 1.0000 2										
0.25 4 4 1 1.0000 0.0001 2 0.00 0.001 0.003 0.008 0.25 4 4 1 0.0100 1.0000 2 0.17 0.001 0.003 0.25 4 4 1 0.0100 1.0000 3 1.00 0.003 0.010 0.25 4 4 1 0.0100 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 0.0100 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 0.0100 0.0001 3 1.00 0.003 0.005 0.25 4 4 1 0.0001 1.0000 2 0.00 0.001 0.003 0.25 4 4 1 0.0001 1.0000 3 1.00 0.002 0.001 0.25 4 4 1 0.0001 0.0001 3										
0.25 4 4 1 1.0000 0.0001 3 1.00 0.003 0.008 0.25 4 4 1 0.0100 1.0000 2 0.17 0.001 0.003 0.010 0.25 4 4 1 0.0100 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 0.0100 0.0010 3 1.00 0.003 0.006 0.25 4 4 1 0.0100 0.0001 3 1.00 0.003 0.005 0.25 4 4 1 0.0100 1.0000 3 1.00 0.003 0.003 0.25 4 4 1 0.0001 1.0000 3 1.00 0.003 0.001 0.25 4 4 1 0.0001 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 0.001 3	0.25									0.008
0.25 4 4 1 0.0100 1.0000 2 0.17 0.001 0.003 0.25 4 4 1 0.0100 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 0.0100 0.0100 3 1.00 0.003 0.006 0.25 4 4 1 0.0100 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 0.0100 1.0000 2 0.00 0.001 0.003 0.25 4 4 1 0.0001 1.0000 3 1.00 0.002 0.003 0.25 4 4 1 0.0001 1.0000 3 1.00 0.002 0.003 0.25 4 4 1 0.0001 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 0.0001 3 1.00										
0.25										
0.25 4 4 1 0.0100 0.0100 2 0.00 0.001 0.000 0.25 4 4 1 0.0100 0.0001 2 0.00 0.001 0.006 0.25 4 4 1 0.0100 0.0001 3 1.00 0.003 0.005 0.25 4 4 1 0.0001 1.00000 2 0.17 0.001 0.003 0.25 4 4 1 0.0001 1.0000 3 1.00 0.002 0.003 0.25 4 4 1 0.0001 0.0100 2 0.00 0.001 0.003 0.25 4 4 1 0.0001 0.0100 3 1.00 0.003 0.006 0.25 4 4 1 0.0001 0.001 3 1.00 0.003 0.001 0.25 4 4 1 0.0001 1.000 3 1.33										
0.25 4 4 1 0.0100 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.005 0.25 4 4 1 0.0001 1.0000 3 1.00 0.002 0.003 0.25 4 4 1 0.0001 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.006 0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.006 0.25 4 4 1 0.0001 1.00001 3 1.00 0.003 0.007 0.25 4 4 1 1.0000 1.0000 3 0.33 0.003 0.019 0.25 4 4 4 1.0000 0.0100 3 1.00		4	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25 4 4 1 0.0100 0.0001 3 1.00 0.003 0.005 0.25 4 4 1 0.0001 1.0000 2 0.17 0.001 0.003 0.25 4 4 1 0.0001 0.0100 3 1.00 0.001 0.001 0.25 4 4 1 0.0001 0.010 3 1.00 0.003 0.006 0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.006 0.25 4 4 1 0.0001 0.0001 3 1.00 0.001 0.001 0.25 4 4 4 1.0000 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0100 3 1.30 0.003 0.003 0.25 4 4 4 1.0000 0.0100 3 1.00										
0.25 4 4 1 0.0001 1.0000 2 0.17 0.001 0.003 0.25 4 4 1 0.0001 1.0000 3 1.00 0.002 0.003 0.25 4 4 1 0.0001 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.007 0.25 4 4 1 0.0001 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 1.0000 3 0.33 0.003 0.019 0.25 4 4 4 1.0000 0.0100 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0001 3 1.00										
0.25 4 4 1 0.0001 1.0000 3 1.00 0.002 0.003 0.25 4 4 1 0.0001 0.0100 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.000 0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.007 0.25 4 4 1 0.0001 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 1.0000 3 0.33 0.003 0.019 0.25 4 4 4 1.0000 0.0100 3 1.00 0.001 0.003 0.25 4 4 4 1.0000 0.0001 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0001 3 1.00										
0.25 4 4 1 0.0001 0.0100 3 1.00 0.003 0.006 0.25 4 4 1 0.0001 0.0001 2 0.00 0.001 0.001 0.25 4 4 1 0.0001 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 1.0000 3 0.033 0.001 0.003 0.25 4 4 4 1.0000 0.0100 2 0.50 0.001 0.003 0.25 4 4 4 1.0000 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 1.0000 0.0001 3 1.00 0.003 0.003 0.25 4 4 4 1.0000 0.0001 3 1.00 0.003 0.03 0.25 4 4 4 0.0100 1.0000 2 0.17		4								
0.25										
0.25 4 4 1 0.0001 0.0001 3 1.00 0.003 0.007 0.25 4 4 4 1.0000 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0100 3 0.033 0.003 0.019 0.25 4 4 4 1.0000 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 1.0000 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 1.0000 0.0001 2 0.17 0.001 0.003 0.25 4 4 4 0.0100 1.0000 3 0.83 0.003 0.004 0.25 4 4 4 0.0100 1.0000 3 0.83 0.003 0.003 0.25 4 4 4 0.0100 0.0100 3 1.00										
0.25 4 4 4 1.0000 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 1.0000 3 0.33 0.003 0.019 0.25 4 4 4 1.0000 0.0100 2 0.50 0.001 0.003 0.25 4 4 4 1.0000 0.0001 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0001 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0001 3 1.00 0.003 0.004 0.25 4 4 4 0.0100 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 0.0100 1.0000 3 0.83 0.001 0.003 0.25 4 4 4 0.0100 0.0100 3 1.00										
0.25 4 4 4 1.0000 0.0100 2 0.50 0.001 0.003 0.25 4 4 4 1.0000 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 1.0000 0.0001 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 0.0100 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 0.0100 1.0000 3 0.83 0.003 0.018 0.25 4 4 4 0.0100 0.0100 3 1.00 0.003 0.03 0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0100 0.0001 3 1.00										
0.25 4 4 4 1.0000 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 1.0000 0.0001 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0001 3 1.00 0.003 0.004 0.25 4 4 4 0.0100 1.0000 3 0.03 0.011 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.003 0.003 0.018 0.25 4 4 4 0.0100 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0001 1.0000 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 1.0000										
0.25 4 4 4 1.0000 0.0001 2 0.17 0.001 0.003 0.25 4 4 4 1.0000 0.0001 3 1.00 0.003 0.004 0.25 4 4 4 0.0100 1.0000 3 0.83 0.003 0.018 0.25 4 4 4 0.0100 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0100 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0100 0.0100 3 1.00 0.003 0.008 0.25 4 4 4 0.0100 0.0001 3 1.00 0.003 0.003 0.25 4 4 4 0.0100 0.001 3 1.00 0.003 0.03 0.25 4 4 4 0.0001 1.0000 3 0.83										
0.25 4 4 4 1.0000 0.0001 3 1.00 0.003 0.004 0.25 4 4 4 0.0100 1.0000 2 0.17 0.001 0.003 0.25 4 4 4 0.0100 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0100 0.0100 3 1.00 0.003 0.008 0.25 4 4 4 0.0100 0.0100 3 1.00 0.003 0.008 0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.003 0.25 4 4 4 0.0001 1.0000 3 0.83 0.003 0.03 0.25 4 4 4 0.0001 0.1000 2 0.83										
0.25 4 4 4 0.0100 1.0000 3 0.83 0.003 0.018 0.25 4 4 4 0.0100 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0100 0.0001 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.003 0.25 4 4 4 0.0001 1.0000 3 0.83 0.003 0.021 0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.021 0.25 4 4 4 0.0001 0.0100 3 1.00										
0.25 4 4 4 0.0100 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0100 0.0100 3 1.00 0.003 0.008 0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.003 0.25 4 4 4 0.0001 1.0000 3 1.83 0.003 0.021 0.25 4 4 4 0.0001 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0001 2 0.67	0.25	4	4	4	0.0100	1.0000		0.17	0.001	0.003
0.25 4 4 4 0.0100 0.0100 3 1.00 0.003 0.008 0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.002 0.25 4 4 4 0.0001 1.0000 3 0.83 0.003 0.021 0.25 4 4 4 0.0001 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0001 2 0.67 0.001 0.004 0.25 4 4 4 0.0001 0.0001 3 1.00										
0.25 4 4 4 0.0100 0.0001 2 0.67 0.001 0.003 0.25 4 4 4 0.0100 0.0001 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.003 0.25 4 4 4 0.0001 0.0100 2 0.83 0.003 0.021 0.25 4 4 4 0.0001 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0001 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0001 3 1.00 0.004 0.007 0.25 4 4 16 1.0000 1.0000 3 0.00										
0.25 4 4 4 0.0100 0.0001 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 1.0000 2 0.50 0.001 0.003 0.25 4 4 4 0.0001 0.0100 2 0.83 0.003 0.021 0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0001 2 0.67 0.001 0.004 0.25 4 4 4 0.0001 0.0001 3 1.00 0.004 0.007 0.25 4 4 4 0.0001 0.0001 3 1.00 0.004 0.007 0.25 4 4 16 1.0000 1.0000 3 0.00										
0.25 4 4 4 0.0001 1.0000 3 0.83 0.003 0.021 0.25 4 4 4 0.0001 0.0100 2 0.83 0.001 0.003 0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0001 2 0.67 0.001 0.004 0.25 4 4 4 0.0001 0.0001 3 1.00 0.004 0.007 0.25 4 4 16 1.0000 1.0000 2 0.00 0.001 0.002 0.25 4 4 16 1.0000 1.0000 2 0.00 0.001 0.002 0.25 4 4 16 1.0000 0.0100 2 0.67 0.001 0.004 0.25 4 4 16 1.0000 0.0100 3 1.00	0.25				0.0100	0.0001	3	1.00	0.003	0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.25 4 4 4 0.0001 0.0100 3 1.00 0.003 0.003 0.25 4 4 4 0.0001 0.0001 2 0.67 0.001 0.004 0.25 4 4 4 0.0001 0.0001 3 1.00 0.004 0.007 0.25 4 4 16 1.0000 1.0000 3 0.00 0.021 0.001 0.002 0.25 4 4 16 1.0000 1.0000 3 0.00 0.021 0.031 0.25 4 4 16 1.0000 0.0100 2 0.67 0.001 0.004 0.25 4 4 16 1.0000 0.0100 3 1.00 0.004 0.004 0.25 4 4 16 1.0000 0.0001 2 1.00 0.004 0.005 0.25 4 4 16 1.0000 0.0001 3 </td <td></td>										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.25	4	4	4	0.0001	0.0001	2	0.67	0.001	0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		4	4				3			
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.25 4 4 16 0.0100 1.0000 3 0.00 0.028 0.037 0.25 4 4 16 0.0100 0.0100 2 1.00 0.004 0.005 0.25 4 4 16 0.0100 0.0100 3 1.00 0.004 0.005 0.25 4 4 16 0.0100 0.0001 2 0.83 0.001 0.005 0.25 4 4 16 0.0100 0.0001 3 1.00 0.004 0.011 0.25 4 4 16 0.0001 1.0000 2 0.00 0.001 0.003 0.25 4 4 16 0.0001 1.0000 2 0.00 0.001 0.003 0.25 4 4 16 0.0001 1.0000 3 0.00 0.033 0.037 0.25 4 4 16 0.0001 0.000 2 1.00<										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.25 4 4 16 0.0100 0.0100 3 1.00 0.004 0.005 0.25 4 4 16 0.0100 0.0001 2 0.83 0.001 0.005 0.25 4 4 16 0.0100 0.0001 3 1.00 0.004 0.011 0.25 4 4 16 0.0001 1.0000 2 0.00 0.001 0.003 0.25 4 4 16 0.0001 1.0000 3 0.00 0.033 0.037 0.25 4 4 16 0.0001 0.0100 2 1.00 0.004 0.005										
0.25 4 4 16 0.0100 0.0001 3 1.00 0.004 0.011 0.25 4 4 16 0.0001 1.0000 2 0.00 0.001 0.003 0.25 4 4 16 0.0001 1.0000 3 0.00 0.033 0.037 0.25 4 4 16 0.0001 0.0100 2 1.00 0.004 0.005	0.25	4	4	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25 4 4 16 0.0001 1.0000 2 0.00 0.001 0.003 0.25 4 4 16 0.0001 1.0000 3 0.00 0.033 0.037 0.25 4 4 16 0.0001 0.0100 2 1.00 0.004 0.005										
0.25 4 4 16 0.0001 1.0000 3 0.00 0.033 0.037 0.25 4 4 16 0.0001 0.0100 2 1.00 0.004 0.005										
0.25 4 4 16 0.0001 0.0100 2 1.00 0.004 0.005										
0.25 4 16 0.0001 0.0100 3 1.00 0.004 0.005	0.25				0.0001	0.0100		1.00	0.004	0.005
	0.25	4	4	16	0.0001	0.0100	3	1.00	0.004	0.005

0.25 4 4 16 0.0001 0.0001 0.25 4 4 16 0.0001 0.0001 0.25 4 4 64 1.0000 1.0000 0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 </th <th>2 3 2 3 2 3 2 3 2 3 2 3</th> <th>1.00 1.00 0.00 0.00 1.00 1.00 1.00</th> <th>0.005 0.004 0.003 0.048 0.008 0.008</th> <th>0.006 0.006 0.005 0.066 0.011</th>	2 3 2 3 2 3 2 3 2 3 2 3	1.00 1.00 0.00 0.00 1.00 1.00 1.00	0.005 0.004 0.003 0.048 0.008 0.008	0.006 0.006 0.005 0.066 0.011
0.25 4 4 64 1.0000 1.0000 0.25 4 4 64 1.0000 1.0000 0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 </td <td>2 3 2 3 2 3 2 3 2</td> <td>0.00 0.00 1.00 1.00 1.00</td> <td>0.003 0.048 0.008 0.008</td> <td>0.005 0.066 0.011</td>	2 3 2 3 2 3 2 3 2	0.00 0.00 1.00 1.00 1.00	0.003 0.048 0.008 0.008	0.005 0.066 0.011
0.25 4 4 64 1.0000 1.0000 0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001	3 2 3 2 3 2 3	0.00 1.00 1.00 1.00 1.00	0.048 0.008 0.008	0.066 0.011
0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001	2 3 2 3 2 3	1.00 1.00 1.00 1.00	0.008	0.011
0.25 4 4 64 1.0000 0.0100 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001	3 2 3 2 3	1.00 1.00 1.00	0.008	
0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001 0.25 4 4 64 0.0100 0.0001	2 3 2 3	1.00		
0.25 4 4 64 1.0000 0.0001 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001 0.25 4 4 64 0.0100 0.0001	3 2 3	1.00		0.011
0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001 0.25 4 4 64 0.0100 0.0001	2 3		0.009	0.014
0.25 4 4 64 0.0100 1.0000 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001 0.25 4 4 64 0.0100 0.0001	3	0.00	0.003	0.006
0.25 4 4 64 0.0100 0.0100 0.25 4 4 64 0.0100 0.0001		0.00	0.085	0.210
0.25 4 4 64 0.0100 0.0001	2	1.00	0.010	0.014
	3	1.00	0.009	0.011
	2	1.00	0.012	0.018
0.25 4 4 64 0.0100 0.0001	3	1.00	0.016	0.018
0.25 4 4 64 0.0001 1.0000	2	0.00	0.006	0.008
0.25 4 4 64 0.0001 1.0000 0.25 4 4 64 0.0001 0.0100	2	1.00	0.081	0.124
0.25 4 4 64 0.0001 0.0100	3	1.00	0.011	0.012
0.25 4 4 64 0.0001 0.0001	2	1.00	0.013	0.012
0.25 4 4 64 0.0001 0.0001	3	1.00	0.014	0.015
0.25 4 4 256 1.0000 1.0000	2	0.00	0.011	0.017
0.25 4 4 256 1.0000 1.0000	3	0.00	0.260	0.283
0.25 4 4 256 1.0000 0.0100	2	1.00	0.037	0.053
0.25 4 4 256 1.0000 0.0100	3	1.00	0.037	0.052
0.25 4 4 256 1.0000 0.0001	2	1.00	0.044	0.050
0.25 4 4 256 1.0000 0.0001 0.25 4 4 256 0.0100 1.0000	3	1.00	0.044	0.049
		0.00	0.017	0.027 1.042
0.25 4 4 256 0.0100 1.0000 0.25 4 4 256 0.0100 0.0100	3 2	0.00 1.00	0.338 0.046	0.071
0.25 4 4 256 0.0100 0.0100	3	1.00	0.045	0.071
0.25 4 4 256 0.0100 0.0001	2	1.00	0.060	0.092
0.25 4 4 256 0.0100 0.0001	3	1.00	0.060	0.097
0.25 4 4 256 0.0001 1.0000	2	0.00	0.026	0.042
0.25 4 4 256 0.0001 1.0000	3	0.00	0.556	1.750
0.25 4 4 256 0.0001 0.0100	2	1.00	0.092	0.102
0.25 4 4 256 0.0001 0.0100	3	1.00	0.088	0.100
0.25 4 4 256 0.0001 0.0001	2	1.00	0.075	0.113
0.25 4 4 256 0.0001 0.0001 0.25 4 16 1 1.0000 1.0000	2	1.00	0.074	0.114
0.25 4 16 1 1.0000 1.0000	3	1.00	0.001	0.001
0.25 4 16 1 1.0000 0.0100	2	0.00	0.003	0.001
0.25 4 16 1 1.0000 0.0100	3	0.83	0.003	0.016
0.25 4 16 1 1.0000 0.0001	2	0.00	0.001	0.001
0.25 4 16 1 1.0000 0.0001	3	0.67	0.003	0.280
0.25 4 16 1 0.0100 1.0000	2	0.33	0.001	0.003
0.25 4 16 1 0.0100 1.0000	3	1.00	0.003	0.003
0.25 4 16 1 0.0100 0.0100	2	0.00	0.001	0.001
0.25 4 16 1 0.0100 0.0100	3	1.00	0.003	0.003
0.25 4 16 1 0.0100 0.0001 0.25 4 16 1 0.0100 0.0001	3	0.00	0.001	0.001
0.25 4 16 1 0.0100 0.0001	2	0.00	0.003	0.001
0.25 4 16 1 0.0001 1.0000	3	1.00	0.003	0.003
0.25 4 16 1 0.0001 0.0100	2	0.00	0.001	0.001
0.25 4 16 1 0.0001 0.0100	3	0.83	0.003	0.036
0.25 4 16 1 0.0001 0.0001	2	0.00	0.001	0.001
0.25 4 16 1 0.0001 0.0001	3	0.83	0.003	0.015
0.25 4 16 4 1.0000 1.0000	2	0.00	0.001	0.002
0.25 4 16 4 1.0000 1.0000	3	1.00	0.003	0.008
0.25 4 16 4 1.0000 0.0100 0.25 4 16 4 1.0000 0.0100	2	0.17	0.001	0.003
0.25 4 16 4 1.0000 0.0100 0.25 4 16 4 1.0000 0.0001	2	0.83	0.003	0.016 0.004
0.25 4 16 4 1.0000 0.0001	3	1.00	0.001	0.004
0.25 4 16 4 0.0100 1.0000	2	0.17	0.003	0.003
0.25 4 16 4 0.0100 1.0000	3	0.83	0.003	0.021
0.25 4 16 4 0.0100 0.0100	2	0.83	0.001	0.004
0.25 4 16 4 0.0100 0.0100	3	1.00	0.004	0.004
0.25 4 16 4 0.0100 0.0001	2	0.67	0.001	0.004
0.25 4 16 4 0.0100 0.0001	3	0.83	0.004	0.020
0.25 4 16 4 0.0001 1.0000	2	0.67	0.001	0.004
0.25 4 16 4 0.0001 1.0000	3	0.83	0.004	0.019
0.25 4 16 4 0.0001 0.0100 0.25 4 16 4 0.0001 0.0100	3	1.00	0.004	0.004
0.25 4 16 4 0.0001 0.0100	2	1.00	0.004	0.004
0.25 4 16 4 0.0001 0.0001	3	1.00	0.004	0.004
0.25 4 16 4 0.0001 0.0001	2	0.00	0.004	0.004
0.25 4 16 16 1.0000 1.0000	3	0.00	0.022	0.031

0.25	mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.25										
0.25										0.005
0.25										0.005
0.25										0.005
0.25	0.25	4			0.0100	1.0000	2		0.001	0.003
0.25	0.25	4	16	16	0.0100	1.0000	3	0.00	0.028	0.036
0.25	0.25	4	16	16		0.0100	2	1.00	0.004	0.006
0.25			16			0.0100				0.006
0.25										0.006
0.25										0.006
0.25										
0.25										
0.25										
0.25										
O.25										0.007
0.25										0.005
0.25		4								0.145
0.25	0.25	4	16	64	1.0000	0.0100	2	0.83	0.001	0.008
0.25			16		1.0000	0.0100			0.008	0.009
0.25 4 16 64 0.0100 1.0000 2 0.00 0.004 0.00 0.25 4 16 64 0.0100 1.0000 3 0.00 0.061 0.09 0.25 4 16 64 0.0100 0.0100 2 1.00 0.010 0.01 0.25 4 16 64 0.0100 0.0001 2 1.00 0.015 0.01 0.25 4 16 64 0.0100 0.0001 3 1.00 0.011 0.01 0.25 4 16 64 0.0001 1.0000 2 0.00 0.066 0.00 0.25 4 16 64 0.0001 1.0000 3 0.00 0.066 0.00 0.25 4 16 64 0.0001 0.0100 3 1.00 0.011 0.01 0.25 4 16 64 0.0001 0.0001 3 1.0										0.010
0.25 4 16 64 0.0100 1.0000 3 0.00 0.061 0.09 0.25 4 16 64 0.0100 0.0100 2 1.00 0.010 0.01 0.25 4 16 64 0.0100 0.0001 2 1.00 0.015 0.01 0.25 4 16 64 0.0100 0.0001 3 1.00 0.011 0.01 0.25 4 16 64 0.0001 1.0000 2 0.00 0.006 0.00 0.25 4 16 64 0.0001 1.0000 3 0.00 0.094 0.12 0.25 4 16 64 0.0001 0.0100 2 1.00 0.014 0.01 0.25 4 16 64 0.0001 0.0100 3 1.00 0.014 0.01 0.25 4 16 256 1.0000 1.0000 2 0.										0.010
0.25 4 16 64 0.0100 0.0100 2 1.00 0.010 0.01 0.25 4 16 64 0.0100 0.0001 3 1.00 0.015 0.01 0.25 4 16 64 0.0100 0.0001 2 1.00 0.011 0.01 0.25 4 16 64 0.0001 1.0000 2 0.00 0.006 0.00 0.25 4 16 64 0.0001 1.0000 3 0.00 0.004 0.12 0.25 4 16 64 0.0001 0.0100 2 1.00 0.011 0.01 0.25 4 16 64 0.0001 0.0100 3 1.00 0.014 0.01 0.25 4 16 64 0.0001 0.0001 3 1.00 0.014 0.02 0.25 4 16 256 1.0000 1.0000 3 0.										0.006
0.25 4 16 64 0.0100 0.0100 3 1.00 0.010 0.01 0.25 4 16 64 0.0100 0.0001 2 1.00 0.015 0.01 0.25 4 16 64 0.0001 1.0000 2 0.00 0.006 0.00 0.25 4 16 64 0.0001 1.0000 3 0.00 0.094 0.12 0.25 4 16 64 0.0001 0.0100 2 1.00 0.011 0.01 0.25 4 16 64 0.0001 0.0100 3 1.00 0.014 0.01 0.25 4 16 64 0.0001 0.0001 3 1.00 0.014 0.02 0.25 4 16 64 0.0001 0.0001 3 1.00 0.014 0.02 0.25 4 16 256 1.0000 1.0000 3 1.										0.090
0.25										0.015
0.25										
0.25 4 16 64 0.0001 1.0000 2 0.00 0.006 0.00 0.25 4 16 64 0.0001 1.0000 3 0.00 0.094 0.12 0.25 4 16 64 0.0001 0.0100 3 1.00 0.011 0.01 0.25 4 16 64 0.0001 0.0001 2 1.00 0.014 0.01 0.25 4 16 64 0.0001 0.0001 2 1.00 0.014 0.02 0.25 4 16 256 1.0000 1.0000 2 0.00 0.011 0.01 0.25 4 16 256 1.0000 1.0000 3 0.00 0.183 0.85 0.25 4 16 256 1.0000 0.0100 3 1.00 0.043 0.06 0.25 4 16 256 1.0000 0.0100 3 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>0.017</td></td<>										0.017
0.25 4 16 64 0.0001 1.0000 3 0.00 0.094 0.12 0.25 4 16 64 0.0001 0.0100 2 1.00 0.011 0.01 0.25 4 16 64 0.0001 0.0001 2 1.00 0.014 0.01 0.25 4 16 64 0.0001 0.0001 3 1.00 0.014 0.02 0.25 4 16 64 0.0001 1.0000 2 0.00 0.011 0.01 0.25 4 16 256 1.0000 1.0000 3 0.00 0.113 0.01 0.25 4 16 256 1.0000 0.0100 3 1.00 0.043 0.08 0.25 4 16 256 1.0000 0.0001 3 1.00 0.047 0.07 0.25 4 16 256 1.0000 0.0001 3 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>0.008</td></td<>										0.008
0.25 4 16 64 0.0001 0.0100 2 1.00 0.011 0.01 0.25 4 16 64 0.0001 0.0100 3 1.00 0.014 0.01 0.25 4 16 64 0.0001 0.0001 2 1.00 0.014 0.02 0.25 4 16 64 0.0001 1.0000 2 0.00 0.011 0.01 0.25 4 16 256 1.0000 1.0000 3 0.00 0.011 0.01 0.25 4 16 256 1.0000 0.0100 2 0.67 0.001 0.05 0.25 4 16 256 1.0000 0.0100 3 1.00 0.038 0.08 0.25 4 16 256 1.0000 0.0001 3 1.00 0.047 0.07 0.25 4 16 256 0.0100 1.0000 3 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>0.120</td></t<>										0.120
0.25 4 16 64 0.0001 0.0100 3 1.00 0.014 0.01 0.25 4 16 64 0.0001 0.0001 2 1.00 0.016 0.02 0.25 4 16 64 0.0001 1.0000 2 0.00 0.011 0.01 0.25 4 16 256 1.0000 1.0000 3 0.00 0.011 0.01 0.25 4 16 256 1.0000 0.0100 2 0.67 0.001 0.05 0.25 4 16 256 1.0000 0.0100 3 1.00 0.038 0.08 0.25 4 16 256 1.0000 0.0001 2 1.00 0.047 0.07 0.25 4 16 256 1.0000 0.0001 3 1.00 0.047 0.07 0.25 4 16 256 0.0100 1.0000 3 <		4								0.018
0.25 4 16 64 0.0001 0.0001 3 1.00 0.014 0.02 0.25 4 16 256 1.0000 1.0000 2 0.00 0.011 0.01 0.25 4 16 256 1.0000 1.0000 3 0.00 0.183 0.85 0.25 4 16 256 1.0000 0.0100 2 0.67 0.001 0.05 0.25 4 16 256 1.0000 0.0100 3 1.00 0.038 0.08 0.25 4 16 256 1.0000 0.0001 2 1.00 0.047 0.07 0.25 4 16 256 0.0100 1.0000 3 1.00 0.033 0.90 0.25 4 16 256 0.0100 1.0000 3 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0100 3	0.25	4	16	64		0.0100	3	1.00	0.014	0.018
0.25 4 16 256 1.0000 1.0000 2 0.00 0.011 0.01 0.25 4 16 256 1.0000 1.0000 3 0.00 0.183 0.85 0.25 4 16 256 1.0000 0.0100 2 0.67 0.001 0.038 0.08 0.25 4 16 256 1.0000 0.0001 2 1.00 0.047 0.07 0.25 4 16 256 1.0000 0.0001 2 1.00 0.047 0.07 0.25 4 16 256 1.0000 0.0001 3 1.00 0.052 0.07 0.25 4 16 256 0.0100 1.0000 2 0.00 0.017 0.02 0.25 4 16 256 0.0100 0.0100 3 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0100	0.25	4	16	64	0.0001	0.0001	2	1.00	0.016	0.022
0.25 4 16 256 1.0000 1.0000 3 0.00 0.183 0.85 0.25 4 16 256 1.0000 0.0100 2 0.67 0.001 0.05 0.25 4 16 256 1.0000 0.0001 3 1.00 0.038 0.08 0.25 4 16 256 1.0000 0.0001 3 1.00 0.032 0.07 0.25 4 16 256 1.0000 0.0001 3 1.00 0.052 0.07 0.25 4 16 256 0.0100 1.0000 3 0.00 0.017 0.02 0.25 4 16 256 0.0100 1.0000 3 0.00 0.393 0.94 0.25 4 16 256 0.0100 0.0100 3 1.00 0.051 0.05 0.25 4 16 256 0.0100 0.0001 3							3			0.023
0.25 4 16 256 1.0000 0.0100 2 0.67 0.001 0.05 0.25 4 16 256 1.0000 0.0100 3 1.00 0.038 0.08 0.25 4 16 256 1.0000 0.0001 2 1.00 0.047 0.07 0.25 4 16 256 1.0000 1.0000 2 0.00 0.017 0.02 0.25 4 16 256 0.0100 1.0000 2 0.00 0.017 0.02 0.25 4 16 256 0.0100 1.0000 3 0.00 0.393 0.94 0.25 4 16 256 0.0100 0.0100 2 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0001 3 1.00 0.064 0.09 0.25 4 16 256 0.0100 0.0001 3										0.017
0.25 4 16 256 1.0000 0.0100 3 1.00 0.038 0.08 0.25 4 16 256 1.0000 0.0001 2 1.00 0.047 0.07 0.25 4 16 256 1.0000 0.0001 3 1.00 0.052 0.07 0.25 4 16 256 0.0100 1.0000 3 0.00 0.017 0.02 0.25 4 16 256 0.0100 1.0000 3 0.00 0.033 0.94 0.25 4 16 256 0.0100 0.0100 3 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0100 3 1.00 0.064 0.09 0.25 4 16 256 0.0100 0.0001 2 1.00 0.064 0.09 0.25 4 16 256 0.0001 1.0000 2										0.856
0.25 4 16 256 1.0000 0.0001 2 1.00 0.047 0.07 0.25 4 16 256 1.0000 0.0001 3 1.00 0.052 0.07 0.25 4 16 256 0.0100 1.0000 3 0.00 0.017 0.02 0.25 4 16 256 0.0100 0.0100 2 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0100 2 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0100 3 1.00 0.064 0.09 0.25 4 16 256 0.0100 0.0001 2 1.00 0.064 0.09 0.25 4 16 256 0.0001 1.0000 3 1.00 0.063 0.09 0.25 4 16 256 0.0001 1.0000 3										0.052
0.25 4 16 256 1.0000 0.0001 3 1.00 0.052 0.07 0.25 4 16 256 0.0100 1.0000 2 0.00 0.017 0.02 0.25 4 16 256 0.0100 1.0000 3 0.00 0.393 0.94 0.25 4 16 256 0.0100 0.0100 3 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0100 3 1.00 0.051 0.05 0.25 4 16 256 0.0100 0.0001 2 1.00 0.064 0.09 0.25 4 16 256 0.0100 0.0001 3 1.00 0.063 0.09 0.25 4 16 256 0.0001 1.0000 3 0.00 0.027 0.04 0.25 4 16 256 0.0001 0.0100 3										
0.25 4 16 256 0.0100 1.0000 2 0.00 0.017 0.02 0.25 4 16 256 0.0100 1.0000 3 0.00 0.393 0.94 0.25 4 16 256 0.0100 0.0100 2 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0001 2 1.00 0.044 0.09 0.25 4 16 256 0.0100 0.0001 2 1.00 0.064 0.09 0.25 4 16 256 0.0100 0.0001 3 1.00 0.064 0.09 0.25 4 16 256 0.0001 1.0000 3 0.00 0.27 0.04 0.25 4 16 256 0.0001 1.0000 3 0.00 0.417 1.09 0.25 4 16 256 0.0001 0.0100 3										
0.25 4 16 256 0.0100 1.0000 3 0.00 0.393 0.94 0.25 4 16 256 0.0100 0.0100 2 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0001 3 1.00 0.051 0.05 0.25 4 16 256 0.0100 0.0001 3 1.00 0.064 0.09 0.25 4 16 256 0.0100 0.0001 3 1.00 0.064 0.09 0.25 4 16 256 0.0001 1.0000 2 0.00 0.027 0.04 0.25 4 16 256 0.0001 1.0000 3 0.00 0.417 1.09 0.25 4 16 256 0.0001 0.0100 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 2										
0.25 4 16 256 0.0100 0.0100 2 1.00 0.049 0.05 0.25 4 16 256 0.0100 0.0100 3 1.00 0.051 0.05 0.25 4 16 256 0.0100 0.0001 2 1.00 0.064 0.09 0.25 4 16 256 0.0001 1.0000 2 0.00 0.027 0.04 0.25 4 16 256 0.0001 1.0000 2 0.00 0.027 0.04 0.25 4 16 256 0.0001 1.0000 2 0.00 0.027 0.04 0.25 4 16 256 0.0001 0.0100 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 3										0.943
0.25 4 16 256 0.0100 0.0100 3 1.00 0.051 0.05 0.25 4 16 256 0.0100 0.0001 2 1.00 0.064 0.09 0.25 4 16 256 0.0001 1.0000 2 0.00 0.027 0.04 0.25 4 16 256 0.0001 1.0000 3 0.00 0.417 1.09 0.25 4 16 256 0.0001 1.0000 3 0.00 0.417 1.09 0.25 4 16 256 0.0001 0.0100 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0100 3 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.072 0.10 0.25 4 64 1 1.0000 1.0000 3										0.052
0.25 4 16 256 0.0100 0.0001 3 1.00 0.063 0.09 0.25 4 16 256 0.0001 1.0000 2 0.00 0.027 0.04 0.25 4 16 256 0.0001 1.0000 3 0.00 0.417 1.09 0.25 4 16 256 0.0001 0.0100 3 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0100 3 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.073 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.072 0.10 0.25 4 64 1 1.0000 1.0000 3		4					3			0.053
0.25 4 16 256 0.0001 1.0000 2 0.00 0.027 0.04 0.25 4 16 256 0.0001 1.0000 3 0.00 0.417 1.09 0.25 4 16 256 0.0001 0.0100 2 1.00 0.066 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.073 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.072 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.072 0.10 0.25 4 64 1 1.0000 1.0000 3 1.00 0.001 0.00 0.25 4 64 1 1.0000 0.0100 3 <t< td=""><td>0.25</td><td>4</td><td>16</td><td>256</td><td>0.0100</td><td>0.0001</td><td>2</td><td>1.00</td><td>0.064</td><td>0.097</td></t<>	0.25	4	16	256	0.0100	0.0001	2	1.00	0.064	0.097
0.25 4 16 256 0.0001 1.0000 3 0.00 0.417 1.09 0.25 4 16 256 0.0001 0.0100 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.073 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.073 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.073 0.10 0.25 4 164 1 1.0000 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 2 <td< td=""><td>0.25</td><td>4</td><td>16</td><td>256</td><td>0.0100</td><td>0.0001</td><td>3</td><td>1.00</td><td>0.063</td><td>0.098</td></td<>	0.25	4	16	256	0.0100	0.0001	3	1.00	0.063	0.098
0.25 4 16 256 0.0001 0.0100 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.073 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.072 0.10 0.25 4 64 1 1.0000 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00			16			1.0000				0.042
0.25 4 16 256 0.0001 0.0100 3 1.00 0.060 0.10 0.25 4 16 256 0.0001 0.0001 2 1.00 0.073 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.072 0.10 0.25 4 64 1 1.0000 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0100 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>1.096</td>										1.096
0.25 4 16 256 0.0001 0.0001 2 1.00 0.073 0.10 0.25 4 16 256 0.0001 0.0001 3 1.00 0.072 0.10 0.25 4 64 1 1.0000 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0100 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0100 3 1.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>0.102</td>										0.102
0.25 4 16 256 0.0001 0.0001 3 1.00 0.072 0.10 0.25 4 64 1 1.0000 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0100 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 2 0.17										0.102
0.25 4 64 1 1.0000 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00										0.101
0.25 4 64 1 1.0000 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 2 0.17 0.001 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 0.0100 2 0.00	0.00						-			
0.25 4 64 1 1.0000 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0100 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 2 0.17 0.001 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 2 0.00										0.001
0.25 4 64 1 1.0000 0.0100 3 1.00 0.003 0.00 0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 2 0.17 0.001 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0100 3 0.83 0.003 0.01 0.25 4 64 1 0.0100 0.0001 2 0.00										0.003
0.25 4 64 1 1.0000 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 2 0.17 0.001 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0100 3 0.83 0.003 0.01 0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 3 0.67										0.003
0.25 4 64 1 1.0000 0.0001 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 1.0000 2 0.17 0.001 0.00 0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0100 3 0.83 0.003 0.01 0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 3 0.67 0.003 0.02 0.25 4 64 1 0.0001 1.0000 2 0.00										0.001
0.25 4 64 1 0.0100 1.0000 3 1.00 0.003 0.00 0.25 4 64 1 0.0100 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0100 3 0.83 0.003 0.01 0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 3 0.67 0.003 0.02 0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00					1.0000	0.0001		1.00	0.003	0.004
0.25 4 64 1 0.0100 0.0100 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0100 3 0.83 0.003 0.01 0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 3 0.67 0.003 0.02 0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00 0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00										0.003
0.25 4 64 1 0.0100 0.0100 3 0.83 0.003 0.01 0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 3 0.67 0.003 0.02 0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00										0.003
0.25 4 64 1 0.0100 0.0001 2 0.00 0.001 0.00 0.25 4 64 1 0.0100 0.0001 3 0.67 0.003 0.02 0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00										0.001
0.25 4 64 1 0.0100 0.0001 3 0.67 0.003 0.02 0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00										0.016
0.25 4 64 1 0.0001 1.0000 2 0.00 0.001 0.00										0.001
										0.029
0.20 $+$ 0.4 $+$ 0.0001 1.0000 0.100 0.003 0.00										
										0.003
										0.001
										0.001
										0.013
										0.001
										0.021
	0.25	4	64	4	1.0000	0.0100	2			0.003
	$\overline{}$									0.005
										0.004
0.25 4 64 4 1.0000 0.0001 3 1.00 0.004 0.00	0.25	4	64	4	1.0000	0.0001	3	1.00	0.004	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	4	64	4	0.0100	1.0000	2	0.00	0.001	0.002
0.25	4	64	4	0.0100	1.0000	3	0.50	0.004	0.024
0.25	4	64	4	0.0100	0.0100	2	1.00	0.004	0.004
0.25	4	64	4	0.0100	0.0100	3	1.00	0.004	0.004
0.25	4	64	4	0.0100	0.0001	2	0.67	0.001	0.004
0.25	4	64	4	0.0100	0.0001	3	1.00	0.004	0.004
0.25	4	64	4	0.0001	1.0000	2	0.67	0.001	0.004
0.25	4	64	4	0.0001	1.0000	3	1.00	0.004	0.004
0.25	4	64	4	0.0001	0.0100	2	0.83	0.001	0.004
0.25	4	64	4	0.0001	0.0100	3	1.00	0.004	0.004
0.25	4	64	4	0.0001	0.0001	3	1.00	0.004	0.004
0.25	4	64	16	1.0000	1.0000	2	0.00	0.003	0.004
0.25	4	64	16	1.0000	1.0000	3	0.17	0.003	0.025
0.25	4	64	16	1.0000	0.0100	2	0.17	0.001	0.004
0.25	4	64	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	4	64	16	1.0000	0.0001	2	0.83	0.001	0.005
0.25	4	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.25	4	64	16	0.0100	1.0000	2	0.17	0.001	0.004
0.25	4	64	16	0.0100	1.0000	3	0.50	0.004	0.033
0.25	4	64	16	0.0100	0.0100	2	1.00	0.005	0.006
0.25	4	64	16	0.0100	0.0100	3	1.00	0.005	0.006
0.25	4	64	16 16	0.0100	0.0001	3	0.83 1.00	0.001	0.006
0.25	4	64	16	0.0100	1.0000	2	0.33	0.004	0.004
0.25	4	64	16	0.0001	1.0000	3	0.33	0.001	0.004
0.25	4	64	16	0.0001	0.0100	2	1.00	0.004	0.006
0.25	4	64	16	0.0001	0.0100	3	1.00	0.004	0.006
0.25	4	64	16	0.0001	0.0001	2	1.00	0.005	0.007
0.25	4	64	16	0.0001	0.0001	3	1.00	0.005	0.006
0.25	4	64	64	1.0000	1.0000	2	0.00	0.001	0.005
0.25	4	64	64	1.0000	1.0000	3	0.00	0.048	0.600
0.25	4	64	64	1.0000	0.0100	2	0.50	0.001	0.009
0.25	4	64	64	1.0000	0.0100	3	1.00	0.008	0.008
0.25	4	64	64	1.0000	0.0001	2	1.00	0.010	0.010
0.25	4	64	64	1.0000 0.0100	1.0000	3	1.00 0.00	0.009	0.015
0.25	4	64	64	0.0100	1.0000	3	0.00	0.004	0.005
0.25	4	64	64	0.0100	0.0100	2	1.00	0.001	0.002
0.25	4	64	64	0.0100	0.0100	3	1.00	0.010	0.011
0.25	4	64	64	0.0100	0.0001	2	1.00	0.011	0.012
0.25	4	64	64	0.0100	0.0001	3	1.00	0.011	0.012
0.25	4	64	64	0.0001	1.0000	2	0.00	0.001	0.009
0.25	4	64	64	0.0001	1.0000	3	0.00	0.093	0.167
0.25	4	64	64	0.0001	0.0100	2	1.00	0.017	0.018
0.25	4	64	64	0.0001	0.0100	3	1.00	0.017	0.018
0.25	4	64	64	0.0001	0.0001	2	1.00	0.020	0.022
0.25	4	64	64	0.0001	0.0001	3	1.00	0.021	0.022
0.25	4	64	256	1.0000	1.0000	3	0.00	0.012	0.017
0.25	4	64	256 256	1.0000	1.0000 0.0100	2	0.00	0.198	0.282 0.052
0.25	4	64	256	1.0000	0.0100	3	0.33	0.001	0.032
0.25	4	64	256	1.0000	0.0001	2	1.00	0.033	0.059
0.25	4	64	256	1.0000	0.0001	3	1.00	0.049	0.073
0.25	4	64	256	0.0100	1.0000	2	0.00	0.016	0.021
0.25	4	64	256	0.0100	1.0000	3	0.00	0.275	0.387
0.25	4	64	256	0.0100	0.0100	2	1.00	0.048	0.079
0.25	4	64	256	0.0100	0.0100	3	1.00	0.049	0.079
0.25	4	64	256	0.0100	0.0001	2	1.00	0.067	0.093
0.25	4	64	256	0.0100	0.0001	3	1.00	0.064	0.092
0.25	4	64	256	0.0001	1.0000	2	0.00	0.027	0.042
0.25	4	64	256	0.0001	1.0000	3	0.00	0.427	1.209
0.25	4	64	256 256	0.0001	0.0100	3	1.00	0.059	0.089
0.25	4	64	256	0.0001	0.0100	2	1.00	0.060	0.097
0.25	4	64	256	0.0001	0.0001	3	1.00	0.117	0.127
0.25	4	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	4	256	1	1.0000	1.0000	3	0.83	0.003	0.013
0.25	4	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	4	256	1	1.0000	0.0100	3	0.50	0.003	0.016
0.25	4	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	4	256	1	1.0000	0.0001	3	0.67	0.003	0.017
0.25	4	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	4	256	1	0.0100	1.0000	3	0.83	0.003	0.015
0.25	4	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	4	256	1	0.0100	0.0100	3	0.83	0.003	0.016

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	4	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.25	4	256	1	0.0100	0.0001	3	1.00	0.003	0.004
0.25	4	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	4	256 256	1	0.0001	1.0000 0.0100	3	0.83	0.003	0.016 0.001
0.25	4	256	1	0.0001	0.0100	3	1.00	0.001	0.001
0.25	4	256	1	0.0001	0.0001	2	0.00	0.003	0.003
0.25	4	256	1	0.0001	0.0001	3	0.83	0.003	0.016
0.25	4	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	4	256	4	1.0000	1.0000	3	0.50	0.003	0.015
0.25	4	256	4	1.0000	0.0100	2	0.50	0.001	0.004
0.25	4	256 256	4	1.0000	0.0100	3	1.00 0.17	0.003	0.004
0.25	4	256	4	1.0000	0.0001	3	1.00	0.001	0.004
0.25	4	256	4	0.0100	1.0000	2	0.33	0.001	0.003
0.25	4	256	4	0.0100	1.0000	3	0.33	0.003	0.019
0.25	4	256	4	0.0100	0.0100	2	0.67	0.001	0.004
0.25	4	256	4	0.0100	0.0100	3	1.00	0.003	0.003
0.25	4	256	4	0.0100	0.0001	2	0.67	0.001	0.004
0.25	4	256 256	4	0.0100	0.0001 1.0000	3	1.00 0.33	0.003	0.004
0.25	4	256	4	0.0001	1.0000	3	0.55	0.001	0.004
0.25	4	256	4	0.0001	0.0100	2	0.83	0.001	0.004
0.25	4	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	4	256	4	0.0001	0.0001	2	0.83	0.001	0.005
0.25	4	256	4	0.0001	0.0001	3	0.83	0.003	0.016
0.25	4	256 256	16 16	1.0000	1.0000	3	0.00	0.001	0.002
0.25	4	256	16	1.0000	0.0100	2	0.55	0.004	0.272
0.25	4	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	4	256	16	1.0000	0.0001	2	0.67	0.001	0.006
0.25	4	256	16	1.0000	0.0001	3	1.00	0.005	0.006
0.25	4	256	16	0.0100	1.0000	2	0.17	0.001	0.005
0.25	4	256	16 16	0.0100	1.0000 0.0100	3 2	0.17	0.004	0.032
0.25	4	256 256	16	0.0100	0.0100	3	1.00	0.004	0.049
0.25	4	256	16	0.0100	0.0001	2	1.00	0.005	0.007
0.25	4	256	16	0.0100	0.0001	3	1.00	0.005	0.006
0.25	4	256	16	0.0001	1.0000	2	0.50	0.001	0.006
0.25	4	256	16	0.0001	1.0000	3	0.83	0.006	0.043
0.25	4	256	16	0.0001	0.0100	2	1.00	0.006	0.007
0.25	4	256 256	16 16	0.0001	0.0100	3	1.00	0.006	0.006
0.25	4	256	16	0.0001	0.0001	3	1.00	0.005	0.007
0.25	4	256	64	1.0000	1.0000	2	0.00	0.001	0.004
0.25	4	256	64	1.0000	1.0000	3	0.17	0.009	0.062
0.25	4	256	64	1.0000	0.0100	2	0.67	0.001	0.011
0.25	4	256	64	1.0000	0.0100	3	1.00	0.011	0.012
0.25	4	256	64	1.0000	0.0001	2	1.00	0.015	0.016
0.25	4	256 256	64 64	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.013	0.016
0.25	4	256	64	0.0100	1.0000	3	0.00	0.012	0.088
0.25	4	256	64	0.0100	0.0100	2	1.00	0.010	0.015
0.25	4	256	64	0.0100	0.0100	3	1.00	0.010	0.015
0.25	4	256	64	0.0100	0.0001	2	1.00	0.011	0.012
0.25	4	256	64	0.0100	0.0001	3	1.00	0.011	0.013
0.25	4	256 256	64	0.0001	1.0000	3	0.50	0.001	0.012
0.25	4	256	64	0.0001	0.0100	2	1.00	0.010	0.079
0.25	4	256	64	0.0001	0.0100	3	1.00	0.011	0.019
0.25	4	256	64	0.0001	0.0001	2	1.00	0.014	0.022
0.25	4	256	64	0.0001	0.0001	3	1.00	0.014	0.022
0.25	4	256	256	1.0000	1.0000	2	0.00	0.011	0.017
0.25	4	256	256	1.0000	1.0000	3	0.00	0.235	0.810
0.25	4	256 256	256 256	1.0000	0.0100	3	0.33 1.00	0.001	0.050 0.053
0.25	4	256	256	1.0000	0.0100	2	1.00	0.045	0.059
0.25	4	256	256	1.0000	0.0001	3	1.00	0.046	0.071
0.25	4	256	256	0.0100	1.0000	2	0.00	0.001	0.026
0.25	4	256	256	0.0100	1.0000	3	0.17	0.037	0.436
0.25	4	256	256	0.0100	0.0100	2	1.00	0.050	0.080
0.25	4	256	256	0.0100	0.0100	3	1.00	0.048	0.080
0.25	4	256 256	256 256	0.0100	0.0001	3	1.00	0.061	0.093
0.25	4	256	256	0.0001	1.0000	2	0.00	0.026	0.039
0.25	4	256	256	0.0001	1.0000	3	0.00	0.412	1.439
$\overline{}$									

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	4	256	256	0.0001	0.0100	2	1.00	0.066	0.082
0.25	4	256	256	0.0001	0.0100	3	1.00	0.069	0.085
0.25	4	256	256	0.0001	0.0001	2	1.00	0.078	0.114
0.25	4	256	256	0.0001	0.0001	3	1.00	0.076	0.121
0.25	16	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	16 16	1	1	1.0000	1.0000 0.0100	3	1.00 0.00	0.003	0.005
0.25	16	1	1	1.0000	0.0100	3	1.00	0.001	0.001
0.25	16	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	16	1	1	1.0000	0.0001	3	1.00	0.003	0.004
0.25	16	1	1	0.0100	1.0000	2	0.17	0.001	0.003
0.25	16	1	1	0.0100	1.0000	3	1.00	0.003	0.005
0.25	16	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	16 16	1	1	0.0100	0.0100	3	1.00	0.003	0.004
0.25	16	1	1	0.0100	0.0001	3	0.50	0.001	0.001
0.25	16	1	1	0.0001	1.0000	2	0.00	0.003	0.001
0.25	16	1	1	0.0001	1.0000	3	0.83	0.003	0.013
0.25	16	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	16	1	1	0.0001	0.0100	3	1.00	0.003	0.005
0.25	16	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	16	1	1	0.0001	0.0001	3	1.00	0.003	0.004
0.25	16 16	1	4	1.0000	1.0000	2	0.00	0.001	0.002
0.25	16	1	4	1.0000	0.0100	2	0.30	0.003	0.018
0.25	16	1	4	1.0000	0.0100	3	1.00	0.001	0.003
0.25	16	1	4	1.0000	0.0001	2	0.50	0.001	0.004
0.25	16	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.25	16	1	4	0.0100	1.0000	2	0.33	0.001	0.004
0.25	16	1	4	0.0100	1.0000	3	1.00	0.003	0.005
0.25	16 16	1	4	0.0100	0.0100	2	0.50 1.00	0.001	0.004
0.25	16	1	4	0.0100	0.0001	2	0.67	0.003	0.007
0.25	16	1	4	0.0100	0.0001	3	1.00	0.004	0.007
0.25	16	1	4	0.0001	1.0000	2	0.50	0.001	0.004
0.25	16	1	4	0.0001	1.0000	3	0.83	0.003	0.017
0.25	16	1	4	0.0001	0.0100	2	1.00	0.003	0.004
0.25 0.25	16 16	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	16	1	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	16	1	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	16	1	16	1.0000	1.0000	3	0.00	0.029	0.031
0.25	16	1	16	1.0000	0.0100	2	0.83	0.001	0.005
0.25	16	1	16	1.0000	0.0100	3	1.00	0.005	0.009
0.25	16	1	16	1.0000	0.0001	2	1.00	0.005	0.006
0.25	16	1	16	1.0000	1.0000	3	1.00 0.00	0.005	0.006
0.25	16 16	1	16 16	0.0100	1.0000	3	0.00	0.001	0.003
0.25	16	1	16	0.0100	0.0100	2	1.00	0.004	0.005
0.25	16	1	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	16	1	16	0.0100	0.0001	2	0.83	0.001	0.005
0.25	16	1	16	0.0100	0.0001	3	1.00	0.004	0.009
0.25	16	1	16	0.0001	1.0000	2	0.00	0.001	0.002
0.25	16 16	1	16 16	0.0001	1.0000 0.0100	3	0.00 1.00	0.028	0.037
0.25	16	1	16	0.0001	0.0100	3	1.00	0.004	0.006
0.25	16	1	16	0.0001	0.0001	2	1.00	0.004	0.005
0.25	16	1	16	0.0001	0.0001	3	1.00	0.005	0.006
0.25	16	1	64	1.0000	1.0000	2	0.00	0.003	0.004
0.25	16	1	64	1.0000	1.0000	3	0.00	0.046	0.554
0.25	16	1	64	1.0000	0.0100	2	0.83	0.001	0.012
0.25	16	1	64	1.0000	0.0100	3	1.00	0.007	0.027
0.25	16 16	1	64 64	1.0000	0.0001	3	1.00	0.009	0.010 0.010
0.25	16	1	64	0.0100	1.0000	2	0.00	0.003	0.005
0.25	16	1	64	0.0100	1.0000	3	0.00	0.062	0.083
0.25	16	1	64	0.0100	0.0100	2	1.00	0.010	0.015
0.25	16	1	64	0.0100	0.0100	3	1.00	0.009	0.015
0.25	16	1	64	0.0100	0.0001	2	1.00	0.011	0.018
0.25	16	1	64	0.0100	1.0000	3	1.00 0.00	0.012	0.017
0.25	16 16	1	64	0.0001	1.0000	2	0.00	0.006	0.006
0.25	16	1	64	0.0001	0.0100	2	1.00	0.088	0.094
						3	1.00	0.011	0.013
0.25	16	1	64	0.0001	0.0100	3	1.00	0.011	0.015
	16 16	1	64	0.0001	0.0100	2	1.00	0.014	0.013

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	16	1	256	1.0000	1.0000	2	0.00	0.011	0.017
0.25	16	1	256	1.0000	1.0000	3	0.00	0.189	0.279
0.25	16	1	256	1.0000	0.0100	2	1.00	0.034	0.044
0.25	16 16	1	256 256	1.0000	0.0100	3	1.00	0.033	0.036
0.25	16	1	256	1.0000	0.0001	3	1.00	0.048	0.049
0.25	16	1	256	0.0100	1.0000	2	0.00	0.018	0.019
0.25	16	1	256	0.0100	1.0000	3	0.00	0.299	0.306
0.25	16	1	256	0.0100	0.0100	2	1.00	0.048	0.052
0.25	16 16	1	256 256	0.0100	0.0100	3	1.00	0.047	0.051
0.25	16	1	256	0.0100	0.0001	3	1.00	0.058	0.089
0.25	16	1	256	0.0001	1.0000	2	0.00	0.025	0.040
0.25	16	1	256	0.0001	1.0000	3	0.00	0.408	1.547
0.25	16 16	1	256 256	0.0001	0.0100	2	1.00	0.064	0.067
0.25	16	1	256	0.0001	0.0001	2	1.00	0.064	0.067 0.086
0.25	16	1	256	0.0001	0.0001	3	1.00	0.078	0.084
0.25	16	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	16	4	1	1.0000	1.0000	3	1.00	0.005	0.737
0.25	16	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	16 16	4	1	1.0000	0.0100	3	0.50	0.003	0.018
0.25	16	4	1	1.0000	0.0001	3	1.00	0.001	0.001
0.25	16	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	16	4	1	0.0100	1.0000	3	1.00	0.003	0.006
0.25	16	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	16 16	4	1	0.0100	0.0100	3	0.50	0.004	0.014
0.25	16	4	1	0.0100	0.0001	3	0.67	0.003	0.013
0.25	16	4	1	0.0001	1.0000	2	0.50	0.001	0.003
0.25	16	4	1	0.0001	1.0000	3	1.00	0.003	0.006
0.25	16	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	16 16	4	1	0.0001	0.0100	3	0.67	0.003	0.014
0.25	16	4	1	0.0001	0.0001	3	0.83	0.003	0.062
0.25	16	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	16	4	4	1.0000	1.0000	3	0.83	0.004	0.019
0.25	16 16	4	4	1.0000	0.0100	3	0.17 1.00	0.001	0.003
0.25	16	4	4	1.0000	0.0001	2	0.83	0.003	0.004
0.25	16	4	4	1.0000	0.0001	3	1.00	0.003	0.003
0.25	16	4	4	0.0100	1.0000	2	0.33	0.001	0.003
0.25	16	4	4	0.0100	1.0000	3	0.83	0.003	0.019
0.25	16 16	4	4	0.0100	0.0100	3	0.67 1.00	0.001	0.003
0.25	16	4	4	0.0100	0.0100	2	0.50	0.003	0.007
0.25	16	4	4	0.0100	0.0001	3	1.00	0.003	0.007
0.25	16	4	4	0.0001	1.0000	2	0.50	0.001	0.004
0.25	16	4	4	0.0001	1.0000	3	0.83	0.003	0.015
0.25	16 16	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	16	4	4	0.0001	0.0100	2	0.83	0.003	0.003
0.25	16	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	16	4	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	16	4	16	1.0000	1.0000	3	0.17	0.003	0.025
0.25	16 16	4	16 16	1.0000 1.0000	0.0100 0.0100	3	0.67 1.00	0.001 0.004	0.005 0.010
0.25	16	4	16	1.0000	0.0001	2	1.00	0.004	0.006
0.25	16	4	16	1.0000	0.0001	3	1.00	0.004	0.005
0.25	16	4	16	0.0100	1.0000	2	0.00	0.001	0.002
0.25	16	4	16	0.0100	1.0000	3	0.17	0.004	0.030
0.25	16 16	4	16 16	0.0100	0.0100 0.0100	3	1.00	0.004	0.005
0.25	16	4	16	0.0100	0.0001	2	1.00	0.004	0.005
0.25	16	4	16	0.0100	0.0001	3	1.00	0.005	0.006
0.25	16	4	16	0.0001	1.0000	2	0.00	0.001	0.003
0.25	16	4	16	0.0001	1.0000	3	0.17	0.005	0.034
0.25	16 16	4	16 16	0.0001 0.0001	0.0100	2	1.00	0.004	0.006 0.005
0.25	16	4	16	0.0001	0.0001	2	1.00	0.005	0.005
0.25	16	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.25	16	4	64	1.0000	1.0000	2	0.00	0.003	0.004
0.25	16 16	4	64	1.0000	1.0000 0.0100	3	0.00	0.046	0.065 0.012
0.25	16	4	64	1.0000	0.0100	3	1.00	0.001	0.012
5.23	10	<u>'</u>	J.	1.5000	5.5100	5	1.00	0.011	0.012

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	16	4	64	1.0000	0.0001	2	1.00	0.010	0.014
0.25	16	4	64	1.0000	0.0001	3	1.00	0.009	0.014
0.25	16	4	64	0.0100	1.0000	2	0.00	0.004	0.006
0.25	16	4	64	0.0100	1.0000	3	0.00	0.065	0.091
0.25	16	4	64	0.0100	0.0100	2	1.00	0.010	0.014
0.25	16	4	64	0.0100	0.0100	3	1.00	0.010	0.059
0.25	16	4	64	0.0100	0.0001	2	1.00	0.011	0.012
0.25	16	4	64	0.0100	0.0001	3	1.00	0.010	0.012
0.25	16	4	64	0.0001	1.0000	2	0.00	0.005	0.008
0.25	16 16	4	64	0.0001	1.0000 0.0100	3	1.00	0.090	0.122
0.25	16	4	64	0.0001	0.0100	3	1.00	0.011	0.014
0.25	16	4	64	0.0001	0.0001	2	1.00	0.011	0.018
0.25	16	4	64	0.0001	0.0001	3	1.00	0.013	0.022
0.25	16	4	256	1.0000	1.0000	2	0.00	0.011	0.017
0.25	16	4	256	1.0000	1.0000	3	0.00	0.187	0.285
0.25	16	4	256	1.0000	0.0100	2	1.00	0.033	0.035
0.25	16	4	256	1.0000	0.0100	3	1.00	0.033	0.034
0.25	16	4	256	1.0000	0.0001	2	1.00	0.046	0.070
0.25	16	4	256	1.0000	0.0001	3	1.00	0.046	0.056
0.25	16	4	256	0.0100	1.0000	2	0.00	0.018	0.027
0.25	16 16	4	256 256	0.0100	1.0000 0.0100	3	0.00 1.00	0.303	0.619 0.076
0.25	16	4	256	0.0100	0.0100	3	1.00	0.046	0.076
0.25	16	4	256	0.0100	0.0100	2	1.00	0.043	0.067
0.25	16	4	256	0.0100	0.0001	3	1.00	0.058	0.090
0.25	16	4	256	0.0001	1.0000	2	0.00	0.027	0.041
0.25	16	4	256	0.0001	1.0000	3	0.00	0.484	3.293
0.25	16	4	256	0.0001	0.0100	2	1.00	0.059	0.087
0.25	16	4	256	0.0001	0.0100	3	1.00	0.058	0.097
0.25	16	4	256	0.0001	0.0001	2	1.00	0.095	0.128
0.25	16	4	256	0.0001	0.0001	3	1.00	0.085	0.127
0.25	16	16	1	1.0000	1.0000	2	0.17	0.001	0.003
0.25	16	16	1	1.0000	1.0000	3	0.83	0.003	0.017
0.25	16 16	16 16	1	1.0000	0.0100	3	1.00	0.001	0.001
0.25	16	16	1	1.0000	0.0100	2	0.00	0.003	0.006
0.25	16	16	1	1.0000	0.0001	3	1.00	0.001	0.001
0.25	16	16	1	0.0100	1.0000	2	0.17	0.003	0.003
0.25	16	16	1	0.0100	1.0000	3	1.00	0.003	0.008
0.25	16	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	16	16	1	0.0100	0.0100	3	0.83	0.003	0.016
0.25	16	16	1	0.0100	0.0001	2	0.00	0.001	0.001
0.25	16	16	1	0.0100	0.0001	3	1.00	0.003	0.004
0.25	16	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	16	16	1	0.0001	1.0000	3	0.67	0.003	0.017
0.25	16	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	16	16	1	0.0001	0.0100	3	1.00	0.003	0.005
0.25	16 16	16 16	1	0.0001	0.0001	3	0.00 1.00	0.001	0.001
0.25	16	16	4	1.0000	1.0000	2	0.00	0.003	0.009
0.25	16	16	4	1.0000	1.0000	3	0.83	0.001	0.020
0.25	16	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.25	16	16	4	1.0000	0.0100	3	1.00	0.003	0.004
0.25	16	16	4	1.0000	0.0001	2	0.17	0.001	0.003
0.25	16	16	4	1.0000	0.0001	3	1.00	0.003	0.008
0.25	16	16	4	0.0100	1.0000	2	0.17	0.001	0.004
0.25	16	16	4	0.0100	1.0000	3	0.83	0.003	0.022
0.25	16	16	4	0.0100	0.0100	2	0.83	0.001	0.004
0.25	16	16	4	0.0100	0.0100	3	1.00	0.003 0.001	0.004
0.25	16 16	16 16	4	0.0100	0.0001	3	0.67 1.00	0.001	0.004
0.25	16	16	4	0.0100	1.0000	2	1.00	0.003	0.004
0.25	16	16	4	0.0001	1.0000	3	1.00	0.003	0.004
0.25	16	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.25	16	16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	16	16	4	0.0001	0.0001	2	0.50	0.001	0.003
0.25	16	16	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	16	16	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	16	16	16	1.0000	1.0000	3	0.33	0.003	0.026
0.25	16	16	16	1.0000	0.0100	2	0.17	0.001	0.005
0.25	16	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	16	16	16	1.0000	0.0001	2	0.50	0.001	0.005
0.25	16 16	16 16	16 16	1.0000 0.0100	0.0001 1.0000	2	1.00 0.00	0.004	0.006
0.25	16	16	16	0.0100	1.0000	3	0.67	0.001	0.001
0.23	10	10	10	0.0100	1.0000	J	0.07	0.004	0.056

mul	m_1	m_2	\tau	TR	DTR	alg	SR	mint	maxt
0.25	16 16	16 16	16 16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	16	16	16	0.0100	0.0100	2	1.00	0.004	0.003
0.25	16	16	16	0.0100	0.0001	3	1.00	0.004	0.048
0.25	16	16	16	0.0001	1.0000	2	0.50	0.001	0.005
0.25	16	16	16	0.0001	1.0000	3	0.83	0.004	0.032
0.25	16	16	16	0.0001	0.0100	2	1.00	0.004	0.005
0.25	16	16	16	0.0001	0.0100	3	1.00	0.004	0.005
0.25	16	16	16	0.0001	0.0001	2	1.00	0.005	0.007
0.25	16	16	16	0.0001	0.0001	3	1.00	0.005	0.006
0.25	16	16	64	1.0000	1.0000	2	0.00	0.001	0.005
0.25	16	16	64	1.0000	1.0000	3	0.00	0.047	0.056
0.25	16	16	64	1.0000	0.0100	2	0.83	0.001	0.009
0.25	16	16	64	1.0000	0.0100	3	1.00	0.008	0.011
0.25	16 16	16 16	64	1.0000	0.0001	3	1.00	0.009	0.013 0.012
0.25	16	16	64	0.0100	1.0000	2	0.00	0.009	0.012
0.25	16	16	64	0.0100	1.0000	3	0.00	0.065	0.077
0.25	16	16	64	0.0100	0.0100	2	0.83	0.001	0.012
0.25	16	16	64	0.0100	0.0100	3	1.00	0.010	0.012
0.25	16	16	64	0.0100	0.0001	2	1.00	0.011	0.014
0.25	16	16	64	0.0100	0.0001	3	1.00	0.012	0.014
0.25	16	16	64	0.0001	1.0000	2	0.00	0.001	0.007
0.25	16	16	64	0.0001	1.0000	3	0.00	0.084	0.093
0.25	16	16	64	0.0001	0.0100	2	1.00	0.011	0.012
0.25	16	16	64	0.0001	0.0100	3	1.00	0.011	0.014
0.25	16	16	64	0.0001	0.0001	2	1.00	0.014	0.015
0.25	16 16	16 16	64 256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.013	0.015
0.25	16	16	256	1.0000	1.0000	3	0.00	0.011	0.017
0.25	16	16	256	1.0000	0.0100	2	0.83	0.103	0.702
0.25	16	16	256	1.0000	0.0100	3	1.00	0.033	0.037
0.25	16	16	256	1.0000	0.0001	2	1.00	0.047	0.050
0.25	16	16	256	1.0000	0.0001	3	1.00	0.048	0.050
0.25	16	16	256	0.0100	1.0000	2	0.00	0.017	0.025
0.25	16	16	256	0.0100	1.0000	3	0.00	0.289	0.316
0.25	16	16	256	0.0100	0.0100	2	1.00	0.051	0.054
0.25	16	16	256	0.0100	0.0100	3	1.00	0.049	0.052
0.25	16	16	256	0.0100	0.0001	2	1.00	0.065	1.111
0.25	16	16	256	0.0100	0.0001	3	1.00	0.064	0.098
0.25	16	16	256	0.0001	1.0000	2	0.00	0.025	0.042
0.25	16 16	16 16	256 256	0.0001	1.0000 0.0100	3	0.00 1.00	0.420	0.667
0.25	16	16	256	0.0001	0.0100	3	1.00	0.063	0.067
0.25	16	16	256	0.0001	0.0001	2	1.00	0.003	0.122
0.25	16	16	256	0.0001	0.0001	3	1.00	0.080	0.089
0.25	16	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	16	64	1	1.0000	1.0000	3	1.00	0.003	0.003
0.25	16	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	16	64	1	1.0000	0.0100	3	0.67	0.003	0.014
0.25	16	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	16	64	1	1.0000	0.0001	3	0.83	0.003	0.013
0.25	16	64	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	16	64	1	0.0100	1.0000	3	1.00	0.003	0.003
0.25	16 16	64	1	0.0100	0.0100	2	0.00 1.00	0.001	0.001
0.25	16	64	1	0.0100	0.0100	2	0.00	0.003	0.003
0.25	16	64	1	0.0100	0.0001	3	1.00	0.001	0.001
0.25	16	64	1	0.0001	1.0000	2	0.00	0.003	0.001
0.25	16	64	1	0.0001	1.0000	3	1.00	0.003	0.006
0.25	16	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	16	64	1	0.0001	0.0100	3	1.00	0.003	0.003
0.25	16	64	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	16	64	1	0.0001	0.0001	3	0.83	0.003	0.014
0.25	16	64	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	16	64	4	1.0000	1.0000	3	1.00	0.003	0.004
0.25	16	64	4	1.0000	0.0100	2	0.33	0.001	0.003
0.25	16	64	4	1.0000	0.0100	3	1.00	0.003	0.003
0.25	16 16	64 64	4	1.0000	0.0001	2	0.33 1.00	0.001	0.004 0.004
0.25	16	64	4	0.0100	1.00001	2	0.33	0.003	0.004
0.25	16	64	4	0.0100	1.0000	3	1.00	0.001	0.003
0.25	16	64	4	0.0100	0.0100	2	0.67	0.003	0.003
0.25	16	64	4	0.0100	0.0100	3	1.00	0.003	0.003
0.25	16	64	4	0.0100	0.0001	2	0.83	0.001	0.003
0.25	16	64	4	0.0100	0.0001	3	1.00	0.003	0.003

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	16	64	4	0.0001	1.0000	2	0.33	0.001	0.003
0.25	16	64	4	0.0001	1.0000	3	0.50	0.003	0.020
0.25	16	64	4	0.0001	0.0100	2	1.00	0.003	0.003
0.25	16	64	4	0.0001	0.0100	3	1.00	0.003	0.003
0.25	16	64	4	0.0001	0.0001	2	0.83	0.001	0.004
0.25	16	64	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	16	64	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	16	64	16	1.0000	1.0000	3	0.83	0.003	0.024
0.25	16	64	16	1.0000	0.0100	2	1.00	0.004	0.004
0.25	16 16	64	16 16	1.0000	0.0100	3	1.00	0.004	0.004
0.25	16	64	16	1.0000	0.0001	3	1.00	0.004	0.004
0.25	16	64	16	0.0100	1.0000	2	0.00	0.001	0.002
0.25	16	64	16	0.0100	1.0000	3	0.33	0.004	0.029
0.25	16	64	16	0.0100	0.0100	2	1.00	0.004	0.005
0.25	16	64	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	16	64	16	0.0100	0.0001	2	1.00	0.005	0.006
0.25	16	64	16	0.0100	0.0001	3	1.00	0.006	0.006
0.25	16	64	16	0.0001	1.0000	2	0.50	0.001	0.006
0.25	16	64	16	0.0001	1.0000	3	0.67	0.006	0.041
0.25	16	64	16	0.0001	0.0100	3	1.00	0.004	0.006
0.25	16 16	64	16 16	0.0001	0.0100	2	1.00	0.004	0.006
0.25	16	64	16	0.0001	0.0001	3	1.00	0.005	0.008
0.25	16	64	64	1.0000	1.0000	2	0.00	0.003	0.007
0.25	16	64	64	1.0000	1.0000	3	0.00	0.001	0.003
0.25	16	64	64	1.0000	0.0100	2	0.33	0.001	0.011
0.25	16	64	64	1.0000	0.0100	3	1.00	0.007	0.012
0.25	16	64	64	1.0000	0.0001	2	1.00	0.010	0.014
0.25	16	64	64	1.0000	0.0001	3	1.00	0.010	0.015
0.25	16	64	64	0.0100	1.0000	2	0.00	0.001	0.006
0.25	16	64	64	0.0100	1.0000	3	0.00	0.074	0.091
0.25	16	64	64	0.0100	0.0100	2	1.00	0.010	0.015
0.25	16	64	64	0.0100	0.0100	3	1.00	0.012	0.051
0.25	16 16	64	64 64	0.0100	0.0001	3	1.00	0.011	0.018
0.25	16	64	64	0.0100	1.0000	2	1.00 0.33	0.012	0.018 0.015
0.25	16	64	64	0.0001	1.0000	3	0.50	0.001	0.013
0.25	16	64	64	0.0001	0.0100	2	1.00	0.011	0.108
0.25	16	64	64	0.0001	0.0100	3	1.00	0.012	0.018
0.25	16	64	64	0.0001	0.0001	2	1.00	0.021	0.022
0.25	16	64	64	0.0001	0.0001	3	1.00	0.021	0.022
0.25	16	64	256	1.0000	1.0000	2	0.00	0.011	0.017
0.25	16	64	256	1.0000	1.0000	3	0.00	0.196	0.870
0.25	16	64	256	1.0000	0.0100	2	0.50	0.001	0.052
0.25	16	64	256	1.0000	0.0100	3	1.00	0.052	0.055
0.25	16	64	256	1.0000	0.0001	2	1.00	0.073	0.074
0.25	16 16	64	256 256	1.0000	1.0000	3	1.00 0.00	0.072	0.074
0.25	16	64	256	0.0100	1.0000	3	0.00	0.020	0.030
0.25	16	64	256	0.0100	0.0100	2	1.00	0.321	0.720
0.25	16	64	256	0.0100	0.0100	3	1.00	0.049	0.058
0.25	16	64	256	0.0100	0.0001	2	1.00	0.061	0.071
0.25	16	64	256	0.0100	0.0001	3	1.00	0.060	0.096
0.25	16	64	256	0.0001	1.0000	2	0.00	0.025	0.041
0.25	16	64	256	0.0001	1.0000	3	0.00	0.636	2.650
0.25	16	64	256	0.0001	0.0100	2	1.00	0.060	0.100
0.25	16	64	256	0.0001	0.0100	3	1.00	0.058	0.101
0.25	16	64	256	0.0001	0.0001	2	1.00	0.076	0.124 0.114
0.25	16 16	64 256	256 1	1.0000	0.0001 1.0000	3	0.00	0.076	0.114
0.25	16	256	1	1.0000	1.0000	3	1.00	0.001	0.001
0.25	16	256	1	1.0000	0.0100	2	0.00	0.003	0.003
0.25	16	256	1	1.0000	0.0100	3	0.83	0.003	0.013
0.25	16	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	16	256	1	1.0000	0.0001	3	0.50	0.003	0.014
0.25	16	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	16	256	1	0.0100	1.0000	3	0.50	0.003	0.014
0.25	16	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	16	256	1	0.0100	0.0100	3	1.00	0.003	0.003
0.25	16	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.25	16	256	1	0.0100	0.0001	3	0.83	0.003	0.016
0.25	16	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	16 16	256 256	1	0.0001	1.0000 0.0100	3	0.83	0.003	0.013
0.25	16	256	1	0.0001	0.0100	3	0.83	0.001	0.001
0.23	10	230	1	0.0001	0.0100		0.03	0.003	0.014

mul	m_1	m_2	τ	TR	DTR	alg	SR	mint	maxt
			- ' '						
0.25	16 16	256 256	1	0.0001	0.0001	3	0.00 1.00	0.001	0.001
0.25	16	256	4	1.0000	1.00001	2	0.00	0.003	0.004
0.25	16	256	4	1.0000	1.0000	3	0.50	0.001	0.001
0.25	16	256	4	1.0000	0.0100	2	0.17	0.003	0.004
0.25	16	256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.25	16	256	4	1.0000	0.0001	2	0.17	0.001	0.003
0.25	16	256	4	1.0000	0.0001	3	1.00	0.003	0.004
0.25	16	256	4	0.0100	1.0000	2	0.33	0.001	0.003
0.25	16	256	4	0.0100	1.0000	3	0.67	0.003	0.016
0.25	16	256	4	0.0100	0.0100	2	0.83	0.001	0.004
0.25	16	256	4	0.0100	0.0100	3	1.00	0.003	0.004
0.25	16	256	4	0.0100	0.0001	2	0.50	0.001	0.004
0.25	16	256	4	0.0100	0.0001	3	1.00	0.003	0.004
0.25	16	256	4	0.0001	1.0000	2	0.50	0.001	0.003
0.25	16	256	4	0.0001	1.0000	3	0.83	0.003	0.018
0.25	16	256	4	0.0001	0.0100	2	1.00	0.003	0.004
0.25	16	256	4	0.0001	0.0100	3	1.00	0.003	0.003
0.25	16	256	4	0.0001	0.0001	2	0.83	0.001	0.004
0.25	16	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	16	256	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	16	256	16	1.0000	1.0000	3	0.17	0.003	0.031
0.25	16	256	16	1.0000	0.0100	2	0.17	0.001	0.005
0.25	16	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	16	256	16	1.0000	0.0001	2	0.33	0.001	0.006
0.25	16 16	256 256	16 16	1.0000	1.0000	3	1.00 0.33	0.004	0.005
0.25	16	256	16	0.0100	1.0000	3	0.33	0.001	0.005
0.25	16	256	16	0.0100	0.0100	2	1.00	0.004	0.029
0.25	16	256	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	16	256	16	0.0100	0.0001	2	1.00	0.005	0.006
0.25	16	256	16	0.0100	0.0001	3	1.00	0.005	0.006
0.25	16	256	16	0.0001	1.0000	2	0.33	0.001	0.006
0.25	16	256	16	0.0001	1.0000	3	0.50	0.004	0.042
0.25	16	256	16	0.0001	0.0100	2	1.00	0.004	0.007
0.25	16	256	16	0.0001	0.0100	3	1.00	0.004	0.006
0.25	16	256	16	0.0001	0.0001	2	1.00	0.005	0.007
0.25	16	256	16	0.0001	0.0001	3	1.00	0.005	0.007
0.25	16	256	64	1.0000	1.0000	2	0.00	0.001	0.004
0.25	16	256	64	1.0000	1.0000	3	0.00	0.045	0.817
0.25	16	256	64	1.0000	0.0100	2	0.67	0.001	0.008
0.25	16	256	64	1.0000	0.0100	3	1.00	0.008	0.008
0.25	16	256	64	1.0000	0.0001	2	1.00	0.010	0.016
0.25	16	256	64	1.0000	0.0001	3	1.00	0.010	0.016
0.25	16	256	64	0.0100	1.0000	2	0.00	0.001	0.006
0.25	16	256	64	0.0100	1.0000	3	0.50	0.012	0.090
0.25	16	256	64	0.0100	0.0100	2	1.00	0.010	0.016
0.25	16	256	64	0.0100	0.0100	3	1.00	0.010	0.015
0.25	16	256	64	0.0100	0.0001	2	1.00	0.011	0.019
0.25	16	256 256	64 64	0.0100	0.0001 1.0000	2	1.00	0.013	0.018
0.25	16 16	256	64	0.0001	1.0000	3	0.00	0.001	0.008
0.25	16	256	64	0.0001	0.0100	2	1.00	0.013	0.021
0.25	16	256	64	0.0001	0.0100	3	1.00	0.012	0.021
0.25	16	256	64	0.0001	0.0001	2	1.00	0.012	0.010
0.25	16	256	64	0.0001	0.0001	3	1.00	0.012	0.022
0.25	16	256	256	1.0000	1.0000	2	0.00	0.011	0.017
0.25	16	256	256	1.0000	1.0000	3	0.00	0.181	0.282
0.25	16	256	256	1.0000	0.0100	2	0.17	0.001	0.034
0.25	16	256	256	1.0000	0.0100	3	1.00	0.033	0.052
0.25	16	256	256	1.0000	0.0001	2	0.67	0.001	0.221
0.25	16	256	256	1.0000	0.0001	3	1.00	0.062	0.077
0.25	16	256	256	0.0100	1.0000	2	0.00	0.001	0.027
0.25	16	256	256	0.0100	1.0000	3	0.00	0.285	0.413
0.25	16	256	256	0.0100	0.0100	2	1.00	0.047	0.051
0.25	16	256	256	0.0100	0.0100	3	1.00	0.047	0.067
0.25	16	256	256	0.0100	0.0001	2	1.00	0.064	0.097
0.25	16	256	256	0.0100	0.0001	3	1.00	0.064	0.096
0.25	16	256	256	0.0001	1.0000	2	0.00	0.001	0.040
0.25	16	256	256	0.0001	1.0000	3	0.00	0.388	1.290
0.25	16	256	256	0.0001	0.0100	2	1.00	0.065	0.070
0.25	16	256	256	0.0001	0.0100	3	1.00	0.064	0.067
0.25	16 16	256 256	256 256	0.0001	0.0001	2	1.00	0.078	0.085 0.084
0.25	64	236	236	1.0000	1.00001	3	0.00	0.080	0.084
0.25	64	1	1	1.0000	1.0000	3	1.00	0.001	0.001
0.23	04	1	1	1.0000	1.0000		1.00	0.003	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	64	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	64	1	1	1.0000	0.0100	3	0.83	0.003	0.013
0.25	64	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	64	1	1	1.0000	0.0001	3	1.00	0.003	0.004
0.25	64	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	64	1	1	0.0100	1.0000	3	0.67	0.003	0.014
0.25	64	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	64	1	1	0.0100	0.0100	3	1.00 0.00	0.003	0.003
0.25	64	1	1	0.0100	0.0001	3	0.00	0.001	0.001
0.25	64	1	1	0.0001	1.0000	2	0.00	0.003	0.001
0.25	64	1	1	0.0001	1.0000	3	0.67	0.003	0.013
0.25	64	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	64	1	1	0.0001	0.0100	3	1.00	0.003	0.004
0.25	64	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	64	1	1	0.0001	0.0001	3	0.83	0.003	0.015
0.25	64	1	4	1.0000	1.0000	2	0.00 1.00	0.001	0.001
0.25	64	1	4	1.0000	1.0000 0.0100	3	0.00	0.003	0.005
0.25	64	1	4	1.0000	0.0100	3	1.00	0.001	0.001
0.25	64	1	4	1.0000	0.0001	2	0.00	0.003	0.003
0.25	64	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.25	64	1	4	0.0100	1.0000	2	0.17	0.001	0.003
0.25	64	1	4	0.0100	1.0000	3	0.33	0.003	0.019
0.25	64	1	4	0.0100	0.0100	2	0.67	0.001	0.004
0.25	64	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.25	64	1	4	0.0100	0.0001	2	1.00	0.003	0.003
0.25	64	1	4	0.0100	0.0001	3	1.00	0.003	0.003
0.25	64	1	4	0.0001	1.0000	3	0.17	0.001	0.003
0.25	64	1	4	0.0001	0.0100	2	0.83	0.003	0.020
0.25	64	1	4	0.0001	0.0100	3	1.00	0.003	0.003
0.25	64	1	4	0.0001	0.0001	2	1.00	0.003	0.003
0.25	64	1	4	0.0001	0.0001	3	1.00	0.003	0.003
0.25	64	1	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	64	1	16	1.0000	1.0000	3	0.17	0.006	0.023
0.25	64	1	16	1.0000	0.0100	2	0.33	0.001	0.004
0.25	64	1	16	1.0000	0.0100	3	1.00	0.004	0.036
0.25	64	1	16	1.0000	0.0001	2	1.00	0.004	0.005
0.25	64 64	1	16 16	1.0000 0.0100	1.0000	3	1.00 0.00	0.004	0.006
0.25	64	1	16	0.0100	1.0000	3	0.00	0.001	0.003
0.25	64	1	16	0.0100	0.0100	2	1.00	0.004	0.005
0.25	64	1	16	0.0100	0.0100	3	1.00	0.004	0.005
0.25	64	1	16	0.0100	0.0001	2	1.00	0.004	0.005
0.25	64	1	16	0.0100	0.0001	3	1.00	0.004	0.006
0.25	64	1	16	0.0001	1.0000	2	0.67	0.002	0.006
0.25	64	1	16	0.0001	1.0000	3	0.67	0.004	0.034
0.25	64	1	16	0.0001	0.0100	2	1.00	0.004	0.006
0.25	64	1	16 16	0.0001	0.0100	3	1.00	0.004	0.005
0.25	64	1	16	0.0001	0.0001	3	1.00	0.004	0.006
0.25	64	1	64	1.0000	1.0000	2	0.00	0.004	0.004
0.25	64	1	64	1.0000	1.0000	3	0.00	0.040	0.062
0.25	64	1	64	1.0000	0.0100	2	0.17	0.001	0.011
0.25	64	1	64	1.0000	0.0100	3	1.00	0.011	0.028
0.25	64	1	64	1.0000	0.0001	2	0.83	0.001	0.014
0.25	64	1	64	1.0000	0.0001	3	1.00	0.009	0.015
0.25	64	1	64	0.0100	1.0000	2	0.00	0.001	0.006
0.25	64	1	64	0.0100	1.0000	3	0.00	0.056	0.091
0.25	64	1	64	0.0100	0.0100	3	1.00	0.010	0.015 0.016
0.25	64	1	64	0.0100	0.0001	2	1.00	0.010	0.013
0.25	64	1	64	0.0100	0.0001	3	1.00	0.011	0.013
0.25	64	1	64	0.0001	1.0000	2	0.00	0.001	0.008
0.25	64	1	64	0.0001	1.0000	3	0.00	0.077	0.127
0.25	64	1	64	0.0001	0.0100	2	1.00	0.014	0.018
0.25	64	1	64	0.0001	0.0100	3	1.00	0.011	0.018
0.25	64	1	64	0.0001	0.0001	2	1.00	0.013	0.015
0.25	64	1	64	0.0001	0.0001	3	1.00	0.014	0.017
0.25	64	1	256	1.0000	1.0000	2	0.00	0.010	0.011
0.25	64 64	1	256 256	1.0000	1.0000 0.0100	3	0.00	0.173	0.216 0.050
0.25	64	1	256	1.0000	0.0100	3	0.50	0.001	0.030
0.25	64	1	256	1.0000	0.0001	2	1.00	0.040	0.777
0.25	64	1	256	1.0000	0.0001	3	1.00	0.061	0.074

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	64	1	256	0.0100	1.0000	2	0.00	0.017	0.025
0.25	64	1	256	0.0100	1.0000	3	0.00	0.284	0.396
0.25	64	1	256	0.0100	0.0100	2	1.00	0.053	0.077
0.25	64	1	256	0.0100	0.0100	3	1.00	0.053	0.075
0.25	64	1	256 256	0.0100	0.0001	3	1.00	0.060	0.105 0.087
0.25	64	1	256	0.0100	1.0000	2	0.00	0.000	0.040
0.25	64	1	256	0.0001	1.0000	3	0.00	0.412	0.656
0.25	64	1	256	0.0001	0.0100	2	1.00	0.060	0.066
0.25	64	1	256	0.0001	0.0100	3	1.00	0.060	0.066
0.25	64	1	256	0.0001	0.0001	2	1.00	0.078	0.125
0.25	64	1	256	0.0001	0.0001	3	1.00	0.079	0.126
0.25	64	4	1	1.0000	1.0000	3	0.00	0.001	0.001
0.25	64	4	1	1.0000	0.0100	2	0.83	0.003	0.001
0.25	64	4	1	1.0000	0.0100	3	1.00	0.003	0.007
0.25	64	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	64	4	1	1.0000	0.0001	3	1.00	0.003	0.004
0.25	64	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	64	4	1	0.0100	1.0000	3	1.00	0.003	0.004
0.25	64	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	64	4	1	0.0100	0.0100	3	1.00 0.00	0.003	0.015
0.25	64	4	1	0.0100	0.0001	3	0.00	0.001	0.001
0.25	64	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	64	4	1	0.0001	1.0000	3	0.83	0.003	0.016
0.25	64	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	64	4	1	0.0001	0.0100	3	0.83	0.003	0.017
0.25	64	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	64	4	1 4	0.0001 1.0000	1.0000	3	0.50	0.003	0.016
0.25	64	4	4	1.0000	1.0000	3	0.83	0.001	0.002
0.25	64	4	4	1.0000	0.0100	2	0.33	0.001	0.003
0.25	64	4	4	1.0000	0.0100	3	1.00	0.003	0.006
0.25	64	4	4	1.0000	0.0001	2	0.17	0.001	0.003
0.25	64	4	4	1.0000	0.0001	3	1.00	0.003	0.006
0.25	64	4	4	0.0100	1.0000	2	0.17	0.001	0.003
0.25	64	4	4	0.0100	1.0000 0.0100	3	0.50	0.003	0.018
0.25	64	4	4	0.0100	0.0100	3	1.00	0.001	0.004
0.25	64	4	4	0.0100	0.0001	2	0.83	0.001	0.004
0.25	64	4	4	0.0100	0.0001	3	1.00	0.003	0.004
0.25	64	4	4	0.0001	1.0000	2	0.67	0.001	0.003
0.25	64	4	4	0.0001	1.0000	3	0.83	0.003	0.018
0.25	64	4	4	0.0001	0.0100	2	0.83	0.001	0.004
0.25	64	4	4	0.0001	0.0100	3	1.00 0.67	0.003	0.003
0.25	64	4	4	0.0001	0.0001	3	1.00	0.001	0.003
0.25	64	4	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	64	4	16	1.0000	1.0000	3	0.33	0.003	0.024
0.25	64	4	16	1.0000	0.0100	2	0.50	0.001	0.005
0.25	64	4	16	1.0000	0.0100	3	1.00	0.005	0.009
0.25	64	4	16	1.0000	0.0001	2	0.83	0.001	0.006
0.25	64	4	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.006	0.013
0.25	64	4	16	0.0100	1.0000	3	0.00	0.001	0.003
0.25	64	4	16	0.0100	0.0100	2	1.00	0.004	0.006
0.25	64	4	16	0.0100	0.0100	3	1.00	0.004	0.006
0.25	64	4	16	0.0100	0.0001	2	1.00	0.006	0.006
0.25	64	4	16	0.0100	0.0001	3	1.00	0.006	0.006
0.25	64	4	16 16	0.0001	1.0000	3	0.33	0.001	0.005 0.040
0.25	64	4	16	0.0001	0.0100	2	1.00	0.004	0.040
0.25	64	4	16	0.0001	0.0100	3	1.00	0.004	0.006
0.25	64	4	16	0.0001	0.0001	2	1.00	0.005	0.006
0.25	64	4	16	0.0001	0.0001	3	1.00	0.005	0.006
0.25	64	4	64	1.0000	1.0000	2	0.00	0.003	0.004
0.25	64	4	64	1.0000	1.0000	3	0.00	0.044	0.057
		4	64	1.0000	0.0100	3	0.50 1.00	0.001	0.009
0.25	64		6/						
0.25	64	4	64		0.0001	2.	1.00	0.009	0.010
0.25			64 64 64	1.0000	0.0001	3	1.00	0.009	0.010
0.25 0.25 0.25	64 64	4	64	1.0000					
0.25 0.25 0.25 0.25 0.25 0.25	64 64 64 64	4 4 4 4	64 64 64 64	1.0000 1.0000 0.0100 0.0100	0.0001 1.0000 1.0000	3 2 3	1.00 0.00 0.00	0.009 0.001 0.061	0.011 0.006 0.082
0.25 0.25 0.25 0.25 0.25	64 64 64 64	4 4 4 4	64 64 64	1.0000 1.0000 0.0100	0.0001 1.0000	3 2	1.00	0.009 0.001	0.011 0.006

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	64	4	64	0.0100	0.0001	2	1.00	0.011	0.058
0.25	64	4	64	0.0100	0.0001	3	1.00	0.012	0.018
0.25	64	4	64	0.0001	1.0000	2	0.00	0.001	0.008
0.25	64	4	64	0.0001	1.0000	3	0.17	0.011	0.127
0.25	64	4	64	0.0001	0.0100	2	1.00	0.011	0.013
0.25	64	4	64	0.0001	0.0100	3	1.00	0.012	0.014
0.25	64	4	64	0.0001	0.0001	2	1.00	0.014	0.016
0.25	64	4	64	0.0001	0.0001	3	1.00	0.014	0.019
0.25	64	4	256	1.0000	1.0000	2	0.00	0.011	0.017
0.25	64	4	256	1.0000	1.0000	3	0.00	0.187	0.937
0.25	64	4	256 256	1.0000	0.0100	3	0.50 1.00	0.001	0.051
0.25	64	4	256	1.0000	0.0001	2	1.00	0.033	0.033
0.25	64	4	256	1.0000	0.0001	3	1.00	0.060	0.074
0.25	64	4	256	0.0100	1.0000	2	0.00	0.017	0.020
0.25	64	4	256	0.0100	1.0000	3	0.00	0.286	0.905
0.25	64	4	256	0.0100	0.0100	2	1.00	0.049	0.080
0.25	64	4	256	0.0100	0.0100	3	1.00	0.053	0.079
0.25	64	4	256	0.0100	0.0001	2	1.00	0.064	0.098
0.25	64	4	256	0.0100	0.0001	3	1.00	0.063	0.097
0.25	64	4	256	0.0001	1.0000	2	0.00	0.026	0.040
0.25	64	4	256	0.0001	1.0000	3	0.00	0.415	1.481
0.25	64	4	256 256	0.0001	0.0100	3	1.00	0.060	0.099
0.25	64	4	256	0.0001	0.0100	2	1.00	0.060	0.099
0.25	64	4	256	0.0001	0.0001	3	1.00	0.077	0.122
0.25	64	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	64	16	1	1.0000	1.0000	3	0.67	0.001	0.001
0.25	64	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	64	16	1	1.0000	0.0100	3	0.83	0.003	0.016
0.25	64	16	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	64	16	1	1.0000	0.0001	3	1.00	0.003	0.009
0.25	64	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	64	16	1	0.0100	1.0000	3	0.83	0.003	0.016
0.25	64	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	64	16	1	0.0100	0.0100	3	1.00 0.00	0.004	0.007
0.25	64	16 16	1	0.0100	0.0001	3	0.67	0.001	0.001
0.25	64	16	1	0.0100	1.0000	2	0.07	0.004	0.017
0.25	64	16	1	0.0001	1.0000	3	1.00	0.003	0.007
0.25	64	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	64	16	1	0.0001	0.0100	3	0.83	0.003	0.015
0.25	64	16	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	64	16	1	0.0001	0.0001	3	1.00	0.003	0.005
0.25	64	16	4	1.0000	1.0000	2	0.00	0.001	0.002
0.25	64	16	4	1.0000	1.0000	3	0.50	0.003	0.017
0.25	64	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.25	64	16	4	1.0000	0.0100	3	1.00	0.003	0.007
0.25	64	16 16	4	1.0000	0.0001	3	0.50 1.00	0.001	0.004
0.25	64	16	4	0.0100	1.0000	2	0.17	0.003	0.007
0.25	64	16	4	0.0100	1.0000	3	0.17	0.001	0.003
0.25	64	16	4	0.0100	0.0100	2	0.67	0.003	0.004
0.25	64	16	4	0.0100	0.0100	3	1.00	0.003	0.004
0.25	64	16	4	0.0100	0.0001	2	0.83	0.001	0.004
0.25	64	16	4	0.0100	0.0001	3	1.00	0.003	0.004
0.25	64	16	4	0.0001	1.0000	2	0.33	0.001	0.003
0.25	64	16	4	0.0001	1.0000	3	0.83	0.003	0.020
0.25	64	16	4	0.0001	0.0100	2	0.50	0.001	0.003
0.25	64	16	4	0.0001	0.0100	3	1.00	0.003	0.008
0.25	64	16 16	4	0.0001	0.0001	2	1.00	0.003 0.003	0.004
0.25	64	16	16	1.0000	1.0000	3	0.00	0.003	0.004
0.25	64	16	16	1.0000	1.0000	3	0.00	0.001	0.002
0.25	64	16	16	1.0000	0.0100	2	0.55	0.003	0.023
0.25	64	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	64	16	16	1.0000	0.0001	2	0.67	0.001	0.005
0.25	64	16	16	1.0000	0.0001	3	1.00	0.004	0.005
0.25	64	16	16	0.0100	1.0000	2	0.00	0.001	0.002
0.25	64	16	16	0.0100	1.0000	3	0.33	0.004	0.029
0.25	64	16	16	0.0100	0.0100	2	0.83	0.001	0.005
0.25	64	16	16	0.0100	0.0100	3	1.00	0.004	0.006
0.25	64	16	16	0.0100	0.0001	2	0.83	0.001	0.006
0.25	64	16	16	0.0100	0.0001	3	1.00	0.004	0.006
0.25	64	16 16	16 16	0.0001	1.0000	2	0.50	0.001	0.006
0.25	64					1	U 0 /		

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	64	16	16	0.0001	0.0100	2	1.00	0.004	0.006
0.25	64	16	16	0.0001	0.0100	3	1.00	0.004	0.006
0.25	64	16	16	0.0001	0.0001	2	1.00	0.005	0.006
0.25	64	16	16	0.0001	0.0001	3	1.00	0.005	0.007
0.25	64	16	64	1.0000	1.0000	2	0.00	0.001	0.005
0.25	64	16	64	1.0000	1.0000	3	0.00	0.043	0.622
0.25	64	16	64	1.0000	0.0100	2	0.67	0.001	0.009
0.25	64	16 16	64	1.0000	0.0100	3	1.00 0.83	0.007	0.008
0.25	64	16	64	1.0000	0.0001	3	1.00	0.001	0.012
0.25	64	16	64	0.0100	1.0000	2	0.00	0.001	0.006
0.25	64	16	64	0.0100	1.0000	3	0.33	0.011	0.090
0.25	64	16	64	0.0100	0.0100	2	1.00	0.009	0.012
0.25	64	16	64	0.0100	0.0100	3	1.00	0.010	0.011
0.25	64	16	64	0.0100	0.0001	2	1.00	0.011	0.014
0.25	64	16 16	64	0.0100	1.0000	3	0.00	0.010	0.014
0.25	64	16	64	0.0001	1.0000	3	0.00	0.000	0.007
0.25	64	16	64	0.0001	0.0100	2	1.00	0.016	0.018
0.25	64	16	64	0.0001	0.0100	3	1.00	0.011	0.019
0.25	64	16	64	0.0001	0.0001	2	1.00	0.016	0.017
0.25	64	16	64	0.0001	0.0001	3	1.00	0.014	0.015
0.25	64	16	256	1.0000	1.0000	2	0.00	0.011	0.013
0.25	64	16	256	1.0000	1.0000	3	0.00	0.180	0.194
0.25	64	16 16	256 256	1.0000	0.0100	3	0.50 1.00	0.001	0.033
0.25	64	16	256	1.0000	0.0100	2	1.00	0.033	0.066
0.25	64	16	256	1.0000	0.0001	3	1.00	0.046	0.059
0.25	64	16	256	0.0100	1.0000	2	0.00	0.018	0.029
0.25	64	16	256	0.0100	1.0000	3	0.00	0.287	0.415
0.25	64	16	256	0.0100	0.0100	2	1.00	0.046	0.050
0.25	64	16	256	0.0100	0.0100	3	1.00	0.047	0.053
0.25	64	16 16	256 256	0.0100	0.0001	2	1.00	0.096	0.098
0.25	64	16	256	0.0100	1.0000	2	0.00	0.083	0.098
0.25	64	16	256	0.0001	1.0000	3	0.00	0.424	2.008
0.25	64	16	256	0.0001	0.0100	2	1.00	0.060	0.093
0.25	64	16	256	0.0001	0.0100	3	1.00	0.058	0.097
0.25	64	16	256	0.0001	0.0001	2	1.00	0.077	0.110
0.25	64	16	256	0.0001	0.0001	3	1.00	0.076	0.126
0.25	64	64 64	1	1.0000	1.0000	3	0.00	0.001	0.001
0.25	64	64	1	1.0000	1.0000 0.0100	2	0.00	0.003	0.008
0.25	64	64	1	1.0000	0.0100	3	1.00	0.003	0.001
0.25	64	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	64	64	1	1.0000	0.0001	3	1.00	0.003	0.008
0.25	64	64	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	64	64	1	0.0100	1.0000	3	1.00	0.003	0.005
0.25	64	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	64	64	1	0.0100	0.0100	3	0.83	0.003	0.016
0.25	64	64	1	0.0100	0.0001	3	1.00	0.001	0.001
0.25	64	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	64	64	1	0.0001	1.0000	3	0.83	0.003	0.014
0.25	64	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	64	64	1	0.0001	0.0100	3	0.83	0.003	0.013
0.25	64	64 64	1	0.0001	0.0001	3	0.00 1.00	0.001	0.001
0.25	64	64	4	1.0000	1.0000	2	0.00	0.003	0.001
0.25	64	64	4	1.0000	1.0000	3	1.00	0.003	0.001
0.25	64	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.25	64	64	4	1.0000	0.0100	3	1.00	0.003	0.007
0.25	64	64	4	1.0000	0.0001	2	0.17	0.001	0.003
0.25	64	64	4	1.0000	0.0001	3	1.00	0.003	0.003
0.25	64	64	4	0.0100	1.0000	3	0.17	0.001	0.003
0.25	64	64	4	0.0100	0.0100	2	0.83	0.003	0.016
0.25	64	64	4	0.0100	0.0100	3	1.00	0.001	0.004
0.25	64	64	4	0.0100	0.0001	2	0.67	0.001	0.004
0.25	64	64	4	0.0100	0.0001	3	1.00	0.004	0.007
0.25	64	64	4	0.0001	1.0000	2	0.50	0.001	0.004
0.25	64	64	4	0.0001	1.0000	3	1.00	0.004	0.004
0.25	64	64	4	0.0001	0.0100	2	0.83	0.001	0.004
0.25	64	64	4	0.0001	0.0100	3	1.00 0.50	0.004	0.004
0.25	64	64	4	0.0001	0.0001	3	1.00	0.001	0.004
0.23	04	J-4		0.0001	0.0001		1.00	0.004	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	64	64	16	1.0000	1.0000	2	0.00	0.001	0.003
0.25	64	64	16	1.0000	1.0000	3	0.67	0.004	0.032
0.25	64	64	16	1.0000	0.0100	2	0.33	0.001	0.005
0.25	64	64	16	1.0000	0.0100	3	1.00	0.005	0.005
0.25	64	64	16	1.0000	0.0001	2	1.00	0.006	0.006
0.25	64	64	16	1.0000	0.0001	3	1.00	0.006	0.006
0.25	64	64	16	0.0100	1.0000	2	0.00	0.001	0.003
0.25	64	64	16	0.0100	1.0000	3	0.33	0.006	0.038
0.25	64	64	16	0.0100	0.0100	2	1.00	0.004	0.006
0.25	64	64	16	0.0100	0.0100	2	1.00	0.004	0.006
0.25	64	64	16 16	0.0100	0.0001	3	0.83 1.00	0.001	0.006
0.25	64	64	16	0.0001	1.0000	2	0.33	0.000	0.005
0.25	64	64	16	0.0001	1.0000	3	0.67	0.001	0.003
0.25	64	64	16	0.0001	0.0100	2	1.00	0.006	0.007
0.25	64	64	16	0.0001	0.0100	3	1.00	0.006	0.006
0.25	64	64	16	0.0001	0.0001	2	1.00	0.006	0.007
0.25	64	64	16	0.0001	0.0001	3	1.00	0.007	0.007
0.25	64	64	64	1.0000	1.0000	2	0.00	0.001	0.004
0.25	64	64	64	1.0000	1.0000	3	0.33	0.008	0.065
0.25	64	64	64	1.0000	0.0100	2	0.33	0.001	0.011
0.25	64	64	64	1.0000	0.0100	3	1.00	0.008	0.012
0.25	64	64	64	1.0000	0.0001	3	1.00	0.010	0.010
0.25	64	64	64	0.0100	1.00001	2	0.00	0.010	0.011
0.25	64	64	64	0.0100	1.0000	3	0.00	0.001	0.001
0.25	64	64	64	0.0100	0.0100	2	1.00	0.008	0.039
0.25	64	64	64	0.0100	0.0100	3	1.00	0.009	0.011
0.25	64	64	64	0.0100	0.0001	2	1.00	0.011	0.018
0.25	64	64	64	0.0100	0.0001	3	1.00	0.011	0.018
0.25	64	64	64	0.0001	1.0000	2	0.33	0.001	0.013
0.25	64	64	64	0.0001	1.0000	3	0.33	0.011	0.117
0.25	64	64	64	0.0001	0.0100	2	1.00	0.011	0.019
0.25	64	64	64	0.0001	0.0100	3	1.00	0.011	0.018
0.25	64	64	64	0.0001	0.0001	2	1.00	0.014	0.022
0.25	64	64	64	0.0001	0.0001	3	1.00	0.016	0.021
0.25	64	64	256	1.0000	1.0000	2	0.00	0.001	0.017
0.25	64	64	256 256	1.0000	1.0000 0.0100	2	0.00	0.182	0.819
0.25	64	64	256	1.0000	0.0100	3	1.00	0.001	0.051
0.25	64	64	256	1.0000	0.0001	2	1.00	0.031	0.073
0.25	64	64	256	1.0000	0.0001	3	1.00	0.046	0.074
0.25	64	64	256	0.0100	1.0000	2	0.00	0.021	0.028
0.25	64	64	256	0.0100	1.0000	3	0.00	0.313	1.020
0.25	64	64	256	0.0100	0.0100	2	1.00	0.048	0.075
0.25	64	64	256	0.0100	0.0100	3	1.00	0.049	0.077
0.25	64	64	256	0.0100	0.0001	2	1.00	0.080	0.098
0.25	64	64	256	0.0100	0.0001	3	1.00	0.082	0.098
0.25	64	64	256	0.0001	1.0000	2	0.00	0.027	0.042
0.25	64	64	256	0.0001	1.0000	3	0.00	0.428	1.538
0.25	64	64	256 256	0.0001	0.0100	3	1.00	0.059	0.097
0.25	64	64	256	0.0001	0.0100	2	1.00	0.058	0.097 0.124
0.25	64	64	256	0.0001	0.0001	3	1.00	0.075	0.124
0.25	64	256	1	1.0000	1.0000	2	0.00	0.070	0.001
0.25	64	256	1	1.0000	1.0000	3	1.00	0.003	0.003
0.25	64	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	64	256	1	1.0000	0.0100	3	1.00	0.003	0.007
0.25	64	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	64	256	1	1.0000	0.0001	3	1.00	0.003	0.003
0.25	64	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	64	256	1	0.0100	1.0000	3	1.00	0.003	0.003
0.25	64	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	64	256 256	1	0.0100	0.0100	3	1.00 0.00	0.003	0.003
0.25	64	256	1	0.0100	0.0001	3	0.00	0.001	0.001
0.25	64	256	1	0.0100	1.00001	2	0.83	0.003	0.014
0.25	64	256	1	0.0001	1.0000	3	1.00	0.001	0.001
0.25	64	256	1	0.0001	0.0100	2	0.00	0.003	0.003
0.25	64	256	1	0.0001	0.0100	3	0.83	0.003	0.014
0.25	64	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	64	256	1	0.0001	0.0001	3	1.00	0.003	0.003
0.25	64	256	4	1.0000	1.0000	2	0.00	0.001	0.002
0.25	64	256	4	1.0000	1.0000	3	0.83	0.003	0.015
	(1	256	4	1.0000	0.0100	2	0.33	0.001	0.003
0.25	64	256	4	1.0000	0.0100	3	1.00	0.003	0.004

mul	m_1	m_2	τ	TR	DTR	alg	SR	mint	maxt
			- ' '						
0.25	64	256 256	4	1.0000	0.0001	2	0.67	0.001	0.003
0.25	64	256	4	0.0100	1.00001	3	1.00 0.33	0.003	0.004
0.25	64		4	0.0100	1.0000	3			
0.25	64	256 256	4	0.0100	0.0100	2	0.33	0.003	0.019
0.25	64	256	4	0.0100	0.0100	3	1.00	0.001	0.003
0.25	64	256	4	0.0100	0.0001	2	0.67	0.003	0.004
0.25	64	256	4	0.0100	0.0001	3	1.00	0.001	0.004
0.25	64	256	4	0.0001	1.0000	2	0.50	0.003	0.003
0.25	64	256	4	0.0001	1.0000	3	1.00	0.001	0.003
0.25	64	256	4	0.0001	0.0100	2	0.83	0.003	0.004
0.25	64	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.25	64	256	4	0.0001	0.0001	2	0.83	0.001	0.004
0.25	64	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	64	256	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	64	256	16	1.0000	1.0000	3	0.67	0.003	0.026
0.25	64	256	16	1.0000	0.0100	2	0.50	0.001	0.004
0.25	64	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	64	256	16	1.0000	0.0001	2	1.00	0.004	0.006
0.25	64	256	16	1.0000	0.0001	3	1.00	0.004	0.006
0.25	64	256	16	0.0100	1.0000	2	0.17	0.001	0.004
0.25	64	256	16	0.0100	1.0000	3	0.50	0.004	0.028
0.25	64	256	16	0.0100	0.0100	2	0.83	0.001	0.005
0.25	64	256	16	0.0100	0.0100	3	1.00	0.004	0.006
0.25	64	256	16	0.0100	0.0001	2	0.83	0.001	0.005
0.25	64	256	16	0.0100	0.0001	3	1.00	0.004	0.005
0.25	64	256	16	0.0001	1.0000	2	0.17	0.001	0.004
0.25	64	256	16	0.0001	1.0000	3	0.17	0.006	0.043
0.25	64	256	16	0.0001	0.0100	2	1.00	0.006	0.010
0.25	64	256	16	0.0001	0.0100	3	1.00	0.006	0.010
0.25	64	256	16	0.0001	0.0001	2	1.00	0.006	0.007
0.25	64	256	16	0.0001	0.0001	3	1.00	0.006	0.007
0.25	64	256	64	1.0000	1.0000	2	0.00	0.001	0.004
0.25	64	256	64	1.0000	1.0000	3	0.17	0.006	0.293
0.25	64	256	64	1.0000	0.0100	2	0.17	0.001	0.008
0.25	64	256	64	1.0000	0.0100	3	1.00	0.008	0.009
0.25	64	256	64	1.0000	0.0001	2	0.67	0.001	0.011
0.25	64	256	64	1.0000	0.0001	3	1.00	0.011	0.011
0.25	64	256	64	0.0100	1.0000	2	0.00	0.001	0.005
0.25	64	256	64	0.0100	1.0000	3	0.33	0.008	0.067
0.25	64	256	64	0.0100	0.0100	2	0.83	0.001	0.012
0.25	64	256	64	0.0100	0.0100	3	1.00	0.010	0.012
0.25	64	256	64	0.0100	0.0001	2	1.00	0.012	0.018
0.25	64	256	64	0.0100	0.0001	3	1.00	0.011	0.018
0.25	64	256	64	0.0001	1.0000	2	0.00	0.001	0.007
0.25	64	256	64	0.0001	1.0000	3	0.00	0.084	0.091
0.25	64	256	64	0.0001	0.0100	2	1.00	0.012	0.015
0.25	64	256	64	0.0001	0.0100	3	1.00	0.012	0.014
0.25	64	256	64	0.0001	0.0001	2	1.00	0.013	0.016
0.25	64	256	64	0.0001	0.0001	3	1.00	0.013	0.016
0.25	64	256	256	1.0000	1.0000	3	0.00	0.011	0.017
0		256	256	1.0000	1.0000	-	0.00	0.189	0.282
0.25	64	256	256	1.0000	0.0100	3	0.17	0.001	
0.25	64	256 256	256 256	1.0000	0.0100	2	1.00 0.83	0.036	0.056
0.25	64	256	256	1.0000	0.0001	3	1.00	0.001	0.673
0.25	64	256	256	0.0100	1.00001	2	0.00	0.047	0.026
0.25	64	256	256	0.0100	1.0000	3	0.00	0.302	0.026
0.25	64	256	256	0.0100	0.0100	2	1.00	0.302	0.388
0.25	64	256	256	0.0100	0.0100	3	1.00	0.047	0.050
0.25	64	256	256	0.0100	0.0100	2	1.00	0.047	0.030
0.25	64	256	256	0.0100	0.0001	3	1.00	0.064	0.080
0.25	64	256	256	0.0001	1.0000	2	0.00	0.004	0.037
0.25	64	256	256	0.0001	1.0000	3	0.00	0.463	1.520
0.25	64	256	256	0.0001	0.0100	2	1.00	0.061	0.093
0.25	64	256	256	0.0001	0.0100	3	1.00	0.061	0.091
0.25	64	256	256	0.0001	0.0001	2	1.00	0.074	0.106
0.25	64	256	256	0.0001	0.0001	3	1.00	0.075	0.102
0.25	256	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	1	1	1.0000	1.0000	3	0.67	0.003	0.014
0.25	256	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	256	1	1	1.0000	0.0100	3	1.00	0.003	0.004
0.25	256	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	256	1	1	1.0000	0.0001	3	1.00	0.004	0.004
0.25	256	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	256	1	1	0.0100	1.0000	3	0.83	0.003	0.016

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	256	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	256	1	1	0.0100	0.0100	3	0.67	0.003	0.016
0.25	256	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.25	256	1	1	0.0100	0.0001	3	0.83	0.003	0.271
0.25	256	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	256	1	1	0.0001	1.0000	3	0.50	0.003	0.680
0.25	256	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	256	1	1	0.0001	0.0100	3	0.83	0.004	0.016
0.25	256	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	256 256	1	1 4	0.0001	0.0001	2	1.00 0.00	0.004	0.004
0.25	256	1	4	1.0000	1.0000	3	0.50	0.001	0.001
0.25	256	1	4	1.0000	0.0100	2	0.33	0.004	0.018
0.25	256	1	4	1.0000	0.0100	3	1.00	0.003	0.004
0.25	256	1	4	1.0000	0.0001	2	0.33	0.001	0.004
0.25	256	1	4	1.0000	0.0001	3	1.00	0.004	0.004
0.25	256	1	4	0.0100	1.0000	2	0.00	0.001	0.002
0.25	256	1	4	0.0100	1.0000	3	0.67	0.004	0.023
0.25	256	1	4	0.0100	0.0100	2	0.83	0.001	0.004
0.25	256	1	4	0.0100	0.0100	3	1.00	0.004	0.004
0.25	256	1	4	0.0100	0.0001	2	0.50	0.001	0.004
0.25	256 256	1	4	0.0100	0.0001 1.0000	2	1.00 0.67	0.004	0.004
0.25	256	1	4	0.0001	1.0000	3	0.67	0.001	0.004
0.25	256	1	4	0.0001	0.0100	2	1.00	0.004	0.020
0.25	256	1	4	0.0001	0.0100	3	1.00	0.004	0.004
0.25	256	1	4	0.0001	0.0001	2	1.00	0.004	0.004
0.25	256	1	4	0.0001	0.0001	3	1.00	0.004	0.004
0.25	256	1	16	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	1	16	1.0000	1.0000	3	0.50	0.005	0.023
0.25	256	1	16	1.0000	0.0100	2	0.33	0.001	0.005
0.25	256	1	16	1.0000	0.0100	3	1.00	0.005	0.005
0.25	256	1	16	1.0000	0.0001	2	1.00	0.006	0.006
0.25	256	1	16	1.0000	0.0001	3	1.00	0.006	0.006
0.25	256 256	1	16 16	0.0100	1.0000	3	0.00	0.001	0.002
0.25	256	1	16	0.0100	1.0000 0.0100	2	0.83	0.004	0.029
0.25	256	1	16	0.0100	0.0100	3	1.00	0.001	0.003
0.25	256	1	16	0.0100	0.0001	2	0.67	0.004	0.006
0.25	256	1	16	0.0100	0.0001	3	1.00	0.005	0.007
0.25	256	1	16	0.0001	1.0000	2	0.33	0.001	0.006
0.25	256	1	16	0.0001	1.0000	3	0.50	0.006	0.043
0.25	256	1	16	0.0001	0.0100	2	1.00	0.006	0.007
0.25	256	1	16	0.0001	0.0100	3	1.00	0.006	0.006
0.25	256	1	16	0.0001	0.0001	2	1.00	0.006	0.008
0.25	256	1	16	0.0001	0.0001	3	1.00	0.006	0.008
0.25	256	1	64	1.0000	1.0000	2	0.00	0.001	0.004
0.25	256	1	64	1.0000	1.0000	3	0.33	0.014	0.061
0.25	256 256	1	64	1.0000	0.0100	3	0.50 1.00	0.001	0.009
0.25	256	1	64	1.0000	0.0100	2	0.83	0.008	0.013
0.25	256	1	64	1.0000	0.0001	3	1.00	0.001	0.011
0.25	256	1	64	0.0100	1.0000	2	0.00	0.001	0.004
0.25	256	1	64	0.0100	1.0000	3	0.50	0.012	0.061
0.25	256	1	64	0.0100	0.0100	2	1.00	0.010	0.011
0.25	256	1	64	0.0100	0.0100	3	1.00	0.010	0.011
0.25	256	1	64	0.0100	0.0001	2	1.00	0.012	0.018
0.25	256	1	64	0.0100	0.0001	3	1.00	0.012	0.018
0.25	256	1	64	0.0001	1.0000	2	0.17	0.001	0.017
0.25	256	1	64 64	0.0001	1.0000 0.0100	3	0.33	0.017	0.130
0.25	256 256	1	64	0.0001	0.0100	3	1.00	0.012	0.071 0.019
0.25	256	1	64	0.0001	0.0100	2	1.00	0.014	0.019
0.25	256	1	64	0.0001	0.0001	3	1.00	0.014	0.017
0.25	256	1	256	1.0000	1.0000	2	0.00	0.001	0.016
0.25	256	1	256	1.0000	1.0000	3	0.17	0.021	0.987
0.25	256	1	256	1.0000	0.0100	2	0.33	0.001	0.036
0.25	256	1	256	1.0000	0.0100	3	1.00	0.034	0.067
0.25	256	1	256	1.0000	0.0001	2	1.00	0.049	0.072
0.25	256	1	256	1.0000	0.0001	3	1.00	0.058	0.074
0.25	256	1	256	0.0100	1.0000	2	0.00	0.001	0.026
0.25	256	1	256	0.0100	1.0000	3	0.00	0.336	0.408
0.25	256	1	256	0.0100	0.0100	2	1.00	0.048	0.050
0.25	256	1	256	0.0100	0.0100	2	1.00	0.047	0.050
0.25	256 256	1	256 256	0.0100	0.0001	3	1.00	0.061	0.097 0.088
0.23	230	1	230	0.0100	0.0001	3	1.00	0.001	0.000

mul	m.	m -		TR	DTR	ala	SR	mint	movt
mul	m_1	m_2	\tau			alg		mint	maxt
0.25	256	1	256	0.0001	1.0000	2	0.00	0.025	0.029
0.25	256	1	256	0.0001	1.0000	3	0.00	0.421	0.448
0.25	256	1	256	0.0001	0.0100	2	1.00	0.061	0.102
0.25	256	1	256	0.0001	0.0100	3	1.00	0.066	0.102
0.25	256	1	256	0.0001	0.0001	2	1.00	0.082	0.128
0.25	256	1	256	0.0001	0.0001	3	1.00	0.079	0.124
0.25	256	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	4	1	1.0000	1.0000	3	0.67	0.003	0.092
0.25	256 256	4	1	1.0000	0.0100	3	0.00	0.001	0.001
0.25	256	4	1	1.0000	0.0100	2	1.00 0.00	0.003	0.004
0.25	256	4	1	1.0000	0.0001	3	1.00	0.001	0.001
0.25	256	4	1	0.0100	1.0000	2	0.00	0.004	0.003
0.25	256	4	1	0.0100	1.0000	3	0.50	0.001	0.001
0.25	256	4	1	0.0100	0.0100	2	0.00	0.003	0.001
0.25	256	4	1	0.0100	0.0100	3	1.00	0.003	0.005
0.25	256	4	1	0.0100	0.0001	2	0.00	0.003	0.003
0.25	256	4	1	0.0100	0.0001	3	0.67	0.003	0.014
0.25	256	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	256	4	1	0.0001	1.0000	3	0.83	0.003	0.001
0.25	256	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	256	4	1	0.0001	0.0100	3	1.00	0.003	0.003
0.25	256	4	1	0.0001	0.0001	2	0.00	0.003	0.003
0.25	256	4	1	0.0001	0.0001	3	0.83	0.003	0.013
0.25	256	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	4	4	1.0000	1.0000	3	0.83	0.003	0.014
0.25	256	4	4	1.0000	0.0100	2	0.67	0.001	0.003
0.25	256	4	4	1.0000	0.0100	3	0.83	0.003	0.014
0.25	256	4	4	1.0000	0.0001	2	0.33	0.001	0.003
0.25	256	4	4	1.0000	0.0001	3	1.00	0.003	0.003
0.25	256	4	4	0.0100	1.0000	2	0.17	0.001	0.003
0.25	256	4	4	0.0100	1.0000	3	0.50	0.003	0.019
0.25	256	4	4	0.0100	0.0100	2	0.50	0.001	0.003
0.25	256	4	4	0.0100	0.0100	3	1.00	0.003	0.005
0.25	256	4	4	0.0100	0.0001	2	0.67	0.001	0.004
0.25	256	4	4	0.0100	0.0001	3	1.00	0.003	0.003
0.25	256	4	4	0.0001	1.0000	2	1.00	0.003	0.003
0.25	256	4	4	0.0001	1.0000	3	1.00	0.003	0.003
0.25	256	4	4	0.0001	0.0100	2	0.50	0.001	0.003
0.25	256	4	4	0.0001	0.0100	3	1.00	0.003	0.006
0.25	256	4	4	0.0001	0.0001	2	0.67	0.001	0.003
0.25	256	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	256	4	16	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	4	16	1.0000	1.0000	3	0.67	0.004	0.020
0.25	256	4	16	1.0000	0.0100	2	0.50	0.001	0.004
0.25	256	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	256	4	16	1.0000	0.0001	2	0.83	0.001	0.005
0.25	256	4	16	1.0000	0.0001	3	1.00	0.004	0.005
0.25	256	4	16	0.0100	1.0000	2	0.00	0.001	0.002
0.25	256	4	16	0.0100	1.0000	3	0.67	0.004	0.027
0.25	256	4	16	0.0100	0.0100	2	0.67	0.001	0.005
0.25	256	4	16	0.0100	0.0100	3	1.00	0.004	0.009
0.25	256	4	16	0.0100	0.0001	2	1.00	0.005	0.007
0.25	256	4	16	0.0100	0.0001	3	1.00	0.005	0.007
0.25	256	4	16	0.0001	1.0000	2	0.50	0.001	0.006
0.25	256	4	16	0.0001	0.0100	3	0.67	0.005	
0.25	256 256	4	16 16	0.0001	0.0100	3	1.00	0.004	0.006
0.25	256	4	16	0.0001	0.0100	2	0.83	0.004	0.006
0.25	256	4	16	0.0001	0.0001	3	1.00	0.001	0.006
0.25	256	4	64	1.0000	1.00001	2	0.00	0.003	0.007
0.25	256	4	64	1.0000	1.0000	3	0.00	0.001	0.004
0.25	256	4	64	1.0000	0.0100	2	0.00	0.038	0.088
0.25	256	4	64	1.0000	0.0100	3	1.00	0.001	0.012
0.25	256	4	64	1.0000	0.0001	2	0.83	0.001	0.029
0.25	256	4	64	1.0000	0.0001	3	1.00	0.011	0.024
0.25	256	4	64	0.0100	1.0000	2	0.00	0.001	0.006
0.25	256	4	64	0.0100	1.0000	3	0.50	0.009	0.088
0.25	256	4	64	0.0100	0.0100	2	1.00	0.014	0.015
0.25	256	4	64	0.0100	0.0100	3	1.00	0.015	0.016
0.25	256	4	64	0.0100	0.0001	2	1.00	0.017	0.018
0.25	256	4	64	0.0100	0.0001	3	1.00	0.017	0.018
0.25	256	4	64	0.0001	1.0000	2	0.17	0.001	0.016
0.25	256	4	64	0.0001	1.0000	3	0.17	0.016	0.127
0.25	256	4	64	0.0001	0.0100	2	1.00	0.012	0.016
0.25	256	4	64	0.0001	0.0100	3	1.00	0.012	0.014

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	256	4	64	0.0001	0.0001	2	1.00	0.017	0.020
0.25	256	4	64	0.0001	0.0001	3	1.00	0.014	0.016
0.25	256	4	256	1.0000	1.0000	2	0.00	0.001	0.015
0.25	256	4	256	1.0000	1.0000 0.0100	2	0.00	0.201	1.675
0.25	256 256	4	256 256	1.0000	0.0100	3	0.67 1.00	0.001	0.053
0.25	256	4	256	1.0000	0.0100	2	0.83	0.038	0.093
0.25	256	4	256	1.0000	0.0001	3	1.00	0.059	0.073
0.25	256	4	256	0.0100	1.0000	2	0.00	0.001	0.027
0.25	256	4	256	0.0100	1.0000	3	0.00	0.264	0.805
0.25	256	4	256	0.0100	0.0100	2	1.00	0.049	0.070
0.25	256	4	256	0.0100	0.0100	3	1.00	0.049	0.075
0.25	256	4	256	0.0100	0.0001	2	1.00	0.077	0.094
0.25	256	4	256	0.0100	0.0001	3	1.00	0.079	0.094
0.25	256	4	256	0.0001	1.0000	2	0.00	0.001	0.040
0.25	256 256	4	256 256	0.0001	1.0000 0.0100	2	1.00	0.395	1.280 0.101
0.25	256	4	256	0.0001	0.0100	3	1.00	0.096	0.101
0.25	256	4	256	0.0001	0.0001	2	1.00	0.075	0.100
0.25	256	4	256	0.0001	0.0001	3	1.00	0.076	0.127
0.25	256	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	16	1	1.0000	1.0000	3	0.33	0.003	0.031
0.25	256	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.25	256	16	1	1.0000	0.0100	3	1.00	0.003	0.011
0.25	256	16	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	256	16	1	1.0000	0.0001	3	1.00	0.003	0.008
0.25	256	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.25	256	16	1	0.0100	1.0000	3	0.50	0.003	0.016
0.25	256 256	16 16	1	0.0100	0.0100	2	1.00	0.001	0.001
0.25	256	16	1	0.0100	0.0100	3	0.00	0.003	0.006
0.25	256	16	1	0.0100	0.0001	3	0.83	0.001	0.001
0.25	256	16	1	0.0100	1.0000	2	0.00	0.003	0.001
0.25	256	16	1	0.0001	1.0000	3	0.67	0.003	0.014
0.25	256	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	256	16	1	0.0001	0.0100	3	0.83	0.003	0.014
0.25	256	16	1	0.0001	0.0001	2	0.00	0.001	0.001
0.25	256	16	1	0.0001	0.0001	3	1.00	0.003	0.006
0.25	256	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	16	4	1.0000	1.0000	3	0.67	0.003	0.015
0.25	256	16	4	1.0000	0.0100	2	0.17	0.001	0.003
0.25	256	16	4	1.0000	0.0100	3	1.00	0.003	0.006
0.25	256	16	4	1.0000	0.0001	2	0.50	0.001	0.004
0.25	256 256	16 16	4	1.0000 0.0100	0.0001 1.0000	2	1.00 0.50	0.004	0.004
0.25	256	16	4	0.0100	1.0000	3	0.83	0.001	0.004
0.25	256	16	4	0.0100	0.0100	2	0.50	0.003	0.019
0.25	256	16	4	0.0100	0.0100	3	1.00	0.004	0.004
0.25	256	16	4	0.0100	0.0001	2	0.50	0.001	0.004
0.25	256	16	4	0.0100	0.0001	3	1.00	0.004	0.004
0.25	256	16	4	0.0001	1.0000	2	0.33	0.001	0.004
0.25	256	16	4	0.0001	1.0000	3	0.50	0.004	0.025
0.25	256	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.25	256	16	4	0.0001	0.0100	3	1.00	0.004	0.004
0.25	256	16	4	0.0001	0.0001	2	1.00	0.004	0.004
0.25	256	16	4	0.0001	0.0001	3	1.00	0.004	0.004
0.25	256	16	16	1.0000	1.0000	2	0.00	0.001	0.002
0.25	256 256	16 16	16 16	1.0000	1.0000 0.0100	2	0.33	0.004	0.027
0.25	256	16	16	1.0000	0.0100	3	1.00	0.001	0.003
0.25	256	16	16	1.0000	0.0100	2	0.67	0.004	0.005
0.25	256	16	16	1.0000	0.0001	3	1.00	0.001	0.003
0.25	256	16	16	0.0100	1.0000	2	0.00	0.001	0.002
0.25	256	16	16	0.0100	1.0000	3	0.33	0.007	0.033
0.25	256	16	16	0.0100	0.0100	2	0.83	0.001	0.006
0.25	256	16	16	0.0100	0.0100	3	1.00	0.005	0.009
0.25	256	16	16	0.0100	0.0001	2	1.00	0.006	0.006
0.25	256	16	16	0.0100	0.0001	3	1.00	0.006	0.007
0.25	256	16	16	0.0001	1.0000	2	0.17	0.001	0.006
0.25	256	16	16	0.0001	1.0000	3	0.67	0.006	0.487
0.25	256	16	16	0.0001	0.0100	2	1.00	0.006	0.007
0.25	256	16	16	0.0001	0.0100	3	1.00	0.006	0.007
0.25	256	16	16	0.0001	0.0001	2	1.00	0.007	0.008
0.25	256 256	16 16	16 64	0.0001 1.0000	1.00001	3	0.00	0.007	0.007
0.25	256	16	64	1.0000	1.0000	3	0.00	0.001	0.064
0.23	230	10	0+	1.0000	1.0000	J	0.55	0.000	0.004

mul	m_1	m_2	τ	TR	DTR	alg	SR	mint	maxt
0.25	256	16	64	1.0000	0.0100	2	0.50	0.001	0.011
0.25	256	16	64	1.0000	0.0100	3	1.00	0.011	0.071
0.25	256	16	64	1.0000	0.0001	2	0.83	0.001	0.016
0.25	256	16	64	1.0000	0.0001	3	1.00	0.011	0.016
0.25	256	16	64	0.0100	1.0000	2	0.00	0.001	0.006
0.25	256	16	64	0.0100	1.0000	3	0.33	0.010	0.091
0.25	256	16	64	0.0100	0.0100	2	1.00	0.009	0.011
0.25	256 256	16 16	64	0.0100	0.0100	3	1.00	0.009	0.011
0.25	256	16	64	0.0100	0.0001	3	1.00	0.011	0.012
0.25	256	16	64	0.0001	1.0000	2	0.00	0.001	0.006
0.25	256	16	64	0.0001	1.0000	3	0.17	0.010	0.094
0.25	256	16	64	0.0001	0.0100	2	1.00	0.012	0.018
0.25	256	16	64	0.0001	0.0100	3	1.00	0.012	0.018
0.25	256	16	64	0.0001	0.0001	2	1.00	0.022	0.023
0.25	256 256	16 16	256	0.0001 1.0000	0.0001 1.0000	3 2	1.00	0.018	0.023
0.25	256	16	256	1.0000	1.0000	3	0.00	0.001	0.016
0.25	256	16	256	1.0000	0.0100	2	0.83	0.001	0.051
0.25	256	16	256	1.0000	0.0100	3	1.00	0.037	0.051
0.25	256	16	256	1.0000	0.0001	2	1.00	0.047	0.074
0.25	256	16	256	1.0000	0.0001	3	1.00	0.047	0.075
0.25	256	16	256	0.0100	1.0000	2	0.00	0.001	0.027
0.25	256	16	256	0.0100	1.0000	3	0.00	0.284	0.405
0.25	256 256	16 16	256 256	0.0100	0.0100	3	1.00	0.055	0.079
0.25	256	16	256	0.0100	0.0100	2	1.00	0.057	0.080
0.25	256	16	256	0.0100	0.0001	3	1.00	0.058	0.098
0.25	256	16	256	0.0001	1.0000	2	0.17	0.001	0.079
0.25	256	16	256	0.0001	1.0000	3	0.17	0.078	0.659
0.25	256	16	256	0.0001	0.0100	2	1.00	0.061	0.087
0.25	256	16	256	0.0001	0.0100	3	1.00	0.061	0.079
0.25	256	16	256	0.0001	0.0001	2	1.00	0.078	0.112
0.25	256 256	16 64	256	0.0001 1.0000	0.0001 1.0000	3	1.00 0.17	0.078	0.088
0.25	256	64	1	1.0000	1.0000	3	0.17	0.001	0.003
0.25	256	64	1	1.0000	0.0100	2	0.00	0.003	0.001
0.25	256	64	1	1.0000	0.0100	3	1.00	0.003	0.006
0.25	256	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.25	256	64	1	1.0000	0.0001	3	1.00	0.003	0.007
0.25	256	64	1	0.0100	1.0000	2	0.17	0.001	0.003
0.25	256 256	64 64	1	0.0100	1.0000	3	1.00	0.003	0.005
0.25	256	64	1	0.0100	0.0100	3	0.00 1.00	0.001	0.001
0.25	256	64	1	0.0100	0.0001	2	0.00	0.003	0.003
0.25	256	64	1	0.0100	0.0001	3	0.67	0.004	0.017
0.25	256	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.25	256	64	1	0.0001	1.0000	3	0.50	0.006	0.016
0.25	256	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.25	256	64	1	0.0001	0.0100	3	0.83	0.003	0.017
0.25	256 256	64 64	1	0.0001	0.0001	3	1.00	0.001	0.001
0.25	256	64	4	1.0000	1.0000	2	0.00	0.003	0.008
0.25	256	64	4	1.0000	1.0000	3	0.83	0.003	0.022
0.25	256	64	4	1.0000	0.0100	2	0.17	0.001	0.003
0.25	256	64	4	1.0000	0.0100	3	1.00	0.003	0.008
0.25	256	64	4	1.0000	0.0001	2	0.50	0.001	0.004
0.25	256	64	4	1.0000	0.0001	3	1.00	0.004	0.009
0.25	256 256	64 64	4	0.0100	1.0000	3	0.00	0.001	0.002
0.25	256	64	4	0.0100	0.0100	2	0.83	0.004	0.020
0.25	256	64	4	0.0100	0.0100	3	1.00	0.001	0.004
0.25	256	64	4	0.0100	0.0001	2	0.83	0.001	0.004
0.25	256	64	4	0.0100	0.0001	3	1.00	0.004	0.004
0.25	256	64	4	0.0001	1.0000	2	0.33	0.001	0.004
0.25	256	64	4	0.0001	1.0000	3	0.83	0.003	0.023
0.25	256	64 64	4	0.0001	0.0100	2	0.67	0.001	0.004
0.25	256 256	64	4	0.0001	0.0100	3 2	1.00 0.83	0.003	0.008
0.25	256	64	4	0.0001	0.0001	3	1.00	0.001	0.004
0.25	256	64	16	1.0000	1.0000	2	0.00	0.004	0.007
0.25	256	64	16	1.0000	1.0000	3	0.67	0.004	0.032
0.25	256	64	16	1.0000	0.0100	2	0.33	0.001	0.005
0.25	256	64	16	1.0000	0.0100	3	1.00	0.004	0.010
	256	64	16	1.0000	0.0001	2	0.67	0.001	0.004
0.25	256	64	16	1.0000	0.0001	3	1.00	0.004	0.009

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	256	64	16	0.0100	1.0000	2	0.00	0.001	0.002
0.25	256	64	16	0.0100	1.0000	3	0.17	0.004	0.029
0.25	256	64	16	0.0100	0.0100	2	0.67	0.001	0.010
0.25	256	64	16	0.0100	0.0100	3	1.00	0.004	0.004
0.25	256	64	16	0.0100	0.0001	2	1.00	0.004	0.005
0.25	256	64	16	0.0100	0.0001	3	1.00	0.004	0.005
0.25	256 256	64	16 16	0.0001	1.0000	3	0.17	0.001	0.004
0.25	256	64	16	0.0001	0.0100	2	1.00	0.005	0.005
0.25	256	64	16	0.0001	0.0100	3	1.00	0.003	0.005
0.25	256	64	16	0.0001	0.0001	2	1.00	0.004	0.005
0.25	256	64	16	0.0001	0.0001	3	1.00	0.004	0.005
0.25	256	64	64	1.0000	1.0000	2	0.00	0.001	0.003
0.25	256	64	64	1.0000	1.0000	3	0.83	0.006	0.047
0.25	256	64	64	1.0000	0.0100	2	0.17	0.001	0.011
0.25	256	64	64	1.0000	0.0100	3	1.00	0.008	0.012
0.25	256 256	64	64	1.0000	0.0001	3	0.67 1.00	0.001	0.016 0.016
0.25	256	64	64	0.0100	1.0000	2	0.00	0.010	0.016
0.25	256	64	64	0.0100	1.0000	3	0.00	0.001	0.065
0.25	256	64	64	0.0100	0.0100	2	1.00	0.010	0.014
0.25	256	64	64	0.0100	0.0100	3	1.00	0.009	0.014
0.25	256	64	64	0.0100	0.0001	2	1.00	0.011	0.013
0.25	256	64	64	0.0100	0.0001	3	1.00	0.011	0.014
0.25	256	64	64	0.0001	1.0000	2	0.33	0.001	0.012
0.25	256	64	64	0.0001	1.0000	3	0.50	0.011	0.084
0.25	256	64	64	0.0001	0.0100	2	1.00	0.011	0.018
0.25	256	64	64	0.0001	0.0100	3	1.00	0.011	0.019
0.25	256 256	64	64	0.0001	0.0001	3	1.00	0.014	0.023
0.25	256	64	256	1.0000	1.0000	2	0.00	0.013	0.023
0.25	256	64	256	1.0000	1.0000	3	0.33	0.022	0.759
0.25	256	64	256	1.0000	0.0100	2	0.00	0.001	0.001
0.25	256	64	256	1.0000	0.0100	3	1.00	0.035	0.052
0.25	256	64	256	1.0000	0.0001	2	0.83	0.001	0.078
0.25	256	64	256	1.0000	0.0001	3	1.00	0.049	0.077
0.25	256	64	256	0.0100	1.0000	2	0.00	0.017	0.027
0.25	256	64	256	0.0100	1.0000	3	0.00	0.300	0.401
0.25	256	64	256	0.0100	0.0100	3	1.00	0.048	0.052
0.25	256 256	64 64	256 256	0.0100	0.0100	2	1.00	0.048	0.049
0.25	256	64	256	0.0100	0.0001	3	1.00	0.062	0.096
0.25	256	64	256	0.0001	1.0000	2	0.00	0.003	0.032
0.25	256	64	256	0.0001	1.0000	3	0.17	0.055	0.542
0.25	256	64	256	0.0001	0.0100	2	1.00	0.062	0.088
0.25	256	64	256	0.0001	0.0100	3	1.00	0.060	0.082
0.25	256	64	256	0.0001	0.0001	2	1.00	0.078	0.085
0.25	256	64	256	0.0001	0.0001	3	1.00	0.078	0.113
0.25	256	256	1	1.0000	1.0000	2	0.17	0.001	0.003
0.25	256	256 256	1	1.0000	1.0000	3	1.00	0.003	0.168
0.25	256 256	256	1	1.0000	0.0100	3	0.00 1.00	0.001	0.001
0.25	256	256	1	1.0000	0.0100	2	0.00	0.003	0.007
0.25	256	256	1	1.0000	0.0001	3	1.00	0.003	0.009
0.25	256	256	1	0.0100	1.0000	2	0.17	0.001	0.003
0.25	256	256	1	0.0100	1.0000	3	0.83	0.003	0.014
0.25	256	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.25	256	256	1	0.0100	0.0100	3	1.00	0.003	0.003
0.25	256	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.25	256	256	1	0.0100	0.0001	3	1.00	0.003	0.003
0.25	256 256	256 256	1	0.0001	1.0000	3	0.00 1.00	0.001	0.001
0.25	256	256	1	0.0001	0.0100	2	0.00	0.003	0.006
0.25	256	256	1	0.0001	0.0100	3	1.00	0.001	0.001
0.25	256	256	1	0.0001	0.0001	2	0.00	0.003	0.001
0.25	256	256	1	0.0001	0.0001	3	0.83	0.003	0.014
0.25	256	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	256	4	1.0000	1.0000	3	1.00	0.003	0.008
0.25	256	256	4	1.0000	0.0100	2	0.50	0.001	0.003
0.25	256	256	4	1.0000	0.0100	3	1.00	0.003	0.005
0.25	256	256	4	1.0000	0.0001	2	0.33	0.001	0.003
0.25	256	256	4	1.0000	0.0001	3	1.00	0.003	0.004
0.25	256 256	256 256	4	0.0100	1.0000	3	0.50	0.001	0.003
0.25	256	256	4	0.0100	0.0100	2	0.67	0.003	0.020
0.25	256	256	4	0.0100	0.0100	3	1.00	0.001	0.004
0.23	230	230	4	0.0100	0.0100	3	1.00	0.003	0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.25	256	256	4	0.0100	0.0001	2	0.67	0.001	0.003
0.25	256	256	4	0.0100	0.0001	3	1.00	0.003	0.003
0.25	256	256	4	0.0001	1.0000	2	0.33	0.003	0.004
			4						
0.25	256	256 256		0.0001	1.0000	3	1.00	0.003	0.004
0.25	256		4	0.0001	0.0100	2	0.83	0.001	0.004
0.25	256	256	4	0.0001	0.0100	3	1.00	0.003	0.003
0.25	256	256	4	0.0001	0.0001	2	1.00	0.003	0.004
0.25	256	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.25	256	256	16	1.0000	1.0000	2	0.00	0.001	0.001
0.25	256	256	16	1.0000	1.0000	3	0.67	0.003	0.024
0.25	256	256	16	1.0000	0.0100	2	0.17	0.001	0.005
0.25	256	256	16	1.0000	0.0100	3	1.00	0.004	0.005
0.25	256	256	16	1.0000	0.0001	2	0.50	0.001	0.006
0.25	256	256	16	1.0000	0.0001	3	1.00	0.006	0.007
0.25	256	256	16	0.0100	1.0000	2	0.17	0.001	0.004
0.25	256	256	16	0.0100	1.0000	3	0.67	0.004	0.029
0.25	256	256	16	0.0100	0.0100	2	1.00	0.004	0.029
0.25	256	256	16	0.0100	0.0100	3	1.00	0.004	0.006
0.25	256	256	16	0.0100	0.0001	2	0.83	0.001	0.005
0.25	256	256	16	0.0100	0.0001	3	1.00	0.005	0.006
0.25	256	256	16	0.0001	1.0000	2	0.50	0.001	0.005
0.25	256	256	16	0.0001	1.0000	3	1.00	0.004	0.005
0.25	256	256	16	0.0001	0.0100	2	1.00	0.005	0.005
0.25	256	256	16	0.0001	0.0100	3	1.00	0.005	0.005
0.25	256	256	16	0.0001	0.0001	2	1.00	0.005	0.005
0.25	256	256	16	0.0001	0.0001	3	1.00	0.005	0.006
0.25	256	256	64	1.0000	1.0000	2	0.00	0.003	0.001
0.25	256	256	64	1.0000	1.0000	3	0.67	0.006	0.046
0.25	256	256	64	1.0000	0.0100	2	0.00	0.000	0.001
0.25	256	256	64	1.0000	0.0100	3	1.00		
								0.008	0.009
0.25	256	256	64	1.0000	0.0001	2	0.83	0.001	0.011
0.25	256	256	64	1.0000	0.0001	3	1.00	0.010	0.011
0.25	256	256	64	0.0100	1.0000	2	0.00	0.001	0.001
0.25	256	256	64	0.0100	1.0000	3	0.83	0.008	0.060
0.25	256	256	64	0.0100	0.0100	2	1.00	0.009	0.011
0.25	256	256	64	0.0100	0.0100	3	1.00	0.010	0.011
0.25	256	256	64	0.0100	0.0001	2	1.00	0.012	0.018
0.25	256	256	64	0.0100	0.0001	3	1.00	0.012	0.017
0.25	256	256	64	0.0001	1.0000	2	1.00	0.010	0.012
0.25	256	256	64	0.0001	1.0000	3	1.00	0.010	0.012
0.25	256	256	64	0.0001	0.0100	2	1.00	0.012	0.014
0.25	256	256	64	0.0001	0.0100	3	1.00	0.012	0.014
0.25	256	256	64	0.0001	0.0001	2	1.00	0.012	0.014
			64						
0.25	256	256		0.0001	0.0001	3	1.00	0.014	0.016
0.25	256	256	256	1.0000	1.0000	2	0.00	0.001	0.013
0.25	256	256	256	1.0000	1.0000	3	0.33	0.024	0.193
0.25	256	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.25	256	256	256	1.0000	0.0100	3	1.00	0.037	0.054
0.25	256	256	256	1.0000	0.0001	2	0.83	0.001	0.079
0.25	256	256	256	1.0000	0.0001	3	1.00	0.050	0.079
0.25	256	256	256	0.0100	1.0000	2	0.00	0.001	0.020
0.25	256	256	256	0.0100	1.0000	3	0.17	0.040	0.991
0.25	256	256	256	0.0100	0.0100	2	1.00	0.051	0.055
0.25	256	256	256	0.0100	0.0100	3	1.00	0.052	0.065
0.25	256	256	256	0.0100	0.0001	2	1.00	0.064	0.067
0.25	256	256	256	0.0100	0.0001	3	1.00	0.064	0.068
0.25	256	256	256	0.0001	1.0000	2	0.33	0.004	0.060
0.25	256	256	256	0.0001	1.0000	3	0.33	0.001	0.766
0.25	256	256	256	0.0001	0.0100	2	1.00	0.064	0.069
0.25	256	256	256	0.0001	0.0100	3	1.00	0.064	0.068
0.25	256	256	256	0.0001	0.0001	2	1.00	0.083	0.117
0.25	256	256	256	0.0001	0.0001	3	1.00	0.076	0.106
0.33	1	1	1	1.0000	1.0000	2	0.33	0.001	0.003
0.33	1	1	1	1.0000	1.0000	3	0.83	0.003	0.013
0.33	1	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	1	1	1.0000	0.0100	3	0.83	0.004	0.013
0.33	1	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	1	1	1	1.0000	0.0001	3	0.67	0.006	0.013
0.33	1	1	1	0.0100	1.0000	2	0.50	0.000	0.003
0.33	1	1	1	0.0100	1.0000	3	0.83	0.001	0.003
0.33	1	1	1	0.0100	0.0100	2	0.00	0.003	0.013
0.33	1	1	1	0.0100	0.0100	3	0.83	0.005	0.013
0.33	1	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	1	1	1	0.0100	0.0001	3	0.67	0.007	0.014
0.33	1	1	1	0.0001	1.0000	2	0.83	0.001	0.003
0.33	1	1	1	0.0001	1.0000	3	1.00	0.003	0.007
								_	

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	1	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	1	1	1	0.0001	0.0100	3	0.83	0.004	0.014
0.33	1	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	1	1	1	0.0001	0.0001	3	1.00	0.004	0.010
0.33	1	1	4	1.0000	1.0000	2	0.00	0.002	0.002
0.33	1	1	4	1.0000	1.0000	3	0.00	0.018	0.020
0.33	1	1	4	1.0000	0.0100	2	0.83	0.001	0.004
0.33	1	1	4	1.0000	0.0100	3	1.00	0.003	0.009
0.33	1	1	4	1.0000	0.0001	2	0.67	0.001	0.004
0.33	1	1	4	1.0000 0.0100	0.0001 1.0000	2	1.00 0.00	0.003	0.009
0.33	1	1	4	0.0100	1.0000	3	0.00	0.001	0.002
0.33	1	1	4	0.0100	0.0100	2	1.00	0.003	0.004
0.33	1	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.33	1	1	4	0.0100	0.0001	2	0.83	0.001	0.004
0.33	1	1	4	0.0100	0.0001	3	1.00	0.004	0.005
0.33	1	1	4	0.0001	1.0000	2	0.00	0.002	0.002
0.33	1	1	4	0.0001	1.0000	3	0.00	0.021	0.027
0.33	1	1	4	0.0001	0.0100	2	0.67	0.001	0.004
0.33	1	1	4	0.0001	0.0100	3	1.00	0.003	0.009
0.33	1	1	4	0.0001	0.0001	2	1.00	0.003	0.004
0.33	1	1	4 16	0.0001 1.0000	1.0000	2	1.00 0.00	0.003	0.004
0.33	1	1	16	1.0000	1.0000	3	0.00	0.002	0.002
0.33	1	1	16	1.0000	0.0100	2	1.00	0.030	0.005
0.33	1	1	16	1.0000	0.0100	3	1.00	0.004	0.005
0.33	1	1	16	1.0000	0.0001	2	1.00	0.004	0.005
0.33	1	1	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	1	1	16	0.0100	1.0000	2	0.00	0.003	0.003
0.33	1	1	16	0.0100	1.0000	3	0.00	0.038	0.039
0.33	1	1	16	0.0100	0.0100	2	1.00	0.005	0.005
0.33	1	1	16	0.0100	0.0100	3	1.00	0.005	0.005
0.33	1	1	16	0.0100	0.0001	2	1.00	0.005	0.006
0.33	1	1	16 16	0.0100	1.0000	3	1.00 0.00	0.006	0.009
0.33	1	1	16	0.0001	1.0000	3	0.00	0.003	0.003
0.33	1	1	16	0.0001	0.0100	2	1.00	0.004	0.006
0.33	1	1	16	0.0001	0.0100	3	1.00	0.004	0.005
0.33	1	1	16	0.0001	0.0001	2	1.00	0.005	0.007
0.33	1	1	16	0.0001	0.0001	3	1.00	0.005	0.007
0.33	1	1	64	1.0000	1.0000	2	0.00	0.004	0.005
0.33	1	1	64	1.0000	1.0000	3	0.00	0.056	0.066
0.33	1	1	64	1.0000	0.0100	2	1.00	0.011	0.012
0.33	1	1	64	1.0000	0.0100	3	1.00	0.011	0.012
0.33	1	1	64	1.0000	0.0001	2	1.00	0.010	0.014
0.33	1	1	64	1.0000 0.0100	1.0000	3	1.00 0.00	0.009	0.015
0.33	1	1	64	0.0100	1.0000	3	0.00	0.060	0.003
0.33	1	1	64	0.0100	0.0100	2	1.00	0.009	0.010
0.33	1	1	64	0.0100	0.0100	3	1.00	0.009	0.009
0.33	1	1	64	0.0100	0.0001	2	1.00	0.011	0.012
0.33	1	1	64	0.0100	0.0001	3	1.00	0.011	0.012
0.33	1	1	64	0.0001	1.0000	2	0.00	0.006	0.009
0.33	1	1	64	0.0001	1.0000	3	0.00	0.098	0.128
0.33	1	1	64	0.0001	0.0100	2	1.00	0.018	0.018
0.33	1	1	64	0.0001	0.0100	3	1.00	0.017	0.018
0.33	1	1	64 64	0.0001	0.0001	2	1.00	0.021	0.022
0.33	1	1	256	0.0001 1.0000	1.00001	3	1.00 0.00	0.020	0.022
0.33	1	1	256	1.0000	1.0000	3	0.00	0.011	0.017
0.33	1	1	256	1.0000	0.0100	2	0.00	0.179	0.993
0.33	1	1	256	1.0000	0.0100	3	0.00	0.363	0.430
0.33	1	1	256	1.0000	0.0001	2	1.00	0.068	0.072
0.33	1	1	256	1.0000	0.0001	3	1.00	0.072	0.073
0.33	1	1	256	0.0100	1.0000	2	0.00	0.017	0.029
0.33	1	1	256	0.0100	1.0000	3	0.00	0.291	1.842
0.33	1	1	256	0.0100	0.0100	2	0.17	0.025	0.076
0.33	1	1	256	0.0100	0.0100	3	0.17	0.072	1.057
0.33	1	1	256	0.0100	0.0001	2	1.00	0.060	0.061
0.33	1	1	256 256	0.0100	1.0000	3	1.00 0.00	0.060	0.097
0.33	1	1	256	0.0001	1.0000	3	0.00	0.028	0.041 1.210
0.33	1	1	256	0.0001	0.0100	2	0.00	0.301	0.053
0.33	1	1	256	0.0001	0.0100	3	0.00	0.520	1.076
0.33	1	1	256	0.0001	0.0001	2	1.00	0.075	0.090
0.33	1	1	256	0.0001	0.0001	3	1.00	0.073	0.081
	-								

mul	m_1	m_2	τ	TR	DTR	alg	SR	mint	maxt
0.33	1	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	1	4	1	1.0000	1.0000	3	0.67	0.003	0.013
0.33	1	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	4	1	1.0000	0.0100	3	1.00	0.003	0.010
0.33	1	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	1	4	1	1.0000	0.0001	3	0.83	0.003	0.015
0.33	1	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	1	4	1	0.0100	1.0000 0.0100	3	0.67	0.003	0.014
0.33	1	4	1	0.0100	0.0100	3	0.83	0.001	0.001
0.33	1	4	1	0.0100	0.0001	2	0.00	0.003	0.001
0.33	1	4	1	0.0100	0.0001	3	0.50	0.003	0.014
0.33	1	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	1	4	1	0.0001	1.0000	3	0.67	0.003	0.013
0.33	1	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	1	4	1	0.0001	0.0100	3	0.83	0.003	0.014
0.33	1	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	1	4	1 4	0.0001 1.0000	0.0001 1.0000	3	0.33	0.003	0.014
0.33	1	4	4	1.0000	1.0000	3	0.00	0.001	0.001
0.33	1	4	4	1.0000	0.0100	2	0.50	0.001	0.003
0.33	1	4	4	1.0000	0.0100	3	1.00	0.003	0.006
0.33	1	4	4	1.0000	0.0001	2	0.83	0.001	0.003
0.33	1	4	4	1.0000	0.0001	3	1.00	0.003	0.004
0.33	1	4	4	0.0100	1.0000	2	0.17	0.001	0.003
0.33	1	4	4	0.0100	1.0000	3	0.33	0.003	0.019
0.33	1	4	4	0.0100	0.0100	2	0.83	0.001	0.003
0.33	1	4	4	0.0100	0.0100	3	1.00 0.50	0.003	0.004
0.33	1	4	4	0.0100	0.0001	3	1.00	0.001	0.003
0.33	1	4	4	0.0001	1.0000	2	0.17	0.003	0.003
0.33	1	4	4	0.0001	1.0000	3	0.33	0.003	0.025
0.33	1	4	4	0.0001	0.0100	2	1.00	0.003	0.004
0.33	1	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	1	4	4	0.0001	0.0001	2	1.00	0.004	0.004
0.33	1	4	4	0.0001	0.0001	3	1.00	0.004	0.004
0.33	1	4	16 16	1.0000	1.0000	3	0.00	0.002	0.002
0.33	1	4	16	1.0000	0.0100	2	1.00	0.024	0.004
0.33	1	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.33	1	4	16	1.0000	0.0001	2	1.00	0.004	0.005
0.33	1	4	16	1.0000	0.0001	3	1.00	0.004	0.005
0.33	1	4	16	0.0100	1.0000	2	0.00	0.002	0.003
0.33	1	4	16	0.0100	1.0000	3	0.00	0.028	0.034
0.33	1	4	16	0.0100	0.0100	2	1.00	0.004	0.006
0.33	1	4	16 16	0.0100	0.0100	3	1.00	0.004	0.006
0.33	1	4	16	0.0100	0.0001	3	1.00	0.004	0.006
0.33	1	4	16	0.0001	1.0000	2	0.00	0.002	0.003
0.33	1	4	16	0.0001	1.0000	3	0.00	0.034	0.036
0.33	1	4	16	0.0001	0.0100	2	1.00	0.004	0.006
0.33	1	4	16	0.0001	0.0100	3	1.00	0.004	0.006
0.33	1	4	16	0.0001	0.0001	2	1.00	0.005	0.007
0.33	1	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.33	1	4	64	1.0000	1.0000	3	0.00	0.003	0.089 0.545
0.33	1	4	64	1.0000	0.0100	2	1.00	0.049	0.008
0.33	1	4	64	1.0000	0.0100	3	1.00	0.008	0.008
0.33	1	4	64	1.0000	0.0001	2	1.00	0.009	0.014
0.33	1	4	64	1.0000	0.0001	3	1.00	0.009	0.015
0.33	1	4	64	0.0100	1.0000	2	0.00	0.005	0.006
0.33	1	4	64	0.0100	1.0000	3	0.00	0.064	0.094
0.33	1	4	64	0.0100	0.0100	2	1.00	0.009	0.010
0.33	1	4	64	0.0100	0.0100	3	1.00	0.009	0.010
0.33	1	4	64	0.0100	0.0001	3	1.00	0.011	0.012
0.33	1	4	64	0.0001	1.0000	2	0.00	0.005	0.006
0.33	1	4	64	0.0001	1.0000	3	0.00	0.084	0.113
0.33	1	4	64	0.0001	0.0100	2	1.00	0.012	0.017
0.33	1	4	64	0.0001	0.0100	3	1.00	0.011	0.017
0.33	1	4	64	0.0001	0.0001	2	1.00	0.015	0.022
0.33	1	4	64	0.0001	0.0001	3	1.00	0.016	0.021
0.33	1	4	256	1.0000	1.0000	2	0.00	0.011	0.013
0.33	1	4	256 256	1.0000	1.0000 0.0100	3	0.00	0.193	0.200
0.33	1	4	256	1.0000	0.0100	3	0.00	0.010	0.867
0.55		7	230	1.0000	0.0100	J	0.00	0.211	0.007

mul	m_1	m_2	au	TR	DTR	alg	SR	mint	maxt
0.33	1	4	256	1.0000	0.0001	2	1.00	0.047	0.050
0.33	1	4	256	1.0000	0.0001	3	1.00	0.048	0.049
0.33	1	4	256 256	0.0100	1.0000	3	0.00	0.017	0.020
0.33	1	4	256	0.0100	0.0100	2	0.67	0.232	0.076
0.33	1	4	256	0.0100	0.0100	3	0.67	0.045	0.441
0.33	1	4	256	0.0100	0.0001	2	1.00	0.064	0.095
0.33	1	4	256	0.0100	0.0001	3	1.00	0.064	0.093
0.33	1	4	256	0.0001	1.0000	2	0.00	0.024	0.027
0.33	1	4	256 256	0.0001	1.0000 0.0100	2	1.00	0.418	0.559
0.33	1	4	256	0.0001	0.0100	3	1.00	0.064	0.300
0.33	1	4	256	0.0001	0.0001	2	1.00	0.075	0.089
0.33	1	4	256	0.0001	0.0001	3	1.00	0.075	0.086
0.33	1	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	1	16	1	1.0000	1.0000	3	0.33	0.003	0.016
0.33	1	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	16 16	1	1.0000	0.0100	3	0.67	0.003	0.016
0.33	1	16	1	1.0000	0.0001	3	0.33	0.001	0.001
0.33	1	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	1	16	1	0.0100	1.0000	3	0.67	0.003	0.014
0.33	1	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	1	16	1	0.0100	0.0100	3	0.83	0.003	0.015
0.33	1	16	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	1	16	1	0.0100	0.0001	3	0.50	0.003	0.015
0.33	1	16 16	1	0.0001	1.0000	3	0.00	0.001	0.001
0.33	1	16	1	0.0001	0.0100	2	0.17	0.003	0.010
0.33	1	16	1	0.0001	0.0100	3	0.67	0.001	0.001
0.33	1	16	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	1	16	1	0.0001	0.0001	3	0.50	0.003	0.014
0.33	1	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	1	16	4	1.0000	1.0000	3	0.33	0.006	0.016
0.33	1	16	4	1.0000	0.0100	2	0.33	0.001	0.004
0.33	1	16 16	4	1.0000	0.0100	3	0.67	0.003	0.014
0.33	1	16	4	1.0000	0.0001	3	0.17 1.00	0.001	0.003
0.33	1	16	4	0.0100	1.0000	2	0.17	0.003	0.004
0.33	1	16	4	0.0100	1.0000	3	0.33	0.003	0.015
0.33	1	16	4	0.0100	0.0100	2	1.00	0.003	0.003
0.33	1	16	4	0.0100	0.0100	3	1.00	0.003	0.004
0.33	1	16	4	0.0100	0.0001	2	0.33	0.001	0.004
0.33	1	16	4	0.0100	0.0001	3	1.00	0.003	0.004
0.33	1	16	4	0.0001	1.0000	2	0.33	0.001	0.004
0.33	1	16 16	4	0.0001	1.0000 0.0100	3	0.50	0.003	0.022
0.33	1	16	4	0.0001	0.0100	3	0.83	0.001	0.004
0.33	1	16	4	0.0001	0.0001	2	1.00	0.003	0.004
0.33	1	16	4	0.0001	0.0001	3	1.00	0.003	0.004
0.33	1	16	16	1.0000	1.0000	2	0.00	0.001	0.002
0.33	1	16	16	1.0000	1.0000	3	0.00	0.019	0.030
0.33	1	16	16	1.0000	0.0100	2	0.33	0.001	0.004
0.33	1	16 16	16 16	1.0000	0.0100	3	1.00 0.83	0.004	0.005
0.33	1	16	16	1.0000	0.0001	3	1.00	0.001	0.005
0.33	1	16	16	0.0100	1.0000	2	0.00	0.004	0.003
0.33	1	16	16	0.0100	1.0000	3	0.00	0.023	0.002
0.33	1	16	16	0.0100	0.0100	2	1.00	0.004	0.006
0.33	1	16	16	0.0100	0.0100	3	1.00	0.004	0.006
0.33	1	16	16	0.0100	0.0001	2	1.00	0.004	0.007
0.33	1	16	16	0.0100	0.0001	3	1.00	0.004	0.006
0.33	1	16	16	0.0001	1.0000	2	0.00	0.001	0.003
0.33	1	16 16	16 16	0.0001	1.0000 0.0100	3	0.00 1.00	0.028	0.044
0.33	1	16	16	0.0001	0.0100	3	1.00	0.004	0.006
0.33	1	16	16	0.0001	0.0001	2	1.00	0.005	0.007
0.33	1	16	16	0.0001	0.0001	3	1.00	0.005	0.006
0.33	1	16	64	1.0000	1.0000	2	0.00	0.003	0.005
0.33	1	16	64	1.0000	1.0000	3	0.00	0.050	0.068
0.33	1	16	64	1.0000	0.0100	2	0.67	0.001	0.008
0.33	1	16	64	1.0000	0.0100	3	1.00	0.008	0.010
0.33	1	16	64	1.0000	0.0001	2	1.00	0.009	0.011
0.33	1	16 16	64	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.009	0.012
0.33	1	16	64	0.0100	1.0000	3	0.00	0.062	0.003
3.33	1	10	0.7	5.5100	1.0000	J	5.00	5.002	0.071

mul	m_1	m_2	τ	TR	DTR	alg	SR	mint	maxt
0.33	1	16	64	0.0100	0.0100	2	1.00	0.009	0.015
0.33	1	16	64	0.0100	0.0100	3	1.00	0.010	0.015
0.33	1	16	64	0.0100	0.0001	2	1.00	0.011	0.013
0.33	1	16	64	0.0100	0.0001	3	1.00	0.011	0.017
0.33	1	16	64	0.0001	1.0000	2	0.00	0.006	0.008
0.33	1	16 16	64	0.0001	1.0000 0.0100	3	0.00 1.00	0.088	0.090
0.33	1	16	64	0.0001	0.0100	3	1.00	0.011	0.014
0.33	1	16	64	0.0001	0.0001	2	1.00	0.013	0.016
0.33	1	16	64	0.0001	0.0001	3	1.00	0.014	0.015
0.33	1	16	256	1.0000	1.0000	2	0.00	0.011	0.017
0.33	1	16	256 256	1.0000	1.0000 0.0100	3	0.00	0.194	0.283
0.33	1	16 16	256	1.0000	0.0100	3	0.00	0.016	0.025
0.33	1	16	256	1.0000	0.0001	2	1.00	0.069	0.723
0.33	1	16	256	1.0000	0.0001	3	1.00	0.047	0.074
0.33	1	16	256	0.0100	1.0000	2	0.00	0.019	0.027
0.33	1	16	256	0.0100	1.0000	3	0.00	0.299	0.454
0.33	1	16	256	0.0100	0.0100	2	1.00	0.052	0.377
0.33	1	16 16	256 256	0.0100	0.0100	3	1.00	0.049	0.070
0.33	1	16	256	0.0100	0.0001	3	1.00	0.060	0.062
0.33	1	16	256	0.0001	1.0000	2	0.00	0.000	0.002
0.33	1	16	256	0.0001	1.0000	3	0.00	0.441	0.473
0.33	1	16	256	0.0001	0.0100	2	1.00	0.060	0.064
0.33	1	16	256	0.0001	0.0100	3	1.00	0.060	0.065
0.33	1	16	256	0.0001	0.0001	2	1.00	0.080	0.604 0.128
0.33	1	16 64	256	0.0001 1.0000	0.0001 1.0000	3	1.00	0.074	0.128
0.33	1	64	1	1.0000	1.0000	3	0.00	0.001	0.001
0.33	1	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	64	1	1.0000	0.0100	3	0.67	0.003	0.016
0.33	1	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	1	64	1	1.0000	0.0001	3	0.67	0.003	0.015
0.33	1	64	1	0.0100	1.0000	3	0.00	0.001	0.001
0.33	1	64	1	0.0100	0.0100	2	0.00	0.003	0.001
0.33	1	64	1	0.0100	0.0100	3	0.67	0.003	0.016
0.33	1	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	1	64	1	0.0100	0.0001	3	0.33	0.003	0.016
0.33	1	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	1	64	1	0.0001	1.0000 0.0100	3	0.67	0.003	0.016
0.33	1	64	1	0.0001	0.0100	3	0.00	0.001	0.001
0.33	1	64	1	0.0001	0.0001	2	0.07	0.003	0.001
0.33	1	64	1	0.0001	0.0001	3	0.67	0.003	0.015
0.33	1	64	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	1	64	4	1.0000	1.0000	3	0.00	0.014	0.017
0.33	1	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	64	4	1.0000	0.0100	3	0.67	0.003	0.018
0.33	1	64	4	1.0000	0.0001	3	1.00	0.001	0.003
0.33	1	64	4	0.0100	1.0000	2	0.00	0.001	0.002
0.33	1	64	4	0.0100	1.0000	3	0.50	0.003	0.024
0.33	1	64	4	0.0100	0.0100	2	0.17	0.001	0.004
0.33	1	64	4	0.0100	0.0100	3	1.00	0.004	0.004
0.33	1	64	4	0.0100	0.0001	3	0.67 1.00	0.001	0.004
0.33	1	64	4	0.0100	1.0000	2	0.67	0.004	0.004
0.33	1	64	4	0.0001	1.0000	3	0.67	0.004	0.019
0.33	1	64	4	0.0001	0.0100	2	0.83	0.001	0.004
0.33	1	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	1	64	4	0.0001	0.0001	2	1.00	0.003	0.004
0.33	1	64	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.003	0.004
0.33	1	64	16	1.0000	1.0000	3	0.00	0.001	0.001
0.33	1	64	16	1.0000	0.0100	2	0.00	0.017	0.021
0.33	1	64	16	1.0000	0.0100	3	1.00	0.004	0.004
0.33	1	64	16	1.0000	0.0001	2	0.33	0.001	0.004
0.33	1	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.33	1	64	16	0.0100	1.0000	2	0.00	0.001	0.001
0.33	1	64 64	16 16	0.0100	1.0000 0.0100	3	0.50 1.00	0.004	0.022
1 (1.2.2.1	, ,			0.0100	0.0100	4	1.00		
0.33	1	64	16		0.0100	3	1.00	0.004	0.005
0.33 0.33 0.33				0.0100 0.0100	0.0100 0.0001	3	1.00	0.004 0.004	0.005 0.005

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	1	64	16	0.0001	1.0000	2	0.33	0.001	0.005
0.33	1	64	16	0.0001	1.0000	3	0.33	0.005	0.025
0.33	1	64	16	0.0001	0.0100	2	1.00	0.004	0.005
0.33	1	64	16	0.0001	0.0100	3	1.00	0.004	0.005
0.33	1	64	16	0.0001	0.0001	2	1.00	0.005	0.005
0.33	1	64	16	0.0001	0.0001	3	1.00	0.005	0.005
0.33	1	64	64	1.0000	1.0000	2	0.00	0.001	0.003
0.33	1	64	64	1.0000	1.0000	3	0.00	0.038	0.044
0.33	1	64	64	1.0000	0.0100	2	0.50	0.001	0.008
0.33	1	64	64	1.0000	0.0100	3	1.00	0.008	0.015
0.33	1	64	64	1.0000	0.0001	3	1.00	0.010	0.011
0.33	1	64	64	0.0100	1.0000	2	0.00	0.010	0.016
0.33	1	64	64	0.0100	1.0000	3	0.00	0.001	0.087
0.33	1	64	64	0.0100	0.0100	2	0.83	0.001	0.014
0.33	1	64	64	0.0100	0.0100	3	1.00	0.010	0.012
0.33	1	64	64	0.0100	0.0001	2	1.00	0.011	0.014
0.33	1	64	64	0.0100	0.0001	3	1.00	0.011	0.013
0.33	1	64	64	0.0001	1.0000	2	0.17	0.001	0.012
0.33	1	64	64	0.0001	1.0000	3	0.17	0.011	0.862
0.33	1	64	64	0.0001	0.0100	2	1.00	0.018	0.019
0.33	1	64	64	0.0001	0.0100	3	1.00	0.017	0.018
0.33	1	64	64	0.0001	0.0001	2	1.00	0.019	0.023
0.33	1	64	64 256	0.0001 1.0000	0.0001 1.0000	3	0.00	0.019	0.023
0.33	1	64	256	1.0000	1.0000	3	0.00	0.011	0.017
0.33	1	64	256	1.0000	0.0100	2	0.00	0.181	0.283
0.33	1	64	256	1.0000	0.0100	3	0.33	0.037	0.362
0.33	1	64	256	1.0000	0.0001	2	1.00	0.047	0.074
0.33	1	64	256	1.0000	0.0001	3	1.00	0.048	0.073
0.33	1	64	256	0.0100	1.0000	2	0.00	0.017	0.027
0.33	1	64	256	0.0100	1.0000	3	0.00	0.275	0.492
0.33	1	64	256	0.0100	0.0100	2	1.00	0.052	0.077
0.33	1	64	256	0.0100	0.0100	3	1.00	0.054	0.072
0.33	1	64	256	0.0100	0.0001	2	1.00	0.070	0.096
0.33	1	64	256	0.0100	0.0001	3	1.00	0.077	0.096
0.33	1	64	256	0.0001	1.0000	2	0.00	0.039	0.056
0.33	1	64	256 256	0.0001	1.0000 0.0100	2	0.00 1.00	0.648	1.073 0.098
0.33	1	64	256	0.0001	0.0100	3	1.00	0.063	0.098
0.33	1	64	256	0.0001	0.0001	2	1.00	0.003	0.084
0.33	1	64	256	0.0001	0.0001	3	1.00	0.076	0.092
0.33	1	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	1	256	1	1.0000	1.0000	3	0.67	0.003	0.014
0.33	1	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	256	1	1.0000	0.0100	3	0.67	0.003	0.014
0.33	1	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	1	256	1	1.0000	0.0001	3	0.83	0.003	0.014
0.33	1	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	1	256	1	0.0100	1.0000	3	0.83	0.003	0.012
0.33	1	256 256	1	0.0100	0.0100	3	0.00	0.001	0.001 0.014
0.33	1	256	1	0.0100	0.0100	2	0.83	0.003	0.014
0.33	1	256	1	0.0100	0.0001	3	0.83	0.001	0.001
0.33	1	256	1	0.0001	1.0000	2	0.00	0.003	0.001
0.33	1	256	1	0.0001	1.0000	3	0.17	0.003	0.014
0.33	1	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	1	256	1	0.0001	0.0100	3	0.50	0.003	0.014
0.33	1	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	1	256	1	0.0001	0.0001	3	0.50	0.003	0.014
0.33	1	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	1	256	4	1.0000	1.0000	3	0.50	0.003	0.015
0.33	1	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	256 256	4	1.0000	0.0100	2	0.50	0.003	0.015
0.33	1	256	4	1.0000	0.0001	3	1.00	0.001	0.004
0.33	1	256	4	0.0100	1.0000	2	0.00	0.004	0.004
0.33	1	256	4	0.0100	1.0000	3	0.50	0.001	0.001
0.33	1	256	4	0.0100	0.0100	2	0.67	0.004	0.004
0.33	1	256	4	0.0100	0.0100	3	0.83	0.003	0.004
0.33	1	256	4	0.0100	0.0001	2	0.50	0.001	0.003
0.33	1	256	4	0.0100	0.0001	3	1.00	0.003	0.003
0.33	1	256	4	0.0001	1.0000	2	0.17	0.001	0.003
0.33	1	256	4	0.0001	1.0000	3	0.50	0.003	0.016
0.33	1	256	4	0.0001	0.0100	2	0.83	0.001	0.004
0.33	1	256	4	0.0001	0.0100	3	1.00	0.003	0.004

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.33	1	256	4	0.0001	0.0001	2	1.00	0.003	0.004
0.33	1	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.33	1	256	16	1.0000	1.0000	2	0.00	0.003	0.002
0.33	1	256	16	1.0000	1.0000	3	0.50	0.004	0.031
0.33	1	256	16	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	256	16	1.0000	0.0100	3	1.00	0.005	0.006
0.33	1	256	16	1.0000	0.0001	2	1.00	0.004	0.006
0.33	1	256	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	1	256	16	0.0100	1.0000	2	0.00	0.001	0.002
0.33	1	256 256	16	0.0100	1.0000 0.0100	3	0.17 1.00	0.004	0.028
0.33	1	256	16 16	0.0100	0.0100	3	1.00	0.004	0.004
0.33	1	256	16	0.0100	0.0001	2	0.83	0.001	0.005
0.33	1	256	16	0.0100	0.0001	3	1.00	0.004	0.005
0.33	1	256	16	0.0001	1.0000	2	0.17	0.001	0.006
0.33	1	256	16	0.0001	1.0000	3	0.50	0.006	0.035
0.33	1	256	16	0.0001	0.0100	2	1.00	0.006	0.007
0.33	1	256	16	0.0001	0.0100	3	1.00	0.006	0.007
0.33	1	256	16	0.0001	0.0001	2	1.00	0.007	0.007
0.33	1	256	16	0.0001	0.0001	3	1.00	0.006	0.007
0.33	1	256 256	64 64	1.0000	1.0000	2	0.00	0.001	0.004
0.33	1	256	64	1.0000	0.0100	2	0.00	0.037	0.004
0.33	1	256	64	1.0000	0.0100	3	1.00	0.001	0.013
0.33	1	256	64	1.0000	0.0001	2	0.83	0.001	0.016
0.33	1	256	64	1.0000	0.0001	3	1.00	0.010	0.014
0.33	1	256	64	0.0100	1.0000	2	0.00	0.001	0.006
0.33	1	256	64	0.0100	1.0000	3	0.33	0.009	0.089
0.33	1	256	64	0.0100	0.0100	2	1.00	0.010	0.014
0.33	1	256	64	0.0100	0.0100	3	1.00	0.010	0.014
0.33	1	256	64	0.0100	0.0001	2	1.00	0.011	0.012
0.33	1	256 256	64	0.0100	1.0000	3	1.00 0.00	0.011	0.012
0.33	1	256	64	0.0001	1.0000	3	0.00	0.001	0.088
0.33	1	256	64	0.0001	0.0100	2	1.00	0.011	0.018
0.33	1	256	64	0.0001	0.0100	3	1.00	0.012	0.062
0.33	1	256	64	0.0001	0.0001	2	1.00	0.013	0.017
0.33	1	256	64	0.0001	0.0001	3	1.00	0.013	0.016
0.33	1	256	256	1.0000	1.0000	2	0.00	0.001	0.012
0.33	1	256	256	1.0000	1.0000	3	0.00	0.166	0.729
0.33	1	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.33	1	256 256	256 256	1.0000	0.0100	3	0.33	0.038	0.304
0.33	1	256	256	1.0000	0.0001	3	1.00	0.047	0.050
0.33	1	256	256	0.0100	1.0000	2	0.00	0.001	0.019
0.33	1	256	256	0.0100	1.0000	3	0.00	0.251	0.887
0.33	1	256	256	0.0100	0.0100	2	1.00	0.051	0.057
0.33	1	256	256	0.0100	0.0100	3	1.00	0.049	0.058
0.33	1	256	256	0.0100	0.0001	2	1.00	0.058	0.064
0.33	1	256	256	0.0100	0.0001	3	1.00	0.059	0.091
0.33	1	256	256	0.0001	1.0000	3	0.00	0.001	1.280
0.33	1	256 256	256 256	0.0001	1.0000 0.0100	2	0.00 1.00	0.482	0.096
0.33	1	256	256	0.0001	0.0100	3	1.00	0.076	0.100
0.33	1	256	256	0.0001	0.0001	2	1.00	0.009	0.100
0.33	1	256	256	0.0001	0.0001	3	1.00	0.100	0.123
0.33	4	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	4	1	1	1.0000	1.0000	3	0.33	0.006	0.016
0.33	4	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	4	1	1	1.0000	0.0100	3	0.67	0.004	0.016
0.33	4	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	4	1	1	1.0000 0.0100	0.0001 1.0000	3	0.67	0.004	0.014
0.33	4	1	1	0.0100	1.0000	3	0.00	0.001	0.001
0.33	4	1	1	0.0100	0.0100	2	0.00	0.003	0.001
0.33	4	1	1	0.0100	0.0100	3	0.67	0.004	0.013
0.33	4	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	4	1	1	0.0100	0.0001	3	0.67	0.003	0.014
0.33	4	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	4	1	1	0.0001	1.0000	3	0.83	0.004	0.013
0.33	4	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	4	1	1	0.0001	0.0100	3	0.50	0.005	0.013
0.33	4	1	1	0.0001	0.0001	3	0.00	0.001	0.001
0.33	4	1	4	1.0000	1.0000	2	0.00	0.003	0.002
0.33	4	1	4	1.0000	1.0000	3	0.17	0.007	0.130
	•		•				,	,	

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	4	1	4	1.0000	0.0100	2	0.33	0.001	0.003
0.33	4	1	4	1.0000	0.0100	3	1.00	0.003	0.011
0.33	4	1	4	1.0000	0.0001	2	0.33	0.001	0.003
0.33	4	1	4	1.0000	0.0001	3	1.00	0.003	0.010
0.33	4	1	4	0.0100	1.0000	2	0.00	0.001	0.002
0.33	4	1	4	0.0100	1.0000 0.0100	2	0.17	0.007	0.018
0.33	4	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.33	4	1	4	0.0100	0.0001	2	0.33	0.003	0.004
0.33	4	1	4	0.0100	0.0001	3	1.00	0.004	0.010
0.33	4	1	4	0.0001	1.0000	2	0.33	0.001	0.003
0.33	4	1	4	0.0001	1.0000	3	0.33	0.003	0.024
0.33	4	1	4	0.0001	0.0100	2	0.83	0.001	0.003
0.33	4	1	4	0.0001	0.0100	3	1.00	0.003	0.005
0.33	4	1	4	0.0001	0.0001	2	1.00	0.003	0.004
0.33	4	1	4	0.0001	0.0001	3	1.00	0.003	0.004
0.33	4	1	16	1.0000	1.0000	2	0.00	0.002	0.002
0.33	4	1	16 16	1.0000	1.0000 0.0100	3	0.00	0.023	0.031
0.33	4	1	16	1.0000	0.0100	3	1.00	0.001	0.004
0.33	4	1	16	1.0000	0.0001	2	1.00	0.004	0.008
0.33	4	1	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	4	1	16	0.0100	1.0000	2	0.00	0.002	0.004
0.33	4	1	16	0.0100	1.0000	3	0.00	0.029	0.250
0.33	4	1	16	0.0100	0.0100	2	1.00	0.004	0.005
0.33	4	1	16	0.0100	0.0100	3	1.00	0.004	0.006
0.33	4	1	16	0.0100	0.0001	2	1.00	0.004	0.006
0.33	4	1	16	0.0100	0.0001	3	1.00	0.004	0.006
0.33	4	1	16	0.0001	1.0000	2	0.00	0.003	0.003
0.33	4	1	16	0.0001	1.0000	3	0.00	0.037	0.046
0.33	4	1	16 16	0.0001	0.0100	3	1.00	0.004	0.006
0.33	4	1	16	0.0001	0.0100	2	1.00	0.004	0.008
0.33	4	1	16	0.0001	0.0001	3	1.00	0.005	0.008
0.33	4	1	64	1.0000	1.0000	2	0.00	0.003	0.004
0.33	4	1	64	1.0000	1.0000	3	0.00	0.056	0.065
0.33	4	1	64	1.0000	0.0100	2	0.83	0.001	0.011
0.33	4	1	64	1.0000	0.0100	3	1.00	0.008	0.011
0.33	4	1	64	1.0000	0.0001	2	1.00	0.009	0.014
0.33	4	1	64	1.0000	0.0001	3	1.00	0.009	0.014
0.33	4	1	64	0.0100	1.0000	2	0.00	0.004	0.006
0.33	4	1	64	0.0100	1.0000	3	0.00	0.063	0.092
0.33	4	1	64	0.0100	0.0100	2	1.00	0.009	0.011
0.33	4	1	64	0.0100	0.0100	2	1.00	0.010	0.011
0.33	4	1	64	0.0100	0.0001	3	1.00	0.011	0.012
0.33	4	1	64	0.0100	1.0000	2	0.00	0.016	0.013
0.33	4	1	64	0.0001	1.0000	3	0.00	0.084	0.008
0.33	4	1	64	0.0001	0.0100	2	1.00	0.012	0.017
0.33	4	1	64	0.0001	0.0100	3	1.00	0.011	0.016
0.33	4	1	64	0.0001	0.0001	2	1.00	0.016	0.020
0.33	4	1	64	0.0001	0.0001	3	1.00	0.013	0.022
0.33	4	1	256	1.0000	1.0000	2	0.00	0.011	0.023
0.33	4	1	256	1.0000	1.0000	3	0.00	0.189	1.448
0.33	4	1	256	1.0000	0.0100	2	0.00	0.016	0.026
0.33	4	1	256	1.0000	0.0100	3	0.00	0.273	0.380
0.33	4	1	256	1.0000	0.0001	2	1.00	0.050	0.074
0.33	4	1	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.047	0.073
0.33	4	1	256	0.0100	1.0000	3	0.00	0.021	0.038
0.33	4	1	256	0.0100	0.0100	2	0.67	0.323	0.731
0.33	4	1	256	0.0100	0.0100	3	0.67	0.046	0.568
0.33	4	1	256	0.0100	0.0001	2	1.00	0.058	0.094
0.33	4	1	256	0.0100	0.0001	3	1.00	0.058	0.077
0.33	4	1	256	0.0001	1.0000	2	0.00	0.032	0.041
0.33	4	1	256	0.0001	1.0000	3	0.00	0.546	1.325
0.33	4	1	256	0.0001	0.0100	2	1.00	0.064	0.095
0.33	4	1	256	0.0001	0.0100	3	1.00	0.063	0.092
0.33	4	1	256	0.0001	0.0001	2	1.00	0.071	0.111
0.33	4	1	256	0.0001	0.0001	3	1.00	0.074	0.115
0.33	4	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	4	4	1	1.0000	1.0000	3	1.00	0.003	0.009
0.33	4	4	1	1.0000	0.0100	3	0.00	0.001	0.001
0.33	4	4	1	1.0000	0.0001	2	0.00	0.003	0.008
	4	4	1	1.0000	0.0001		0.50	0.001	0.001
0.33	4	4	1	1.0000	0.0001	3	0.50	0.003	0.020

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.33	4	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	4	4	1	0.0100	1.0000	3	0.83	0.003	0.013
0.33	4	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	4	4	1	0.0100	0.0100	3	0.83	0.003	0.013
0.33	4	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	4	4	1	0.0100	1.0000	3	1.00 0.00	0.003	0.010
0.33	4	4	1	0.0001	1.0000	3	1.00	0.001	0.001
0.33	4	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	4	4	1	0.0001	0.0100	3	1.00	0.003	0.010
0.33	4	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	4	4	1	0.0001	0.0001	3	0.67	0.003	0.017
0.33	4	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	4	4	4	1.0000	1.0000 0.0100	3	0.17	0.008	0.020
0.33	4	4	4	1.0000	0.0100	3	1.00	0.001	0.001
0.33	4	4	4	1.0000	0.0001	2	0.33	0.001	0.003
0.33	4	4	4	1.0000	0.0001	3	1.00	0.003	0.008
0.33	4	4	4	0.0100	1.0000	2	0.67	0.001	0.004
0.33	4	4	4	0.0100	1.0000	3	0.83	0.003	0.021
0.33	4	4	4	0.0100	0.0100	2	0.67	0.001	0.004
0.33	4	4	4	0.0100	0.0100	3	1.00	0.003	0.014
0.33	4	4	4	0.0100	0.0001	3	1.00	0.004	0.004
0.33	4	4	4	0.0001	1.0000	2	0.33	0.001	0.004
0.33	4	4	4	0.0001	1.0000	3	0.50	0.003	0.024
0.33	4	4	4	0.0001	0.0100	2	1.00	0.003	0.004
0.33	4	4	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	4	4	4	0.0001	0.0001	3	0.67 1.00	0.001	0.004
0.33	4	4	16	1.0000	1.0000	2	0.00	0.003	0.003
0.33	4	4	16	1.0000	1.0000	3	0.00	0.027	0.031
0.33	4	4	16	1.0000	0.0100	2	0.67	0.001	0.005
0.33	4	4	16	1.0000	0.0100	3	1.00	0.004	0.005
0.33	4	4	16	1.0000	0.0001	2	1.00	0.004	0.005
0.33	4	4	16 16	1.0000 0.0100	1.0000	3	1.00	0.004	0.006
0.33	4	4	16	0.0100	1.0000	3	0.00	0.034	0.003
0.33	4	4	16	0.0100	0.0100	2	0.83	0.001	0.006
0.33	4	4	16	0.0100	0.0100	3	1.00	0.005	0.010
0.33	4	4	16	0.0100	0.0001	2	1.00	0.006	0.006
0.33	4	4	16	0.0100	0.0001	3	1.00	0.006	0.006
0.33	4	4	16 16	0.0001	1.0000	3	0.00	0.001	0.003
0.33	4	4	16	0.0001	0.0100	2	1.00	0.039	0.047
0.33	4	4	16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	4	4	16	0.0001	0.0001	2	1.00	0.005	0.042
0.33	4	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.33	4	4	64	1.0000	1.0000	2	0.00	0.003	0.004
0.33	4	4	64 64	1.0000	1.0000 0.0100	3	0.00 1.00	0.049	0.057
0.33	4	4	64	1.0000	0.0100	3	1.00	0.008	0.020
0.33	4	4	64	1.0000	0.0001	2	1.00	0.009	0.011
0.33	4	4	64	1.0000	0.0001	3	1.00	0.009	0.014
0.33	4	4	64	0.0100	1.0000	2	0.00	0.004	0.005
0.33	4	4	64	0.0100	1.0000	3	0.00	0.063	0.604
0.33	4	4	64 64	0.0100	0.0100	3	1.00	0.009	0.014
0.33	4	4	64	0.0100	0.0100	2	1.00	0.010	0.014
0.33	4	4	64	0.0100	0.0001	3	1.00	0.013	0.018
0.33	4	4	64	0.0001	1.0000	2	0.00	0.006	0.009
0.33	4	4	64	0.0001	1.0000	3	0.00	0.087	0.118
0.33	4	4	64	0.0001	0.0100	2	1.00	0.011	0.017
0.33	4	4	64	0.0001	0.0100	3	1.00	0.013	0.018
0.33	4	4	64 64	0.0001	0.0001	3	1.00	0.014	0.023
0.33	4	4	256	1.0000	1.0000	2	0.00	0.013	0.021
0.33	4	4	256	1.0000	1.0000	3	0.00	0.182	0.284
0.33	4	4	256	1.0000	0.0100	2	0.00	0.017	0.026
0.33	4	4	256	1.0000	0.0100	3	0.00	0.274	0.870
0.33	4	4	256	1.0000	0.0001	2	1.00	0.044	0.073
0.33	4	4	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.045 0.027	0.073 0.028
0.33	4	4	256	0.0100	1.0000	3	0.00	0.027	0.028
0.33	4	4	256	0.0100	0.0100	2	1.00	0.070	0.430
0.33	4	4	256	0.0100	0.0100	3	1.00	0.075	0.078

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	4	4	256	0.0100	0.0001	2	1.00	0.066	0.100
0.33	4	4	256	0.0100	0.0001	3	1.00	0.065	0.100
0.33	4	4	256	0.0001	1.0000	2	0.00	0.026	0.053
0.33	4	4	256	0.0001	1.0000	3	0.00	0.432	1.751
0.33	4	4	256	0.0001	0.0100	2	1.00	0.059	0.064
0.33	4	4	256 256	0.0001	0.0100	3	1.00	0.059	0.065 0.114
0.33	4	4	256	0.0001	0.0001	3	1.00	0.089	0.114
0.33	4	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	4	16	1	1.0000	1.0000	3	0.50	0.003	0.018
0.33	4	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	4	16	1	1.0000	0.0100	3	1.00	0.003	0.003
0.33	4	16	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	4	16	1	1.0000	0.0001	3	0.50	0.003	0.017
0.33	4	16 16	1	0.0100	1.0000	3	0.00	0.001	0.001
0.33	4	16	1	0.0100	0.0100	2	0.00	0.003	0.001
0.33	4	16	1	0.0100	0.0100	3	0.83	0.003	0.014
0.33	4	16	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	4	16	1	0.0100	0.0001	3	0.67	0.003	0.020
0.33	4	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	4	16	1	0.0001	1.0000	3	0.83	0.003	0.016
0.33	4	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	4	16	1	0.0001	0.0100	3	0.50	0.003	0.015
0.33	4	16 16	1	0.0001	0.0001	3	0.00	0.001	0.001
0.33	4	16	4	1.0000	1.0000	2	0.00	0.003	0.023
0.33	4	16	4	1.0000	1.0000	3	0.00	0.001	0.001
0.33	4	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.33	4	16	4	1.0000	0.0100	3	1.00	0.004	0.005
0.33	4	16	4	1.0000	0.0001	2	0.17	0.001	0.004
0.33	4	16	4	1.0000	0.0001	3	0.83	0.004	0.023
0.33	4	16 16	4	0.0100	1.0000	3	0.50	0.001	0.004
0.33	4	16	4	0.0100	1.0000 0.0100	2	0.83	0.003	0.024
0.33	4	16	4	0.0100	0.0100	3	1.00	0.001	0.004
0.33	4	16	4	0.0100	0.0001	2	0.50	0.001	0.004
0.33	4	16	4	0.0100	0.0001	3	1.00	0.004	0.014
0.33	4	16	4	0.0001	1.0000	2	0.67	0.001	0.004
0.33	4	16	4	0.0001	1.0000	3	0.67	0.003	0.021
0.33	4	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.33	4	16	4	0.0001	0.0100	3	1.00 0.67	0.003	0.004
0.33	4	16	4	0.0001	0.0001	3	1.00	0.001	0.004
0.33	4	16	16	1.0000	1.0000	2	0.00	0.004	0.004
0.33	4	16	16	1.0000	1.0000	3	0.00	0.022	0.029
0.33	4	16	16	1.0000	0.0100	2	0.33	0.001	0.005
0.33	4	16	16	1.0000	0.0100	3	1.00	0.004	0.005
0.33	4	16	16	1.0000	0.0001	2	0.67	0.001	0.006
0.33	4	16	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	4	16 16	16 16	0.0100	1.0000	3	0.00	0.001	0.003
0.33	4	16	16	0.0100	0.0100	2	0.00	0.028	0.037
0.33	4	16	16	0.0100	0.0100	3	1.00	0.001	0.006
0.33	4	16	16	0.0100	0.0001	2	1.00	0.004	0.006
0.33	4	16	16	0.0100	0.0001	3	1.00	0.004	0.006
0.33	4	16	16	0.0001	1.0000	2	0.00	0.001	0.002
0.33	4	16	16	0.0001	1.0000	3	0.00	0.028	0.034
0.33	4	16	16	0.0001	0.0100	2	1.00	0.004	0.005
0.33	4	16	16	0.0001	0.0100	2	1.00	0.004	0.005
0.33	4	16	16 16	0.0001	0.0001	3	1.00	0.005	0.005
0.33	4	16	64	1.0000	1.0000	2	0.00	0.003	0.005
0.33	4	16	64	1.0000	1.0000	3	0.00	0.047	0.623
0.33	4	16	64	1.0000	0.0100	2	0.83	0.001	0.011
0.33	4	16	64	1.0000	0.0100	3	1.00	0.008	0.011
0.33	4	16	64	1.0000	0.0001	2	1.00	0.009	0.014
0.33	4	16	64	1.0000	0.0001	3	1.00	0.010	0.014
0.33	4	16	64	0.0100	1.0000	2	0.00	0.001	0.006
0.33	4	16 16	64	0.0100	1.0000 0.0100	2	1.00	0.062	0.090
0.33	4	16	64	0.0100	0.0100	3	1.00	0.010	0.013
0.33	4	16	64	0.0100	0.0001	2	1.00	0.014	0.014
0.33	4	16	64	0.0100	0.0001	3	1.00	0.017	0.055
0.33		16 16	64 64	0.0100	1.0000	2	0.00	0.017	0.009

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	4	16	64	0.0001	0.0100	2	1.00	0.012	0.017
0.33	4	16	64	0.0001	0.0100	3	1.00	0.012	0.017
0.33	4	16	64	0.0001	0.0001	2	1.00	0.014	0.023
0.33	4	16	64	0.0001	0.0001	3	1.00	0.014	0.023
0.33	4	16	256	1.0000	1.0000	2	0.00	0.011	0.017
0.33	4	16	256	1.0000	1.0000	3	0.00	0.181	0.280
0.33	4	16	256	1.0000	0.0100	2	0.17	0.016	0.051
0.33	4	16	256	1.0000	0.0100	3	0.17	0.048	0.930
0.33	4	16	256	1.0000	0.0001	2	1.00	0.046	0.071
0.33	4	16 16	256 256	1.0000 0.0100	0.0001 1.0000	2	1.00 0.00	0.045 0.017	0.074
0.33	4	16	256	0.0100	1.0000	3	0.00	0.285	1.166
0.33	4	16	256	0.0100	0.0100	2	1.00	0.068	0.075
0.33	4	16	256	0.0100	0.0100	3	1.00	0.054	0.075
0.33	4	16	256	0.0100	0.0001	2	1.00	0.066	0.097
0.33	4	16	256	0.0100	0.0001	3	1.00	0.067	0.098
0.33	4	16	256	0.0001	1.0000	2	0.00	0.027	0.040
0.33	4	16	256	0.0001	1.0000	3	0.00	0.527	0.984
0.33	4	16 16	256 256	0.0001	0.0100	3	1.00	0.058	0.089
0.33	4	16	256	0.0001	0.0001	2	1.00	0.039	0.074
0.33	4	16	256	0.0001	0.0001	3	1.00	0.074	0.127
0.33	4	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	4	64	1	1.0000	1.0000	3	0.50	0.003	0.013
0.33	4	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	4	64	1	1.0000	0.0100	3	0.83	0.003	0.014
0.33	4	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	4	64	1	1.0000	0.0001	3	0.67	0.003	0.016
0.33	4	64	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	4	64	1	0.0100	1.0000 0.0100	3	0.00	0.003	0.015
0.33	4	64	1	0.0100	0.0100	3	0.50	0.003	0.016
0.33	4	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	4	64	1	0.0100	0.0001	3	0.83	0.003	0.017
0.33	4	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	4	64	1	0.0001	1.0000	3	0.50	0.003	0.015
0.33	4	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	4	64	1	0.0001	0.0100	3	0.67	0.003	0.016
0.33	4	64	1	0.0001	0.0001	3	0.00	0.001	0.001
0.33	4	64	4	1.0000	1.0000	2	0.07	0.003	0.001
0.33	4	64	4	1.0000	1.0000	3	0.50	0.003	0.017
0.33	4	64	4	1.0000	0.0100	2	0.17	0.001	0.003
0.33	4	64	4	1.0000	0.0100	3	0.83	0.003	0.018
0.33	4	64	4	1.0000	0.0001	2	0.33	0.001	0.004
0.33	4	64	4	1.0000	0.0001	3	1.00	0.003	0.004
0.33	4	64	4	0.0100	1.0000	2	0.17	0.001	0.003
0.33	4	64	4	0.0100	1.0000 0.0100	2	0.50	0.003	0.017
0.33	4	64	4	0.0100	0.0100	3	1.00	0.001	0.004
0.33	4	64	4	0.0100	0.0001	2	0.50	0.004	0.004
0.33	4	64	4	0.0100	0.0001	3	1.00	0.003	0.004
0.33	4	64	4	0.0001	1.0000	2	0.83	0.001	0.004
0.33	4	64	4	0.0001	1.0000	3	0.83	0.003	0.014
0.33	4	64	4	0.0001	0.0100	2	0.67	0.001	0.004
0.33	4	64	4	0.0001	0.0100	3	1.00	0.003	0.003
0.33	4	64 64	4	0.0001	0.0001	3	0.83	0.001	0.004
0.33	4	64	16	1.0000	1.00001	2	0.83	0.003	0.016
0.33	4	64	16	1.0000	1.0000	3	0.00	0.001	0.002
0.33	4	64	16	1.0000	0.0100	2	0.33	0.001	0.004
0.33	4	64	16	1.0000	0.0100	3	0.83	0.004	0.019
0.33	4	64	16	1.0000	0.0001	2	0.83	0.001	0.005
0.33	4	64	16	1.0000	0.0001	3	1.00	0.004	0.005
0.33	4	64	16	0.0100	1.0000	2	0.00	0.001	0.002
0.33	4	64	16	0.0100	1.0000	3	0.00	0.022	0.036
0.33	4	64 64	16 16	0.0100	0.0100	3	0.83 1.00	0.001	0.004
0.33	4	64	16	0.0100	0.0100	2	1.00	0.004	0.003
0.33	4	64	16	0.0100	0.0001	3	1.00	0.004	0.005
0.33	4	64	16	0.0001	1.0000	2	0.33	0.001	0.006
0.33	4	64	16	0.0001	1.0000	3	0.67	0.005	0.041
0.33	4	64	16	0.0001	0.0100	2	1.00	0.006	0.006
0.33	4	64	16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	4	64	16	0.0001	0.0001	2	1.00	0.006	0.007
0.33	4	64	16	0.0001	0.0001	3	1.00	0.005	0.007

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.33	4	64	64	1.0000	1.0000	2	0.00	0.001	0.005
0.33	4	64	64	1.0000	1.0000	3	0.00	0.060	0.066
0.33	4	64	64	1.0000	0.0100	2	0.00	0.001	0.001
0.33	4	64	64	1.0000	0.0100	3	1.00	0.011	0.012
0.33	4	64	64	1.0000	0.0001	2	1.00	0.010	0.015
0.33	4	64	64	1.0000	0.0001	3	1.00	0.010	0.015
0.33	4	64	64	0.0100	1.0000	2	0.00	0.001	0.006
0.33	4	64	64	0.0100	1.0000	3	0.00	0.061	0.529
0.33	4	64	64	0.0100	0.0100	2	1.00	0.014	0.015
0.33	4	64	64	0.0100	0.0100	3	1.00	0.014	0.015
0.33	4	64	64	0.0100	0.0001	3	1.00	0.011	0.017 0.016
0.33	4	64	64	0.0001	1.0000	2	0.00	0.011	0.016
0.33	4	64	64	0.0001	1.0000	3	0.00	0.001	0.086
0.33	4	64	64	0.0001	0.0100	2	1.00	0.012	0.054
0.33	4	64	64	0.0001	0.0100	3	1.00	0.012	0.018
0.33	4	64	64	0.0001	0.0001	2	1.00	0.015	0.021
0.33	4	64	64	0.0001	0.0001	3	1.00	0.014	0.022
0.33	4	64	256	1.0000	1.0000	2	0.00	0.011	0.016
0.33	4	64	256	1.0000	1.0000	3	0.00	0.201	0.277
0.33	4	64	256	1.0000	0.0100	2	0.00	0.001	0.024
0.33	4	64	256	1.0000	0.0100	3	0.50	0.072	2.411
0.33	4	64	256 256	1.0000	0.0001	3	1.00	0.053 0.050	0.068
0.33	4	64	256	0.0100	1.00001	2	0.00	0.050	0.069
0.33	4	64	256	0.0100	1.0000	3	0.00	0.017	0.026
0.33	4	64	256	0.0100	0.0100	2	1.00	0.283	0.400
0.33	4	64	256	0.0100	0.0100	3	1.00	0.033	0.079
0.33	4	64	256	0.0100	0.0001	2	1.00	0.068	0.144
0.33	4	64	256	0.0100	0.0001	3	1.00	0.079	0.977
0.33	4	64	256	0.0001	1.0000	2	0.00	0.025	0.041
0.33	4	64	256	0.0001	1.0000	3	0.00	0.414	0.641
0.33	4	64	256	0.0001	0.0100	2	1.00	0.061	0.096
0.33	4	64	256	0.0001	0.0100	3	1.00	0.065	0.095
0.33	4	64	256	0.0001	0.0001	2	1.00	0.075	0.121
0.33	4	64	256	0.0001	0.0001	3	1.00	0.076	0.121
0.33	4	256 256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	4	256	1	1.0000	1.0000 0.0100	3	0.67	0.003	0.016
0.33	4	256	1	1.0000	0.0100	3	0.50	0.001	0.001
0.33	4	256	1	1.0000	0.0001	2	0.00	0.003	0.001
0.33	4	256	1	1.0000	0.0001	3	0.67	0.003	0.017
0.33	4	256	1	0.0100	1.0000	2	0.17	0.001	0.003
0.33	4	256	1	0.0100	1.0000	3	0.83	0.003	0.016
0.33	4	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	4	256	1	0.0100	0.0100	3	0.83	0.003	0.016
0.33	4	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	4	256	1	0.0100	0.0001	3	0.67	0.003	0.016
0.33	4	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	4	256	1	0.0001	1.0000	3	0.67	0.003	0.015
0.33	4	256 256	1	0.0001	0.0100	3	0.00	0.001	0.001
0.33	4	256	1	0.0001	0.0100	2	0.67	0.003	0.014
0.33	4	256	1	0.0001	0.0001	3	1.00	0.001	0.001
0.33	4	256	4	1.0000	1.0000	2	0.00	0.003	0.003
0.33	4	256	4	1.0000	1.0000	3	0.17	0.004	0.017
0.33	4	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.33	4	256	4	1.0000	0.0100	3	1.00	0.003	0.004
0.33	4	256	4	1.0000	0.0001	2	0.33	0.001	0.004
0.33	4	256	4	1.0000	0.0001	3	1.00	0.003	0.004
0.33	4	256	4	0.0100	1.0000	2	0.00	0.001	0.002
0.33	4	256	4	0.0100	1.0000	3	0.67	0.003	0.023
0.33	4	256	4	0.0100	0.0100	2	0.33	0.001	0.004
0.33	4	256 256	4	0.0100	0.0100	3	0.67	0.003	0.022
0.33	4	256	4	0.0100	0.0001	3	0.67	0.001	0.005
0.33	4	256	4	0.0100	1.00001	2	0.83	0.003	0.018
0.33	4	256	4	0.0001	1.0000	3	0.33	0.001	0.003
0.33	4	256	4	0.0001	0.0100	2	0.83	0.003	0.019
0.33	4	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	4	256	4	0.0001	0.0001	2	0.67	0.001	0.004
0.33	4	256	4	0.0001	0.0001	3	1.00	0.004	0.004
						2	0.00	0.001	0.052
0.33	4	256	16	1.0000	1.0000				
0.33	4	256	16	1.0000	1.0000	3	1.00	0.004	0.005
	4								

0.33	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33										0.006
0.33										
0.33										
0.33										
0.33										
0.33										
0.33		4		16	0.0100	0.0001	3			
0.33										
0.33										
0.33										
0.33										
0.33										
0.33	0.33	4	256	64	1.0000	1.0000	2	0.00	0.001	0.004
0.33										
0.33										
0.33										
0.33										
0.33										
0.33										
0.33	0.33									
0.33										
0.33										
0.33										
0.33										
0.33										
0.33 4 256 64 0.0001 0.0001 3 1.00 0.021 0.023 0.33 4 256 256 1.0000 1.0000 2 0.00 0.001 0.071 0.33 4 256 256 1.0000 0.0100 2 0.00 0.001 0.016 0.33 4 256 256 1.0000 0.0100 2 0.00 0.001 0.016 0.33 4 256 256 1.0000 0.0001 2 0.83 0.001 0.074 0.33 4 256 256 1.0000 0.0001 2 0.00 0.001 0.072 0.33 4 256 256 0.0100 1.0000 2 0.00 0.001 0.027 0.33 4 256 256 0.0100 1.0000 3 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.0001 <	0.33	4		64	0.0001	0.0100	3	1.00	0.017	0.018
0.33										
0.33 4 256 256 1.0000 1.0000 3 0.00 0.204 0.263 0.33 4 256 256 1.0000 0.0100 2 0.00 0.001 0.016 0.33 4 256 256 1.0000 0.0001 2 0.33 0.001 0.071 0.33 4 256 256 1.0000 0.0001 2 0.00 0.051 0.074 0.33 4 256 256 0.0100 1.0000 2 0.00 0.001 0.027 0.33 4 256 256 0.0100 0.0100 2 1.00 0.072 0.078 0.33 4 256 256 0.0100 0.0100 2 1.00 0.066 0.078 0.33 4 256 256 0.0100 0.0100 3 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.001 <										
0.33 4 256 256 1.0000 0.0100 2 0.00 0.001 0.016 0.33 4 256 256 1.0000 0.0100 3 0.50 0.036 1.270 0.33 4 256 256 1.0000 0.0001 2 0.83 0.001 0.071 0.33 4 256 256 1.0000 0.0001 3 0.00 0.001 0.002 0.33 4 256 256 0.0100 1.0000 2 0.00 0.001 0.007 0.33 4 256 256 0.0100 0.0100 3 1.00 0.072 0.078 0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.0001 3 1.00 0.066 0.098 0.33 4 256 256 0.0001 1.0000										
0.33 4 256 256 1.0000 0.0100 3 0.50 0.036 1.270 0.33 4 256 256 1.0000 0.0001 2 0.83 0.001 0.071 0.33 4 256 256 1.0000 1.0000 2 0.00 0.001 0.027 0.33 4 256 256 0.0100 1.0000 2 0.00 0.001 0.027 0.33 4 256 256 0.0100 0.0100 2 1.00 0.072 0.078 0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.0001 3 1.00 0.062 0.096 0.33 4 256 256 0.0001 1.0000 3 1.00 0.062 0.096 0.33 4 256 256 0.0001 1.0000										
0.33 4 256 256 1.0000 0.0001 2 0.83 0.001 0.071 0.33 4 256 256 1.0000 0.0001 3 1.00 0.051 0.074 0.33 4 256 256 0.0100 1.0000 3 0.00 0.276 0.432 0.33 4 256 256 0.0100 1.0000 3 0.00 0.072 0.078 0.33 4 256 256 0.0100 0.0100 3 1.00 0.069 0.078 0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0001 1.0000 3 1.00 0.062 0.096 0.33 4 256 256 0.0001 1.0000 3 0.00 0.415 0.602 0.33 4 256 256 0.0001 0.0100										
0.33 4 256 256 0.0100 1.0000 2 0.00 0.001 0.027 0.33 4 256 256 0.0100 1.0000 3 0.00 0.276 0.432 0.33 4 256 256 0.0100 0.0100 3 1.00 0.069 0.078 0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.0001 3 1.00 0.062 0.096 0.33 4 256 256 0.0001 1.0000 2 0.00 0.025 0.040 0.33 4 256 256 0.0001 1.0000 3 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0100 2 1.00 0.115 0.124 0.33 4 256 256 0.0001 0.0001		4								
0.33 4 256 256 0.0100 1.0000 3 0.00 0.276 0.432 0.33 4 256 256 0.0100 0.0100 2 1.00 0.072 0.078 0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.0001 3 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.0001 3 1.00 0.066 0.096 0.33 4 256 256 0.0001 1.0000 3 0.00 0.415 0.602 0.33 4 256 256 0.0001 1.0000 3 1.00 0.073 0.09 0.33 4 256 256 0.0001 0.0100 2 1.00 0.073 0.09 0.33 4 256 256 0.0001 0.0010 <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>										
0.33 4 256 256 0.0100 0.0100 2 1.00 0.072 0.078 0.33 4 256 256 0.0100 0.0100 3 1.00 0.069 0.078 0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0001 1.0000 2 0.00 0.025 0.040 0.33 4 256 256 0.0001 1.0000 3 0.00 0.415 0.602 0.33 4 256 256 0.0001 1.0000 3 0.00 0.415 0.602 0.33 4 256 256 0.0001 0.0100 3 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0100 3 1.00 0.115 0.124 0.33 16 1 1 1.0000 1.0001 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>										
0.33 4 256 256 0.0100 0.0100 3 1.00 0.069 0.078 0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0001 1.0000 2 0.00 0.025 0.040 0.33 4 256 256 0.0001 1.0000 2 0.00 0.0415 0.602 0.33 4 256 256 0.0001 1.0000 3 1.00 0.079 0.100 0.33 4 256 256 0.0001 0.0100 3 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0001 2 1.00 0.115 0.124 0.33 1 256 256 0.0001 0.0001 3 1.00 0.110 1.12 0.33 16 1 1 1.0000 1.0000 <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>										
0.33 4 256 256 0.0100 0.0001 2 1.00 0.066 0.098 0.33 4 256 256 0.0100 0.0001 3 1.00 0.062 0.096 0.33 4 256 256 0.0001 1.0000 2 0.00 0.025 0.040 0.33 4 256 256 0.0001 0.0100 2 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0100 2 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0001 3 1.00 0.0115 0.124 0.33 4 256 256 0.0001 0.0001 3 1.00 0.115 0.124 0.33 16 1 1.0000 1.00001 3 0.67 0.001 0.001 0.33 16 1 1.0000 0.0100 2 0.00 <										
0.33 4 256 256 0.0100 0.0001 3 1.00 0.062 0.096 0.33 4 256 256 0.0001 1.0000 2 0.00 0.025 0.040 0.33 4 256 256 0.0001 0.0100 2 1.00 0.079 0.100 0.33 4 256 256 0.0001 0.0100 2 1.00 0.079 0.100 0.33 4 256 256 0.0001 0.0100 3 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0001 2 1.00 0.115 0.124 0.33 16 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 3 <td></td>										
0.33 4 256 256 0.0001 1.0000 3 0.00 0.415 0.602 0.33 4 256 256 0.0001 0.0100 2 1.00 0.079 0.100 0.33 4 256 256 0.0001 0.0001 2 1.00 0.015 0.099 0.33 4 256 256 0.0001 0.0001 2 1.00 0.115 0.124 0.33 16 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 1.0000 3 0.67 0.004 0.016 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 3 0.67 0.003 0.014 0.33 16 1 1 1.0000 0.0001 3										
0.33 4 256 256 0.0001 0.0100 2 1.00 0.079 0.100 0.33 4 256 256 0.0001 0.0100 3 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0001 2 1.00 0.115 0.124 0.33 4 256 256 0.0001 0.0001 3 1.00 0.101 0.124 0.33 16 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 3 0.67 0.003 0.014 0.33 16 1 1 0.0000 0.0001 3			256		0.0001	1.0000	2	0.00	0.025	0.040
0.33 4 256 256 0.0001 0.0100 3 1.00 0.073 0.099 0.33 4 256 256 0.0001 0.0001 2 1.00 0.115 0.124 0.33 4 256 256 0.0001 0.0001 3 1.00 0.101 0.124 0.33 16 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 3 0.67 0.003 0.014 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 1.0000 2										
0.33 4 256 256 0.0001 0.0001 2 1.00 0.115 0.124 0.33 4 256 256 0.0001 0.0001 3 1.00 0.101 0.128 0.33 16 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 3 0.67 0.003 0.014 0.33 16 1 1 1.0000 0.0001 3 0.67 0.003 0.014 0.33 16 1 1 0.0000 0.0001 3 0.67 0.003 0.014 0.33 16 1 1 0.0100 1.00001 3 <										
0.33 4 256 256 0.0001 0.0001 3 1.00 0.101 0.128 0.33 16 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0100 3 0.67 0.003 0.014 0.33 16 1 1 1.0000 0.0001 3 0.67 0.003 0.014 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 2 0										
0.33 16 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 1.0000 3 0.67 0.004 0.016 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 1.0000 3 0.67 0.003 0.014 0.33 16 1 1 0.0100 0.0100 3 0.50										
0.33 16 1 1 1.0000 1.0000 3 0.67 0.004 0.016 0.33 16 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 1.0000 3 0.67 0.003 0.014 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 3 0.50										
0.33 16 1 1 1.0000 0.0100 3 0.67 0.003 0.014 0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 3 0.50 0.003 0.014 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 3 0.83						1.0000			0.004	
0.33 16 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 1.0000 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 3 0.50 0.003 0.014 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0001 1.0000 3 0.83										
0.33 16 1 1 1.0000 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.1000 3 0.67 0.003 0.014 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 2 0.00 0.003 0.014 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 3 0.83										
0.33 16 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 1.0000 3 0.67 0.003 0.014 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 3 0.83 0.003 0.013 0.33 16 1 1 0.0001 0.0100 2 0.00										
0.33 16 1 1 0.0100 1.0000 3 0.67 0.003 0.014 0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 3 0.83 0.003 0.013 0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0100 2 0.00										
0.33 16 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0100 3 0.50 0.003 0.014 0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0010 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 3 0.17										
0.33 16 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0100 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 3 0.83 0.003 0.013 0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0100 3 0.17 0.004 0.016 0.33 16 1 1 0.0001 0.0010 3 0.17 0.004 0.001 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 4 1.0000 1.0000 2 0.00										
0.33 16 1 1 0.0100 0.0001 3 0.83 0.003 0.014 0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 3 0.83 0.003 0.013 0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.016 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 3 0.83 0.003 0.017 0.33 16 1 4 1.0000 1.0000 3 0.00										
0.33 16 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 1.0000 3 0.83 0.003 0.013 0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 3 0.83 0.003 0.017 0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 1.0000 3 0.00 0.016 0.023 0.33 16 1 4 1.0000 0.0100 3 0.83										
0.33 16 1 1 0.0001 1.0000 3 0.83 0.003 0.013 0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 3 0.17 0.004 0.016 0.33 16 1 1 0.0001 0.0001 3 0.83 0.003 0.017 0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 1.0000 3 0.00 0.016 0.023 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 2 0.00										
0.33 16 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0100 3 0.17 0.004 0.016 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 1.0000 3 0.00 0.016 0.023 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83										
0.33 16 1 1 0.0001 0.0100 3 0.17 0.004 0.016 0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 3 0.83 0.003 0.017 0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83 0.003 0.022 0.33 16 1 4 1.0000 0.0001 2 0.00										
0.33 16 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.33 16 1 1 0.0001 0.0001 3 0.83 0.003 0.017 0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.023 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.022 0.33 16 1 4 1.0000 0.0000 3 0.83 0.003 0.022 0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83										
0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 1.0000 3 0.00 0.016 0.023 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83 0.004 0.022 0.33 16 1 4 1.0000 1.0000 2 0.00 0.001 0.001										
0.33 16 1 4 1.0000 1.0000 3 0.00 0.016 0.023 0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0010 3 0.83 0.003 0.022 0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83 0.004 0.022 0.33 16 1 4 0.0100 1.0000 2 0.00 0.001 0.001										
0.33 16 1 4 1.0000 0.0100 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0100 3 0.83 0.003 0.022 0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83 0.004 0.022 0.33 16 1 4 0.0100 1.0000 2 0.00 0.001 0.001										
0.33 16 1 4 1.0000 0.0100 3 0.83 0.003 0.022 0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83 0.004 0.022 0.33 16 1 4 0.0100 1.0000 2 0.00 0.001 0.001										
0.33 16 1 4 1.0000 0.0001 2 0.00 0.001 0.002 0.33 16 1 4 1.0000 0.0001 3 0.83 0.004 0.022 0.33 16 1 4 0.0100 1.0000 2 0.00 0.001 0.001										
0.33 16 1 4 1.0000 0.0001 3 0.83 0.004 0.022 0.33 16 1 4 0.0100 1.0000 2 0.00 0.001 0.001										
0.33 16 1 4 0.0100 1.0000 3 0.50 0.006 0.021	0.33		1	4	0.0100	1.0000		0.00	0.001	0.001
	0.33	16	1	4	0.0100	1.0000	3	0.50	0.006	0.021

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	16	1	4	0.0100	0.0100	2	0.67	0.001	0.004
0.33	16	1	4	0.0100	0.0100	3	0.67	0.003	0.018
0.33	16	1	4	0.0100	0.0001	2	0.50	0.001	0.004
0.33	16	1	4	0.0100	0.0001	3	1.00	0.003	0.007
0.33	16	1	4	0.0001	1.0000	2	0.50	0.001	0.004
0.33	16 16	1	4	0.0001	1.0000	2	0.50	0.003	0.022
0.33	16	1	4	0.0001	0.0100	3	0.67 1.00	0.001	0.004
0.33	16	1	4	0.0001	0.0001	2	1.00	0.003	0.003
0.33	16	1	4	0.0001	0.0001	3	1.00	0.003	0.003
0.33	16	1	16	1.0000	1.0000	2	0.00	0.001	0.002
0.33	16	1	16	1.0000	1.0000	3	0.00	0.021	0.029
0.33	16	1	16	1.0000	0.0100	2	0.17	0.001	0.005
0.33	16	1	16	1.0000	0.0100	3	1.00	0.004	0.009
0.33	16	1	16	1.0000	0.0001	2	0.83	0.001	0.005
0.33	16	1	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	16 16	1	16 16	0.0100	1.0000	3	0.00	0.001	0.003
0.33	16	1	16	0.0100	0.0100	2	1.00	0.024	0.036
0.33	16	1	16	0.0100	0.0100	3	1.00	0.004	0.006
0.33	16	1	16	0.0100	0.0001	2	0.83	0.001	0.006
0.33	16	1	16	0.0100	0.0001	3	1.00	0.006	0.011
0.33	16	1	16	0.0001	1.0000	2	0.00	0.001	0.003
0.33	16	1	16	0.0001	1.0000	3	0.00	0.038	0.046
0.33	16	1	16	0.0001	0.0100	2	1.00	0.006	0.006
0.33	16	1	16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	16	1	16	0.0001	0.0001	2	1.00	0.006	0.007
0.33	16	1	16	0.0001	0.0001	3	1.00	0.006	0.007
0.33	16 16	1	64	1.0000	1.0000	3	0.00	0.003	0.004
0.33	16	1	64	1.0000	0.0100	2	0.83	0.049	0.080
0.33	16	1	64	1.0000	0.0100	3	1.00	0.003	0.017
0.33	16	1	64	1.0000	0.0001	2	1.00	0.014	0.014
0.33	16	1	64	1.0000	0.0001	3	1.00	0.013	0.014
0.33	16	1	64	0.0100	1.0000	2	0.00	0.005	0.006
0.33	16	1	64	0.0100	1.0000	3	0.00	0.080	0.660
0.33	16	1	64	0.0100	0.0100	2	1.00	0.014	0.015
0.33	16	1	64	0.0100	0.0100	3	1.00	0.013	0.014
0.33	16	1	64	0.0100	0.0001	2	1.00	0.016	0.017
0.33	16 16	1	64 64	0.0100	1.0000	3	1.00 0.00	0.016	0.017
0.33	16	1	64	0.0001	1.0000	3	0.00	0.008	0.126
0.33	16	1	64	0.0001	0.0100	2	1.00	0.113	0.120
0.33	16	1	64	0.0001	0.0100	3	1.00	0.011	0.017
0.33	16	1	64	0.0001	0.0001	2	1.00	0.015	0.021
0.33	16	1	64	0.0001	0.0001	3	1.00	0.016	0.021
0.33	16	1	256	1.0000	1.0000	2	0.00	0.010	0.017
0.33	16	1	256	1.0000	1.0000	3	0.00	0.180	0.272
0.33	16	1	256	1.0000	0.0100	2	0.00	0.016	0.025
0.33	16	1	256	1.0000	0.0100	3	0.00	0.273	1.204
0.33	16	1	256	1.0000	0.0001	2	1.00	0.049	0.074
0.33	16 16	1	256 256	1.0000 0.0100	0.0001 1.0000	3 2	1.00 0.00	0.059	0.073
0.33	16	1	256	0.0100	1.0000	3	0.00	0.017	0.027
0.33	16	1	256	0.0100	0.0100	2	1.00	0.283	0.433
0.33	16	1	256	0.0100	0.0100	3	1.00	0.046	0.087
0.33	16	1	256	0.0100	0.0001	2	1.00	0.076	0.097
0.33	16	1	256	0.0100	0.0001	3	1.00	0.087	0.097
0.33	16	1	256	0.0001	1.0000	2	0.00	0.025	0.041
0.33	16	1	256	0.0001	1.0000	3	0.00	0.614	1.193
0.33	16	1	256	0.0001	0.0100	2	1.00	0.065	0.100
0.33	16	1	256	0.0001	0.0100	3	1.00	0.070	0.096
0.33	16	1	256	0.0001	0.0001	2	1.00	0.074	0.116
0.33	16 16	1 4	256	1.00001	0.0001 1.0000	2	1.00 0.00	0.078	0.117
0.33	16	4	1	1.0000	1.0000	3	0.67	0.001	0.001
0.33	16	4	1	1.0000	0.0100	2	0.00	0.003	0.001
0.33	16	4	1	1.0000	0.0100	3	0.50	0.004	0.015
0.33	16	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	16	4	1	1.0000	0.0001	3	0.50	0.004	0.015
0.33	16	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	16	4	1	0.0100	1.0000	3	1.00	0.003	0.006
0.33	16	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	16	4	1	0.0100	0.0100	3	0.83	0.003	0.012
0.33	16	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	16	4	1	0.0100	0.0001	3	0.50	0.003	0.014

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	16	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	16 16	4	1	0.0001	1.0000 0.0100	3	0.67	0.003	0.027
0.33	16	4	1	0.0001	0.0100	3	1.00	0.001	0.001
0.33	16	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	16	4	1	0.0001	0.0001	3	0.67	0.005	0.015
0.33	16	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	16 16	4	4	1.0000	1.0000 0.0100	3	0.17	0.004	0.018
0.33	16	4	4	1.0000	0.0100	3	1.00	0.003	0.011
0.33	16	4	4	1.0000	0.0001	2	0.50	0.001	0.004
0.33	16	4	4	1.0000	0.0001	3	1.00	0.004	0.007
0.33	16 16	4	4	0.0100	1.0000	3	0.17	0.001	0.004
0.33	16	4	4	0.0100	0.0100	2	0.33	0.001	0.004
0.33	16	4	4	0.0100	0.0100	3	0.83	0.004	0.018
0.33	16	4	4	0.0100	0.0001	2	0.67	0.001	0.004
0.33	16 16	4	4	0.0100	0.0001 1.0000	3	1.00 0.50	0.003	0.008
0.33	16	4	4	0.0001	1.0000	3	0.50	0.001	0.004
0.33	16	4	4	0.0001	0.0100	2	0.83	0.001	0.004
0.33	16	4	4	0.0001	0.0100	3	1.00	0.003	0.006
0.33	16 16	4	4	0.0001	0.0001	3	0.33	0.001	0.004 0.016
0.33	16	4	16	1.0000	1.0000	2	0.83	0.004	0.002
0.33	16	4	16	1.0000	1.0000	3	0.00	0.026	0.031
0.33	16	4	16	1.0000	0.0100	2	0.50	0.001	0.005
0.33	16 16	4	16 16	1.0000	0.0100	3	1.00 0.67	0.005	0.011
0.33	16	4	16	1.0000	0.0001	3	1.00	0.001	0.006
0.33	16	4	16	0.0100	1.0000	2	0.00	0.001	0.002
0.33	16	4	16	0.0100	1.0000	3	0.00	0.025	0.036
0.33	16	4	16	0.0100	0.0100	2	1.00	0.004	0.006
0.33	16 16	4	16 16	0.0100	0.0100	3	1.00 0.83	0.004	0.006
0.33	16	4	16	0.0100	0.0001	3	1.00	0.005	0.011
0.33	16	4	16	0.0001	1.0000	2	0.00	0.001	0.003
0.33	16	4	16	0.0001	1.0000	3	0.00	0.035	0.043
0.33	16 16	4	16 16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	16	4	16	0.0001	0.0001	2	1.00	0.005	0.006
0.33	16	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.33	16	4	64	1.0000	1.0000	2	0.00	0.001	0.003
0.33	16 16	4	64 64	1.0000	1.0000 0.0100	3	0.00	0.046	0.058
0.33	16	4	64	1.0000	0.0100	3	1.00	0.001	0.012
0.33	16	4	64	1.0000	0.0001	2	1.00	0.009	0.011
0.33	16	4	64	1.0000	0.0001	3	1.00	0.009	0.010
0.33	16	4	64	0.0100	1.0000	2	0.00	0.004	0.005
0.33	16 16	4	64 64	0.0100	1.0000 0.0100	3	0.00 1.00	0.062	0.102 0.016
0.33	16	4	64	0.0100	0.0100	3	1.00	0.010	0.015
0.33	16	4	64	0.0100	0.0001	2	1.00	0.016	0.018
0.33	16	4	64	0.0100	0.0001	3	1.00	0.016	0.018
0.33	16 16	4	64	0.0001	1.0000	3	0.00	0.006	0.008 0.128
0.33	16	4	64	0.0001	0.0100	2	1.00	0.016	0.128
0.33	16	4	64	0.0001	0.0100	3	1.00	0.012	0.018
0.33	16	4	64	0.0001	0.0001	2	1.00	0.017	0.023
0.33	16 16	4	64 256	0.0001 1.0000	0.0001 1.0000	2	1.00 0.00	0.014 0.014	0.023 0.017
0.33	16	4	256	1.0000	1.0000	3	0.00	0.014	1.004
0.33	16	4	256	1.0000	0.0100	2	0.00	0.001	0.026
0.33	16	4	256	1.0000	0.0100	3	0.00	0.274	0.431
0.33	16	4	256	1.0000	0.0001	2	1.00	0.045	0.073
0.33	16 16	4	256 256	1.0000 0.0100	0.0001 1.0000	2	1.00	0.045 0.018	0.074 0.028
0.33	16	4	256	0.0100	1.0000	3	0.00	0.295	0.938
0.33	16	4	256	0.0100	0.0100	2	1.00	0.046	0.068
0.33	16	4	256	0.0100	0.0100	3	1.00	0.046	0.067
0.33	16 16	4	256 256	0.0100	0.0001	2	1.00	0.065	0.098
0.33	16	4	256	0.0001	1.0000	2	0.00	0.028	0.041
0.33	16	4	256	0.0001	1.0000	3	0.00	0.424	0.879
0.33	16	4	256	0.0001	0.0100	2	1.00	0.094	0.098
0.33	16	4	256	0.0001	0.0100	3	1.00	0.086	0.098

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	16	4	256	0.0001	0.0001	2	1.00	0.119	0.126
0.33	16	4	256	0.0001	0.0001	3	1.00	0.120	0.124
0.33	16	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	16	16	1	1.0000	1.0000	3	1.00	0.003	0.012
0.33	16	16	1	1.0000	0.0100	2	0.00	0.001	0.147
0.33	16 16	16 16	1	1.0000	0.0100	2	0.83	0.003	0.016
0.33	16	16	1	1.0000	0.0001	3	0.67	0.001	0.001
0.33	16	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	16	16	1	0.0100	1.0000	3	0.83	0.003	0.030
0.33	16	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	16	16	1	0.0100	0.0100	3	0.83	0.003	0.017
0.33	16	16	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	16 16	16 16	1	0.0100	0.0001	3	0.83	0.003	0.017
0.33	16	16	1	0.0001	1.0000	3	0.83	0.001	0.001
0.33	16	16	1	0.0001	0.0100	2	0.00	0.003	0.001
0.33	16	16	1	0.0001	0.0100	3	0.83	0.003	0.016
0.33	16	16	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	16	16	1	0.0001	0.0001	3	0.83	0.003	0.016
0.33	16	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	16	16	4	1.0000	1.0000	3	0.17	0.003	0.021
0.33	16 16	16 16	4	1.0000	0.0100	3	1.00	0.001	0.001
0.33	16	16	4	1.0000	0.0100	2	0.17	0.004	0.009
0.33	16	16	4	1.0000	0.0001	3	1.00	0.001	0.004
0.33	16	16	4	0.0100	1.0000	2	0.17	0.001	0.003
0.33	16	16	4	0.0100	1.0000	3	0.50	0.003	0.038
0.33	16	16	4	0.0100	0.0100	2	0.67	0.001	0.003
0.33	16	16	4	0.0100	0.0100	3	1.00	0.003	0.006
0.33	16	16	4	0.0100	0.0001	2	0.50	0.001	0.004
0.33	16 16	16 16	4	0.0100	1.0000	2	0.83	0.003	0.017
0.33	16	16	4	0.0001	1.0000	3	0.83	0.001	0.004
0.33	16	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.33	16	16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	16	16	4	0.0001	0.0001	2	1.00	0.003	0.004
0.33	16	16	4	0.0001	0.0001	3	1.00	0.003	0.004
0.33	16	16	16	1.0000	1.0000	2	0.00	0.001	0.001
0.33	16 16	16 16	16 16	1.0000	1.0000 0.0100	3	0.00	0.022	0.028
0.33	16	16	16	1.0000	0.0100	3	1.00	0.001	0.004
0.33	16	16	16	1.0000	0.0001	2	0.33	0.004	0.006
0.33	16	16	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	16	16	16	0.0100	1.0000	2	0.00	0.001	0.001
0.33	16	16	16	0.0100	1.0000	3	0.17	0.005	0.033
0.33	16	16	16	0.0100	0.0100	2	1.00	0.005	0.006
0.33	16	16	16	0.0100	0.0100	3	1.00	0.005	0.006
0.33	16 16	16 16	16 16	0.0100	0.0001	3	1.00	0.004	0.006
0.33	16	16	16	0.0100	1.00001	2	0.50	0.004	0.006
0.33	16	16	16	0.0001	1.0000	3	0.50	0.001	0.003
0.33	16	16	16	0.0001	0.0100	2	1.00	0.006	0.006
0.33	16	16	16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	16	16	16	0.0001	0.0001	2	1.00	0.005	0.007
0.33	16	16	16	0.0001	0.0001	3	1.00	0.006	0.007
0.33	16 16	16 16	64 64	1.0000	1.0000	3	0.00	0.001	0.004
0.33	16	16	64	1.0000	0.0100	2	0.50	0.043	0.008
0.33	16	16	64	1.0000	0.0100	3	1.00	0.001	0.008
0.33	16	16	64	1.0000	0.0001	2	1.00	0.010	0.011
0.33	16	16	64	1.0000	0.0001	3	1.00	0.009	0.010
0.33	16	16	64	0.0100	1.0000	2	0.00	0.001	0.005
0.33	16	16	64	0.0100	1.0000	3	0.00	0.060	0.083
0.33	16	16	64 64	0.0100	0.0100	2	1.00	0.011	0.015
0.33	16 16	16 16	64	0.0100	0.0100	2	1.00	0.013 0.016	0.015 0.018
0.33	16	16	64	0.0100	0.0001	3	1.00	0.010	0.018
0.33	16	16	64	0.0001	1.0000	2	0.00	0.006	0.009
0.33	16	16	64	0.0001	1.0000	3	0.00	0.096	0.132
0.33	16	16	64	0.0001	0.0100	2	1.00	0.012	0.018
0.33	16	16	64	0.0001	0.0100	3	1.00	0.015	0.018
0.33	16	16	64	0.0001	0.0001	2	1.00	0.017	0.022
0.33	16	16	64	0.0001	0.0001	3	1.00	0.014	0.022
0.33	16 16	16	256 256	1.0000	1.0000	2	0.00	0.011	0.384
0.33	10	16	230	1.0000	1.0000	3	0.00	0.181	0.200

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	16	16	256	1.0000	0.0100	2	0.50	0.001	0.054
0.33	16	16	256	1.0000	0.0100	3	0.50	0.044	0.411
0.33	16 16	16	256 256	1.0000	0.0001	3	1.00	0.048	0.072 0.072
0.33	16	16 16	256	0.0100	1.0000	2	0.00	0.049	0.072
0.33	16	16	256	0.0100	1.0000	3	0.00	0.325	0.515
0.33	16	16	256	0.0100	0.0100	2	1.00	0.053	0.074
0.33	16	16	256	0.0100	0.0100	3	1.00	0.051	0.075
0.33	16	16	256	0.0100	0.0001	2	1.00	0.058	0.098
0.33	16 16	16 16	256 256	0.0100	1.0000	3	1.00 0.00	0.058	0.092
0.33	16	16	256	0.0001	1.0000	3	0.00	0.428	1.612
0.33	16	16	256	0.0001	0.0100	2	1.00	0.092	0.098
0.33	16	16	256	0.0001	0.0100	3	1.00	0.073	0.097
0.33	16 16	16 16	256 256	0.0001	0.0001	2	1.00	0.075 0.076	0.122 0.121
0.33	16	64	230	1.0000	1.00001	2	0.00	0.076	0.001
0.33	16	64	1	1.0000	1.0000	3	0.67	0.003	0.014
0.33	16	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	16	64	1	1.0000	0.0100	3	0.83	0.003	0.014
0.33	16	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	16 16	64	1	1.0000 0.0100	0.0001 1.0000	3	0.83	0.003	0.013
0.33	16	64	1	0.0100	1.0000	3	0.50	0.003	0.001
0.33	16	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	16	64	1	0.0100	0.0100	3	0.67	0.003	0.016
0.33	16 16	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	16	64	1	0.0100	1.00001	3	0.67	0.003	0.016
0.33	16	64	1	0.0001	1.0000	3	0.50	0.003	0.016
0.33	16	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	16	64	1	0.0001	0.0100	3	0.67	0.003	0.016
0.33	16 16	64	1	0.0001	0.0001	3	0.00	0.001	0.001
0.33	16	64	4	1.0000	1.00001	2	0.07	0.003	0.001
0.33	16	64	4	1.0000	1.0000	3	0.67	0.003	0.421
0.33	16	64	4	1.0000	0.0100	2	0.17	0.001	0.004
0.33	16	64	4	1.0000	0.0100	3	0.83	0.003	0.013
0.33	16 16	64	4	1.0000	0.0001	3	0.33 1.00	0.001	0.004
0.33	16	64	4	0.0100	1.0000	2	0.17	0.004	0.004
0.33	16	64	4	0.0100	1.0000	3	0.50	0.003	0.019
0.33	16	64	4	0.0100	0.0100	2	0.33	0.001	0.003
0.33	16	64	4	0.0100	0.0100	3	0.83	0.003	0.018
0.33	16 16	64	4	0.0100	0.0001	3	0.83 1.00	0.001	0.004
0.33	16	64	4	0.0100	1.0000	2	0.50	0.003	0.004
0.33	16	64	4	0.0001	1.0000	3	0.67	0.004	0.022
0.33	16	64	4	0.0001	0.0100	2	1.00	0.003	0.004
0.33	16	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	16 16	64	4	0.0001	0.0001	3	0.83 1.00	0.001	0.004 0.004
0.33	16	64	16	1.0000	1.0000	2	0.00	0.003	0.004
0.33	16	64	16	1.0000	1.0000	3	0.17	0.005	0.029
0.33	16	64	16	1.0000	0.0100	2	0.67	0.001	0.005
0.33	16 16	64	16 16	1.0000	0.0100	3	1.00 0.83	0.005 0.001	0.005
0.33	16	64	16	1.0000	0.0001	3	1.00	0.001	0.006
0.33	16	64	16	0.0100	1.0000	2	0.00	0.001	0.002
0.33	16	64	16	0.0100	1.0000	3	0.50	0.005	0.036
0.33	16	64	16	0.0100	0.0100	2	1.00	0.004	0.006
0.33	16 16	64	16 16	0.0100	0.0100	3 2	1.00	0.004	0.006
0.33	16	64	16	0.0100	0.0001	3	1.00	0.006	0.006
0.33	16	64	16	0.0001	1.0000	2	0.17	0.001	0.004
0.33	16	64	16	0.0001	1.0000	3	0.17	0.004	0.035
0.33	16	64	16	0.0001	0.0100	2	1.00	0.004	0.006
0.33	16 16	64	16 16	0.0001	0.0100	3	1.00	0.004	0.007
0.33	16	64	16	0.0001	0.0001	3	1.00	0.005	0.007
0.33	16	64	64	1.0000	1.0000	2	0.00	0.001	0.005
0.33	16	64	64	1.0000	1.0000	3	0.00	0.052	0.067
0.33	16	64	64	1.0000	0.0100	2	0.83	0.001	0.008
0.33	16 16	64	64	1.0000	0.0100	3	1.00	0.007	0.009
0.33	16	64	64	1.0000	0.0001	3	1.00	0.010	0.011
				1.5000				2.310	

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	16	64	64	0.0100	1.0000	2	0.00	0.001	0.005
0.33	16	64	64	0.0100	1.0000	3	0.00	0.057	0.153
0.33	16	64	64	0.0100	0.0100	2	1.00	0.011	0.015
0.33	16	64	64	0.0100	0.0100	3	1.00	0.010	0.014
0.33	16	64	64	0.0100	0.0001	2	1.00	0.012	0.014
0.33	16	64	64	0.0100	0.0001	3	1.00	0.011	0.015
0.33	16	64	64	0.0001	1.0000	2	0.00	0.001	0.008
0.33	16	64	64	0.0001	1.0000	3	0.00	0.082	0.125
0.33	16	64	64	0.0001	0.0100	2	1.00	0.012	0.019
0.33	16	64	64	0.0001	0.0100	3	1.00	0.011	0.018
0.33	16 16	64	64	0.0001	0.0001	2	1.00	0.017 0.016	0.022 0.022
0.33	16	64	256	1.0000	1.0000	2	0.00	0.010	0.022
0.33	16	64	256	1.0000	1.0000	3	0.00	0.180	0.880
0.33	16	64	256	1.0000	0.0100	2	0.00	0.001	0.025
0.33	16	64	256	1.0000	0.0100	3	0.17	0.132	0.427
0.33	16	64	256	1.0000	0.0001	2	1.00	0.050	0.074
0.33	16	64	256	1.0000	0.0001	3	1.00	0.049	0.074
0.33	16	64	256	0.0100	1.0000	2	0.00	0.017	0.026
0.33	16	64	256	0.0100	1.0000	3	0.00	0.360	0.963
0.33	16	64	256	0.0100	0.0100	2	1.00	0.075	0.080
0.33	16	64	256	0.0100	0.0100	3	1.00	0.055	0.079
0.33	16	64	256 256	0.0100	0.0001	2	1.00	0.058	0.062
0.33	16	64		0.0100	0.0001	3		0.057	0.063
0.33	16 16	64	256 256	0.0001	1.0000	3	0.00	0.027	0.041 1.232
0.33	16	64	256	0.0001	0.0100	2	1.00	0.044	0.100
0.33	16	64	256	0.0001	0.0100	3	1.00	0.083	0.100
0.33	16	64	256	0.0001	0.0001	2	1.00	0.074	0.101
0.33	16	64	256	0.0001	0.0001	3	1.00	0.074	0.108
0.33	16	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	16	256	1	1.0000	1.0000	3	0.83	0.003	0.013
0.33	16	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	16	256	1	1.0000	0.0100	3	0.67	0.003	0.014
0.33	16	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	16	256	1	1.0000	0.0001	3	0.67	0.003	0.016
0.33	16	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	16 16	256 256	1	0.0100	1.0000 0.0100	2	0.67	0.003	0.014
0.33	16	256	1	0.0100	0.0100	3	0.50	0.001	0.001
0.33	16	256	1	0.0100	0.0001	2	0.00	0.003	0.001
0.33	16	256	1	0.0100	0.0001	3	0.67	0.003	0.015
0.33	16	256	1	0.0001	1.0000	2	0.00	0.001	0.005
0.33	16	256	1	0.0001	1.0000	3	0.83	0.002	0.012
0.33	16	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	16	256	1	0.0001	0.0100	3	0.33	0.003	0.016
0.33	16	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	16	256	1	0.0001	0.0001	3	0.50	0.003	0.016
0.33	16	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	16	256	4	1.0000	1.0000	3	0.50	0.003	0.018
0.33	16	256	4	1.0000	0.0100	2	0.33	0.001	0.004
0.33	16 16	256 256	4	1.0000	0.0100	3 2	1.00 0.83	0.003	0.004
0.33	16	256	4	1.0000	0.0001	3	1.00	0.001	0.003
0.33	16	256	4	0.0100	1.0000	2	0.00	0.003	0.004
0.33	16	256	4	0.0100	1.0000	3	0.83	0.003	0.001
0.33	16	256	4	0.0100	0.0100	2	0.50	0.001	0.004
0.33	16	256	4	0.0100	0.0100	3	1.00	0.004	0.004
0.33	16	256	4	0.0100	0.0001	2	0.33	0.001	0.004
0.33	16	256	4	0.0100	0.0001	3	1.00	0.003	0.036
0.33	16	256	4	0.0001	1.0000	2	0.00	0.001	0.001
0.33	16	256	4	0.0001	1.0000	3	0.50	0.003	0.018
0.33	16	256	4	0.0001	0.0100	2	1.00	0.003	0.004
0.33	16	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	16	256	4	0.0001	0.0001	2	0.50	0.001	0.004
0.33	16 16	256 256	4 16	0.0001 1.0000	0.0001 1.0000	2	1.00	0.004	0.008
0.33	16	256	16	1.0000	1.0000	3	0.50	0.001	0.001
0.33	16	256	16	1.0000	0.0100	2	0.33	0.001	0.020
0.33	16	256	16	1.0000	0.0100	3	1.00	0.001	0.004
0.33	16	256	16	1.0000	0.0001	2	0.83	0.001	0.006
		256	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	16	250							
0.33	16	256	16	0.0100	1.0000	2	0.00	0.001	0.001
				0.0100 0.0100	1.0000	3	0.00	0.001	0.001
0.33	16	256	16						

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	16	256	16	0.0100	0.0001	2	0.83	0.001	0.006
0.33	16	256	16	0.0100	0.0001	3	1.00	0.001	0.005
0.33	16	256	16	0.0001	1.0000	2	0.17	0.003	0.006
0.33	16	256	16	0.0001	1.0000	3	0.33	0.005	0.043
0.33	16	256	16	0.0001	0.0100	2	1.00	0.005	0.006
0.33	16	256	16	0.0001	0.0100	3	1.00	0.004	0.006
0.33	16	256	16	0.0001	0.0001	2	1.00	0.005	0.007
0.33	16	256	16	0.0001	0.0001	3	1.00	0.007	0.007
0.33	16	256	64	1.0000	1.0000	2	0.00	0.001	0.005
0.33	16	256 256	64	1.0000	1.0000 0.0100	3	0.00	0.048	0.067
0.33	16 16	256	64	1.0000	0.0100	3	1.00	0.001	0.009
0.33	16	256	64	1.0000	0.0001	2	0.67	0.001	0.003
0.33	16	256	64	1.0000	0.0001	3	1.00	0.010	0.012
0.33	16	256	64	0.0100	1.0000	2	0.00	0.001	0.004
0.33	16	256	64	0.0100	1.0000	3	0.17	0.019	0.062
0.33	16	256	64	0.0100	0.0100	2	1.00	0.010	0.026
0.33	16	256	64	0.0100	0.0100	3	1.00	0.010	0.011
0.33	16	256	64	0.0100	0.0001	2	1.00	0.011	0.019
0.33	16	256	64	0.0100	0.0001	3	1.00	0.011	0.018
0.33	16 16	256 256	64 64	0.0001	1.0000	2	0.17 0.17	0.001	0.016
0.33	16	256	64	0.0001	0.0100	2	1.00	0.013	0.120
0.33	16	256	64	0.0001	0.0100	3	1.00	0.011	0.019
0.33	16	256	64	0.0001	0.0001	2	1.00	0.014	0.023
0.33	16	256	64	0.0001	0.0001	3	1.00	0.016	0.034
0.33	16	256	256	1.0000	1.0000	2	0.00	0.001	0.049
0.33	16	256	256	1.0000	1.0000	3	0.00	0.183	0.807
0.33	16	256	256	1.0000	0.0100	2	0.00	0.001	0.017
0.33	16	256	256	1.0000	0.0100	3	0.67	0.038	0.377
0.33	16	256	256	1.0000	0.0001	2	0.83	0.001	0.077
0.33	16	256 256	256 256	1.0000	1.0000	3	1.00 0.00	0.056	0.073
0.33	16 16	256	256	0.0100	1.0000	3	0.00	0.001	0.028 2.918
0.33	16	256	256	0.0100	0.0100	2	1.00	0.064	0.080
0.33	16	256	256	0.0100	0.0100	3	1.00	0.073	0.080
0.33	16	256	256	0.0100	0.0001	2	1.00	0.060	0.067
0.33	16	256	256	0.0100	0.0001	3	1.00	0.060	0.073
0.33	16	256	256	0.0001	1.0000	2	0.00	0.001	0.041
0.33	16	256	256	0.0001	1.0000	3	0.00	0.393	1.075
0.33	16	256	256	0.0001	0.0100	2	1.00	0.088	0.097
0.33	16	256	256	0.0001	0.0100	3	1.00	0.083	0.096
0.33	16 16	256 256	256 256	0.0001	0.0001	3	1.00	0.080	0.123 0.125
0.33	64	1	1	1.0000	1.0000	2	0.00	0.093	0.001
0.33	64	1	1	1.0000	1.0000	3	0.83	0.003	0.013
0.33	64	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	64	1	1	1.0000	0.0100	3	0.67	0.003	0.016
0.33	64	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	64	1	1	1.0000	0.0001	3	0.83	0.003	0.013
0.33	64	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	64	1	1	0.0100	1.0000	3	0.83	0.003	0.016
0.33	64	1	1	0.0100	0.0100	3	0.00	0.001	0.001
0.33	64	1	1	0.0100	0.0100	2	0.50	0.003	0.016
0.33	64	1	1	0.0100	0.0001	3	0.67	0.001	0.001
0.33	64	1	1	0.0001	1.0000	2	0.00	0.003	0.001
0.33	64	1	1	0.0001	1.0000	3	0.50	0.003	0.016
0.33	64	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	64	1	1	0.0001	0.0100	3	0.83	0.003	0.013
0.33	64	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	64	1	1	0.0001	0.0001	3	0.67	0.003	0.014
0.33	64	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	64	1	4	1.0000	1.0000 0.0100	3	0.00	0.013	0.453
0.33	64	1	4	1.0000	0.0100	3	0.17	0.001	0.003
0.33	64	1	4	1.0000	0.0001	2	0.33	0.003	0.003
0.33	64	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.33	64	1	4	0.0100	1.0000	2	0.17	0.001	0.004
0.33	64	1	4	0.0100	1.0000	3	0.67	0.003	0.018
0.33	64	1	4	0.0100	0.0100	2	0.50	0.001	0.004
0.33	64	1	4	0.0100	0.0100	3	1.00	0.004	0.004
0.33	64	1	4	0.0100	0.0001	2	0.67	0.001	0.004
0.33	64	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.33	64	1	4	0.0001	1.0000	3	0.50	0.001	0.003
0.55	04	1	+	0.0001	1.0000		0.03	0.003	0.010

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	64	1	4	0.0001	0.0100	2	0.83	0.001	0.004
0.33	64	1	4	0.0001	0.0100	3	1.00	0.003	0.003
0.33	64	1	4	0.0001	0.0001	2	0.83	0.001	0.003
0.33	64	1	4	0.0001	0.0001	3	1.00	0.003	0.004
0.33	64	1	16	1.0000	1.0000	2	0.00	0.001	0.002
0.33	64	1	16	1.0000	1.0000	2	0.00	0.017	0.025
0.33	64	1	16 16	1.0000	0.0100	3	1.00	0.001	0.005
0.33	64	1	16	1.0000	0.0001	2	0.67	0.004	0.006
0.33	64	1	16	1.0000	0.0001	3	1.00	0.005	0.006
0.33	64	1	16	0.0100	1.0000	2	0.00	0.001	0.003
0.33	64	1	16	0.0100	1.0000	3	0.17	0.008	0.036
0.33	64	1	16	0.0100	0.0100	2	1.00	0.005	0.006
0.33	64	1	16	0.0100	0.0100	3	1.00	0.005	0.006
0.33	64	1	16	0.0100	0.0001	2	1.00	0.006	0.007
0.33	64	1	16 16	0.0100	0.0001 1.0000	3	1.00	0.006	0.006
0.33	64	1	16	0.0001	1.0000	3	0.00	0.001	0.003
0.33	64	1	16	0.0001	0.0100	2	1.00	0.009	0.006
0.33	64	1	16	0.0001	0.0100	3	1.00	0.006	0.007
0.33	64	1	16	0.0001	0.0001	2	1.00	0.006	0.007
0.33	64	1	16	0.0001	0.0001	3	1.00	0.007	0.007
0.33	64	1	64	1.0000	1.0000	2	0.00	0.001	0.004
0.33	64	1	64	1.0000	1.0000	3	0.00	0.049	0.061
0.33	64	1	64	1.0000	0.0100	2	0.33	0.001	0.011
0.33	64	1	64	1.0000	0.0100	3	1.00	0.011	0.017
0.33	64	1	64	1.0000	0.0001		0.83	0.001	0.015
0.33	64	1	64 64	1.0000 0.0100	0.0001 1.0000	3	1.00	0.010	0.015
0.33	64	1	64	0.0100	1.0000	3	0.00	0.001	0.006
0.33	64	1	64	0.0100	0.0100	2	1.00	0.011	0.015
0.33	64	1	64	0.0100	0.0100	3	1.00	0.014	0.015
0.33	64	1	64	0.0100	0.0001	2	1.00	0.016	0.018
0.33	64	1	64	0.0100	0.0001	3	1.00	0.015	0.018
0.33	64	1	64	0.0001	1.0000	2	0.00	0.001	0.014
0.33	64	1	64	0.0001	1.0000	3	0.00	0.073	0.157
0.33	64	1	64	0.0001	0.0100	2	1.00	0.011	0.017
0.33	64	1	64 64	0.0001	0.0100	3	1.00	0.011	0.018
0.33	64	1	64	0.0001	0.0001	3	1.00	0.013	0.022
0.33	64	1	256	1.0000	1.0000	2	0.00	0.010	0.016
0.33	64	1	256	1.0000	1.0000	3	0.00	0.199	0.324
0.33	64	1	256	1.0000	0.0100	2	0.17	0.001	0.053
0.33	64	1	256	1.0000	0.0100	3	0.17	0.052	0.352
0.33	64	1	256	1.0000	0.0001	2	1.00	0.050	0.074
0.33	64	1	256	1.0000	0.0001	3	1.00	0.050	0.074
0.33	64 64	1	256	0.0100	1.0000	2	0.00	0.017	0.027
0.33	64	1	256 256	0.0100	0.0100	3	0.00 1.00	0.281	0.904
0.33	64	1	256	0.0100	0.0100	3	1.00	0.048	0.079
0.33	64	1	256	0.0100	0.0001	2	1.00	0.047	0.096
0.33	64	1	256	0.0100	0.0001	3	1.00	0.072	0.096
0.33	64	1	256	0.0001	1.0000	2	0.00	0.026	0.039
0.33	64	1	256	0.0001	1.0000	3	0.00	0.505	1.010
0.33	64	1	256	0.0001	0.0100	2	1.00	0.072	0.098
0.33	64	1	256	0.0001	0.0100	3	1.00	0.071	0.093
0.33	64	1	256	0.0001	0.0001	3	1.00	0.083	0.116 0.126
0.33	64	4	256 1	1.0000	1.00001	2	1.00 0.00	0.097	0.126
0.33	64	4	1	1.0000	1.0000	3	0.67	0.001	0.686
0.33	64	4	1	1.0000	0.0100	2	0.00	0.003	0.001
0.33	64	4	1	1.0000	0.0100	3	0.50	0.003	0.015
0.33	64	4	1	1.0000	0.0001	2	0.00	0.001	0.009
0.33	64	4	1	1.0000	0.0001	3	0.50	0.003	0.015
0.33	64	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	64	4	1	0.0100	1.0000	3	0.67	0.003	0.014
0.33	64	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	64	4	1	0.0100	0.0100	3	0.83	0.003	0.014
0.33	64	4	1	0.0100	0.0001	3	0.67	0.001	0.001
0.33	64	4	1	0.0100	1.0000	2	0.00	0.003	0.001
0.33	U 1	4	1	0.0001	1.0000	3	0.83	0.003	0.001
	64	-							
0.33	64 64	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33				0.0001 0.0001	0.0100 0.0100	3	0.00	0.001	0.001
	64	4	1						

mul	m_1	m_2	\tau	TR	DTR	alg	SR	mint	maxt
0.33	64	4	4	1.0000	1.0000	3	0.00	0.001	0.001
0.33	64	4	4	1.0000	0.0100	2	0.00	0.003	0.001
0.33	64	4	4	1.0000	0.0100	3	1.00	0.003	0.004
0.33	64	4	4	1.0000	0.0001	2	0.33	0.001	0.003
0.33	64	4	4	1.0000	0.0001	3	1.00	0.003	0.011
0.33	64	4	4	0.0100	1.0000	2	0.17	0.001	0.003
0.33	64	4	4	0.0100	1.0000	3	1.00	0.003	0.005
0.33	64	4	4	0.0100	0.0100	2	0.33	0.001	0.004
0.33	64	4	4	0.0100	0.0100	3	0.83	0.004	0.020
0.33	64	4	4	0.0100	0.0001	2	0.67	0.001	0.004
0.33	64	4	4	0.0100	0.0001	3	0.83	0.004	0.020
0.33	64	4	4	0.0001	1.0000	3	0.50	0.001	0.004
0.33	64	4	4	0.0001	0.0100	2	0.83	0.003	0.020
0.33	64	4	4	0.0001	0.0100	3	0.83	0.003	0.007
0.33	64	4	4	0.0001	0.0001	2	0.50	0.003	0.004
0.33	64	4	4	0.0001	0.0001	3	0.83	0.003	0.015
0.33	64	4	16	1.0000	1.0000	2	0.00	0.001	0.001
0.33	64	4	16	1.0000	1.0000	3	0.00	0.018	0.026
0.33	64	4	16	1.0000	0.0100	2	0.83	0.001	0.005
0.33	64	4	16	1.0000	0.0100	3	1.00	0.005	0.007
0.33	64	4	16	1.0000	0.0001	2	0.50	0.001	0.006
0.33	64	4	16	1.0000	0.0001	3	1.00	0.006	0.009
0.33	64	4	16	0.0100	1.0000	2	0.00	0.001	0.001
0.33	64	4	16	0.0100	1.0000	3	0.17	0.009	0.031
0.33	64	4	16 16	0.0100	0.0100	3	0.83	0.001	0.006
0.33	64	4	16	0.0100	0.0100	2	0.83	0.003	0.006
0.33	64	4	16	0.0100	0.0001	3	1.00	0.006	0.012
0.33	64	4	16	0.0001	1.0000	2	0.50	0.001	0.006
0.33	64	4	16	0.0001	1.0000	3	0.50	0.004	0.134
0.33	64	4	16	0.0001	0.0100	2	1.00	0.006	0.006
0.33	64	4	16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	64	4	16	0.0001	0.0001	2	1.00	0.005	0.007
0.33	64	4	16	0.0001	0.0001	3	1.00	0.005	0.019
0.33	64	4	64	1.0000	1.0000	2	0.00	0.001	0.004
0.33	64	4	64	1.0000	1.0000	3	0.00	0.053	0.062
0.33	64	4	64	1.0000	0.0100	2	0.00	0.001	0.001
0.33	64	4	64	1.0000	0.0100	3	1.00	0.012	0.026
0.33	64	4	64	1.0000	0.0001	3	1.00	0.010	0.013
0.33	64	4	64	0.0100	1.0000	2	0.00	0.001	0.006
0.33	64	4	64	0.0100	1.0000	3	0.00	0.061	0.091
0.33	64	4	64	0.0100	0.0100	2	1.00	0.014	0.015
0.33	64	4	64	0.0100	0.0100	3	1.00	0.014	0.015
0.33	64	4	64	0.0100	0.0001	2	1.00	0.011	0.017
0.33	64	4	64	0.0100	0.0001	3	1.00	0.011	0.017
0.33	64	4	64	0.0001	1.0000	2	0.00	0.001	0.009
0.33	64	4	64	0.0001	1.0000	3	0.00	0.069	0.233
0.33	64	4	64	0.0001	0.0100	2	1.00	0.011	0.018
0.33	64	4	64	0.0001	0.0100	3 2	1.00	0.011	0.018
0.33	64	4	64	0.0001	0.0001	3	1.00	0.021	0.023
0.33	64	4	256	1.0000	1.0000	2	0.00	0.021	0.023
0.33	64	4	256	1.0000	1.0000	3	0.00	0.010	0.304
0.33	64	4	256	1.0000	0.0100	2	0.00	0.001	0.024
0.33	64	4	256	1.0000	0.0100	3	0.17	0.034	0.798
0.33	64	4	256	1.0000	0.0001	2	0.83	0.001	0.074
0.33	64	4	256	1.0000	0.0001	3	1.00	0.056	0.077
0.33	64	4	256	0.0100	1.0000	2	0.00	0.018	0.027
0.33	64	4	256	0.0100	1.0000	3	0.00	0.298	0.636
0.33	64	4	256	0.0100	0.0100	2	1.00	0.060	0.079
0.33	64	4	256	0.0100	0.0100	3	1.00	0.055	0.078
0.33	64	4	256	0.0100	0.0001	2	1.00	0.070	0.094
0.33	64 64	4	256 256	0.0100	0.0001 1.0000	3	1.00	0.068	0.097 0.041
0.33	64	4	256	0.0001	1.0000	3	0.00	0.023	0.663
0.33	64	4	256	0.0001	0.0100	2	1.00	0.431	0.003
0.33	64	4	256	0.0001	0.0100	3	1.00	0.059	0.100
0.33	64	4	256	0.0001	0.0001	2	1.00	0.111	0.126
0.33	64	4	256	0.0001	0.0001	3	1.00	0.088	0.125
0.33	64	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	64	16	1	1.0000	1.0000	3	0.50	0.003	0.031
0.33	64	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	64	16	1	1.0000	0.0100	3	0.83	0.003	0.016

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	64	16	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	64	16	1	1.0000	0.0001	3	0.83	0.009	0.019
0.33	64	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	64	16	1	0.0100	1.0000	3	0.17	0.007	0.017
0.33	64	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	64	16 16	1	0.0100	0.0100	2	0.07	0.000	0.001
0.33	64	16	1	0.0100	0.0001	3	0.67	0.003	0.016
0.33	64	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	64	16	1	0.0001	1.0000	3	0.83	0.003	0.017
0.33	64	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	64	16	1	0.0001	0.0100	3	0.50	0.004	0.016
0.33	64	16 16	1	0.0001	0.0001	3	0.00	0.001	0.001
0.33	64	16	4	1.0000	1.0000	2	0.00	0.003	0.001
0.33	64	16	4	1.0000	1.0000	3	0.33	0.003	0.022
0.33	64	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.33	64	16	4	1.0000	0.0100	3	0.83	0.003	0.015
0.33	64	16	4	1.0000	0.0001	2	0.67	0.001	0.003
0.33	64	16 16	4	1.0000	0.0001	2	1.00	0.003	0.009
0.33	64	16	4	0.0100	1.0000	3	0.00	0.001	0.001
0.33	64	16	4	0.0100	0.0100	2	0.67	0.003	0.010
0.33	64	16	4	0.0100	0.0100	3	1.00	0.003	0.010
0.33	64	16	4	0.0100	0.0001	2	0.50	0.001	0.004
0.33	64	16	4	0.0100	0.0001	3	1.00	0.003	0.011
0.33	64	16	4	0.0001	1.0000	2	0.33	0.001	0.003
0.33	64	16 16	4	0.0001	1.0000 0.0100	2	0.33	0.003	0.019
0.33	64	16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.33	64	16	4	0.0001	0.0001	2	0.67	0.001	0.004
0.33	64	16	4	0.0001	0.0001	3	1.00	0.003	0.006
0.33	64	16	16	1.0000	1.0000	2	0.00	0.001	0.002
0.33	64	16	16	1.0000	1.0000	3	0.33	0.003	0.024
0.33	64	16 16	16 16	1.0000	0.0100	3	0.17 1.00	0.001	0.004
0.33	64	16	16	1.0000	0.0001	2	0.50	0.004	0.008
0.33	64	16	16	1.0000	0.0001	3	1.00	0.004	0.009
0.33	64	16	16	0.0100	1.0000	2	0.00	0.001	0.001
0.33	64	16	16	0.0100	1.0000	3	0.17	0.004	0.035
0.33	64	16	16	0.0100	0.0100	2	0.83	0.001	0.006
0.33	64	16	16	0.0100	0.0100	3	1.00	0.005	0.006
0.33	64	16 16	16 16	0.0100	0.0001	3	1.00	0.006	0.007 0.006
0.33	64	16	16	0.0001	1.0000	2	0.33	0.000	0.006
0.33	64	16	16	0.0001	1.0000	3	0.50	0.006	0.044
0.33	64	16	16	0.0001	0.0100	2	1.00	0.006	0.006
0.33	64	16	16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	64	16	16	0.0001	0.0001	2	0.83	0.001	0.007
0.33	64	16 16	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.006	0.007 0.004
0.33	64	16	64	1.0000	1.0000	3	0.00	0.001	0.004
0.33	64	16	64	1.0000	0.0100	2	0.00	0.044	0.002
0.33	64	16	64	1.0000	0.0100	3	1.00	0.009	0.017
0.33	64	16	64	1.0000	0.0001	2	0.50	0.001	0.015
0.33	64	16	64	1.0000	0.0001	3	1.00	0.012	0.015
0.33	64	16 16	64 64	0.0100	1.0000	3	0.00	0.001	0.006
0.33	64	16	64	0.0100	0.0100	2	1.00	0.075	0.091
0.33	64	16	64	0.0100	0.0100	3	1.00	0.012	0.015
0.33	64	16	64	0.0100	0.0001	2	1.00	0.011	0.014
0.33	64	16	64	0.0100	0.0001	3	1.00	0.011	0.016
0.33	64	16	64	0.0001	1.0000	2	0.00	0.001	0.008
0.33	64	16	64	0.0001	1.0000	3	0.00	0.088	0.198
0.33	64	16 16	64	0.0001	0.0100	3	1.00	0.012	0.018 0.015
0.33	64	16	64	0.0001	0.0100	2	1.00	0.011	0.013
0.33	64	16	64	0.0001	0.0001	3	1.00	0.014	0.019
0.33	64	16	256	1.0000	1.0000	2	0.00	0.011	0.017
0.33	64	16	256	1.0000	1.0000	3	0.00	0.195	0.794
0.33	64	16	256	1.0000	0.0100	2	0.17	0.001	0.051
0.33	64 64	16 16	256	1.0000	0.0100	3	0.33	0.046	0.279
0.33	64	16	256 256	1.0000	0.0001	3	0.83 1.00	0.001	0.074 0.075
0.33	64	16	256	0.0100	1.0000	2	0.00	0.073	0.073
0.33	64	16	256	0.0100	1.0000	3	0.00	0.284	0.445
						-		-	L

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	64	16	256	0.0100	0.0100	2	1.00	0.050	0.091
0.33	64	16	256	0.0100	0.0100	3	1.00	0.048	0.348
0.33	64	16 16	256 256	0.0100	0.0001	2	1.00	0.060	0.096
0.33	64	16	256	0.0100	1.0000	2	0.00	0.001	0.042
0.33	64	16	256	0.0001	1.0000	3	0.00	0.467	1.053
0.33	64	16	256	0.0001	0.0100	2	1.00	0.062	0.097
0.33	64	16	256	0.0001	0.0100	3	1.00	0.067	0.097
0.33	64	16 16	256 256	0.0001	0.0001	2	1.00	0.077	0.126 0.123
0.33	64	64	1	1.0000	1.0000	2	0.00	0.073	0.123
0.33	64	64	1	1.0000	1.0000	3	0.67	0.003	0.030
0.33	64	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	64	64	1	1.0000	0.0100	3	0.67	0.003	0.015
0.33	64	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	64	64	1	0.0100	1.0000	2	0.00	0.003	0.001
0.33	64	64	1	0.0100	1.0000	3	1.00	0.003	0.006
0.33	64	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	64	64	1	0.0100	0.0100	3	0.83	0.003	0.015
0.33	64	64	1	0.0100	0.0001	3	0.00	0.001	0.001
0.33	64	64	1	0.0001	1.0000	2	0.07	0.003	0.001
0.33	64	64	1	0.0001	1.0000	3	1.00	0.003	0.006
0.33	64	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	64	64	1	0.0001	0.0100	3	0.83	0.003	0.016
0.33	64	64	1	0.0001	0.0001	3	0.83	0.001	0.001
0.33	64	64	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	64	64	4	1.0000	1.0000	3	0.50	0.003	0.018
0.33	64	64	4	1.0000	0.0100	2	0.17	0.001	0.003
0.33	64	64	4	1.0000	0.0100	3	1.00 0.00	0.003	0.009
0.33	64	64	4	1.0000	0.0001	3	1.00	0.001	0.001
0.33	64	64	4	0.0100	1.0000	2	0.17	0.001	0.003
0.33	64	64	4	0.0100	1.0000	3	0.50	0.003	0.021
0.33	64 64	64	4	0.0100 0.0100	0.0100	2	0.67 1.00	0.001	0.003
0.33	64	64	4	0.0100	0.0001	2	0.67	0.003	0.201
0.33	64	64	4	0.0100	0.0001	3	1.00	0.003	0.008
0.33	64	64	4	0.0001	1.0000	2	0.50	0.001	0.004
0.33	64	64	4	0.0001	1.0000	3	1.00	0.003	0.004
0.33	64	64	4	0.0001	0.0100	2	1.00	0.003	0.004
0.33	64	64	4	0.0001	0.0001	2	0.50	0.003	0.004
0.33	64	64	4	0.0001	0.0001	3	1.00	0.004	0.011
0.33	64	64	16	1.0000	1.0000	2	0.00	0.001	0.001
0.33	64	64	16 16	1.0000	1.0000 0.0100	3	0.50	0.004	0.028
0.33	64	64	16	1.0000	0.0100	3	1.00	0.001	0.005
0.33	64	64	16	1.0000	0.0001	2	0.33	0.001	0.006
0.33	64	64	16	1.0000	0.0001	3	1.00	0.006	0.006
0.33	64	64	16	0.0100	1.0000	2	0.00	0.001	0.001
0.33	64	64	16 16	0.0100	1.0000 0.0100	3	0.50	0.005	0.034
0.33	64	64	16	0.0100	0.0100	3	1.00	0.005	0.006
0.33	64	64	16	0.0100	0.0001	2	1.00	0.006	0.006
0.33	64	64	16	0.0100	0.0001	3	1.00	0.006	0.006
0.33	64 64	64	16 16	0.0001 0.0001	1.0000 1.0000	2	0.33 0.83	0.001 0.005	0.006 0.036
0.33	64	64	16	0.0001	0.0100	2	1.00	0.005	0.007
0.33	64	64	16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	64	64	16	0.0001	0.0001	2	1.00	0.006	0.007
0.33	64 64	64	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00	0.007	0.007
0.33	64	64	64	1.0000	1.0000	3	0.00	0.001	0.061
0.33	64	64	64	1.0000	0.0100	2	0.00	0.001	0.001
0.33	64	64	64	1.0000	0.0100	3	1.00	0.012	0.012
0.33	64	64	64	1.0000	0.0001	2	0.83	0.001	0.016
0.33	64	64	64	1.0000 0.0100	0.0001 1.0000	2	1.00 0.00	0.015	0.016
0.33	64	64	64	0.0100	1.0000	3	0.00	0.010	0.000
0.33	64	64	64	0.0100	0.0100	2	1.00	0.009	0.011
0.33	64	64	64	0.0100	0.0100	3	1.00	0.010	0.011
0.33	64 64	64	64 64	0.0100	0.0001	2	1.00	0.011	0.013
0.33	04	04	04	0.0100	0.0001	3	1.00	0.011	0.012

$\boxed{ \begin{array}{c c c c c c c c c c c c c c c c c c c $	OTR alg SR mint maxt
	.0000 2 0.33 0.001 0.016
	.0000 3 0.33 0.010 0.119
0.33 64 64 64 0.0001 0.	.0100 2 1.00 0.013 0.018
0.33 64 64 64 0.0001 0.	.0100 3 1.00 0.011 0.018
0.33 64 64 64 0.0001 0.	.0001 2 1.00 0.014 0.023
	.0001 3 1.00 0.014 0.023
	.0000 2 0.00 0.011 0.017
	0000 3 0.00 0.182 0.800
	0100 2 0.17 0.001 0.034
	.0100 3 1.00 0.033 0.040 .0001 2 1.00 0.046 0.074
	.0001 2 1.00 0.046 0.074 .0001 3 1.00 0.046 0.075
	0000 2 0.00 0.001 0.027
	0000 3 0.00 0.417 1.383
	0100 2 1.00 0.049 0.079
	.0100 3 1.00 0.050 0.078
0.33 64 64 256 0.0100 0.	.0001 2 1.00 0.090 0.095
0.33 64 64 256 0.0100 0.	.0001 3 1.00 0.087 0.093
	.0000 2 0.00 0.001 0.042
	.0000 3 0.00 0.400 1.623
	0100 2 1.00 0.095 0.098
	0100 3 1.00 0.083 0.098
	.0001 2 1.00 0.094 0.124 .0001 3 1.00 0.080 0.124
	.0001 3 1.00 0.080 0.124 .0000 2 0.00 0.001 0.001
	.0000 2 0.00 0.001 0.001 .0000 3 0.50 0.003 0.023
	0100 2 0.00 0.001 0.001
	0100 3 0.67 0.003 0.015
	0001 2 0.00 0.001 0.001
0.33 64 256 1 1.0000 0	.0001 3 0.67 0.003 0.017
0.33 64 256 1 0.0100 1.	.0000 2 0.00 0.001 0.001
	.0000 3 0.50 0.003 0.014
	.0100 2 0.00 0.001 0.001
	.0100 3 0.67 0.003 2.030
	.0001 2 0.00 0.001 0.001
	0001 3 0.50 0.004 0.029
	0000 2 0.00 0.001 0.001
	.0000 3 0.67 0.003 0.017 .0100 2 0.00 0.001 0.001
	0100 3 0.67 0.003 0.017
	.0001 2 0.00 0.001 0.001
	0001 3 0.83 0.003 0.016
	.0000 2 0.00 0.001 0.001
	.0000 3 0.50 0.003 0.020
0.33 64 256 4 1.0000 0.	.0100 2 0.17 0.001 0.004
	.0100 3 1.00 0.003 0.008
	.0001 2 0.33 0.001 0.004
	.0001 3 1.00 0.004 0.004
	0000 2 0.00 0.001 0.001
	0000 3 0.50 0.004 0.023
	.0100 2 0.50 0.001 0.004 .0100 3 1.00 0.003 0.005
	.0100 3 1.00 0.003 0.005 .0001 2 0.33 0.001 0.004
	.0001 2 0.33 0.001 0.004 .0001 3 0.67 0.004 0.019
	0000 2 0.67 0.001 0.004
	0000 3 0.83 0.003 0.022
	0100 2 0.83 0.001 0.004
	0100 3 1.00 0.003 0.004
	0001 2 1.00 0.003 0.004
	.0001 3 1.00 0.003 0.016
	.0000 2 0.00 0.001 0.001
	.0000 3 0.50 0.004 0.023
	0100 2 0.50 0.001 0.005
	0100 3 1.00 0.005 0.005
	0001 2 0.67 0.001 0.006
	.0001 3 1.00 0.004 0.006 .0000 2 0.00 0.001 0.001
	.0000 2 0.00 0.001 0.001 .0000 3 0.17 0.005 0.035
	0100 2 0.83 0.001 0.005
	0100 2 0.83 0.001 0.003
	0001 2 1.00 0.004 0.005
	.0001 3 1.00 0.004 0.005
0.33 64 256 16 0.0001 1.	.0001 3 1.00 0.004 0.005 .0000 2 0.33 0.001 0.005
0.33 64 256 16 0.0001 1.	.0000 2 0.33 0.001 0.005 .0000 3 0.50 0.004 0.035
0.33 64 256 16 0.0001 1. 0.33 64 256 16 0.0001 0.	.0000 2 0.33 0.001 0.005

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	64	256	16	0.0001	0.0001	2	1.00	0.005	0.006
0.33	64	256	16	0.0001	0.0001	3	1.00	0.005	0.006
0.33	64	256 256	64 64	1.0000	1.0000	2	0.00	0.001	0.004 0.152
0.33	64	256	64	1.0000	0.0100	2	0.33	0.006	0.132
0.33	64	256	64	1.0000	0.0100	3	1.00	0.008	0.012
0.33	64	256	64	1.0000	0.0001	2	0.67	0.001	0.016
0.33	64	256	64	1.0000	0.0001	3	1.00	0.013	0.016
0.33	64	256	64	0.0100	1.0000	2	0.00	0.001	0.006
0.33	64	256 256	64	0.0100	1.0000 0.0100	3	0.17	0.012	0.079
0.33	64	256	64	0.0100	0.0100	3	1.00	0.010	0.012
0.33	64	256	64	0.0100	0.0001	2	1.00	0.012	0.018
0.33	64	256	64	0.0100	0.0001	3	1.00	0.011	0.018
0.33	64	256	64	0.0001	1.0000	2	0.17	0.001	0.015
0.33	64	256 256	64 64	0.0001	0.0100	3	0.50 1.00	0.015 0.012	0.123 0.018
0.33	64	256	64	0.0001	0.0100	3	1.00	0.013	0.017
0.33	64	256	64	0.0001	0.0001	2	1.00	0.014	0.021
0.33	64	256	64	0.0001	0.0001	3	1.00	0.014	0.022
0.33	64	256	256	1.0000	1.0000	2	0.00	0.001	0.011
0.33	64	256 256	256 256	1.0000	1.0000 0.0100	3	0.00	0.149	0.202 0.052
0.33	64	256	256	1.0000	0.0100	3	0.17	0.001	0.032
0.33	64	256	256	1.0000	0.0001	2	1.00	0.070	0.079
0.33	64	256	256	1.0000	0.0001	3	1.00	0.073	0.079
0.33	64	256	256	0.0100	1.0000	2	0.00	0.001	0.026
0.33	64 64	256 256	256 256	0.0100 0.0100	1.0000 0.0100	3	0.00	0.309	1.599 0.077
0.33	64	256	256	0.0100	0.0100	3	1.00	0.054	0.074
0.33	64	256	256	0.0100	0.0001	2	1.00	0.066	0.095
0.33	64	256	256	0.0100	0.0001	3	1.00	0.074	0.094
0.33	64	256	256	0.0001	1.0000	2	0.00	0.001	0.042
0.33	64	256 256	256 256	0.0001	1.0000 0.0100	3	0.00 1.00	0.468	0.899
0.33	64	256	256	0.0001	0.0100	3	1.00	0.061	0.100
0.33	64	256	256	0.0001	0.0001	2	1.00	0.076	0.127
0.33	64	256	256	0.0001	0.0001	3	1.00	0.076	0.127
0.33	256	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	256 256	1	1	1.0000	1.0000 0.0100	3	0.50	0.003	0.014
0.33	256	1	1	1.0000	0.0100	3	0.00	0.001	0.001
0.33	256	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	256	1	1	1.0000	0.0001	3	0.83	0.003	0.016
0.33	256	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	256 256	1	1	0.0100	1.0000 0.0100	3	0.83	0.003	0.015
0.33	256	1	1	0.0100	0.0100	3	0.00	0.001	0.001 0.526
0.33	256	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	256	1	1	0.0100	0.0001	3	0.83	0.003	0.017
0.33	256	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	256	1	1	0.0001	1.0000	3 2	0.50	0.003	0.016
0.33	256 256	1	1	0.0001	0.0100	3	0.00	0.001	0.001 0.016
0.33	256	1	1	0.0001	0.0001	2	0.00	0.003	0.001
0.33	256	1	1	0.0001	0.0001	3	0.67	0.003	0.014
0.33	256	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	256 256	1	4	1.0000	1.0000 0.0100	3	0.67	0.003	0.015
0.33	256	1	4	1.0000	0.0100	3	0.17	0.001	0.003
0.33	256	1	4	1.0000	0.0001	2	0.50	0.003	0.003
0.33	256	1	4	1.0000	0.0001	3	1.00	0.003	0.004
0.33	256	1	4	0.0100	1.0000	2	0.00	0.001	0.001
0.33	256	1	4	0.0100	1.0000	3	0.17	0.004	0.161
0.33	256 256	1	4	0.0100	0.0100	3	0.83 1.00	0.001	0.004
0.33	256	1	4	0.0100	0.0001	2	0.83	0.004	0.004
0.33	256	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.33	256	1	4	0.0001	1.0000	2	0.00	0.001	0.001
0.33	256	1	4	0.0001	1.0000	3	0.17	0.003	0.018
0.33	256 256	1	4	0.0001	0.0100	2	0.50 1.00	0.001	0.004
0.33	256	1	4	0.0001	0.0001	2	0.67	0.003	0.004
0.33	256	1	4	0.0001	0.0001	3	1.00	0.003	0.005
0.33	256	1	16	1.0000	1.0000	2	0.00	0.001	0.002
0.33	256	1	16	1.0000	1.0000	3	0.33	0.004	0.026

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	256	1	16	1.0000	0.0100	2	0.33	0.001	0.005
0.33	256	1	16	1.0000	0.0100	3	1.00	0.004	0.005
0.33	256	1	16	1.0000	0.0001	2	0.67	0.001	0.006
0.33	256	1	16	1.0000	0.0001	3	1.00	0.004	0.007
0.33	256	1	16	0.0100	1.0000	2	0.00	0.001	0.002
0.33	256 256	1	16	0.0100	1.0000	2	0.33	0.005	0.028
0.33	256	1	16 16	0.0100	0.0100	3	1.00	0.001	0.005
0.33	256	1	16	0.0100	0.0001	2	1.00	0.004	0.005
0.33	256	1	16	0.0100	0.0001	3	1.00	0.004	0.005
0.33	256	1	16	0.0001	1.0000	2	0.33	0.001	0.004
0.33	256	1	16	0.0001	1.0000	3	0.67	0.004	0.025
0.33	256	1	16	0.0001	0.0100	2	1.00	0.004	0.005
0.33	256	1	16	0.0001	0.0100	3	1.00	0.004	0.005
0.33	256	1	16	0.0001	0.0001	2	1.00	0.005	0.006
0.33	256 256	1	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.005	0.006
0.33	256	1	64	1.0000	1.0000	3	0.00	0.001	0.003
0.33	256	1	64	1.0000	0.0100	2	0.17	0.012	0.009
0.33	256	1	64	1.0000	0.0100	3	0.83	0.008	0.049
0.33	256	1	64	1.0000	0.0001	2	0.67	0.001	0.016
0.33	256	1	64	1.0000	0.0001	3	1.00	0.015	0.030
0.33	256	1	64	0.0100	1.0000	2	0.00	0.001	0.006
0.33	256	1	64	0.0100	1.0000	3	0.17	0.023	0.089
0.33	256	1	64	0.0100	0.0100	2	1.00	0.015	0.016
0.33	256 256	1	64	0.0100	0.0100	3	1.00	0.015	0.016 0.018
0.33	256	1	64	0.0100	0.0001	3	1.00	0.017	0.018
0.33	256	1	64	0.0001	1.0000	2	0.17	0.001	0.013
0.33	256	1	64	0.0001	1.0000	3	0.33	0.017	0.336
0.33	256	1	64	0.0001	0.0100	2	1.00	0.012	0.018
0.33	256	1	64	0.0001	0.0100	3	1.00	0.012	0.018
0.33	256	1	64	0.0001	0.0001	2	1.00	0.014	0.019
0.33	256	1	64	0.0001	0.0001	3	1.00	0.013	0.022
0.33	256 256	1	256 256	1.0000	1.0000	3	0.00	0.001	0.001
0.33	256	1	256	1.0000	0.0100	2	0.00	0.131	0.279
0.33	256	1	256	1.0000	0.0100	3	0.50	0.042	0.314
0.33	256	1	256	1.0000	0.0001	2	1.00	0.075	0.078
0.33	256	1	256	1.0000	0.0001	3	1.00	0.075	0.077
0.33	256	1	256	0.0100	1.0000	2	0.00	0.001	0.026
0.33	256	1	256	0.0100	1.0000	3	0.00	0.424	3.778
0.33	256	1	256	0.0100	0.0100	2	1.00	0.056	0.081
0.33	256 256	1	256 256	0.0100	0.0100	2	1.00	0.049	0.080
0.33	256	1	256	0.0100	0.0001	3	1.00	0.057	0.088
0.33	256	1	256	0.0001	1.0000	2	0.17	0.001	0.053
0.33	256	1	256	0.0001	1.0000	3	0.17	0.056	1.321
0.33	256	1	256	0.0001	0.0100	2	1.00	0.095	0.102
0.33	256	1	256	0.0001	0.0100	3	1.00	0.098	0.103
0.33	256	1	256	0.0001	0.0001	2	1.00	0.113	0.126
0.33	256	1	256	0.0001	0.0001	3	1.00	0.077	0.127
0.33	256 256	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	256	4	1	1.0000	0.0100	2	0.07	0.003	0.014
0.33	256	4	1	1.0000	0.0100	3	0.83	0.003	0.014
0.33	256	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	256	4	1	1.0000	0.0001	3	0.67	0.003	0.016
0.33	256	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	256	4	1	0.0100	1.0000	3	0.67	0.003	0.014
0.33	256	4	1	0.0100	0.0100	2	0.00	0.001	0.007
0.33	256 256	4	1	0.0100	0.0100	3	0.50	0.003	0.014
0.33	256	4	1	0.0100	0.0001	3	0.50	0.001	0.001
0.33	256	4	1	0.0100	1.0000	2	0.00	0.003	0.001
0.33	256	4	1	0.0001	1.0000	3	0.50	0.003	0.014
0.33	256	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	256	4	1	0.0001	0.0100	3	0.50	0.003	0.044
0.33	256	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	256	4	1	0.0001	0.0001	3	0.83	0.003	0.013
0.33	256	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	256 256	4	4	1.0000	1.0000 0.0100	3	0.33	0.004	0.018
0.33	256	4	4	1.0000	0.0100	3	0.50	0.001	0.004
0.33	256	4	4	1.0000	0.0001	2	0.83	0.003	0.018
0.33	256	4	4	1.0000	0.0001	3	1.00	0.001	0.004

mul	m_1	ma	$ \tau $	TR	DTR	alg	SR	mint	maxt
		m_2							
0.33	256 256	4	4	0.0100	1.0000	3	0.17	0.001	0.003
0.33	256	4	4	0.0100	0.0100	2	0.07	0.003	0.004
0.33	256	4	4	0.0100	0.0100	3	1.00	0.003	0.004
0.33	256	4	4	0.0100	0.0001	2	0.50	0.001	0.003
0.33	256	4	4	0.0100	0.0001	3	0.83	0.003	0.015
0.33	256	4	4	0.0001	1.0000	2	0.33	0.001	0.004
0.33	256	4	4	0.0001	1.0000	3	0.67	0.004	0.020
0.33	256	4	4	0.0001	0.0100	2	1.00	0.004	0.004
0.33	256	4	4	0.0001	0.0100	3	1.00	0.004	0.004
0.33	256	4	4	0.0001	0.0001	2	0.83	0.001	0.004
0.33	256	4	4	0.0001	0.0001	3	1.00	0.004	0.004
0.33	256	4	16	1.0000	1.0000	3	0.00	0.001	0.002
0.33	256 256	4	16 16	1.0000	0.0100	2	0.17	0.005	0.025
0.33	256	4	16	1.0000	0.0100	3	1.00	0.001	0.003
0.33	256	4	16	1.0000	0.0001	2	0.83	0.004	0.007
0.33	256	4	16	1.0000	0.0001	3	1.00	0.005	0.011
0.33	256	4	16	0.0100	1.0000	2	0.33	0.001	0.005
0.33	256	4	16	0.0100	1.0000	3	0.83	0.005	0.035
0.33	256	4	16	0.0100	0.0100	2	0.83	0.001	0.006
0.33	256	4	16	0.0100	0.0100	3	1.00	0.006	0.011
0.33	256	4	16	0.0100	0.0001	2	0.83	0.001	0.006
0.33	256	4	16	0.0100	0.0001	3	1.00	0.006	0.006
0.33	256	4	16	0.0001	1.0000	2	0.50	0.001	0.006
0.33	256	4	16	0.0001	1.0000	3	0.50	0.006	0.036
0.33	256	4	16	0.0001	0.0100	2	1.00	0.006	0.006
0.33	256 256	4	16 16	0.0001	0.0100	3	1.00	0.006	0.006
0.33	256	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.33	256	4	64	1.0000	1.0000	2	0.00	0.003	0.003
0.33	256	4	64	1.0000	1.0000	3	0.17	0.007	0.612
0.33	256	4	64	1.0000	0.0100	2	0.17	0.001	0.008
0.33	256	4	64	1.0000	0.0100	3	1.00	0.008	0.015
0.33	256	4	64	1.0000	0.0001	2	0.83	0.001	0.016
0.33	256	4	64	1.0000	0.0001	3	1.00	0.011	0.031
0.33	256	4	64	0.0100	1.0000	2	0.17	0.001	0.011
0.33	256	4	64	0.0100	1.0000	3	0.17	0.011	0.107
0.33	256	4	64	0.0100	0.0100	2	0.83	0.001	0.015
0.33	256	4	64	0.0100	0.0100	3	1.00	0.010	0.015
0.33	256 256	4	64	0.0100	0.0001	3	1.00	0.017 0.017	0.017 0.018
0.33	256	4	64	0.0100	1.00001	2	0.50	0.017	0.018
0.33	256	4	64	0.0001	1.0000	3	0.50	0.010	0.016
0.33	256	4	64	0.0001	0.0100	2	1.00	0.012	0.018
0.33	256	4	64	0.0001	0.0100	3	1.00	0.012	0.019
0.33	256	4	64	0.0001	0.0001	2	1.00	0.014	0.023
0.33	256	4	64	0.0001	0.0001	3	1.00	0.013	0.023
0.33	256	4	256	1.0000	1.0000	2	0.00	0.001	0.091
0.33	256	4	256	1.0000	1.0000	3	0.00	0.175	0.273
0.33	256	4	256	1.0000	0.0100	2	0.00	0.001	0.001
0.33	256	4	256	1.0000	0.0100	3	0.33	0.101	2.368
0.33	256	4	256	1.0000	0.0001	2	0.67	0.001	0.057
0.33	256 256	4	256 256	1.0000 0.0100	0.0001 1.0000	2	1.00	0.047	0.136 0.027
0.33	256	4	256	0.0100	1.0000	3	0.00	0.001	0.027
0.33	256	4	256	0.0100	0.0100	2	1.00	0.294	0.457
0.33	256	4	256	0.0100	0.0100	3	1.00	0.046	0.055
0.33	256	4	256	0.0100	0.0001	2	1.00	0.064	0.098
0.33	256	4	256	0.0100	0.0001	3	1.00	0.064	0.097
0.33	256	4	256	0.0001	1.0000	2	0.00	0.001	0.029
0.33	256	4	256	0.0001	1.0000	3	0.00	0.418	0.464
0.33	256	4	256	0.0001	0.0100	2	1.00	0.065	0.081
0.33	256	4	256	0.0001	0.0100	3	1.00	0.065	0.104
0.33	256	4	256	0.0001	0.0001	2	1.00	0.079	0.138
0.33	256	4	256	0.0001	0.0001	3	1.00	0.087	1.732
0.33	256	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	256 256	16 16	1	1.0000	1.0000 0.0100	2	0.17	0.004	0.016
0.33	256	16	1	1.0000	0.0100	3	0.67	0.001	0.001
0.33	256	16	1	1.0000	0.0001	2	0.07	0.003	0.001
0.33	256	16	1	1.0000	0.0001	3	1.00	0.003	0.004
0.33	256	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.33	256	16	1	0.0100	1.0000	3	0.33	0.003	0.014
0.33	256	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	256	16	1	0.0100	0.0100	3	0.83	0.003	0.014

0.33 256 16	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.033 256 16										
1.033 256 16										
0.33 256 16										
0.33 256 16										
0.33 256 16										
0.33 256 16										
0.33 256 16	0.33	256	16	1	0.0001	0.0001	3	0.83	0.003	0.013
0.33 256 16 4 1.0000 0.0100 2 0.17 0.001 0.003 0.33 256 16 4 1.0000 0.0001 2 0.33 0.001 0.003 0.33 256 16 4 1.0000 0.0001 3 0.83 0.003 0.017 0.33 256 16 4 0.0100 1.0000 3 0.50 0.003 0.016 0.33 256 16 4 0.0100 0.0100 2 0.83 0.001 0.004 0.33 256 16 4 0.0100 0.0001 2 0.67 0.001 0.003 0.33 256 16 4 0.0100 0.0001 2 0.67 0.001 0.003 0.33 256 16 4 0.0001 1.0000 3 0.67 0.001 0.003 0.33 256 16 4 0.0001 0.000 3										
0.33 256 16										
0.33 256 16 4 1,0000 0,0001 2 0.33 0,001 0,003 0.33 256 16 4 1,0000 0,0001 3 0,003 0,017 0.33 256 16 4 0,0100 1,0000 3 0,50 0,003 0,016 0.33 256 16 4 0,0100 0,000 0,001 0,001 0.33 256 16 4 0,0100 0,000 3 1,00 0,003 0,004 0.33 256 16 4 0,0100 0,0001 2 0,67 0,001 0,003 0.33 256 16 4 0,0001 1,000 0,033 0,001 0,003 0,003 0.33 256 16 4 0,0001 0,010 2 0,67 0,001 0,003 0.33 256 16 4 0,0001 0,0001 2 0,67 0,001 0,0										
0.33 256 16 4 1,0000 0,0001 3 0,033 0,0003 0,0017 0.33 256 16 4 0,0100 1,0000 2 0,17 0,001 0,004 0.33 256 16 4 0,0100 0,0100 2 0,83 0,001 0,004 0.33 256 16 4 0,0100 0,0001 3 1,00 0,003 0,004 0.33 256 16 4 0,0100 0,0001 3 1,00 0,003 0,004 0.33 256 16 4 0,0001 1,0000 3 1,00 0,003 0,001 0.33 256 16 4 0,0001 0,1000 3 1,00 0,003 0,017 0.33 256 16 4 0,0001 0,004 0,023 0,007 0.33 256 16 16 1,0000 1,0000 2 0,00 0,										
0.33 256 16 4 0.0100 0.0000 3 0.50 0.003 0.016 0.33 256 16 4 0.0100 0.0100 2 0.83 0.001 0.003 0.33 256 16 4 0.0100 0.0001 2 0.67 0.001 0.003 0.33 256 16 4 0.0100 0.0001 3 1.00 0.003 0.006 0.33 256 16 4 0.0001 1.0000 2 0.33 0.001 0.003 0.33 256 16 4 0.0001 0.0100 3 1.00 0.003 0.017 0.33 256 16 4 0.0001 0.0100 3 1.00 0.003 0.007 0.33 256 16 16 1.0000 1.0000 2 0.00 0.001 0.000 0.33 256 16 16 1.0000 1.0000 2 </td <td></td>										
0.33 256 16 4 0.0100 0.0100 2 0.83 0.001 0.003 0.33 256 16 4 0.0100 0.0001 2 0.67 0.001 0.003 0.33 256 16 4 0.0100 0.0001 2 0.67 0.001 0.003 0.33 256 16 4 0.0001 1.0000 2 0.33 0.001 0.003 0.001 0.33 256 16 4 0.0001 0.0100 3 1.00 0.003 0.018 0.33 256 16 4 0.0001 0.0100 3 1.00 0.001 0.001 0.33 256 16 4 0.0001 0.0001 3 0.067 0.001 0.004 0.33 256 16 16 1.0000 1.0000 3 0.50 0.001 0.001 0.33 256 16 16 1.0000 0.0		256	16	4			2		0.001	
0.33 256 16 4 0.0100 0.0100 3 1.00 0.0031 0.004 0.33 256 16 4 0.0100 0.0001 2 0.67 0.001 0.003 0.33 256 16 4 0.0001 1.000 2 0.33 0.001 0.003 0.33 256 16 4 0.0001 1.0000 3 0.67 0.001 0.001 0.33 256 16 4 0.0001 0.0100 2 0.67 0.001 0.001 0.33 256 16 4 0.0001 0.0010 3 1.00 0.003 0.001 0.33 256 16 16 1.0000 1.0000 2 0.00 0.001 0.000 0.33 256 16 16 1.0000 0.0000 2 0.03 0.001 0.002 0.33 256 16 16 1.0000 0.0010 2<										
0.33 256 16 4 0.0100 0.0001 2 0.67 0.001 0.003 0.006 0.33 256 16 4 0.0001 1.000 0.003 0.006 0.33 256 16 4 0.0001 1.0000 3 0.67 0.003 0.018 0.33 256 16 4 0.0001 0.0100 3 1.00 0.003 0.018 0.33 256 16 4 0.0001 0.0100 3 1.00 0.003 0.007 0.33 256 16 4 0.0001 0.0001 3 0.67 0.001 0.004 0.33 256 16 16 1.0000 1.0000 2 0.067 0.001 0.004 0.33 256 16 16 1.0000 1.0000 3 0.50 0.004 0.028 0.33 256 16 16 1.0000 0.0001 2 0										
0.33 256 16 4 0.0100 0.0001 3 1.00 0.003 0.006 0.33 256 16 4 0.0001 1.0000 2 0.33 0.001 0.003 0.018 0.33 256 16 4 0.0001 0.0100 2 0.67 0.001 0.004 0.33 256 16 4 0.0001 0.0010 2 0.67 0.001 0.004 0.33 256 16 4 0.0001 0.0001 3 0.83 0.003 0.001 0.33 256 16 16 1.0000 1.0000 3 0.50 0.004 0.001 0.33 256 16 16 1.0000 1.0000 3 0.50 0.004 0.028 0.33 256 16 16 1.0000 0.0100 3 1.00 0.004 0.006 0.33 256 16 16 1.0000 0.										
0.33 256 16 4 0.0001 1.0000 2 0.33 0.001 0.003 0.018 0.33 256 16 4 0.0001 1.0000 3 0.067 0.001 0.004 0.33 256 16 4 0.0001 0.0100 3 1.00 0.003 0.007 0.33 256 16 4 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 16 16 1.0000 1.0000 2 0.00 0.001 0.001 0.33 256 16 16 1.0000 0.0100 2 0.33 0.001 0.004 0.028 0.33 256 16 16 1.0000 0.0100 3 1.00 0.004 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.005 0.010 0.33 256 16 16 1										
0.33 256 16										
0.33 256 16 4 0.0001 0.0100 3 1.00 0.003 0.007 0.33 256 16 4 0.0001 0.0001 3 0.03 0.001 0.001 0.33 256 16 16 1.0000 1.0000 2 0.00 0.001 0.001 0.33 256 16 16 11.0000 0.0000 2 0.00 0.001 0.001 0.33 256 16 16 11.0000 0.0100 2 0.33 0.001 0.004 0.33 256 16 16 16 10.000 0.0001 3 1.00 0.004 0.006 0.33 256 16 16 16 10.000 0.0001 3 1.00 0.004 0.004 0.33 256 16 16 10.0100 1.0000 2 0.00 0.001 0.044 0.006 0.33 256 16										
0.33 256 16 4 0.0001 0.0001 2 0.67 0.001 0.004 0.33 256 16 16 10.000 1.0000 2 0.00 0.001 0.001 0.33 256 16 16 11.0000 1.0000 3 0.50 0.004 0.028 0.33 256 16 16 11.0000 0.0100 2 0.00 0.001 0.004 0.33 256 16 16 11.0000 0.0100 3 1.00 0.004 0.006 0.33 256 16 16 16 0.0100 1.0000 0.001 3 1.00 0.005 0.010 0.33 256 16 16 0.0100 1.0000 3 1.00 0.005 0.010 0.33 256 16 16 0.0100 0.0100 2 1.00 0.004 0.006 0.33 256 16 16 <t></t>	0.33	256	16	4	0.0001	0.0100	2	0.67	0.001	0.004
0.33 256 16 4 0.0001 0.0001 3 0.83 0.003 0.001 0.002 0.001 0.001 0.001 0.003 0.502 0.001 0.001 0.001 0.003 0.503 0.566 1.616 1.6100 0.0010 0.010 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.003 0.003 0.001 0.001										
0.33 256 16 16 1.0000 1.0000 2 0.00 0.001 0.001 0.33 256 16 16 1.0000 0.0100 3 1.00 0.004 0.008 0.33 256 16 16 1.0000 0.0100 3 1.00 0.004 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.004 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.005 0.010 0.33 256 16 16 1.0000 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.005 0.010 0.33 256 16 16 0.0100 1.0000 2 0.00 0.001 0.004 0.033 256 16 16 0.0100 1.0000 2 0.00 0.001 0.004 0.033 256 16 16 0.0100 0.0000 2 0.00 0.006 0.026 0.33 256 16 16 0.0100 0.0100 2 0.00 0.004 0.006 0.33 256 16 16 0.0100 0.0100 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 1.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 0.0001 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 0.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 0.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 0.0000 2 0.03 0.005 0.008 0.33 256 16 16 0.0001 0.0000 2 0.00 0.005 0.008 0.33 256 16 16 0.0001 0.0001 2 1.00 0.005 0.008 0.33 256 16 16 0.0001 0.0001 2 1.00 0.005 0.008 0.33 256 16 16 0.0001 0.0001 2 1.00 0.005 0.008 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 0.0001 0.0000 2 0.50 0.001 0.016 0.33 256 16 64 0.0001 0.0000 2 0.00 0.001 0.016 0.										
0.33 256 16 16 1.0000 1.0000 3 0.50 0.004 0.028 0.33 256 16 16 1.0000 0.0100 3 1.00 0.004 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.004 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.005 0.010 0.33 256 16 16 0.0100 1.0000 2 0.00 0.001 0.004 0.33 256 16 16 0.0100 1.0000 3 0.00 0.006 1.265 0.33 256 16 16 0.0100 0.0100 2 1.00 0.004 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0001 1.0000										
0.33 256 16 16 1.0000 0.0100 2 0.33 0.001 0.004 0.33 256 16 16 1.0000 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.005 0.010 0.33 256 16 16 0.0100 1.0000 2 0.00 0.001 0.004 0.33 256 16 16 0.0100 1.0000 3 0.50 0.006 1.265 0.33 256 16 16 0.0100 0.0100 2 1.00 0.004 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.005 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 1.0000										
0.33 256 16 16 1.0000 0.0100 3 1.00 0.004 0.006 0.33 256 16 16 1.0000 0.0001 3 1.00 0.005 0.010 0.33 256 16 16 1.0000 1.0000 2 0.00 0.001 0.004 0.33 256 16 16 0.0100 1.0000 3 0.50 0.006 1.265 0.33 256 16 16 0.0100 0.0100 2 1.00 0.004 0.006 0.33 256 16 16 0.0100 0.0100 3 1.00 0.005 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 1.0000 3 0.33 0.001 0.006 0.33 256 16 16 0.0001 1.0000										
0.33 256 16 16 1.0000 0.0001 3 1.00 0.005 0.010 0.33 256 16 16 0.0100 1.0000 2 0.00 0.001 0.004 0.33 256 16 16 0.0100 1.0000 3 0.50 0.006 1.265 0.33 256 16 16 0.0100 0.0100 3 1.00 0.005 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 1.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 0.0100 3 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0010	0.33				1.0000				0.004	
0.33 256 16 16 0.0100 1.0000 2 0.00 0.001 0.004 0.33 256 16 16 0.0100 1.0000 3 0.50 0.006 1.265 0.33 256 16 16 0.0100 0.0100 2 1.00 0.004 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 1.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 1.0000 2 0.33 0.001 0.005 0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.006 0.33 256 16 16 0.00001 0.0001			16	16		0.0001			0.001	0.006
0.33 256 16 16 0.0100 1.0000 3 0.50 0.006 1.265 0.33 256 16 16 0.0100 0.0100 2 1.00 0.004 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.005 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 1.0000 2 0.33 0.006 0.006 0.33 256 16 16 0.0001 1.0000 3 0.33 0.006 0.041 0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.009 0.33 256 16 16 16 0.0001										
0.33 256 16 16 0.0100 0.0100 2 1.00 0.004 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0001 1.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 1.0000 3 0.33 0.006 0.006 0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0100 3 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0001 3 1.00 0.005 0.059 0.33 256 16 64 1.0000 1.0000										
0.33 256 16 16 0.0100 0.0100 3 1.00 0.005 0.006 0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0100 0.0001 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 1.0000 3 0.33 0.006 0.041 0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0100 3 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0001 3 1.00 0.005 0.008 0.33 256 16 64 1.0000 1.0000 2 0.00 0.001 0.003 0.33 256 16 64 1.0000 0.0100										
0.33 256 16 16 0.0100 0.0001 2 0.83 0.001 0.006 0.33 256 16 16 0.0001 0.0001 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 1.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 1.0000 3 0.33 0.006 0.041 0.33 256 16 16 0.0001 0.0100 3 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0001 3 1.00 0.005 0.008 0.33 256 16 16 16 0.0001 1.0000 2 0.00 0.001 0.005 0.33 256 16 64 1.0000 1.0000 3 0.17 0.006 0.058 0.33 256 16 64 1.0000										
0.33 256 16 16 0.0001 1.0000 2 0.33 0.001 0.006 0.33 256 16 16 0.0001 1.0000 3 0.33 0.006 0.041 0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0010 2 1.00 0.005 0.008 0.33 256 16 16 0.0001 0.0001 3 1.00 0.005 0.008 0.33 256 16 64 1.0000 1.0000 2 0.00 0.001 0.003 0.33 256 16 64 1.0000 0.0100 3 1.10 0.006 0.058 0.33 256 16 64 1.0000 0.0100 2 0.50 0.001 0.011 0.33 256 16 64 1.0000 0.0001										
0.33 256 16 16 0.0001 1.0000 3 0.33 0.006 0.041 0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0001 2 1.00 0.005 0.008 0.33 256 16 16 0.0001 0.0001 3 1.00 0.005 0.009 0.33 256 16 64 1.0000 1.0000 2 0.00 0.001 0.003 0.33 256 16 64 1.0000 1.0000 3 0.17 0.006 0.058 0.33 256 16 64 1.0000 0.0100 3 0.01 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.011 0.001 0.011 0.001 0.011 0.001 0.011 0.001 0.011 0.001 0.011 0.011		256	16	16			3			
0.33 256 16 16 0.0001 0.0100 2 1.00 0.005 0.006 0.33 256 16 16 0.0001 0.0100 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 0.0001 2 1.00 0.005 0.008 0.33 256 16 64 1.0000 1.0000 2 0.00 0.001 0.003 0.33 256 16 64 1.0000 1.0000 3 0.17 0.006 0.058 0.33 256 16 64 1.0000 0.0100 2 0.50 0.001 0.011 0.33 256 16 64 1.0000 0.0100 3 1.00 0.009 0.019 0.33 256 16 64 1.0000 0.0001 3 1.00 0.010 0.016 0.33 256 16 64 0.0100 1.0000										
0.33 256 16 16 0.0001 0.0100 3 1.00 0.006 0.006 0.33 256 16 16 0.0001 0.0001 2 1.00 0.005 0.008 0.33 256 16 16 16 0.0001 1.0000 2 0.00 0.001 0.055 0.33 256 16 64 1.0000 1.0000 3 0.17 0.006 0.058 0.33 256 16 64 1.0000 0.0100 2 0.50 0.001 0.011 0.33 256 16 64 1.0000 0.0100 3 1.00 0.009 0.019 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 0.0001 3 1.00 0.010 0.016 0.33 256 16 64 0.0100										
0.33 256 16 16 0.0001 0.0001 2 1.00 0.005 0.008 0.33 256 16 16 0.0001 0.0001 3 1.00 0.005 0.059 0.33 256 16 64 1.0000 1.0000 3 0.17 0.006 0.053 0.33 256 16 64 1.0000 0.0100 2 0.50 0.001 0.011 0.33 256 16 64 1.0000 0.0100 3 1.00 0.009 0.019 0.33 256 16 64 1.0000 0.0100 3 1.00 0.009 0.019 0.33 256 16 64 1.0000 0.0001 3 1.00 0.010 0.016 0.33 256 16 64 1.0100 1.0000 2 0.00 0.001 0.017 0.33 256 16 64 0.0100 1.0000										
0.33 256 16 16 0.0001 0.0001 3 1.00 0.005 0.059 0.33 256 16 64 1.0000 1.0000 2 0.00 0.001 0.003 0.33 256 16 64 1.0000 0.0100 2 0.50 0.001 0.018 0.33 256 16 64 1.0000 0.0100 3 1.00 0.009 0.019 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 0.0100 1.0000 3 1.00 0.010 0.017 0.33 256 16 64 0.0100 1.0000 3 0.17 0.008 0.080 0.33 256 16 64 0.0100 0.0100										
0.33 256 16 64 1.0000 1.0000 2 0.00 0.001 0.003 0.33 256 16 64 1.0000 1.0000 3 0.17 0.006 0.058 0.33 256 16 64 1.0000 0.0100 2 0.50 0.001 0.019 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 0.0001 3 1.00 0.010 0.016 0.33 256 16 64 1.0000 0.0001 3 1.00 0.010 0.017 0.33 256 16 64 0.0100 1.0000 3 0.01 0.001 0.001 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.016 0.33 256 16 64 0.0100 0.0001										
0.33 256 16 64 1.0000 0.0100 2 0.50 0.001 0.011 0.33 256 16 64 1.0000 0.0100 3 1.00 0.009 0.019 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 0.0001 2 0.00 0.001 0.006 0.33 256 16 64 0.0100 1.0000 2 0.00 0.001 0.006 0.33 256 16 64 0.0100 1.0000 3 0.17 0.008 0.080 0.33 256 16 64 0.0100 0.0100 3 1.00 0.011 0.014 0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.016 0.33 256 16 64 0.0001 1.0000										
0.33 256 16 64 1.0000 0.0100 3 1.00 0.009 0.019 0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 1.0000 2 0.00 0.001 0.017 0.33 256 16 64 0.0100 1.0000 3 0.17 0.008 0.080 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.014 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.014 0.33 256 16 64 0.0100 0.0100 3 1.00 0.011 0.016 0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.016 0.33 256 16 64 0.0001 1.0000	0.33	256	16	64	1.0000	1.0000	3	0.17	0.006	0.058
0.33 256 16 64 1.0000 0.0001 2 0.67 0.001 0.016 0.33 256 16 64 1.0000 0.0001 3 1.00 0.010 0.017 0.33 256 16 64 0.0100 1.0000 2 0.00 0.001 0.008 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.014 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.014 0.33 256 16 64 0.0100 0.0100 3 1.00 0.010 0.016 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.016 0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.014 0.33 256 16 64 0.0001 1.0000										
0.33 256 16 64 1.0000 0.0001 3 1.00 0.010 0.017 0.33 256 16 64 0.0100 1.0000 2 0.00 0.001 0.006 0.33 256 16 64 0.0100 1.0000 3 0.17 0.008 0.080 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.016 0.33 256 16 64 0.0100 0.0100 3 1.00 0.010 0.016 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.016 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.016 0.33 256 16 64 0.0001 1.0000 3 0.17 0.001 0.012 0.33 256 16 64 0.0001 1.0000										
0.33 256 16 64 0.0100 1.0000 2 0.00 0.001 0.006 0.33 256 16 64 0.0100 1.0000 3 0.17 0.008 0.080 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.014 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.016 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.016 0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.016 0.33 256 16 64 0.0001 1.0000 2 0.17 0.001 0.016 0.33 256 16 64 0.0001 1.0000 3 0.17 0.013 0.108 0.33 256 16 64 0.0001 0.0100										
0.33 256 16 64 0.0100 1.0000 3 0.17 0.008 0.080 0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.014 0.33 256 16 64 0.0100 0.0100 3 1.00 0.010 0.016 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.014 0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.014 0.33 256 16 64 0.0001 1.0000 2 0.17 0.001 0.014 0.33 256 16 64 0.0001 1.0000 3 0.17 0.013 0.108 0.33 256 16 64 0.0001 0.0100 2 1.00 0.012 0.018 0.33 256 16 64 0.0001 0.0001										
0.33 256 16 64 0.0100 0.0100 2 0.83 0.001 0.014 0.33 256 16 64 0.0100 0.0100 3 1.00 0.010 0.016 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.016 0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.016 0.33 256 16 64 0.0001 1.0000 2 0.17 0.001 0.016 0.33 256 16 64 0.0001 1.0000 3 0.17 0.013 0.108 0.33 256 16 64 0.0001 0.0100 2 1.00 0.012 0.018 0.33 256 16 64 0.0001 0.0100 3 1.00 0.011 0.019 0.33 256 16 64 0.0001 0.0001										
0.33 256 16 64 0.0100 0.0100 3 1.00 0.010 0.016 0.33 256 16 64 0.0100 0.0001 2 1.00 0.011 0.016 0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.016 0.33 256 16 64 0.0001 1.0000 2 0.17 0.001 0.018 0.33 256 16 64 0.0001 1.0000 3 0.17 0.013 0.108 0.33 256 16 64 0.0001 0.0100 2 1.00 0.012 0.018 0.33 256 16 64 0.0001 0.0100 2 1.00 0.011 0.019 0.33 256 16 64 0.0001 0.0001 2 1.00 0.015 0.022 0.33 256 16 64 0.0001 0.0001										
0.33 256 16 64 0.0100 0.0001 3 1.00 0.011 0.014 0.33 256 16 64 0.0001 1.0000 2 0.17 0.001 0.016 0.33 256 16 64 0.0001 1.0000 3 0.17 0.013 0.108 0.33 256 16 64 0.0001 0.0100 3 1.00 0.011 0.019 0.33 256 16 64 0.0001 0.0100 3 1.00 0.011 0.019 0.33 256 16 64 0.0001 0.0001 2 1.00 0.015 0.022 0.33 256 16 64 0.0001 0.0001 3 1.00 0.014 0.022 0.33 256 16 64 0.0001 0.0001 3 1.00 0.014 0.022 0.33 256 16 256 1.0000 1.0000	0.33	256	16	64	0.0100	0.0100		1.00	0.010	0.016
0.33 256 16 64 0.0001 1.0000 2 0.17 0.001 0.016 0.33 256 16 64 0.0001 1.0000 3 0.17 0.013 0.108 0.33 256 16 64 0.0001 0.0100 2 1.00 0.012 0.018 0.33 256 16 64 0.0001 0.0100 3 1.00 0.011 0.012 0.33 256 16 64 0.0001 0.0001 2 1.00 0.015 0.022 0.33 256 16 64 0.0001 0.0001 3 1.00 0.014 0.022 0.33 256 16 256 1.0000 1.0000 2 0.00 0.001 0.011 0.33 256 16 256 1.0000 1.0000 3 0.00 0.011 0.011 0.33 256 16 256 1.0000 0.0100										
0.33 256 16 64 0.0001 1.0000 3 0.17 0.013 0.108 0.33 256 16 64 0.0001 0.0100 2 1.00 0.012 0.018 0.33 256 16 64 0.0001 0.0100 3 1.00 0.011 0.019 0.33 256 16 64 0.0001 0.0001 3 1.00 0.014 0.022 0.33 256 16 64 0.0001 0.0001 3 1.00 0.014 0.022 0.33 256 16 64 0.0001 1.0000 2 0.00 0.001 0.011 0.33 256 16 256 1.0000 1.0000 3 0.00 0.011 0.011 0.33 256 16 256 1.0000 1.0000 3 0.00 0.011 0.022 0.33 256 16 256 1.0000 0.0100										
0.33 256 16 64 0.0001 0.0100 2 1.00 0.012 0.018 0.33 256 16 64 0.0001 0.0100 3 1.00 0.011 0.019 0.33 256 16 64 0.0001 0.0001 2 1.00 0.014 0.022 0.33 256 16 64 0.0001 1.0000 2 0.00 0.014 0.022 0.33 256 16 256 1.0000 1.0000 2 0.00 0.001 0.011 0.33 256 16 256 1.0000 1.0000 3 0.00 0.011 0.015 0.33 256 16 256 1.0000 0.0100 2 0.00 0.001 0.002 0.33 256 16 256 1.0000 0.0100 3 0.33 0.001 0.022 0.33 256 16 256 1.0000 0.0001										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.33	256								
0.33 256 16 256 1.0000 1.0000 3 0.00 0.159 2.003 0.33 256 16 256 1.0000 0.0100 2 0.00 0.001 0.022 0.33 256 16 256 1.0000 0.0010 3 0.33 0.037 0.413 0.33 256 16 256 1.0000 0.0001 2 0.83 0.001 0.078 0.33 256 16 256 1.0000 0.0001 3 1.00 0.050 0.079 0.33 256 16 256 0.0100 1.0000 2 0.00 0.001 0.019 0.33 256 16 256 0.0100 1.0000 3 0.00 0.277 0.997 0.33 256 16 256 0.0100 0.100 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0100										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.33 256 16 256 1.0000 0.0100 3 0.33 0.037 0.413 0.33 256 16 256 1.0000 0.0001 2 0.83 0.001 0.078 0.33 256 16 256 1.0000 0.0001 3 1.00 0.050 0.079 0.33 256 16 256 0.0100 1.0000 2 0.00 0.001 0.019 0.33 256 16 256 0.0100 0.0100 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0100 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0100 3 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0001 2 1.00 0.054 0.090 0.33 256 16 256 0.0100 0.0001										
0.33 256 16 256 1.0000 0.0001 2 0.83 0.001 0.078 0.33 256 16 256 1.0000 0.0001 3 1.00 0.050 0.079 0.33 256 16 256 0.0100 1.0000 2 0.00 0.001 0.019 0.33 256 16 256 0.0100 1.0000 3 0.00 0.277 0.997 0.33 256 16 256 0.0100 0.0100 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0100 3 1.00 0.053 0.079 0.33 256 16 256 0.0100 0.0001 2 1.00 0.053 0.079 0.33 256 16 256 0.0100 0.0001 2 1.00 0.094 0.099 0.33 256 16 256 0.0100 0.0001										
0.33 256 16 256 1.0000 0.0001 3 1.00 0.050 0.079 0.33 256 16 256 0.0100 1.0000 2 0.00 0.001 0.019 0.33 256 16 256 0.0100 1.0000 3 0.00 0.277 0.997 0.33 256 16 256 0.0100 0.0100 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0001 2 1.00 0.053 0.079 0.33 256 16 256 0.0100 0.0001 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0001 2 1.00 0.094 0.099 0.33 256 16 256 0.0100 0.0001 3 1.00 0.094 0.099 0.33 256 16 256 0.0001 1.0000										
0.33 256 16 256 0.0100 1.0000 2 0.00 0.001 0.019 0.33 256 16 256 0.0100 1.0000 3 0.00 0.277 0.997 0.33 256 16 256 0.0100 0.0100 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0100 3 1.00 0.053 0.079 0.33 256 16 256 0.0100 0.0001 2 1.00 0.094 0.099 0.33 256 16 256 0.0100 0.0001 3 1.00 0.094 0.099 0.33 256 16 256 0.0100 1.0000 2 0.00 0.001 0.041										
0.33 256 16 256 0.0100 0.0100 2 1.00 0.054 0.080 0.33 256 16 256 0.0100 0.0100 3 1.00 0.053 0.079 0.33 256 16 256 0.0100 0.0001 2 1.00 0.094 0.099 0.33 256 16 256 0.0100 0.0001 3 1.00 0.094 0.099 0.33 256 16 256 0.0001 1.0000 2 0.00 0.001 0.041										
0.33 256 16 256 0.0100 0.0100 3 1.00 0.053 0.079 0.33 256 16 256 0.0100 0.0001 2 1.00 0.094 0.099 0.33 256 16 256 0.0100 0.0001 3 1.00 0.094 0.099 0.33 256 16 256 0.0001 1.0000 2 0.00 0.001 0.041										
0.33 256 16 256 0.0100 0.0001 2 1.00 0.094 0.099 0.33 256 16 256 0.0100 0.0001 3 1.00 0.094 0.099 0.33 256 16 256 0.0001 1.0000 2 0.00 0.001 0.041										
0.33 256 16 256 0.0100 0.0001 3 1.00 0.094 0.099 0.33 256 16 256 0.0001 1.0000 2 0.00 0.001 0.041										
0.33 256 16 256 0.0001 1.0000 2 0.00 0.001 0.041										
0.55 250 10 250 0.0001 1.0000 5 0.00 0.500 1.580	0.33	256	16	256	0.0001	1.0000	3	0.00	0.360	1.386

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	256	16	256	0.0001	0.0100	2	1.00	0.095	0.100
0.33	256	16	256	0.0001	0.0100	3	1.00	0.082	0.102
0.33	256 256	16	256 256	0.0001	0.0001	2	1.00	0.088	0.122 0.416
0.33	256	16 64	1	1.0000	1.00001	2	0.00	0.101	0.416
0.33	256	64	1	1.0000	1.0000	3	0.67	0.005	0.016
0.33	256	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	256	64	1	1.0000	0.0100	3	0.17	0.005	0.017
0.33	256	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.33	256 256	64 64	1	1.0000 0.0100	0.0001 1.0000	3	0.83	0.003	0.019
0.33	256	64	1	0.0100	1.0000	3	0.83	0.003	0.016
0.33	256	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.33	256	64	1	0.0100	0.0100	3	0.50	0.004	0.014
0.33	256	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	256 256	64 64	1	0.0100	0.0001 1.0000	3	0.50	0.004	0.017
0.33	256	64	1	0.0001	1.0000	3	0.67	0.004	0.016
0.33	256	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	256	64	1	0.0001	0.0100	3	0.83	0.003	0.017
0.33	256	64	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	256 256	64 64	1 4	0.0001 1.0000	0.0001 1.0000	2	0.33	0.004	0.018
0.33	256	64	4	1.0000	1.0000	3	0.50	0.003	0.001
0.33	256	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.33	256	64	4	1.0000	0.0100	3	0.83	0.004	0.021
0.33	256	64	4	1.0000	0.0001	2	0.00	0.001	0.001
0.33	256 256	64 64	4	1.0000 0.0100	0.0001 1.0000	3	1.00 0.33	0.005 0.001	0.010
0.33	256	64	4	0.0100	1.0000	3	0.83	0.001	0.004
0.33	256	64	4	0.0100	0.0100	2	0.67	0.001	0.004
0.33	256	64	4	0.0100	0.0100	3	1.00	0.003	3.997
0.33	256	64	4	0.0100	0.0001	2	0.33	0.001	0.003
0.33	256 256	64	4	0.0100	0.0001 1.0000	3	1.00 0.67	0.003	0.520 0.004
0.33	256	64	4	0.0001	1.0000	3	0.67	0.001	0.004
0.33	256	64	4	0.0001	0.0100	2	0.67	0.001	0.003
0.33	256	64	4	0.0001	0.0100	3	1.00	0.003	0.003
0.33	256	64	4	0.0001	0.0001	2	1.00	0.003	0.004
0.33	256 256	64	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.003	0.004
0.33	256	64	16	1.0000	1.0000	3	0.00	0.001	0.003
0.33	256	64	16	1.0000	0.0100	2	0.17	0.001	0.005
0.33	256	64	16	1.0000	0.0100	3	1.00	0.005	0.007
0.33	256	64	16	1.0000	0.0001	2	0.33	0.001	0.006
0.33	256 256	64 64	16 16	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.006	0.006
0.33	256	64	16	0.0100	1.0000	3	0.50	0.001	0.003
0.33	256	64	16	0.0100	0.0100	2	0.83	0.001	0.006
0.33	256	64	16	0.0100	0.0100	3	1.00	0.005	0.006
0.33	256	64	16	0.0100	0.0001	2	0.83	0.001	0.006
0.33	256 256	64	16 16	0.0100	0.0001 1.0000	3 2	1.00 0.50	0.004	0.005 0.004
0.33	256	64	16	0.0001	1.0000	3	0.83	0.001	0.004
0.33	256	64	16	0.0001	0.0100	2	1.00	0.005	0.005
0.33	256	64	16	0.0001	0.0100	3	1.00	0.004	0.005
0.33	256	64	16	0.0001	0.0001	2	1.00	0.005	0.006
0.33	256 256	64 64	16 64	0.0001 1.0000	0.0001 1.0000	2	1.00 0.00	0.005	0.006
0.33	256	64	64	1.0000	1.0000	3	0.00	0.001	0.001
0.33	256	64	64	1.0000	0.0100	2	0.17	0.001	0.009
0.33	256	64	64	1.0000	0.0100	3	1.00	0.008	0.010
0.33	256	64	64	1.0000	0.0001	2	1.00	0.010	0.015
0.33	256 256	64 64	64	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.011	0.016
0.33	256	64	64	0.0100	1.0000	3	0.00	0.001	0.063
0.33	256	64	64	0.0100	0.0100	2	0.83	0.001	0.013
0.33	256	64	64	0.0100	0.0100	3	1.00	0.011	0.013
0.33	256	64	64	0.0100	0.0001	2	1.00	0.012	0.018
0.33	256 256	64	64	0.0100	1.0000	3	1.00 0.67	0.012	0.018
0.33	256	64	64	0.0001	1.0000	3	0.83	0.001	0.003
0.33	256	64	64	0.0001	0.0100	2	1.00	0.012	0.019
0.33	256	64	64	0.0001	0.0100	3	1.00	0.014	0.019
0.33	256	64	64	0.0001	0.0001	2	1.00	0.014	0.023
0.33	256	64	64	0.0001	0.0001	3	1.00	0.015	0.023

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.33	256	64	256	1.0000	1.0000	2	0.00	0.001	0.017
0.33	256	64	256	1.0000	1.0000	3	0.00	0.160	1.382
0.33	256	64	256	1.0000	0.0100	2	0.00	0.001	0.001
0.33	256	64	256	1.0000	0.0100	3	0.50	0.036	0.384
0.33	256	64	256	1.0000	0.0001	2	0.67	0.001	0.053
0.33	256	64	256	1.0000	0.0001	3	1.00	0.051	0.073
0.33	256	64	256	0.0100	1.0000	2	0.00	0.001	0.020
0.33	256	64	256	0.0100	1.0000	3	0.00	0.257	0.640
0.33	256	64	256	0.0100	0.0100	2	1.00	0.050	0.055
0.33	256	64	256	0.0100	0.0100	2	1.00	0.050	0.058
0.33	256 256	64	256 256	0.0100	0.0001	3	1.00	0.060	0.066 0.074
0.33	256	64	256	0.0001	1.0000	2	0.00	0.003	0.074
0.33	256	64	256	0.0001	1.0000	3	0.00	0.343	0.681
0.33	256	64	256	0.0001	0.0100	2	1.00	0.061	0.068
0.33	256	64	256	0.0001	0.0100	3	1.00	0.065	0.101
0.33	256	64	256	0.0001	0.0001	2	1.00	0.071	0.084
0.33	256	64	256	0.0001	0.0001	3	1.00	0.073	0.094
0.33	256	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.33	256	256	1	1.0000	1.0000	3	1.00	0.003	0.018
0.33	256	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.33	256	256	1	1.0000	0.0100	3	0.83	0.003	0.017
0.33	256	256	1	1.0000	0.0001	3	0.00 1.00	0.001	0.001
0.33	256 256	256 256	1	0.0100	1.00001	2	0.00	0.003	0.008
0.33	256	256	1	0.0100	1.0000	3	0.83	0.001	0.001
0.33	256	256	1	0.0100	0.0100	2	0.00	0.003	0.001
0.33	256	256	1	0.0100	0.0100	3	0.50	0.004	0.020
0.33	256	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.33	256	256	1	0.0100	0.0001	3	0.83	0.003	0.013
0.33	256	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.33	256	256	1	0.0001	1.0000	3	0.83	0.005	0.013
0.33	256	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.33	256	256	1	0.0001	0.0100	3	0.67	0.005	0.016
0.33	256	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.33	256	256	1	0.0001	0.0001	3	0.83	0.003	0.014
0.33	256	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.33	256 256	256 256	4	1.0000	1.0000 0.0100	2	0.67	0.003	0.016
0.33	256	256	4	1.0000	0.0100	3	1.00	0.001	0.001
0.33	256	256	4	1.0000	0.0001	2	0.00	0.003	0.001
0.33	256	256	4	1.0000	0.0001	3	1.00	0.003	0.009
0.33	256	256	4	0.0100	1.0000	2	0.00	0.001	0.001
0.33	256	256	4	0.0100	1.0000	3	0.50	0.003	0.018
0.33	256	256	4	0.0100	0.0100	2	0.50	0.001	0.004
0.33	256	256	4	0.0100	0.0100	3	1.00	0.003	0.012
0.33	256	256	4	0.0100	0.0001	2	0.67	0.001	0.004
0.33	256	256	4	0.0100	0.0001	3	1.00	0.003	0.004
0.33	256	256	4	0.0001	1.0000	2	0.67	0.001	0.004
0.33	256	256	4	0.0001	1.0000	3	0.83	0.003	0.020
0.33	256	256	4	0.0001	0.0100	2	0.83	0.001	0.004
0.33	256 256	256 256	4	0.0001	0.0100	3 2	1.00	0.003	0.011
0.33	256	256	4	0.0001	0.0001	3	1.00	0.004	0.004
0.33	256	256	16	1.0000	1.0000	2	0.00	0.003	0.004
0.33	256	256	16	1.0000	1.0000	3	0.67	0.004	0.030
0.33	256	256	16	1.0000	0.0100	2	0.17	0.001	0.004
0.33	256	256	16	1.0000	0.0100	3	1.00	0.004	0.011
0.33	256	256	16	1.0000	0.0001	2	0.67	0.001	0.006
0.33	256	256	16	1.0000	0.0001	3	1.00	0.004	0.006
0.33	256	256	16	0.0100	1.0000	2	0.00	0.001	0.001
0.33	256	256	16	0.0100	1.0000	3	0.83	0.004	0.029
0.33	256	256	16	0.0100	0.0100	2	0.67	0.001	0.005
0.33	256	256	16	0.0100	0.0100	3	1.00	0.004	0.006
0.33	256	256	16	0.0100	0.0001	2	0.83	0.001	0.006
0.33	256 256	256 256	16 16	0.0100	0.0001 1.0000	2	1.00 0.33	0.005	0.005
0.33	256	256	16	0.0001	1.0000	3	0.33	0.001	0.003
0.33	256	256	16	0.0001	0.0100	2	1.00	0.005	0.007
0.33	256	256	16	0.0001	0.0100	3	1.00	0.005	0.007
0.33	256	256	16	0.0001	0.0001	2	1.00	0.006	0.008
		256	16	0.0001	0.0001	3	1.00	0.007	0.008
0.33	256			- 1					
0.33	256	256	64	1.0000	1.0000	2	0.00	0.001	0.001
			64 64	1.0000 1.0000	1.0000	3	0.00	0.001	0.001
0.33	256	256							

1.033 256 256 64 1.0000 0.0001 2 1.00 0.010 0.014 0.33 256 256 64 1.0000 0.0001 3 1.00 0.010 0.014 0.33 256 255 64 0.0100 0.0000 3 0.07 0.009 0.004 0.33 256 255 64 0.0100 0.0100 2 0.03 0.001 0.073 0.33 256 255 64 0.0100 0.0100 2 0.00 0.001 0.013 0.33 256 255 64 0.0100 0.0001 3 1.00 0.011 0.013 0.33 256 255 64 0.0100 0.0001 3 1.00 0.011 0.013 0.33 256 255 64 0.0100 0.0001 3 1.00 0.011 0.013 0.33 256 255 64 0.0100 0.0001 3 1.00 0.011 0.014 0.33 256 255 64 0.0001 0.0001 2 1.00 0.011 0.015 0.33 256 255 64 0.0001 0.0000 2 0.50 0.001 0.015 0.33 256 255 64 0.0001 0.0000 2 0.50 0.001 0.015 0.33 256 255 64 0.0001 0.0000 2 0.00 0.001 0.015 0.33 256 255 64 0.0001 0.0100 2 1.00 0.015 0.019 0.33 256 255 64 0.0001 0.0100 2 1.00 0.015 0.019 0.33 256 255 54 0.0001 0.0100 2 1.00 0.012 0.019 0.33 256 255 55 64 0.0001 0.0010 2 1.00 0.001 0.016 0.33 256 255 255 1.0000 0.0001 2 1.00 0.002 0.023 0.33 256 255 255 1.0000 0.0001 2 0.00 0.001 0.016 0.33 256 255 255 1.0000 0.0001 2 0.00 0.001 0.016 0.33 256 255 255 1.0000 0.0001 2 0.00 0.001 0.016 0.33 256 255 255 1.0000 0.0001 2 0.00 0.001 0.001 0.33 256 255 255 1.0000 0.0001 2 0.00 0.001 0.001 0.33 256 256 256 1.0000 0.0001 2 0.00 0.001 0.001 0.33 256 256 256 0.0000 0.0001 2 0.00 0.001 0.001 0.33 256 256 256 0.0000 0.0001 2 0.00 0.0001 0.001 0.33 256 256 256 0.0000 0.0001 2 0.00 0.0001 0.001 0.33 256 256 256 0.0000 0.0001 2 0.00 0.0001 0.33 256 256 256 0.0000 0.0000 2	mul	222	m	lel.	TR	DTR	olo	SR	mint	moret
0.33 256 255 64 0.000 0.0001 3 1.00 0.010 0.001 0.33 256 255 64 0.0100 0.0001 3 1.00 0.001 0.001 0.33 256 255 64 0.0100 0.0001 3 1.00 0.001 0.001 0.33 256 256 64 0.0100 0.0001 2 0.03 0.001 0.073 0.33 256 256 64 0.0100 0.0001 2 1.00 0.011 0.013 0.33 256 256 64 0.0100 0.0001 2 1.00 0.011 0.015 0.33 256 256 64 0.0100 0.0001 3 1.00 0.011 0.015 0.33 256 256 64 0.0001 0.0000 2 0.50 0.001 0.016 0.33 256 256 64 0.0001 0.0000 3 0.33 0.001 0.007 0.33 256 256 64 0.0001 0.0100 3 0.38 0.016 0.097 0.33 256 256 64 0.0001 0.0100 3 0.03 0.001 0.016 0.33 256 256 64 0.0001 0.0100 3 1.00 0.012 0.019 0.33 256 256 64 0.0001 0.0100 3 1.00 0.015 0.019 0.33 256 256 64 0.0001 0.0001 2 1.00 0.020 0.023 0.33 256 256 546 0.0001 0.0001 2 1.00 0.020 0.023 0.33 256 256 256 1.0000 1.0000 3 1.00 0.020 0.023 0.33 256 256 256 1.0000 1.0000 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 1.0000 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 0.0100 3 0.83 0.035 1.535 0.33 256 256 256 1.0000 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 1.0000 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001	mul	m_1	m_2				alg		mint	maxt
0.33 256 256 64 0.0100 1.0000 2 0.00 0.001 0.001										
0.33 256 256 64 0.0100 0.0100 2 0.83 0.001 0.073										
0.33 256 256 64 0.0100 0.0100 2 0.03 0.001 0.013 0.33 256 256 64 0.0100 0.0001 3 1.00 0.011 0.014 0.33 256 256 64 0.0100 0.0001 3 1.00 0.011 0.015 0.033 256 256 64 0.0001 0.0000 2 0.00 0.011 0.016 0.033 256 256 64 0.0001 0.0000 2 0.00 0.010 0.016 0.033 256 256 64 0.0001 0.0000 3 0.38 0.016 0.097 0.33 256 256 64 0.0001 0.0100 3 1.00 0.015 0.019 0.33 256 256 64 0.0001 0.0100 3 1.00 0.012 0.019 0.33 256 256 64 0.0001 0.0001 3 1.00 0.015 0.019 0.33 256 256 64 0.0001 0.0001 3 1.00 0.020 0.023 0.33 256 256 64 0.0001 0.0001 3 1.00 0.020 0.023 0.33 256 256 64 0.0001 0.0001 3 1.00 0.020 0.023 0.33 256 256 256 1.0000 1.0000 3 1.00 0.020 0.023 0.33 256 256 256 1.0000 1.0000 3 1.00 0.020 0.023 0.33 256 256 256 1.0000 1.0000 3 1.00 0.020 0.023 0.33 256 256 256 1.0000 0.0000 3 1.00 0.001 0.001 0.000 0.00000 0.0000 0.00000 0.00000 0.00000 0.00000 0.000000 0.00000000										
0.33 256 256 64 0.0100 0.0001 3 1.00 0.011 0.014										
0.33 256 256 64 0.0100 0.0001 2 0.00 0.001 0.015 0.33 256 256 64 0.0001 0.0000 3 0.00 0.011 0.015 0.33 256 256 64 0.0001 0.0000 3 0.83 0.016 0.097 0.33 256 256 64 0.0001 0.0100 2 1.00 0.012 0.001 0.33 256 256 64 0.0001 0.0100 3 1.00 0.015 0.019 0.33 256 256 64 0.0001 0.0100 3 1.00 0.012 0.019 0.33 256 255 64 0.0001 0.0001 2 1.00 0.020 0.023 0.33 256 255 54 0.0001 0.0001 2 0.00 0.0001 0.001 0.33 256 255 256 1.0000 1.0000 2 0.00 0.001 0.015 0.33 256 255 256 1.0000 0.0001 2 0.00 0.001 0.016 0.33 256 256 256 1.0000 0.0000 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 0.0100 2 0.00 0.001 0.001 0.33 256 256 256 1.0000 0.0100 2 0.00 0.001 0.001 0.33 256 256 256 1.0000 0.0100 2 0.00 0.001 0.001 0.33 256 256 256 1.0000 0.0100 2 0.07 0.001 0.001 0.33 256 256 256 1.0000 0.0100 2 0.07 0.001 0.001 0.33 256 256 256 0.0000 0.0010 2 0.07 0.001 0.001 0.33 256 256 256 0.0000 0.0010 2 0.07 0.001 0.001 0.33 256 256 256 0.0000 0.0010 2 0.07 0.001 0.001 0.33 256 256 256 0.0000 0.0001 3 0.00 0.001 0.001 0.33 256 256 256 0.0000 0.0010 3 0.00 0.001 0.001 0.33 256 256 256 0.0100 0.0100 2 0.83 0.001 0.076 0.33 256 256 256 0.0100 0.0001 3 1.00 0.056 0.079 0.33 256 256 256 0.0000 0.0100 3 1.00 0.076 0.007 0.33 256 256 256 0.0000 0.0100 2 0.00 0.001 0.001 0.33 256 256 256 0.0000 0.0010 2 0.00 0.000 0.001 0.33 256 256 256 0.0000 0.0010 2 0.00 0.000 0.001 0.33 256 256 256 0.0000 0.0000 2 0.00 0.000 0.000 0.33 256 256 256 0.0000 0										
0.33 256 256 64 0.0001 0.0001 3 1.00 0.011 0.015										
0.33 256 256 64 0.0001 1.0000 2 0.50 0.001 0.016 0.097 0.33 256 256 64 0.0001 0.0100 2 1.00 0.015 0.097 0.33 256 256 64 0.0001 0.0100 3 1.00 0.015 0.019 0.33 256 256 64 0.0001 0.0001 3 1.00 0.015 0.019 0.33 256 256 64 0.0001 0.0001 3 1.00 0.020 0.023 0.33 256 256 64 0.0001 0.0001 3 1.00 0.020 0.023 0.33 256 256 256 1.0000 1.0000 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 0.0001 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 0.0100 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 0.0100 2 0.00 0.001 0.016 0.33 256 256 256 1.0000 0.0100 2 0.07 0.001 0.016 0.33 256 256 256 1.0000 0.0100 2 0.07 0.001 0.016 0.33 256 256 256 1.0000 0.0001 2 0.67 0.001 0.078 0.33 256 256 256 1.0000 0.0001 2 0.67 0.001 0.078 0.33 256 256 256 0.0000 0.0001 2 0.67 0.001 0.078 0.33 256 256 256 0.0000 0.0001 2 0.07 0.005 0.080 0.33 256 256 256 0.0010 0.0000 2 0.00 0.001 0.021 0.33 256 256 256 0.0100 0.0000 2 0.00 0.001 0.021 0.33 256 256 256 0.0100 0.0000 2 0.03 0.003 0.05 0.33 256 256 256 0.0000 0.0000 3 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0000 3 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0000 3 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0000 3 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0000 3 0.000 0.000 0.000 0.33 256 256 256 0.0000 0.0000 3 0.000 0.0000 0.0000 0.33 256 256 256 0.0000 0.0000 3 0.000 0.000 0.0000 0.33 256 256 256 0.0000 0.0000 3 0.000 0.0000 0.33 256 256 256 0.0000 0.0000 3 0.000 0.0000 0.33 256 256 256 0.0000										
0.33 256 256 64 0.0001 0.0100 2 1.000 0.012 0.019 0.33 256 256 64 0.0001 0.0100 3 1.000 0.015 0.019 0.33 256 256 64 0.0001 0.0001 2 1.000 0.020 0.023 0.33 256 256 64 0.0001 0.0001 2 1.000 0.020 0.023 0.33 256 256 256 1.0000 1.0000 2 0.000 0.001 0.016 0.33 256 256 256 1.0000 1.0000 2 0.000 0.001 0.016 0.33 256 256 256 1.0000 0.0001 2 0.000 0.001 0.001 0.33 256 256 256 1.0000 0.0000 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 0.0000 3 0.033 0.035 0.033 0.33 256 256 256 1.0000 0.0000 3 0.033 0.035 0.035 0.33 256 256 256 1.0000 0.0001 3 1.00 0.055 0.080 0.33 256 256 256 0.0100 0.0001 3 1.00 0.055 0.080 0.33 256 256 256 0.0100 0.0001 3 1.00 0.055 0.080 0.33 256 256 256 0.0100 0.0000 3 0.17 0.037 0.425 0.33 256 256 256 0.0100 0.0000 3 0.17 0.037 0.425 0.33 256 256 256 0.0100 0.0100 3 0.07 0.076 0.33 256 256 256 0.0100 0.0100 2 0.03 0.010 0.076 0.33 256 256 256 0.0100 0.0100 2 0.03 0.007 0.097 0.33 256 256 256 0.0100 0.0100 2 1.00 0.076 0.097 0.33 256 256 256 0.0100 0.0001 2 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0001 2 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0001 2 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0001 2 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0000 3 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0000 3 1.00 0.076 0.097 0.33 256 256 256 0.0000 0.0000 2 0.000 0.0000 0.0000 0.33 256 256 256 0.0000 0.0000 2 0.000 0.0000 0.0000 0.34 256 256 256 0.0000 0.0000 2 0.000 0.0000 0.0000 0.35 0.35 0.0000										
0.33 256 256 64 0.0001 0.0100 2 1.00 0.012 0.019										
0.33 256 256 64 0.0001 0.0001 2 1.00 0.015 0.019 0.33 256 256 64 0.0001 0.0001 3 1.00 0.020 0.023 0.33 256 256 256 64 0.0001 0.0001 3 1.00 0.020 0.023 0.33 256 256 256 256 1.0000 1.0000 2 0.00 0.001 0.016 0.33 256 256 256 256 1.0000 0.0000 2 0.00 0.001 0.001 0.33 256 256 256 256 1.0000 0.0100 2 0.00 0.001 0.001 0.33 256 256 256 256 1.0000 0.0100 2 0.00 0.001 0.001 0.33 256 256 256 256 1.0000 0.0001 3 0.38 0.035 1.535 0.33 256 256 256 256 1.0000 0.0001 3 1.00 0.055 0.080 0.33 256 256 256 0.0100 1.0000 2 0.00 0.001 0.021 0.33 256 256 256 0.0100 1.0000 3 1.00 0.055 0.080 0.33 256 256 256 0.0100 1.0000 3 0.17 0.037 0.425 0.33 256 256 256 0.0100 0.0100 3 1.00 0.056 0.079 0.33 256 256 256 0.0100 0.0100 3 1.00 0.056 0.079 0.33 256 256 256 0.0100 0.0100 3 1.00 0.056 0.079 0.33 256 256 256 0.0100 0.0001 2 1.00 0.070 0.097 0.33 256 256 256 0.0100 0.0001 2 1.00 0.070 0.097 0.33 256 256 256 0.0100 0.0001 2 1.00 0.070 0.097 0.33 256 256 256 0.0001 0.0000 2 0.033 0.001 0.076 0.33 256 256 256 0.0001 0.0000 2 0.033 0.001 0.076 0.33 256 256 256 0.0001 0.0000 2 0.000 0.000 0.33 256 256 256 0.0000 0.0000 2 0.00 0.0078 0.092 0.33 256 256 256 0.0000 0.0000 2 0.00 0.0078 0.092 0.33 256 256 256 0.0000 0.0000 2 0.00 0.0078 0.092 0.33 256 256 256 0.0000 0.0000 3 0.0000 0.0000 0.30 1 1 1 1.00000 0.0000 3 0.0000 0.0000 0.30 1 1 1 1.00000 0.0000 3 0.000 0.0000 0.30 1 1 1 1.00000 0.0000 3 0.000 0.0000 0.50 1 1 1 1.00000										
0.33 256 256 64 0.0001 0.0001 2 1.00 0.020 0.023 0.33 256 256 256 1.0000 1.0000 2 0.00 0.001 0.016 0.33 256 256 256 1.0000 0.0000 3 0.17 0.022 0.257 0.33 256 256 256 1.0000 0.0100 3 0.37 0.002 0.33 256 256 256 1.0000 0.0100 3 0.33 0.000 0.001 0.33 256 256 256 1.0000 0.0001 3 0.33 0.000 0.33 256 256 256 1.0000 0.0001 3 0.33 0.035 1.535 0.33 256 256 256 1.0000 0.0001 3 1.00 0.055 0.080 0.33 256 256 256 1.0000 0.0001 3 1.00 0.055 0.080 0.33 256 256 256 0.0000 1.0000 2 0.00 0.001 0.021 0.33 256 256 256 0.0100 1.0000 2 0.00 0.001 0.021 0.33 256 256 256 0.0100 0.0000 3 0.17 0.037 0.425 0.33 256 256 256 0.0100 0.0000 3 1.00 0.056 0.079 0.33 256 256 256 0.0100 0.0000 2 0.03 0.005 0.000 0.33 256 256 256 0.0100 0.0001 2 1.00 0.076 0.097 0.33 256 256 256 0.0010 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0001 3 0.00 0.007 0.098 0.33 256 256 256 0.0001 0.0001 2 1.00 0.077 0.098 0.33 256 256 256 0.0001 0.0001 2 1.00 0.077 0.098 0.33 256 256 256 0.0001 0.0001 2 0.00 0.001 0.001 0.33 256 256 256 0.0001 0.0001 2 0.00 0.001 0.001 0.35 1 1 1 1 0.0000 0.0001 2 0.00 0.001 0.001 0.35 1 1 1 1 0.0000 0.0001 2 0.00 0.001 0.001 0.35 1 1 1 1 0.0000 0.0001 2 0.00										
0.33 256 256 256 1.0000 1.0000 2 0.000 0.001 0.001										
0.33 256 256 256 1.0000 1.0000 2 0.00 0.001 0.016										
0.33 256 256 256 1.0000 0.0000 3 0.17 0.022 0.257										
0.33 256 256 256 1.0000 0.0100 2 0.00 0.001 0.001										
0.33 256 256 256 1.0000 0.0001 3 0.83 0.035 1.535 0.33 256 256 256 1.0000 0.0001 3 1.00 0.0055 0.080 0.33 256 256 256 256 0.0100 1.0000 2 0.00 0.001 0.021 0.33 256 256 256 256 0.0100 1.0000 2 0.00 0.001 0.021 0.33 256 256 256 256 0.0100 0.0100 2 0.83 0.001 0.076 0.33 256 256 256 0.0100 0.0100 2 1.00 0.076 0.079 0.33 256 256 256 0.0100 0.0001 2 1.00 0.076 0.079 0.33 256 256 256 0.0100 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0010 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 0.0000 2 0.33 0.001 0.092 0.33 256 256 256 0.0001 0.0000 2 0.33 0.001 0.092 0.33 256 256 256 0.0001 0.0000 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0001 2 1.00 0.078 0.126 0.33 256 256 256 0.0001 0.0001 2 1.00 0.076 0.126 0.35 256 256 256 0.0001 0.0001 2 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 4 0.0000 0.0000 2 0.00 0.001 0.001 0.5										
0.33 256 256 256 1.0000 0.0001 2 0.067 0.001 0.078										
0.33 256 256 256 256 0.1000 0.0001 3 1.00 0.0055 0.080										
0.33 256 256 256 0.0100 1.0000 2 0.00 0.001 0.021										
0.33 256 256 256 0.0100 0.00100 3 0.17 0.037 0.425 0.33 256 256 256 256 0.0100 0.0100 3 1.00 0.056 0.079 0.33 256 256 256 256 0.0100 0.0001 3 1.00 0.070 0.097 0.33 256 256 256 256 0.0100 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 256 0.0001 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 256 0.0001 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 0.0001 0.0000 2 0.33 0.001 0.092 0.33 256 256 256 0.0001 0.0000 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0010 3 1.00 0.072 0.100 0.33 256 256 256 0.0001 0.0001 3 1.00 0.077 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.078 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.0000 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.001 0.50 1 1 1 0.0100 0.0001 3 0.33 0.009 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 3 0.33 0.009 0.001 0.50 1 1 1 0.0100 0.0000 3 0.50 0.000 0.001 0.50 1 1 1 0.0100 0.0000 3 0.50 0.000 0.001 0.50 1 1 1 0.0100 0.0000 3 0.50 0.000 0.001 0.50 1 1 1 0.0100 0.0000 3 0.50 0.001 0.50 1 1 1 0.0100 0.0000 3 0.50 0.001 0.50 1 1 1 0.0000 0.000 3 0.00 0.001 0.50 1 1 4 0.0000 0.0000 3										
0.33 256 256 256 256 0.0100 0.0100 2 0.83 0.001 0.076 0.079 0.33 256 256 256 0.0100 0.0001 2 1.00 0.076 0.097 0.33 256 256 256 0.0100 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 0.0001 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 0.0001 1.0000 3 0.50 0.080 1.064 0.033 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0001 2 1.00 0.078 0.126 0.33 256 256 256 0.0001 0.0001 2 1.00 0.076 0.126 0.33 256 256 256 0.0001 0.0001 2 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.1000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.0100 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0000 0.0001 0.0001 0.001 0.001 0.50 1 1 4 0.0000 0.0001 0.										
0.33 256 256 256 0.0100 0.0100 3 1.00 0.056 0.079 0.33 256 256 256 0.0100 0.0001 3 1.00 0.070 0.097 0.33 256 256 256 256 0.0001 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 256 0.0001 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 256 0.0001 0.0000 2 0.00 0.072 0.100 0.33 256 256 256 256 0.0001 0.0100 3 1.00 0.072 0.100 0.33 256 256 256 256 0.0001 0.0100 3 1.00 0.072 0.100 0.33 256 256 256 0.0001 0.0001 2 1.00 0.078 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0010 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0010 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0010 3 0.33 0.009 0.012 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 4 0.0000 0.0000 2 0.00 0.001 0.001 0.50 1 1 4 0.0000 0.0000 2 0.00 0.001 0.001 0.50 1 1 4 0.0000 0.0000 2										
0.33 256 256 256 256 0.0100 0.0001 2 1.00 0.076 0.097 0.33 256 256 256 256 0.0100 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 256 0.0001 1.0000 3 0.50 0.080 1.064 0.033 256 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0001 3 1.00 0.072 0.100 0.33 256 256 256 0.0001 0.0001 2 1.00 0.078 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 1.0000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.1000 2 0.00 0.001 0.001 0.50 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.895 0.50 1 1 1 0.0100 0.0001 3 0.33 0.009 0.895 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0000 0.0001 0.0000 0.000 0.001 0.001 0.50 1 1 1 0.0000 0.0000 2 0.00 0.001 0.001 0.50 1 1 4 0.0000 0.0000 0.0000 0.001 0.001 0.50 1 1 4 0.0000 0.0000 0.0000										
0.33 256 256 256 256 0.0100 0.0001 3 1.00 0.076 0.097 0.33 256 256 256 256 0.0001 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 256 0.0001 0.0100 3 1.00 0.077 0.100 0.33 256 256 256 0.0001 0.0001 2 1.00 0.078 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.0000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.0100 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 3 0.33 0.009 0.895 0.50 1 1 1 0.0100 0.0000 3 0.50 0.006 0.009 0.50 1 1 1 0.0100 0.0000 3 0.50 0.006 0.009 0.50 1 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 3 0.57 0.006 0.009 0.50 1 1 1 0.0100 0.0000 3 0.57 0.007 0.001 0.50 1 1 1 0.0000 0.0001 3 0.50 0.000 0.001 0.50 1 1 1 0.0000 0.0001 3 0.57 0.007 0.014 0.50 1 1 1 0.0000 0.0001 3 0.57 0.007 0.014 0.50 1 1 1 0.0000 0.0000 3 0.57 0.007 0.014 0.50 1 1 4 0.0000 0.0000 3 0.000 0.001 0.50 1 1 4 0.0000 0.0000 2 0.00 0.001 0.001 0.50 1 1 4 0.0000 0.0000 3 0.00 0.001 0										
0.33 256 256 256 0.0001 1.0000 2 0.33 0.001 0.092 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0001 2 1.00 0.073 0.098 0.33 256 256 256 0.0001 0.0001 3 1.00 0.078 0.126 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.1000 3 0.33 0.007 0.012 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 1.00100 0.0001 3 0.33 0.009 0.895 0.50 1 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0000 3 0.50 0.006 0.009 0.50 1 1 1 0.0100 0.0000 3 0.50 0.006 0.009 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 2 0.50 0.001 0.001 0.001 0.50 1 1										
0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 256 0.0001 0.0001 3 1.00 0.072 0.100 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.089 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.895 0.50 1 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 2	0.33				0.0001	1.0000			0.001	0.092
0.33 256 256 256 0.0001 0.0100 2 1.00 0.073 0.098 0.33 256 256 256 256 0.0001 0.0001 3 1.00 0.072 0.100 0.33 256 256 256 0.0001 0.0001 3 1.00 0.076 0.126 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 1.0000 0.0100 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.012 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.089 0.50 1 1 1 1.0000 0.0001 3 0.33 0.009 0.895 0.50 1 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.50 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 0.0001 0.0001 2										
0.33 256 256 256 0.0001 0.0001 2 1.00 0.078 0.126	0.33	256	256	256	0.0001	0.0100	2	1.00	0.073	0.098
0.33	0.33	256	256	256	0.0001	0.0100	3	1.00	0.072	0.100
0.50	0.33	256	256	256	0.0001	0.0001	2	1.00	0.078	0.126
0.50	0.33	256	256	256	0.0001	0.0001	3	1.00	0.076	0.126
0.50	0.50	1	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	0.50	1	1	1	1.0000	1.0000	3	0.33	0.007	0.012
0.50	0.50	1	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50			1	1	1.0000	0.0100			0.009	0.012
0.50		1	1	1		0.0001	2		0.001	0.001
0.50			1	1						
0.50 1 1 1 0.0100 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 0.0100 0.0100 3 0.50 0.010 0.012 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0101 0.0001 3 0.17 0.011 0.042 0.50 1 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 1.0000 3 0.67 0.007 0.014 0.50 1 1 1 0.0001 0.0100 3 0.067 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 1.0000 1.0000 3 0.33										
0.50 1 1 1 0.0100 0.0100 3 0.50 0.010 0.012 0.50 1 1 1 0.0100 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.17 0.011 0.042 0.50 1 1 1 0.0001 1.0000 2 0.00 0.001 0.014 0.50 1 1 1 0.0001 1.0000 3 0.67 0.007 0.014 0.50 1 1 1 0.0001 0.0100 3 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.33 0.009 0.001 0.50 1 1 4 1.0000 1.0000 3 0.30										
0.50										
0.50 1 1 1 0.0100 0.0001 3 0.17 0.011 0.042 0.50 1 1 1 0.0001 1.0000 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 1.0000 3 0.67 0.007 0.014 0.50 1 1 1 0.0001 0.0100 2 0.00 0.001 0.016 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.33 0.009 0.017 0.50 1 1 4 1.0000 1.0000 3 0.00 0.001 0.002 0.50 1 1 4 1.0000 0.0100 3 0.50										
0.50										
0.50 1 1 1 0.0001 1.0000 3 0.67 0.007 0.014 0.50 1 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0100 3 0.00 0.011 0.016 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.017 0.50 1 1 1 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.50 1 1 4 1.0000 1.0000 3 0.00 0.016 0.022 0.50 1 1 4 1.0000 0.0100 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 3 0.50										
0.50 1 1 1 0.0001 0.0100 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0100 3 0.00 0.011 0.016 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.002 0.50 1 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.002 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0001 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 3 1.00										
0.50 1 1 1 0.0001 0.0100 3 0.00 0.011 0.016 0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.00 0.001 0.001 0.50 1 1 4 1.0000 1.0000 3 0.00 0.001 0.002 0.50 1 1 4 1.0000 1.0000 3 0.00 0.016 0.022 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0100 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 2 0.50 0.001 0.004 0.50 1 1 4 1.0000 0.0001 3 1.00										
0.50 1 1 1 0.0001 0.0001 2 0.00 0.001 0.001 0.50 1 1 1 0.0001 0.0001 3 0.33 0.009 0.017 0.50 1 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0100 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 2 0.50 0.001 0.004 0.50 1 1 4 1.0000 0.0001 3 1.00 0.003 0.010 0.50 1 1 4 0.0100 1.0000 3 0.00										
0.50 1 1 1 0.0001 0.0001 3 0.33 0.009 0.017 0.50 1 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.50 1 1 4 1.0000 1.0000 3 0.00 0.016 0.022 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0100 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 2 0.50 0.001 0.004 0.50 1 1 4 1.0000 0.0001 3 1.00 0.003 0.010 0.50 1 1 4 0.0100 1.0000 3 0.00 0.001 0.001 0.50 1 1 4 0.0100 0.0100 3 0.83										
0.50 1 1 4 1.0000 1.0000 2 0.00 0.001 0.002 0.50 1 1 4 1.0000 1.0000 3 0.00 0.016 0.022 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0010 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 2 0.50 0.001 0.004 0.50 1 1 4 1.0000 0.0001 3 1.00 0.003 0.010 0.50 1 1 4 1.0000 0.0001 3 1.00 0.003 0.010 0.50 1 1 4 0.0100 1.0000 3 0.00 0.001 0.001 0.50 1 1 4 0.0100 0.0100 3 0.83										
0.50 1 1 4 1.0000 1.0000 3 0.00 0.016 0.022 0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0100 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 2 0.50 0.001 0.001 0.50 1 1 4 1.0000 0.0001 3 1.00 0.003 0.010 0.50 1 1 4 1.0000 0.0001 3 1.00 0.003 0.010 0.50 1 1 4 0.0100 1.0000 3 0.00 0.001 0.001 0.50 1 1 4 0.0100 0.0100 2 0.50 0.001 0.004 0.50 1 1 4 0.0100 0.0001 3 0.83										
0.50 1 1 4 1.0000 0.0100 2 0.17 0.001 0.003 0.50 1 1 4 1.0000 0.0100 3 0.50 0.003 0.018 0.50 1 1 4 1.0000 0.0001 2 0.50 0.001 0.004 0.50 1 1 4 1.0000 0.0001 3 1.00 0.003 0.010 0.50 1 1 4 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 1 4 0.0100 1.0000 3 0.00 0.001 0.001 0.50 1 1 4 0.0100 0.0000 3 0.00 0.001 0.002 0.50 1 1 4 0.0100 0.0100 3 0.83 0.003 0.012 0.50 1 1 4 0.0100 0.0001 3 1.00										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.00						-			
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$				4						0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		1	1	4		0.0100				0.005
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			1	4						
0.50 1 1 16 1.0000 0.0100 2 0.83 0.003 0.005 0.50 1 1 16 1.0000 0.0100 3 1.00 0.004 0.010 0.50 1 1 16 1.0000 0.0001 2 1.00 0.004 0.005 0.50 1 1 16 1.0000 0.0001 3 1.00 0.004 0.005 0.50 1 1 16 0.0100 1.0000 2 0.00 0.003 0.003 0.50 1 1 16 0.0100 1.0000 2 0.00 0.003 0.003	0.50	1	1	16	1.0000		2	0.00	0.002	
0.50 1 1 16 1.0000 0.0100 3 1.00 0.004 0.010 0.50 1 1 16 1.0000 0.0001 2 1.00 0.004 0.005 0.50 1 1 16 1.0000 0.0001 3 1.00 0.004 0.005 0.50 1 1 16 0.0100 1.0000 2 0.00 0.003 0.003										
0.50 1 1 16 1.0000 0.0001 2 1.00 0.004 0.005 0.50 1 1 16 1.0000 0.0001 3 1.00 0.004 0.005 0.50 1 1 16 0.0100 1.0000 2 0.00 0.003 0.003										
0.50 1 1 16 1.0000 0.0001 3 1.00 0.004 0.005 0.50 1 1 16 0.0100 1.0000 2 0.00 0.003 0.003										
0.50 1 1 16 0.0100 1.0000 2 0.00 0.003 0.003										
0.50 1 1 16 0.0100 1.0000 3 0.00 0.028 0.038										
	0.50	1	1	16	0.0100	1.0000	3	0.00	0.028	0.038

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	1	1	16	0.0100	0.0100	2	1.00	0.004	0.006
0.50	1	1	16	0.0100	0.0100	3	1.00	0.004	0.005
0.50	1	1	16	0.0100	0.0001	2	1.00	0.004	0.006
0.50	1	1	16	0.0100	0.0001	3	1.00	0.005	0.007
0.50	1	1	16	0.0001	1.0000	2	0.00	0.003	0.004
0.50	1	1	16	0.0001	1.0000	3	0.00	0.042	0.758
0.50	1	1	16	0.0001	0.0100	2	1.00	0.004	0.006
0.50	1	1	16	0.0001	0.0100	3	1.00	0.004	0.007
0.50	1	1	16	0.0001	0.0001	2	1.00	0.006	0.007
0.50	1	1	16 64	0.0001	0.0001	2	1.00 0.00	0.006	0.007
0.50	1	1	64	1.0000	1.0000	3	0.00	0.004	0.005
0.50	1	1	64	1.0000	0.0100	2	0.67	0.004	0.003
0.50	1	1	64	1.0000	0.0100	3	0.83	0.008	0.066
0.50	1	1	64	1.0000	0.0001	2	1.00	0.009	0.014
0.50	1	1	64	1.0000	0.0001	3	1.00	0.009	0.014
0.50	1	1	64	0.0100	1.0000	2	0.00	0.004	0.006
0.50	1	1	64	0.0100	1.0000	3	0.00	0.063	0.066
0.50	1	1	64	0.0100	0.0100	2	1.00	0.010	0.010
0.50	1	1	64	0.0100	0.0100	3	1.00	0.010	0.010
0.50	1	1	64	0.0100	0.0001	2	1.00	0.012	0.013
0.50	1	1	64 64	0.0100	1.0000	3	1.00	0.012	0.013
0.50	1	1	64	0.0001	1.0000	3	0.00	0.007	0.079
0.50	1	1	64	0.0001	0.0100	2	1.00	0.093	0.130
0.50	1	1	64	0.0001	0.0100	3	1.00	0.017	0.018
0.50	1	1	64	0.0001	0.0001	2	1.00	0.012	0.023
0.50	1	1	64	0.0001	0.0001	3	1.00	0.015	0.023
0.50	1	1	256	1.0000	1.0000	2	0.00	0.012	0.017
0.50	1	1	256	1.0000	1.0000	3	0.00	0.181	1.424
0.50	1	1	256	1.0000	0.0100	2	0.00	0.017	0.028
0.50	1	1	256	1.0000	0.0100	3	0.00	0.280	0.460
0.50	1	1	256	1.0000	0.0001	2	1.00	0.046	0.049
0.50	1	1	256	1.0000	0.0001	3	1.00	0.046	0.067
0.50	1	1	256 256	0.0100	1.0000	3	0.00	0.018	0.029
0.50	1	1	256	0.0100	1.0000 0.0100	2	0.00	0.296	0.404
0.50	1	1	256	0.0100	0.0100	3	0.00	0.023	0.933
0.50	1	1	256	0.0100	0.0001	2	1.00	0.427	0.102
0.50	1	1	256	0.0100	0.0001	3	1.00	0.066	0.103
0.50	1	1	256	0.0001	1.0000	2	0.00	0.026	0.075
0.50	1	1	256	0.0001	1.0000	3	0.00	0.458	3.724
0.50	1	1	256	0.0001	0.0100	2	0.17	0.033	0.069
0.50	1	1	256	0.0001	0.0100	3	0.17	0.083	0.697
0.50	1	1	256	0.0001	0.0001	2	1.00	0.082	0.112
0.50	1	1	256	0.0001	0.0001	3	1.00	0.081	0.132
0.50	1	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	1	4	1	1.0000	1.0000	3	0.67	0.011	0.194
0.50	1	4	1	1.0000	0.0100	3	0.00	0.001	0.001
0.50	1	4	1	1.0000	0.0100	2	0.17	0.003	0.017
0.50	1	4	1	1.0000	0.0001	3	0.00	0.001	0.001
0.50	1	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	1	4	1	0.0100	1.0000	3	0.33	0.003	0.012
0.50	1	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	1	4	1	0.0100	0.0100	3	0.17	0.003	0.011
0.50	1	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	1	4	1	0.0100	0.0001	3	0.33	0.004	0.013
0.50	1	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	1	4	1	0.0001	1.0000	3	0.17	0.009	0.014
0.50	1	4	1	0.0001	0.0100	3	0.00	0.001	0.001
0.50	1	4	1	0.0001	0.0100	2	0.17	0.003	0.011
0.50	1	4	1	0.0001	0.0001	3	0.00	0.001	0.001
0.50	1	4	4	1.0000	1.0000	2	0.00	0.003	0.040
0.50	1	4	4	1.0000	1.0000	3	0.00	0.009	0.016
0.50	1	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	1	4	4	1.0000	0.0100	3	0.50	0.004	0.019
0.50	1	4	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	1	4	4	1.0000	0.0001	3	0.83	0.004	0.017
0.50	1	4	4	0.0100	1.0000	2	0.00	0.001	0.001
0.50	1	4	4	0.0100	1.0000	3	0.17	0.009	0.021
0.50	1	4	4	0.0100	0.0100	2	0.33	0.001	0.004
0.50	1	4	4	0.0100	0.0100	3	1.00	0.003	0.010
0.50	1	4	4	0.0100	0.0001	2	0.67	0.001	0.004
1 11 70 1	1	4	4	0.0100	0.0001	3	0.83	0.003	0.012

mul	m_1	m_2	τ	TR	DTR	alg	SR	mint	maxt
0.50	1	4	4	0.0001	1.0000	2	0.00	0.001	0.001
0.50	1	4	4	0.0001	1.0000	3	0.00	0.011	0.033
0.50	1	4	4	0.0001	0.0100	2	0.83	0.001	0.004
0.50	1	4	4	0.0001	0.0100	3	0.83	0.004	0.013
0.50	1	4	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	1	4	16	1.0000	0.0001 1.0000	3	1.00 0.00	0.004	0.016
0.50	1	4	16	1.0000	1.0000	3	0.00	0.001	0.026
0.50	1	4	16	1.0000	0.0100	2	0.50	0.001	0.005
0.50	1	4	16	1.0000	0.0100	3	0.83	0.005	0.025
0.50	1	4	16	1.0000	0.0001	2	1.00	0.005	0.006
0.50	1	4	16	1.0000	0.0001	3	1.00	0.005	0.006
0.50	1	4	16 16	0.0100	1.0000	3	0.00	0.001	0.003
0.50	1	4	16	0.0100	0.0100	2	1.00	0.027	0.029
0.50	1	4	16	0.0100	0.0100	3	1.00	0.004	0.005
0.50	1	4	16	0.0100	0.0001	2	1.00	0.004	0.005
0.50	1	4	16	0.0100	0.0001	3	1.00	0.004	0.005
0.50	1	4	16	0.0001	1.0000	2	0.00	0.003	0.004
0.50	1	4	16 16	0.0001	1.0000 0.0100	3	1.00	0.033	0.043
0.50	1	4	16	0.0001	0.0100	3	1.00	0.004	0.006
0.50	1	4	16	0.0001	0.0001	2	1.00	0.004	0.000
0.50	1	4	16	0.0001	0.0001	3	1.00	0.005	0.013
0.50	1	4	64	1.0000	1.0000	2	0.00	0.003	0.005
0.50	1	4	64	1.0000	1.0000	3	0.00	0.048	0.068
0.50	1	4	64	1.0000	0.0100	2	0.67	0.001	0.011
0.50	1	4	64 64	1.0000	0.0100	3 2	0.67 1.00	0.008	0.089
0.50	1	4	64	1.0000	0.0001	3	1.00	0.010	0.014
0.50	1	4	64	0.0100	1.0000	2	0.00	0.005	0.010
0.50	1	4	64	0.0100	1.0000	3	0.00	0.071	0.110
0.50	1	4	64	0.0100	0.0100	2	1.00	0.009	0.012
0.50	1	4	64	0.0100	0.0100	3	1.00	0.010	0.012
0.50	1	4	64 64	0.0100	0.0001	3	1.00	0.011	0.018
0.50	1	4	64	0.0100	1.0000	2	0.00	0.012	0.008
0.50	1	4	64	0.0001	1.0000	3	0.00	0.099	0.234
0.50	1	4	64	0.0001	0.0100	2	1.00	0.011	0.013
0.50	1	4	64	0.0001	0.0100	3	1.00	0.011	0.015
0.50	1	4	64	0.0001	0.0001	2	1.00	0.013	0.015
0.50	1	4	256	0.0001 1.0000	0.0001 1.0000	3	0.00	0.014	0.016
0.50	1	4	256	1.0000	1.0000	3	0.00	0.011	0.017
0.50	1	4	256	1.0000	0.0100	2	0.00	0.016	0.019
0.50	1	4	256	1.0000	0.0100	3	0.00	0.295	0.300
0.50	1	4	256	1.0000	0.0001	2	1.00	0.044	0.075
0.50	1	4	256	1.0000	0.0001	3	1.00	0.045	0.073
0.50	1	4	256 256	0.0100	1.0000	3	0.00	0.017	0.028
0.50	1	4	256	0.0100	0.0100	2	0.00	0.303	0.449
0.50	1	4	256	0.0100	0.0100	3	0.83	0.047	0.406
0.50	1	4	256	0.0100	0.0001	2	1.00	0.061	0.068
0.50	1	4	256	0.0100	0.0001	3	1.00	0.060	0.087
0.50	1	4	256	0.0001	1.0000	2	0.00	0.025	0.029
0.50	1	4	256 256	0.0001	1.0000 0.0100	3	0.00	0.419 0.068	0.645 2.447
0.50	1	4	256	0.0001	0.0100	3	0.83	0.068	1.345
0.50	1	4	256	0.0001	0.0001	2	1.00	0.083	0.125
0.50	1	4	256	0.0001	0.0001	3	1.00	0.081	0.126
0.50	1	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	1	16	1	1.0000	1.0000	3	0.33	0.003	0.011
0.50	1	16 16	1	1.0000	0.0100	3	0.00	0.001	0.001
0.50	1	16	1	1.0000	0.0100	2	0.33	0.003	0.001
0.50	1	16	1	1.0000	0.0001	3	0.17	0.003	0.001
0.50	1	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	1	16	1	0.0100	1.0000	3	0.17	0.003	0.012
0.50	1	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	1	16	1	0.0100	0.0100	3	0.33	0.003	0.012
0.50	1	16 16	1	0.0100	0.0001	3	0.00	0.001	0.001
0.50	1	16	1	0.0100	1.0000	2	0.00	0.009	0.012
	- 1				1.0000	3	0.00	0.010	0.011
0.50	1	16	1	0.0001	1.0000		0.00		0.011
0.50 0.50 0.50	1 1 1	16 16 16	1 1	0.0001	0.0100	2 3	0.00	0.001	0.001

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	1	16	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	1	16	1	0.0001	0.0001	3	0.33	0.003	0.011
0.50	1	16 16	4	1.0000	1.0000	3	0.00	0.001	0.001
0.50	1	16	4	1.0000	0.0100	2	0.00	0.009	0.001
0.50	1	16	4	1.0000	0.0100	3	0.17	0.004	0.016
0.50	1	16	4	1.0000	0.0001	2	0.17	0.001	0.003
0.50	1	16	4	1.0000	0.0001	3	0.50	0.003	0.012
0.50	1	16	4	0.0100	1.0000	2	0.17	0.001	0.003
0.50	1	16 16	4	0.0100	1.0000 0.0100	3	0.17	0.004	0.015
0.50	1	16	4	0.0100	0.0100	3	0.83	0.001	0.004
0.50	1	16	4	0.0100	0.0001	2	0.33	0.001	0.003
0.50	1	16	4	0.0100	0.0001	3	0.50	0.003	0.035
0.50	1	16	4	0.0001	1.0000	2	0.00	0.001	0.001
0.50	1	16	4	0.0001	1.0000	3	0.00	0.010	0.015
0.50	1	16 16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.50	1	16	4	0.0001	0.0100	2	0.83	0.003	0.004
0.50	1	16	4	0.0001	0.0001	3	0.83	0.001	0.003
0.50	1	16	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	1	16	16	1.0000	1.0000	3	0.00	0.012	1.728
0.50	1	16	16	1.0000	0.0100	2	0.33	0.001	0.005
0.50	1	16	16	1.0000	0.0100	3	0.67	0.004	0.021
0.50	1	16 16	16 16	1.0000	0.0001	2	0.33 1.00	0.001	0.004
0.50	1	16	16	0.0100	1.00001	2	0.00	0.004	0.004
0.50	1	16	16	0.0100	1.0000	3	0.00	0.001	0.001
0.50	1	16	16	0.0100	0.0100	2	1.00	0.004	0.006
0.50	1	16	16	0.0100	0.0100	3	1.00	0.004	0.006
0.50	1	16	16	0.0100	0.0001	2	1.00	0.004	0.006
0.50	1	16	16	0.0100	0.0001	3	1.00	0.004	0.006
0.50	1	16 16	16 16	0.0001	1.0000	2	0.00	0.001	0.001
0.50	1	16	16	0.0001	0.0100	2	1.00	0.006	0.006
0.50	1	16	16	0.0001	0.0100	3	1.00	0.005	0.006
0.50	1	16	16	0.0001	0.0001	2	1.00	0.005	0.006
0.50	1	16	16	0.0001	0.0001	3	1.00	0.005	0.007
0.50	1	16	64	1.0000	1.0000	2	0.00	0.003	0.005
0.50	1	16	64	1.0000	1.0000	3	0.00	0.048	0.065
0.50	1	16 16	64 64	1.0000	0.0100	3	0.50	0.001	0.012
0.50	1	16	64	1.0000	0.0001	2	1.00	0.008	0.002
0.50	1	16	64	1.0000	0.0001	3	1.00	0.009	0.014
0.50	1	16	64	0.0100	1.0000	2	0.00	0.005	0.005
0.50	1	16	64	0.0100	1.0000	3	0.00	0.062	0.080
0.50	1	16	64	0.0100	0.0100	2	1.00	0.014	0.016
0.50	1	16	64	0.0100	0.0100	3	1.00	0.010	0.016
0.50	1	16 16	64	0.0100	0.0001	2	1.00	0.011	0.018
0.50	1	16	64	0.0100	1.0000	2	0.00	0.011	0.010
0.50	1	16	64	0.0001	1.0000	3	0.00	0.088	0.129
0.50	1	16	64	0.0001	0.0100	2	1.00	0.011	0.014
0.50	1	16	64	0.0001	0.0100	3	1.00	0.011	0.014
0.50	1	16	64	0.0001	0.0001	2	1.00	0.013	0.015
0.50	1	16 16	64 256	0.0001 1.0000	0.0001 1.0000	3 2	1.00 0.00	0.013	0.015
0.50	1	16	256	1.0000	1.0000	3	0.00	0.011	0.017
0.50	1	16	256	1.0000	0.0100	2	0.00	0.001	0.016
0.50	1	16	256	1.0000	0.0100	3	0.00	0.245	1.418
0.50	1	16	256	1.0000	0.0001	2	1.00	0.049	0.073
0.50	1	16	256	1.0000	0.0001	3	1.00	0.051	0.073
0.50	1	16	256	0.0100	1.0000	2	0.00	0.016	0.026
0.50	1	16	256 256	0.0100	1.0000 0.0100	3	0.00 1.00	0.275	0.436
0.50	1	16		0.0100		3	1.00		
0.50	1 1	16 16		0.0100	0.01001	.)	1.00	0.049	ו אכט,ט ו
0.50	1 1 1	16 16 16	256 256	0.0100 0.0100	0.0100	2	1.00	0.049 0.061	0.058
	1	16	256	0.0100 0.0100	0.0001 0.0001			0.061 0.062	0.065 0.067
0.50	1 1 1	16 16 16 16	256 256 256 256	0.0100 0.0100 0.0001	0.0001 0.0001 1.0000	2 3 2	1.00 1.00 0.00	0.061 0.062 0.025	0.065 0.067 0.037
0.50	1 1 1 1 1	16 16 16 16 16	256 256 256 256 256	0.0100 0.0100 0.0001 0.0001	0.0001 0.0001 1.0000 1.0000	2 3 2 3	1.00 1.00 0.00 0.00	0.061 0.062 0.025 0.420	0.065 0.067 0.037 0.440
0.50 0.50	1 1 1 1 1 1	16 16 16 16 16 16	256 256 256 256 256 256 256	0.0100 0.0100 0.0001 0.0001 0.0001	0.0001 0.0001 1.0000 1.0000 0.0100	2 3 2 3 2	1.00 1.00 0.00 0.00 1.00	0.061 0.062 0.025 0.420 0.059	0.065 0.067 0.037 0.440 0.097
0.50 0.50 0.50	1 1 1 1 1 1	16 16 16 16 16 16 16	256 256 256 256 256 256 256 256	0.0100 0.0100 0.0001 0.0001 0.0001 0.0001	0.0001 0.0001 1.0000 1.0000 0.0100 0.0100	2 3 2 3 2 3	1.00 1.00 0.00 0.00 1.00	0.061 0.062 0.025 0.420 0.059 0.063	0.065 0.067 0.037 0.440 0.097 0.097
0.50 0.50 0.50 0.50	1 1 1 1 1 1	16 16 16 16 16 16	256 256 256 256 256 256 256 256 256	0.0100 0.0100 0.0001 0.0001 0.0001 0.0001	0.0001 0.0001 1.0000 1.0000 0.0100	2 3 2 3 2 3 2	1.00 1.00 0.00 0.00 1.00	0.061 0.062 0.025 0.420 0.059 0.063 0.081	0.065 0.067 0.037 0.440 0.097 0.097 0.094
0.50 0.50 0.50	1 1 1 1 1 1 1	16 16 16 16 16 16 16 16	256 256 256 256 256 256 256 256	0.0100 0.0100 0.0001 0.0001 0.0001 0.0001	0.0001 0.0001 1.0000 1.0000 0.0100 0.0100 0.0001	2 3 2 3 2 3	1.00 1.00 0.00 0.00 1.00 1.00	0.061 0.062 0.025 0.420 0.059 0.063	0.065 0.067 0.037 0.440 0.097 0.097

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	1	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	1	64	1	1.0000	0.0100	3	0.00	0.009	0.010
0.50	1	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	1	64	1	1.0000 0.0100	0.0001 1.0000	3	0.50	0.003	0.010
0.50	1	64	1	0.0100	1.0000	3	0.00	0.001	0.001
0.50	1	64	1	0.0100	0.0100	2	0.00	0.003	0.001
0.50	1	64	1	0.0100	0.0100	3	0.17	0.003	0.011
0.50	1	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	1	64	1	0.0100	0.0001	3	0.50	0.003	0.010
0.50	1	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	1	64 64	1	0.0001	1.0000 0.0100	3	0.17	0.003	0.009
0.50	1	64	1	0.0001	0.0100	3	0.00	0.001	0.001
0.50	1	64	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	1	64	1	0.0001	0.0001	3	0.50	0.003	0.011
0.50	1	64	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	1	64	4	1.0000	1.0000	3	0.00	0.010	0.017
0.50	1	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	1	64	4	1.0000	0.0100	2	0.00	0.004	0.001
0.50	1	64	4	1.0000	0.0001	3	0.67	0.001	0.001
0.50	1	64	4	0.0100	1.0000	2	0.33	0.001	0.005
0.50	1	64	4	0.0100	1.0000	3	0.50	0.003	0.013
0.50	1	64	4	0.0100	0.0100	2	0.00	0.001	0.001
0.50	1	64	4	0.0100	0.0100	3	0.33	0.004	0.018
0.50	1	64	4	0.0100	0.0001	3	0.50 0.67	0.001	0.004 0.014
0.50	1	64	4	0.0100	1.0000	2	0.67	0.003	0.014
0.50	1	64	4	0.0001	1.0000	3	0.83	0.004	0.013
0.50	1	64	4	0.0001	0.0100	2	0.83	0.001	0.004
0.50	1	64	4	0.0001	0.0100	3	1.00	0.004	0.005
0.50	1	64	4	0.0001	0.0001	2	1.00	0.004	0.004
0.50	1	64	4	0.0001	0.0001	3	1.00	0.004	0.005
0.50	1	64	16 16	1.0000	1.0000	3	0.00	0.001	0.002
0.50	1	64	16	1.0000	0.0100	2	0.33	0.001	0.004
0.50	1	64	16	1.0000	0.0100	3	1.00	0.004	0.005
0.50	1	64	16	1.0000	0.0001	2	0.50	0.001	0.006
0.50	1	64	16	1.0000	0.0001	3	1.00	0.004	0.006
0.50	1	64	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	1	64	16 16	0.0100	1.0000 0.0100	3	0.00 1.00	0.021	4.823 0.005
0.50	1	64	16	0.0100	0.0100	3	1.00	0.004	0.005
0.50	1	64	16	0.0100	0.0001	2	1.00	0.004	0.005
0.50	1	64	16	0.0100	0.0001	3	1.00	0.004	0.006
0.50	1	64	16	0.0001	1.0000	2	0.33	0.001	0.004
0.50	1	64	16	0.0001	1.0000	3	0.33	0.004	0.027
0.50	1	64	16	0.0001	0.0100	2	1.00	0.004	0.005
0.50	1	64	16 16	0.0001	0.0100	3	1.00	0.004	0.005
0.50	1	64	16	0.0001	0.0001	3	1.00	0.005	0.006
0.50	1	64	64	1.0000	1.0000	2	0.00	0.001	0.003
0.50	1	64	64	1.0000	1.0000	3	0.00	0.028	0.045
0.50	1	64	64	1.0000	0.0100	2	0.33	0.001	0.008
0.50	1	64	64	1.0000	0.0100	3	0.50	0.008	0.048
0.50	1	64	64 64	1.0000 1.0000	0.0001 0.0001	3	0.83 1.00	0.001 0.010	0.011 0.012
0.50	1	64	64	0.0100	1.00001	2	0.00	0.010	0.012
0.50	1	64	64	0.0100	1.0000	3	0.00	0.048	0.082
0.50	1	64	64	0.0100	0.0100	2	1.00	0.011	0.015
0.50	1	64	64	0.0100	0.0100	3	1.00	0.010	0.015
0.50	1	64	64	0.0100	0.0001	2	1.00	0.013	0.016
0.50	1	64	64	0.0100	0.0001	3	1.00	0.011	0.017
0.50	1	64	64 64	0.0001	1.0000	2	0.00	0.001	0.008
0.50	1	64	64	0.0001	0.0100	2	1.00	0.078	0.113
0.50	1	64	64	0.0001	0.0100	3	1.00	0.011	0.013
0.50	1	64	64	0.0001	0.0001	2	1.00	0.014	0.015
0.50	1	64	64	0.0001	0.0001	3	1.00	0.014	0.015
0.50	1	64	256	1.0000	1.0000	2	0.00	0.001	0.017
0.50	1	64	256	1.0000	1.0000	3	0.00	0.178	0.280
0.50	1	64	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	1	64	256 256	1.0000	0.0100	3	0.00 1.00	0.195 0.046	1.609 0.072
0.50	1	64	256	1.0000	0.0001	3	1.00	0.046	0.072
0.50	1	OΤ	200	1.0000	5.0001		1.00	0.010	J.001

0.50	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50										
0.50										
0.50		1	64			0.0100				
0.50	0.50	1	64	256	0.0100	0.0100	3	1.00	0.053	0.078
0.50	0.50	1	64	256	0.0100	0.0001	2	1.00	0.065	0.097
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50	0.50	1	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	0.50	1	256	1	1.0000	0.0100		0.33	0.003	0.012
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50		1		1	0.0001		3	0.33	0.003	
0.50					0.0001	0.0001			0.001	
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50 1 256 4 0.0100 0.0001 2 0.67 0.001 0.004 0.50 1 256 4 0.0100 0.0001 3 0.67 0.003 0.020 0.50 1 256 4 0.0001 1.0000 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 0.0100 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 0.0100 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 0.0100 3 1.00 0.004 0.004 0.50 1 256 4 0.0001 0.0001 3 1.00 0.004 0.004 0.50 1 256 4 0.0001 0.0001 3 0.83 0.001 0.004 0.50 1 256 16 1.0000 1.0000 3				4						
0.50 1 256 4 0.0100 0.0001 3 0.67 0.003 0.020 0.50 1 256 4 0.0001 1.0000 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 0.0100 2 0.67 0.001 0.001 0.50 1 256 4 0.0001 0.0100 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 0.0100 3 1.00 0.004 0.004 0.50 1 256 4 0.0001 0.0001 3 0.00 0.004 0.50 1 256 4 0.0001 0.0001 3 0.83 0.001 0.004 0.50 1 256 16 1.0000 1.0000 3 0.17 0.005 0.018 0.50 1 256 16 1.0000 0.0100 2 0.33	0.50	1	256	4	0.0100	0.0100	3	1.00	0.004	0.004
0.50 1 256 4 0.0001 1.0000 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 1.0000 3 0.67 0.004 0.011 0.50 1 256 4 0.0001 0.0100 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 0.0100 3 1.00 0.004 0.004 0.50 1 256 4 0.0001 0.0001 2 0.83 0.001 0.004 0.50 1 256 4 0.0001 0.0001 3 0.83 0.003 0.014 0.50 1 256 16 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 1.0000 0.0100 3 0.83 0.004 0.016 0.50 1 256 16 1.0000 0.0001 2										
0.50 1 256 4 0.0001 1.0000 3 0.67 0.004 0.011 0.50 1 256 4 0.0001 0.0100 2 0.67 0.001 0.004 0.50 1 256 4 0.0001 0.0001 2 0.83 0.001 0.004 0.50 1 256 4 0.0001 0.0001 2 0.83 0.001 0.004 0.50 1 256 4 0.0001 0.0001 2 0.83 0.003 0.014 0.50 1 256 16 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 1.0000 0.0100 3 0.17 0.005 0.018 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.00 0.50 1 256 16 1.0000 0.0001 2										
0.50										
0.50 1 256 4 0.0001 0.0100 3 1.00 0.004 0.004 0.50 1 256 4 0.0001 0.0001 2 0.83 0.001 0.004 0.50 1 256 4 0.0001 0.0001 3 0.83 0.003 0.014 0.50 1 256 16 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0100 3 0.83 0.004 0.016 0.50 1 256 16 1.0000 0.0001 3 1.00 0.066 0.007 0.50 1 256 16 0.0100 1.0000 2										
0.50 1 256 4 0.0001 0.0001 2 0.83 0.001 0.004 0.50 1 256 4 0.0001 0.0001 3 0.83 0.003 0.014 0.50 1 256 16 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0100 3 0.83 0.004 0.016 0.50 1 256 16 1.0000 0.0001 2 0.33 0.001 0.065 0.50 1 256 16 1.0000 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 0.0100 1.0000 3										
0.50 1 256 4 0.0001 0.0001 3 0.83 0.003 0.014 0.50 1 256 16 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 1.0000 0.0100 3 0.17 0.005 0.018 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0001 2 0.33 0.001 0.065 0.50 1 256 16 1.0000 0.0001 2 0.33 0.001 0.065 0.50 1 256 16 1.0000 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 1.0000 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 0.0100 0.0100 2										
0.50 1 256 16 1.0000 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 1.0000 1.0000 3 0.17 0.005 0.018 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0100 3 0.83 0.004 0.016 0.50 1 256 16 1.0000 0.0001 2 0.33 0.004 0.065 0.50 1 256 16 1.0000 0.0001 2 0.33 0.001 0.065 0.50 1 256 16 1.0000 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 0.0100 1.0000 3 0.17 0.005 0.24 0.50 1 256 16 0.0100 0.0100 2										
0.50 1 256 16 1.0000 1.0000 3 0.17 0.005 0.018 0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0100 3 0.83 0.004 0.016 0.50 1 256 16 1.0000 0.0001 2 0.33 0.001 0.065 0.50 1 256 16 1.0000 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 0.0100 1.0000 3 0.17 0.005 0.024 0.50 1 256 16 0.0100 0.0100 3 1.00 0.001 0.00 0.50 1 256 16 0.0100 0.0001 2										
0.50 1 256 16 1.0000 0.0100 2 0.33 0.001 0.005 0.50 1 256 16 1.0000 0.0100 3 0.83 0.004 0.016 0.50 1 256 16 1.0000 0.0001 2 0.33 0.001 0.065 0.50 1 256 16 1.0000 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 0.0100 1.0000 3 0.17 0.005 0.024 0.50 1 256 16 0.0100 0.0100 2 0.83 0.001 0.006 0.50 1 256 16 0.0100 0.0001 2 0.83 0.001 0.006 0.50 1 256 16 0.0100 0.0001 3 <td></td>										
0.50 1 256 16 1.0000 0.0001 2 0.33 0.001 0.065 0.50 1 256 16 1.0000 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 0.0100 1.0000 2 0.00 0.001 0.001 0.50 1 256 16 0.0100 0.0100 2 0.83 0.001 0.006 0.50 1 256 16 0.0100 0.0100 2 0.83 0.001 0.006 0.50 1 256 16 0.0100 0.0100 3 1.00 0.006 0.006 0.50 1 256 16 0.0100 0.0001 2 0.83 0.001 0.006 0.50 1 256 16 0.0100 0.0001 3 1.00 0.006 0.007 0.50 1 256 16 0.0001 1.0000 3 <td>0.50</td> <td>1</td> <td>256</td> <td></td> <td></td> <td></td> <td>2</td> <td>0.33</td> <td>0.001</td> <td></td>	0.50	1	256				2	0.33	0.001	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.50		256		0.0001			1.00		0.007
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.50 1 256 64 1.0000 1.0000 3 0.00 0.024 0.038 0.50 1 256 64 1.0000 0.0100 2 0.17 0.001 0.014 0.50 1 256 64 1.0000 0.0100 3 0.17 0.008 1.260 0.50 1 256 64 1.0000 0.0001 2 0.33 0.001 0.012 0.50 1 256 64 1.0000 0.0001 3 1.00 0.011 0.012 0.50 1 256 64 0.0100 1.0000 2 0.00 0.001 0.006 0.50 1 256 64 0.0100 1.0000 3 0.00 0.040 0.091 0.50 1 256 64 0.0100 0.0100 2 1.00 0.011 0.016										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.50 1 256 64 1.0000 0.0100 3 0.17 0.008 1.260 0.50 1 256 64 1.0000 0.0001 2 0.33 0.001 0.012 0.50 1 256 64 1.0000 0.0001 3 1.00 0.011 0.017 0.50 1 256 64 0.0100 1.0000 2 0.00 0.001 0.006 0.50 1 256 64 0.0100 1.0000 3 0.00 0.040 0.091 0.50 1 256 64 0.0100 0.0100 2 1.00 0.011 0.016										
0.50 1 256 64 1.0000 0.0001 2 0.33 0.001 0.012 0.50 1 256 64 1.0000 0.0001 3 1.00 0.011 0.017 0.50 1 256 64 0.0100 1.0000 2 0.00 0.001 0.006 0.50 1 256 64 0.0100 1.0000 3 0.00 0.040 0.091 0.50 1 256 64 0.0100 0.0100 2 1.00 0.011 0.016										
0.50 1 256 64 1.0000 0.0001 3 1.00 0.011 0.017 0.50 1 256 64 0.0100 1.0000 2 0.00 0.001 0.006 0.50 1 256 64 0.0100 1.0000 3 0.00 0.040 0.091 0.50 1 256 64 0.0100 0.0100 2 1.00 0.011 0.016										
0.50 1 256 64 0.0100 1.0000 2 0.00 0.001 0.006 0.50 1 256 64 0.0100 1.0000 3 0.00 0.040 0.091 0.50 1 256 64 0.0100 0.0100 2 1.00 0.011 0.016										
0.50 1 256 64 0.0100 1.0000 3 0.00 0.040 0.091 0.50 1 256 64 0.0100 0.0100 2 1.00 0.011 0.016										
0.50 1 256 64 0.0100 0.0100 2 1.00 0.011 0.016										
0.50 1 256 64 0.0100 0.0100 3 1.00 0.010 0.016										

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
$\underline{}$									
0.50	1	256 256	64	0.0100	0.0001	3	1.00	0.017	0.019
0.50	1	256	64	0.0100	1.0000	2	0.50	0.017	0.070
0.50	1	256	64	0.0001	1.0000	3	0.50	0.001	0.013
0.50	1	256	64	0.0001	0.0100	2	1.00	0.011	0.013
0.50	1	256	64	0.0001	0.0100	3	1.00	0.011	0.013
0.50	1	256	64	0.0001	0.0001	2	1.00	0.014	0.015
0.50	1	256	64	0.0001	0.0001	3	1.00	0.013	0.014
0.50	1	256	256	1.0000	1.0000	2	0.00	0.001	0.015
0.50	1	256	256	1.0000	1.0000	3	0.00	0.124	0.182
0.50	1	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	1	256	256	1.0000	0.0100	3	0.00	0.142	4.471
0.50	1	256	256	1.0000	0.0001	2	0.33	0.001	0.077
0.50	1	256	256	1.0000	0.0001	3	1.00	0.054	0.079
0.50	1	256	256	0.0100	1.0000	2	0.00	0.001	0.026
0.50	1	256	256	0.0100	1.0000	3	0.00	0.243	0.421
0.50	1	256	256	0.0100	0.0100	2	0.83	0.001	0.076
0.50	1	256	256	0.0100	0.0100	3	1.00	0.062	0.075
0.50	1	256	256	0.0100	0.0001	2	1.00	0.063	0.115
0.50	1	256	256	0.0100	0.0001	3	1.00	0.063	0.098
0.50	1	256	256	0.0001	1.0000	2	0.00	0.001	0.041
0.50	1	256	256	0.0001	1.0000	3	0.00	0.409	0.651
0.50	1	256	256	0.0001	0.0100	2	1.00	0.061	0.093
0.50	1	256	256	0.0001	0.0100	3	1.00	0.065	0.095
0.50	1	256 256	256 256	0.0001	0.0001	2	1.00	0.091	0.128
0.50	4	236	236	1.0000	1.00001	3	0.00	0.086	0.127
0.50	4	1	1	1.0000	1.0000	3	0.00	0.001	0.001
0.50	4	1	1	1.0000	0.0100	2	0.00	0.004	0.001
0.50	4	1	1	1.0000	0.0100	3	0.00	0.011	0.016
0.50	4	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	4	1	1	1.0000	0.0001	3	0.17	0.010	0.042
0.50	4	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	4	1	1	0.0100	1.0000	3	0.17	0.007	0.012
0.50	4	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	4	1	1	0.0100	0.0100	3	0.00	0.009	0.011
0.50	4	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	4	1	1	0.0100	0.0001	3	0.17	0.009	0.010
0.50	4	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	4	1	1	0.0001	1.0000	3	0.17	0.007	0.022
0.50	4	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	4	1	1	0.0001	0.0100	3	0.17	0.009	0.012
0.50	4	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	4	1	1	0.0001	0.0001	3	0.33	0.008	0.011
0.50	4	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	4	1	4	1.0000	1.0000	3	0.00	0.011	0.016
0.50	4	1	4	1.0000	0.0100	2	0.17	0.001	0.003
0.50	4	1	4	1.0000	0.0100	3	0.50	0.003	0.015
0.50	4	1	4	1.0000	0.0001	2	0.33	0.001	0.003
0.50	4	1	4	0.0100	1.00001	3	0.67	0.003	0.016
0.50	4	1	4	0.0100	1.0000	3	0.00	0.001	0.001
0.50	4	1	4	0.0100	0.0100	2	0.83	0.012	0.020
0.50	4	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.50	4	1	4	0.0100	0.0001	2	0.50	0.001	0.003
0.50	4	1	4	0.0100	0.0001	3	0.67	0.003	0.027
0.50	4	1	4	0.0001	1.0000	2	0.17	0.001	0.003
0.50	4	1	4	0.0001	1.0000	3	0.17	0.003	0.016
0.50	4	1	4	0.0001	0.0100	2	0.83	0.001	0.003
0.50	4	1	4	0.0001	0.0100	3	0.83	0.003	0.011
0.50	4	1	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	4	1	4	0.0001	0.0001	3	1.00	0.003	0.008
0.50	4	1	16	1.0000	1.0000	2	0.00	0.001	0.002
0.50	4	1	16	1.0000	1.0000	3	0.00	0.022	0.113
0.50	4	1	16	1.0000	0.0100	2	0.50	0.001	0.004
0.50	4	1	16	1.0000	0.0100	3	0.83	0.004	0.021
0.50	4	1	16	1.0000	0.0001	2	1.00	0.004	0.006
0.50	4	1	16	1.0000	0.0001	3	1.00	0.004	0.006
0.50	4	1	16	0.0100	1.0000	2	0.00	0.002	0.003
0.50	4	1	16 16	0.0100	1.0000 0.0100	2	0.00 1.00	0.028	0.038
0.50	4	1	16	0.0100	0.0100	3	1.00	0.005	0.006
0.50	4	1	16	0.0100	0.0100	2	1.00	0.005	0.006
0.50	4	1	16	0.0100	0.0001	3	1.00	0.006	0.007
0.50	4	1	16	0.0001	1.0000	2	0.00	0.003	0.003
0.50	4	1	16	0.0001	1.0000	3	0.00	0.044	0.003
0.50			10	0.0001	1.0000		0.00	0.011	0.010

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	4	1	16	0.0001	0.0100	2	1.00	0.006	0.006
0.50	4	1	16	0.0001	0.0100	3	1.00	0.006	0.006
0.50	4	1	16	0.0001	0.0001	2	1.00	0.006	0.007
0.50	4	1	16	0.0001	0.0001	3	1.00	0.006	0.007
0.50	4	1	64	1.0000	1.0000	2	0.00	0.004	0.004
0.50	4	1	64 64	1.0000	1.0000	2	0.00	0.061	0.063
0.50	4	1	64	1.0000	0.0100	3	0.50	0.003	0.884
0.50	4	1	64	1.0000	0.0001	2	1.00	0.010	0.012
0.50	4	1	64	1.0000	0.0001	3	1.00	0.009	0.012
0.50	4	1	64	0.0100	1.0000	2	0.00	0.004	0.005
0.50	4	1	64	0.0100	1.0000	3	0.00	0.062	0.071
0.50	4	1	64	0.0100	0.0100	2	1.00	0.009	0.015
0.50	4	1	64	0.0100	0.0100	3	1.00	0.009	0.015
0.50	4	1	64	0.0100	0.0001	2	1.00	0.012	0.017
0.50	4	1	64	0.0100	1.0000	3	1.00	0.011	0.017
0.50	4	1	64	0.0001	1.0000	3	0.00	0.008	0.009
0.50	4	1	64	0.0001	0.0100	2	1.00	0.015	0.018
0.50	4	1	64	0.0001	0.0100	3	1.00	0.013	0.018
0.50	4	1	64	0.0001	0.0001	2	1.00	0.016	0.023
0.50	4	1	64	0.0001	0.0001	3	1.00	0.014	0.061
0.50	4	1	256	1.0000	1.0000	2	0.00	0.011	0.017
0.50	4	1	256	1.0000	1.0000	3	0.00	0.181	0.286
0.50	4	1	256	1.0000	0.0100	2	0.00	0.022	0.033
0.50	4	1	256	1.0000	0.0100	3	0.00	0.295	0.803
0.50	4	1	256 256	1.0000	0.0001	3	1.00	0.046 0.048	0.050
0.50	4	1	256	0.0100	1.0000	2	0.00	0.048	0.071
0.50	4	1	256	0.0100	1.0000	3	0.00	0.018	1.532
0.50	4	1	256	0.0100	0.0100	2	0.50	0.026	0.048
0.50	4	1	256	0.0100	0.0100	3	0.50	0.047	0.635
0.50	4	1	256	0.0100	0.0001	2	1.00	0.071	1.062
0.50	4	1	256	0.0100	0.0001	3	1.00	0.063	0.101
0.50	4	1	256	0.0001	1.0000	2	0.00	0.025	0.039
0.50	4	1	256	0.0001	1.0000	3	0.00	0.410	0.589
0.50	4	1	256	0.0001	0.0100	2	1.00	0.067	0.093
0.50	4	1	256 256	0.0001	0.0100	3	1.00	0.070	0.096 0.110
0.50	4	1	256	0.0001	0.0001	3	1.00	0.076	0.116
0.50	4	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	4	4	1	1.0000	1.0000	3	0.50	0.007	0.010
0.50	4	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	4	4	1	1.0000	0.0100	3	0.50	0.009	0.010
0.50	4	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	4	4	1	1.0000	0.0001	3	0.17	0.003	0.017
0.50	4	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	4	4	1	0.0100	0.0100	3	0.50	0.008	0.013
0.50	4	4	1	0.0100	0.0100	3	0.00	0.001	0.001
0.50	4	4	1	0.0100	0.0001	2	0.00	0.004	0.001
0.50	4	4	1	0.0100	0.0001	3	0.33	0.003	0.017
0.50	4	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	4	4	1	0.0001	1.0000	3	0.33	0.009	0.142
0.50	4	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	4	4	1	0.0001	0.0100	3	0.67	0.004	0.014
0.50	4	4	1	0.0001	0.0001	3	0.00	0.001	0.012
0.50	4	4	4	1.0000	1.00001	2	0.17	0.009	0.016
0.50	4	4	4	1.0000	1.0000	3	0.00	0.001	0.001
0.50	4	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	4	4	4	1.0000	0.0100	3	0.83	0.004	0.018
0.50	4	4	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	4	4	4	1.0000	0.0001	3	0.33	0.013	0.057
0.50	4	4	4	0.0100	1.0000	2	0.17	0.001	0.004
0.50	4	4	4	0.0100	1.0000	3	0.33	0.004	0.018
0.50	4	4	4	0.0100	0.0100	2	0.33	0.001	0.003
0.50	4	4	4	0.0100	0.0100	3	0.83	0.003	0.014
0.50	4	4	4	0.0100	0.0001	3	1.00	0.001	0.004
0.50	4	4	4	0.0100	1.0000	2	0.83	0.003	0.004
0.50				0.0001	1.0000	3	0.83	0.004	0.020
	4	4	4						
0.50		4	4	0.0001	0.0100	2	0.67	0.001	0.004
	4		4			2	0.67 1.00	0.001 0.004	0.004 0.007
0.50	4	4	4	0.0001	0.0100				

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.50	4	4	16	1.0000	1.0000	2	0.00	0.001	0.003
0.50	4	4	16	1.0000	1.0000	3	0.00	0.023	0.427
0.50	4	4	16	1.0000	0.0100	2	0.33	0.001	0.004
0.50	4	4	16	1.0000	0.0100	3	0.67	0.004	0.027
0.50	4	4	16	1.0000	0.0001	2	0.50	0.001	0.006
0.50	4	4	16	1.0000	0.0001	3	1.00	0.006	0.011
0.50	4	4	16 16	0.0100	1.0000	2	0.00	0.001	0.003
0.50	4	4	16	0.0100	0.0100	2	1.00	0.026	0.006
0.50	4	4	16	0.0100	0.0100	3	1.00	0.005	0.006
0.50	4	4	16	0.0100	0.0001	2	1.00	0.006	0.007
0.50	4	4	16	0.0100	0.0001	3	1.00	0.006	0.006
0.50	4	4	16	0.0001	1.0000	2	0.00	0.001	0.001
0.50	4	4	16	0.0001	1.0000	3	0.00	0.034	0.042
0.50	4	4	16	0.0001	0.0100	2	1.00	0.006	0.006
0.50	4	4	16 16	0.0001	0.0100	3	1.00	0.006	0.006
0.50	4	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.50	4	4	64	1.0000	1.0000	2	0.00	0.003	0.007
0.50	4	4	64	1.0000	1.0000	3	0.00	0.045	0.066
0.50	4	4	64	1.0000	0.0100	2	0.83	0.001	0.012
0.50	4	4	64	1.0000	0.0100	3	1.00	0.011	0.056
0.50	4	4	64	1.0000	0.0001	2	1.00	0.014	0.014
0.50	4	4	64	1.0000	0.0001	3	1.00	0.013	0.014
0.50	4	4	64	0.0100	1.0000	2	0.00	0.006	0.007
0.50	4	4	64	0.0100	1.0000 0.0100	3	0.00 1.00	0.088	0.092
0.50	4	4	64	0.0100	0.0100	3	1.00	0.010	0.013
0.50	4	4	64	0.0100	0.0001	2	1.00	0.011	0.014
0.50	4	4	64	0.0100	0.0001	3	1.00	0.011	0.012
0.50	4	4	64	0.0001	1.0000	2	0.00	0.006	0.009
0.50	4	4	64	0.0001	1.0000	3	0.00	0.087	0.127
0.50	4	4	64	0.0001	0.0100	2	1.00	0.017	0.018
0.50	4	4	64 64	0.0001	0.0100	3	1.00	0.016	0.018
0.50	4	4	64	0.0001	0.0001	3	1.00	0.014	0.053
0.50	4	4	256	1.0000	1.0000	2	0.00	0.021	0.031
0.50	4	4	256	1.0000	1.0000	3	0.00	0.183	0.282
0.50	4	4	256	1.0000	0.0100	2	0.00	0.020	0.026
0.50	4	4	256	1.0000	0.0100	3	0.00	0.407	0.880
0.50	4	4	256	1.0000	0.0001	2	1.00	0.045	0.062
0.50	4	4	256	1.0000	0.0001	3	1.00	0.045	0.059
0.50	4	4	256 256	0.0100	1.0000	3	0.00	0.018	0.027 0.455
0.50	4	4	256	0.0100	0.0100	2	1.00	0.331	0.433
0.50	4	4	256	0.0100	0.0100	3	1.00	0.048	0.076
0.50	4	4	256	0.0100	0.0001	2	1.00	0.060	0.097
0.50	4	4	256	0.0100	0.0001	3	1.00	0.060	0.098
0.50	4	4	256	0.0001	1.0000	2	0.00	0.026	0.041
0.50	4	4	256	0.0001	1.0000	3	0.00	0.416	0.655
0.50	4	4	256	0.0001	0.0100	3	1.00	0.086	0.100
0.50	4	4	256 256	0.0001	0.0100	2	1.00	0.080	0.102 1.119
0.50	4	4	256	0.0001	0.0001	3	1.00	0.116	0.129
0.50	4	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	4	16	1	1.0000	1.0000	3	0.33	0.003	0.011
0.50	4	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	4	16	1	1.0000	0.0100	3	0.00	0.009	0.016
0.50	4	16	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	4	16	1	1.0000 0.0100	0.0001	3	0.50	0.003	0.011
0.50	4	16 16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	4	16	1	0.0100	0.0100	2	0.17	0.003	0.001
0.50	4	16	1	0.0100	0.0100	3	0.17	0.001	0.016
0.50	4	16	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	4	16	1	0.0100	0.0001	3	0.00	0.009	0.012
0.50	4	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	4	16	1	0.0001	1.0000	3	0.17	0.003	0.016
0.50	4	16 16	1	0.0001	0.0100 0.0100	2	0.00	0.001	0.001 0.011
0.50		16	1	0.0001	0.0100	2	0.00	0.009	0.001
		10			0.0001	3	0.00	0.001	0.001
0.50	4	16	1	0.00011	0.00011				
0.50		16 16	1 4	0.0001 1.0000	1.0000	2	0.00	0.001	0.001
0.50	4 4 4	16 16	4	1.0000 1.0000	1.0000 1.0000	2	0.00 0.17	0.001 0.003	0.001 0.012
0.50	4	16	4	1.0000	1.0000	2	0.00	0.001	0.001

0.50	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50 4 16 4 0.0100 1.0000 2 0.17 0.001 0.013 0.50 4 16 4 0.0100 0.0100 2 0.50 0.001 0.003 0.50 4 16 4 0.0100 0.0100 3 1.00 0.003 0.003 0.50 4 16 4 0.0100 0.0001 2 0.00 0.001 0.003 0.001 0.50 4 16 4 0.0010 0.000 2 0.50 0.001 0.003 0.50 4 16 4 0.0001 1.0000 3 0.67 0.003 0.013 0.50 4 16 4 0.0001 0.0100 3 0.87 0.003 0.013 0.50 4 16 4 0.0001 0.0100 3 0.83 0.003 0.013 0.50 4 16 4 0.0001 0.0000 3										
0.50 4 16 4 0.0100 0.0100 3 0.17 0.003 0.013 0.50 4 16 4 0.0100 0.0100 3 1.00 0.003 0.003 0.50 4 16 4 0.0100 0.0001 3 1.00 0.003 0.002 0.50 4 16 4 0.0100 0.0001 1.00 0.003 0.012 0.50 4 16 4 0.0001 1.0000 2 0.50 0.001 0.003 0.50 4 16 4 0.0001 0.0100 2 0.50 0.001 0.001 0.50 4 16 4 0.0001 0.0010 2 0.50 0.001 0.003 0.50 4 16 16 0.0001 0.0001 2 0.50 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.00										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50	0.50	4	16	4	0.0001	1.0000	2	0.50	0.001	0.003
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50		4	16		1.0000					
0.50	0.50	4	16	16	1.0000	0.0100		0.67	0.004	0.027
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50	0.50	4				0.0001	3			
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50	0.50	4	16	64	1.0000	0.0100	2	0.00	0.001	0.001
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50	0.50	4	16	64	0.0100	0.0001	2	1.00	0.011	0.013
0.50 4 16 64 0.0001 1.0000 3 0.00 0.084 0.124 0.50 4 16 64 0.0001 0.0100 2 1.00 0.015 0.018 0.50 4 16 64 0.0001 0.0100 3 1.00 0.011 0.018 0.50 4 16 64 0.0001 0.0001 2 1.00 0.013 0.015 0.50 4 16 64 0.0001 0.0001 3 1.00 0.013 0.022 0.50 4 16 256 1.0000 1.0000 2 0.00 0.011 0.017 0.50 4 16 256 1.0000 1.0000 3 0.00 0.260 0.285 0.50 4 16 256 1.0000 0.0100 3 0.00 0.376 2.435 0.50 4 16 256 1.0000 0.0001 3										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.50 4 16 256 1.0000 1.0000 2 0.00 0.011 0.017 0.50 4 16 256 1.0000 1.0000 3 0.00 0.260 0.285 0.50 4 16 256 1.0000 0.0100 2 0.00 0.001 0.026 0.50 4 16 256 1.0000 0.0100 3 0.00 0.376 2.435 0.50 4 16 256 1.0000 0.0001 2 1.00 0.046 0.072 0.50 4 16 256 1.0000 0.0001 3 1.00 0.045 0.066 0.50 4 16 256 0.0100 1.0000 2 0.00 0.018 0.021 0.50 4 16 256 0.0100 1.0000 3 0.00 0.301 0.769 0.50 4 16 256 0.0100 0.0100 3 <td></td>										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.50		16	256			2	0.00	0.011	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.50		16		0.0100	0.0100	2	1.00		0.053
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.50		16	256	0.0001	0.0001	2	1.00	0.080	0.084
0.50 4 64 1 1.0000 1.0000 3 0.00 0.009 0.011 0.50 4 64 1 1.0000 0.0100 2 0.00 0.001 0.001 0.50 4 64 1 1.0000 0.0100 3 0.33 0.003 0.011 0.50 4 64 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 4 64 1 1.0000 0.0001 3 0.17 0.003 0.011 0.50 4 64 1 0.0100 1.0000 2 0.00 0.001 0.001										
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.50 4 64 1 1.0000 0.0100 3 0.33 0.003 0.011 0.50 4 64 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 4 64 1 1.0000 0.0001 3 0.17 0.003 0.011 0.50 4 64 1 0.0100 1.0000 2 0.00 0.001 0.001										
0.50 4 64 1 1.0000 0.0001 2 0.00 0.001 0.001 0.50 4 64 1 1.0000 0.0001 3 0.17 0.003 0.011 0.50 4 64 1 0.0100 1.0000 2 0.00 0.001 0.001										
0.50 4 64 1 1.0000 0.0001 3 0.17 0.003 0.011 0.50 4 64 1 0.0100 1.0000 2 0.00 0.001 0.001										
0.50 4 64 1 0.0100 1.0000 2 0.00 0.001 0.001										
0.50 4 64 1 0.0100 1.0000 3 0.17 0.003 0.055	0.50	4	64	1	0.0100	1.0000	3	0.17	0.003	0.055

0.50	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50					0.0100					0.001
0.50										
0.50										
0.50										
0.50										
0.50	0.50	4	64	1	0.0001	0.0100	2		0.001	0.001
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50		4		4						
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50										
0.50	0.50	4	64	16	1.0000	1.0000	3	0.00	0.012	0.019
0.50										
0.50										
0.50 4 64 16 0.0100 1.0000 2 0.00 0.001 0.001 0.50 4 64 16 0.0100 1.0000 3 0.00 0.014 0.027 0.50 4 64 16 0.0100 0.0100 2 1.00 0.004 0.005 0.50 4 64 16 0.0100 0.0001 2 0.83 0.001 0.007 0.50 4 64 16 0.0100 0.0001 3 1.00 0.005 0.007 0.50 4 64 16 0.0001 1.0000 2 0.17 0.001 0.007 0.50 4 64 16 0.0001 1.0000 2 0.17 0.001 0.007 0.50 4 64 16 0.0001 0.0100 2 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0100 2										
0.50 4 64 16 0.0100 1.0000 3 0.00 0.014 0.027 0.50 4 64 16 0.0100 0.0100 2 1.00 0.004 0.005 0.50 4 64 16 0.0100 0.0001 2 0.83 0.001 0.007 0.50 4 64 16 0.0100 0.0001 2 0.83 0.001 0.007 0.50 4 64 16 0.0001 1.0000 2 0.17 0.001 0.006 0.50 4 64 16 0.0001 1.0000 3 0.33 0.006 0.004 0.50 4 64 16 0.0001 0.0100 2 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.007 0.50 4 64 16 0.0001 0.0001 3										
0.50 4 64 16 0.0100 0.0100 3 1.00 0.004 0.005 0.50 4 64 16 0.0100 0.0001 2 0.83 0.001 0.007 0.50 4 64 16 0.0100 0.0001 3 1.00 0.005 0.007 0.50 4 64 16 0.0001 1.0000 3 0.33 0.006 0.044 0.50 4 64 16 0.0001 0.0100 2 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0100 3 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.007 0.50 4 64 16 1.0000 1.0000 3 0.00 0.001 0.000 0.50 4 64 64 1.0000 1.0000 3	0.50								0.014	0.027
0.50 4 64 16 0.0100 0.0001 2 0.83 0.001 0.007 0.50 4 64 16 0.0100 0.0001 3 1.00 0.005 0.007 0.50 4 64 16 0.0001 1.0000 3 0.33 0.006 0.044 0.50 4 64 16 0.0001 0.0100 2 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0100 3 1.33 0.006 0.004 0.50 4 64 16 0.0001 0.0100 3 1.00 0.007 0.006 0.50 4 64 16 1.0001 0.0001 3 1.00 0.007 0.008 0.50 4 64 64 1.0000 1.0000 3 1.00 0.007 0.000 0.50 4 64 64 1.0000 0.0100 3										
0.50 4 64 16 0.0100 0.0001 3 1.00 0.005 0.007 0.50 4 64 16 0.0001 1.0000 2 0.17 0.001 0.006 0.50 4 64 16 0.0001 1.0000 3 0.33 0.006 0.044 0.50 4 64 16 0.0001 0.0100 2 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0001 3 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.007 0.50 4 64 16 1.0000 1.0000 3 1.00 0.007 0.008 0.50 4 64 64 1.0000 1.0000 3 0.00 0.030 0.004 0.50 4 64 64 1.0000 0.0100 3										
0.50 4 64 16 0.0001 1.0000 2 0.17 0.001 0.006 0.50 4 64 16 0.0001 1.0000 3 0.33 0.006 0.044 0.50 4 64 16 0.0001 0.0100 2 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0100 3 1.00 0.007 0.007 0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.008 0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.008 0.50 4 64 64 1.0000 1.0000 2 0.00 0.001 0.004 0.50 4 64 64 1.0000 0.0100 3 0.00 0.030 0.065 0.50 4 64 64 1.0000 0.0100 3										
0.50 4 64 16 0.0001 0.0100 2 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0100 3 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0001 2 1.00 0.007 0.007 0.50 4 64 16 1.0000 1.0000 2 0.00 0.001 0.001 0.50 4 64 64 1.0000 1.0000 3 0.00 0.001 0.004 0.50 4 64 64 1.0000 0.0100 2 0.17 0.001 0.005 0.50 4 64 64 1.0000 0.0100 3 0.17 0.011 0.067 0.50 4 64 64 1.0000 0.0001 3 0.17 0.011 0.067 0.50 4 64 64 1.0000 0.0001 3										
0.50 4 64 16 0.0001 0.0100 3 1.00 0.005 0.006 0.50 4 64 16 0.0001 0.0001 2 1.00 0.007 0.007 0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.008 0.50 4 64 64 1.0000 1.0000 3 0.00 0.031 0.00 0.003 0.00 0.003 0.00 0.003 0.00 0.003 0.00 0.003 0.00 0.001 0.00										
0.50 4 64 16 0.0001 0.0001 2 1.00 0.007 0.007 0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.008 0.50 4 64 64 1.0000 1.0000 2 0.00 0.001 0.004 0.50 4 64 64 1.0000 0.0100 2 0.17 0.001 0.012 0.50 4 64 64 1.0000 0.0100 3 0.01 0.011 0.067 0.50 4 64 64 1.0000 0.0100 3 0.17 0.011 0.067 0.50 4 64 64 1.0000 0.0001 3 0.001 0.015 0.50 4 64 64 1.0000 0.0001 3 1.00 0.010 0.015 0.50 4 64 64 0.0100 1.0000 3 1.00										
0.50 4 64 16 0.0001 0.0001 3 1.00 0.007 0.008 0.50 4 64 64 1.0000 1.0000 2 0.00 0.001 0.004 0.50 4 64 64 1.0000 0.1000 3 0.00 0.030 0.065 0.50 4 64 64 1.0000 0.0100 2 0.17 0.001 0.01 0.50 4 64 64 1.0000 0.0100 3 0.17 0.001 0.015 0.50 4 64 64 1.0000 0.0001 2 0.83 0.001 0.015 0.50 4 64 64 1.0000 0.0001 3 1.00 0.010 0.016 0.50 4 64 64 0.0100 1.0000 2 0.00 0.001 0.012 0.50 4 64 64 <t>0.0100 0.0100 3 <</t>										
0.50 4 64 64 1.0000 1.0000 2 0.00 0.001 0.004 0.50 4 64 64 1.0000 1.0000 3 0.00 0.030 0.065 0.50 4 64 64 1.0000 0.0100 2 0.17 0.001 0.012 0.50 4 64 64 1.0000 0.0010 3 0.01 0.011 0.015 0.50 4 64 64 1.0000 0.0001 2 0.83 0.001 0.015 0.50 4 64 64 1.0000 0.0001 3 1.00 0.010 0.016 0.50 4 64 64 0.0100 1.0000 3 0.00 0.057 0.197 0.50 4 64 64 0.0100 0.0100 3 0.00 0.057 0.197 0.50 4 64 64 0.0100 0.0100 3										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		4								
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
0.50 4 64 64 1.0000 0.0001 2 0.83 0.001 0.015 0.50 4 64 64 1.0000 0.0001 3 1.00 0.010 0.016 0.50 4 64 64 0.0100 1.0000 2 0.00 0.001 0.004 0.50 4 64 64 0.0100 0.0100 2 1.00 0.011 0.012 0.00 0.010 0.012 0.00 0.010 0.012 0.00 0.010 0.012 0.00 0.010 0.012 0.00 0.011 0.012 0.00 0.011 0.012 0.00 0.011 0.019 0.012 0.00 0.011 0.019 0.012 0.00 0.011 0.019 0.011 </td <td></td>										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0.50		64	64	0.0100	1.0000	2	0.00	0.001	0.004
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0.50	4	64	64	0.0100	0.0001	3	1.00	0.013	0.019
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0.50			64	0.0001	0.0001	3	1.00	0.020	0.023
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.50 4 64 256 1.0000 0.0100 3 0.00 0.135 2.056 0.50 4 64 256 1.0000 0.0001 2 1.00 0.046 0.050 0.50 4 64 256 1.0000 0.0001 3 1.00 0.046 0.047 0.50 4 64 256 0.0100 1.0000 2 0.00 0.001 0.025 0.50 4 64 256 0.0100 1.0000 3 0.00 0.352 0.425 0.50 4 64 256 0.0100 0.0100 2 1.00 0.051 0.080 0.50 4 64 256 0.0100 0.0100 2 1.00 0.072 0.080 0.50 4 64 256 0.0100 0.0100 3 1.00 0.072 0.080 0.50 4 64 256 0.0100 0.0001 2 <td></td>										
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.50 4 64 256 1.0000 0.0001 3 1.00 0.046 0.047 0.50 4 64 256 0.0100 1.0000 2 0.00 0.001 0.026 0.50 4 64 256 0.0100 1.0000 3 0.00 0.352 0.425 0.50 4 64 256 0.0100 0.0100 2 1.00 0.051 0.080 0.50 4 64 256 0.0100 0.0100 3 1.00 0.072 0.080 0.50 4 64 256 0.0100 0.0001 2 1.00 0.092 0.101										
0.50 4 64 256 0.0100 1.0000 3 0.00 0.352 0.425 0.50 4 64 256 0.0100 0.0100 2 1.00 0.051 0.080 0.50 4 64 256 0.0100 0.0100 3 1.00 0.072 0.080 0.50 4 64 256 0.0100 0.0001 2 1.00 0.092 0.101	0.50		64	256	1.0000	0.0001	3	1.00	0.046	0.047
0.50 4 64 256 0.0100 0.0100 2 1.00 0.051 0.080 0.50 4 64 256 0.0100 0.0100 3 1.00 0.072 0.080 0.50 4 64 256 0.0100 0.0001 2 1.00 0.092 0.101										
0.50 4 64 256 0.0100 0.0100 3 1.00 0.072 0.080 0.50 4 64 256 0.0100 0.0001 2 1.00 0.092 0.101										
0.50 4 64 256 0.0100 0.0001 2 1.00 0.092 0.101										
0.50 4 64 256 0.0100 0.0001 3 1.00 0.086 0.097										
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0.50	4	64	256	0.0100	0.0001	3	1.00	0.086	0.097

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	4	64	256	0.0001	1.0000	2	0.00	0.001	0.029
0.50	4	64	256	0.0001	1.0000	3	0.00	0.409	0.594
0.50	4	64	256	0.0001	0.0100	2	1.00	0.068	0.100
0.50	4	64	256	0.0001	0.0100	3	1.00	0.069	0.098
0.50	4	64	256	0.0001	0.0001	2	1.00	0.077	0.120
0.50	4	64	256	0.0001	0.0001	3	1.00	0.076	0.119
0.50	4	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	4	256	1	1.0000	1.0000	3	0.17	0.003	0.010
0.50	4	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	4	256	1	1.0000	0.0100	3	0.50	0.003	0.011
0.50	4	256 256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	4	256	1	0.0100	1.0000	2	0.00	0.003	0.012
0.50	4	256	1	0.0100	1.0000	3	0.00	0.001	0.001
0.50	4	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	4	256	1	0.0100	0.0100	3	0.00	0.009	0.010
0.50	4	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	4	256	1	0.0100	0.0001	3	0.17	0.003	0.047
0.50	4	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	4	256	1	0.0001	1.0000	3	0.50	0.003	0.011
0.50	4	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	4	256	1	0.0001	0.0100	3	0.17	0.003	0.012
0.50	4	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	4	256	1	0.0001	0.0001	3	0.33	0.003	0.013
0.50	4	256 256	4	1.0000	1.0000	3	0.00	0.001	0.001
0.50	4	256	4	1.0000	0.0100	2	0.17	0.004	0.009
0.50	4	256	4	1.0000	0.0100	3	0.50	0.001	0.001
0.50	4	256	4	1.0000	0.0001	2	0.17	0.001	0.004
0.50	4	256	4	1.0000	0.0001	3	0.50	0.004	0.019
0.50	4	256	4	0.0100	1.0000	2	0.00	0.001	0.001
0.50	4	256	4	0.0100	1.0000	3	0.17	0.004	0.019
0.50	4	256	4	0.0100	0.0100	2	0.33	0.001	0.003
0.50	4	256	4	0.0100	0.0100	3	0.83	0.003	0.013
0.50	4	256	4	0.0100	0.0001	2	0.50	0.001	0.004
0.50	4	256	4	0.0100	0.0001	3	0.83	0.004	0.014
0.50	4	256	4	0.0001	1.0000	2	0.33	0.001	0.004
0.50	4	256 256	4	0.0001	1.0000 0.0100	2	0.67	0.003	0.015
0.50	4	256	4	0.0001	0.0100	3	1.00	0.001	0.004
0.50	4	256	4	0.0001	0.0001	2	1.00	0.004	0.004
0.50	4	256	4	0.0001	0.0001	3	1.00	0.004	0.004
0.50	4	256	16	1.0000	1.0000	2	0.00	0.001	0.002
0.50	4	256	16	1.0000	1.0000	3	0.17	0.005	0.031
0.50	4	256	16	1.0000	0.0100	2	0.17	0.001	0.005
0.50	4	256	16	1.0000	0.0100	3	0.50	0.005	0.018
0.50	4	256	16	1.0000	0.0001	2	0.83	0.001	0.006
0.50	4	256	16	1.0000	0.0001	3	1.00	0.006	0.006
0.50	4	256	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	4	256	16	0.0100	1.0000	3	0.00	0.023	0.028
0.50	4	256	16	0.0100	0.0100	2	0.67	0.001	0.006
0.50 0.50	4	256 256	16 16	0.0100	0.0100	3 2	1.00	0.004	0.006
0.50	4	256	16	0.0100	0.0001	3	1.00	0.005	0.037
0.50	4	256	16	0.0100	1.0000	2	0.17	0.003	0.007
0.50	4	256	16	0.0001	1.0000	3	0.33	0.001	0.048
0.50	4	256	16	0.0001	0.0100	2	1.00	0.006	0.006
0.50	4	256	16	0.0001	0.0100	3	1.00	0.006	0.006
0.50	4	256	16	0.0001	0.0001	2	1.00	0.006	0.007
0.50	4	256	16	0.0001	0.0001	3	1.00	0.006	0.007
0.50	4	256	64	1.0000	1.0000	2	0.00	0.001	0.004
0.50	4	256	64	1.0000	1.0000	3	0.00	0.034	0.063
0.50	4	256	64	1.0000	0.0100	2	0.00	0.001	0.001
0.50	4	256	64	1.0000	0.0100	3	0.67	0.012	0.059
0.50	4	256	64	1.0000	0.0001	2	0.50	0.001	0.016
0.50	4	256	64	1.0000	0.0001	3	1.00	0.015	0.017
0.50	4	256	64	0.0100	1.0000	2	0.00	0.001	0.001
0.50	4	256 256	64	0.0100	1.0000 0.0100	3	0.00 1.00	0.038	0.078
0.50	4	256	64	0.0100	0.0100	3	1.00	0.010	0.013
0.50	4	256	64	0.0100	0.0001	2	1.00	0.010	0.013
0.50	4	256	64	0.0100	0.0001	3	1.00	0.011	0.013
				0.0001	1.0000	2	0.00	0.001	0.001
	4	256	04						
0.50	4	256 256	64 64	0.0001	1.0000	3	0.17	0.016	0.487
0.50							0.17 1.00	0.016 0.014	0.487 0.019

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	4	256	64	0.0001	0.0001	2	1.00	0.020	0.022
0.50	4	256	64	0.0001	0.0001	3	1.00	0.020	0.022
0.50	4	256 256	256 256	1.0000	1.0000	3	0.00	0.001	0.017
0.50	4	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	4	256	256	1.0000	0.0100	3	0.17	0.054	0.224
0.50	4	256	256	1.0000	0.0001	2	0.83	0.001	0.079
0.50	4	256 256	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.055	0.081 0.017
0.50	4	256	256	0.0100	1.0000	3	0.00	0.250	0.884
0.50	4	256	256	0.0100	0.0100	2	0.83	0.001	0.055
0.50	4	256 256	256	0.0100	0.0100	3	1.00	0.050	0.082
0.50	4	256	256 256	0.0100	0.0001	2	1.00	0.065	0.100
0.50	4	256	256	0.0001	1.0000	2	0.00	0.001	0.028
0.50	4	256	256	0.0001	1.0000	3	0.00	0.218	1.214
0.50	4	256 256	256 256	0.0001	0.0100	3	1.00	0.066	0.069
0.50	4	256	256	0.0001	0.0100	2	1.00	0.063	0.073
0.50	4	256	256	0.0001	0.0001	3	1.00	0.078	0.085
0.50	16	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	16 16	1	1	1.0000	1.0000 0.0100	2	0.33	0.003	0.010
0.50	16	1	1	1.0000	0.0100	3	0.00	0.001	0.001
0.50	16	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	16	1	1	1.0000	0.0001	3	0.33	0.004	0.010
0.50	16 16	1	1	0.0100	1.0000	3	0.00	0.001	0.001
0.50	16	1	1	0.0100	0.0100	2	0.00	0.009	0.001
0.50	16	1	1	0.0100	0.0100	3	0.17	0.004	0.046
0.50	16	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	16 16	1	1	0.0100	0.0001 1.0000	3	0.17	0.004	0.056
0.50	16	1	1	0.0001	1.0000	3	0.00	0.001	0.061
0.50	16	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	16	1	1	0.0001	0.0100	3	0.00	0.010	0.012
0.50	16	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	16	1	4	1.0000	1.0000	2	0.00	0.004	0.0012
0.50	16	1	4	1.0000	1.0000	3	0.17	0.010	0.011
0.50	16	1	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	1	4	1.0000	0.0100	3	0.17	0.004	0.015
0.50	16	1	4	1.0000	0.0001	3	0.67	0.003	0.003
0.50	16	1	4	0.0100	1.0000	2	0.17	0.001	0.003
0.50	16	1	4	0.0100	1.0000	3	0.33	0.003	0.060
0.50	16 16	1	4	0.0100	0.0100 0.0100	2	0.33	0.001	0.003 0.016
0.50	16	1	4	0.0100	0.0001	2	0.67	0.003	0.003
0.50	16	1	4	0.0100	0.0001	3	0.67	0.003	0.013
0.50	16	1	4	0.0001	1.0000	2	0.67	0.001	0.004
0.50	16 16	1	4	0.0001	1.0000 0.0100	3 2	0.67	0.003	0.014
0.50	16	1	4	0.0001	0.0100	3	1.00	0.003	0.004
0.50	16	1	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	16	1	16	0.0001 1.0000	0.0001 1.0000	3	0.83	0.003	0.012
0.50	16 16	1	16	1.0000	1.0000	3	0.00	0.001	0.001
0.50	16	1	16	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	1	16	1.0000	0.0100	3	0.00	0.015	0.027
0.50	16 16	1	16 16	1.0000	0.0001	3	0.17 1.00	0.001	0.006
0.50	16	1	16	0.0100	1.0000	2	0.00	0.000	0.003
0.50	16	1	16	0.0100	1.0000	3	0.00	0.026	0.036
0.50	16	1	16	0.0100	0.0100	2	0.83	0.001	0.006
0.50	16 16	1	16 16	0.0100	0.0100	2	1.00 0.83	0.004	0.006 0.004
0.50	16	1	16	0.0100	0.0001	3	1.00	0.001	0.004
0.50	16	1	16	0.0001	1.0000	2	0.00	0.001	0.002
0.50	16	1	16	0.0001	1.0000	3	0.00	0.018	0.705
0.50	16 16	1	16 16	0.0001	0.0100	2	1.00	0.004	0.005 0.005
0.50	16	1	16	0.0001	0.0100	2	1.00	0.004	0.005
0.50	16	1	16	0.0001	0.0001	3	1.00	0.005	0.005
0.50	16	1	64	1.0000	1.0000	2	0.00	0.003	0.004
0.50	16	1	64	1.0000	1.0000	3	0.00	0.044	0.165

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
0.50	16	1	64	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	1	64	1.0000	0.0100	3	0.33	0.013	0.082
0.50	16	1	64	1.0000	0.0001	2	1.00	0.009	0.014
0.50	16	1	64	1.0000	0.0001	3	1.00	0.009	0.015
0.50	16	1	64	0.0100	1.0000	2	0.00	0.001	0.006
0.50	16	1	64	0.0100	1.0000	3	0.00	0.060	0.088
0.50	16	1	64	0.0100	0.0100	2	1.00	0.011	0.015
0.50	16	1	64	0.0100	0.0100	3	1.00	0.014	0.015
0.50	16	1	64	0.0100	0.0001	2	1.00	0.011	0.018
0.50	16 16	1	64	0.0100	0.0001	2	1.00	0.011	0.017
0.50	16	1	64	0.0001	1.0000	3	0.00	0.006	0.008
0.50	16	1	64	0.0001	0.0100	2	1.00	0.030	0.093
0.50	16	1	64	0.0001	0.0100	3	1.00	0.011	0.014
0.50	16	1	64	0.0001	0.0001	2	1.00	0.014	0.016
0.50	16	1	64	0.0001	0.0001	3	1.00	0.014	0.014
0.50	16	1	256	1.0000	1.0000	2	0.00	0.011	0.013
0.50	16	1	256	1.0000	1.0000	3	0.00	0.184	0.195
0.50	16	1	256	1.0000	0.0100	2	0.00	0.001	0.042
0.50	16	1	256	1.0000	0.0100	3	0.00	0.311	5.486
0.50	16	1	256	1.0000	0.0001	2	1.00	0.045	0.072
0.50	16	1	256	1.0000	0.0001	3	1.00	0.045	0.058
0.50	16 16	1	256 256	0.0100	1.0000	3	0.00	0.018	0.026
0.50	16	1	256	0.0100	0.0100	2	1.00	0.309	1.316 0.078
0.50	16	1	256	0.0100	0.0100	3	1.00	0.047	0.078
0.50	16	1	256	0.0100	0.0001	2	1.00	0.046	0.072
0.50	16	1	256	0.0100	0.0001	3	1.00	0.085	0.102
0.50	16	1	256	0.0001	1.0000	2	0.00	0.027	0.041
0.50	16	1	256	0.0001	1.0000	3	0.00	0.456	1.213
0.50	16	1	256	0.0001	0.0100	2	1.00	0.062	0.092
0.50	16	1	256	0.0001	0.0100	3	1.00	0.059	0.095
0.50	16	1	256	0.0001	0.0001	2	1.00	0.074	0.089
0.50	16	1	256	0.0001	0.0001	3	1.00	0.074	0.121
0.50	16	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	16	4	1	1.0000	1.0000	3	0.33	0.011	0.013
0.50	16	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16 16	4	1	1.0000	0.0100	3	0.17	0.010	0.034
0.50	16	4	1	1.0000	0.0001	3	0.00	0.001	0.744
0.50	16	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	4	1	0.0100	1.0000	3	0.17	0.006	0.016
0.50	16	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	16	4	1	0.0100	0.0100	3	0.00	0.011	0.017
0.50	16	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	16	4	1	0.0100	0.0001	3	0.00	0.011	0.012
0.50	16	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	16	4	1	0.0001	1.0000	3	0.00	0.011	0.013
0.50	16	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	16	4	1	0.0001	0.0100	3	0.17	0.004	0.016
0.50	16 16	4	1	0.0001	0.0001	3	0.00	0.001	0.001 0.014
0.50	16	4	4	1.0000	1.0000	2	0.00	0.011	0.001
0.50	16	4	4	1.0000	1.0000	3	0.17	0.007	0.120
0.50	16	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	4	4	1.0000	0.0100	3	0.17	0.007	0.018
0.50	16	4	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	16	4	4	1.0000	0.0001	3	0.67	0.004	0.017
0.50	16	4	4	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	4	4	0.0100	1.0000	3	0.17	0.006	0.021
0.50	16	4	4	0.0100	0.0100	2	0.50	0.001	0.004
0.50	16	4	4	0.0100	0.0100	3	0.50	0.004	0.017
0.50	16	4	4	0.0100	0.0001	2	0.50	0.001	0.004
0.50	16 16	4	4	0.0100	0.0001 1.0000	3	0.67	0.004	0.015 0.004
0.50	16	4	4	0.0001	1.0000	3	0.17	0.001	0.004
0.50	16	4	4	0.0001	0.0100	2	0.17	0.004	0.023
0.50	16	4	4	0.0001	0.0100	3	1.00	0.001	0.004
0.50	16	4	4	0.0001	0.0001	2	0.83	0.004	0.004
0.50	16	4	4	0.0001	0.0001	3	1.00	0.004	0.014
0.50	16	4	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	16	4	16	1.0000	1.0000	3	0.00	0.019	0.026
0.50	16	4	16	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	4	16	1.0000	0.0100	3	0.83	0.006	0.015
	16	4	16	1.0000	0.0001	2	0.50	0.001	0.006
0.50	16	4	16	1.0000	0.0001	3	1.00	0.004	0.010

mul	m_1	m_2	\tau	TR	DTR	alg	SR	mint	maxt
0.50	16	4	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	4	16	0.0100	1.0000	3	0.00	0.001	0.028
0.50	16	4	16	0.0100	0.0100	2	0.83	0.001	0.006
0.50	16	4	16	0.0100	0.0100	3	1.00	0.005	0.011
0.50	16	4	16	0.0100	0.0001	2	1.00	0.006	0.007
0.50	16 16	4	16 16	0.0100	0.0001	3	1.00 0.17	0.006	0.007
0.50	16	4	16	0.0001	1.0000	2	0.17	0.001	0.006
0.50	16	4	16	0.0001	0.0100	2	1.00	0.006	0.006
0.50	16	4	16	0.0001	0.0100	3	1.00	0.006	0.006
0.50	16	4	16	0.0001	0.0001	2	1.00	0.005	0.008
0.50	16	4	16	0.0001	0.0001	3	1.00	0.005	0.007
0.50	16	4	64	1.0000	1.0000	2	0.00	0.001	0.003
0.50	16 16	4	64	1.0000	1.0000 0.0100	3	0.00	0.042	0.045
0.50	16	4	64	1.0000	0.0100	3	0.17	0.001	0.077
0.50	16	4	64	1.0000	0.0001	2	1.00	0.009	0.014
0.50	16	4	64	1.0000	0.0001	3	1.00	0.009	0.014
0.50	16	4	64	0.0100	1.0000	2	0.00	0.001	0.005
0.50	16	4	64	0.0100	1.0000	3	0.00	0.061	0.065
0.50	16 16	4	64 64	0.0100	0.0100	2	1.00	0.009	0.015 0.015
0.50	16	4	64	0.0100	0.0100	2	1.00	0.010	0.013
0.50	16	4	64	0.0100	0.0001	3	1.00	0.011	0.018
0.50	16	4	64	0.0001	1.0000	2	0.00	0.006	0.009
0.50	16	4	64	0.0001	1.0000	3	0.00	0.088	1.234
0.50	16	4	64	0.0001	0.0100	2	1.00	0.010	0.012
0.50	16	4	64	0.0001	0.0100	3	1.00	0.011	0.012
0.50	16 16	4	64	0.0001	0.0001	2	1.00	0.014	0.015 0.015
0.50	16	4	256	1.0000	1.0000	2	0.00	0.014	0.013
0.50	16	4	256	1.0000	1.0000	3	0.00	0.182	0.283
0.50	16	4	256	1.0000	0.0100	2	0.00	0.001	0.019
0.50	16	4	256	1.0000	0.0100	3	0.00	0.259	0.296
0.50	16	4	256	1.0000	0.0001	2	1.00	0.046	0.146
0.50	16 16	4	256 256	1.0000 0.0100	0.0001 1.0000	3	0.00	0.045	0.503 0.027
0.50	16	4	256	0.0100	1.0000	3	0.00	0.280	0.027
0.50	16	4	256	0.0100	0.0100	2	1.00	0.047	0.070
0.50	16	4	256	0.0100	0.0100	3	1.00	0.047	0.077
0.50	16	4	256	0.0100	0.0001	2	1.00	0.068	0.094
0.50	16	4	256	0.0100	0.0001	3	1.00	0.066	0.086
0.50	16 16	4	256 256	0.0001	1.0000	3	0.00	0.025 0.411	0.038 0.758
0.50	16	4	256	0.0001	0.0100	2	1.00	0.411	0.738
0.50	16	4	256	0.0001	0.0100	3	1.00	0.085	0.097
0.50	16	4	256	0.0001	0.0001	2	1.00	0.080	0.841
0.50	16	4	256	0.0001	0.0001	3	1.00	0.085	0.126
0.50	16	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	16	16	1	1.0000	1.0000	3	0.33	0.003	0.015
0.50	16 16	16 16	1	1.0000	0.0100	3	0.00	0.001	0.001
0.50	16	16	1	1.0000	0.0001	2	0.00	0.003	0.001
0.50	16	16	1	1.0000	0.0001	3	0.17	0.003	0.015
0.50	16	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	16	1	0.0100	1.0000	3	0.33	0.003	0.018
0.50	16 16	16 16	1	0.0100	0.0100	3	0.00	0.001	0.001
0.50	16	16	1	0.0100	0.0100	2	0.00	0.003	0.001
0.50	16	16	1	0.0100	0.0001	3	0.33	0.004	0.001
0.50	16	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	16	16	1	0.0001	1.0000	3	0.17	0.003	0.017
0.50	16	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	16	16	1	0.0001	0.0100	3	0.33	0.003	0.014
0.50	16 16	16 16	1	0.0001	0.0001	3	0.00	0.001	0.001
0.50	16	16	4	1.0000	1.0000	2	0.00	0.003	0.001
0.50	16	16	4	1.0000	1.0000	3	0.17	0.003	0.017
0.50	16	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	16	4	1.0000	0.0100	3	0.33	0.004	0.018
0.50	16	16	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	16 16	16 16	4	1.0000 0.0100	0.0001 1.0000	3	0.83	0.004	0.019
0.50	16	16	4	0.0100	1.0000	3	0.00	0.001	0.001
0.50	16	16	4	0.0100	0.0100	2	0.33	0.003	0.004
0.50	16	16	4	0.0100	0.0100	3	0.83	0.004	0.018

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	16	16	4	0.0100	0.0001	2	0.17	0.001	0.004
0.50	16	16	4	0.0100	0.0001	3	0.67	0.004	0.017
0.50	16	16	4	0.0001	1.0000	2	0.50	0.001	0.004
0.50	16	16	4	0.0001	1.0000	3	0.67	0.004	0.019
0.50	16	16	4	0.0001	0.0100	2	0.67	0.001	0.004
0.50	16	16	4	0.0001	0.0100	3	1.00	0.004	0.004
0.50	16	16	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	16	16	4	0.0001	0.0001	3	1.00	0.003	0.004
0.50	16	16	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	16	16 16	16	1.0000	1.0000	3	0.17	0.005	0.031
0.50	16 16	16	16 16	1.0000	0.0100	3	0.50	0.001	0.001
0.50	16	16	16	1.0000	0.0001	2	0.30	0.004	0.023
0.50	16	16	16	1.0000	0.0001	3	1.00	0.006	0.014
0.50	16	16	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	16	16	0.0100	1.0000	3	0.00	0.018	0.031
0.50	16	16	16	0.0100	0.0100	2	1.00	0.005	0.005
0.50	16	16	16	0.0100	0.0100	3	1.00	0.005	0.006
0.50	16	16	16	0.0100	0.0001	2	1.00	0.005	0.006
0.50	16	16	16	0.0100	0.0001	3	1.00	0.004	0.006
0.50	16	16	16	0.0001	1.0000	2	0.33	0.001	0.006
0.50	16	16	16	0.0001	1.0000 0.0100	3	0.33	0.006	0.034
0.50	16 16	16 16	16 16	0.0001	0.0100	3	1.00	0.006	0.007
0.50	16	16	16	0.0001	0.0100	2	1.00	0.006	0.006
0.50	16	16	16	0.0001	0.0001	3	1.00	0.006	0.007
0.50	16	16	64	1.0000	1.0000	2	0.00	0.001	0.004
0.50	16	16	64	1.0000	1.0000	3	0.00	0.055	0.065
0.50	16	16	64	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	16	64	1.0000	0.0100	3	0.67	0.008	0.085
0.50	16	16	64	1.0000	0.0001	2	0.83	0.001	0.015
0.50	16	16	64	1.0000	0.0001	3	1.00	0.010	0.015
0.50	16	16	64	0.0100	1.0000	2	0.00	0.001	0.006
0.50	16	16	64	0.0100	1.0000	3	0.00	0.066	0.087
0.50	16 16	16 16	64	0.0100	0.0100	2	1.00	0.010	0.014
0.50	16	16	64	0.0100	0.0100	3	1.00	0.010	0.014
0.50	16	16	64	0.0100	0.0001	3	1.00	0.011	0.014
0.50	16	16	64	0.0100	1.0000	2	0.00	0.011	0.013
0.50	16	16	64	0.0001	1.0000	3	0.00	0.073	0.185
0.50	16	16	64	0.0001	0.0100	2	1.00	0.017	0.018
0.50	16	16	64	0.0001	0.0100	3	1.00	0.016	0.018
0.50	16	16	64	0.0001	0.0001	2	1.00	0.018	0.022
0.50	16	16	64	0.0001	0.0001	3	1.00	0.018	0.022
0.50	16	16	256	1.0000	1.0000	2	0.00	0.016	0.017
0.50	16	16	256	1.0000	1.0000	3	0.00	0.258	0.282
0.50	16	16	256	1.0000	0.0100	2	0.00	0.001	0.026
0.50	16	16	256	1.0000	0.0100	3	0.00	0.258	1.048
0.50	16 16	16 16	256 256	1.0000	0.0001	3	1.00	0.047 0.048	0.050
0.50	16	16	256	0.0100	1.0000	2	0.00	0.048	0.030
0.50	16	16	256	0.0100	1.0000	3	0.00	0.017	0.371
0.50	16	16	256	0.0100	0.0100	2	1.00	0.049	0.053
0.50	16	16	256	0.0100	0.0100	3	1.00	0.050	0.055
0.50	16	16	256	0.0100	0.0001	2	1.00	0.063	0.098
0.50	16	16	256	0.0100	0.0001	3	1.00	0.062	0.098
0.50	16	16	256	0.0001	1.0000	2	0.00	0.027	0.042
0.50	16	16	256	0.0001	1.0000	3	0.00	0.431	1.102
0.50	16	16	256	0.0001	0.0100	2	1.00	0.063	0.103
0.50	16	16	256 256	0.0001	0.0100	3	1.00	0.060	0.101
0.50	16 16	16 16	256	0.0001	0.0001	3	1.00	0.073	0.089
0.50	16	64	230	1.0000	1.0000	2	0.00	0.073	0.084
0.50	16	64	1	1.0000	1.0000	3	0.33	0.001	0.001
0.50	16	64	1	1.0000	0.0100	2	0.00	0.003	0.001
0.50	16	64	1	1.0000	0.0100	3	0.33	0.003	0.013
0.50	16	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	16	64	1	1.0000	0.0001	3	0.33	0.003	0.011
0.50	16	64	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	64	1	0.0100	1.0000	3	0.17	0.003	0.011
0.50	16	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	16	64	1	0.0100	0.0100	3	0.17	0.003	0.012
0.50	16	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	16	64	1	0.0100	0.0001	3	0.17	0.003	0.018
0.50	16 16	64 64	1	0.0001	1.0000	3	0.00	0.001	0.001
0.50	10	04	1	0.0001	1.0000	3	0.00	0.009	0.011

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	16	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	16	64	1	0.0001	0.0100	3	0.50	0.003	0.013
0.50	16 16	64	1	0.0001	0.0001	3	0.00	0.001	0.001
0.50	16	64	4	1.0000	1.0000	2	0.00	0.010	0.001
0.50	16	64	4	1.0000	1.0000	3	0.17	0.003	0.015
0.50	16	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	64	4	1.0000	0.0100	3	0.00	0.013	0.023
0.50	16	64	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	16 16	64	4	1.0000 0.0100	0.0001 1.0000	3	0.33	0.004	0.014
0.50	16	64	4	0.0100	1.0000	3	0.00	0.010	0.015
0.50	16	64	4	0.0100	0.0100	2	0.50	0.001	0.004
0.50	16	64	4	0.0100	0.0100	3	1.00	0.003	0.003
0.50	16 16	64 64	4	0.0100	0.0001	2	0.33	0.001	0.003 0.015
0.50	16	64	4	0.0001	1.0000	2	0.07	0.003	0.003
0.50	16	64	4	0.0001	1.0000	3	0.33	0.003	0.014
0.50	16	64	4	0.0001	0.0100	2	1.00	0.003	0.003
0.50	16	64	4	0.0001	0.0100	3	1.00	0.003	0.003
0.50	16 16	64 64	4	0.0001	0.0001	2	1.00	0.003	0.004
0.50	16	64	16	1.0000	1.0000	2	0.00	0.003	0.003
0.50	16	64	16	1.0000	1.0000	3	0.00	0.014	0.018
0.50	16	64	16	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	64	16	1.0000	0.0100	3	0.83	0.004	0.016
0.50	16 16	64	16 16	1.0000	0.0001	3	0.67 1.00	0.001	0.006
0.50	16	64	16	0.0100	1.0000	2	0.00	0.004	0.000
0.50	16	64	16	0.0100	1.0000	3	0.17	0.010	0.028
0.50	16	64	16	0.0100	0.0100	2	0.83	0.001	0.006
0.50	16	64	16	0.0100	0.0100	3	1.00	0.006	0.006
0.50	16 16	64	16 16	0.0100	0.0001	2	1.00	0.006	0.006
0.50	16	64	16	0.0001	1.0000	2	0.33	0.001	0.006
0.50	16	64	16	0.0001	1.0000	3	0.50	0.004	0.044
0.50	16	64	16	0.0001	0.0100	2	1.00	0.004	0.006
0.50	16 16	64	16 16	0.0001 0.0001	0.0100	2	1.00	0.004	0.006
0.50	16	64	16	0.0001	0.0001	3	1.00	0.005	0.007
0.50	16	64	64	1.0000	1.0000	2	0.00	0.001	0.005
0.50	16	64	64	1.0000	1.0000	3	0.00	0.043	0.066
0.50	16	64	64	1.0000	0.0100	2	0.17	0.001	0.008
0.50	16 16	64	64 64	1.0000	0.0100	3	0.67	0.008	0.051
0.50	16	64	64	1.0000	0.0001	3	1.00	0.001	0.011
0.50	16	64	64	0.0100	1.0000	2	0.00	0.001	0.004
0.50	16	64	64	0.0100	1.0000	3	0.00	0.039	0.064
0.50	16	64	64	0.0100	0.0100	2	0.83	0.001	0.010
0.50	16 16	64	64 64	0.0100	0.0100	3	1.00	0.010	0.011
0.50	16	64	64	0.0100	0.0001	3	1.00	0.011	0.018
0.50	16	64	64	0.0001	1.0000	2	0.00	0.001	0.001
0.50	16	64	64	0.0001	1.0000	3	0.00	0.048	0.092
0.50	16 16	64	64 64	0.0001	0.0100	3	1.00	0.011	0.013
0.50	16	64	64	0.0001	0.0100	2	1.00	0.012	0.013
0.50	16	64	64	0.0001	0.0001	3	1.00	0.014	0.017
0.50	16	64	256	1.0000	1.0000	2	0.00	0.001	0.013
0.50	16	64	256	1.0000	1.0000	3	0.00	0.183	0.801
0.50	16 16	64	256 256	1.0000	0.0100	3	0.00	0.001	0.019 0.366
0.50	16	64	256	1.0000	0.0001	2	1.00	0.173	0.074
0.50	16	64	256	1.0000	0.0001	3	1.00	0.051	0.074
0.50	16	64	256	0.0100	1.0000	2	0.00	0.001	0.027
0.50	16	64 64	256 256	0.0100	1.0000 0.0100	3	0.00	0.406	1.230 0.079
0.50	16 16	64	256	0.0100	0.0100	2	1.00	0.050	0.079
0.50	16	64	256	0.0100	0.0001	2	1.00	0.060	0.071
0.50	16	64	256	0.0100	0.0001	3	1.00	0.060	0.082
0.50	16	64	256	0.0001	1.0000	2	0.00	0.001	0.042
0.50	16 16	64 64	256 256	0.0001	1.0000 0.0100	3	0.00 1.00	0.409	1.091 0.064
0.50	16	64	256	0.0001	0.0100	3	1.00	0.059	0.064
0.50	16	64	256	0.0001	0.0001	2	1.00	0.081	0.127
0.50	16	64	256	0.0001	0.0001	3	1.00	0.081	0.127

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	16	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	16	256	1	1.0000	1.0000	3	0.33	0.003	0.014
0.50	16	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	256	1	1.0000	0.0100	3	0.00	0.011	0.014
0.50	16	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	16	256	1	1.0000	0.0001	3	0.50	0.003	0.010
0.50	16	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	256	1	0.0100	1.0000	3	0.17	0.008	0.011
0.50	16	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	16 16	256 256	1	0.0100	0.0100	3	0.50	0.003	0.011
0.50	16	256	1	0.0100	0.0001	3	0.00	0.001	0.001
0.50	16	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	16	256	1	0.0001	1.0000	3	0.00	0.011	0.011
0.50	16	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	16	256	1	0.0001	0.0100	3	0.50	0.003	0.011
0.50	16	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	16	256	1	0.0001	0.0001	3	0.00	0.009	0.010
0.50	16	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	16	256	4	1.0000	1.0000	3	0.17	0.003	0.012
0.50	16	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16 16	256 256	4	1.0000	0.0100	3	0.33	0.004	0.014
0.50	16	256	4	1.0000	0.0001	3	0.17	0.001	0.004
0.50	16	256	4	0.0100	1.0000	2	0.83	0.004	0.003
0.50	16	256	4	0.0100	1.0000	3	0.17	0.001	0.003
0.50	16	256	4	0.0100	0.0100	2	0.17	0.001	0.003
0.50	16	256	4	0.0100	0.0100	3	0.83	0.003	0.010
0.50	16	256	4	0.0100	0.0001	2	0.33	0.001	0.004
0.50	16	256	4	0.0100	0.0001	3	0.67	0.003	0.011
0.50	16	256	4	0.0001	1.0000	2	0.17	0.001	0.004
0.50	16	256	4	0.0001	1.0000	3	0.50	0.004	0.015
0.50	16	256	4	0.0001	0.0100	2	0.83	0.001	0.004
0.50	16	256	4	0.0001	0.0100	3	1.00	0.004	0.004
0.50	16 16	256 256	4	0.0001	0.0001	3	1.00	0.004	0.004
0.50	16	256	16	1.0000	0.0001 1.0000	2	1.00 0.00	0.004	0.004
0.50	16	256	16	1.0000	1.0000	3	0.00	0.001	0.001
0.50	16	256	16	1.0000	0.0100	2	0.33	0.004	0.005
0.50	16	256	16	1.0000	0.0100	3	0.67	0.004	0.017
0.50	16	256	16	1.0000	0.0001	2	0.17	0.001	0.004
0.50	16	256	16	1.0000	0.0001	3	1.00	0.004	0.009
0.50	16	256	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	16	256	16	0.0100	1.0000	3	0.17	0.005	0.027
0.50	16	256	16	0.0100	0.0100	2	0.83	0.001	0.006
0.50	16	256	16	0.0100	0.0100	3	1.00	0.004	0.006
0.50	16	256	16	0.0100	0.0001	2	1.00	0.005	0.005
0.50	16	256	16	0.0100	0.0001	3	1.00	0.005	0.006
0.50	16 16	256 256	16 16	0.0001	1.0000	3	0.17	0.001	0.004
0.50	16	256	16	0.0001	0.0100	2	1.00	0.004	0.024
0.50	16	256	16	0.0001	0.0100	3	1.00	0.003	0.005
0.50	16	256	16	0.0001	0.0001	2	1.00	0.005	0.005
0.50	16	256	16	0.0001	0.0001	3	1.00	0.005	0.006
0.50	16	256	64	1.0000	1.0000	2	0.00	0.001	0.003
0.50	16	256	64	1.0000	1.0000	3	0.17	0.025	0.058
0.50	16	256	64	1.0000	0.0100	2	0.00	0.001	0.001
0.50	16	256	64	1.0000	0.0100	3	0.50	0.009	0.052
0.50	16	256	64	1.0000	0.0001	2	0.50	0.001	0.015
0.50	16	256	64 64	1.0000 0.0100	0.0001	3	0.83	0.010	0.078
0.50	16 16	256 256	64	0.0100	1.0000	3	0.00	0.001	0.006 0.087
0.50	16	256	64	0.0100	0.0100	2	1.00	0.047	0.087
0.50	16	256	64	0.0100	0.0100	3	1.00	0.013	0.016
0.50	16	256	64	0.0100	0.0001	2	1.00	0.014	0.018
0.50	16	256	64	0.0100	0.0001	3	1.00	0.013	0.019
0.50	16	256	64	0.0001	1.0000	2	0.00	0.001	0.006
0.50	16	256	64	0.0001	1.0000	3	0.17	0.011	0.122
0.50	16	256	64	0.0001	0.0100	2	1.00	0.013	0.018
0.50	16	256	64	0.0001	0.0100	3	1.00	0.013	0.018
0.50	16	256	64	0.0001	0.0001	2	1.00	0.021	0.023
0.50	16	256	64	0.0001	0.0001	3	1.00	0.014	0.052
0.50	16	256	256	1.0000	1.0000	2	0.00	0.001	0.017
0.50	16 16	256 256	256 256	1.0000	1.0000 0.0100	3	0.00	0.166	0.245
0.50	16	256	256	1.0000	0.0100	3	0.00	0.001	0.850
0.50	10	230	230	1.0000	0.0100	3	0.17	0.050	0.050

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	16	256	256	1.0000	0.0001	2	0.67	0.001	0.078
0.50	16	256	256	1.0000	0.0001	3	1.00	0.054	0.083
0.50	16 16	256	256	0.0100	1.0000	2	0.00	0.001	0.022
0.50	16	256 256	256 256	0.0100	0.0100	3	0.00	0.257	0.388
0.50	16	256	256	0.0100	0.0100	3	1.00	0.076	0.081
0.50	16	256	256	0.0100	0.0001	2	1.00	0.089	0.101
0.50	16	256	256	0.0100	0.0001	3	1.00	0.083	0.100
0.50	16	256	256	0.0001	1.0000	2	0.00	0.001	0.040
0.50	16 16	256 256	256 256	0.0001	1.0000 0.0100	3	0.00 1.00	0.416	0.646 0.101
0.50	16	256	256	0.0001	0.0100	3	1.00	0.097	0.102
0.50	16	256	256	0.0001	0.0001	2	1.00	0.085	0.128
0.50	16	256	256	0.0001	0.0001	3	1.00	0.109	0.127
0.50	64	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	1	1	1.0000	0.0100	2	0.00	0.004	0.021
0.50	64	1	1	1.0000	0.0100	3	0.17	0.004	0.069
0.50	64	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	64	1	1	1.0000	0.0001	3	0.17	0.004	0.011
0.50	64	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	64	1	1	0.0100	1.0000 0.0100	2	0.00	0.009	0.011
0.50	64	1	1	0.0100	0.0100	3	0.00	0.001	0.001
0.50	64	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	64	1	1	0.0100	0.0001	3	0.33	0.003	0.010
0.50	64	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	64 64	1	1	0.0001	1.0000 0.0100	3	0.33	0.003	0.011
0.50	64	1	1	0.0001	0.0100	3	0.17	0.004	0.012
0.50	64	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	64	1	1	0.0001	0.0001	3	0.17	0.004	0.012
0.50	64	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	1	4	1.0000	1.0000 0.0100	3	0.17	0.007	0.017
0.50	64	1	4	1.0000	0.0100	3	0.50	0.004	0.017
0.50	64	1	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	64	1	4	1.0000	0.0001	3	0.67	0.004	0.019
0.50	64	1	4	0.0100	1.0000	3	0.00	0.001	0.001
0.50	64	1	4	0.0100	0.0100	2	0.50	0.004	0.003
0.50	64	1	4	0.0100	0.0100	3	0.67	0.003	0.019
0.50	64	1	4	0.0100	0.0001	2	0.17	0.001	0.004
0.50	64	1	4	0.0100	0.0001	3	0.50	0.004	0.014
0.50	64	1	4	0.0001	1.0000	3	0.17	0.001	0.004
0.50	64	1	4	0.0001	0.0100	2	1.00	0.004	0.020
0.50	64	1	4	0.0001	0.0100	3	1.00	0.004	0.004
0.50	64	1	4	0.0001	0.0001	2	0.50	0.001	0.004
0.50	64	1	4	0.0001	0.0001	3	0.83	0.004	0.020
0.50	64	1	16	1.0000	1.0000	3	0.00	0.001	0.002
0.50	64	1	16 16	1.0000	1.0000 0.0100	2	0.00	0.013	0.030
0.50	64	1	16	1.0000	0.0100	3	0.67	0.005	0.034
0.50	64	1	16	1.0000	0.0001	2	0.17	0.001	0.006
0.50	64	1	16	1.0000	0.0001	3	1.00	0.006	0.009
0.50	64	1	16 16	0.0100 0.0100	1.0000	2	0.00	0.001	0.001 0.027
0.50	64	1	16	0.0100	0.0100	2	0.83	0.019	0.027
0.50	64	1	16	0.0100	0.0100	3	1.00	0.006	0.008
0.50	64	1	16	0.0100	0.0001	2	0.83	0.001	0.006
0.50	64	1	16	0.0100	0.0001	3	1.00	0.006	0.007
0.50	64	1	16 16	0.0001	1.0000	3	0.17	0.001	0.006
0.50	64	1	16	0.0001	0.0100	2	1.00	0.006	0.039
0.50	64	1	16	0.0001	0.0100	3	1.00	0.006	0.007
0.50	64	1	16	0.0001	0.0001	2	1.00	0.005	0.007
0.50	64	1	16	0.0001	0.0001	3	1.00	0.005	0.007
0.50	64 64	1	64 64	1.0000	1.0000	2	0.00	0.001	0.004
0.50	64	1	64	1.0000	0.0100	2	0.00	0.049	0.000
0.50	64	1	64	1.0000	0.0100	3	0.33	0.011	0.062
0.50	64	1	64	1.0000	0.0001	2	1.00	0.015	0.016
0.50	64	1	64	1.0000	0.0001	3	1.00	0.015	0.015
0.50	64	1	64 64	0.0100	1.0000	2	0.00	0.001	0.001 0.650
0.50	04	1	04	0.0100	1.0000	3	0.00	0.043	0.030

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	64	1	64	0.0100	0.0100	2	1.00	0.011	0.028
0.50	64	1	64	0.0100	0.0100	3	1.00	0.010	0.015
0.50	64	1	64	0.0100	0.0001	2	1.00	0.016	0.018
0.50	64	1	64	0.0100	0.0001 1.0000	3	1.00 0.00	0.016	0.018
0.50	64	1	64	0.0001	1.0000	3	0.00	0.001	0.009
0.50	64	1	64	0.0001	0.0100	2	1.00	0.014	0.137
0.50	64	1	64	0.0001	0.0100	3	1.00	0.011	0.014
0.50	64	1	64	0.0001	0.0001	2	1.00	0.018	0.022
0.50	64	1	64	0.0001	0.0001	3	1.00	0.021	0.022
0.50	64	1	256	1.0000	1.0000	2	0.00	0.011	0.017
0.50	64	1	256	1.0000	1.0000	3	0.00	0.190	0.277
0.50	64	1	256	1.0000	0.0100	2	0.00	0.001	0.025
0.50	64	1	256 256	1.0000	0.0100	3	0.00 1.00	0.167 0.048	1.060 0.090
0.50	64	1	256	1.0000	0.0001	3	1.00	0.048	0.090
0.50	64	1	256	0.0100	1.0000	2	0.00	0.016	0.027
0.50	64	1	256	0.0100	1.0000	3	0.00	0.274	0.321
0.50	64	1	256	0.0100	0.0100	2	1.00	0.052	0.059
0.50	64	1	256	0.0100	0.0100	3	1.00	0.052	0.054
0.50	64	1	256	0.0100	0.0001	2	1.00	0.058	0.065
0.50	64	1	256	0.0100	0.0001	3	1.00	0.059	0.065
0.50	64	1	256 256	0.0001	1.0000	2	0.00	0.027	0.040
0.50	64	1	256	0.0001	1.0000 0.0100	3	0.00 1.00	0.439	1.007 0.086
0.50	64	1	256	0.0001	0.0100	3	1.00	0.061	0.066
0.50	64	1	256	0.0001	0.0001	2	1.00	0.071	0.253
0.50	64	1	256	0.0001	0.0001	3	1.00	0.071	0.126
0.50	64	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	4	1	1.0000	1.0000	3	0.33	0.003	0.041
0.50	64	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	4	1	1.0000	0.0100	3	0.67	0.003	0.011
0.50	64	4	1	1.0000	0.0001	3	0.00	0.001	0.001
0.50	64	4	1	0.0100	1.0000	2	0.00	0.004	0.001
0.50	64	4	1	0.0100	1.0000	3	0.00	0.009	0.019
0.50	64	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	64	4	1	0.0100	0.0100	3	0.33	0.003	0.012
0.50	64	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	64	4	1	0.0100	0.0001	3	0.50	0.003	0.011
0.50	64	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	64	4	1	0.0001	1.0000 0.0100	3	0.17	0.009	0.010
0.50	64	4	1	0.0001	0.0100	3	0.00	0.001	0.001
0.50	64	4	1	0.0001	0.0001	2	0.00	0.004	0.001
0.50	64	4	1	0.0001	0.0001	3	0.17	0.004	0.013
0.50	64	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	4	4	1.0000	1.0000	3	0.00	0.011	0.017
0.50	64	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	4	4	1.0000	0.0100	3	0.33	0.004	0.018
0.50	64	4	4	1.0000	0.0001	3	0.00	0.001	0.001
0.50	64	4	4	0.0100	1.00001	2	0.17	0.003	0.016
0.50	64	4	4	0.0100	1.0000	3	0.33	0.001	0.001
0.50	64	4	4	0.0100	0.0100	2	0.50	0.001	0.003
0.50	64	4	4	0.0100	0.0100	3	0.83	0.003	0.010
0.50	64	4	4	0.0100	0.0001	2	0.50	0.001	0.004
0.50	64	4	4	0.0100	0.0001	3	0.67	0.004	0.019
0.50	64	4	4	0.0001	1.0000	2	0.50	0.001	0.004
0.50	64	4	4	0.0001	1.0000 0.0100	3	0.67 1.00	0.004	0.021
0.50	64	4	4	0.0001	0.0100	3	1.00	0.004	0.004
0.50	64	4	4	0.0001	0.0001	2	0.83	0.004	0.004
0.50	64	4	4	0.0001	0.0001	3	0.83	0.004	0.014
0.50	64	4	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	4	16	1.0000	1.0000	3	0.00	0.009	0.025
0.50	64	4	16	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	4	16	1.0000	0.0100	3	0.67	0.008	0.027
0.50	64	4	16	1.0000	0.0001	2	0.50	0.001	0.006
0.50	64	4	16 16	1.0000 0.0100	0.0001 1.0000	2	1.00 0.00	0.005	0.013
0.50	64	4	16	0.0100	1.0000	3	0.00	0.001	0.001
0.50	64	4	16	0.0100	0.0100	2	0.83	0.001	0.005
0.50	0+					_			
0.50	64	4	16	0.0100	0.0100	3	1.00	0.004	0.010
0.50					0.0100 0.0001 0.0001	3 2 3	1.00 0.67 1.00	0.004 0.001 0.004	0.010 0.005 0.013

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	64	4	16	0.0001	1.0000	2	0.33	0.001	0.004
0.50	64	4	16	0.0001	1.0000	3	0.33	0.004	0.026
0.50	64	4	16 16	0.0001	0.0100	3	1.00	0.004	0.005
0.50	64	4	16	0.0001	0.0001	2	1.00	0.005	0.005
0.50	64	4	16	0.0001	0.0001	3	1.00	0.005	0.006
0.50	64	4	64	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	4	64	1.0000	1.0000	3	0.00	0.022	0.046
0.50	64 64	4	64 64	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	4	64	1.0000	0.0001	2	1.00	0.015	0.076
0.50	64	4	64	1.0000	0.0001	3	1.00	0.015	0.016
0.50	64	4	64	0.0100	1.0000	2	0.00	0.001	0.006
0.50	64	4	64	0.0100	1.0000	3	0.00	0.065	0.090
0.50	64	4	64	0.0100	0.0100	2	1.00	0.014	0.016 0.015
0.50	64	4	64	0.0100	0.0001	2	1.00	0.014	0.013
0.50	64	4	64	0.0100	0.0001	3	1.00	0.016	0.018
0.50	64	4	64	0.0001	1.0000	2	0.00	0.001	0.008
0.50	64	4	64	0.0001	1.0000	3	0.00	0.083	0.733
0.50	64	4	64 64	0.0001	0.0100	2	1.00	0.011	0.014
0.50	64	4	64	0.0001	0.0100	2	1.00	0.012	0.013
0.50	64	4	64	0.0001	0.0001	3	1.00	0.013	0.015
0.50	64	4	256	1.0000	1.0000	2	0.00	0.011	0.013
0.50	64	4	256	1.0000	1.0000	3	0.00	0.176	0.217
0.50	64	4	256 256	1.0000	0.0100	3	0.00	0.001	0.024 0.415
0.50	64	4	256	1.0000	0.0100	2	0.83	0.200	0.413
0.50	64	4	256	1.0000	0.0001	3	1.00	0.065	0.075
0.50	64	4	256	0.0100	1.0000	2	0.00	0.019	0.110
0.50	64	4	256	0.0100	1.0000	3	0.00	0.363	0.441
0.50	64 64	4	256 256	0.0100	0.0100	2	1.00	0.047	0.080
0.50	64	4	256	0.0100	0.0100	2	1.00	0.046	0.079
0.50	64	4	256	0.0100	0.0001	3	1.00	0.057	0.097
0.50	64	4	256	0.0001	1.0000	2	0.00	0.025	0.074
0.50	64	4	256	0.0001	1.0000	3	0.00	0.424	1.135
0.50	64	4	256 256	0.0001	0.0100	3	1.00	0.065	0.072
0.50	64	4	256	0.0001	0.0100	2	1.00	0.064	0.081
0.50	64	4	256	0.0001	0.0001	3	1.00	0.078	0.086
0.50	64	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	16	1	1.0000	1.0000	3	0.33	0.003	0.011
0.50	64	16	1	1.0000	0.0100	3	0.00	0.001	0.001
0.50	64	16 16	1	1.0000	0.0100	2	0.17	0.004	0.014
0.50	64	16	1	1.0000	0.0001	3	0.17	0.011	1.089
0.50	64	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	64	16	1	0.0100	1.0000	3	0.17	0.006	0.014
0.50	64	16	1	0.0100	0.0100	3	0.00	0.001	0.001
0.50	64	16 16	1	0.0100	0.0100	2	0.00	0.009	0.013
0.50	64	16	1	0.0100	0.0001	3	0.17	0.004	0.013
0.50	64	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	64	16	1	0.0001	1.0000	3	0.17	0.007	0.012
0.50	64	16 16	1	0.0001	0.0100	3	0.00	0.001	0.001 0.014
0.50	64	16	1	0.0001	0.0100	2	0.00	0.003	0.001
0.50	64	16	1	0.0001	0.0001	3	0.17	0.007	0.011
0.50	64	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	16	4	1.0000	1.0000	3	0.17	0.004	0.015
0.50	64	16 16	4	1.0000	0.0100	3	0.00	0.001	0.001
0.50	64	16	4	1.0000	0.0100	2	0.83	0.003	0.016
0.50	64	16	4	1.0000	0.0001	3	0.33	0.003	0.018
0.50	64	16	4	0.0100	1.0000	2	0.00	0.001	0.001
0.50	64	16	4	0.0100	1.0000	3	0.33	0.005	0.015
0.50	64 64	16	4	0.0100	0.0100	2	0.83	0.001	0.003 0.004
0.50	64	16 16	4	0.0100	0.0100	3	1.00 0.33	0.003	0.004
0.50	64	16	4	0.0100	0.0001	3	0.55	0.001	0.003
0.50	64	16	4	0.0001	1.0000	2	0.33	0.001	0.003
0.50	64	16	4	0.0001	1.0000	3	0.33	0.003	0.014
0.50	64	16	4	0.0001	0.0100	2	0.67	0.001	0.004
0.50	64	16	4	0.0001	0.0100	3	1.00	0.003	0.014

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	64	16	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	64	16	4	0.0001	0.0001	3	0.83	0.003	0.014
0.50	64	16	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	16	16	1.0000	1.0000	3	0.17	0.004	0.023
0.50	64	16	16 16	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	16 16	16	1.0000	0.0100	2	0.30	0.003	0.028
0.50	64	16	16	1.0000	0.0001	3	0.83	0.004	0.026
0.50	64	16	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	64	16	16	0.0100	1.0000	3	0.17	0.010	0.026
0.50	64	16	16	0.0100	0.0100	2	0.50	0.001	0.006
0.50	64	16	16	0.0100	0.0100	3	1.00	0.005	0.017
0.50	64	16 16	16 16	0.0100	0.0001	3	0.83 1.00	0.001	0.006
0.50	64	16	16	0.0100	1.0000	2	0.33	0.003	0.018
0.50	64	16	16	0.0001	1.0000	3	0.33	0.004	0.031
0.50	64	16	16	0.0001	0.0100	2	1.00	0.004	0.005
0.50	64	16	16	0.0001	0.0100	3	1.00	0.004	0.006
0.50	64	16	16	0.0001	0.0001	2	1.00	0.006	0.007
0.50	64	16 16	16 64	0.0001	0.0001	3	1.00	0.007	0.008
0.50	64	16	64	1.0000	1.0000	3	0.00	0.001	0.003
0.50	64	16	64	1.0000	0.0100	2	0.00	0.040	0.001
0.50	64	16	64	1.0000	0.0100	3	0.67	0.012	0.080
0.50	64	16	64	1.0000	0.0001	2	0.83	0.001	0.014
0.50	64	16	64	1.0000	0.0001	3	1.00	0.010	0.014
0.50	64	16	64	0.0100	1.0000	2	0.00	0.001	0.005
0.50	64	16 16	64 64	0.0100	1.0000 0.0100	2	0.00 1.00	0.043	0.068
0.50	64	16	64	0.0100	0.0100	3	1.00	0.010	0.013
0.50	64	16	64	0.0100	0.0001	2	1.00	0.011	0.018
0.50	64	16	64	0.0100	0.0001	3	1.00	0.012	0.051
0.50	64	16	64	0.0001	1.0000	2	0.00	0.001	0.006
0.50	64	16	64	0.0001	1.0000	3	0.00	0.072	0.092
0.50	64	16 16	64 64	0.0001	0.0100	3	1.00	0.012	0.013 0.014
0.50	64	16	64	0.0001	0.0001	2	1.00	0.011	0.014
0.50	64	16	64	0.0001	0.0001	3	1.00	0.013	0.016
0.50	64	16	256	1.0000	1.0000	2	0.00	0.011	0.013
0.50	64	16	256	1.0000	1.0000	3	0.00	0.181	0.833
0.50	64	16	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	16	256	1.0000	0.0100	3	0.00	0.159	0.253
0.50	64	16 16	256 256	1.0000	0.0001	3	1.00	0.048 0.047	0.050
0.50	64	16	256	0.0100	1.0000	2	0.00	0.047	0.031
0.50	64	16	256	0.0100	1.0000	3	0.00	0.276	0.332
0.50	64	16	256	0.0100	0.0100	2	1.00	0.049	0.079
0.50	64	16	256	0.0100	0.0100	3	1.00	0.050	0.065
0.50	64	16	256	0.0100	0.0001	2	1.00	0.062	0.098
0.50	64	16 16	256 256	0.0100	0.0001 1.0000	3	1.00 0.00	0.062	0.139 0.041
0.50	64	16	256	0.0001	1.0000	3	0.00	0.001	0.649
0.50	64	16	256	0.0001	0.0100	2	1.00	0.418	0.049
0.50	64	16	256	0.0001	0.0100	3	1.00	0.065	0.098
0.50	64	16	256	0.0001	0.0001	2	1.00	0.075	0.092
0.50	64	16	256	0.0001	0.0001	3	1.00	0.075	0.110
0.50	64	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	64	1	1.0000	1.0000 0.0100	3	0.17	0.011	0.016
0.50	64	64	1	1.0000	0.0100	3	0.50	0.001	0.001
0.50	64	64	1	1.0000	0.0001	2	0.00	0.003	0.001
0.50	64	64	1	1.0000	0.0001	3	0.33	0.011	0.016
0.50	64	64	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	64	64	1	0.0100	1.0000	3	0.33	0.004	0.013
0.50	64	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	64	64	1	0.0100	0.0100	2	0.33	0.003	0.014 0.001
0.50	64	64	1	0.0100	0.0001	3	0.00	0.001	0.001
0.50	64	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	64	64	1	0.0001	1.0000	3	0.67	0.003	0.014
0.50	64	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	64	64	1	0.0001	0.0100	3	0.17	0.004	0.014
0.50	64	64	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	64	64	1 4	0.0001 1.0000	0.0001 1.0000	2	0.67	0.003	0.014
0.50	64	64	4	1.0000	1.0000	3	0.00	0.001	0.001
0.50	04	04	-	1.0000	1.0000	J	0.33	0.003	0.010

0.50 64 64 4 1.0000 0.0100 3 0.33 0.004 6 0.50 64 64 4 1.0000 0.0001 2 0.00 0.001 6 0.50 64 64 4 1.0000 0.0001 3 0.33 0.004 6 0.50 64 64 4 0.0100 1.0000 3 0.50 0.004 6 0.50 64 64 4 0.0100 1.0000 3 0.50 0.004 6 0.50 64 64 4 0.0100 0.0100 2 0.17 0.001 0 0.50 6 64 64 4 0.0100 0.0001 3 0.67 0.004 6 0.50 6 64 64 4 0.0100 0.0001 3 0.67 0.004 6 0.50 6 64 64 4 0.0001 1.000 0.004 6 0.50<	0.001
0.50 64 64 4 1.0000 0.0001 2 0.00 0.001 0 0.50 64 64 4 1.0000 0.0001 3 0.33 0.004 6 0.50 64 64 4 0.0100 1.0000 2 0.17 0.001 6 0.50 64 64 4 0.0100 1.0000 3 0.50 0.004 6 0.50 64 64 4 0.0100 0.0100 2 0.17 0.001 6 0.50 6 64 64 4 0.0100 0.0100 3 0.67 0.004 6 0.50 6 64 64 4 0.0100 0.0001 3 0.67 0.004 6 0.50 64 64 4 0.0100 0.0001 3 1.00 0.004 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0	
0.50 64 64 4 1.0000 0.0001 3 0.33 0.004 6 0.50 64 64 4 0.0100 1.0000 2 0.17 0.001 6 0.50 64 64 4 0.0100 1.0000 3 0.50 0.004 6 0.50 64 64 4 0.0100 0.0100 2 0.17 0.001 6 0.50 64 64 4 0.0100 0.0100 3 0.67 0.001 6 0.64 64 4 0.0100 0.0001 3 0.67 0.001 0.004 6 0.50 64 64 4 0.0100 0.0001 3 1.00 0.004 6 0.50 64 64 4 0.0001 1.00 0.004 6 0.50 64 64 4 0.0001 1.0000 2 0.67 0.001 6 0.50 64 64 4 <t< td=""><td>0.018</td></t<>	0.018
0.50 64 64 4 0.0100 1.0000 2 0.17 0.001 0 0.50 64 64 4 0.0100 1.0000 3 0.50 0.004 6 0.50 64 64 4 0.0100 0.0100 3 0.67 0.001 6 0.50 64 64 4 0.0100 0.0001 2 0.83 0.001 6 0.50 64 64 4 0.0100 0.0001 2 0.83 0.001 6 0.50 6 64 64 4 0.0100 0.0001 3 1.00 0.004 6 0.50 6 64 64 4 0.0001 1.0000 2 0.67 0.001 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0	0.001
0.50 64 64 4 0.0100 1.0000 3 0.50 0.004 6 0.50 64 64 4 0.0100 0.0100 2 0.17 0.001 6 0.50 64 64 4 0.0100 0.0100 3 0.67 0.004 6 0.50 64 64 4 0.0100 0.0001 2 0.83 0.001 6 0.50 64 64 4 0.0100 0.0001 3 1.00 0.004 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 0.0100 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.000 3 1.00 0.004<	0.004
0.50 64 64 4 0.0100 0.0100 3 0.67 0.004 6 0.50 64 64 4 0.0100 0.0001 2 0.83 0.001 6 0.50 64 64 4 0.0101 0.0001 3 1.00 0.004 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 0.000 2 1.00 0.004 6 0.50 64 64 4 0.0001 0.0100 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.0001 2 0.67 0.001 6 0.50 64 64 16 1.00001 0.0001 3 0.67 0.00	0.014
0.50 64 64 4 0.0100 0.0001 2 0.83 0.001 0 0.50 64 64 4 0.0100 0.0001 3 1.00 0.004 6 0.50 64 64 4 0.0001 1.0000 2 0.67 0.001 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 0.0100 2 1.00 0.004 6 0.50 64 64 4 0.0001 0.0100 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.0001 2 0.67 0.001 6 0.50 64 64 4 0.0001 0.0001 3 0.67 0.004 6 0.50 64 64 16 1.0000 1.0000 3 0.17 0.00	0.004
0.50 64 64 4 0.0100 0.0001 3 1.00 0.004 6 0.50 64 64 4 0.0001 1.0000 2 0.67 0.001 6 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 0.0100 2 1.00 0.004 6 0.50 64 64 4 0.0001 0.0100 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.0001 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.0001 3 0.67 0.001 6 0.50 64 64 16 1.0000 1.0000 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0100 2 0.00 0.0	0.016
0.50 64 64 4 0.0001 1.0000 2 0.67 0.001 0 0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 0.0100 2 1.00 0.004 6 0.50 64 64 4 0.0001 0.0100 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.0001 2 0.67 0.001 6 0.50 64 64 4 0.0001 0.0001 3 0.67 0.004 6 0.50 64 64 16 1.0000 1.0000 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0100 3 0.17 0.005 6 0.50 64 64 16 1.0000 0.0100 3 0.83 0.	0.004
0.50 64 64 4 0.0001 1.0000 3 0.83 0.004 6 0.50 64 64 4 0.0001 0.0100 2 1.00 0.004 6 0.50 64 64 4 0.0001 0.0100 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.0001 2 0.67 0.001 6 0.50 64 64 4 0.0001 0.0001 3 0.67 0.004 6 0.50 64 64 4 0.0001 1.0000 2 0.00 0.001 6 0.50 64 64 16 1.0000 1.0000 3 0.17 0.005 6 0.50 64 64 16 1.0000 0.0100 3 0.83 0.006 0.001 0 0.00 0.001 0 0 0.00 0.001 0 0 0 </td <td>0.004</td>	0.004
0.50 64 64 4 0.0001 0.0100 3 1.00 0.004 6 0.50 64 64 4 0.0001 0.0001 2 0.67 0.001 6 0.50 64 64 4 0.0001 0.0001 3 0.67 0.004 6 0.50 64 64 16 1.0000 1.0000 3 0.17 0.005 6 0.50 64 64 16 1.0000 1.0000 3 0.17 0.005 0.00 0.001 6 0.50 64 64 16 1.0000 0.0100 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0100 3 0.83 0.006 6 0.50 6 4 64 16 1.0000 0.0001 2 0.33 0.001 6 0.50 6 4 64 16 1.0000 0.0001	0.013
0.50 64 64 4 0.0001 0.0001 2 0.67 0.001 0 0.50 64 64 4 0.0001 0.0001 3 0.67 0.004 6 0.50 64 64 16 1.0000 1.0000 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0100 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0100 2 0.00 0.001 0 0.00 0.001 0 0.00 0.001 0 0.00 0.001 0 0.00 0.001 0 0.00 0.001 0 0.00 0.001 0 0.00 0.001 0 0.00 0.001 0	0.004
0.50 64 64 4 0.0001 0.0001 3 0.67 0.004 6 0.50 64 64 16 1.0000 1.0000 2 0.00 0.001 6 0.50 64 64 16 1.0000 1.0000 3 0.17 0.005 6 0.50 64 64 16 1.0000 0.0100 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0100 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0001 2 0.33 0.001 6 0.50 64 64 16 1.0000 0.0001 3 1.00 0.005 6 0.50 64 64 16 0.0100 1.0000 2 0.00 0.001 6 0.50 64 64 16 0.0100 1.0000 3 0.33 <	0.004
0.50 64 64 16 1.0000 1.0000 2 0.00 0.001 0.005 0.50 64 64 16 1.0000 1.0000 3 0.17 0.005 0.005 0.005 0.001 0.000 0.0010 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.000 0.0001 0.000 0.0001 0.000 0.0001 0.000 0.000 0.0001 0.000 0.0001 0.000 <td>0.004</td>	0.004
0.50 64 64 16 1.0000 1.0000 3 0.17 0.005 6 0.50 64 64 16 1.0000 0.0100 2 0.00 0.001 6 0.50 64 64 16 1.0000 0.0001 3 0.83 0.006 6 0.50 64 64 16 1.0000 0.0001 3 1.00 0.005 6 0.50 64 64 16 1.0000 0.0001 3 1.00 0.005 0.00 0.001 6 0.50 64 64 16 0.0100 1.0000 2 0.00 0.001 6 0.50 64 64 16 0.0100 1.0000 3 0.33 0.005 6 0.50 64 64 16 0.0100 1.0000 3 0.33 0.001 6 0.50 64 64 16 0.0100 0.0100	0.001
0.50 64 64 16 1.0000 0.0100 3 0.83 0.006 6 0.50 64 64 16 1.0000 0.0001 2 0.33 0.001 6 0.50 64 64 16 1.0000 0.0001 3 1.00 0.005 6 0.50 64 64 16 0.0100 1.0000 2 0.00 0.001 6 0.50 64 64 16 0.0100 1.0000 3 0.33 0.005 6 0.50 64 64 16 0.0100 0.0100 2 0.83 0.001 6 0.50 64 64 16 0.0100 0.0100 3 1.00 0.005 6 0.50 64 64 16 0.0100 0.0001 2 1.00 0.006 6 0.50 64 64 16 0.0100 0.0001 3 1.00	0.020
0.50 64 64 16 1.0000 0.0001 2 0.33 0.001 0 0.50 64 64 16 1.0000 0.0001 3 1.00 0.005 0 0.50 64 64 16 0.0100 1.0000 2 0.00 0.001 0 0.50 64 64 16 0.0100 1.0000 3 0.33 0.005 0 0.50 64 64 16 0.0100 0.0100 2 0.83 0.001 0 0.50 64 64 16 0.0100 0.0100 3 1.00 0.005 0 0.50 64 64 16 0.0100 0.0001 2 1.00 0.006 0 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 0 0.50 64 64 16 0.0001 1.0000 3 0.67	0.001
0.50 64 64 16 1.0000 0.0001 3 1.00 0.005 6 0.50 64 64 16 0.0100 1.0000 2 0.00 0.001 6 0.50 64 64 16 0.0100 1.0000 3 0.33 0.005 6 0.50 64 64 16 0.0100 0.0100 2 0.83 0.001 6 0.50 64 64 16 0.0100 0.0100 3 1.00 0.005 6 0.50 64 64 16 0.0100 0.0001 2 1.00 0.006 6 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 6 0.50 64 64 16 0.0001 1.0000 3 0.67 0.001 6 0.50 64 64 16 0.0001 1.0000 3 0.67	0.027
0.50 64 64 16 0.0100 1.0000 2 0.00 0.001 0 0.50 64 64 16 0.0100 1.0000 3 0.33 0.005 0 0.50 64 64 16 0.0100 0.0100 2 0.83 0.001 0 0.50 64 64 16 0.0100 0.0001 2 1.00 0.005 0 0.50 64 64 16 0.0100 0.0001 2 1.00 0.006 0 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 0 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 0 0.50 64 64 16 0.0001 1.0000 2 0.67 0.001 0 0.50 64 64 16 0.0001 1.0000 3 0.67	0.006
0.50 64 64 16 0.0100 1.0000 3 0.33 0.005 6 0.50 64 64 16 0.0100 0.0100 2 0.83 0.001 6 0.50 64 64 16 0.0100 0.0001 3 1.00 0.005 6 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 6 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 6 0.50 64 64 16 0.0001 1.0000 2 0.67 0.001 6 0.50 64 64 16 0.0001 1.0000 3 0.67 0.004 6 0.50 64 64 16 0.0001 1.0000 3 0.67 0.004 6 0.50 64 64 16 0.0001 0.0100 2 1.00	0.000
0.50 64 64 16 0.0100 0.0100 3 1.00 0.005 6 0.50 64 64 16 0.0100 0.0001 2 1.00 0.006 6 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 6 0.50 64 64 16 0.0001 1.0000 2 0.67 0.001 6 0.50 64 64 16 0.0001 1.0000 3 0.67 0.004 6 0.50 64 64 16 0.0001 0.0100 2 1.00 0.005 6 0.50 64 64 16 0.0001 0.0100 3 1.00 0.005 6 0.50 64 64 16 0.0001 0.0100 3 1.00 0.006 6 0.50 64 64 16 0.0001 0.0001 2 1.00	0.027
0.50 64 64 16 0.0100 0.0001 2 1.00 0.006 0 0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 0 0.50 64 64 16 0.0001 1.0000 2 0.67 0.001 0 0.50 64 64 16 0.0001 0.0100 2 1.00 0.005 0 0.50 64 64 16 0.0001 0.0100 2 1.00 0.005 0 0.50 64 64 16 0.0001 0.0100 3 1.00 0.005 0 0.50 64 64 16 0.0001 0.0001 2 1.00 0.006 0 0.50 64 64 16 0.0001 0.0001 2 1.00 0.006 0 0.50 64 64 64 16 0.0001 0.0001 3 <t< td=""><td>0.006</td></t<>	0.006
0.50 64 64 16 0.0100 0.0001 3 1.00 0.006 0 0.50 64 64 16 0.0001 1.0000 2 0.67 0.001 0 0.50 64 64 16 0.0001 1.0000 3 0.67 0.004 0 0.50 64 64 16 0.0001 0.0100 2 1.00 0.005 0 0.50 64 64 16 0.0001 0.0001 2 1.00 0.005 0 0.50 64 64 16 0.0001 0.0001 2 1.00 0.005 0 0.50 64 64 16 0.0001 0.0001 2 1.00 0.006 0 0.50 64 64 16 0.0001 0.0001 3 1.00 0.006 0 0.50 64 64 16 0.0001 0.0001 3 1.00	0.006
0.50 64 64 16 0.0001 1.0000 2 0.67 0.001 0.001 0.50 64 64 16 0.0001 1.0000 3 0.67 0.004 0.004 0.50 64 64 16 0.0001 0.0100 2 1.00 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.005 0.006	0.007
0.50 64 64 16 0.0001 1.0000 3 0.67 0.004 6 0.50 64 64 16 0.0001 0.0100 2 1.00 0.005 6 0.50 64 64 16 0.0001 0.0100 3 1.00 0.005 6 0.50 64 64 16 0.0001 0.0001 2 1.00 0.006 6 0.50 64 64 16 0.0001 0.0001 3 1.00 0.006 6 0.50 64 64 64 1,0000 1,0000 2 0.00 0.001 6 0.50 64 64 64 1,0000 1,0000 2 0.00 0.001 6 0.50 64 64 64 1,0000 1,0000 3 0.17 0.009 6 0.50 64 64 64 1,0000 0.0100 2 0.00	0.007
0.50 64 64 16 0.0001 0.0100 3 1.00 0.005 6 0.50 64 64 16 0.0001 0.0001 2 1.00 0.006 6 0.50 64 64 16 0.0001 0.0001 3 1.00 0.006 6 0.50 64 64 64 1.0000 1.0000 2 0.00 0.001 6 0.50 64 64 64 1.0000 1.0000 3 0.17 0.009 6 0.50 64 64 64 1.0000 0.0100 2 0.00 0.001 6 0.50 64 64 64 1.0000 0.0100 2 0.00 0.001 6	0.021
0.50 64 64 16 0.0001 0.0001 2 1.00 0.006 0 0.50 64 64 16 0.0001 0.0001 3 1.00 0.006 0 0.50 64 64 64 1.0000 1.0000 2 0.00 0.001 0 0.50 64 64 64 1.0000 1.0000 3 0.17 0.009 0 0.50 64 64 64 1.0000 0.0100 2 0.00 0.001 0	0.006
0.50 64 64 16 0.0001 0.0001 3 1.00 0.006 0 0.50 64 64 64 1.0000 1.0000 2 0.00 0.001 0 0.50 64 64 64 1.0000 1.0000 3 0.17 0.009 0 0.50 64 64 64 1.0000 0.0100 2 0.00 0.001 0	0.006
0.50 64 64 64 1.0000 1.0000 2 0.00 0.001 0 0.50 64 64 64 1.0000 1.0000 3 0.17 0.009 0 0.50 64 64 64 1.0000 0.0100 2 0.00 0.001 0	0.007
0.50 64 64 64 1.0000 0.0100 2 0.00 0.001	0.001
	0.056
0.50 64 64 64 1.000N N.010N 3 0.17 0.000 1	0.001
	0.066
	0.024
	0.001
	0.081
	0.016
	0.016
	0.022
	0.016
	0.134
	0.019
	0.018
0.50 64 64 64 0.0001 0.0001 3 1.00 0.021	0.023
	0.011
	0.298
	0.001
	0.055
0.50 64 64 256 1.0000 0.0001 3 1.00 0.048	0.052
	0.019
	0.617
	0.007
0.50 64 64 256 0.0100 0.0001 2 1.00 0.062 0	0.069
	0.067
	0.029
	0.099
	0.098
0.50 64 64 256 0.0001 0.0001 2 1.00 0.080	0.084
	0.085
	0.001
	0.001
0.50 64 256 1 1.0000 0.0001 2 0.00 0.001	0.023
0.50 64 256 1 1.0000 0.0001 3 0.17 0.004 0	0.023

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	64	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	64	256	1	0.0100	1.0000	3	0.00	0.009	0.013
0.50	64	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	64	256	1	0.0100	0.0100	3	0.17	0.003	0.014
0.50	64	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	64	256	1	0.0100	0.0001	3	0.33	0.003	0.010
0.50	64	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	64	256	1	0.0001	1.0000	3	0.00	0.009	0.013
0.50	64	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	64	256 256	1	0.0001	0.0100	3	0.33	0.003	0.009
0.50	64	256	1	0.0001	0.0001	3	0.67	0.001	0.001
0.50	64	256	4	1.0000	1.0000	2	0.00	0.003	0.001
0.50	64	256	4	1.0000	1.0000	3	0.33	0.004	0.015
0.50	64	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	256	4	1.0000	0.0100	3	0.00	0.010	0.012
0.50	64	256	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	64	256	4	1.0000	0.0001	3	0.50	0.003	0.019
0.50	64	256	4	0.0100	1.0000	2	0.17	0.001	0.004
0.50	64	256	4	0.0100	1.0000	3	0.50	0.003	0.016
0.50	64	256 256	4	0.0100	0.0100	3	0.67	0.001	0.003
0.50	64	256	4	0.0100	0.0100	2	0.83	0.003	0.011
0.50	64	256	4	0.0100	0.0001	3	0.67	0.001	0.004
0.50	64	256	4	0.0001	1.0000	2	0.67	0.004	0.020
0.50	64	256	4	0.0001	1.0000	3	0.67	0.001	0.004
0.50	64	256	4	0.0001	0.0100	2	1.00	0.003	0.004
0.50	64	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.50	64	256	4	0.0001	0.0001	2	1.00	0.003	0.004
0.50	64	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.50	64	256	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	64	256	16	1.0000	1.0000	3	0.00	0.016	0.024
0.50	64	256	16	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	256	16	1.0000	0.0100	3	0.83	0.004	0.018
0.50	64	256 256	16 16	1.0000	0.0001	3	0.50	0.001	0.006
0.50	64	256	16	0.0100	0.0001 1.0000	2	1.00 0.00	0.004	0.006
0.50	64	256	16	0.0100	1.0000	3	0.00	0.001	0.001
0.50	64	256	16	0.0100	0.0100	2	0.67	0.003	0.005
0.50	64	256	16	0.0100	0.0100	3	1.00	0.004	0.005
0.50	64	256	16	0.0100	0.0001	2	1.00	0.005	0.007
0.50	64	256	16	0.0100	0.0001	3	1.00	0.005	0.007
0.50	64	256	16	0.0001	1.0000	2	0.33	0.001	0.006
0.50	64	256	16	0.0001	1.0000	3	0.33	0.006	0.034
0.50	64	256	16	0.0001	0.0100	2	1.00	0.004	0.006
0.50	64	256	16	0.0001	0.0100	3	1.00	0.005	0.007
0.50	64	256	16	0.0001	0.0001	2	1.00	0.005	0.014
0.50	64	256	16	0.0001	0.0001	3	1.00	0.005	0.013
0.50	64	256 256	64	1.0000	1.0000	3	0.00	0.001	0.004 1.063
0.50	64	256	64	1.0000	0.0100	2	0.17	0.009	0.008
0.50	64	256	64	1.0000	0.0100	3	0.83	0.001	0.056
0.50	64	256	64	1.0000	0.0001	2	0.50	0.001	0.011
0.50	64	256	64	1.0000	0.0001	3	1.00	0.010	0.011
0.50	64	256	64	0.0100	1.0000	2	0.00	0.001	0.001
0.50	64	256	64	0.0100	1.0000	3	0.17	0.032	0.065
0.50	64	256	64	0.0100	0.0100	2	1.00	0.012	0.015
0.50	64	256	64	0.0100	0.0100	3	1.00	0.010	0.015
0.50	64	256	64	0.0100	0.0001	2	0.83	0.001	0.014
0.50	64 64	256	64 64	0.0100	0.0001 1.0000	3	1.00 0.17	0.012	0.016
0.50	64	256 256	64	0.0001	1.0000	3	0.17	0.001	0.011
0.50	64	256	64	0.0001	0.0100	2	1.00	0.011	0.089
0.50	64	256	64	0.0001	0.0100	3	1.00	0.012	0.015
0.50	64	256	64	0.0001	0.0001	2	1.00	0.012	0.013
0.50	64	256	64	0.0001	0.0001	3	1.00	0.014	0.016
0.50	64	256	256	1.0000	1.0000	2	0.00	0.001	0.013
0.50	64	256	256	1.0000	1.0000	3	0.00	0.148	0.194
0.50	64	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	64	256	256	1.0000	0.0100	3	0.33	0.036	0.241
0.50	64	256	256	1.0000	0.0001	2	0.67	0.001	0.055
0.50	64	256	256	1.0000	0.0001	3	1.00	0.051	0.062
0.50	64	256	256	0.0100	1.0000	2	0.00	0.001	0.019
0.50	64	256 256	256 256	0.0100 0.0100	1.0000 0.0100	2	0.00 1.00	0.192	0.849 0.056
0.50	64	256	256	0.0100	0.0100	3	1.00	0.049	0.036
0.50	04	230	230	0.0100	0.0100	J	1.00	0.049	0.077

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	64	256	256	0.0100	0.0001	2	1.00	0.090	0.097
0.50	64	256	256	0.0100	0.0001	3	1.00	0.092	0.098
0.50	64	256	256	0.0001	1.0000	2	0.00	0.001	0.040
0.50	64	256 256	256 256	0.0001	1.0000 0.0100	3	0.00 1.00	0.420	1.008 0.101
0.50	64	256	256	0.0001	0.0100	3	1.00	0.099	0.101
0.50	64	256	256	0.0001	0.0001	2	1.00	0.073	0.101
0.50	64	256	256	0.0001	0.0001	3	1.00	0.073	0.124
0.50	256	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	1	1	1.0000	1.0000	3	0.17	0.004	0.011
0.50	256	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256 256	1	1	1.0000	0.0100	3	0.33	0.004	0.012
0.50	256	1	1	1.0000	0.0001	3	0.00	0.001	0.721
0.50	256	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	1	1	0.0100	1.0000	3	0.33	0.003	0.011
0.50	256	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	256	1	1	0.0100	0.0100	3	0.17	0.004	0.011
0.50	256 256	1	1	0.0100	0.0001	3	0.00	0.001	0.001
0.50	256	1	1	0.0100	1.0000	2	0.50	0.004	0.033
0.50	256	1	1	0.0001	1.0000	3	0.67	0.003	0.001
0.50	256	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	256	1	1	0.0001	0.0100	3	0.50	0.003	0.011
0.50	256	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	256	1	1	0.0001	0.0001	3	0.17	0.004	0.027
0.50	256	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256 256	1	4	1.0000	1.0000 0.0100	3	0.33	0.005	0.018
0.50	256	1	4	1.0000	0.0100	3	0.17	0.001	0.060
0.50	256	1	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	1	4	1.0000	0.0001	3	0.67	0.005	0.015
0.50	256	1	4	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	1	4	0.0100	1.0000	3	0.17	0.005	0.019
0.50	256	1	4	0.0100	0.0100	2	0.17	0.001	0.004
0.50	256	1	4	0.0100	0.0100	3	0.50	0.004	0.014
0.50	256 256	1	4	0.0100	0.0001	3	0.50 1.00	0.001	0.004
0.50	256	1	4	0.0100	1.0000	2	0.50	0.004	0.003
0.50	256	1	4	0.0001	1.0000	3	0.50	0.003	0.018
0.50	256	1	4	0.0001	0.0100	2	0.67	0.001	0.004
0.50	256	1	4	0.0001	0.0100	3	1.00	0.003	0.005
0.50	256	1	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	256 256	1	4 16	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.004	0.004
0.50	256	1	16	1.0000	1.0000	3	0.00	0.001	0.001
0.50	256	1	16	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	1	16	1.0000	0.0100	3	0.50	0.004	0.024
0.50	256	1	16	1.0000	0.0001	2	0.33	0.001	0.006
0.50	256	1	16	1.0000	0.0001	3	1.00	0.005	0.007
0.50	256	1	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256 256	1	16 16	0.0100	1.0000 0.0100	3 2	0.00	0.018	0.029
0.50	256	1	16	0.0100	0.0100	3	1.00	0.001	0.005
0.50	256	1	16	0.0100	0.0001	2	1.00	0.004	0.005
0.50	256	1	16	0.0100	0.0001	3	1.00	0.005	0.005
0.50	256	1	16	0.0001	1.0000	2	0.17	0.001	0.005
0.50	256	1	16	0.0001	1.0000	3	0.33	0.005	0.025
0.50	256	1	16	0.0001	0.0100	2	1.00	0.004	0.005
0.50	256 256	1	16 16	0.0001	0.0100	2	1.00	0.005	0.005 0.006
0.50	256	1	16	0.0001	0.0001	3	1.00	0.005	0.006
0.50	256	1	64	1.0000	1.0000	2	0.00	0.003	0.000
0.50	256	1	64	1.0000	1.0000	3	0.00	0.024	0.034
0.50	256	1	64	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	1	64	1.0000	0.0100	3	0.50	0.009	0.089
0.50	256	1	64	1.0000	0.0001	2	0.33	0.001	0.012
0.50	256 256	1	64 64	1.0000	0.0001 1.0000	3	1.00 0.00	0.010	0.016
0.50	256	1	64	0.0100	1.0000	3	0.00	0.001	0.006
0.50	256	1	64	0.0100	0.0100	2	0.17	0.043	0.016
0.50	256	1	64	0.0100	0.0100	3	1.00	0.010	0.016
0.50	256	1	64	0.0100	0.0001	2	1.00	0.017	0.018
0.50	256	1	64	0.0100	0.0001	3	1.00	0.017	0.018
0.50	256	1	64	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256	1	64	0.0001	1.0000	3	0.00	0.063	0.099

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	256	1	64	0.0001	0.0100	2	1.00	0.018	0.020
0.50	256	1	64	0.0001	0.0100	3	1.00	0.013	0.019
0.50	256	1	64	0.0001	0.0001	2	1.00	0.015	0.027
0.50	256	1	64	0.0001	0.0001	3	1.00	0.014	0.030
0.50	256	1	256	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	1	256	1.0000	1.0000	3	0.00	0.088	0.162
0.50	256	1	256	1.0000	0.0100	2	0.00	0.001	0.016
0.50	256	1	256	1.0000	0.0100	3	0.17	0.042	0.284
0.50	256	1	256	1.0000	0.0001	2	0.83	0.001	0.077
0.50	256 256	1	256 256	1.0000 0.0100	1.0000	2	1.00 0.00	0.057	0.148
0.50	256	1	256	0.0100	1.0000	3	0.00	0.001	0.023
0.50	256	1	256	0.0100	0.0100	2	1.00	0.054	0.082
0.50	256	1	256	0.0100	0.0100	3	1.00	0.053	0.082
0.50	256	1	256	0.0100	0.0001	2	1.00	0.065	0.099
0.50	256	1	256	0.0100	0.0001	3	1.00	0.065	0.097
0.50	256	1	256	0.0001	1.0000	2	0.00	0.001	0.027
0.50	256	1	256	0.0001	1.0000	3	0.00	0.311	1.514
0.50	256	1	256	0.0001	0.0100	2	1.00	0.061	0.071
0.50	256	1	256	0.0001	0.0100	3	1.00	0.061	0.070
0.50	256	1	256	0.0001	0.0001	2	1.00	0.076	0.092
0.50	256 256	1 4	256	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.075	0.099
0.50	256	4	1	1.0000	1.0000	3	0.00	0.001	0.001
0.50	256	4	1	1.0000	0.0100	2	0.17	0.004	0.010
0.50	256	4	1	1.0000	0.0100	3	0.00	0.001	0.001
0.50	256	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	4	1	1.0000	0.0001	3	0.33	0.004	0.012
0.50	256	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	4	1	0.0100	1.0000	3	0.17	0.004	0.011
0.50	256	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	256	4	1	0.0100	0.0100	3	0.33	0.004	0.014
0.50	256	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	256	4	1	0.0100	0.0001	3	0.33	0.004	0.012
0.50	256	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256 256	4	1	0.0001	1.0000 0.0100	2	0.17	0.008	0.011
0.50	256	4	1	0.0001	0.0100	3	0.00	0.001	0.001
0.50	256	4	1	0.0001	0.0001	2	0.00	0.003	0.001
0.50	256	4	1	0.0001	0.0001	3	0.17	0.004	0.012
0.50	256	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	4	4	1.0000	1.0000	3	0.50	0.004	0.013
0.50	256	4	4	1.0000	0.0100	2	0.17	0.001	0.003
0.50	256	4	4	1.0000	0.0100	3	0.67	0.003	0.013
0.50	256	4	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	4	4	1.0000	0.0001	3	0.67	0.003	0.019
0.50	256	4	4	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256 256	4	4	0.0100	1.0000	3	0.00	0.010	0.035
0.50	256	4	4	0.0100	0.0100	3	0.50	0.001	0.004
0.50	256	4	4	0.0100	0.0100	2	0.83	0.004	0.013
0.50	256	4	4	0.0100	0.0001	3	0.83	0.001	0.004
0.50	256	4	4	0.0001	1.0000	2	0.33	0.001	0.003
0.50	256	4	4	0.0001	1.0000	3	0.33	0.003	0.027
0.50	256	4	4	0.0001	0.0100	2	0.67	0.001	0.004
0.50	256	4	4	0.0001	0.0100	3	0.83	0.003	0.011
0.50	256	4	4	0.0001	0.0001	2	1.00	0.003	0.004
0.50	256	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.50	256	4	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	4	16	1.0000	1.0000	3	0.17	0.008	0.021
0.50	256 256	4	16 16	1.0000	0.0100	3	0.00	0.001	0.001
0.50	256	4	16	1.0000	0.0100	2	0.50	0.005	0.026
0.50	256	4	16	1.0000	0.0001	3	1.00	0.001	0.006
0.50	256	4	16	0.0100	1.0000	2	0.00	0.000	0.007
0.50	256	4	16	0.0100	1.0000	3	0.17	0.010	0.028
0.50	256	4	16	0.0100	0.0100	2	0.67	0.001	0.006
0.50	256	4	16	0.0100	0.0100	3	1.00	0.005	0.016
0.50	256	4	16	0.0100	0.0001	2	1.00	0.006	0.007
0.50	256	4	16	0.0100	0.0001	3	1.00	0.006	0.006
0.50	256	4	16	0.0001	1.0000	2	0.17	0.001	0.006
0.50	256	4	16	0.0001	1.0000	3	0.33	0.006	0.034
0.50	256	4	16	0.0001	0.0100	2	1.00	0.005	0.006
0.50	256	4	16	0.0001	0.0100	3	1.00	0.005	0.006
0.50	256 256	4	16 16	0.0001	0.0001	2	1.00	0.005	0.006
0.50			10		U.UUUT	3	1.00	0.005	0.005

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	256 256	4	64	1.0000	1.0000	3	0.00	0.001	0.004
0.50	256	4	64	1.0000	0.0100	2	0.00	0.022	0.034
0.50	256	4	64	1.0000	0.0100	3	0.00	0.001	0.001
0.50	256	4	64	1.0000	0.0001	2	0.67	0.001	0.011
0.50	256	4	64	1.0000	0.0001	3	1.00	0.010	0.032
0.50	256	4	64	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	4	64	0.0100	1.0000	3	0.00	0.040	0.788
0.50	256	4	64	0.0100	0.0100	2	1.00	0.010	0.015
0.50	256	4	64	0.0100	0.0100	3	1.00	0.010	0.044
0.50	256	4	64	0.0100	0.0001	2	1.00	0.013	0.018
0.50	256	4	64	0.0100	0.0001	3	1.00	0.011	0.018
0.50	256	4	64	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256	4	64	0.0001	1.0000	3	0.17	0.016	0.094
0.50	256	4	64	0.0001	0.0100	2	1.00	0.012	0.019
0.50	256	4	64	0.0001	0.0100	3	1.00	0.011	0.019
0.50	256	4	64	0.0001	0.0001	2	1.00	0.014	0.018
0.50	256	4	64	0.0001	0.0001	3	1.00	0.014	0.018
0.50	256	4	256	1.0000	1.0000	2	0.00	0.001	0.011
0.50	256	4	256	1.0000	1.0000	3	0.00	0.158	0.245
0.50	256	4	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	4	256	1.0000	0.0100	3	0.00	0.132	0.301
0.50	256	4	256	1.0000	0.0001	3	0.67	0.001	0.079
0.50	256 256	4	256	0.0100	0.0001	2	1.00	0.079	0.153 0.028
0.50	256	4	256 256	0.0100	1.0000	3	0.00	0.001	0.028
0.50	256	4	256	0.0100	0.0100	2	1.00	0.334	0.426
0.50	256	4	256	0.0100	0.0100	3	1.00	0.070	0.080
0.50	256	4	256	0.0100	0.0001	2	1.00	0.077	0.082
0.50	256	4	256	0.0100	0.0001	3	1.00	0.093	0.098
0.50	256	4	256	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256	4	256	0.0001	1.0000	3	0.00	0.435	0.642
0.50	256	4	256	0.0001	0.0100	2	1.00	0.061	0.096
0.50	256	4	256	0.0001	0.0100	3	1.00	0.061	0.093
0.50	256	4	256	0.0001	0.0001	2	1.00	0.076	0.216
0.50	256	4	256	0.0001	0.0001	3	1.00	0.075	0.121
0.50	256	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	16	1	1.0000	1.0000	3	0.00	0.011	0.017
0.50	256	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	16	1	1.0000	0.0100	3	0.33	0.009	0.012
0.50	256	16	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	16	1	1.0000	0.0001	3	0.17	0.004	0.012
0.50	256	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	16	1	0.0100	1.0000	3	0.00	0.009	0.015
0.50	256 256	16 16	1	0.0100	0.0100	3	0.00	0.001	0.001
0.50	256	16	1	0.0100	0.0100	2	0.00	0.003	0.001
0.50	256	16	1	0.0100	0.0001	3	0.67	0.001	0.001
0.50	256	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256	16	1	0.0001	1.0000	3	0.00	0.001	0.001
0.50	256	16	1	0.0001	0.0100	2	0.00	0.004	0.001
0.50	256	16	1	0.0001	0.0100	3	0.50	0.003	0.010
0.50	256	16	1	0.0001	0.0001	2	0.00	0.001	0.001
0.50	256	16	1	0.0001	0.0001	3	0.67	0.003	0.012
0.50	256	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	16	4	1.0000	1.0000	3	0.00	0.010	0.015
0.50	256	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	16	4	1.0000	0.0100	3	0.50	0.004	0.015
0.50	256	16	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	16	4	1.0000	0.0001	3	0.67	0.004	0.013
0.50	256	16	4	0.0100	1.0000	2	0.17	0.001	0.003
0.50	256	16	4	0.0100	1.0000	3	0.50	0.003	0.011
0.50	256	16	4	0.0100	0.0100	2	1.00	0.003	0.004
0.50	256 256	16 16	4	0.0100	0.0100	3	1.00 0.33	0.003	0.004
0.50	256	16	4	0.0100	0.0001	3	0.55	0.001	0.004
0.50	256	16	4	0.0100	1.00001	2	0.07	0.004	0.001
0.50	256	16	4	0.0001	1.0000	3	0.33	0.001	0.001
0.50	256	16	4	0.0001	0.0100	2	1.00	0.003	0.004
0.50	256	16	4	0.0001	0.0100	3	1.00	0.003	0.003
0.50	256	16	4	0.0001	0.0001	2	1.00	0.003	0.004
0.50	256	16	4	0.0001	0.0001	3	1.00	0.003	0.004
0.50	256	16	16	1.0000	1.0000	2	0.00	0.001	0.002
0.50	256	16	16	1.0000	1.0000	3	0.17	0.008	0.031
0.50	256	16	16	1.0000	0.0100	2	0.17	0.001	0.005
0.50	256	16	16	1.0000	0.0100	3	0.67	0.005	0.023

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	256	16	16	1.0000	0.0001	2	0.67	0.001	0.006
0.50	256	16	16	1.0000	0.0001	3	1.00	0.004	0.019
0.50	256	16	16	0.0100	1.0000	2	0.00	0.001	0.002
0.50	256	16	16	0.0100	1.0000	3	0.17	0.012	0.028
0.50	256	16	16	0.0100	0.0100	2	1.00	0.004	0.005
0.50	256 256	16	16	0.0100	0.0100	2	1.00 0.83	0.004	0.005
0.50	256	16 16	16 16	0.0100	0.0001	3	1.00	0.001	0.007
0.50	256	16	16	0.0001	1.0000	2	0.33	0.003	0.006
0.50	256	16	16	0.0001	1.0000	3	0.33	0.006	0.037
0.50	256	16	16	0.0001	0.0100	2	1.00	0.006	0.007
0.50	256	16	16	0.0001	0.0100	3	1.00	0.006	0.007
0.50	256	16	16	0.0001	0.0001	2	1.00	0.005	0.006
0.50	256	16	16	0.0001	0.0001	3	1.00	0.005	0.006
0.50	256	16	64	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256 256	16 16	64 64	1.0000	1.0000	3	0.00	0.026	0.034
0.50	256	16	64	1.0000	0.0100	3	0.17	0.001	0.008
0.50	256	16	64	1.0000	0.0001	2	0.83	0.003	0.037
0.50	256	16	64	1.0000	0.0001	3	1.00	0.010	0.031
0.50	256	16	64	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	16	64	0.0100	1.0000	3	0.00	0.032	0.055
0.50	256	16	64	0.0100	0.0100	2	0.67	0.001	0.015
0.50	256	16	64	0.0100	0.0100	3	1.00	0.010	0.016
0.50	256	16	64	0.0100	0.0001	2	0.83	0.001	0.014
0.50	256 256	16 16	64	0.0100	1.0000	2	1.00 0.17	0.012	0.014
0.50	256	16	64	0.0001	1.0000	3	0.17	0.001	0.011
0.50	256	16	64	0.0001	0.0100	2	1.00	0.011	0.088
0.50	256	16	64	0.0001	0.0100	3	1.00	0.012	0.013
0.50	256	16	64	0.0001	0.0001	2	1.00	0.013	0.016
0.50	256	16	64	0.0001	0.0001	3	1.00	0.013	0.016
0.50	256	16	256	1.0000	1.0000	2	0.00	0.001	0.013
0.50	256	16	256	1.0000	1.0000	3	0.00	0.164	0.908
0.50	256	16	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256 256	16 16	256 256	1.0000	0.0100	2	0.00	0.130	0.207
0.50	256	16	256	1.0000	0.0001	3	1.00	0.001	0.055
0.50	256	16	256	0.0100	1.0000	2	0.00	0.049	0.033
0.50	256	16	256	0.0100	1.0000	3	0.00	0.217	0.311
0.50	256	16	256	0.0100	0.0100	2	1.00	0.048	0.054
0.50	256	16	256	0.0100	0.0100	3	1.00	0.048	0.055
0.50	256	16	256	0.0100	0.0001	2	1.00	0.060	0.095
0.50	256	16	256	0.0100	0.0001	3	1.00	0.060	0.093
0.50	256	16	256	0.0001	1.0000	2	0.00	0.001	0.032
0.50	256 256	16 16	256 256	0.0001	1.0000 0.0100	3	0.00 1.00	0.354	0.594 0.134
0.50	256	16	256	0.0001	0.0100	3	1.00	0.071	0.134
0.50	256	16	256	0.0001	0.0001	2	1.00	0.077	0.125
0.50	256	16	256	0.0001	0.0001	3	1.00	0.077	0.126
0.50	256	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	64	1	1.0000	1.0000	3	0.17	0.008	0.010
0.50	256	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	64	1	1.0000	0.0100	3	0.33	0.003	0.011
0.50	256 256	64	1	1.0000	0.0001	3	0.00	0.001	0.001
0.50	256	64	1	0.0100	1.0000	2	0.17	0.003	0.012
0.50	256	64	1	0.0100	1.0000	3	0.00	0.001	0.001
0.50	256	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.50	256	64	1	0.0100	0.0100	3	0.17	0.004	0.010
0.50	256	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.50	256	64	1	0.0100	0.0001	3	0.50	0.003	0.010
0.50	256	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256	64	1	0.0001	1.0000	3	0.50	0.004	0.009
0.50	256 256	64	1	0.0001	0.0100	3	0.00	0.001	0.001
0.50	256	64	1	0.0001	0.0100	2	0.07	0.003	0.011
0.50	256	64	1	0.0001	0.0001	3	0.00	0.001	0.001
0.50	256	64	4	1.0000	1.0000	2	0.00	0.004	0.001
0.50	256	64	4	1.0000	1.0000	3	0.17	0.004	0.015
0.50	256	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	64	4	1.0000	0.0100	3	0.83	0.003	0.013
0.50	256	64	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	64	4	1.0000	0.0001	3	0.67	0.008	0.022
0.50	256 256	64	4	0.0100	1.0000	2	0.00	0.001	0.001
	/ 10	64	4	0.0100	1.0000	3	0.00	0.010	0.020

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	256	64	4	0.0100	0.0100	2	0.17	0.001	0.004
0.50	256	64	4	0.0100	0.0100	3	0.50	0.004	0.021
0.50	256	64	4	0.0100	0.0001	2	0.33	0.001	0.004
0.50	256 256	64	4	0.0100	0.0001 1.0000	3	0.83	0.004	0.021
0.50	256	64	4	0.0001	1.0000	3	0.50	0.001	0.004
0.50	256	64	4	0.0001	0.0100	2	1.00	0.003	0.004
0.50	256	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.50	256	64	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	256	64	4	0.0001	0.0001	3	1.00	0.003	0.006
0.50	256	64	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256 256	64 64	16 16	1.0000	1.0000 0.0100	3	0.17 0.17	0.004	0.029
0.50	256	64	16	1.0000	0.0100	3	1.00	0.001	0.003
0.50	256	64	16	1.0000	0.0001	2	0.33	0.001	0.006
0.50	256	64	16	1.0000	0.0001	3	0.67	0.005	0.028
0.50	256	64	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	64	16	0.0100	1.0000	3	0.00	0.016	0.024
0.50	256	64	16	0.0100	0.0100	2	1.00	0.005	0.006
0.50	256 256	64	16 16	0.0100	0.0100	3	1.00 0.83	0.004	0.006
0.50	256	64	16	0.0100	0.0001	3	1.00	0.001	0.007 0.012
0.50	256	64	16	0.0100	1.0000	2	0.17	0.003	0.012
0.50	256	64	16	0.0001	1.0000	3	0.50	0.006	0.042
0.50	256	64	16	0.0001	0.0100	2	1.00	0.004	0.007
0.50	256	64	16	0.0001	0.0100	3	1.00	0.005	0.007
0.50	256	64	16	0.0001	0.0001	2	0.83	0.001	0.007
0.50	256	64	16	0.0001	0.0001	3	1.00	0.005	0.008
0.50	256	64	64	1.0000	1.0000	3	0.00	0.001	0.001
0.50	256 256	64	64	1.0000	0.0100	2	0.17 0.17	0.006	0.062
0.50	256	64	64	1.0000	0.0100	3	0.17	0.001	0.056
0.50	256	64	64	1.0000	0.0001	2	0.83	0.001	0.016
0.50	256	64	64	1.0000	0.0001	3	1.00	0.012	0.016
0.50	256	64	64	0.0100	1.0000	2	0.00	0.001	0.006
0.50	256	64	64	0.0100	1.0000	3	0.00	0.047	0.544
0.50	256	64	64	0.0100	0.0100	2	1.00	0.010	0.011
0.50	256	64	64	0.0100	0.0100	3	1.00	0.010	0.011
0.50	256 256	64	64	0.0100	0.0001	3	1.00	0.011	0.013
0.50	256	64	64	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256	64	64	0.0001	1.0000	3	0.00	0.058	0.094
0.50	256	64	64	0.0001	0.0100	2	1.00	0.012	0.014
0.50	256	64	64	0.0001	0.0100	3	1.00	0.012	0.015
0.50	256	64	64	0.0001	0.0001	2	1.00	0.015	0.021
0.50	256	64	64	0.0001	0.0001	3	1.00	0.014	0.022
0.50	256 256	64 64	256 256	1.0000	1.0000	2	0.00	0.001 0.134	0.016 0.280
0.50	256	64	256	1.0000	0.0100	2	0.00	0.134	0.280
0.50	256	64	256	1.0000	0.0100	3	0.33	0.036	0.218
0.50	256	64	256	1.0000	0.0001	2	0.67	0.001	0.053
0.50	256	64	256	1.0000	0.0001	3	1.00	0.049	0.064
0.50	256	64	256	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	64	256	0.0100	1.0000	3	0.00	0.208	0.909
0.50	256 256	64	256 256	0.0100	0.0100	3	0.67 1.00	0.001	0.079
0.50	256	64	256	0.0100	0.0100	2	1.00	0.076	0.064
0.50	256	64	256	0.0100	0.0001	3	1.00	0.060	0.062
0.50	256	64	256	0.0001	1.0000	2	0.00	0.001	0.042
0.50	256	64	256	0.0001	1.0000	3	0.00	0.212	1.384
0.50	256	64	256	0.0001	0.0100	2	1.00	0.062	0.072
0.50	256	64	256	0.0001	0.0100	3	1.00	0.062	0.095
0.50	256 256	64	256	0.0001	0.0001	2	1.00	0.078	0.084
0.50	256	64 256	256	1.0000	0.0001 1.0000	3	0.00	0.078	0.084
0.50	256	256	1	1.0000	1.0000	3	0.00	0.001	0.001
0.50	256	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	256	1	1.0000	0.0100	3	0.33	0.003	0.024
0.50	256	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	256	1	1.0000	0.0001	3	0.00	0.009	0.014
0.50	256	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256 256	256 256	1	0.0100	1.0000 0.0100	3	0.33	0.003	0.013
0.50	256	256	1	0.0100	0.0100	3	0.50	0.001	0.001
0.50	256	256	1	0.0100	0.0001	2	0.00	0.003	0.001
0.50	256	256	1	0.0100	0.0001	3	0.17	0.003	0.030

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.50	256	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.50	256	256	1	0.0001	1.0000	3	0.33	0.004	0.014
0.50	256	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.50	256 256	256	1	0.0001	0.0100	3	0.50	0.003	0.013
0.50	256	256 256	1	0.0001	0.0001	3	0.00	0.001	0.001
0.50	256	256	4	1.0000	1.0000	2	0.00	0.003	0.010
0.50	256	256	4	1.0000	1.0000	3	0.33	0.003	0.013
0.50	256	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	256	4	1.0000	0.0100	3	0.33	0.003	0.018
0.50	256	256	4	1.0000	0.0001	2	0.00	0.001	0.001
0.50	256	256	4	1.0000	0.0001	3	0.67	0.003	0.012
0.50	256	256	4	0.0100	1.0000	2	0.17	0.001	0.003
0.50	256	256	4	0.0100	1.0000	3	0.33	0.003	0.013
0.50	256 256	256 256	4	0.0100	0.0100	3	0.50 1.00	0.001	0.004
0.50	256	256	4	0.0100	0.0001	2	0.17	0.003	0.003
0.50	256	256	4	0.0100	0.0001	3	0.50	0.003	0.012
0.50	256	256	4	0.0001	1.0000	2	0.67	0.001	0.003
0.50	256	256	4	0.0001	1.0000	3	0.83	0.003	0.017
0.50	256	256	4	0.0001	0.0100	2	0.67	0.001	0.003
0.50	256	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.50	256	256	4	0.0001	0.0001	2	0.83	0.001	0.004
0.50	256	256	4	0.0001	0.0001	3	1.00	0.003	0.004
0.50	256 256	256 256	16	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	256	16 16	1.0000	0.0100	3	0.50	0.003	0.017
0.50	256	256	16	1.0000	0.0100	3	0.67	0.001	0.001
0.50	256	256	16	1.0000	0.0001	2	0.07	0.004	0.015
0.50	256	256	16	1.0000	0.0001	3	1.00	0.005	0.010
0.50	256	256	16	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256	256	16	0.0100	1.0000	3	0.33	0.004	0.023
0.50	256	256	16	0.0100	0.0100	2	0.50	0.001	0.006
0.50	256	256	16	0.0100	0.0100	3	1.00	0.004	0.006
0.50	256	256	16	0.0100	0.0001	2	0.67	0.001	0.005
0.50	256 256	256 256	16 16	0.0100	0.0001	3	1.00 0.17	0.005	0.006
0.50	256	256	16	0.0001	1.0000	3	0.17	0.001	0.004
0.50	256	256	16	0.0001	0.0100	2	1.00	0.004	0.029
0.50	256	256	16	0.0001	0.0100	3	1.00	0.005	0.005
0.50	256	256	16	0.0001	0.0001	2	1.00	0.005	0.005
0.50	256	256	16	0.0001	0.0001	3	1.00	0.005	0.005
0.50	256	256	64	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	256	64	1.0000	1.0000	3	0.00	0.027	0.037
0.50	256	256	64	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	256	64	1.0000	0.0100	3	0.67	0.008	0.050
0.50	256 256	256 256	64 64	1.0000	0.0001	2	0.50 1.00	0.001	0.011
0.50	256	256	64	0.0100	1.0000	2	0.00	0.010	0.013
0.50	256	256	64	0.0100	1.0000	3	0.33	0.001	0.933
0.50	256	256	64	0.0100	0.0100	2	1.00	0.010	0.015
0.50	256	256	64	0.0100	0.0100	3	1.00	0.010	0.015
0.50	256	256	64	0.0100	0.0001	2	0.83	0.001	0.013
0.50	256	256	64	0.0100	0.0001	3	1.00	0.012	0.014
0.50	256	256	64	0.0001	1.0000	2	0.33	0.001	0.012
0.50	256 256	256	64	0.0001	1.0000	3	0.50	0.012	0.094
0.50	256	256 256	64 64	0.0001	0.0100	3	1.00	0.017 0.018	0.019
0.50	256	256	64	0.0001	0.0100	2	1.00	0.018	0.019
0.50	256	256	64	0.0001	0.0001	3	1.00	0.019	0.023
0.50	256	256	256	1.0000	1.0000	2	0.00	0.001	0.001
0.50	256	256	256	1.0000	1.0000	3	0.00	0.093	0.240
0.50	256	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.50	256	256	256	1.0000	0.0100	3	0.50	0.035	0.374
0.50	256	256	256	1.0000	0.0001	2	0.33	0.001	0.079
0.50	256	256	256	1.0000	0.0001	3	1.00	0.070	0.082
0.50	256	256	256	0.0100	1.0000	2	0.00	0.001	0.001
0.50	256 256	256 256	256 256	0.0100	1.0000 0.0100	3 2	0.00 1.00	0.214	0.496 0.082
0.50	256	256	256	0.0100	0.0100	3	1.00	0.051	0.082
0.50	256	256	256	0.0100	0.0001	2	1.00	0.049	0.080
0.50	256	256	256	0.0100	0.0001	3	1.00	0.084	0.102
0.50	256	256	256	0.0001	1.0000	2	0.00	0.001	0.001
0.50									
0.00	256	256	256	0.0001	1.0000	3	0.00	0.320	1.464
0.50	256 256 256	256 256 256	256 256 256	0.0001 0.0001 0.0001	0.0100 0.0100	2 3	1.00	0.320 0.062 0.061	0.078 0.070

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	$_{ m mint}$	maxt
0.50	256	256	256	0.0001	0.0001	2	1.00	0.076	0.124
0.50	256	256	256	0.0001	0.0001	3	1.00	0.072	0.127
0.67	1	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	1	1	1	1.0000	1.0000	3	0.50	0.006	0.013
0.67	1	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	1	1	1	1.0000	0.0100	3	0.00	0.007	0.007
0.67	1	1	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	1	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	1	1	1	0.0100	1.0000	3	0.50	0.006	0.011
0.67	1	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	1	1	1	0.0100	0.0100	3	0.00	0.007	0.011
0.67	1	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	1	1	1	0.0100	0.0001	3	0.00	0.006	0.010
0.67	1	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	1	1	1	0.0001	0.0100	2	0.00	0.000	0.001
0.67	1	1	1	0.0001	0.0100	3	0.00	0.006	0.010
0.67	1	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	1	1	1	0.0001	0.0001	3	0.00	0.005	0.011
0.67	1	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	1	1	4	1.0000	1.0000	3	0.00	0.014	0.042
0.67	1	1	4	1.0000	0.0100	3	0.33	0.001	0.004
0.67	1	1	4	1.0000	0.0100	2	0.00	0.003	0.010
0.67	1	1	4	1.0000	0.0001	3	0.67	0.001	0.001
0.67	1	1	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	1	1	4	0.0100	1.0000	3	0.00	0.015	0.019
0.67	1	1	4	0.0100	0.0100	2	1.00	0.003	0.004
0.67	1	1	4	0.0100	0.0100	3	1.00	0.003	0.004
0.67	1	1	4	0.0100	0.0001	2	0.67	0.001	0.004
0.67	1	1	4	0.0100	0.0001 1.0000	3 2	1.00 0.00	0.004	0.015
0.67	1	1	4	0.0001	1.0000	3	0.00	0.001	0.001
0.67	1	1	4	0.0001	0.0100	2	0.83	0.001	0.004
0.67	1	1	4	0.0001	0.0100	3	0.83	0.004	0.015
0.67	1	1	4	0.0001	0.0001	2	0.83	0.001	0.004
0.67	1	1	4	0.0001	0.0001	3	1.00	0.004	0.009
0.67	1	1	16 16	1.0000	1.0000	3	0.00	0.002	0.002
0.67	1	1	16	1.0000	0.0100	2	0.50	0.001	0.006
0.67	1	1	16	1.0000	0.0100	3	0.67	0.004	0.042
0.67	1	1	16	1.0000	0.0001	2	1.00	0.004	0.006
0.67	1	1	16	1.0000	0.0001	3	1.00	0.004	0.006
0.67	1	1	16	0.0100	1.0000	2	0.00	0.002	0.005
0.67	1	1	16 16	0.0100	1.0000 0.0100	3	0.00	0.028	0.730
0.67	1	1	16	0.0100	0.0100	3	0.83	0.001	0.000
0.67	1	1	16	0.0100	0.0001	2	1.00	0.004	0.007
0.67	1	1	16	0.0100	0.0001	3	1.00	0.004	0.006
0.67	1	1	16	0.0001	1.0000	2	0.00	0.003	0.003
0.67	1	1	16	0.0001	1.0000	3	0.00	0.041	0.047
0.67	1	1	16	0.0001	0.0100	2	1.00	0.006	0.006
0.67	1	1	16 16	0.0001	0.0100	3	1.00	0.006	0.006
0.67	1	1	16	0.0001	0.0001	3	1.00	0.006	0.007
0.67	1	1	64	1.0000	1.0000	2	0.00	0.004	0.004
0.67	1	1	64	1.0000	1.0000	3	0.00	0.062	0.064
0.67	1	1	64	1.0000	0.0100	2	0.00	0.004	0.006
0.67	1	1	64	1.0000	0.0100	3	0.00	0.083	0.090
0.67	1	1	64	1.0000	0.0001	2	1.00	0.009	0.014
0.67	1	1	64	0.0100	1.0000	3	1.00 0.00	0.009	0.014
0.67	1	1	64	0.0100	1.0000	3	0.00	0.004	0.006
0.67	1	1	64	0.0100	0.0100	2	1.00	0.010	0.015
0.67	1	1	64	0.0100	0.0100	3	1.00	0.010	0.015
0.67	1	1	64	0.0100	0.0001	2	1.00	0.014	0.018
0.67	1	1	64	0.0100	0.0001	3	1.00	0.011	0.018
0.67	1	1	64 64	0.0001	1.0000	3	0.00	0.006	0.008
0.67	1	1	64	0.0001	0.0100	2	1.00	0.083	0.123
0.67	1	1	64	0.0001	0.0100	3	1.00	0.011	0.012
0.67	1	1	64	0.0001	0.0001	2	1.00	0.014	0.015
0.67	1	1	64	0.0001	0.0001	3	1.00	0.014	0.015
0.67	1	1	256	1.0000	1.0000	2	0.00	0.011	0.017
0.67	1	1	256	1.0000	1.0000	3	0.00	0.191	1.070

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	1	1	256	1.0000	0.0100	2	0.00	0.016	0.020
0.67	1	1	256	1.0000	0.0100	3	0.00	0.282	0.331
0.67	1	1	256	1.0000	0.0001	2	1.00	0.049	0.075
0.67	1	1	256	1.0000	0.0001	3	1.00	0.047	0.074
0.67	1	1	256	0.0100	1.0000	2	0.00	0.018	0.029
0.67	1	1	256	0.0100	1.0000	3	0.00	0.318	0.949
0.67	1	1	256	0.0100	0.0100	2	0.00	0.027	0.038
0.67	1	1	256	0.0100	0.0100	3	0.00	0.417	0.438
0.67	1	1	256 256	0.0100	0.0001	3	1.00	0.059	0.075 0.090
0.67	1	1	256	0.0001	1.0000	2	0.00	0.000	0.090
0.67	1	1	256	0.0001	1.0000	3	0.00	0.432	1.045
0.67	1	1	256	0.0001	0.0100	2	0.17	0.033	0.059
0.67	1	1	256	0.0001	0.0100	3	0.17	0.058	1.002
0.67	1	1	256	0.0001	0.0001	2	1.00	0.078	0.127
0.67	1	1	256	0.0001	0.0001	3	1.00	0.078	0.126
0.67	1	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	1	4	1	1.0000	1.0000	3	0.00	0.006	0.011
0.67	1	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	1	4	1	1.0000	0.0100	3	0.00	0.006	0.009
0.67	1	4	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	1	4	1	0.0100	1.0000	2	0.00	0.000	0.007
0.67	1	4	1	0.0100	1.0000	3	0.17	0.005	0.010
0.67	1	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	1	4	1	0.0100	0.0100	3	0.00	0.006	0.047
0.67	1	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	1	4	1	0.0100	0.0001	3	0.00	0.005	0.008
0.67	1	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	1	4	1	0.0001	1.0000	3	0.00	0.005	0.023
0.67	1	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	1	4	1	0.0001	0.0100	2	0.00	0.006	0.008
0.67	1	4	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	1	4	4	1.0000	1.0000	2	0.00	0.000	0.007
0.67	1	4	4	1.0000	1.0000	3	0.00	0.006	0.012
0.67	1	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	1	4	4	1.0000	0.0100	3	0.33	0.004	0.014
0.67	1	4	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	1	4	4	1.0000	0.0001	3	0.17	0.004	0.014
0.67	1	4	4	0.0100	1.0000	2	0.17	0.001	0.004
0.67	1	4	4	0.0100	1.0000	3	0.17	0.004	0.013
0.67	1	4	4	0.0100	0.0100	2	0.67	0.001	0.004
0.67	1	4	4	0.0100	0.0100	2	0.83	0.003	0.006
0.67	1	4	4	0.0100	0.0001	3	0.83	0.001	0.004
0.67	1	4	4	0.0001	1.0000	2	0.03	0.003	0.004
0.67	1	4	4	0.0001	1.0000	3	0.17	0.003	0.011
0.67	1	4	4	0.0001	0.0100	2	0.50	0.001	0.004
0.67	1	4	4	0.0001	0.0100	3	0.67	0.004	0.014
0.67	1	4	4	0.0001	0.0001	2	0.50	0.001	0.004
0.67	1	4	4	0.0001	0.0001	3	0.83	0.003	0.008
0.67	1	4	16	1.0000	1.0000	2	0.00	0.001	0.002
0.67	1	4	16	1.0000	1.0000	3	0.00	0.027	0.032
0.67	1	4	16	1.0000	0.0100	3	0.17	0.001	0.005
0.67	1	4	16 16	1.0000	0.0100	2	0.33	0.005	0.029
0.67	1	4	16	1.0000	0.0001	3	1.00	0.001	0.004
0.67	1	4	16	0.0100	1.0000	2	0.00	0.004	0.003
0.67	1	4	16	0.0100	1.0000	3	0.00	0.025	0.002
0.67	1	4	16	0.0100	0.0100	2	0.83	0.001	0.004
0.67	1	4	16	0.0100	0.0100	3	1.00	0.004	0.012
0.67	1	4	16	0.0100	0.0001	2	1.00	0.005	0.005
0.67	1	4	16	0.0100	0.0001	3	1.00	0.004	0.005
0.67	1	4	16	0.0001	1.0000	2	0.00	0.001	0.002
0.67	1	4	16	0.0001	1.0000	3	0.00	0.032	0.759
0.67	1	4	16	0.0001	0.0100	2	1.00	0.004	0.006
0.67	1	4	16	0.0001	0.0100	3	1.00	0.004	0.006
0.67	1	4	16 16	0.0001	0.0001	3	1.00	0.005	0.007 0.007
0.67	1	4	64	1.0000	1.0000	2	0.00	0.003	0.007
0.67	1	4	64	1.0000	1.0000	3	0.00	0.062	0.066
0.67	1	4	64	1.0000	0.0100	2	0.00	0.002	0.006
0.67	1	4	64	1.0000	0.0100	3	0.00	0.081	0.090
0.67	1	4	64	1.0000	0.0001	2	1.00	0.014	0.014
0.67	1	4	64	1.0000	0.0001	3	1.00	0.014	0.014
	•		٧.				00		

0.67	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	0.67								0.004	0.006
0.67										
0.67										
0.67										
0.67										
0.67										
0.67	0.67	1	4	64	0.0001	1.0000	3	0.00	0.084	0.101
0.67										
0.67										
0.67										
0.67										
0.67										
0.67	0.67	1	4	256	1.0000	0.0100		0.00	0.001	0.026
0.67	0.67									
0.67										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.67										
0.67										
0.67	0.67			256	0.0100	0.0001	2		0.063	0.065
0.67										
0.67										
0.67										
0.67										
0.67										
0.67	0.67	1	4	256	0.0001	0.0001	3	1.00	0.079	0.084
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		1	16	1	0.0001			0.00	0.001	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			16			0.0001	2	0.17	0.001	0.003
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.67				1.0000	1.0000	2			0.002
0.67 1 16 16 1.0000 0.0100 3 0.33 0.005 0.022 0.67 1 16 16 1.0000 0.0001 2 0.33 0.001 0.004 0.67 1 16 16 1.0000 0.0001 3 1.00 0.004 0.013 0.67 1 16 16 0.0100 1.0000 2 0.00 0.013 0.023 0.67 1 16 16 0.0100 1.0000 3 0.00 0.013 0.023 0.67 1 16 16 0.0100 0.0100 2 0.67 0.001 0.005										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.67 1 16 16 1.0000 0.0001 3 1.00 0.004 0.013 0.67 1 16 16 0.0100 1.0000 2 0.00 0.001 0.001 0.67 1 16 16 0.0100 1.0000 3 0.00 0.013 0.023 0.67 1 16 16 0.0100 0.0100 2 0.67 0.001 0.005										
0.67 1 16 16 0.0100 1.0000 2 0.00 0.001 0.001 0.67 1 16 16 0.0100 1.0000 3 0.00 0.013 0.023 0.67 1 16 16 0.0100 0.0100 2 0.67 0.001 0.005										
0.67 1 16 16 0.0100 1.0000 3 0.00 0.013 0.023 0.67 1 16 16 0.0100 0.0100 2 0.67 0.001 0.005										
0.67 1 16 16 0.0100 0.0100 2 0.67 0.001 0.005										
0.67 1 16 16 0.0100 0.0100 3 1.00 0.004 0.006										
5.5. 1 10 10 5.5100 5.5100 5 1.00 6.004 6.000	0.67	1	16	16	0.0100	0.0100	3	1.00	0.004	0.006

	0.001	
		0.005
	0.004	0.005
	0.001	0.005 0.025
	0.004	0.023
	0.004	0.005
	0.005	0.006
	0.005	0.006
	0.001	0.004
	0.042	0.065
	0.001	0.000
	0.001	0.010
0.67 1 16 64 1.0000 0.0001 3 1.00	0.010	0.011
	0.004	0.006
	0.063	0.077
	0.009	0.011
	0.009	0.011
	0.012	0.018
	0.001	0.006
0.67 1 16 64 0.0001 1.0000 3 0.00	0.083	0.092
	0.011	0.014
	0.011	0.013
	0.015	0.015 0.015
	0.014	0.015
	0.011	0.781
	0.001	0.016
	0.245	0.421
	0.046	0.068
	0.045	0.068
	0.017	0.025 0.705
	0.052	0.060
	0.052	0.057
0.67 1 16 256 0.0100 0.0001 2 1.00	0.081	0.098
	0.086	0.098
	0.025	0.040
	0.514	1.657
	0.060	0.061
	0.039	0.128
	0.109	0.128
	0.001	0.001
	0.006	0.007
	0.001	0.001
	0.007	0.015
	0.001	0.001
	0.003	0.007
	0.006	0.007
	0.001	0.001
	0.006	0.037
	0.001	0.001
	0.006	1.057 0.001
	0.001	0.001
	0.001	0.001
0.67 1 64 1 0.0001 0.0100 3 0.00	0.006	0.015
	0.001	0.001
	0.005	0.006
	0.001	0.001
	0.006	0.043
	0.001	0.001
	0.001	0.003
0.67 1 64 4 1.0000 0.0001 3 0.17	0.003	0.016
	0.001	0.001
	0.006	0.010
	0.001	0.003 0.014
	0.003	0.014
	0.001	0.004
	0.001	0.003
0.67 1 64 4 0.0001 1.0000 3 0.17	0.003	0.014

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	1	64	4	0.0001	0.0100	2	0.50	0.001	0.003
0.67	1	64	4	0.0001	0.0100	3	0.67	0.003	0.006
0.67	1	64	4	0.0001	0.0001	2	1.00	0.003	0.004
0.67	1	64	16	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.003	0.004
0.67	1	64	16	1.0000	1.0000	3	0.00	0.007	0.012
0.67	1	64	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	1	64	16	1.0000	0.0100	3	0.17	0.006	0.027
0.67	1	64	16	1.0000	0.0001	2	0.67	0.001	0.006
0.67	1	64	16 16	1.0000 0.0100	0.0001 1.0000	3	0.83	0.006	0.023
0.67	1	64	16	0.0100	1.0000	3	0.00	0.001	0.042
0.67	1	64	16	0.0100	0.0100	2	0.83	0.001	0.006
0.67	1	64	16	0.0100	0.0100	3	1.00	0.005	0.006
0.67	1	64	16	0.0100	0.0001	2	0.83	0.001	0.007
0.67	1	64	16 16	0.0100	0.0001	3	0.83	0.006	0.033
0.67	1	64	16	0.0001	1.0000	3	0.00	0.001	0.001
0.67	1	64	16	0.0001	0.0100	2	1.00	0.006	0.007
0.67	1	64	16	0.0001	0.0100	3	1.00	0.006	0.007
0.67	1	64	16	0.0001	0.0001	2	1.00	0.006	0.007
0.67	1	64	16	0.0001	0.0001	3	1.00	0.006	0.007
0.67	1	64	64	1.0000	1.0000	3	0.00	0.001	0.004
0.67	1	64	64	1.0000	0.0100	2	0.00	0.046	0.001
0.67	1	64	64	1.0000	0.0100	3	0.00	0.022	0.059
0.67	1	64	64	1.0000	0.0001	2	0.50	0.001	0.016
0.67	1	64	64	1.0000	0.0001	3	1.00	0.010	0.017
0.67	1	64	64	0.0100	1.0000	3	0.00	0.001	0.001
0.67	1	64	64	0.0100	0.0100	2	1.00	0.023	0.036
0.67	1	64	64	0.0100	0.0100	3	1.00	0.010	0.015
0.67	1	64	64	0.0100	0.0001	2	1.00	0.011	0.018
0.67	1	64	64	0.0100	0.0001	3	1.00	0.011	0.018
0.67	1	64	64	0.0001	1.0000	2	0.00	0.001	0.001
0.67	1	64	64	0.0001	1.0000 0.0100	3	0.00 1.00	0.070	0.105 0.019
0.67	1	64	64	0.0001	0.0100	3	1.00	0.017	0.019
0.67	1	64	64	0.0001	0.0001	2	1.00	0.021	0.023
0.67	1	64	64	0.0001	0.0001	3	1.00	0.021	0.023
0.67	1	64	256	1.0000	1.0000	2	0.00	0.010	0.015
0.67	1	64	256 256	1.0000	1.0000	3	0.00	0.183	0.891
0.67	1	64	256	1.0000	0.0100	3	0.00	0.001	0.018
0.67	1	64	256	1.0000	0.0001	2	0.67	0.001	0.050
0.67	1	64	256	1.0000	0.0001	3	1.00	0.046	0.076
0.67	1	64	256	0.0100	1.0000	2	0.00	0.001	0.018
0.67	1	64	256	0.0100	1.0000	3	0.00	0.268	0.972
0.67	1	64	256 256	0.0100	0.0100	2	1.00	0.048	0.053
0.67	1	64	256	0.0100	0.0100	2	1.00	0.048	0.031
0.67	1	64	256	0.0100	0.0001	3	1.00	0.061	0.066
0.67	1	64	256	0.0001	1.0000	2	0.00	0.025	0.027
0.67	1	64	256	0.0001	1.0000	3	0.00	0.435	0.463
0.67	1	64	256 256	0.0001	0.0100	3	1.00	0.065	0.098
0.67	1	64	256	0.0001	0.0001	2	1.00	0.064	0.398
0.67	1	64	256	0.0001	0.0001	3	1.00	0.079	0.092
0.67	1	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	1	256	1	1.0000	1.0000	3	0.00	0.006	0.006
0.67	1	256 256	1	1.0000	0.0100	3	0.00	0.001	0.001
0.67	1	256	1	1.0000	0.0100	2	0.17	0.003	0.006
0.67	1	256	1	1.0000	0.0001	3	0.17	0.003	0.006
0.67	1	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	1	256	1	0.0100	1.0000	3	0.00	0.005	0.006
0.67	1	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	1	256 256	1	0.0100	0.0100	3	0.00	0.005	0.008
0.67	1	256	1	0.0100	0.0001	3	0.00	0.001	0.001
0.67	1	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	1	256	1	0.0001	1.0000	3	0.00	0.005	0.006
0.67	1	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	1	256	1	0.0001	0.0100	3	0.00	0.006	0.006
0.67	1	256 256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.07	1	230	1	0.0001	0.0001	3	0.17	0.003	0.000

0.67 1 256 4 1.0000 1.0000 2 0.00 0.00 0.67 1 256 4 1.0000 1.0000 3 0.00 0.00 0.67 1 256 4 1.0000 0.0100 2 0.17 0.00 0.67 1 256 4 1.0000 0.0100 2 0.17 0.00 0.67 1 256 4 1.0000 0.0100 2 0.17 0.00	5 0.007
0.67 1 256 4 1.0000 0.0100 2 0.17 0.00	
0.67 1 256 4 1.0000 0.0100 3 0.17 0.000 0.67 1 256 4 1.0000 0.0001 2 0.17 0.00	
0.67 1 256 4 1.0000 0.0001 2 0.17 0.00	
0.67 1 256 4 0.0100 1.0000 2 0.00 0.00	
0.67 1 256 4 0.0100 1.0000 3 0.17 0.00	
0.67 1 256 4 0.0100 0.0100 2 0.17 0.00	
0.67 1 256 4 0.0100 0.0100 3 0.50 0.000	3 0.007
0.67 1 256 4 0.0100 0.0001 2 0.33 0.00	
0.67 1 256 4 0.0100 0.0001 3 0.50 0.000	
0.67 1 256 4 0.0001 1.0000 2 0.33 0.00	
0.67 1 256 4 0.0001 1.0000 3 0.50 0.00 0.67 1 256 4 0.0001 0.0100 2 0.83 0.00	
0.67 1 256 4 0.0001 0.0100 2 0.83 0.00 0.67 1 256 4 0.0001 0.0100 3 1.00 0.00	
0.67 1 256 4 0.0001 0.0001 2 0.67 0.00	
0.67 1 256 4 0.0001 0.0001 3 1.00 0.000	
0.67 1 256 16 1.0000 1.0000 2 0.00 0.00	
0.67 1 256 16 1.0000 1.0000 3 0.00 0.00	7 0.010
0.67 1 256 16 1.0000 0.0100 2 0.00 0.00	0.001
0.67 1 256 16 1.0000 0.0100 3 0.00 0.000	
0.67 1 256 16 1.0000 0.0001 2 0.50 0.00	
0.67 1 256 16 1.0000 0.0001 3 0.83 0.00	
0.67 1 256 16 0.0100 1.0000 2 0.00 0.00 0.67 1 256 16 0.0100 1.0000 3 0.00 0.00	
0.67	
0.67 1 256 16 0.0100 0.0100 2 0.67 0.00	
0.67 1 256 16 0.0100 0.0001 2 0.83 0.00	
0.67 1 256 16 0.0100 0.0001 3 1.00 0.00	
0.67 1 256 16 0.0001 1.0000 2 0.50 0.00	1 0.006
0.67 1 256 16 0.0001 1.0000 3 0.50 0.000	5 0.035
0.67 1 256 16 0.0001 0.0100 2 1.00 0.000	
0.67 1 256 16 0.0001 0.0100 3 1.00 0.000	
0.67 1 256 16 0.0001 0.0001 2 1.00 0.000	
0.67 1 256 16 0.0001 0.0001 3 1.00 0.000 0.67 1 256 64 1.0000 1.0000 2 0.00 0.00	
0.67 1 256 64 1.0000 1.0000 2 0.00 0.00 0.67 1 256 64 1.0000 1.0000 3 0.00 0.01	
0.67 1 256 64 1.0000 1.0000 3 0.00 0.01	
0.67 1 256 64 1.0000 0.0100 3 0.17 0.013	
0.67 1 256 64 1.0000 0.0001 2 0.67 0.00	
0.67 1 256 64 1.0000 0.0001 3 1.00 0.01	1 0.017
0.67 1 256 64 0.0100 1.0000 2 0.00 0.00	
0.67 1 256 64 0.0100 1.0000 3 0.00 0.01	
0.67 1 256 64 0.0100 0.0100 2 1.00 0.010	
0.67 1 256 64 0.0100 0.0100 3 1.00 0.010	
0.67 1 256 64 0.0100 0.0001 2 1.00 0.012 0.67 1 256 64 0.0100 0.0001 3 1.00 0.01	
0.67 1 256 64 0.0001 1.0000 2 0.17 0.00	
0.67 1 256 64 0.0001 1.0000 2 0.17 0.00	
0.67 1 256 64 0.0001 0.0100 2 1.00 0.011	
0.67 1 256 64 0.0001 0.0100 3 1.00 0.011	
0.67 1 256 64 0.0001 0.0001 2 1.00 0.01	
0.67 1 256 64 0.0001 0.0001 3 1.00 0.01	
0.67 1 256 256 1.0000 1.0000 2 0.00 0.00	
0.67 1 256 256 1.0000 1.0000 3 0.00 0.08	
0.67 1 256 256 1.0000 0.0100 2 0.00 0.00 0.67 1 256 256 1.0000 0.0100 3 0.00 0.07	
0.67	
0.67 1 256 256 1.0000 0.0001 2 0.67 0.00	
0.67 1 256 256 0.0100 1.0000 2 0.00 0.00	
0.67 1 256 256 0.0100 1.0000 3 0.00 0.13°	
0.67 1 256 256 0.0100 0.0100 2 0.83 0.00	1 0.064
0.67 1 256 256 0.0100 0.0100 3 1.00 0.06	
0.67 1 256 256 0.0100 0.0001 2 1.00 0.060	
0.67 1 256 256 0.0100 0.0001 3 1.00 0.06	
0.67 1 256 256 0.0001 1.0000 2 0.00 0.00	
0.67 1 256 256 0.0001 1.0000 3 0.00 0.34 0.67 1 256 256 0.0001 0.0100 2 1.00 0.09	
0.67 1 256 256 0.0001 0.0100 2 1.00 0.09 0.67 1 256 256 0.0001 0.0100 3 1.00 0.09	
0.67 1 256 256 0.0001 0.0001 2 1.00 0.07	
0.67 1 256 256 0.0001 0.0001 3 1.00 0.07	
0.67 4 1 1 1.0000 1.0000 2 0.00 0.00	
0.67 4 1 1 1.0000 1.0000 3 0.00 0.000	
0.67 4 1 1 1.0000 0.0100 2 0.00 0.00	
0.67 4 1 1 1.0000 0.0100 3 0.00 0.00	7 0.010

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	4	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	4	1	1	1.0000	0.0001	3	0.00	0.007	0.007
0.67	4	1	1	0.0100	1.0000	3	0.00	0.001	0.001
0.67	4	1	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	4	1	1	0.0100	0.0100	3	0.00	0.007	0.007
0.67	4	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	4	1 1	1	0.0100	0.0001 1.0000	3	0.00	0.007	0.031
0.67	4	1	1	0.0001	1.0000	3	0.00	0.005	0.013
0.67	4	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	4	1	1	0.0001	0.0100	3	0.00	0.007	0.010
0.67	4	1	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	4	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	1	4	1.0000	1.0000	3	0.00	0.007	0.010
0.67	4	1	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	1	4	1.0000	0.0100	3	0.17	0.007	0.016
0.67	4	1	4	1.0000	0.0001	3	0.50	0.004	0.024
0.67	4	1	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	4	1	4	0.0100	1.0000 0.0100	3	0.00	0.006	0.013
0.67	4	1	4	0.0100	0.0100	3	0.50	0.001	0.004
0.67	4	1	4	0.0100	0.0001	2	1.00	0.003	0.004
0.67	4	1	4	0.0100	0.0001	3	1.00	0.003	0.004
0.67	4	1	4	0.0001	1.0000	3	0.17 0.17	0.001	0.004
0.67	4	1	4	0.0001	0.0100	2	0.17	0.004	0.004
0.67	4	1	4	0.0001	0.0100	3	0.83	0.004	0.022
0.67	4	1	4	0.0001	0.0001	2	0.50	0.001	0.005
0.67	4	1	16	0.0001 1.0000	0.0001 1.0000	3	0.67	0.004	0.012
0.67	4	1	16	1.0000	1.0000	3	0.00	0.001	0.002
0.67	4	1	16	1.0000	0.0100	2	0.17	0.001	0.005
0.67	4	1	16	1.0000	0.0100	3	0.33	0.005	0.030
0.67	4	1	16 16	1.0000	0.0001	2	0.50 1.00	0.001	0.005
0.67	4	1	16	0.0100	1.0000	2	0.00	0.004	0.003
0.67	4	1	16	0.0100	1.0000	3	0.00	0.027	0.035
0.67	4	1	16	0.0100	0.0100	2	0.83	0.001	0.006
0.67	4	1	16 16	0.0100	0.0100	3	1.00	0.005	0.011
0.67	4	1	16	0.0100	0.0001	3	1.00	0.006	0.006
0.67	4	1	16	0.0001	1.0000	2	0.00	0.001	0.003
0.67	4	1	16	0.0001	1.0000	3	0.00	0.040	0.046
0.67	4	1	16 16	0.0001	0.0100	3	1.00	0.004	0.006
0.67	4	1	16	0.0001	0.0001	2	1.00	0.005	0.006
0.67	4	1	16	0.0001	0.0001	3	1.00	0.005	0.006
0.67	4	1	64	1.0000	1.0000	3	0.00	0.003	0.005
0.67	4	1	64	1.0000	1.0000 0.0100	2	0.00	0.047	0.667
0.67	4	1	64	1.0000	0.0100	3	0.00	0.059	0.066
0.67	4	1	64	1.0000	0.0001	2	1.00	0.009	0.011
0.67	4	1	64 64	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.009	0.011
0.67	4	1	64	0.0100	1.0000	3	0.00	0.064	0.066
0.67	4	1	64	0.0100	0.0100	2	1.00	0.009	0.012
0.67	4	1	64	0.0100	0.0100	3	1.00	0.010	0.011
0.67	4	1	64	0.0100	0.0001	3	1.00	0.011	0.015
0.67	4	1	64	0.0001	1.0000	2	0.00	0.006	0.007
0.67	4	1	64	0.0001	1.0000	3	0.00	0.089	0.094
0.67	4	1	64	0.0001	0.0100	2	1.00	0.011	0.013
0.67	4	1	64 64	0.0001	0.0100	3	1.00	0.011	0.013 0.015
0.67	4	1	64	0.0001	0.0001	3	1.00	0.013	0.015
0.67	4	1	256	1.0000	1.0000	2	0.00	0.011	0.013
0.67	4	1	256 256	1.0000	1.0000 0.0100	3	0.00	0.182	0.232 0.026
0.67	4	1	256	1.0000	0.0100	3	0.00	0.017	0.026
0.67	4	1	256	1.0000	0.0001	2	1.00	0.044	0.063
0.67	4	1	256	1.0000	0.0001	3	1.00	0.044	0.066
0.67	4	1	256 256	0.0100	1.0000	2	0.00	0.017	0.027 0.427
0.07	4	1	230	0.0100	1.0000	3	0.00	0.300	0.427

0.67	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	0.67	4		256	0.0100	0.0100	2	0.83	0.001	0.076
0.67	0.67	4	1	256	0.0100	0.0100	3	0.83	0.052	0.919
0.67			1							
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67		4	4							
0.67	0.67	4	4	1	1.0000	1.0000	3	0.00	0.006	0.010
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67		4	4	1						
0.67	0.67	4	4	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67										
0.67	0.67	4	4	4	1.0000	1.0000	3	0.00	0.006	0.011
0.67	0.67	4	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67										
0.67										
0.67										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.67										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.67 4 4 4 0.0001 1.0000 2 0.33 0.001 0.004 0.67 4 4 4 0.0001 1.0000 3 0.33 0.003 0.698 0.67 4 4 4 0.0001 0.0100 2 0.67 0.001 0.004 0.67 4 4 4 0.0001 0.0100 3 1.00 0.003 0.013 0.67 4 4 4 0.0001 0.0001 2 0.67 0.001 0.004 0.67 4 4 4 0.0001 0.0001 3 0.67 0.003 0.015 0.67 4 4 16 1.0000 1.0000 3 0.00 0.001 0.001 0.67 4 4 16 1.0000 0.0100 3 0.00 0.001 0.001 0.67 4 4 16 1.0000 0.0100 3 0.50				4						
0.67 4 4 4 0.0001 1.0000 3 0.33 0.003 0.698 0.67 4 4 4 0.0001 0.0100 2 0.67 0.001 0.004 0.67 4 4 4 0.0001 0.0001 3 1.00 0.003 0.013 0.67 4 4 4 0.0001 0.0001 2 0.67 0.001 0.001 0.67 4 4 4 0.0001 0.0001 3 0.67 0.001 0.001 0.67 4 4 4 16 1.0000 1.0000 3 0.00 0.001 0.001 0.67 4 4 16 1.0000 0.0100 2 0.00 0.001 0.001 0.67 4 4 16 1.0000 0.0100 3 0.50 0.005 0.032 0.67 4 4 16 1.0000 0.0001 3	0.67	4	4	4	0.0100	0.0001	3	0.67	0.003	0.015
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.67 4 4 4 0.0001 0.0100 3 1.00 0.003 0.013 0.67 4 4 4 0.0001 0.0001 2 0.67 0.001 0.004 0.67 4 4 4 0.0001 0.0001 3 0.67 0.003 0.015 0.67 4 4 16 1.0000 1.0000 3 0.00 0.001 0.001 0.67 4 4 16 1.0000 1.0000 3 0.00 0.001 0.001 0.67 4 4 16 1.0000 0.0100 2 0.00 0.001 0.001 0.67 4 4 16 1.0000 0.0001 3 0.50 0.005 0.032 0.67 4 4 16 1.0000 0.0001 3 0.50 0.001 0.004 0.67 4 4 16 0.0100 1.0000 3 0.00 <td></td>										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		4								
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0.67	4	4	16	1.0000	0.0100	2	0.00	0.001	0.001
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$				16	0.0100		2	1.00	0.004	
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		4								
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0.67				1.0000	0.0100	2			0.004
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{cccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.67 4 4 64 0.0100 0.0100 2 1.00 0.010 0.015 0.67 4 4 64 0.0100 0.0100 3 1.00 0.009 0.014 0.67 4 4 64 0.0100 0.0001 2 1.00 0.017 0.018										
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$										
0.67 4 4 64 0.0100 0.0001 2 1.00 0.017 0.018										
$\begin{bmatrix} 0.07 \end{bmatrix} + \begin{bmatrix} 4 \end{bmatrix} + \begin{bmatrix} 4 \end{bmatrix} 0 + \begin{bmatrix} 0.0100 \end{bmatrix} 0.0101 \end{bmatrix} 0.0011 = 3 + \begin{bmatrix} 1.00 \end{bmatrix} 0.017 + \begin{bmatrix} 0.018 \end{bmatrix}$	0.67	4	4	64	0.0100	0.0001	3	1.00	0.017	0.018

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	4	4	64	0.0001	1.0000	2	0.00	0.008	0.009
0.67	4	4	64	0.0001	1.0000	3	0.00	0.118	0.130
0.67	4	4	64	0.0001	0.0100	2	1.00	0.017	0.018
0.67	4	4	64 64	0.0001	0.0100	3	1.00	0.017	0.019
0.67	4	4	64	0.0001	0.0001	3	1.00	0.020	0.023
0.67	4	4	256	1.0000	1.0000	2	0.00	0.011	0.017
0.67	4	4	256	1.0000	1.0000	3	0.00	0.209	1.308
0.67	4	4	256	1.0000	0.0100	2	0.00	0.001	0.027
0.67	4	4	256	1.0000	0.0100	3	0.00	0.262	0.345
0.67	4	4	256 256	1.0000	0.0001	2	1.00	0.050	0.075 0.080
0.67	4	4	256	0.0100	1.0000	2	0.00	0.039	0.030
0.67	4	4	256	0.0100	1.0000	3	0.00	0.281	1.048
0.67	4	4	256	0.0100	0.0100	2	1.00	0.049	0.066
0.67	4	4	256	0.0100	0.0100	3	1.00	0.049	0.071
0.67	4	4	256	0.0100	0.0001	2	1.00	0.064	0.067
0.67	4	4	256 256	0.0100	0.0001 1.0000	3	1.00 0.00	0.065	0.066
0.67	4	4	256	0.0001	1.0000	3	0.00	0.027	1.397
0.67	4	4	256	0.0001	0.0100	2	1.00	0.086	0.099
0.67	4	4	256	0.0001	0.0100	3	1.00	0.067	0.100
0.67	4	4	256	0.0001	0.0001	2	1.00	0.075	0.102
0.67	4	4	256	0.0001	0.0001	3	1.00	0.076	0.108
0.67	4	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	16 16	1	1.0000	1.0000 0.0100	3	0.00	0.005	0.007
0.67	4	16	1	1.0000	0.0100	3	0.00	0.001	0.001
0.67	4	16	1	1.0000	0.0001	2	0.00	0.003	0.001
0.67	4	16	1	1.0000	0.0001	3	0.00	0.005	0.007
0.67	4	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	4	16	1	0.0100	1.0000	3	0.17	0.003	0.007
0.67	4	16 16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	4	16	1	0.0100	0.0001	2	0.00	0.000	0.042
0.67	4	16	1	0.0100	0.0001	3	0.00	0.005	0.007
0.67	4	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	4	16	1	0.0001	1.0000	3	0.00	0.005	0.009
0.67	4	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	4	16	1	0.0001	0.0100	3	0.00	0.006	0.010
0.67	4	16 16	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	4	16	4	1.0000	1.0000	2	0.00	0.000	0.021
0.67	4	16	4	1.0000	1.0000	3	0.00	0.006	0.012
0.67	4	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	16	4	1.0000	0.0100	3	0.00	0.005	0.018
0.67	4	16	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	4	16 16	4	1.0000 0.0100	0.0001	2	0.17	0.004	0.017
0.67	4	16	4	0.0100	1.0000	3	0.17	0.001	0.004
0.67	4	16	4	0.0100	0.0100	2	0.17	0.004	0.004
0.67	4	16	4	0.0100	0.0100	3	0.33	0.004	0.019
0.67	4	16	4	0.0100	0.0001	2	0.50	0.001	0.004
0.67	4	16	4	0.0100	0.0001	3	0.67	0.004	0.014
0.67	4	16	4	0.0001	1.0000	3	0.50	0.001	0.004
0.67	4	16 16	4	0.0001	0.0100	2	0.50	0.004	0.012
0.67	4	16	4	0.0001	0.0100	3	0.67	0.001	0.004
0.67	4	16	4	0.0001	0.0001	2	0.83	0.001	0.004
0.67	4	16	4	0.0001	0.0001	3	0.83	0.004	0.962
0.67	4	16	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	16	16	1.0000	1.0000	3	0.00	0.007	0.024
0.67	4	16 16	16 16	1.0000	0.0100	3	0.00	0.001	0.001
0.67	4	16	16	1.0000	0.0100	2	0.33	0.009	0.020
0.67	4	16	16	1.0000	0.0001	3	0.17	0.004	0.026
0.67	4	16	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	4	16	16	0.0100	1.0000	3	0.00	0.012	0.024
0.67	4	16	16	0.0100	0.0100	2	1.00	0.005	0.006
0.67	4	16	16	0.0100	0.0100	3	1.00	0.005	0.006
0.67	4	16 16	16 16	0.0100	0.0001	2	1.00	0.006	0.006
0.67	4	16	16	0.0100	1.0000	2	0.00	0.000	0.000
0.67	4	16	16	0.0001	1.0000	3	0.00	0.009	0.039
0.67	4	16	16	0.0001	0.0100	2	1.00	0.006	0.007
0.67	4	16	16	0.0001	0.0100	3	1.00	0.006	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	4	16	16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	4	16	16	0.0001	0.0001	3	1.00	0.004	0.007
0.67	4	16	64	1.0000	1.0000	2	0.00	0.001	0.003
0.67	4	16	64	1.0000	1.0000	3	0.00	0.042	0.046
0.67	4	16 16	64	1.0000	0.0100	3	0.00	0.001	0.004
0.67	4	16	64	1.0000	0.0001	2	1.00	0.042	0.000
0.67	4	16	64	1.0000	0.0001	3	1.00	0.009	0.014
0.67	4	16	64	0.0100	1.0000	2	0.00	0.001	0.006
0.67	4	16	64	0.0100	1.0000	3	0.00	0.065	0.090
0.67	4	16	64	0.0100	0.0100	2	1.00	0.010	0.013
0.67	4	16	64	0.0100	0.0100	3	1.00	0.010	0.012
0.67	4	16	64	0.0100	0.0001	2	1.00	0.010	0.018
0.67	4	16	64	0.0100	0.0001	3	1.00	0.010	0.018
0.67	4	16 16	64	0.0001	1.0000	2	0.00	0.001	0.008
0.67	4	16	64	0.0001	0.0100	2	1.00	0.107	0.130
0.67	4	16	64	0.0001	0.0100	3	1.00	0.012	0.018
0.67	4	16	64	0.0001	0.0001	2	1.00	0.013	0.017
0.67	4	16	64	0.0001	0.0001	3	1.00	0.015	0.017
0.67	4	16	256	1.0000	1.0000	2	0.00	0.011	0.017
0.67	4	16	256	1.0000	1.0000	3	0.00	0.186	0.727
0.67	4	16	256	1.0000	0.0100	2	0.00	0.001	0.018
0.67	4	16	256	1.0000	0.0100	3	0.00	0.181	0.435
0.67	4	16	256	1.0000	0.0001	2	1.00	0.048	0.061
0.67	4	16	256	1.0000	0.0001	3	1.00	0.048	0.084
0.67	4	16	256	0.0100	1.0000	2	0.00	0.017	0.027
0.67	4	16	256 256	0.0100	1.0000	3	0.00	0.285	0.931
0.67	4	16 16	256	0.0100	0.0100	3	1.00	0.051	0.057
0.67	4	16	256	0.0100	0.0100	2	1.00	0.049	0.036
0.67	4	16	256	0.0100	0.0001	3	1.00	0.062	0.097
0.67	4	16	256	0.0001	1.0000	2	0.00	0.027	0.057
0.67	4	16	256	0.0001	1.0000	3	0.00	0.443	1.052
0.67	4	16	256	0.0001	0.0100	2	1.00	0.064	0.095
0.67	4	16	256	0.0001	0.0100	3	1.00	0.064	0.073
0.67	4	16	256	0.0001	0.0001	2	1.00	0.081	0.104
0.67	4	16	256	0.0001	0.0001	3	1.00	0.081	0.087
0.67	4	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	64	1	1.0000	1.0000	3	0.00	0.005	0.006
0.67	4	64	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	64	1	1.0000	0.0100	3	0.00	0.005	0.007
0.67	4	64	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	4	64	1	0.0100	1.0000	2	0.00	0.000	0.031
0.67	4	64	1	0.0100	1.0000	3	0.17	0.001	0.001
0.67	4	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	4	64	1	0.0100	0.0100	3	0.17	0.003	0.018
0.67	4	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	4	64	1	0.0100	0.0001	3	0.00	0.005	0.007
0.67	4	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	4	64	1	0.0001	1.0000	3	0.00	0.005	0.007
0.67	4	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	4	64	1	0.0001	0.0100	3	0.33	0.003	0.006
0.67	4	64	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	4	64	4	1.0000	1.0000	2	0.00	0.000	0.007
0.67	4	64	4	1.0000	1.0000	3	0.00	0.001	0.001
0.67	4	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	64	4	1.0000	0.0100	3	0.17	0.004	0.018
0.67	4	64	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	4	64	4	1.0000	0.0001	3	0.00	0.006	0.014
0.67	4	64	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	4	64	4	0.0100	1.0000	3	0.17	0.003	0.018
0.67	4	64	4	0.0100	0.0100	2	0.67	0.001	0.004
0.67	4	64	4	0.0100	0.0100	3	0.83	0.003	0.010
0.67	4	64	4	0.0100	0.0001	2	0.17	0.001	0.004
0.67		64	4	0.0100	0.0001 1.0000	3	0.50	0.004	0.020
0.67	4	64 64	4	0.0001	1.0000	3	0.00	0.001	0.001
0.67	4	64	4	0.0001	0.0100	2	0.67	0.008	0.020
0.67	4	64	4	0.0001	0.0100	3	0.67	0.001	0.004
0.67									
1	4	64	4	0.0001	0.0001	2	0.83	0.001	0.004
0.67			4	0.0001 0.0001	0.0001	3	0.83	0.001	0.004
0.67 0.67	4	64							

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	4	64	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	64	16	1.0000	0.0100	3	0.17	0.010	0.027
0.67	4	64	16 16	1.0000	0.0001	3	0.17	0.001	0.006 0.019
0.67	4	64	16	0.0100	1.0000	2	0.00	0.000	0.001
0.67	4	64	16	0.0100	1.0000	3	0.00	0.008	0.021
0.67	4	64	16	0.0100	0.0100	2	1.00	0.004	0.005
0.67	4	64	16	0.0100	0.0100	3	1.00	0.004	0.069
0.67	4	64	16	0.0100	0.0001	2	0.83	0.001	0.005
0.67	4	64	16 16	0.0100	0.0001 1.0000	3	1.00 0.17	0.004	0.005
0.67	4	64	16	0.0001	1.0000	3	0.33	0.004	0.379
0.67	4	64	16	0.0001	0.0100	2	1.00	0.005	0.006
0.67	4	64	16	0.0001	0.0100	3	1.00	0.004	0.005
0.67	4	64 64	16 16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	4	64	64	0.0001 1.0000	1.0000	2	1.00 0.00	0.003	0.007
0.67	4	64	64	1.0000	1.0000	3	0.00	0.028	0.053
0.67	4	64	64	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	64	64	1.0000	0.0100	3	0.17	0.012	0.071
0.67	4	64	64	1.0000	0.0001	2	0.33	0.001	0.016
0.67	4	64	64	1.0000 0.0100	1.00001	2	1.00 0.00	0.011	0.016
0.67	4	64	64	0.0100	1.0000	3	0.00	0.024	0.079
0.67	4	64	64	0.0100	0.0100	2	1.00	0.010	0.015
0.67	4	64	64	0.0100	0.0100	3	1.00	0.010	0.015
0.67	4	64	64	0.0100	0.0001	3	1.00	0.011	0.016 0.017
0.67	4	64	64	0.0100	1.0000	2	0.00	0.001	0.017
0.67	4	64	64	0.0001	1.0000	3	0.00	0.033	0.114
0.67	4	64	64	0.0001	0.0100	2	1.00	0.017	0.020
0.67	4	64	64	0.0001	0.0100	3	1.00	0.012	0.019
0.67	4	64	64 64	0.0001	0.0001	2	1.00	0.013	0.015 0.015
0.67	4	64	256	1.0000	1.0000	2	0.00	0.001	0.015
0.67	4	64	256	1.0000	1.0000	3	0.00	0.167	0.276
0.67	4	64	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	64	256	1.0000	0.0100	3	0.00	0.081	0.702
0.67	4	64	256 256	1.0000	0.0001	3	0.83 1.00	0.001	0.075 0.078
0.67	4	64	256	0.0100	1.0000	2	0.00	0.001	0.076
0.67	4	64	256	0.0100	1.0000	3	0.00	0.342	0.436
0.67	4	64	256	0.0100	0.0100	2	0.83	0.001	0.078
0.67	4	64	256	0.0100	0.0100	3	0.83	0.050	1.067
0.67	4	64	256 256	0.0100	0.0001	3	1.00	0.074	0.100
0.67	4	64	256	0.0001	1.0000	2	0.00	0.025	0.040
0.67	4	64	256	0.0001	1.0000	3	0.00	0.406	1.023
0.67	4	64	256	0.0001	0.0100	2	1.00	0.063	0.099
0.67	4	64	256	0.0001	0.0100	3	1.00	0.062	0.096
0.67	4	64 64	256 256	0.0001	0.0001	3	1.00	0.075 0.074	0.123 0.123
0.67	4	256	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	256	1	1.0000	1.0000	3	0.00	0.005	0.007
0.67	4	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	256 256	1	1.0000 1.0000	0.0100	3	0.33	0.003	0.007 0.001
0.67	4	256	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	4	256	1	0.0100	1.0000	2	0.00	0.003	0.001
0.67	4	256	1	0.0100	1.0000	3	0.00	0.005	0.007
0.67	4	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	4	256 256	1	0.0100	0.0100	3	0.17	0.003	0.007
0.67	4	256	1	0.0100	0.0001	3	0.00	0.001	0.001
0.67	4	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	4	256	1	0.0001	1.0000	3	0.00	0.006	0.014
0.67	4	256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	4	256 256	1	0.0001	0.0100	3	0.00	0.006	0.007
0.67	4	256	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	4	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	256	4	1.0000	1.0000	3	0.00	0.006	0.010
0.67	4	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	256 256	4	1.0000	0.0100	3	0.17	0.003	0.012 0.001
0.67	4	256	4	1.0000	0.0001	3	0.00	0.001	0.001
U.07			<u> </u>	2.0000			/	2.001	2.017

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	4	256	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	4	256	4	0.0100	1.0000	3	0.17	0.004	0.014
0.67	4	256	4	0.0100	0.0100	2	0.50	0.001	0.004
0.67	4	256 256	4	0.0100	0.0100	2	0.83	0.004	0.008
0.67	4	256	4	0.0100	0.0001	3	1.00	0.001	0.022
0.67	4	256	4	0.0001	1.0000	2	0.33	0.003	0.004
0.67	4	256	4	0.0001	1.0000	3	0.83	0.004	0.013
0.67	4	256	4	0.0001	0.0100	2	0.83	0.001	0.004
0.67	4	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.67	4	256	4	0.0001	0.0001	2	0.67	0.001	0.003
0.67	4	256	4	0.0001	0.0001	3	0.83	0.003	0.010
0.67	4	256	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	256 256	16 16	1.0000	1.0000 0.0100	2	0.00	0.005	0.026
0.67	4	256	16	1.0000	0.0100	3	0.00	0.001	0.001
0.67	4	256	16	1.0000	0.0001	2	0.17	0.001	0.006
0.67	4	256	16	1.0000	0.0001	3	0.67	0.006	0.017
0.67	4	256	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	4	256	16	0.0100	1.0000	3	0.17	0.007	0.023
0.67	4	256	16	0.0100	0.0100	2	0.67	0.001	0.005
0.67	4	256	16	0.0100	0.0100	3	1.00	0.004	0.005
0.67	4	256	16	0.0100	0.0001	2	0.50	0.001	0.007
0.67	4	256 256	16 16	0.0100	0.0001 1.0000	3	1.00 0.33	0.005	0.007
0.67	4	256	16	0.0001	1.0000	3	0.33	0.001	0.005 0.022
0.67	4	256	16	0.0001	0.0100	2	1.00	0.004	0.022
0.67	4	256	16	0.0001	0.0100	3	1.00	0.005	0.006
0.67	4	256	16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	4	256	16	0.0001	0.0001	3	1.00	0.005	0.007
0.67	4	256	64	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	256	64	1.0000	1.0000	3	0.00	0.013	0.042
0.67	4	256	64	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	256 256	64	1.0000	0.0100	3	0.17	0.013	0.063
0.67	4	256	64	1.0000	0.0001	3	1.00	0.001	0.016
0.67	4	256	64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	4	256	64	0.0100	1.0000	3	0.00	0.013	0.764
0.67	4	256	64	0.0100	0.0100	2	1.00	0.010	0.012
0.67	4	256	64	0.0100	0.0100	3	1.00	0.010	0.012
0.67	4	256	64	0.0100	0.0001	2	1.00	0.012	0.018
0.67	4	256	64	0.0100	0.0001	3	1.00	0.012	0.018
0.67	4	256	64 64	0.0001	1.0000	2	0.33	0.001	0.016
0.67	4	256 256	64	0.0001	1.0000 0.0100	2	0.33 1.00	0.010	0.082
0.67	4	256	64	0.0001	0.0100	3	1.00	0.013	0.017
0.67	4	256	64	0.0001	0.0001	2	1.00	0.016	0.023
0.67	4	256	64	0.0001	0.0001	3	1.00	0.014	0.023
0.67	4	256	256	1.0000	1.0000	2	0.00	0.001	0.001
0.67	4	256	256	1.0000	1.0000	3	0.00	0.140	0.185
0.67	4	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	4	256	256	1.0000	0.0100	3	0.00	0.071	0.267
0.67	4	256	256	1.0000	0.0001	2	0.50 1.00	0.001	0.058
0.67	4	256 256	256 256	0.0100	1.0000	3	0.00	0.052	0.062
0.67	4	256	256	0.0100	1.0000	3	0.00	0.001	1.154
0.67	4	256	256	0.0100	0.0100	2	1.00	0.047	0.081
0.67	4	256	256	0.0100	0.0100	3	1.00	0.049	0.078
0.67	4	256	256	0.0100	0.0001	2	1.00	0.060	0.088
0.67	4	256	256	0.0100	0.0001	3	1.00	0.060	0.067
0.67	4	256	256	0.0001	1.0000	2	0.00	0.001	0.001
0.67	4	256	256	0.0001	1.0000	3	0.00	0.318	0.962
0.67	4	256 256	256 256	0.0001	0.0100	3	1.00	0.066	0.105 0.104
0.67	4	256	256	0.0001	0.0100	2	1.00	0.070	0.104
0.67	4	256	256	0.0001	0.0001	3	1.00	0.110	0.128
0.67	16	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	1	1	1.0000	1.0000	3	0.00	0.006	0.011
0.67	16	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	1	1	1.0000	0.0100	3	0.00	0.006	0.007
0.67	16	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	16	1	1	1.0000	0.0001	3	0.00	0.006	0.012
0.67	16 16	1	1	0.0100	1.0000	3	0.00	0.001	0.001
0.67	16	1	1	0.0100	0.0100	2	0.17	0.000	0.007
0.67	16	1	1	0.0100	0.0100	3	0.00	0.007	0.038
						-			

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	16	1	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	16	1	1	0.0100	0.0001	3	0.17	0.004	0.007
0.67	16	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	16	1	1	0.0001	0.0100	3	0.00	0.006	0.006
0.67	16	1	1	0.0001	0.0100	3	0.00	0.006	0.006
0.67	16	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	16	1	1	0.0001	0.0001	3	0.00	0.006	0.007
0.67	16	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	1	4	1.0000	1.0000 0.0100	3	0.00	0.006	0.011
0.67	16	1	4	1.0000	0.0100	3	0.00	0.006	0.015
0.67	16	1	4	1.0000	0.0001	2	0.17	0.001	0.003
0.67	16	1	4	1.0000	0.0001	3	0.33	0.003	0.011
0.67	16 16	1	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	16	1	4	0.0100	0.0100	2	0.00	0.000	0.003
0.67	16	1	4	0.0100	0.0100	3	0.67	0.003	0.011
0.67	16	1	4	0.0100	0.0001	2	0.33	0.001	0.003
0.67	16	1	4	0.0100	0.0001	3	0.67	0.003	0.011
0.67	16	1	4	0.0001	1.0000	2	0.33	0.001	0.003
0.67	16 16	1	4	0.0001	1.0000 0.0100	2	0.33	0.003	0.011
0.67	16	1	4	0.0001	0.0100	3	1.00	0.003	0.003
0.67	16	1	4	0.0001	0.0001	2	0.67	0.001	0.004
0.67	16	1	4	0.0001	0.0001	3	0.67	0.003	0.011
0.67	16 16	1	16 16	1.0000	1.0000	3	0.00	0.001	0.001
0.67	16	1	16	1.0000	0.0100	2	0.00	0.009	0.023
0.67	16	1	16	1.0000	0.0100	3	0.33	0.004	0.031
0.67	16	1	16	1.0000	0.0001	2	0.33	0.001	0.006
0.67	16	1	16	1.0000	0.0001	3	0.83	0.005	0.033
0.67	16 16	1	16 16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	16	1	16	0.0100	0.0100	2	0.00	0.011	0.021
0.67	16	1	16	0.0100	0.0100	3	1.00	0.004	0.007
0.67	16	1	16	0.0100	0.0001	2	0.83	0.001	0.006
0.67	16	1	16	0.0100	0.0001	3	0.83	0.004	0.012
0.67	16	1	16 16	0.0001	1.0000	3	0.00	0.001	0.001
0.67	16	1	16	0.0001	0.0100	2	1.00	0.005	0.039
0.67	16	1	16	0.0001	0.0100	3	1.00	0.005	0.006
0.67	16	1	16	0.0001	0.0001	2	1.00	0.005	0.006
0.67	16	1	16	0.0001	0.0001	3	1.00	0.005	0.007
0.67	16 16	1	64	1.0000	1.0000	3	0.00	0.003	0.004
0.67	16	1	64	1.0000	0.0100	2	0.00	0.040	0.003
0.67	16	1	64	1.0000	0.0100	3	0.00	0.023	0.072
0.67	16	1	64	1.0000	0.0001	2	0.83	0.001	0.011
0.67	16	1	64	1.0000	0.0001	3	1.00	0.009	0.023
0.67	16 16	1	64 64	0.0100 0.0100	1.0000	3	0.00	0.001	0.005 0.072
0.67	16	1	64	0.0100	0.0100	2	1.00	0.062	0.072
0.67	16	1	64	0.0100	0.0100	3	1.00	0.010	0.015
0.67	16	1	64	0.0100	0.0001	2	1.00	0.011	0.048
0.67	16	1	64	0.0100	0.0001	3	1.00	0.012	0.018
0.67	16 16	1	64 64	0.0001 0.0001	1.0000	3	0.00	0.001 0.090	0.008
0.67	16	1	64	0.0001	0.0100	2	1.00	0.012	0.019
0.67	16	1	64	0.0001	0.0100	3	1.00	0.012	0.018
0.67	16	1	64	0.0001	0.0001	2	1.00	0.017	0.022
0.67	16	1	256	0.0001	0.0001	3	1.00	0.015	0.022
0.67	16 16	1	256 256	1.0000	1.0000	3	0.00	0.011	0.017
0.67	16	1	256	1.0000	0.0100	2	0.00	0.001	0.025
0.67	16	1	256	1.0000	0.0100	3	0.00	0.185	0.740
0.67	16	1	256	1.0000	0.0001	2	1.00	0.049	0.051
0.67	16	1	256	1.0000	0.0001	3	1.00	0.047	0.062
0.67	16 16	1	256 256	0.0100 0.0100	1.0000	2	0.00	0.016	0.022
0.67	16	1	256	0.0100	0.0100	2	1.00	0.049	0.054
0.67	16	1	256	0.0100	0.0100	3	1.00	0.051	0.054
0.67	16	1	256	0.0100	0.0001	2	1.00	0.065	0.101
0.67	16	1	256	0.0100	0.0001	3	1.00	0.065	0.111
0.67	16 16	1	256 256	0.0001	1.0000 1.0000	2	0.00	0.025 0.421	0.039 1.010
0.07	10	1	230	0.0001	1.0000	3	0.00	0.721	1.010

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	16	1	256	0.0001	0.0100	2	1.00	0.060	0.066
0.67	16	1	256	0.0001	0.0100	3	1.00	0.061	0.094
0.67	16	1	256	0.0001	0.0001	2	1.00	0.074	0.096
0.67	16	1 4	256	0.0001	0.0001	3	1.00	0.073	0.102
0.67	16 16	4	1	1.0000	1.0000	3	0.00	0.001	0.001
0.67	16	4	1	1.0000	0.0100	2	0.00	0.007	0.012
0.67	16	4	1	1.0000	0.0100	3	0.17	0.007	0.012
0.67	16	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	16	4	1	1.0000	0.0001	3	0.17	0.007	0.030
0.67	16	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	16	4	1	0.0100	1.0000	3	0.17	0.005	0.011
0.67	16	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	16 16	4	1	0.0100	0.0100	3	0.00	0.007	0.010
0.67	16	4	1	0.0100	0.0001	3	0.00	0.001	0.001
0.67	16	4	1	0.0001	1.0000	2	0.00	0.007	0.001
0.67	16	4	1	0.0001	1.0000	3	0.00	0.006	0.014
0.67	16	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	16	4	1	0.0001	0.0100	3	0.00	0.006	0.007
0.67	16	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	16	4	1	0.0001	0.0001	3	0.00	0.006	0.011
0.67	16	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	4	4	1.0000	1.0000	3	0.00	0.004	0.009
0.67	16	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16 16	4	4	1.0000	0.0100	3	0.33	0.003	0.017
0.67	16	4	4	1.0000	0.0001	3	0.00	0.001	0.001
0.67	16	4	4	0.0100	1.0000	2	0.00	0.000	0.010
0.67	16	4	4	0.0100	1.0000	3	0.17	0.003	0.015
0.67	16	4	4	0.0100	0.0100	2	0.50	0.001	0.004
0.67	16	4	4	0.0100	0.0100	3	0.50	0.004	0.012
0.67	16	4	4	0.0100	0.0001	2	0.83	0.001	0.004
0.67	16	4	4	0.0100	0.0001	3	0.83	0.004	0.021
0.67	16	4	4	0.0001	1.0000	2	0.67	0.001	0.004
0.67	16	4	4	0.0001	1.0000	3	0.67	0.004	0.019
0.67	16 16	4	4	0.0001	0.0100	3	0.83 1.00	0.001	0.004
0.67	16	4	4	0.0001	0.0001	2	1.00	0.003	0.010
0.67	16	4	4	0.0001	0.0001	3	1.00	0.003	0.004
0.67	16	4	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	4	16	1.0000	1.0000	3	0.00	0.007	0.020
0.67	16	4	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	4	16	1.0000	0.0100	3	0.33	0.013	0.020
0.67	16	4	16	1.0000	0.0001	2	0.17	0.001	0.006
0.67	16	4	16	1.0000	0.0001	3	0.83	0.006	0.022
0.67	16 16	4	16 16	0.0100	1.0000	3	0.00	0.001	0.001
0.67	16	4	16	0.0100	0.0100	2	1.00	0.016	0.005
0.67	16	4	16	0.0100	0.0100	3	1.00	0.004	0.003
0.67	16	4	16	0.0100	0.0001	2	1.00	0.004	0.004
0.67	16	4	16	0.0100	0.0001	3	1.00	0.004	0.005
0.67	16	4	16	0.0001	1.0000	2	0.00	0.001	0.001
0.67	16	4	16	0.0001	1.0000	3	0.00	0.009	0.023
0.67	16	4	16	0.0001	0.0100	2	1.00	0.005	0.006
0.67	16	4	16	0.0001	0.0100	3	1.00	0.005	0.007
0.67	16	4	16	0.0001	0.0001	2	1.00	0.007	0.007
0.67	16 16	4	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.007	0.007
0.67	16	4	64	1.0000	1.0000	3	0.00	0.001	0.004
0.67	16	4	64	1.0000	0.0100	2	0.00	0.042	0.005
0.67	16	4	64	1.0000	0.0100	3	0.00	0.030	0.064
0.67	16	4	64	1.0000	0.0001	2	0.67	0.001	0.012
0.67	16	4	64	1.0000	0.0001	3	1.00	0.010	0.011
0.67	16	4	64	0.0100	1.0000	2	0.00	0.001	0.004
0.67	16	4	64	0.0100	1.0000	3	0.00	0.062	0.546
0.67	16	4	64	0.0100	0.0100	2	1.00	0.011	0.016
0.67	16	4	64	0.0100	0.0100	3	1.00	0.010	0.015
0.67	16 16	4	64 64	0.0100	0.0001	2	1.00	0.011	0.063
0.67		-		0.0100	1.0000	2	0.00	0.001	0.008
		4	64				2.00	1	
	16	4	64			3	0.00	0.078	0.123
0.67				0.0001	1.0000	3 2	0.00	0.078 0.012	0.123 0.018
0.67	16 16	4	64	0.0001	1.0000				
0.67 0.67	16 16 16	4	64 64	0.0001 0.0001	1.0000 0.0100	2	1.00	0.012	0.018

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	16	4	256	1.0000	1.0000	2	0.00	0.011	0.017
0.67	16	4	256	1.0000	1.0000	3	0.00	0.180	0.278
0.67	16	4	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16 16	4	256 256	1.0000	0.0100	3	1.00	0.138	0.289
0.67	16	4	256	1.0000	0.0001	3	1.00	0.048	0.074
0.67	16	4	256	0.0100	1.0000	2	0.00	0.047	0.031
0.67	16	4	256	0.0100	1.0000	3	0.00	0.277	0.426
0.67	16	4	256	0.0100	0.0100	2	1.00	0.051	0.078
0.67	16	4	256	0.0100	0.0100	3	1.00	0.051	0.078
0.67	16	4	256	0.0100	0.0001	2	1.00	0.063	0.092
0.67	16	4	256	0.0100	0.0001	3	1.00	0.058	0.073
0.67	16 16	4	256 256	0.0001	1.0000	3	0.00	0.031	0.042
0.67	16	4	256	0.0001	0.0100	2	1.00	0.061	0.783
0.67	16	4	256	0.0001	0.0100	3	1.00	0.060	0.312
0.67	16	4	256	0.0001	0.0001	2	1.00	0.078	0.084
0.67	16	4	256	0.0001	0.0001	3	1.00	0.079	0.084
0.67	16	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	16	1	1.0000	1.0000	3	0.00	0.005	0.009
0.67	16	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	16	1	1.0000	0.0100	3	0.00	0.005	0.010
0.67	16 16	16 16	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	16	16	1	0.0100	1.0000	2	0.00	0.006	0.010
0.67	16	16	1	0.0100	1.0000	3	0.00	0.001	0.001
0.67	16	16	1	0.0100	0.0100	2	0.00	0.003	0.001
0.67	16	16	1	0.0100	0.0100	3	0.00	0.006	0.041
0.67	16	16	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	16	16	1	0.0100	0.0001	3	0.00	0.007	0.007
0.67	16	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	16	16	1	0.0001	1.0000	3	0.00	0.006	0.044
0.67	16 16	16 16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	16	16	1	0.0001	0.0100	2	0.00	0.000	0.011
0.67	16	16	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	16	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	16	4	1.0000	1.0000	3	0.00	0.004	0.011
0.67	16	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	16	4	1.0000	0.0100	3	0.00	0.007	0.012
0.67	16	16	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	16	16	4	1.0000	0.0001	3	0.00	0.007	0.014
0.67	16 16	16 16	4	0.0100	1.0000	3	0.00	0.001	0.001
0.67	16	16	4	0.0100	0.0100	2	0.17	0.004	0.013
0.67	16	16	4	0.0100	0.0100	3	0.67	0.003	0.007
0.67	16	16	4	0.0100	0.0001	2	0.17	0.001	0.003
0.67	16	16	4	0.0100	0.0001	3	0.33	0.003	0.019
0.67	16	16	4	0.0001	1.0000	2	0.33	0.001	0.003
0.67	16	16	4	0.0001	1.0000	3	0.50	0.003	0.007
0.67	16	16	4	0.0001	0.0100	2	1.00	0.003	0.003
0.67	16 16	16 16	4	0.0001	0.0100	3	1.00 0.67	0.003	0.003
0.67	16	16	4	0.0001	0.0001	3	1.00	0.001	0.004
0.67	16	16	16	1.0000	1.0000	2	0.00	0.003	0.004
0.67	16	16	16	1.0000	1.0000	3	0.00	0.005	0.014
0.67	16	16	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	16	16	1.0000	0.0100	3	0.00	0.005	0.020
0.67	16	16	16	1.0000	0.0001	2	0.00	0.001	0.001
0.67	16	16	16	1.0000	0.0001	3	0.83	0.004	0.021
0.67	16	16	16	0.0100	1.0000	2	0.17	0.001	0.004
0.67	16 16	16 16	16 16	0.0100	1.0000 0.0100	3	0.17	0.004	0.012
0.67	16	16	16	0.0100	0.0100	3	1.00	0.001	0.004
0.67	16	16	16	0.0100	0.0001	2	0.67	0.004	0.005
0.67	16	16	16	0.0100	0.0001	3	1.00	0.004	0.008
	16	16	16	0.0001	1.0000	2	0.00	0.001	0.001
0.67	16	16	16	0.0001	1.0000	3	0.17	0.005	0.016
0.67		1 2 2	16	0.0001	0.0100	2	1.00	0.005	0.007
0.67 0.67	16	16				2 _	1 1 00		
0.67 0.67 0.67	16 16	16	16	0.0001	0.0100	3	1.00	0.005	0.007
0.67 0.67 0.67 0.67	16 16 16	16 16	16 16	0.0001	0.0001	2	1.00	0.005	0.008
0.67 0.67 0.67 0.67 0.67	16 16 16	16 16 16	16 16 16	0.0001 0.0001	0.0001 0.0001	3	1.00	0.005 0.005	0.008
0.67 0.67 0.67 0.67 0.67 0.67	16 16 16 16	16 16 16 16	16 16 16 64	0.0001 0.0001 1.0000	0.0001 0.0001 1.0000	2 3 2	1.00 1.00 0.00	0.005 0.005 0.001	0.008 0.008 0.004
0.67 0.67 0.67 0.67 0.67	16 16 16	16 16 16	16 16 16	0.0001 0.0001	0.0001 0.0001	3	1.00	0.005 0.005	0.008

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	16	16	64	1.0000	0.0001	2	0.50	0.001	0.011
0.67	16	16	64	1.0000	0.0001	3	1.00	0.010	0.013
0.67	16	16	64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	16	16	64	0.0100	1.0000	3	0.00	0.035	0.080
0.67	16	16	64	0.0100	0.0100	2	1.00	0.010	0.015
0.67	16	16	64	0.0100	0.0100	3	1.00	0.010	0.015
0.67	16	16	64	0.0100	0.0001	2	1.00	0.011	0.013
0.67	16	16	64	0.0100	0.0001	3	1.00	0.011	0.013
0.67	16	16	64	0.0001	1.0000	2	0.00	0.001	0.001
0.67	16 16	16 16	64	0.0001	1.0000 0.0100	3	1.00	0.042	1.319 0.012
0.67	16	16	64	0.0001	0.0100	3	1.00	0.011	0.012
0.67	16	16	64	0.0001	0.0001	2	1.00	0.014	0.014
0.67	16	16	64	0.0001	0.0001	3	1.00	0.013	0.015
0.67	16	16	256	1.0000	1.0000	2	0.00	0.011	0.017
0.67	16	16	256	1.0000	1.0000	3	0.00	0.192	0.278
0.67	16	16	256	1.0000	0.0100	2	0.00	0.001	0.018
0.67	16	16	256	1.0000	0.0100	3	0.00	0.216	0.439
0.67	16	16	256	1.0000	0.0001	2	1.00	0.045	0.047
0.67	16	16	256	1.0000	0.0001	3	1.00	0.045	0.049
0.67	16	16	256 256	0.0100	1.0000	3	0.00	0.017	0.028
0.67	16 16	16 16	256	0.0100	1.0000 0.0100	2	0.00 1.00	0.281	1.189 0.075
0.67	16	16	256	0.0100	0.0100	3	1.00	0.047	0.073
0.67	16	16	256	0.0100	0.0001	2	1.00	0.047	0.008
0.67	16	16	256	0.0100	0.0001	3	1.00	0.003	0.098
0.67	16	16	256	0.0001	1.0000	2	0.00	0.026	0.042
0.67	16	16	256	0.0001	1.0000	3	0.00	0.421	1.254
0.67	16	16	256	0.0001	0.0100	2	1.00	0.089	0.097
0.67	16	16	256	0.0001	0.0100	3	1.00	0.087	0.097
0.67	16	16	256	0.0001	0.0001	2	1.00	0.080	0.167
0.67	16	16	256	0.0001	0.0001	3	1.00	0.079	0.127
0.67	16	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	64	1	1.0000	1.0000	3	0.00	0.006	0.011
0.67	16 16	64	1	1.0000	0.0100	3	0.00	0.001	0.001
0.67	16	64	1	1.0000	0.0100	2	0.00	0.000	0.007
0.67	16	64	1	1.0000	0.0001	3	0.00	0.001	0.007
0.67	16	64	1	0.0100	1.0000	2	0.00	0.003	0.007
0.67	16	64	1	0.0100	1.0000	3	0.00	0.006	0.008
0.67	16	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	16	64	1	0.0100	0.0100	3	0.00	0.007	0.053
0.67	16	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	16	64	1	0.0100	0.0001	3	0.00	0.006	0.007
0.67	16	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	16	64	1	0.0001	1.0000	3	0.00	0.006	0.011
0.67	16	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	16 16	64	1	0.0001	0.0100	3	0.00	0.005	0.007
0.67	16	64	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	16	64	4	1.0000	1.0000	2	0.00	0.007	0.010
0.67	16	64	4	1.0000	1.0000	3	0.00	0.005	0.012
0.67	16	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	64	4	1.0000	0.0100	3	0.00	0.007	0.012
0.67	16	64	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	16	64	4	1.0000	0.0001	3	0.00	0.006	0.012
0.67	16	64	4	0.0100	1.0000	2	0.17	0.001	0.003
0.67	16	64	4	0.0100	1.0000	3	0.17	0.003	0.008
0.67	16	64	4	0.0100	0.0100	2	0.50	0.001	0.004
0.67	16	64	4	0.0100	0.0100	3	0.67	0.004	0.007
0.67	16 16	64	4	0.0100	0.0001	3	0.00	0.001	0.001
0.67	16	64	4	0.0100	1.0000	2	0.55	0.004	0.020
0.67	16	64	4	0.0001	1.0000	3	0.83	0.001	0.003
0.67	16	64	4	0.0001	0.0100	2	0.83	0.003	0.004
0.67	16	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.67	16	64	4	0.0001	0.0001	2	0.83	0.001	0.004
0.67	16	64	4	0.0001	0.0001	3	0.83	0.003	0.014
0.67	16	64	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	64	16	1.0000	1.0000	3	0.00	0.007	0.021
0.67	16	64	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	64	16	1.0000	0.0100	3	0.00	0.010	0.031
0.67	16	64	16	1.0000	0.0001	2	0.00	0.001	0.001
0.67	16	64	16	1.0000	0.0001	2	0.50	0.005	0.020
0.67	16 16	64	16 16	0.0100	1.0000	3	0.00	0.001	0.001
0.07	10	04	10	0.0100	1.0000	3	0.17	0.010	0.041

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	16	64	16	0.0100	0.0100	2	1.00	0.005	0.006
0.67	16	64	16	0.0100	0.0100	3	1.00	0.004	0.006
0.67	16 16	64	16 16	0.0100	0.0001	3	1.00	0.005	0.006
0.67	16	64	16	0.0001	1.0000	2	0.50	0.001	0.005
0.67	16	64	16	0.0001	1.0000	3	0.50	0.004	0.036
0.67	16	64	16	0.0001	0.0100	2	1.00	0.004	0.005
0.67	16 16	64	16 16	0.0001	0.0100	3	1.00	0.004	0.005 0.006
0.67	16	64	16	0.0001	0.0001	3	1.00	0.005	0.005
0.67	16	64	64	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	64	64	1.0000	1.0000	3	0.00	0.032	0.042
0.67	16 16	64	64	1.0000	0.0100	3	0.00	0.001	0.001
0.67	16	64	64	1.0000	0.0001	2	0.33	0.001	0.011
0.67	16	64	64	1.0000	0.0001	3	1.00	0.011	0.015
0.67	16 16	64	64	0.0100	1.0000	3	0.00	0.001	0.001
0.67	16	64	64	0.0100	0.0100	2	1.00	0.023	0.082
0.67	16	64	64	0.0100	0.0100	3	1.00	0.010	0.016
0.67	16	64	64	0.0100	0.0001	2	1.00	0.013	0.017
0.67	16 16	64	64 64	0.0100	0.0001 1.0000	2	1.00 0.00	0.011	0.017 0.008
0.67	16	64	64	0.0001	1.0000	3	0.00	0.001	0.008
0.67	16	64	64	0.0001	0.0100	2	1.00	0.017	0.019
0.67	16	64	64	0.0001	0.0100	3	1.00	0.018	0.019
0.67	16 16	64	64	0.0001	0.0001	3	1.00	0.015	0.022
0.67	16	64	256	1.0000	1.0000	2	0.00	0.014	0.022
0.67	16	64	256	1.0000	1.0000	3	0.00	0.159	0.237
0.67	16	64	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16 16	64	256 256	1.0000	0.0100	3	1.00	0.118	0.206 0.057
0.67	16	64	256	1.0000	0.0001	3	1.00	0.048	0.053
0.67	16	64	256	0.0100	1.0000	2	0.00	0.001	0.028
0.67	16	64	256	0.0100	1.0000	3	0.00	0.289	0.928
0.67	16	64	256 256	0.0100 0.0100	0.0100	2	0.83 1.00	0.001	0.080
0.67	16	64	256	0.0100	0.0001	2	1.00	0.064	0.069
0.67	16	64	256	0.0100	0.0001	3	1.00	0.064	0.065
0.67	16	64	256	0.0001	1.0000	2	0.00	0.001	0.027
0.67	16	64	256 256	0.0001	1.0000 0.0100	3	1.00	0.364	0.538 0.107
0.67	16	64	256	0.0001	0.0100	3	1.00	0.063	0.103
0.67	16	64	256	0.0001	0.0001	2	1.00	0.075	0.124
0.67	16	64 256	256	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.077	0.118
0.67	16 16	256	1	1.0000	1.0000	3	0.00	0.001	0.001
0.67	16	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	256	1	1.0000	0.0100	3	0.00	0.006	0.007
0.67	16 16	256 256	1	1.0000	0.0001	3	0.00	0.001 0.007	0.001
0.67	16	256	1	0.0100	1.0000	2	0.00	0.007	0.007
0.67	16	256	1	0.0100	1.0000	3	0.00	0.007	0.011
0.67	16	256	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	16 16	256 256	1	0.0100 0.0100	0.0100	3	0.00	0.005	0.007 0.001
0.67	16	256	1	0.0100	0.0001	3	0.00	0.005	0.007
0.67	16	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	16	256	1	0.0001	1.0000	3	0.17	0.003	0.007
0.67	16 16	256 256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	16	256	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	16	256	1	0.0001	0.0001	3	0.00	0.005	0.007
0.67	16 16	256 256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	256	4	1.0000	0.0100	2	0.00	0.006	0.013
0.67	16	256	4	1.0000	0.0100	3	0.17	0.004	0.008
0.67	16	256	4	1.0000	0.0001	2	0.17	0.001	0.003
0.67	16 16	256 256	4	1.0000 0.0100	0.0001 1.0000	3	0.33	0.003	0.016
0.67	16	256	4	0.0100	1.0000	3	0.00	0.001	0.001
0.67	16	256	4	0.0100	0.0100	2	0.50	0.001	0.004
0.67	16	256	4	0.0100	0.0100	3	0.67	0.003	0.011
0.67	16 16	256 256	4	0.0100	0.0001	2	0.50 0.67	0.001	0.004 0.007
0.07	10	230	4	0.0100	0.0001	J	0.07	0.003	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	16	256	4	0.0001	1.0000	2	0.33	0.001	0.003
0.67	16	256	4	0.0001	1.0000	3	0.33	0.003	0.010
0.67	16	256	4	0.0001	0.0100	2	0.67	0.001	0.004
0.67	16 16	256 256	4	0.0001	0.0100	3	0.67	0.003	0.006
0.67	16	256	4	0.0001	0.0001	3	0.83	0.001	0.003
0.67	16	256	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	256	16	1.0000	1.0000	3	0.00	0.006	0.014
0.67	16	256	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16	256	16	1.0000	0.0100	3	0.00	0.008	0.022
0.67	16 16	256 256	16 16	1.0000	0.0001	3	0.33	0.001	0.005 0.010
0.67	16	256	16	0.0100	1.0000	2	0.00	0.004	0.010
0.67	16	256	16	0.0100	1.0000	3	0.00	0.005	0.001
0.67	16	256	16	0.0100	0.0100	2	0.67	0.001	0.005
0.67	16	256	16	0.0100	0.0100	3	1.00	0.004	0.006
0.67	16	256	16	0.0100	0.0001	2	1.00	0.005	0.007
0.67	16	256	16	0.0100	0.0001	3	1.00	0.006	0.007
0.67	16 16	256 256	16	0.0001	1.0000	2	0.33	0.001	0.006
0.67	16	256	16 16	0.0001	0.0100	2	1.00	0.006	0.033
0.67	16	256	16	0.0001	0.0100	3	1.00	0.006	0.007
0.67	16	256	16	0.0001	0.0001	2	1.00	0.006	0.007
0.67	16	256	16	0.0001	0.0001	3	1.00	0.006	0.008
0.67	16	256	64	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16	256	64	1.0000	1.0000	3	0.00	0.018	0.040
0.67	16	256	64	1.0000	0.0100	2	0.00	0.001	0.001
0.67	16 16	256 256	64 64	1.0000	0.0100	3	0.33	0.013	0.063 0.016
0.67	16	256	64	1.0000	0.0001	3	0.83	0.001	0.010
0.67	16	256	64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	16	256	64	0.0100	1.0000	3	0.00	0.021	0.632
0.67	16	256	64	0.0100	0.0100	2	0.83	0.001	0.012
0.67	16	256	64	0.0100	0.0100	3	1.00	0.010	0.012
0.67	16	256	64	0.0100	0.0001	2	0.83	0.001	0.014
0.67	16 16	256 256	64	0.0100	0.0001 1.0000	3	1.00 0.00	0.011	0.014
0.67	16	256	64	0.0001	1.0000	3	0.00	0.001	0.001
0.67	16	256	64	0.0001	0.0100	2	1.00	0.013	0.013
0.67	16	256	64	0.0001	0.0100	3	1.00	0.012	0.013
0.67	16	256	64	0.0001	0.0001	2	1.00	0.014	0.063
0.67	16	256	64	0.0001	0.0001	3	1.00	0.014	0.016
0.67	16	256	256	1.0000	1.0000	2	0.00	0.001	0.001
0.67	16 16	256 256	256 256	1.0000	1.0000 0.0100	3	0.00	0.115	0.229
0.67	16	256	256	1.0000	0.0100	3	0.00	0.001	0.304
0.67	16	256	256	1.0000	0.0001	2	0.50	0.001	0.081
0.67	16	256	256	1.0000	0.0001	3	0.83	0.050	0.391
0.67	16	256	256	0.0100	1.0000	2	0.00	0.001	0.016
0.67	16	256	256	0.0100	1.0000	3	0.00	0.136	0.731
0.67	16	256	256	0.0100	0.0100	2	0.67	0.001	0.079
0.67	16 16	256 256	256 256	0.0100	0.0100	3	1.00	0.074	0.082
0.67	16	256	256	0.0100	0.0001	3	1.00	0.057	0.062
0.67	16	256	256	0.0001	1.0000	2	0.00	0.001	0.040
0.67	16	256	256	0.0001	1.0000	3	0.00	0.271	0.787
0.67	16	256	256	0.0001	0.0100	2	1.00	0.061	0.100
0.67	16	256	256	0.0001	0.0100	3	1.00	0.061	0.101
0.67	16	256	256	0.0001	0.0001	2	1.00	0.106	0.128
0.67	16 64	256	256 1	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.109	0.127
0.67	64	1	1	1.0000	1.0000	3	0.00	0.001	0.001
0.67	64	1	1	1.0000	0.0100	2	0.00	0.000	0.007
0.67	64	1	1	1.0000	0.0100	3	0.00	0.005	0.007
0.67	64	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	1	1	1.0000	0.0001	3	0.17	0.004	0.016
0.67	64	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	1	1	0.0100	1.0000	3	0.33	0.004	0.007
0.67	64	1	1	0.0100	0.0100	3	0.00	0.001	0.001
0.67	64	1	1	0.0100	0.0001	2	0.00	0.000	0.019
0.67	64	1	1	0.0100	0.0001	3	0.00	0.006	0.058
0.67	64	1	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	0-						0.15	0.004	
0.67	64	1	1	0.0001	1.0000	3	0.17	0.004	0.011
0.67		1 1 1	1 1 1	0.0001 0.0001 0.0001	1.0000 0.0100 0.0100	3 2 3	0.17	0.004 0.001 0.007	0.011 0.001 0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	64	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	64	1	1	0.0001	0.0001	3	0.17	0.005	0.007
0.67	64	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	1	4	1.0000	1.0000 0.0100	3	0.00	0.006	0.012
0.67	64	1	4	1.0000	0.0100	3	0.00	0.001	0.001
0.67	64	1	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	1	4	1.0000	0.0001	3	0.17	0.004	0.019
0.67	64	1	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	1	4	0.0100	1.0000 0.0100	3	0.00	0.007	0.013
0.67	64	1	4	0.0100	0.0100	3	0.17	0.001	0.004
0.67	64	1	4	0.0100	0.0001	2	0.33	0.001	0.004
0.67	64	1	4	0.0100	0.0001	3	0.50	0.004	0.014
0.67	64	1	4	0.0001	1.0000	2	0.17	0.001	0.004
0.67	64	1	4	0.0001	1.0000 0.0100	3	0.33	0.004	0.018
0.67	64	1	4	0.0001	0.0100	3	0.50	0.004	0.014
0.67	64	1	4	0.0001	0.0001	2	0.50	0.001	0.004
0.67	64	1	4	0.0001	0.0001	3	0.67	0.004	0.021
0.67	64	1	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	1	16 16	1.0000	1.0000 0.0100	3	0.00	0.008	0.017
0.67	64	1	16	1.0000	0.0100	3	0.17	0.006	0.027
0.67	64	1	16	1.0000	0.0001	2	0.33	0.001	0.005
0.67	64	1	16	1.0000	0.0001	3	1.00	0.004	0.006
0.67	64	1	16 16	0.0100	1.0000	3	0.00	0.001	0.001 1.097
0.67	64	1	16	0.0100	0.0100	2	0.83	0.007	0.005
0.67	64	1	16	0.0100	0.0100	3	0.83	0.004	0.036
0.67	64	1	16	0.0100	0.0001	2	1.00	0.004	0.006
0.67	64	1	16	0.0100	0.0001	3 2	1.00	0.005	0.006
0.67	64	1	16 16	0.0001	1.0000	3	0.00	0.001	0.001
0.67	64	1	16	0.0001	0.0100	2	1.00	0.005	0.007
0.67	64	1	16	0.0001	0.0100	3	1.00	0.006	0.007
0.67	64	1	16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	64	1	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.005	0.007
0.67	64	1	64	1.0000	1.0000	3	0.00	0.001	0.054
0.67	64	1	64	1.0000	0.0100	2	0.00	0.001	0.004
0.67	64	1	64	1.0000	0.0100	3	0.00	0.023	0.064
0.67	64	1	64	1.0000	0.0001	2	0.83	0.001	0.016
0.67	64	1	64	0.0100	0.0001 1.0000	3	1.00 0.00	0.011	0.017
0.67	64	1	64	0.0100	1.0000	3	0.00	0.017	0.079
0.67	64	1	64	0.0100	0.0100	2	1.00	0.015	0.016
0.67	64	1	64	0.0100	0.0100	3	1.00	0.015	0.016
0.67	64	1	64 64	0.0100	0.0001	3	1.00	0.011	0.018
0.67	64	1	64	0.0100	1.0000	2	0.00	0.012	0.001
0.67	64	1	64	0.0001	1.0000	3	0.00	0.029	0.074
0.67	64	1	64	0.0001	0.0100	2	1.00	0.012	0.014
0.67	64	1	64	0.0001	0.0100	3	1.00	0.011	0.014
0.67	64	1	64	0.0001	0.0001	3	1.00	0.014	0.018
0.67	64	1	256	1.0000	1.0000	2	0.00	0.009	0.015
0.67	64	1	256	1.0000	1.0000	3	0.00	0.174	0.206
0.67	64	1	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	1	256 256	1.0000	0.0100	3	0.00	0.072	0.926 0.049
0.67	64	1	256	1.0000	0.0001	3	1.00	0.049	0.122
0.67	64	1	256	0.0100	1.0000	2	0.00	0.001	0.018
0.67	64	1	256	0.0100	1.0000	3	0.00	0.262	0.314
0.67	64	1	256 256	0.0100	0.0100	3	1.00	0.050	0.055
0.67	64	1	256	0.0100	0.0100	2	1.00	0.032	0.033
0.67	64	1	256	0.0100	0.0001	3	1.00	0.065	0.097
0.67	64	1	256	0.0001	1.0000	2	0.00	0.025	0.039
0.67	64	1	256	0.0001	1.0000	3	0.00	0.417	0.632
0.67	64	1	256 256	0.0001	0.0100	3	1.00	0.061	0.098
0.67	64	1	256	0.0001	0.0001	2	1.00	0.075	0.244
0.67	64	1	256	0.0001	0.0001	3	1.00	0.076	0.126
0.67	64	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	4	1	1.0000	1.0000	3	0.00	0.006	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	64	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	4	1	1.0000	0.0100	3	0.17	0.004	0.007
0.67	64	4	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	4	1	1.0000	0.0001	3	0.00	0.006	0.007
0.67	64	4	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	4	1	0.0100	1.0000	2	0.00	0.007	0.007
0.67	64	4	1	0.0100	0.0100	3	0.00	0.001	0.001
0.67	64	4	1	0.0100	0.0001	2	0.00	0.004	0.001
0.67	64	4	1	0.0100	0.0001	3	0.00	0.007	0.007
0.67	64	4	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	64	4	1	0.0001	1.0000	3	0.00	0.006	0.024
0.67	64	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	64	4	1	0.0001	0.0100	3	0.33	0.004	0.007
0.67	64	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	64	4	1 4	0.0001 1.0000	1.0000	3	0.00	0.006	0.007
0.67	64	4	4	1.0000	1.0000	3	0.00	0.001	0.001
0.67	64	4	4	1.0000	0.0100	2	0.00	0.000	0.001
0.67	64	4	4	1.0000	0.0100	3	0.00	0.006	0.015
0.67	64	4	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	4	4	1.0000	0.0001	3	0.33	0.005	0.028
0.67	64	4	4	0.0100	1.0000	2	0.17	0.001	0.004
0.67	64	4	4	0.0100	1.0000	3	0.17	0.004	0.026
0.67	64	4	4	0.0100	0.0100	2	0.67	0.001	0.004
0.67	64	4	4	0.0100	0.0100	3	0.83	0.003	0.013
0.67	64	4	4	0.0100	0.0001	2	0.33	0.001	0.004
0.67	64	4	4	0.0100	0.0001 1.0000	3	0.50	0.004	0.009
0.67	64	4	4	0.0001	1.0000	3	0.33	0.001	0.004
0.67	64	4	4	0.0001	0.0100	2	0.67	0.001	0.004
0.67	64	4	4	0.0001	0.0100	3	0.83	0.003	0.006
0.67	64	4	4	0.0001	0.0001	2	0.33	0.001	0.004
0.67	64	4	4	0.0001	0.0001	3	0.33	0.003	0.012
0.67	64	4	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	4	16	1.0000	1.0000	3	0.00	0.009	0.013
0.67	64	4	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	4	16 16	1.0000	0.0100	3	0.17	0.006	0.027
0.67	64	4	16	1.0000	0.0001	3	0.50	0.001	0.032
0.67	64	4	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	4	16	0.0100	1.0000	3	0.00	0.010	0.021
0.67	64	4	16	0.0100	0.0100	2	1.00	0.004	0.005
0.67	64	4	16	0.0100	0.0100	3	1.00	0.004	0.005
0.67	64	4	16	0.0100	0.0001	2	0.67	0.001	0.005
0.67	64	4	16	0.0100	0.0001	3	1.00	0.004	0.009
0.67	64	4	16	0.0001	1.0000	2	0.17	0.001	0.004
0.67	64	4	16 16	0.0001	1.0000 0.0100	3	0.17 1.00	0.004	0.025
0.67	64	4	16	0.0001	0.0100	3	1.00	0.005	0.005
0.67	64	4	16	0.0001	0.0001	2	1.00	0.003	0.005
0.67	64	4	16	0.0001	0.0001	3	1.00	0.004	0.006
0.67	64	4	64	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	4	64	1.0000	1.0000	3	0.00	0.012	0.038
0.67	64	4	64	1.0000	0.0100	2	0.00	0.001	0.004
0.67	64	4	64	1.0000	0.0100	3	0.00	0.016	0.059
0.67	64	4	64	1.0000	0.0001	2	0.50	0.001	0.015
0.67	64	4	64	1.0000 0.0100	0.0001 1.0000	3	1.00	0.011	0.031
0.67	64	4	64	0.0100	1.0000	3	0.00	0.001	0.001
0.67	64	4	64	0.0100	0.0100	2	0.83	0.042	0.008
0.67	64	4	64	0.0100	0.0100	3	1.00	0.014	0.035
0.67	64	4	64	0.0100	0.0001	2	1.00	0.012	0.019
0.67	64	4	64	0.0100	0.0001	3	1.00	0.013	0.018
0.67	64	4	64	0.0001	1.0000	2	0.00	0.001	0.008
0.67	64	4	64	0.0001	1.0000	3	0.00	0.081	0.840
0.67	64	4	64	0.0001	0.0100	2	1.00	0.017	0.019
0.67	64	4	64	0.0001	0.0100	3	1.00	0.018	0.019
0.67	64	4	64 64	0.0001	0.0001	3	1.00	0.013	0.022
0.67	64	4	256	1.0000	1.00001	2	0.00	0.014	0.023
0.67	64	4	256	1.0000	1.0000	3	0.00	0.001	0.210
0.67		4	256	1.0000	0.0100	2	0.00	0.001	0.001
	64								
0.67	64	4	256	1.0000	0.0100	3	0.00	0.140	0.283
0.67 0.67 0.67					0.0100 0.0001 0.0001	3 2	0.00	0.140 0.001 0.049	0.283 0.076 0.076

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	64	4	256	0.0100	1.0000	2	0.00	0.001	0.026
0.67	64	4	256	0.0100	1.0000	3	0.00	0.265	0.872
0.67	64	4	256 256	0.0100	0.0100	3	0.83 1.00	0.001	0.052 0.053
0.67	64	4	256	0.0100	0.0001	2	1.00	0.064	0.065
0.67	64	4	256	0.0100	0.0001	3	1.00	0.064	0.068
0.67	64	4	256	0.0001	1.0000	2	0.00	0.001	0.034
0.67	64	4	256	0.0001	1.0000	3	0.00	0.405	1.370
0.67	64 64	4	256 256	0.0001	0.0100	2	1.00	0.060	0.066 0.067
0.67	64	4	256	0.0001	0.0001	2	1.00	0.076	0.084
0.67	64	4	256	0.0001	0.0001	3	1.00	0.075	0.110
0.67	64	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	16 16	1	1.0000	1.0000	3	0.17	0.005	0.011
0.67	64	16	1	1.0000	0.0100	3	0.00	0.001	0.001
0.67	64	16	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	16	1	1.0000	0.0001	3	0.00	0.007	0.011
0.67	64	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	16	1	0.0100	1.0000	3	0.00	0.006	0.006
0.67	64	16 16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	64	16	1	0.0100	0.0001	2	0.00	0.001	0.022
0.67	64	16	1	0.0100	0.0001	3	0.17	0.004	0.046
0.67	64	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	64	16 16	1	0.0001	1.0000 0.0100	3	0.00	0.006	0.011
0.67	64	16	1	0.0001	0.0100	3	0.00	0.001	0.001
0.67	64	16	1	0.0001	0.0001	2	0.00	0.004	0.003
0.67	64	16	1	0.0001	0.0001	3	0.00	0.005	0.006
0.67	64	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	16 16	4	1.0000	1.0000 0.0100	3	0.17	0.006	0.010
0.67	64	16	4	1.0000	0.0100	3	0.00	0.001	0.001
0.67	64	16	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	16	4	1.0000	0.0001	3	0.00	0.006	0.014
0.67	64	16	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	16 16	4	0.0100	1.0000 0.0100	2	0.17	0.003	0.139
0.67	64	16	4	0.0100	0.0100	3	0.50	0.003	0.016
0.67	64	16	4	0.0100	0.0001	2	0.67	0.001	0.003
0.67	64	16	4	0.0100	0.0001	3	0.67	0.003	0.011
0.67	64 64	16 16	4	0.0001	1.0000	2	0.33	0.001	0.003
0.67	64	16	4	0.0001	0.0100	2	1.00	0.003	0.009
0.67	64	16	4	0.0001	0.0100	3	1.00	0.003	0.004
0.67	64	16	4	0.0001	0.0001	2	0.67	0.001	0.003
0.67	64	16	4	0.0001 1.0000	0.0001	3	0.83	0.003	0.006
0.67	64	16 16	16 16	1.0000	1.0000	3	0.00	0.001	0.001
0.67	64	16	16	1.0000	0.0100	2	0.00	0.001	0.020
0.67	64	16	16	1.0000	0.0100	3	0.17	0.007	0.021
0.67	64	16	16	1.0000	0.0001	2	0.17	0.001	0.004
0.67	64 64	16 16	16 16	1.0000 0.0100	0.0001 1.0000	3	0.83	0.004	0.017
0.67	64	16	16	0.0100	1.0000	3	0.00	0.001	0.001
0.67	64	16	16	0.0100	0.0100	2	1.00	0.004	0.006
0.67	64	16	16	0.0100	0.0100	3	1.00	0.004	0.006
0.67	64 64	16 16	16	0.0100	0.0001	2	1.00	0.004	0.007 0.006
0.67	64	16	16 16	0.0100	1.00001	2	0.17	0.004	0.006
0.67	64	16	16	0.0001	1.0000	3	0.17	0.004	0.004
0.67	64	16	16	0.0001	0.0100	2	1.00	0.005	0.006
0.67	64	16	16	0.0001	0.0100	3	1.00	0.004	0.006
0.67	64	16 16	16 16	0.0001	0.0001	2	1.00	0.005	0.007 0.007
0.67	64	16	64	1.0000	1.0000	2	0.00	0.003	0.007
0.67	64	16	64	1.0000	1.0000	3	0.00	0.016	0.055
0.67	64	16	64	1.0000	0.0100	2	0.00	0.001	0.004
0.67	64	16	64	1.0000	0.0100	3	0.00	0.015	0.324
0.67	64 64	16 16	64 64	1.0000	0.0001	2	0.67 1.00	0.001	0.015 0.015
0.67	64	16	64	0.0100	1.0000	2	0.00	0.010	0.001
0.67	64	16	64	0.0100	1.0000	3	0.00	0.017	0.056
0.67	64	16	64	0.0100	0.0100	2	1.00	0.010	0.012
0.67	64	16	64	0.0100	0.0100	3	1.00	0.010	0.012

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	64	16	64	0.0100	0.0001	2	1.00	0.011	0.013
0.67	64	16	64	0.0100	0.0001	3	1.00	0.011	0.013
0.67	64	16	64	0.0001	1.0000	2	0.00	0.001	0.006
0.67	64	16	64	0.0001	1.0000	3	0.00	0.039	0.088
0.67	64	16 16	64 64	0.0001	0.0100	3	1.00	0.011	0.013
0.67	64	16	64	0.0001	0.0001	2	1.00	0.013	0.014
0.67	64	16	64	0.0001	0.0001	3	1.00	0.014	0.021
0.67	64	16	256	1.0000	1.0000	2	0.00	0.001	0.017
0.67	64	16	256	1.0000	1.0000	3	0.00	0.200	0.302
0.67	64	16	256	1.0000	0.0100	2	0.00	0.001	0.024
0.67	64	16	256	1.0000	0.0100	3	0.17	0.056	0.843
0.67	64	16	256	1.0000	0.0001	2	1.00	0.074	0.075
0.67	64	16	256	1.0000	0.0001	3	1.00	0.074	0.075
0.67	64	16 16	256 256	0.0100	1.0000	2	0.00	0.001	0.028 0.451
0.67	64	16	256	0.0100	0.0100	2	0.83	0.307	0.431
0.67	64	16	256	0.0100	0.0100	3	1.00	0.001	0.079
0.67	64	16	256	0.0100	0.0001	2	1.00	0.060	0.129
0.67	64	16	256	0.0100	0.0001	3	1.00	0.060	0.099
0.67	64	16	256	0.0001	1.0000	2	0.00	0.001	0.042
0.67	64	16	256	0.0001	1.0000	3	0.00	0.414	0.648
0.67	64	16	256	0.0001	0.0100	2	1.00	0.061	0.136
0.67	64	16	256	0.0001	0.0100	3	1.00	0.061	0.101
0.67	64	16	256	0.0001	0.0001	2	1.00	0.101	0.126
0.67	64	16	256	0.0001	0.0001	3	1.00	0.081	0.127
0.67	64	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	64	1	1.0000	0.0100	2	0.00	0.003	0.011
0.67	64	64	1	1.0000	0.0100	3	0.00	0.001	0.001
0.67	64	64	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	64	1	1.0000	0.0001	3	0.00	0.007	0.010
0.67	64	64	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	64	1	0.0100	1.0000	3	0.17	0.003	0.021
0.67	64	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	64	64	1	0.0100	0.0100	3	0.00	0.005	0.038
0.67	64	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	64	64	1	0.0100	0.0001	3	0.17	0.005	0.010
0.67	64	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	64	64	1	0.0001	0.0100	2	0.00	0.000	0.001
0.67	64	64	1	0.0001	0.0100	3	0.00	0.001	0.007
0.67	64	64	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	64	64	1	0.0001	0.0001	3	0.17	0.003	0.136
0.67	64	64	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	64	4	1.0000	1.0000	3	0.00	0.003	0.011
0.67	64	64	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	64	4	1.0000	0.0100	3	0.00	0.006	0.012
0.67	64	64	4	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	64 64	4	1.0000 0.0100	1.0000	3	0.00	0.008	0.019
0.67	64	64	4	0.0100	1.0000	3	0.00	0.001	0.001
0.67	64	64	4	0.0100	0.0100	2	0.33	0.000	0.012
0.67	64	64	4	0.0100	0.0100	3	0.67	0.003	0.008
0.67	64	64	4	0.0100	0.0001	2	0.17	0.001	0.004
0.67	64	64	4	0.0100	0.0001	3	0.33	0.004	0.023
0.67	64	64	4	0.0001	1.0000	2	0.50	0.001	0.004
0.67	64	64	4	0.0001	1.0000	3	0.83	0.004	0.011
0.67	64	64	4	0.0001	0.0100	2	1.00	0.003	0.004
0.67	64	64	4	0.0001	0.0100	3	1.00	0.003	0.004
0.67	64	64 64	4	0.0001	0.0001	3	0.50	0.001	0.004
0.67	64	64	16	1.0000	1.00001	2	0.07	0.004	0.018
0.67	64	64	16	1.0000	1.0000	3	0.00	0.001	0.001
0.67	64	64	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	64	16	1.0000	0.0100	3	0.00	0.008	0.022
0.67	64	64	16	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	64	16	1.0000	0.0001	3	0.67	0.006	0.012
0.67	64	64	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	64	16	0.0100	1.0000	3	0.17	0.005	0.040
0.67	64	64	16	0.0100	0.0100	2	0.83	0.001	0.005
0.67	64	64	16	0.0100	0.0100	2	1.00	0.004	0.006
0.67	64	64	16 16	0.0100	0.0001	3	1.00	0.004	0.007
0.67	64	64	16	0.0100	1.0000	2	0.67	0.004	0.007
0.67	64	64	16	0.0001	1.0000	3	0.67	0.006	0.020

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	64	64	16	0.0001	0.0100	2	1.00	0.006	0.007
0.67	64	64	16	0.0001	0.0100	3	1.00	0.006	0.006
0.67	64	64	16	0.0001	0.0001	2	1.00	0.006	0.007
0.67	64	64	16 64	0.0001 1.0000	0.0001 1.0000	3	0.00	0.006	0.007
0.67	64	64	64	1.0000	1.0000	3	0.00	0.001	0.061
0.67	64	64	64	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	64	64	1.0000	0.0100	3	0.17	0.013	0.072
0.67	64	64	64	1.0000	0.0001	2	0.33	0.001	0.016
0.67	64	64	64	1.0000	0.0001	3	0.83	0.015	0.031
0.67	64	64	64 64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	64	64	0.0100	0.0100	2	1.00	0.021	0.003
0.67	64	64	64	0.0100	0.0100	3	1.00	0.011	0.015
0.67	64	64	64	0.0100	0.0001	2	1.00	0.011	0.012
0.67	64	64	64	0.0100	0.0001	3	1.00	0.011	0.012
0.67	64	64	64	0.0001	1.0000	2	0.17	0.001	0.011
0.67	64	64	64 64	0.0001	1.0000	3	0.17 1.00	0.010	0.080
0.67	64	64	64	0.0001	0.0100	3	1.00	0.012	0.019
0.67	64	64	64	0.0001	0.0001	2	1.00	0.021	0.023
0.67	64	64	64	0.0001	0.0001	3	1.00	0.020	0.022
0.67	64	64	256	1.0000	1.0000	2	0.00	0.001	0.017
0.67	64	64	256	1.0000	1.0000	3	0.00	0.128	0.279
0.67	64	64	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	64	256 256	1.0000	0.0100	3	0.00	0.112	0.266 0.076
0.67	64	64	256	1.0000	0.0001	3	1.00	0.001	0.076
0.67	64	64	256	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	64	256	0.0100	1.0000	3	0.00	0.251	0.745
0.67	64	64	256	0.0100	0.0100	2	1.00	0.063	0.082
0.67	64	64	256	0.0100	0.0100	3	1.00	0.078	0.080
0.67	64 64	64	256 256	0.0100	0.0001	2	1.00	0.058	0.098
0.67	64	64	256	0.0100	1.0000	2	0.00	0.009	0.040
0.67	64	64	256	0.0001	1.0000	3	0.00	0.368	1.288
0.67	64	64	256	0.0001	0.0100	2	1.00	0.067	0.099
0.67	64	64	256	0.0001	0.0100	3	1.00	0.067	0.100
0.67	64	64	256	0.0001	0.0001	2	1.00	0.080	0.084
0.67	64	64	256	0.0001	0.0001	3	1.00	0.080	0.083
0.67	64	256 256	1	1.0000	1.0000	3	0.00	0.001	0.001
0.67	64	256	1	1.0000	0.0100	2	0.00	0.000	0.020
0.67	64	256	1	1.0000	0.0100	3	0.00	0.006	0.007
0.67	64	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	64	256	1	1.0000	0.0001	3	0.17	0.003	0.006
0.67	64	256	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64 64	256 256	1	0.0100	1.0000	3	0.00	0.005	0.010
0.67	64	256	1	0.0100	0.0100	3	0.00	0.001	0.001
0.67	64	256	1	0.0100	0.0001	2	0.00	0.003	0.007
0.67	64	256	1	0.0100	0.0001	3	0.17	0.004	0.006
0.67	64	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	64	256	1	0.0001	1.0000	3	0.00	0.006	0.010
0.67	64	256 256	1	0.0001	0.0100	3	0.00	0.001	0.001
0.67	64	256	1	0.0001	0.0100	2	0.00	0.007	0.010
0.67	64	256	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	64	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	256	4	1.0000	1.0000	3	0.00	0.007	0.045
0.67	64	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	256	4	1.0000	0.0100	3	0.33	0.004	0.016
0.67	64 64	256 256	4	1.0000	0.0001	3	0.17	0.001	0.004
0.67	64	256	4	0.0100	1.0000	2	0.17	0.003	0.013
0.67	64	256	4	0.0100	1.0000	3	0.00	0.001	0.001
0.67	64	256	4	0.0100	0.0100	2	0.50	0.001	0.003
0.67	64	256	4	0.0100	0.0100	3	0.83	0.003	0.007
0.67	64	256	4	0.0100	0.0001	2	0.67	0.001	0.003
0.67	64	256	4	0.0100	0.0001 1.0000	3	0.67	0.003	0.016
0.67	64	256 256	4	0.0001	1.0000	2	0.50	0.001	0.003
0.67	64	256	4	0.0001	0.0100	2	0.67	0.003	0.003
0.67	64	256	4	0.0001	0.0100	3	1.00	0.003	0.004
0.67	64	256	4	0.0001	0.0001	2	0.67	0.001	0.004
0.67	64	256	4	0.0001	0.0001	3	0.83	0.003	0.006

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	64	256	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	256	16	1.0000	1.0000	3	0.00	0.005	0.472
0.67	64	256	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	256	16	1.0000	0.0100	3	0.33	0.005	0.017
0.67	64	256	16	1.0000	0.0001	2	0.17	0.001	0.005
0.67	64	256	16	1.0000	0.0001	3	1.00	0.004	0.013
0.67	64	256	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	256	16	0.0100	1.0000	3	0.00	0.005	0.018
0.67	64	256	16	0.0100	0.0100	2	0.33	0.001	0.004
0.67	64	256	16	0.0100	0.0100	2	1.00	0.004	0.008
0.67	64	256 256	16 16	0.0100	0.0001	3	0.67	0.001	0.007
0.67	64	256	16	0.0001	1.0000	2	0.33	0.003	0.009
0.67	64	256	16	0.0001	1.0000	3	0.33	0.001	0.031
0.67	64	256	16	0.0001	0.0100	2	1.00	0.005	0.041
0.67	64	256	16	0.0001	0.0100	3	1.00	0.005	0.007
0.67	64	256	16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	64	256	16	0.0001	0.0001	3	1.00	0.005	0.007
0.67	64	256	64	1.0000	1.0000	2	0.00	0.001	0.001
0.67	64	256	64	1.0000	1.0000	3	0.00	0.012	0.033
0.67	64	256	64	1.0000	0.0100	2	0.00	0.001	0.001
0.67	64	256	64	1.0000	0.0100	3	0.17	0.012	0.075
0.67	64	256 256	64	1.0000	0.0001	3	0.50 1.00	0.001	0.012
0.67	64	256	64	0.0100	1.00001	2	0.00	0.011	0.014
0.67	64	256	64	0.0100	1.0000	3	0.00	0.001	0.001
0.67	64	256	64	0.0100	0.0100	2	0.17	0.014	0.033
0.67	64	256	64	0.0100	0.0100	3	1.00	0.001	0.015
0.67	64	256	64	0.0100	0.0001	2	1.00	0.011	0.019
0.67	64	256	64	0.0100	0.0001	3	1.00	0.011	0.018
0.67	64	256	64	0.0001	1.0000	2	0.17	0.001	0.016
0.67	64	256	64	0.0001	1.0000	3	0.33	0.016	0.104
0.67	64	256	64	0.0001	0.0100	2	1.00	0.018	0.019
0.67	64	256	64	0.0001	0.0100	3	1.00	0.018	0.019
0.67	64	256	64	0.0001	0.0001	2	1.00	0.013	0.023
0.67	64	256	64	0.0001	0.0001	3	1.00	0.015	0.022
0.67	64 64	256 256	256 256	1.0000	1.0000	2	0.00	0.001	0.017
0.67	64	256	256	1.0000	1.0000 0.0100	2	0.00	0.128	0.280
0.67	64	256	256	1.0000	0.0100	3	0.00	0.001	0.517
0.67	64	256	256	1.0000	0.0001	2	0.33	0.020	0.055
0.67	64	256	256	1.0000	0.0001	3	1.00	0.053	0.082
0.67	64	256	256	0.0100	1.0000	2	0.00	0.001	0.001
0.67	64	256	256	0.0100	1.0000	3	0.00	0.125	0.351
0.67	64	256	256	0.0100	0.0100	2	0.67	0.001	0.080
0.67	64	256	256	0.0100	0.0100	3	1.00	0.056	0.081
0.67	64	256	256	0.0100	0.0001	2	1.00	0.093	0.098
0.67	64	256	256	0.0100	0.0001	3	1.00	0.088	0.098
0.67	64	256	256	0.0001	1.0000	2	0.00	0.001	0.039
0.67	64	256	256	0.0001	1.0000	3	0.00	0.319	0.806
0.67	64	256 256	256 256	0.0001	0.0100	3	1.00	0.068	0.101 0.102
0.67	64	256	256	0.0001	0.0001	2	1.00	0.082	0.102
0.67	64	256	256	0.0001	0.0001	3	1.00	0.073	0.128
0.67	256	1	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	1	1	1.0000	1.0000	3	0.00	0.006	0.511
0.67	256	1	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	1	1	1.0000	0.0100	3	0.00	0.006	0.007
0.67	256	1	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	256	1	1	1.0000	0.0001	3	0.17	0.004	0.012
0.67	256	1	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	1	1	0.0100	1.0000	3	0.17	0.004	0.024
0.67	256	1	1	0.0100	0.0100	3	0.00	0.001	0.001
0.67	256 256	1	1	0.0100	0.0100	2	0.00	0.006	0.007
0.67	256	1	1	0.0100	0.0001	3	0.00	0.001	0.001
0.67	256	1	1	0.0100	1.0000	2	0.00	0.003	0.007
0.67	256	1	1	0.0001	1.0000	3	0.00	0.001	0.007
0.67	256	1	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	256	1	1	0.0001	0.0100	3	0.00	0.006	0.044
	256	1	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67		1	1	0.0001	0.0001	3	0.17	0.005	0.007
	256								
0.67 0.67 0.67	256	1	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67 0.67 0.67 0.67	256 256	1	4	1.0000 1.0000	1.0000	3	0.00	0.007	0.021
0.67 0.67 0.67	256	1	4	1.0000					

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	256 256	1	4	1.0000	0.0001	3	0.00	0.001	0.001
0.67	256	1	4	0.0100	1.00001	2	0.00	0.000	0.001
0.67	256	1	4	0.0100	1.0000	3	0.00	0.001	0.001
0.67	256	1	4	0.0100	0.0100	2	0.33	0.007	0.004
0.67	256	1	4	0.0100	0.0100	3	0.50	0.004	0.019
0.67	256	1	4	0.0100	0.0001	2	0.33	0.004	0.004
0.67	256	1	4	0.0100	0.0001	3	0.50	0.004	0.009
0.67	256	1	4	0.0001	1.0000	2	0.50	0.001	0.004
0.67	256	1	4	0.0001	1.0000	3	0.50	0.003	0.008
0.67	256	1	4	0.0001	0.0100	2	0.67	0.001	0.004
0.67	256	1	4	0.0001	0.0100	3	0.83	0.003	0.008
0.67	256	1	4	0.0001	0.0001	2	0.67	0.001	0.004
0.67	256	1	4	0.0001	0.0001	3	0.67	0.004	0.021
0.67	256	1	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	1	16	1.0000	1.0000	3	0.00	0.007	0.030
0.67	256	1	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	1	16	1.0000	0.0100	3	0.00	0.008	0.025
0.67	256	1	16	1.0000	0.0001	2	0.17	0.001	0.004
0.67	256	1	16	1.0000	0.0001	3	0.67	0.004	0.017
0.67	256	1	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	1	16	0.0100	1.0000	3	0.00	0.009	0.015
0.67	256	1	16	0.0100	0.0100	2	0.83	0.001	0.006
0.67	256	1	16	0.0100	0.0100	3	1.00	0.004	0.006
0.67	256	1	16	0.0100	0.0001	2	1.00	0.005	0.006
0.67	256	1	16 16	0.0100	0.0001 1.0000	3	1.00	0.005	0.006
0.67	256 256	1	16	0.0001	1.0000	3	0.17	0.001	0.005
0.67	256	1	16	0.0001	0.0100	2	1.00	0.005	0.023
0.67	256	1	16	0.0001	0.0100	3	1.00	0.004	0.006
0.67	256	1	16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	256	1	16	0.0001	0.0001	3	1.00	0.005	0.007
0.67	256	1	64	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	1	64	1.0000	1.0000	3	0.00	0.014	0.035
0.67	256	1	64	1.0000	0.0100	2	0.00	0.001	0.006
0.67	256	1	64	1.0000	0.0100	3	0.17	0.019	0.087
0.67	256	1	64	1.0000	0.0001	2	0.33	0.001	0.010
0.67	256	1	64	1.0000	0.0001	3	1.00	0.010	0.018
0.67	256	1	64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	1	64	0.0100	1.0000	3	0.00	0.015	0.057
0.67	256	1	64	0.0100	0.0100	2	0.83	0.001	0.016
0.67	256	1	64	0.0100	0.0100	3	1.00	0.011	0.016
0.67	256	1	64	0.0100	0.0001	2	1.00	0.012	0.014
0.67	256	1	64	0.0100	0.0001	3	1.00	0.011	0.015
0.67	256	1	64	0.0001	1.0000	2	0.00	0.001	0.001
0.67	256	1	64	0.0001	1.0000	3	0.17	0.023	0.049
0.67	256	1	64	0.0001	0.0100	2	1.00	0.012	0.013
0.67	256	1	64	0.0001	0.0100	3	1.00	0.012	0.013
0.67	256	1	64	0.0001	0.0001	2	1.00	0.014	0.015
0.67	256 256	1	64 256	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.013	0.015
0.67	256	1	256	1.0000	1.0000	3	0.00	0.001	0.001
0.67	256	1	256	1.0000	0.0100	2	0.00	0.039	0.199
0.67	256	1	256	1.0000	0.0100	3	0.00	0.001	0.534
0.67	256	1	256	1.0000	0.0001	2	0.83	0.001	0.080
0.67	256	1	256	1.0000	0.0001	3	1.00	0.054	0.122
0.67	256	1	256	0.0100	1.0000	2	0.00	0.001	0.016
0.67	256	1	256	0.0100	1.0000	3	0.00	0.172	0.316
0.67	256	1	256	0.0100	0.0100	2	0.83	0.001	0.054
0.67	256	1	256	0.0100	0.0100	3	1.00	0.052	0.133
0.67	256	1	256	0.0100	0.0001	2	1.00	0.062	0.070
0.67	256	1	256	0.0100	0.0001	3	1.00	0.064	0.065
0.67	256	1	256	0.0001	1.0000	2	0.00	0.001	0.041
0.67	256	1	256	0.0001	1.0000	3	0.00	0.210	0.590
0.67	256	1	256	0.0001	0.0100	2	1.00	0.093	0.105
0.67	256	1	256	0.0001	0.0100	3	1.00	0.093	0.104
0.67	256	1	256	0.0001	0.0001	2	1.00	0.120	0.125
0.67	256	1	256	0.0001	0.0001	3	1.00	0.099	0.130
0.67	256	4	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	4	1	1.0000	1.0000	3	0.00	0.005	0.636
0.67	256	4	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	4		1.0000	0.0100	3	0.00	0.006	0.006
0.67	256 256	4	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	256	4	1	0.0100	1.00001	2	0.17	0.004	0.007
0.67	256	4	1	0.0100	1.0000	3	0.00	0.001	0.001
0.07	230		1	0.0100	1.0000	3	0.00	0.000	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	256	4	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	256	4	1	0.0100	0.0100	3	0.00	0.007	0.007
0.67	256 256	4	1	0.0100	0.0001	3	0.00	0.001	0.001
0.67	256	4	1	0.0100	1.0000	2	0.17	0.004	0.007
0.67	256	4	1	0.0001	1.0000	3	0.00	0.001	0.007
0.67	256	4	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	256	4	1	0.0001	0.0100	3	0.00	0.006	0.007
0.67	256	4	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	256	4	1	0.0001	0.0001	3	0.00	0.007	0.015
0.67	256	4	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	4	4	1.0000	1.0000	3	0.00	0.007	0.012
0.67	256 256	4	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	4	4	1.0000	0.0100	3	0.00	0.007	0.013
0.67	256	4	4	1.0000	0.0001	3	0.00	0.001	0.001
0.67	256	4	4	0.0100	1.0000	2	0.00	0.003	0.020
0.67	256	4	4	0.0100	1.0000	3	0.17	0.005	0.013
0.67	256	4	4	0.0100	0.0100	2	0.17	0.001	0.004
0.67	256	4	4	0.0100	0.0100	3	0.33	0.004	0.019
0.67	256	4	4	0.0100	0.0001	2	0.33	0.001	0.004
0.67	256	4	4	0.0100	0.0001	3	0.50	0.004	0.015
0.67	256	4	4	0.0001	1.0000	2	0.67	0.001	0.004
0.67	256	4	4	0.0001	1.0000	3	0.67	0.004	0.011
0.67	256	4	4	0.0001	0.0100	2	0.67	0.001	0.004
0.67	256 256	4	4	0.0001	0.0100	3	0.83	0.004	0.014
0.67	256	4	4	0.0001	0.0001	3	0.50	0.001	0.004
0.67	256	4	16	1.0000	1.0000	2	0.00	0.004	0.021
0.67	256	4	16	1.0000	1.0000	3	0.00	0.009	0.017
0.67	256	4	16	1.0000	0.0100	2	0.33	0.001	0.005
0.67	256	4	16	1.0000	0.0100	3	0.50	0.005	0.011
0.67	256	4	16	1.0000	0.0001	2	0.00	0.001	0.001
0.67	256	4	16	1.0000	0.0001	3	1.00	0.006	0.007
0.67	256	4	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256 256	4	16 16	0.0100	1.0000	3	0.00	0.010	0.029
0.67	256	4	16	0.0100	0.0100	2	0.67 1.00	0.001	0.006 0.014
0.67	256	4	16	0.0100	0.0001	2	0.83	0.003	0.014
0.67	256	4	16	0.0100	0.0001	3	1.00	0.005	0.009
0.67	256	4	16	0.0001	1.0000	2	0.00	0.001	0.001
0.67	256	4	16	0.0001	1.0000	3	0.00	0.010	0.031
0.67	256	4	16	0.0001	0.0100	2	1.00	0.005	0.006
0.67	256	4	16	0.0001	0.0100	3	1.00	0.005	0.006
0.67	256	4	16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	256	4	16	0.0001	0.0001	3	1.00	0.005	0.006
0.67	256 256	4	64 64	1.0000	1.0000	3	0.00	0.001	0.001
0.67	256	4	64	1.0000	0.0100	2	0.00	0.013	0.049
0.67	256	4	64	1.0000	0.0100	3	0.00	0.001	0.001
0.67	256	4	64	1.0000	0.0001	2	0.67	0.001	0.011
0.67	256	4	64	1.0000	0.0001	3	1.00	0.010	0.024
0.67	256	4	64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	4	64	0.0100	1.0000	3	0.00	0.018	0.047
0.67	256	4	64	0.0100	0.0100	2	0.83	0.001	0.012
0.67	256	4	64	0.0100	0.0100	3	1.00	0.010	0.012
0.67	256	4	64	0.0100	0.0001	2	1.00	0.011	0.013
0.67	256 256	4	64	0.0100	0.0001 1.0000	3	1.00 0.50	0.011	0.013
0.67	256	4	64	0.0001	1.0000	3	0.50	0.001	0.016
0.67	256	4	64	0.0001	0.0100	2	1.00	0.010	0.082
0.67	256	4	64	0.0001	0.0100	3	1.00	0.012	0.029
0.67	256	4	64	0.0001	0.0001	2	1.00	0.016	0.022
0.67	256	4	64	0.0001	0.0001	3	1.00	0.014	0.022
0.67	256	4	256	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	4	256	1.0000	1.0000	3	0.00	0.158	0.918
0.67	256	4	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	4	256	1.0000	0.0100	3	0.00	0.076	0.299
0.67	256 256	4	256 256	1.0000	0.0001	2	0.67 1.00	0.001	0.078 0.178
0.67	256	4	256	0.0100	1.00001	2	0.00	0.055	0.178
0.67	256	4	256	0.0100	1.0000	3	0.00	0.001	0.382
0.67	256	4	256	0.0100	0.0100	2	1.00	0.052	0.238
							1.00	0.064	
0.67	256	4	256	0.0100	0.0100	3	1.00	0.004	0.079
0.67 0.67 0.67	256 256 256	4 4	256 256 256	0.0100 0.0100 0.0100	0.0100 0.0001 0.0001	2 3	1.00	0.081	0.079

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	256	4	256	0.0001	1.0000	2	0.00	0.001	0.001
0.67	256	4	256	0.0001	1.0000	3	0.00	0.126	0.543
0.67	256	4	256	0.0001	0.0100	2	1.00	0.073	0.137
0.67	256 256	4	256 256	0.0001	0.0100	3	1.00	0.069	0.156 0.122
0.67	256	4	256	0.0001	0.0001	3	1.00	0.076	0.122
0.67	256	16	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	16	1	1.0000	1.0000	3	0.00	0.006	0.009
0.67	256	16	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256 256	16 16	1	1.0000	0.0100	3	0.00	0.006	0.006
0.67	256	16	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	256	16	1	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	16	1	0.0100	1.0000	3	0.00	0.006	0.006
0.67	256	16	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	256 256	16 16	1	0.0100	0.0100	3	0.00	0.005	0.006
0.67	256	16	1	0.0100	0.0001	3	0.00	0.001	0.001
0.67	256	16	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	256	16	1	0.0001	1.0000	3	0.00	0.006	0.006
0.67	256	16	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	256 256	16 16	1	0.0001	0.0100	3	0.00	0.006 0.001	0.020
0.67	256	16	1	0.0001	0.0001	3	0.00	0.001	0.001
0.67	256	16	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	16	4	1.0000	1.0000	3	0.00	0.007	0.013
0.67	256	16	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256 256	16 16	4	1.0000	0.0100	3	0.33	0.004	0.013
0.67	256	16	4	1.0000	0.0001	3	0.50	0.004	0.018
0.67	256	16	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	16	4	0.0100	1.0000	3	0.17	0.005	0.021
0.67	256 256	16 16	4	0.0100	0.0100	2	0.67	0.001	0.004
0.67	256	16	4	0.0100	0.0100	2	0.07	0.004	0.012
0.67	256	16	4	0.0100	0.0001	3	0.67	0.004	0.018
0.67	256	16	4	0.0001	1.0000	2	0.50	0.001	0.004
0.67	256	16	4	0.0001	1.0000	3	0.50	0.004	0.021
0.67	256 256	16 16	4	0.0001	0.0100	2	0.83	0.001	0.004
0.67	256	16	4	0.0001	0.0001	2	0.83	0.004	0.007
0.67	256	16	4	0.0001	0.0001	3	1.00	0.004	0.010
0.67	256	16	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	16	16	1.0000	1.0000	3	0.17	0.004	0.024
0.67	256 256	16 16	16 16	1.0000	0.0100	3	0.17	0.001	0.005
0.67	256	16	16	1.0000	0.0001	2	0.50	0.001	0.006
0.67	256	16	16	1.0000	0.0001	3	1.00	0.006	0.007
0.67	256	16	16	0.0100	1.0000	2	0.17	0.001	0.005
0.67	256 256	16 16	16 16	0.0100	1.0000 0.0100	3	0.33	0.005	0.028 0.006
0.67	256	16	16	0.0100	0.0100	3	0.83	0.001	0.000
0.67	256	16	16	0.0100	0.0001	2	0.83	0.001	0.007
0.67	256	16	16	0.0100	0.0001	3	1.00	0.006	0.007
0.67	256	16 16	16	0.0001	1.0000	3	0.33	0.001	0.006
0.67	256 256	16	16 16	0.0001	1.0000 0.0100	2	0.50 1.00	0.004	0.032
0.67	256	16	16	0.0001	0.0100	3	1.00	0.005	0.006
0.67	256	16	16	0.0001	0.0001	2	0.83	0.001	0.007
0.67	256	16	16	0.0001	0.0001	3	1.00	0.005	0.012
0.67	256 256	16 16	64 64	1.0000	1.0000	3	0.00	0.001	0.001
0.67	256	16	64	1.0000	0.0100	2	0.00	0.014	0.041
0.67	256	16	64	1.0000	0.0100	3	0.00	0.023	0.059
0.67	256	16	64	1.0000	0.0001	2	0.50	0.001	0.016
0.67	256	16	64	1.0000	0.0001	3	1.00	0.011	0.016
0.67	256 256	16 16	64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	16	64	0.0100	0.0100	2	0.83	0.024	0.803
0.67	256	16	64	0.0100	0.0100	3	1.00	0.010	0.011
0.67	256	16	64	0.0100	0.0001	2	1.00	0.011	0.012
0.67	256	16 16	64 64	0.0100	0.0001 1.0000	3	1.00	0.011	0.012
0.67	256 256	16	64	0.0001	1.0000	3	0.00	0.001	0.001
0.67	256	16	64	0.0001	0.0100	2	1.00	0.011	0.019
0.67	256	16	64	0.0001	0.0100	3	1.00	0.012	0.018

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	256	16	64	0.0001	0.0001	2	1.00	0.014	0.022
0.67	256	16	64	0.0001	0.0001	3	1.00	0.014	0.023
0.67	256	16	256	1.0000	1.0000	2	0.00	0.001	0.015
0.67	256	16	256	1.0000	1.0000	3	0.00	0.110	0.256
0.67	256	16	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	16	256	1.0000	0.0100	3	0.00	0.069	0.204
0.67	256	16	256	1.0000	0.0001	2	0.33	0.001	0.052
0.67	256	16	256	1.0000	0.0001	3	1.00	0.049	0.213
0.67	256	16	256	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256 256	16 16	256	0.0100	1.0000	2	0.00	0.122	0.576
0.67	256	16	256 256	0.0100	0.0100	3	0.50 1.00	0.001	0.062 0.107
0.67	256	16	256	0.0100	0.0001	2	1.00	0.052	0.107
0.67	256	16	256	0.0100	0.0001	3	1.00	0.063	0.065
0.67	256	16	256	0.0001	1.0000	2	0.00	0.001	0.028
0.67	256	16	256	0.0001	1.0000	3	0.00	0.230	1.135
0.67	256	16	256	0.0001	0.0100	2	1.00	0.069	0.102
0.67	256	16	256	0.0001	0.0100	3	1.00	0.063	0.101
0.67	256	16	256	0.0001	0.0001	2	1.00	0.078	0.127
0.67	256	16	256	0.0001	0.0001	3	1.00	0.078	0.127
0.67	256	64	1	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	64	1	1.0000	1.0000	3	0.17	0.004	0.009
0.67	256 256	64	1	1.0000	0.0100	3	0.00	0.001	0.001
0.67	256	64	1	1.0000	0.0100	2	0.00	0.006	0.010 0.001
0.67	256	64	1	1.0000	0.0001	3	0.00	0.001	0.001
0.67	256	64	1	0.0100	1.0000	2	0.00	0.000	0.010
0.67	256	64	1	0.0100	1.0000	3	0.00	0.007	0.001
0.67	256	64	1	0.0100	0.0100	2	0.00	0.001	0.001
0.67	256	64	1	0.0100	0.0100	3	0.00	0.005	0.033
0.67	256	64	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	256	64	1	0.0100	0.0001	3	0.17	0.007	0.027
0.67	256	64	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	256	64	1	0.0001	1.0000	3	0.00	0.007	0.013
0.67	256	64	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	256	64	1	0.0001	0.0100	3	0.33	0.005	0.011
0.67	256	64	1	0.0001	0.0001	2	0.00	0.001	0.001
0.67	256 256	64	4	0.0001 1.0000	1.0000	2	0.17	0.004	0.007
0.67	256	64	4	1.0000	1.0000	3	0.00	0.001	0.001
0.67	256	64	4	1.0000	0.0100	2	0.17	0.003	0.003
0.67	256	64	4	1.0000	0.0100	3	0.50	0.004	0.013
0.67	256	64	4	1.0000	0.0001	2	0.17	0.001	0.003
0.67	256	64	4	1.0000	0.0001	3	0.33	0.003	0.011
0.67	256	64	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	64	4	0.0100	1.0000	3	0.33	0.003	0.011
0.67	256	64	4	0.0100	0.0100	2	0.33	0.001	0.003
0.67	256	64	4	0.0100	0.0100	3	0.67	0.003	0.007
0.67	256	64	4	0.0100	0.0001	2	0.50	0.001	0.003
0.67	256	64	4	0.0100	0.0001	3	0.83	0.003	0.010
0.67	256 256	64	4	0.0001	1.0000	3	1.00	0.003	0.003
0.67	256	64	4	0.0001	1.0000 0.0100	2	1.00 0.83	0.003	0.003
0.67	256	64	4	0.0001	0.0100	3	0.83	0.001	0.004
0.67	256	64	4	0.0001	0.0001	2	0.67	0.003	0.004
0.67	256	64	4	0.0001	0.0001	3	0.83	0.003	0.004
0.67	256	64	16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	64	16	1.0000	1.0000	3	0.17	0.006	0.015
0.67	256	64	16	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	64	16	1.0000	0.0100	3	0.17	0.008	0.030
0.67	256	64	16	1.0000	0.0001	2	0.17	0.001	0.005
0.67	256	64	16	1.0000	0.0001	3	0.83	0.004	0.018
0.67	256	64	16	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256 256	64	16	0.0100	1.0000	3	0.17	0.004	0.019
0.67	136	64	16 16	0.0100	0.0100	2	0.67	0.001	0.006
0.67		(1		0.0100	0.0100	2	1.00 0.83	0.004	0.007 0.007
0.67	256	64		0.0100					
0.07	256 256	64	16	0.0100					
0.67	256 256 256	64 64	16 16	0.0100	0.0001	3	1.00	0.005	0.007
0.67	256 256 256 256	64 64 64	16 16 16	0.0100 0.0001	0.0001 1.0000	3 2	1.00 0.33	0.005 0.001	0.007 0.006
0.67 0.67 0.67	256 256 256 256 256	64 64	16 16	0.0100 0.0001 0.0001	0.0001 1.0000 1.0000	3 2 3	1.00 0.33 0.33	0.005	0.007 0.006 0.035
0.67	256 256 256 256	64 64 64 64	16 16 16 16	0.0100 0.0001	0.0001 1.0000	3 2	1.00 0.33	0.005 0.001 0.004	0.007 0.006
0.67 0.67	256 256 256 256 256 256	64 64 64 64	16 16 16 16 16	0.0100 0.0001 0.0001 0.0001	0.0001 1.0000 1.0000 0.0100	3 2 3 2	1.00 0.33 0.33 1.00	0.005 0.001 0.004 0.005	0.007 0.006 0.035 0.007
0.67 0.67 0.67	256 256 256 256 256 256 256 256	64 64 64 64 64 64	16 16 16 16 16 16	0.0100 0.0001 0.0001 0.0001 0.0001	0.0001 1.0000 1.0000 0.0100 0.0100	3 2 3 2 3	1.00 0.33 0.33 1.00 1.00	0.005 0.001 0.004 0.005 0.005	0.007 0.006 0.035 0.007 0.006
0.67 0.67 0.67 0.67	256 256 256 256 256 256 256 256 256	64 64 64 64 64 64	16 16 16 16 16 16 16	0.0100 0.0001 0.0001 0.0001 0.0001	0.0001 1.0000 1.0000 0.0100 0.0100 0.0001	3 2 3 2 3 2	1.00 0.33 0.33 1.00 1.00	0.005 0.001 0.004 0.005 0.005 0.005	0.007 0.006 0.035 0.007 0.006

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	256	64	64	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	64	64	1.0000	0.0100	3	0.00	0.015	0.983
0.67	256	64	64	1.0000	0.0001	2	0.33	0.001	0.011
0.67	256 256	64	64	1.0000 0.0100	0.0001 1.0000	3	0.00	0.010	0.021
0.67	256	64	64	0.0100	1.0000	3	0.00	0.001	0.056
0.67	256	64	64	0.0100	0.0100	2	0.50	0.001	0.011
0.67	256	64	64	0.0100	0.0100	3	1.00	0.010	0.013
0.67	256	64	64	0.0100	0.0001	2	1.00	0.012	0.014
0.67	256	64	64	0.0100	0.0001	3	1.00	0.012	0.017
0.67	256	64	64 64	0.0001	1.0000	2	0.00	0.001	0.007
0.67	256 256	64	64	0.0001 0.0001	1.0000 0.0100	2	0.00 1.00	0.022 0.012	0.088
0.67	256	64	64	0.0001	0.0100	3	1.00	0.012	0.014
0.67	256	64	64	0.0001	0.0001	2	1.00	0.015	0.018
0.67	256	64	64	0.0001	0.0001	3	1.00	0.013	0.017
0.67	256	64	256	1.0000	1.0000	2	0.00	0.001	0.017
0.67	256	64	256	1.0000	1.0000	3	0.00	0.055	0.249
0.67	256 256	64 64	256 256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	64	256	1.0000	0.0100	2	0.17	0.030	0.119
0.67	256	64	256	1.0000	0.0001	3	1.00	0.050	0.074
0.67	256	64	256	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	64	256	0.0100	1.0000	3	0.00	0.135	0.525
0.67	256	64	256	0.0100	0.0100	2	0.50	0.001	0.080
0.67	256	64	256	0.0100	0.0100	3	1.00	0.051	0.080
0.67	256 256	64	256 256	0.0100	0.0001	3	1.00	0.060	0.097 0.097
0.67	256	64	256	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	64	256	0.0001	1.0000	3	0.00	0.273	0.584
0.67	256	64	256	0.0001	0.0100	2	1.00	0.060	0.090
0.67	256	64	256	0.0001	0.0100	3	1.00	0.061	0.078
0.67	256	64	256	0.0001	0.0001	2	1.00	0.075	0.108
0.67	256 256	64 256	256 1	0.0001 1.0000	0.0001 1.0000	3 2	1.00 0.00	0.075 0.001	0.114
0.67	256	256	1	1.0000	1.0000	3	0.00	0.001	0.001
0.67	256	256	1	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	256	1	1.0000	0.0100	3	0.17	0.004	0.008
0.67	256	256	1	1.0000	0.0001	2	0.00	0.001	0.001
0.67	256	256	1	1.0000	0.0001	3	0.00	0.005	0.010
0.67	256 256	256 256	1	0.0100	1.0000	3	0.00	0.001	0.001
0.67	256	256	1	0.0100	0.0100	2	0.17	0.003	0.008
0.67	256	256	1	0.0100	0.0100	3	0.00	0.006	0.043
0.67	256	256	1	0.0100	0.0001	2	0.00	0.001	0.001
0.67	256	256	1	0.0100	0.0001	3	0.17	0.005	0.014
0.67	256	256	1	0.0001	1.0000	2	0.00	0.001	0.001
0.67	256	256	1	0.0001	1.0000	3	0.00	0.007	0.011
0.67	256 256	256 256	1	0.0001	0.0100	2	0.00	0.001	0.001
0.67	256	256	1	0.0001	0.0001	2	0.00	0.000	0.007
0.67	256	256	1	0.0001	0.0001	3	0.00	0.005	0.009
0.67	256	256	4	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	256	4	1.0000	1.0000	3	0.00	0.007	0.032
0.67	256	256	4	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256 256	256 256	4	1.0000	0.0100	3	0.00	0.007	0.021
0.67	256	256	4	1.0000	0.0001	3	0.00	0.001	0.001
0.67	256	256	4	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	256	4	0.0100	1.0000	3	0.50	0.004	0.018
0.67	256	256	4	0.0100	0.0100	2	0.50	0.001	0.004
0.67	256	256	4	0.0100	0.0100	3	0.50	0.003	0.011
0.67	256	256	4	0.0100	0.0001	2	0.50	0.001	0.004
0.67	256 256	256 256	4	0.0100	0.0001 1.0000	3	0.50	0.004	0.013
0.67	256	256	4	0.0001	1.0000	3	0.67	0.001	0.004
0.67	256	256	4	0.0001	0.0100	2	0.67	0.001	0.003
0.67	256	256	4	0.0001	0.0100	3	0.67	0.003	0.010
0.67	256	256	4	0.0001	0.0001	2	0.83	0.001	0.004
0.67	256	256	4	0.0001	0.0001	3	1.00	0.003	0.007
0.67	256 256	256 256	16 16	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	256	16	1.0000	0.0100	2	0.17	0.004	0.013
0.67	256	256	16	1.0000	0.0100	3	0.50	0.001	0.001
0.67	256	256	16	1.0000	0.0001	2	0.50	0.001	0.006
0.67	256	256	16	1.0000	0.0001	3	0.83	0.006	0.020

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
0.67	256	256	16	0.0100	1.0000	2	0.00	0.001	0.045
0.67	256	256	16	0.0100	1.0000	3	0.17	0.006	0.055
0.67	256	256	16	0.0100	0.0100	2	0.33	0.001	0.006
0.67	256 256	256 256	16 16	0.0100	0.0100	3	1.00 0.83	0.005	0.014
0.67	256	256	16	0.0100	0.0001	3	1.00	0.001	0.007
0.67	256	256	16	0.0100	1.0000	2	0.67	0.003	0.007
0.67	256	256	16	0.0001	1.0000	3	0.83	0.006	0.013
0.67	256	256	16	0.0001	0.0100	2	1.00	0.006	0.007
0.67	256	256	16	0.0001	0.0100	3	1.00	0.006	0.007
0.67	256	256	16	0.0001	0.0001	2	1.00	0.005	0.007
0.67	256	256	16	0.0001	0.0001	3	1.00	0.006	0.007
0.67	256	256	64	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	256 256	64	1.0000	1.0000	3	0.00	0.018	0.026
0.67	256 256	256	64	1.0000	0.0100	3	0.00	0.001	0.001
0.67	256	256	64	1.0000	0.0001	2	0.17	0.003	0.010
0.67	256	256	64	1.0000	0.0001	3	1.00	0.011	0.040
0.67	256	256	64	0.0100	1.0000	2	0.00	0.001	0.001
0.67	256	256	64	0.0100	1.0000	3	0.00	0.028	0.040
0.67	256	256	64	0.0100	0.0100	2	0.67	0.001	0.011
0.67	256	256	64	0.0100	0.0100	3	1.00	0.009	0.012
0.67	256	256	64	0.0100	0.0001	2	0.83	0.001	0.019
0.67	256	256	64	0.0100	0.0001	3	1.00	0.018	0.020
0.67	256	256	64	0.0001	1.0000	2	0.17	0.001	0.011
0.67	256 256	256 256	64 64	0.0001	1.0000 0.0100	3	0.17 1.00	0.011	0.088
0.67	256	256	64	0.0001	0.0100	3	1.00	0.012	0.019
0.67	256	256	64	0.0001	0.0001	2	1.00	0.012	0.019
0.67	256	256	64	0.0001	0.0001	3	1.00	0.013	0.016
0.67	256	256	256	1.0000	1.0000	2	0.00	0.001	0.001
0.67	256	256	256	1.0000	1.0000	3	0.00	0.059	0.165
0.67	256	256	256	1.0000	0.0100	2	0.00	0.001	0.001
0.67	256	256	256	1.0000	0.0100	3	0.17	0.037	0.396
0.67	256	256	256	1.0000	0.0001	2	0.67	0.001	0.126
0.67	256	256	256	1.0000	0.0001	3	1.00	0.053	0.085
0.67	256	256	256	0.0100	1.0000	2	0.00	0.001	0.017
0.67	256 256	256 256	256 256	0.0100	1.0000 0.0100	3	0.00	0.077	0.302
0.67	256	256	256	0.0100	0.0100	3	1.00	0.001	0.083
0.67	256	256	256	0.0100	0.0001	2	1.00	0.060	0.098
0.67	256	256	256	0.0100	0.0001	3	1.00	0.060	0.098
0.67	256	256	256	0.0001	1.0000	2	0.00	0.001	0.001
0.67	256	256	256	0.0001	1.0000	3	0.00	0.107	0.414
0.67	256	256	256	0.0001	0.0100	2	1.00	0.065	0.069
0.67	256	256	256	0.0001	0.0100	3	1.00	0.062	0.069
0.67	256	256	256	0.0001	0.0001	2	1.00	0.078	0.124
0.67 1.00	256	256	256	0.0001	0.0001 1.0000	2	0.00	0.076	0.127
1.00	1	1	1	1.0000	1.0000	3	0.00	0.001	0.001
1.00	1	1	1	1.0000	0.0100	2	0.00	0.002	0.000
1.00	1	1	1	1.0000	0.0100	3	0.00	0.001	0.002
1.00	1	1	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	1	1	1	1.0000	0.0001	3	0.00	0.002	0.002
1.00	1	1	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	1	1	0.0100	1.0000	3	0.00	0.003	0.042
1.00	1	1	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	1	1	1	0.0100	0.0100	3	0.00	0.002	0.003
1.00	1	1	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	1	1	1	0.0100	0.0001 1.0000	3	0.00	0.002	0.036
1.00	1	1	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	1	1	1	0.0001	0.0100	2	0.00	0.003	0.001
1.00	1	1	1	0.0001	0.0100	3	0.00	0.002	0.003
1.00	1	1	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	1	1	1	0.0001	0.0001	3	0.00	0.002	0.003
1.00	1	1	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	1	4	1.0000	1.0000	3	0.00	0.002	0.009
1.00	1	1	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	1	4	1.0000	0.0100	2	0.17	0.002	0.019
1.00	1	1	4	1.0000	0.0001	3	0.17	0.001	0.004
1.00		1	4	0.0100	1.0000	2	0.00	0.003	0.001
						_			
1.00	1	1	4	0.0100	1.0000	3	0.00	0.010	0.020
1.00					1.0000 0.0100	3 2	0.00	0.010 0.001	0.020 0.004

mul	m_1	m_2		TR	DTR	alg	SR	mint	maxt
1.00	1	1	4	0.0100	0.0001	2	0.67	0.001	0.004
1.00	1	1	4	0.0100	0.0001	3	0.83	0.001	0.004
1.00	1	1	4	0.0001	1.0000	2	0.00	0.001	0.001
1.00	1	1	4	0.0001	1.0000	3	0.00	0.002	0.014
1.00	1	1	4	0.0001	0.0100	2	0.67	0.001	0.003
1.00	1	1	4	0.0001	0.0100	3	0.83	0.002	0.003
1.00	1	1	4	0.0001	0.0001	2	0.83	0.001	0.003
1.00	1	1	4	0.0001	0.0001	3	1.00	0.003	0.017
1.00	1	1	16	1.0000	1.0000	2	0.00	0.001	0.002
1.00	1	1	16 16	1.0000	1.0000 0.0100	3	0.00	0.021	0.024
1.00	1	1	16	1.0000	0.0100	3	0.17	0.001	0.004
1.00	1	1	16	1.0000	0.0001	2	0.67	0.001	0.005
1.00	1	1	16	1.0000	0.0001	3	1.00	0.004	0.011
1.00	1	1	16	0.0100	1.0000	2	0.00	0.001	0.002
1.00	1	1	16	0.0100	1.0000	3	0.00	0.026	0.033
1.00	1	1	16	0.0100	0.0100	2	1.00	0.004	0.006
1.00	1	1	16	0.0100	0.0100	3	1.00	0.004	0.006
1.00	1	1	16	0.0100	0.0001	2	1.00	0.006	0.006
1.00	1	1	16	0.0100	0.0001	3	1.00	0.006	0.006
1.00	1	1	16	0.0001	1.0000	2	0.00	0.001	0.003
1.00	1	1	16 16	0.0001	1.0000 0.0100	3	0.00 1.00	0.034	0.047
1.00	1	1	16	0.0001	0.0100	3	1.00	0.004	0.007
1.00	1	1	16	0.0001	0.0100	2	1.00	0.003	0.007
1.00	1	1	16	0.0001	0.0001	3	1.00	0.005	0.007
1.00	1	1	64	1.0000	1.0000	2	0.00	0.003	0.004
1.00	1	1	64	1.0000	1.0000	3	0.00	0.046	0.061
1.00	1	1	64	1.0000	0.0100	2	0.00	0.001	0.054
1.00	1	1	64	1.0000	0.0100	3	0.00	0.056	0.069
1.00	1	1	64	1.0000	0.0001	2	1.00	0.009	0.014
1.00	1	1	64	1.0000	0.0001	3	1.00	0.009	0.014
1.00	1	1	64	0.0100	1.0000	2	0.00	0.004	0.005
1.00	1	1	64	0.0100	1.0000	3	0.00	0.062	0.069
1.00	1	1	64	0.0100	0.0100	3	1.00	0.009	0.011
1.00	1	1	64	0.0100	0.0100	2	1.00	0.009	0.020
1.00	1	1	64	0.0100	0.0001	3	1.00	0.011	0.013
1.00	1	1	64	0.0001	1.0000	2	0.00	0.005	0.009
1.00	1	1	64	0.0001	1.0000	3	0.00	0.086	1.500
1.00	1	1	64	0.0001	0.0100	2	1.00	0.017	0.018
1.00	1	1	64	0.0001	0.0100	3	1.00	0.016	0.018
1.00	1	1	64	0.0001	0.0001	2	1.00	0.017	0.022
1.00	1	1	64	0.0001	0.0001	3	1.00	0.015	0.022
1.00	1	1	256	1.0000	1.0000	2	0.00	0.011	0.017
1.00	1	1	256	1.0000	1.0000	3	0.00	0.179	0.280
1.00	1	1	256 256	1.0000	0.0100	3	0.00	0.018	0.026 0.325
1.00	1	1	256	1.0000	0.0100	2	1.00	0.299	0.323
1.00	1	1	256	1.0000	0.0001	3	1.00	0.048	0.064
1.00	1	1	256	0.0100	1.0000	2	0.00	0.019	0.030
1.00	1	1	256	0.0100	1.0000	3	0.00	0.316	0.575
1.00	1	1	256	0.0100	0.0100	2	0.00	0.024	0.033
1.00	1	1	256	0.0100	0.0100	3	0.00	0.405	1.022
1.00	1	1	256	0.0100	0.0001	2	1.00	0.064	0.101
1.00	1	1	256	0.0100	0.0001	3	1.00	0.064	0.100
1.00	1	1	256	0.0001	1.0000	2	0.00	0.027	0.042
1.00	1	1	256 256	0.0001	1.0000 0.0100	3	0.00	0.550	1.266
1.00	1	1	256	0.0001	0.0100	3	0.00	0.001	0.001
1.00	1	1	256	0.0001	0.0100	2	1.00	0.344	0.766
1.00	1	1	256	0.0001	0.0001	3	1.00	0.079	0.128
1.00	1	4	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	4	1	1.0000	1.0000	3	0.00	0.002	0.007
1.00	1	4	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	4	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	1	4	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	1	4	1	1.0000	0.0001	3	0.00	0.002	0.002
1.00	1	4	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	4	1	0.0100	1.0000	3	0.00	0.002	0.002
1.00	1	4	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	1	4	1	0.0100	0.0100	3	0.00	0.002	0.002
1.00	1	4	1	0.0100	0.0001	3	0.00	0.001	0.001
1.00	1	4	1	0.0001	1.0000	2	0.00	0.002	0.001
1.00	1	4	1	0.0001	1.0000	3	0.00	0.001	0.001
2.00		<u> </u>		2.0001	0000		2.00	002	3.002

1.00	mul	m_1	m_2	au	TR	DTR	alg	SR	mint	maxt
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00	1.00	1	4	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00										
1.00			-							
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00		1	4	4						
1.00	1.00	1	4	4	0.0001	0.0100	3	0.83	0.002	0.004
1.00	1.00	1	4	4	0.0001	0.0001	2	0.67	0.001	0.004
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00			4							
1.00		1				0.0100	2			0.006
1.00		1		16	0.0100	0.0100		1.00	0.005	0.006
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00										
1.00	1.00	1	4	64	1.0000	1.0000	3	0.00	0.046	0.063
1.00		1	4		1.0000	0.0100	2			
1.00										
1.00										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$		1								
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$										
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										
1.00 1 4 256 0.0001 1.0000 3 0.00 0.409 1.047 1.00 1 4 256 0.0001 0.0100 2 1.00 0.058 0.095 1.00 1 4 256 0.0001 0.0100 3 1.00 0.058 0.097 1.00 1 4 256 0.0001 0.0001 2 1.00 0.108 0.128										
1.00 1 4 256 0.0001 0.0100 2 1.00 0.058 0.095 1.00 1 4 256 0.0001 0.0100 3 1.00 0.058 0.097 1.00 1 4 256 0.0001 0.0001 2 1.00 0.108 0.128										
1.00 1 4 256 0.0001 0.0100 3 1.00 0.058 0.097 1.00 1 4 256 0.0001 0.0001 2 1.00 0.108 0.128										
1.00 1 4 256 0.0001 0.0001 2 1.00 0.108 0.128										
1.00 1 4 256 0.0001 0.0001 3 1.00 0.119 0.126										
			4							

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	1	16	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	16	1	1.0000	1.0000	3	0.00	0.002	0.002
1.00	1	16	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	16 16	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	1	16	1	1.0000	0.0001	3	0.00	0.001	0.001
1.00	1	16	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	16	1	0.0100	1.0000	3	0.00	0.002	0.039
1.00	1	16	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	1	16 16	1	0.0100	0.0100	3	0.00	0.002	0.003
1.00	1	16	1	0.0100	0.0001	3	0.00	0.001	0.001
1.00	1	16	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	1	16	1	0.0001	1.0000	3	0.00	0.002	0.006
1.00	1	16	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	1	16 16	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00	1	16	1	0.0001	0.0001	3	0.00	0.001	0.001
1.00	1	16	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	16	4	1.0000	1.0000	3	0.00	0.002	0.021
1.00	1	16	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	16 16	4	1.0000	0.0100	3	0.00	0.002	0.010
1.00	1	16	4	1.0000	0.0001	3	0.00	0.001	0.001
1.00	1	16	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	16	4	0.0100	1.0000	3	0.00	0.002	0.013
1.00	1	16	4	0.0100	0.0100	2	0.17	0.001	0.003
1.00	1	16 16	4	0.0100	0.0100	3	0.33	0.002	0.013
1.00	1	16	4	0.0100	0.0001	3	0.33	0.001	0.001
1.00	1	16	4	0.0001	1.0000	2	0.33	0.001	0.004
1.00	1	16	4	0.0001	1.0000	3	0.33	0.002	0.024
1.00	1	16	4	0.0001	0.0100	2	1.00	0.003	0.004
1.00	1	16 16	4	0.0001	0.0100	3	1.00 0.33	0.003	0.004
1.00	1	16	4	0.0001	0.0001	3	0.50	0.001	0.004
1.00	1	16	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	16	16	1.0000	1.0000	3	0.00	0.002	0.253
1.00	1	16	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	16 16	16 16	1.0000	0.0100	3	0.00	0.002	0.021
1.00	1	16	16	1.0000	0.0001	3	0.50	0.001	0.023
1.00	1	16	16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	16	16	0.0100	1.0000	3	0.00	0.002	0.015
1.00	1	16	16	0.0100	0.0100	3	0.83	0.001	0.005
1.00	1	16 16	16 16	0.0100	0.0100	2	0.83	0.004	0.014
1.00	1	16	16	0.0100	0.0001	3	1.00	0.005	0.005
1.00	1	16	16	0.0001	1.0000	2	0.00	0.001	0.001
1.00	1	16	16	0.0001	1.0000	3	0.00	0.002	0.017
1.00	1	16 16	16 16	0.0001	0.0100	3	1.00	0.004	0.005
1.00	1	16	16	0.0001	0.0100	2	0.83	0.004	0.005
1.00	1	16	16	0.0001	0.0001	3	1.00	0.005	0.005
1.00	1	16	64	1.0000	1.0000	2	0.00	0.001	0.004
1.00	1	16	64	1.0000	1.0000	3	0.00	0.036	0.058
1.00	1	16 16	64	1.0000	0.0100	3	0.00	0.001	0.001
1.00	1	16	64	1.0000	0.0001	2	0.33	0.002	0.010
1.00	1	16	64	1.0000	0.0001	3	1.00	0.010	0.031
1.00	1	16	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	16 16	64	0.0100	1.0000 0.0100	3	0.00 1.00	0.065	0.081
1.00	1	16	64	0.0100	0.0100	3	1.00	0.010	0.015
1.00	1	16	64	0.0100	0.0001	2	1.00	0.016	0.018
1.00	1	16	64	0.0100	0.0001	3	1.00	0.017	0.018
1.00	1	16	64	0.0001	1.0000	2	0.00	0.001	0.009
1.00	1	16 16	64	0.0001	1.0000 0.0100	3 2	0.00 1.00	0.084	0.133
1.00	1	16	64	0.0001	0.0100	3	1.00	0.014	0.018
1.00	1	16	64	0.0001	0.0001	2	1.00	0.015	0.018
1.00	1	16	64	0.0001	0.0001	3	1.00	0.013	0.015
1.00	1	16	256	1.0000	1.0000	2	0.00	0.011	0.014
1.00	1	16 16	256 256	1.0000	1.0000 0.0100	3	0.00	0.180	0.937
1.00	1	16	256	1.0000	0.0100	3	0.00	0.104	0.382

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	1	16	256	1.0000	0.0001	2	1.00	0.045	0.074
1.00	1	16	256	1.0000	0.0001	3	1.00	0.047	0.079
1.00	1	16	256	0.0100	1.0000	2	0.00	0.016	0.026
1.00	1	16	256	0.0100	1.0000	3	0.00	0.272	1.135
1.00	1	16	256	0.0100	0.0100	2	0.83	0.001	0.053
1.00	1	16 16	256 256	0.0100	0.0100	2	1.00	0.049	0.054
1.00	1	16	256	0.0100	0.0001	3	1.00	0.059	0.062
1.00	1	16	256	0.0001	1.0000	2	0.00	0.026	0.039
1.00	1	16	256	0.0001	1.0000	3	0.00	0.442	1.003
1.00	1	16	256	0.0001	0.0100	2	1.00	0.060	0.070
1.00	1	16	256	0.0001	0.0100	3	1.00	0.063	0.075
1.00	1	16	256	0.0001	0.0001	2	1.00	0.079	0.097
1.00	1	16	256	0.0001	0.0001	3	1.00	0.078	0.084
1.00	1	64	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	64	1	1.0000	1.0000 0.0100	3	0.00	0.002	0.002
1.00	1	64	1	1.0000	0.0100	3	0.00	0.001	0.001
1.00	1	64	1	1.0000	0.0001	2	0.00	0.002	0.002
1.00	1	64	1	1.0000	0.0001	3	0.00	0.002	0.002
1.00	1	64	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	64	1	0.0100	1.0000	3	0.00	0.002	0.036
1.00	1	64	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	1	64	1	0.0100	0.0100	3	0.00	0.002	0.002
1.00	1	64	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	1	64	1	0.0100	0.0001	2	0.00	0.002	0.002
1.00	1	64	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	1	64	1	0.0001	0.0100	2	0.00	0.002	0.002
1.00	1	64	1	0.0001	0.0100	3	0.00	0.002	0.041
1.00	1	64	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	1	64	1	0.0001	0.0001	3	0.00	0.002	0.003
1.00	1	64	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	64	4	1.0000	1.0000	3	0.00	0.002	0.003
1.00	1	64	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	64	4	1.0000	0.0100	2	0.00	0.002	0.013
1.00	1	64	4	1.0000	0.0001	3	0.00	0.001	0.001
1.00	1	64	4	0.0100	1.0000	2	0.00	0.002	0.020
1.00	1	64	4	0.0100	1.0000	3	0.00	0.002	0.030
1.00	1	64	4	0.0100	0.0100	2	0.17	0.001	0.004
1.00	1	64	4	0.0100	0.0100	3	0.17	0.002	0.019
1.00	1	64	4	0.0100	0.0001	2	0.33	0.001	0.004
1.00	1	64	4	0.0100	0.0001	3	0.50	0.002	0.014
1.00	1	64	4	0.0001	1.0000	2	0.50	0.001	0.004
1.00	1	64	4	0.0001	1.0000 0.0100	3	0.67	0.002	0.008
1.00	1	64	4	0.0001	0.0100	3	0.67	0.001	0.004
1.00	1	64	4	0.0001	0.0001	2	0.83	0.002	0.004
1.00	1	64	4	0.0001	0.0001	3	0.83	0.002	0.004
1.00	1	64	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	64	16	1.0000	1.0000	3	0.00	0.002	0.016
1.00	1	64	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	64	16	1.0000	0.0100	3	0.00	0.002	0.026
1.00	1	64	16 16	1.0000	0.0001	3	0.17	0.001	0.006
1.00	1	64	16	0.0100	1.00001	2	0.00	0.002	0.034
1.00	1	64	16	0.0100	1.0000	3	0.00	0.001	0.001
1.00	1	64	16	0.0100	0.0100	2	0.67	0.001	0.006
1.00	1	64	16	0.0100	0.0100	3	0.83	0.002	0.006
1.00	1	64	16	0.0100	0.0001	2	0.67	0.001	0.007
1.00	1	64	16	0.0100	0.0001	3	0.67	0.006	0.012
1.00	1	64	16	0.0001	1.0000	2	0.17	0.001	0.005
1.00	1	64	16	0.0001	1.0000	3	0.17	0.002	0.017
1.00	1	64	16 16	0.0001	0.0100	2	1.00	0.004	0.006
1.00	1	64	16	0.0001	0.0100	2	1.00	0.004	0.005
1.00	1	64	16	0.0001	0.0001	3	1.00	0.005	0.006
1.00	1	64	64	1.0000	1.0000	2	0.00	0.003	0.001
1.00	1	64	64	1.0000	1.0000	3	0.00	0.002	0.033
1.00	1	64	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	64	64	1.0000	0.0100	3	0.00	0.002	0.016
1.00	1	64	64	1.0000	0.0001	2	0.33	0.001	0.012
1.00	1	64	64	1.0000	0.0001	3	0.67	0.010	0.042
1.00	1	64	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	64	64	0.0100	1.0000	3	0.00	0.017	0.046

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	1	64	64	0.0100	0.0100	2	0.83	0.001	0.016
1.00	1	64	64	0.0100	0.0100	3	1.00	0.010	0.016
1.00	1	64	64	0.0100	0.0001	2	1.00	0.012	0.429
1.00	1	64	64	0.0100	1.0000	3	0.00	0.011	0.018
1.00	1	64	64	0.0001	1.0000	3	0.00	0.002	0.082
1.00	1	64	64	0.0001	0.0100	2	1.00	0.013	0.019
1.00	1	64	64	0.0001	0.0100	3	1.00	0.013	0.019
1.00	1	64	64	0.0001	0.0001	2	1.00	0.021	0.030
1.00	1	64	64	0.0001	0.0001	3	0.00	0.020	0.022
1.00	1	64	256 256	1.0000	1.0000	3	0.00	0.001	0.015
1.00	1	64	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	64	256	1.0000	0.0100	3	0.00	0.002	0.196
1.00	1	64	256	1.0000	0.0001	2	0.67	0.001	0.076
1.00	1	64	256	1.0000	0.0001	3	0.83	0.053	0.144
1.00	1	64	256	0.0100	1.0000	2	0.00	0.001	0.026
1.00	1	64	256 256	0.0100	1.0000 0.0100	3	0.00	0.212	1.132 0.070
1.00	1	64	256	0.0100	0.0100	3	1.00	0.001	0.078
1.00	1	64	256	0.0100	0.0001	2	1.00	0.064	0.097
1.00	1	64	256	0.0100	0.0001	3	1.00	0.064	0.097
1.00	1	64	256	0.0001	1.0000	2	0.00	0.001	0.041
1.00	1	64	256	0.0001	1.0000	3	0.00	0.402	0.983
1.00	1	64	256	0.0001	0.0100	3	1.00	0.065	0.067
1.00	1	64	256 256	0.0001	0.0100	2	1.00	0.064	0.068
1.00	1	64	256	0.0001	0.0001	3	1.00	0.076	0.081
1.00	1	256	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	256	1	1.0000	1.0000	3	0.00	0.002	0.010
1.00	1	256	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	256	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	1	256 256	1	1.0000	0.0001	3	0.00	0.001	0.001
1.00	1	256	1	0.0100	1.0000	2	0.00	0.002	0.002
1.00	1	256	1	0.0100	1.0000	3	0.00	0.002	0.038
1.00	1	256	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	1	256	1	0.0100	0.0100	3	0.00	0.002	0.002
1.00	1	256	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	1	256 256	1	0.0100	0.0001 1.0000	3	0.00	0.002	0.043
1.00	1	256	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	1	256	1	0.0001	0.0100	2	0.00	0.002	0.001
1.00	1	256	1	0.0001	0.0100	3	0.00	0.002	0.031
1.00	1	256	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	1	256	1	0.0001	0.0001	3	0.00	0.002	0.004
1.00	1	256	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	256 256	4	1.0000	1.0000 0.0100	3	0.00	0.002	0.006
1.00	1	256	4	1.0000	0.0100	3	0.00	0.001	0.001
1.00	1	256	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	1	256	4	1.0000	0.0001	3	0.00	0.002	0.016
1.00	1	256	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	256	4	0.0100	1.0000	3	0.00	0.002	0.011
1.00	1	256 256	4	0.0100	0.0100	3	0.33	0.001	0.003
1.00	1	256	4	0.0100	0.0100	2	0.33	0.002	0.000
1.00	1	256	4	0.0100	0.0001	3	0.00	0.001	0.001
1.00	1	256	4	0.0001	1.0000	2	0.17	0.001	0.003
1.00	1	256	4	0.0001	1.0000	3	0.17	0.002	0.008
1.00	1	256	4	0.0001	0.0100	2	0.67	0.001	0.004
1.00	1	256 256	4	0.0001	0.0100	3	1.00 0.67	0.003	0.004
1.00	1	256	4	0.0001	0.0001	3	1.00	0.001	0.004
1.00	1	256	16	1.0000	1.0000	2	0.00	0.004	0.004
1.00	1	256	16	1.0000	1.0000	3	0.00	0.002	0.002
1.00	1	256	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	256	16	1.0000	0.0100	3	0.00	0.002	0.699
1.00	1	256	16	1.0000	0.0001	2	0.33	0.001	0.006
1.00	1	256 256	16 16	1.0000 0.0100	1.0000	3	0.83	0.005	0.010
	1		16	0.0100	1.0000	3	0.00	0.001	0.001
1.00		256					2.00	2	
1.00	1	256 256	16	0.0100	0.0100	2	0.50	0.001	0.006
	1				0.0100	3	0.50 1.00	0.001 0.006	0.006 0.006
1.00	1	256	16	0.0100					

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	1	256	16	0.0001	1.0000	2	0.00	0.001	0.001
1.00	1	256	16	0.0001	1.0000	3	0.17	0.002	0.010
1.00	1	256 256	16 16	0.0001	0.0100	3	1.00	0.005	0.006
1.00	1	256	16	0.0001	0.0001	2	1.00	0.005	0.006
1.00	1	256	16	0.0001	0.0001	3	1.00	0.005	0.006
1.00	1	256	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	1	256	64	1.0000	1.0000	3	0.00	0.002	0.052
1.00	1	256	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	1	256 256	64	1.0000	0.0100	3	0.00	0.002	0.069
1.00	1	256	64	1.0000	0.0001	3	0.67	0.001	0.001
1.00	1	256	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	1	256	64	0.0100	1.0000	3	0.00	0.002	0.070
1.00	1	256	64	0.0100	0.0100	2	0.67	0.001	0.016
1.00	1	256	64	0.0100	0.0100	3	1.00	0.013	0.017
1.00	1	256 256	64	0.0100	0.0001	3	1.00	0.012 0.012	0.018 0.017
1.00	1	256	64	0.0100	1.0000	2	0.00	0.012	0.001
1.00	1	256	64	0.0001	1.0000	3	0.00	0.002	0.026
1.00	1	256	64	0.0001	0.0100	2	0.83	0.001	0.013
1.00	1	256	64	0.0001	0.0100	3	1.00	0.011	0.013
1.00	1	256	64	0.0001	0.0001	2	1.00	0.013	0.015
1.00	1	256	64	0.0001	0.0001	3	1.00	0.013	0.016
1.00	1	256 256	256 256	1.0000	1.0000	3	0.00	0.001	0.001 0.156
1.00	1	256	256	1.0000	0.0100	2	0.00	0.020	0.001
1.00	1	256	256	1.0000	0.0100	3	0.00	0.002	0.002
1.00	1	256	256	1.0000	0.0001	2	0.33	0.001	0.061
1.00	1	256	256	1.0000	0.0001	3	0.67	0.053	0.221
1.00	1	256	256	0.0100	1.0000	2	0.00	0.001	0.017
1.00	1	256 256	256 256	0.0100	1.0000 0.0100	3	0.00	0.077	0.589
1.00	1	256	256	0.0100	0.0100	3	1.00	0.001	0.080
1.00	1	256	256	0.0100	0.0001	2	0.83	0.001	0.080
1.00	1	256	256	0.0100	0.0001	3	1.00	0.061	0.097
1.00	1	256	256	0.0001	1.0000	2	0.00	0.001	0.001
1.00	1	256	256	0.0001	1.0000	3	0.00	0.089	0.343
1.00	1	256	256	0.0001	0.0100	2	1.00	0.065	0.067
1.00	1	256 256	256 256	0.0001	0.0100	3	1.00	0.065 0.078	0.073 0.085
1.00	1	256	256	0.0001	0.0001	3	1.00	0.073	0.083
1.00	4	1	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	1	1	1.0000	1.0000	3	0.00	0.002	0.003
1.00	4	1	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	4	1	1	1.0000	0.0100	3	0.00	0.002	0.003
1.00	4	1	1	1.0000	0.0001	3	0.00	0.001	0.001
1.00	4	1	1	1.0000 0.0100	1.0000	2	0.00	0.002	0.034
1.00	4	1	1	0.0100	1.0000	3	0.00	0.002	0.004
1.00	4	1	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	4	1	1	0.0100	0.0100	3	0.00	0.002	0.021
1.00	4	1	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	4	1	1	0.0100	0.0001	3	0.00	0.002	0.002
1.00	4	1	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	4	1	1	0.0001	0.0100	2	0.00	0.002	0.014
1.00	4	1	1	0.0001	0.0100	3	0.00	0.001	0.001
1.00	4	1	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	4	1	1	0.0001	0.0001	3	0.00	0.002	0.002
1.00	4	1	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	1	4	1.0000	1.0000	3	0.00	0.002	0.036
1.00	4	1	4	1.0000	0.0100	3	0.00	0.001	0.001
1.00	4	1	4	1.0000	0.0100	2	0.00	0.002	0.012
1.00	4	1	4	1.0000	0.0001	3	0.33	0.002	0.001
1.00	4	1	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	1	4	0.0100	1.0000	3	0.00	0.002	0.006
1.00	4	1	4	0.0100	0.0100	2	0.67	0.001	0.003
1.00	4	1	4	0.0100	0.0100	3	0.67	0.002	0.003
1.00	4	1	4	0.0100	0.0001	3	0.50	0.001	0.004 0.017
1.00	4	1	4	0.0100	1.0000	2	0.07	0.004	0.017
1.00	4	1	4	0.0001	1.0000	3	0.00	0.002	0.009
1.00	4	1	4	0.0001	0.0100	2	0.83	0.001	0.004
1.00	4	1	4	0.0001	0.0100	3	0.83	0.003	0.013

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	4	1	4	0.0001	0.0001	2	0.67	0.001	0.004
1.00	4	1	4	0.0001	0.0001	3	0.83	0.003	0.011
1.00	4	1	16 16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	1	16	1.0000	0.0100	2	0.00	0.001	0.020
1.00	4	1	16	1.0000	0.0100	3	0.17	0.009	0.024
1.00	4	1	16	1.0000	0.0001	2	0.33	0.001	0.004
1.00	4	1	16	1.0000	0.0001	3	1.00	0.004	0.011
1.00	4	1	16 16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	1	16	0.0100	0.0100	2	1.00	0.004	0.005
1.00	4	1	16	0.0100	0.0100	3	1.00	0.004	0.005
1.00	4	1	16	0.0100	0.0001	2	1.00	0.004	0.005
1.00	4	1	16	0.0100	0.0001	3	1.00	0.004	0.006
1.00	4	1	16 16	0.0001 0.0001	1.0000	2	0.00	0.001	0.001
1.00	4	1	16	0.0001	0.0100	2	1.00	0.023	0.006
1.00	4	1	16	0.0001	0.0100	3	1.00	0.004	0.005
1.00	4	1	16	0.0001	0.0001	2	1.00	0.005	0.006
1.00	4	1	16	0.0001	0.0001	3	1.00	0.005	0.006
1.00	4	1	64 64	1.0000	1.0000	2	0.00	0.003	0.004
1.00	4	1	64	1.0000	0.0100	2	0.00	0.044	0.046
1.00	4	1	64	1.0000	0.0100	3	0.00	0.030	0.066
1.00	4	1	64	1.0000	0.0001	2	1.00	0.009	0.014
1.00	4	1	64	1.0000	0.0001	3	1.00	0.009	0.014
1.00	4	1	64	0.0100	1.0000	3	0.00	0.004	0.006
1.00	4	1	64	0.0100	0.0100	2	1.00	0.004	0.076
1.00	4	1	64	0.0100	0.0100	3	1.00	0.010	0.015
1.00	4	1	64	0.0100	0.0001	2	1.00	0.016	0.018
1.00	4	1	64	0.0100	0.0001	3	1.00	0.016	0.018
1.00	4	1	64	0.0001	1.0000	2	0.00	0.006	0.009
1.00	4	1	64	0.0001	0.0100	2	1.00	0.011	0.130
1.00	4	1	64	0.0001	0.0100	3	1.00	0.011	0.017
1.00	4	1	64	0.0001	0.0001	2	1.00	0.013	0.030
1.00	4	1	64	0.0001	0.0001	3	1.00	0.014	0.047
1.00	4	1	256 256	1.0000	1.0000	2	0.00	0.011	0.013
1.00	4	1	256	1.0000	0.0100	2	0.00	0.180	0.200
1.00	4	1	256	1.0000	0.0100	3	0.00	0.294	0.401
1.00	4	1	256	1.0000	0.0001	2	1.00	0.044	0.051
1.00	4	1	256	1.0000	0.0001	3	1.00	0.044	0.046
1.00	4	1	256 256	0.0100	1.0000	3	0.00	0.016	0.019
1.00	4	1	256	0.0100	0.0100	2	0.50	0.288	0.758
1.00	4	1	256	0.0100	0.0100	3	0.50	0.050	0.443
1.00	4	1	256	0.0100	0.0001	2	1.00	0.092	0.098
1.00	4	1	256	0.0100	0.0001	3	1.00	0.063	0.098
1.00	4	1	256 256	0.0001	1.0000	3	0.00	0.025	0.039 0.852
1.00	4	1	256	0.0001	0.0100	2	0.83	0.422	0.832
1.00	4	1	256	0.0001	0.0100	3	0.83	0.064	0.774
1.00	4	1	256	0.0001	0.0001	2	1.00	0.074	0.081
1.00	4	1 4	256	0.0001	0.0001	3	1.00	0.073	0.087
1.00	4	4	1	1.0000	1.0000	3	0.00	0.001	0.001
1.00	4	4	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	4	4	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	4	4	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	4	4	1	1.0000 0.0100	0.0001 1.0000	3 2	0.00	0.002	0.003
1.00	4	4	1	0.0100	1.0000	3	0.00	0.001	0.001
1.00	4	4	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	4	4	1	0.0100	0.0100	3	0.00	0.003	0.031
1.00	4	4	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	4	4	1	0.0100	0.0001 1.0000	3	0.00	0.002	0.005
1.00	4	4	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	4	4	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	4	4	1	0.0001	0.0100	3	0.00	0.002	0.003
1.00	4	4	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	4	4	1 4	0.0001 1.0000	0.0001 1.0000	3	0.00	0.002	0.003
1.00	4	4	4	1.0000	1.0000	3	0.00	0.001	0.001
1.00	7	-	-	1.0000	1.0000	J	0.00	0.002	0.005

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	4	4	4	1.0000	0.0100	2	0.17	0.001	0.003
1.00	4	4	4	1.0000	0.0100	3	0.17	0.002	0.047
1.00	4	4	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	4	4	4	1.0000 0.0100	1.0000	3	0.00	0.002	0.011
1.00	4	4	4	0.0100	1.0000	3	0.00	0.001	0.001
1.00	4	4	4	0.0100	0.0100	2	0.33	0.002	0.003
1.00	4	4	4	0.0100	0.0100	3	0.33	0.003	0.012
1.00	4	4	4	0.0100	0.0001	2	0.00	0.001	0.001
1.00	4	4	4	0.0100	0.0001	3	0.33	0.002	0.008
1.00	4	4	4	0.0001	1.0000	2	0.33	0.001	0.003
1.00	4	4	4	0.0001	1.0000 0.0100	3	0.67	0.002	0.009
1.00	4	4	4	0.0001	0.0100	3	0.83	0.001	0.004
1.00	4	4	4	0.0001	0.0001	2	0.83	0.001	0.004
1.00	4	4	4	0.0001	0.0001	3	0.83	0.002	0.004
1.00	4	4	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	4	16	1.0000	1.0000	3	0.00	0.002	0.021
1.00	4	4	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	4	4	16	1.0000	0.0100	3	0.00	0.002	0.026
1.00	4	4	16 16	1.0000	0.0001	2	0.00	0.001	0.001
1.00	4	4	16	0.0100	1.00001	2	0.07	0.004	0.024
1.00	4	4	16	0.0100	1.0000	3	0.00	0.001	0.001
1.00	4	4	16	0.0100	0.0100	2	0.67	0.001	0.005
1.00	4	4	16	0.0100	0.0100	3	0.83	0.002	0.005
1.00	4	4	16	0.0100	0.0001	2	1.00	0.004	0.005
1.00	4	4	16	0.0100	0.0001	3	1.00	0.004	0.006
1.00	4	4	16	0.0001	1.0000	2	0.00	0.001	0.001
1.00	4	4	16 16	0.0001	1.0000 0.0100	3	0.00 1.00	0.009	0.022
1.00	4	4	16	0.0001	0.0100	3	1.00	0.004	0.006
1.00	4	4	16	0.0001	0.0001	2	1.00	0.004	0.006
1.00	4	4	16	0.0001	0.0001	3	1.00	0.005	0.006
1.00	4	4	64	1.0000	1.0000	2	0.00	0.001	0.003
1.00	4	4	64	1.0000	1.0000	3	0.00	0.043	0.049
1.00	4	4	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	4	4	64	1.0000	0.0100	3	0.00	0.031	0.081
1.00	4	4	64	1.0000	0.0001	3	0.83	0.001	0.015
1.00	4	4	64	1.0000 0.0100	1.0000	2	1.00 0.00	0.014	0.054
1.00	4	4	64	0.0100	1.0000	3	0.00	0.063	0.003
1.00	4	4	64	0.0100	0.0100	2	1.00	0.010	0.012
1.00	4	4	64	0.0100	0.0100	3	1.00	0.009	0.012
1.00	4	4	64	0.0100	0.0001	2	1.00	0.010	0.012
1.00	4	4	64	0.0100	0.0001	3	1.00	0.011	0.012
1.00	4	4	64	0.0001	1.0000	2	0.00	0.001	0.006
1.00	4	4	64	0.0001	1.0000	3	0.00	0.079	0.086
1.00	4	4	64	0.0001	0.0100	3	1.00	0.012	0.016
1.00	4	4	64	0.0001	0.0100	2	1.00	0.011	0.018
1.00	4	4	64	0.0001	0.0001	3	1.00	0.015	0.022
1.00	4	4	256	1.0000	1.0000	2	0.00	0.013	0.017
1.00	4	4	256	1.0000	1.0000	3	0.00	0.196	0.577
1.00	4	4	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	4	4	256	1.0000	0.0100	3	0.00	0.269	0.404
1.00	4	4	256	1.0000	0.0001	2	1.00	0.047	0.073
1.00	4	4	256 256	1.0000	0.0001 1.0000	3	1.00 0.00	0.047	0.064
1.00	4	4	256	0.0100	1.0000	3	0.00	0.016	1.142
1.00	4	4	256	0.0100	0.0100	2	1.00	0.273	0.079
1.00	4	4	256	0.0100	0.0100	3	1.00	0.065	0.078
1.00	4	4	256	0.0100	0.0001	2	1.00	0.095	0.097
1.00	4	4	256	0.0100	0.0001	3	1.00	0.089	0.096
1.00	4	4	256	0.0001	1.0000	2	0.00	0.025	0.041
1.00	4	4	256	0.0001	1.0000	3	0.00	0.422	0.914
1.00	4	4	256	0.0001	0.0100	2	1.00	0.057	0.061
1.00	4	4	256	0.0001	0.0100	3	1.00	0.058	0.075
1.00	4	4	256 256	0.0001	0.0001	3	1.00	0.117 0.119	0.127 0.127
1.00	4	16	230	1.0000	1.0000	2	0.00	0.119	0.001
1.00	4	16	1	1.0000	1.0000	3	0.00	0.001	0.465
						2	0.00	0.001	0.001
1.00	4	16	1	1.0000	0.0100	2	0.00	0.001	0.001
		16 16	1	1.0000	0.0100	3	0.00	0.002	0.049
1.00	4								

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	4	16	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	16	1	0.0100	1.0000	3	0.00	0.002	0.038
1.00	4	16 16	1	0.0100	0.0100	3	0.00	0.001	0.001
1.00	4	16	1	0.0100	0.0001	2	0.00	0.002	0.001
1.00	4	16	1	0.0100	0.0001	3	0.00	0.002	0.002
1.00	4	16	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	4	16	1	0.0001	1.0000	3	0.00	0.002	0.039
1.00	4	16 16	1	0.0001	0.0100	2	0.00	0.001 0.002	0.001
1.00	4	16	1	0.0001	0.0001	2	0.00	0.001	0.003
1.00	4	16	1	0.0001	0.0001	3	0.00	0.002	0.127
1.00	4	16	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	16 16	4	1.0000	1.0000	3	0.00	0.002	0.006
1.00	4	16	4	1.0000	0.0100	3	0.00	0.001	0.001
1.00	4	16	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	4	16	4	1.0000	0.0001	3	0.00	0.002	0.011
1.00	4	16	4	0.0100	1.0000	2	0.17	0.001	0.003
1.00	4	16 16	4	0.0100	1.0000	3	0.17	0.002	0.019
1.00	4	16	4	0.0100	0.0100	3	0.50	0.001	0.003
1.00	4	16	4	0.0100	0.0001	2	0.50	0.002	0.010
1.00	4	16	4	0.0100	0.0001	3	0.67	0.002	0.007
1.00	4	16	4	0.0001	1.0000	2	0.33	0.001	0.003
1.00	4	16	4	0.0001	1.0000	3	0.33	0.002	0.006
1.00	4	16 16	4	0.0001	0.0100	3	0.50	0.001	0.003
1.00	4	16	4	0.0001	0.0001	2	0.67	0.003	0.004
1.00	4	16	4	0.0001	0.0001	3	0.83	0.002	0.004
1.00	4	16	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	16	16	1.0000	1.0000	2	0.00	0.002	0.013
1.00	4	16 16	16 16	1.0000	0.0100	3	0.00	0.001	0.001
1.00	4	16	16	1.0000	0.0001	2	0.00	0.001	0.001
1.00	4	16	16	1.0000	0.0001	3	0.50	0.005	0.032
1.00	4	16	16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	16 16	16 16	0.0100	1.0000 0.0100	2	0.00	0.002	0.024
1.00	4	16	16	0.0100	0.0100	3	0.83	0.001	0.000
1.00	4	16	16	0.0100	0.0001	2	0.33	0.001	0.007
1.00	4	16	16	0.0100	0.0001	3	0.83	0.002	0.006
1.00	4	16	16	0.0001	1.0000	2	0.00	0.001	0.001
1.00	4	16 16	16 16	0.0001	1.0000 0.0100	3	0.00 1.00	0.002	0.035
1.00	4	16	16	0.0001	0.0100	3	1.00	0.006	0.007
1.00	4	16	16	0.0001	0.0001	2	1.00	0.006	0.007
1.00	4	16	16	0.0001	0.0001	3	1.00	0.006	0.007
1.00	4	16	64	1.0000	1.0000	2	0.00	0.001	0.003
1.00	4	16 16	64 64	1.0000	1.0000 0.0100	3	0.00	0.038	0.049
1.00	4	16	64	1.0000	0.0100	3	0.00	0.001	0.001
1.00	4	16	64	1.0000	0.0001	2	0.33	0.001	0.015
1.00	4	16	64	1.0000	0.0001	3	1.00	0.015	0.029
1.00	4	16 16	64	0.0100 0.0100	1.0000	3	0.00	0.001	0.006
1.00	4	16	64	0.0100	0.0100	2	1.00	0.043	0.083
1.00	4	16	64	0.0100	0.0100	3	1.00	0.010	0.015
1.00	4	16	64	0.0100	0.0001	2	1.00	0.011	0.017
1.00	4	16	64	0.0100	0.0001	3	1.00	0.012	0.025
1.00	4	16 16	64	0.0001	1.0000 1.0000	3	0.00	0.001	0.001 0.115
1.00	4	16	64	0.0001	0.0100	2	1.00	0.039	0.113
1.00	4	16	64	0.0001	0.0100	3	1.00	0.012	0.018
1.00	4	16	64	0.0001	0.0001	2	1.00	0.013	0.014
1.00	4	16	64	0.0001	0.0001	3	1.00	0.013	0.015
1.00	4	16 16	256 256	1.0000	1.0000	3	0.00	0.011	0.016 0.705
1.00	4	16	256	1.0000	0.0100	2	0.00	0.197	0.703
1.00	4	16	256	1.0000	0.0100	3	0.00	0.071	0.310
1.00	4	16	256	1.0000	0.0001	2	1.00	0.046	0.050
1.00	4	16	256	1.0000	0.0001	3	1.00	0.045	0.048
1.00	4	16 16	256 256	0.0100	1.0000	3	0.00	0.016	0.019
1.00	4	16	256	0.0100	0.0100	2	0.83	0.271	0.055
1.00	4	16	256	0.0100	0.0100	3	1.00	0.051	0.054

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	4	16	256	0.0100	0.0001	2	1.00	0.060	0.065
1.00	4	16	256	0.0100	0.0001	3	1.00	0.059	0.065
1.00	4	16	256	0.0001	1.0000	2	0.00	0.026	0.028
1.00	4	16	256	0.0001	1.0000	3	0.00	0.417	0.481
1.00	4	16	256	0.0001	0.0100	2	1.00	0.061	0.077
1.00	4	16 16	256	0.0001	0.0100	3	1.00	0.060	0.339
1.00	4	16	256 256	0.0001	0.0001	3	1.00	0.080	0.125
1.00	4	64	1	1.0000	1.0000	2	0.00	0.000	0.001
1.00	4	64	1	1.0000	1.0000	3	0.00	0.002	0.007
1.00	4	64	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	4	64	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	4	64	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	4	64	1	1.0000	0.0001	3	0.00	0.002	0.003
1.00	4	64	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	64	1	0.0100	1.0000 0.0100	3	0.00	0.002	0.042
1.00	4	64	1	0.0100	0.0100	3	0.00	0.001	0.001
1.00	4	64	1	0.0100	0.0001	2	0.00	0.002	0.001
1.00	4	64	1	0.0100	0.0001	3	0.00	0.002	0.035
1.00	4	64	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	4	64	1	0.0001	1.0000	3	0.00	0.002	0.044
1.00	4	64	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	4	64	1	0.0001	0.0100	3	0.00	0.002	0.003
1.00	4	64	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	4	64	1 4	0.0001 1.0000	1.0000	3	0.00	0.002	0.002
1.00	4	64	4	1.0000	1.0000	3	0.00	0.001	0.001
1.00	4	64	4	1.0000	0.0100	2	0.00	0.002	0.007
1.00	4	64	4	1.0000	0.0100	3	0.00	0.002	0.041
1.00	4	64	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	4	64	4	1.0000	0.0001	3	0.00	0.002	0.008
1.00	4	64	4	0.0100	1.0000	2	0.17	0.001	0.004
1.00	4	64	4	0.0100	1.0000	3	0.17	0.003	0.019
1.00	4	64	4	0.0100	0.0100	2	0.33	0.001	0.004
1.00	4	64	4	0.0100	0.0100	3	0.50	0.002	0.005
1.00	4	64	4	0.0100	0.0001	3	0.33	0.001	0.004
1.00	4	64	4	0.0001	1.0000	2	0.33	0.002	0.004
1.00	4	64	4	0.0001	1.0000	3	0.50	0.002	0.006
1.00	4	64	4	0.0001	0.0100	2	0.83	0.001	0.004
1.00	4	64	4	0.0001	0.0100	3	1.00	0.003	0.004
1.00	4	64	4	0.0001	0.0001	2	1.00	0.004	0.004
1.00	4	64	4	0.0001	0.0001	3	1.00	0.004	0.004
1.00	4	64	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	64	16 16	1.0000	1.0000 0.0100	3	0.00	0.002	0.009
1.00	4	64	16	1.0000	0.0100	3	0.00	0.001	0.001
1.00	4	64	16	1.0000	0.0001	2	0.17	0.001	0.006
1.00	4	64	16	1.0000	0.0001	3	0.33	0.002	0.013
1.00	4	64	16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	64	16	0.0100	1.0000	3	0.00	0.002	0.004
1.00	4	64	16	0.0100	0.0100	2	0.50	0.001	0.006
1.00	4	64	16	0.0100	0.0100	3	0.67	0.006	0.040
1.00	4	64	16 16	0.0100	0.0001	3	0.83 1.00	0.001	0.007
1.00	4	64	16	0.0100	1.00001	2	0.50	0.006	0.007
1.00	4	64	16	0.0001	1.0000	3	0.50	0.001	0.000
1.00	4	64	16	0.0001	0.0100	2	1.00	0.004	0.005
1.00	4	64	16	0.0001	0.0100	3	1.00	0.004	0.005
1.00	4	64	16	0.0001	0.0001	2	1.00	0.005	0.005
1.00	4	64	16	0.0001	0.0001	3	1.00	0.005	0.005
1.00	4	64	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	64	64	1.0000	1.0000	3	0.00	0.005	0.033
1.00	4	64	64	1.0000	0.0100	3	0.00	0.001	0.001
1.00	4	64	64	1.0000	0.0100	2	0.50	0.002	0.042
1.00	4	64	64	1.0000	0.0001	3	0.67	0.001	0.012
1.00	4	64	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	64	64	0.0100	1.0000	3	0.00	0.002	0.055
1.00	4	64	64	0.0100	0.0100	2	0.83	0.001	0.015
		64	64	0.0100	0.0100	3	1.00	0.014	0.015
1.00	4						1.00	0.017	0.041
1.00	4	64	64	0.0100	0.0001	2	1.00	0.017	0.041
1.00	4	64 64	64	0.0100	0.0001	3	1.00	0.015	0.018
1.00	4	64							

1.00	mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00										0.019
1.00										0.019
1.00										0.022
1.00										0.017
1.00										0.277
1.00										0.001
1.00										0.256
1.00										0.079
1.00										0.025
1.00										0.708
1.00										0.067
1.00										0.079
1.00		4								0.099
1.00										0.040
1.00										1.156
1.00										0.100
1.00										0.124
1.00										0.122
1.00										0.001
1.00										0.013
1.00										0.001
1.00	1.00		256	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00										0.003
1.00										
1.00										0.001
1.00										0.124
1.00										0.001
1.00										0.002
1.00										0.001
1.00										0.001
1.00										0.002
1.00										0.001
1.00										0.016
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.032
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.011
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$			256		0.0100			0.00		0.012
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.013
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.00			4						0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.006
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$										0.004
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.00				0.0001	0.0001		0.50		0.004
1.00 4 256 16 1.0000 0.0100 2 0.00 0.001 0.00 1.00 4 256 16 1.0000 0.0100 3 0.00 0.002 0.02 1.00 4 256 16 1.0000 0.0001 2 0.00 0.001 0.00 1.00 4 256 16 1.0000 0.0001 3 0.50 0.002 0.81 1.00 4 256 16 0.0100 1.0000 2 0.00 0.001 0.00 1.00 4 256 16 0.0100 1.0000 3 0.00 0.002 0.00 1.00 4 256 16 0.0100 0.0100 2 0.83 0.001 0.00 1.00 4 256 16 0.0100 0.0100 2 0.83 0.001 0.00 1.00 4 256 16 0.0100 0.0100 3										0.001
1.00 4 256 16 1.0000 0.0100 3 0.00 0.002 0.02 1.00 4 256 16 1.0000 0.0001 2 0.00 0.001 0.00 1.00 4 256 16 1.0000 0.0001 3 0.50 0.002 0.81 1.00 4 256 16 0.0100 1.0000 2 0.00 0.001 0.00 1.00 4 256 16 0.0100 1.0000 3 0.00 0.002 0.02 1.00 4 256 16 0.0100 0.0100 2 0.83 0.001 0.00 1.00 4 256 16 0.0100 0.0100 3 1.00 0.004 0.00										0.008
1.00 4 256 16 1.0000 0.0001 2 0.00 0.001 0.00 1.00 4 256 16 1.0000 0.0001 3 0.50 0.002 0.81 1.00 4 256 16 0.0100 1.0000 2 0.00 0.001 0.00 1.00 4 256 16 0.0100 1.0000 3 0.00 0.002 0.02 1.00 4 256 16 0.0100 0.0100 2 0.83 0.001 0.00 1.00 4 256 16 0.0100 0.0100 3 1.00 0.004 0.00										0.001
1.00 4 256 16 1.0000 0.0001 3 0.50 0.002 0.81 1.00 4 256 16 0.0100 1.0000 2 0.00 0.001 0.00 1.00 4 256 16 0.0100 1.0000 3 0.00 0.002 0.02 1.00 4 256 16 0.0100 0.0100 2 0.83 0.001 0.00 1.00 4 256 16 0.0100 0.0100 3 1.00 0.004 0.00										0.028
1.00 4 256 16 0.0100 1.0000 3 0.00 0.002 0.02 1.00 4 256 16 0.0100 0.0100 2 0.83 0.001 0.00 1.00 4 256 16 0.0100 0.0100 3 1.00 0.004 0.00	1.00	4	256	16	1.0000	0.0001	3	0.50	0.002	0.813
1.00 4 256 16 0.0100 0.0100 2 0.83 0.001 0.00 1.00 4 256 16 0.0100 0.0100 3 1.00 0.004 0.00										0.001
1.00 4 256 16 0.0100 0.0100 3 1.00 0.004 0.00										0.020 0.006
										0.006
										0.006
1.00 4 256 16 0.0100 0.0001 3 1.00 0.005 0.00	1.00		256	16	0.0100	0.0001	3	1.00	0.005	0.006
										0.004
										0.010
1.00 4 256 16 0.0001 0.0100 3 1.00 0.005 0.00								1.00		0.007
1.00 4 256 16 0.0001 0.0001 2 1.00 0.005 0.00	1.00	4	256	16	0.0001	0.0001	2	1.00	0.005	0.007
1.00 4 256 16 0.0001 0.0001 3 1.00 0.005 0.00	1.00	4	256	16	0.0001	0.0001	3	1.00	0.005	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	4	256	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	4	256	64	1.0000	1.0000	3	0.00	0.002	0.034
1.00	4	256 256	64 64	1.0000	0.0100	3	0.00	0.001	0.001
1.00	4	256	64	1.0000	0.0001	2	0.00	0.002	0.043
1.00	4	256	64	1.0000	0.0001	3	0.67	0.002	0.016
1.00	4	256	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	4	256	64	0.0100	1.0000	3	0.00	0.002	0.025
1.00	4	256	64	0.0100	0.0100	2	0.83	0.001	0.016
1.00	4	256 256	64	0.0100	0.0100	2	1.00	0.011	0.016
1.00	4	256	64	0.0100	0.0001	3	1.00	0.011	0.013
1.00	4	256	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00	4	256	64	0.0001	1.0000	3	0.00	0.002	0.067
1.00	4	256	64	0.0001	0.0100	2	1.00	0.012	0.013
1.00	4	256	64	0.0001	0.0100	3	1.00	0.012	0.014
1.00	4	256 256	64	0.0001	0.0001	2	1.00	0.014	0.016
1.00	4	256	256	1.0000	1.0000	2	0.00	0.014	0.013
1.00	4	256	256	1.0000	1.0000	3	0.00	0.116	0.217
1.00	4	256	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	4	256	256	1.0000	0.0100	3	0.00	0.002	0.196
1.00	4	256	256	1.0000	0.0001	2	0.17	0.001	0.081
1.00	4	256	256	1.0000	0.0001	3	0.50	0.002	0.483
1.00	4	256 256	256 256	0.0100	1.0000	2	0.00	0.001	0.001 0.755
1.00	4	256	256	0.0100	0.0100	2	0.83	0.070	0.733
1.00	4	256	256	0.0100	0.0100	3	1.00	0.055	0.080
1.00	4	256	256	0.0100	0.0001	2	1.00	0.083	0.097
1.00	4	256	256	0.0100	0.0001	3	1.00	0.065	0.097
1.00	4	256	256	0.0001	1.0000	2	0.00	0.001	0.001
1.00	4	256 256	256 256	0.0001	1.0000 0.0100	3	0.17 1.00	0.053	0.550
1.00	4	256	256	0.0001	0.0100	3	1.00	0.062	0.101
1.00	4	256	256	0.0001	0.0001	2	1.00	0.082	0.126
1.00	4	256	256	0.0001	0.0001	3	1.00	0.115	0.128
1.00	16	1	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16	1	1	1.0000	1.0000	3	0.00	0.002	0.006
1.00	16	1	1	1.0000	0.0100	3	0.00	0.001	0.001
1.00	16 16	1	1	1.0000	0.0100	2	0.00	0.002	0.002
1.00	16	1	1	1.0000	0.0001	3	0.00	0.001	0.001
1.00	16	1	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16	1	1	0.0100	1.0000	3	0.00	0.002	0.043
1.00	16	1	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	16	1	1	0.0100	0.0100	3	0.00	0.002	0.002
1.00	16 16	1	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	16	1	1	0.0100	1.0000	2	0.00	0.002	0.026
1.00	16	1	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	16	1	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	16	1	1	0.0001	0.0100	3	0.00	0.002	0.078
1.00	16	1	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	16	1	1	0.0001	0.0001	3	0.00	0.002	0.002
1.00	16 16	1	4	1.0000	1.0000	3	0.00	0.001	0.001
1.00	16	1	4	1.0000	0.0100	2	0.00	0.002	0.007
1.00	16	1	4	1.0000	0.0100	3	0.00	0.002	0.006
1.00	16	1	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	16	1	4	1.0000	0.0001	3	0.00	0.002	0.011
1.00	16	1	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16 16	1	4	0.0100	1.0000 0.0100	3	0.17	0.002	0.006
1.00	16	1	4	0.0100	0.0100	3	0.00	0.001	0.001
1.00	16	1	4	0.0100	0.0001	2	0.50	0.002	0.004
1.00	16	1	4	0.0100	0.0001	3	0.67	0.002	0.004
1.00	16	1	4	0.0001	1.0000	2	0.50	0.001	0.003
1.00	16	1	4	0.0001	1.0000	3	0.50	0.002	0.005
1.00	16	1	4	0.0001	0.0100	2	0.50	0.001	0.003
1.00	16 16	1	4	0.0001	0.0100	2	0.50	0.002	0.016 0.004
1.00	16	1	4	0.0001	0.0001	3	0.67	0.001	0.004
1.00	16	1	16	1.0000	1.0000	2	0.00	0.003	0.001
1.00	16	1	16	1.0000	1.0000	3	0.00	0.002	0.012
1.00	16	1	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	1	16	1.0000	0.0100	3	0.00	0.002	0.015

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	16	1	16	1.0000	0.0001	2	0.17	0.001	0.005
1.00	16	1	16	1.0000	0.0001	3	0.50	0.002	0.013
1.00	16 16	1	16 16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16	1	16	0.0100	0.0100	2	0.83	0.002	0.025
1.00	16	1	16	0.0100	0.0100	3	1.00	0.004	0.010
1.00	16	1	16	0.0100	0.0001	2	0.33	0.001	0.006
1.00	16 16	1	16 16	0.0100	0.0001 1.0000	3	0.83	0.002	0.042
1.00	16	1	16	0.0001	1.0000	3	0.00	0.001	0.001
1.00	16	1	16	0.0001	0.0100	2	1.00	0.005	0.005
1.00	16	1	16	0.0001	0.0100	3	1.00	0.004	0.005
1.00	16 16	1	16 16	0.0001	0.0001	2	1.00	0.005	0.007
1.00	16	1	64	1.0000	1.0000	2	0.00	0.003	0.007
1.00	16	1	64	1.0000	1.0000	3	0.00	0.035	0.052
1.00	16	1	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16 16	1	64	1.0000	0.0100	3	0.00	0.023	0.064
1.00	16	1	64	1.0000	0.0001	3	1.00	0.001	0.015
1.00	16	1	64	0.0100	1.0000	2	0.00	0.001	0.006
1.00	16	1	64	0.0100	1.0000	3	0.00	0.060	0.556
1.00	16 16	1	64	0.0100	0.0100	2	1.00	0.010	0.015
1.00	16	1	64	0.0100	0.0001	2	1.00	0.010	0.018
1.00	16	1	64	0.0100	0.0001	3	1.00	0.013	0.018
1.00	16	1	64	0.0001	1.0000	2	0.00	0.001	0.006
1.00	16 16	1	64 64	0.0001	1.0000 0.0100	3	1.00	0.070	0.103
1.00	16	1	64	0.0001	0.0100	3	1.00	0.011	0.012
1.00	16	1	64	0.0001	0.0001	2	1.00	0.014	0.015
1.00	16	1	64	0.0001	0.0001	3	1.00	0.013	0.014
1.00	16 16	1	256 256	1.0000	1.0000	2	0.00	0.011	0.017
1.00	16	1	256	1.0000	0.0100	2	0.00	0.199	0.279
1.00	16	1	256	1.0000	0.0100	3	0.00	0.130	0.629
1.00	16	1	256	1.0000	0.0001	2	0.83	0.035	0.073
1.00	16 16	1	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.046	0.217
1.00	16	1	256	0.0100	1.0000	3	0.00	0.405	0.027
1.00	16	1	256	0.0100	0.0100	2	1.00	0.062	0.076
1.00	16	1	256	0.0100	0.0100	3	1.00	0.052	0.076
1.00	16 16	1	256 256	0.0100	0.0001	2	1.00	0.066	0.097
1.00	16	1	256	0.0100	1.0000	2	0.00	0.031	0.042
1.00	16	1	256	0.0001	1.0000	3	0.00	0.418	1.376
1.00	16	1	256	0.0001	0.0100	2	1.00	0.060	0.097
1.00	16 16	1	256 256	0.0001	0.0100	3	1.00	0.060	0.098
1.00	16	1	256	0.0001	0.0001	3	1.00	0.101	0.123
1.00	16	4	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16	4	1	1.0000	1.0000	3	0.00	0.002	0.002
1.00	16 16	4	1	1.0000	0.0100	3	0.00	0.001	0.001
1.00	16	4	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	16	4	1	1.0000	0.0001	3	0.00	0.002	0.002
1.00	16 16	4	1	0.0100	1.0000	3	0.00	0.001	0.001
1.00	16	4	1	0.0100	0.0100	2	0.00	0.002	0.063
1.00	16	4	1	0.0100	0.0100	3	0.00	0.002	0.031
1.00	16	4	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	16	4	1	0.0100	0.0001	3	0.00	0.002	0.002
1.00	16 16	4	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	16	4	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	16	4	1	0.0001	0.0100	3	0.00	0.002	0.041
1.00	16 16	4	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	16	4	4	1.0000	1.00001	2	0.00	0.002	0.003
1.00	16	4	4	1.0000	1.0000	3	0.00	0.002	0.033
1.00	16	4	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16 16	4	4	1.0000	0.0100	3	0.00	0.002	0.019
1.00	16	4	4	1.0000	0.0001	3	0.00	0.001	0.001
1.00	16	4	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16	4	4	0.0100	1.0000	3	0.17	0.002	0.008

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	16	4	4	0.0100	0.0100	2	0.17	0.001	0.003
1.00	16	4	4	0.0100	0.0100	3	0.17	0.002	0.020
1.00	16	4	4	0.0100	0.0001	2	0.17	0.001	0.004
1.00	16	4	4	0.0100	0.0001	3	0.67	0.002	0.016
1.00	16	4	4	0.0001	1.0000	2	0.33	0.001	0.003
1.00	16 16	4	4	0.0001	1.0000 0.0100	2	0.33	0.002	0.003
1.00	16	4	4	0.0001	0.0100	3	0.83	0.001	0.003
1.00	16	4	4	0.0001	0.0001	2	0.33	0.002	0.004
1.00	16	4	4	0.0001	0.0001	3	0.67	0.003	0.012
1.00	16	4	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16	4	16	1.0000	1.0000	3	0.00	0.002	0.014
1.00	16	4	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	4	16	1.0000	0.0100	3	0.00	0.002	0.014
1.00	16 16	4	16 16	1.0000	0.0001	2	0.00	0.001	0.001
1.00	16	4	16	0.0100	1.0000	2	0.00	0.002	0.020
1.00	16	4	16	0.0100	1.0000	3	0.00	0.002	0.023
1.00	16	4	16	0.0100	0.0100	2	1.00	0.004	0.005
1.00	16	4	16	0.0100	0.0100	3	1.00	0.004	0.006
1.00	16	4	16	0.0100	0.0001	2	0.50	0.001	0.005
1.00	16	4	16	0.0100	0.0001	3	0.67	0.002	0.011
1.00	16	4	16	0.0001	1.0000	2	0.00	0.001	0.001
1.00	16	4	16	0.0001	1.0000	3	0.00	0.002	0.025
1.00	16 16	4	16 16	0.0001	0.0100	3	1.00	0.004	0.007
1.00	16	4	16	0.0001	0.0001	2	1.00	0.004	0.007
1.00	16	4	16	0.0001	0.0001	3	1.00	0.007	0.007
1.00	16	4	64	1.0000	1.0000	2	0.00	0.001	0.004
1.00	16	4	64	1.0000	1.0000	3	0.00	0.028	0.642
1.00	16	4	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	4	64	1.0000	0.0100	3	0.00	0.041	0.075
1.00	16	4	64	1.0000	0.0001	2	0.33	0.001	0.015
1.00	16 16	4	64	1.0000 0.0100	1.0000	3 2	1.00 0.00	0.010	0.032
1.00	16	4	64	0.0100	1.0000	3	0.00	0.001	0.001
1.00	16	4	64	0.0100	0.0100	2	1.00	0.012	0.015
1.00	16	4	64	0.0100	0.0100	3	1.00	0.010	0.015
1.00	16	4	64	0.0100	0.0001	2	1.00	0.012	0.018
1.00	16	4	64	0.0100	0.0001	3	1.00	0.013	0.018
1.00	16	4	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00	16 16	4	64	0.0001	1.0000 0.0100	3	0.00 1.00	0.080	0.181
1.00	16	4	64	0.0001	0.0100	3	1.00	0.011	0.013
1.00	16	4	64	0.0001	0.0001	2	1.00	0.011	0.012
1.00	16	4	64	0.0001	0.0001	3	1.00	0.014	0.015
1.00	16	4	256	1.0000	1.0000	2	0.00	0.011	0.017
1.00	16	4	256	1.0000	1.0000	3	0.00	0.182	0.280
1.00	16	4	256	1.0000	0.0100	2	0.00	0.001	0.024
1.00	16	4	256	1.0000	0.0100	3	0.00	0.002	0.878
1.00	16 16	4	256 256	1.0000	0.0001	3	1.00	0.071	0.075 0.074
1.00	16	4	256	0.0100	1.0000	2	0.00	0.072	0.074
1.00	16	4	256	0.0100	1.0000	3	0.00	0.369	0.781
1.00	16	4	256	0.0100	0.0100	2	1.00	0.064	0.078
1.00	16	4	256	0.0100	0.0100	3	1.00	0.064	0.079
1.00	16	4	256	0.0100	0.0001	2	1.00	0.071	0.122
1.00	16	4	256	0.0100	0.0001	3	1.00	0.073	0.098
1.00	16	4	256	0.0001	1.0000	2	0.00	0.026	0.041
1.00	16 16	4	256 256	0.0001	1.0000 0.0100	3	0.00 1.00	0.413 0.094	0.920
1.00	16	4	256	0.0001	0.0100	3	1.00	0.094	0.099
1.00	16	4	256	0.0001	0.0001	2	1.00	0.082	0.129
1.00	16	4	256	0.0001	0.0001	3	1.00	0.080	0.121
1.00	16	16	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16	16	1	1.0000	1.0000	3	0.00	0.002	0.002
1.00	16	16	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	16	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	16 16	16 16	1	1.0000	0.0001	3	0.00	0.001	0.001
1.00	16	16	1	0.0100	1.00001	2	0.00	0.002	0.002
1.00		10			1.0000	3	0.00	0.001	0.001
		16	1	0.0100					
1.00	16 16	16 16	1	0.0100	0.0100	2	0.00	0.001	0.001
	16								
1.00	16 16	16	1	0.0100	0.0100	2	0.00	0.001	0.001

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	16	16	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	16	16	1	0.0001	1.0000	3	0.00	0.002	0.012
1.00	16 16	16 16	1	0.0001	0.0100	3	0.00	0.001	0.001
1.00	16	16	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	16	16	1	0.0001	0.0001	3	0.00	0.002	0.011
1.00	16	16	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16 16	16 16	4	1.0000	1.0000 0.0100	3	0.00	0.002	0.031
1.00	16	16	4	1.0000	0.0100	3	0.00	0.002	0.027
1.00	16	16	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	16 16	16 16	4	1.0000 0.0100	0.0001	3	0.00	0.002	0.037
1.00	16	16	4	0.0100	1.0000	3	0.00	0.001	0.001
1.00	16	16	4	0.0100	0.0100	2	0.33	0.001	0.003
1.00	16	16	4	0.0100	0.0100	3	0.50	0.002	0.015
1.00	16 16	16	4	0.0100	0.0001	3	0.17	0.001	0.003
1.00	16	16 16	4	0.0100	1.0000	2	0.67	0.002	0.018
1.00	16	16	4	0.0001	1.0000	3	0.67	0.002	0.016
1.00	16	16	4	0.0001	0.0100	2	0.67	0.001	0.004
1.00	16 16	16 16	4	0.0001	0.0100	2	0.67	0.002	0.006
1.00	16	16	4	0.0001	0.0001	3	0.67	0.001	0.004
1.00	16	16	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16	16	16	1.0000	1.0000	3	0.00	0.002	0.007
1.00	16 16	16 16	16 16	1.0000	0.0100	3	0.00	0.001	0.001
1.00	16	16	16	1.0000	0.0100	2	0.00	0.002	0.026
1.00	16	16	16	1.0000	0.0001	3	0.50	0.006	0.308
1.00	16	16	16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16 16	16 16	16 16	0.0100	1.0000 0.0100	3	0.00	0.002	0.010
1.00	16	16	16	0.0100	0.0100	3	0.55	0.001	0.004
1.00	16	16	16	0.0100	0.0001	2	0.67	0.001	0.005
1.00	16	16	16	0.0100	0.0001	3	0.67	0.002	0.017
1.00	16 16	16 16	16 16	0.0001	1.0000	2	0.50	0.001	0.006
1.00	16	16	16	0.0001	0.0100	2	1.00	0.002	0.009
1.00	16	16	16	0.0001	0.0100	3	1.00	0.004	0.006
1.00	16	16	16	0.0001	0.0001	2	1.00	0.005	0.005
1.00	16 16	16 16	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.005	0.006
1.00	16	16	64	1.0000	1.0000	3	0.00	0.002	0.042
1.00	16	16	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	16	64	1.0000	0.0100	3	0.00	0.002	0.030
1.00	16 16	16 16	64 64	1.0000	0.0001	2	0.83 1.00	0.001 0.010	0.011 0.011
1.00	16	16	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16	16	64	0.0100	1.0000	3	0.00	0.003	0.054
1.00	16	16	64	0.0100	0.0100	2	1.00	0.009	0.011
1.00	16 16	16 16	64 64	0.0100	0.0100	3 2	1.00	0.010	0.011
1.00	16	16	64	0.0100	0.0001	3	1.00	0.011	0.012
1.00	16	16	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00	16	16	64 64	0.0001 0.0001	1.0000 0.0100	3	0.00 1.00	0.002 0.011	0.166 0.014
1.00	16 16	16 16	64	0.0001	0.0100	3	1.00	0.011	0.014
1.00	16	16	64	0.0001	0.0001	2	1.00	0.013	0.017
1.00	16	16	64	0.0001	0.0001	3	1.00	0.014	0.016
1.00	16 16	16 16	256 256	1.0000 1.0000	1.0000 1.0000	3	0.00	0.001	0.017 0.274
1.00	16	16	256	1.0000	0.0100	2	0.00	0.194	0.274
1.00	16	16	256	1.0000	0.0100	3	0.00	0.002	0.223
1.00	16	16	256	1.0000	0.0001	2	1.00	0.046	0.065
1.00	16 16	16 16	256 256	1.0000 0.0100	0.0001 1.0000	2	1.00 0.00	0.046	0.059 0.026
1.00	16	16	256	0.0100	1.0000	3	0.00	0.001	0.026
1.00	16	16	256	0.0100	0.0100	2	0.67	0.001	0.079
1.00	16	16	256	0.0100	0.0100	3	1.00	0.049	0.080
1.00	16 16	16 16	256 256	0.0100	0.0001	2	1.00	0.058	0.098 0.097
1.00	16	16	256	0.0100	1.0000	2	0.00	0.001	0.097
1.00	16	16	256	0.0001	1.0000	3	0.00	0.592	1.626
1.00	16	16	256	0.0001	0.0100	2	1.00	0.065	0.102
1.00	16	16	256	0.0001	0.0100	3	1.00	0.063	0.103

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	16	16	256	0.0001	0.0001	2	1.00	0.077	0.115
1.00	16	16	256	0.0001	0.0001	3	1.00	0.081	0.115
1.00	16	64	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16	64	1	1.0000	1.0000	3	0.00	0.002	0.002
1.00	16 16	64	1	1.0000	0.0100	3	0.00	0.001	0.001
1.00	16	64	1	1.0000	0.0001	2	0.00	0.002	0.003
1.00	16	64	1	1.0000	0.0001	3	0.00	0.002	0.002
1.00	16	64	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16	64	1	0.0100	1.0000	3	0.00	0.002	0.038
1.00	16	64	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	16 16	64 64	1	0.0100	0.0100	3	0.00	0.002	0.005
1.00	16	64	1	0.0100	0.0001	3	0.00	0.001	0.001
1.00	16	64	1	0.0001	1.0000	2	0.00	0.002	0.003
1.00	16	64	1	0.0001	1.0000	3	0.00	0.002	0.002
1.00	16	64	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	16	64	1	0.0001	0.0100	3	0.00	0.002	0.029
1.00	16	64	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	16 16	64	1 4	0.0001 1.0000	0.0001 1.0000	3	0.00	0.002	0.004
1.00	16	64	4	1.0000	1.0000	3	0.00	0.001	0.001
1.00	16	64	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	64	4	1.0000	0.0100	3	0.00	0.002	0.002
1.00	16	64	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	16	64	4	1.0000	0.0001	3	0.00	0.002	0.040
1.00	16	64	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16 16	64	4	0.0100	1.0000 0.0100	3	0.00	0.002	0.008
1.00	16	64	4	0.0100	0.0100	3	0.17	0.001	0.004
1.00	16	64	4	0.0100	0.0001	2	0.17	0.001	0.003
1.00	16	64	4	0.0100	0.0001	3	0.50	0.002	0.007
1.00	16	64	4	0.0001	1.0000	2	0.50	0.001	0.004
1.00	16	64	4	0.0001	1.0000	3	0.50	0.002	0.013
1.00	16 16	64	4	0.0001	0.0100	3	0.33	0.001	0.004
1.00	16	64	4	0.0001	0.0001	2	0.67	0.002	0.007
1.00	16	64	4	0.0001	0.0001	3	0.83	0.004	0.009
1.00	16	64	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16	64	16	1.0000	1.0000	3	0.00	0.002	0.006
1.00	16	64	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16 16	64	16 16	1.0000	0.0100	3	0.00	0.002	0.026
1.00	16	64	16	1.0000	0.0001	3	0.17	0.001	0.006
1.00	16	64	16	0.0100	1.0000	2	0.00	0.003	0.001
1.00	16	64	16	0.0100	1.0000	3	0.00	0.002	0.015
1.00	16	64	16	0.0100	0.0100	2	0.33	0.001	0.006
1.00	16	64	16	0.0100	0.0100	3	0.50	0.002	0.013
1.00	16	64	16	0.0100	0.0001	2	0.83	0.001	0.005
1.00	16 16	64	16 16	0.0100	0.0001 1.0000	3	1.00 0.50	0.004	0.014
1.00	16	64	16	0.0001	1.0000	3	0.50	0.001	0.006
1.00	16	64	16	0.0001	0.0100	2	1.00	0.005	0.006
1.00	16	64	16	0.0001	0.0100	3	1.00	0.005	0.006
1.00	16	64	16	0.0001	0.0001	2	1.00	0.005	0.008
1.00	16	64	16	0.0001	0.0001	3	1.00	0.005	0.007
1.00	16 16	64	64 64	1.0000	1.0000	3	0.00	0.001	0.001
1.00	16	64	64	1.0000	0.0100	2	0.00	0.002	0.003
1.00	16	64	64	1.0000	0.0100	3	0.00	0.002	0.053
1.00	16	64	64	1.0000	0.0001	2	0.50	0.001	0.015
1.00	16	64	64	1.0000	0.0001	3	1.00	0.010	0.016
1.00	16	64	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16 16	64	64	0.0100	1.0000 0.0100	3	0.00	0.002	0.059
1.00	16	64	64	0.0100	0.0100	3	1.00	0.001	0.011
1.00	16	64	64	0.0100	0.0001	2	0.83	0.010	0.010
1.00	16	64	64	0.0100	0.0001	3	1.00	0.011	0.013
1.00	16	64	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00		64	64	0.0001	1.0000	3	0.00	0.002	0.047
	16			0.0001	0.0100	2	1.00	0.011	0.013
1.00	16	64	64	0.0001			1.00		
1.00	16 16	64 64	64	0.0001	0.0100	3	1.00	0.011	0.012
1.00 1.00 1.00	16 16 16	64 64 64	64 64	0.0001 0.0001	0.0100	3 2	1.00	0.011 0.014	0.012 0.022
1.00	16 16	64 64	64	0.0001	0.0100	3		0.011	0.012

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	16	64	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	64	256	1.0000	0.0100	3	0.00	0.002	0.300
1.00	16 16	64	256 256	1.0000	0.0001	2	0.50 1.00	0.001	0.050
1.00	16	64	256	0.0100	1.0000	2	0.00	0.001	0.017
1.00	16	64	256	0.0100	1.0000	3	0.00	0.272	0.308
1.00	16	64	256	0.0100	0.0100	2	0.83	0.001	0.055
1.00	16 16	64	256 256	0.0100	0.0100	3	1.00	0.051	0.266 0.065
1.00	16	64	256	0.0100	0.0001	3	1.00	0.057	0.066
1.00	16	64	256	0.0001	1.0000	2	0.00	0.001	0.025
1.00	16	64	256	0.0001	1.0000	3	0.00	0.190	0.461
1.00	16 16	64	256 256	0.0001	0.0100	2	1.00	0.064	0.070
1.00	16	64	256	0.0001	0.0001	2	1.00	0.079	0.484
1.00	16	64	256	0.0001	0.0001	3	1.00	0.076	0.130
1.00	16	256	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16 16	256 256	1	1.0000	1.0000 0.0100	3	0.00	0.002	0.003
1.00	16	256	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	16	256	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	16	256	1	1.0000	0.0001	3	0.00	0.002	0.003
1.00	16 16	256 256	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16	256	1	0.0100	0.0100	2	0.00	0.002	0.023
1.00	16	256	1	0.0100	0.0100	3	0.00	0.002	0.009
1.00	16	256	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	16 16	256 256	1	0.0100	0.0001 1.0000	3	0.00	0.002	0.002
1.00	16	256	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	16	256	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	16	256	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00	16	256	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	16 16	256 256	1 4	0.0001 1.0000	0.0001 1.0000	3	0.00	0.002	0.037
1.00	16	256	4	1.0000	1.0000	3	0.00	0.002	0.036
1.00	16	256	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	256	4	1.0000	0.0100	3	0.00	0.002	0.008
1.00	16 16	256 256	4	1.0000	0.0001	3	0.00	0.001	0.001
1.00	16	256	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	16	256	4	0.0100	1.0000	3	0.00	0.002	0.032
1.00	16	256	4	0.0100	0.0100	2	0.33	0.001	0.003
1.00	16 16	256 256	4	0.0100	0.0100	3	0.33	0.003	0.013
1.00	16	256	4	0.0100	0.0001	3	0.50	0.002	0.043
1.00	16	256	4	0.0001	1.0000	2	0.00	0.001	0.001
1.00	16	256	4	0.0001	1.0000	3	0.00	0.002	0.014
1.00	16 16	256 256	4	0.0001	0.0100	3	1.00	0.003	0.004
1.00	16	256	4	0.0001	0.0001	2	0.83	0.003	0.004
1.00	16	256	4	0.0001	0.0001	3	1.00	0.003	0.004
1.00	16	256	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	16 16	256 256	16 16	1.0000	1.0000 0.0100	3	0.00	0.002	0.010
1.00	16	256	16	1.0000	0.0100	3	0.00	0.001	0.001
1.00	16	256	16	1.0000	0.0001	2	0.17	0.001	0.006
1.00	16	256	16	1.0000	0.0001	3	0.33	0.002	0.019
1.00	16 16	256 256	16 16	0.0100 0.0100	1.0000 1.0000	2	0.00	0.001	0.001
1.00	16	256	16	0.0100	0.0100	2	0.50	0.002	0.018
1.00	16	256	16	0.0100	0.0100	3	0.83	0.002	0.006
1.00	16	256	16	0.0100	0.0001	2	0.67	0.001	0.006
1.00	16 16	256 256	16 16	0.0100	0.0001 1.0000	3	1.00 0.50	0.005	0.007 0.005
1.00	16	256	16	0.0001	1.0000	3	0.50	0.001	0.003
1.00	16	256	16	0.0001	0.0100	2	1.00	0.005	0.007
1.00	16	256	16	0.0001	0.0100	3	1.00	0.005	0.007
1.00	16	256	16	0.0001	0.0001	2	1.00	0.005	0.007
1.00	16 16	256 256	16 64	0.0001 1.0000	0.0001 1.0000	3	1.00 0.00	0.006	0.008
1.00	16	256	64	1.0000	1.0000	3	0.00	0.002	0.054
1.00	16	256	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	16	256	64	1.0000	0.0100	3	0.00	0.002	0.013
1.00	16 16	256 256	64 64	1.0000	0.0001	2	0.50 0.67	0.001	0.012
1.00	10	230	04	1.0000	0.0001	3	0.07	0.010	0.030

mu	$ \mathbf{l} m_1$	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	0 16	256	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00		256	64	0.0100	1.0000	3	0.00	0.002	0.056
1.00		256	64	0.0100	0.0100	2	0.50	0.001	0.011
1.00		256	64	0.0100	0.0100	3	0.83	0.010	0.038
1.00		256	64	0.0100	0.0001	2	1.00	0.011	0.012
1.00		256 256	64	0.0100	1.0000	3 2	1.00 0.17	0.011	0.013
1.00		256	64	0.0001	1.0000	3	0.17	0.001	0.011
1.00		256	64	0.0001	0.0100	2	1.00	0.002	0.011
1.00		256	64	0.0001	0.0100	3	1.00	0.011	0.013
1.00		256	64	0.0001	0.0001	2	1.00	0.014	0.021
1.00		256	64	0.0001	0.0001	3	1.00	0.013	0.021
1.00) 16	256	256	1.0000	1.0000	2	0.00	0.001	0.011
1.00) 16	256	256	1.0000	1.0000	3	0.00	0.046	0.193
1.00) 16	256	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00		256	256	1.0000	0.0100	3	0.00	0.002	0.111
1.00		256	256	1.0000	0.0001	2	0.33	0.001	0.054
1.00		256	256	1.0000	0.0001	3	0.83	0.053	0.111
1.00		256	256	0.0100	1.0000	2	0.00	0.001	0.018
1.00		256	256	0.0100	1.0000	3	0.00	0.002	0.290
1.00		256	256	0.0100	0.0100	2	0.67	0.001	0.055
1.00		256 256	256 256	0.0100	0.0100	3 2	1.00	0.054	0.055
1.00		256	256	0.0100	0.0001	3	1.00	0.064	0.065
1.00		256	256	0.0100	1.0000	2	0.00	0.001	0.003
1.00		256	256	0.0001	1.0000	3	0.00	0.001	1.126
1.00		256	256	0.0001	0.0100	2	1.00	0.066	0.068
1.00		256	256	0.0001	0.0100	3	1.00	0.066	0.069
1.00	0 16	256	256	0.0001	0.0001	2	1.00	0.082	0.124
1.00		256	256	0.0001	0.0001	3	1.00	0.082	0.124
1.00		1	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00		1	1	1.0000	1.0000	3	0.00	0.002	0.010
1.00		1	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00		1	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00		1	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00		1	1	1.0000 0.0100	0.0001 1.0000	3	0.00	0.002	0.003
1.00		1	1	0.0100	1.0000	3	0.00	0.001	0.001
1.00		1	1	0.0100	0.0100	2	0.00	0.002	0.028
1.00		1	1	0.0100	0.0100	3	0.00	0.001	0.003
1.00		1	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00		1	1	0.0100	0.0001	3	0.00	0.002	0.047
1.00) 64	1	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	0 64	1	1	0.0001	1.0000	3	0.00	0.002	0.002
1.00) 64	1	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00		1	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00		1	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00		1	1	0.0001	0.0001	3	0.00	0.002	0.014
1.00		1	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00		1	4	1.0000	1.0000	3	0.00	0.002	0.005
1.00		1	4	1.0000	0.0100	3	0.00	0.001	0.001
1.00		1	4	1.0000	0.0100	2	0.00	0.002	0.018
1.00		1	4	1.0000	0.0001	3	0.00	0.001	0.001
1.00		1	4	0.0100	1.0000	2	0.00	0.002	0.010
1.00		1	4	0.0100	1.0000	3	0.00	0.001	0.010
1.00		1	4	0.0100	0.0100	2	0.17	0.001	0.003
1.00		1	4	0.0100	0.0100	3	0.17	0.002	0.011
1.00		1	4	0.0100	0.0001	2	0.33	0.001	0.003
1.00		1	4	0.0100	0.0001	3	0.33	0.002	0.016
1.00		1	4	0.0001	1.0000	2	0.33	0.001	0.003
1.00		1	4	0.0001	1.0000	3	0.33	0.002	0.011
1.00		1	4	0.0001	0.0100	2	0.67	0.001	0.004
1.00		1	4	0.0001	0.0100	3	0.67	0.002	0.004
1.00		1	4	0.0001	0.0001	2	0.33	0.001	0.004
1.00		1	16	0.0001 1.0000	0.0001	3	0.50	0.002	0.011
1.00		1	16 16	1.0000	1.0000	3	0.00	0.001	0.001
1.00		1	16	1.0000	0.0100	2	0.00	0.002	0.013
1.00		1	16	1.0000	0.0100	3	0.00	0.001	0.001
1.00		1	16	1.0000	0.0001	2	0.17	0.002	0.006
		1 *			0.0001	3	0.33	0.002	0.023
1.00		1	16	1.0000	0.0001				
1.00	0 64	1	16 16	0.0100	1.0000	2	0.00	0.001	0.001
	0 64								
1.00	0 64 0 64 0 64	1	16	0.0100	1.0000	2	0.00	0.001	0.001

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	64	1	16	0.0100	0.0001	2	0.83	0.001	0.006
1.00	64	1	16	0.0100	0.0001	3	0.83	0.005	0.017
1.00	64	1	16	0.0001	1.0000	2	0.00	0.001	0.001
1.00	64	1	16 16	0.0001	1.0000 0.0100	3	0.00 1.00	0.002	0.027
1.00	64	1	16	0.0001	0.0100	3	1.00	0.005	0.040
1.00	64	1	16	0.0001	0.0001	2	1.00	0.005	0.007
1.00	64	1	16	0.0001	0.0001	3	1.00	0.005	0.007
1.00	64	1	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	1	64	1.0000	1.0000 0.0100	3	0.00	0.002	0.033
1.00	64	1	64	1.0000	0.0100	3	0.00	0.001	0.046
1.00	64	1	64	1.0000	0.0001	2	0.67	0.001	0.013
1.00	64	1	64	1.0000	0.0001	3	1.00	0.010	0.018
1.00	64	1	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	1	64 64	0.0100	1.0000 0.0100	3	0.00	0.013	0.049
1.00	64	1	64	0.0100	0.0100	3	1.00	0.001	0.010
1.00	64	1	64	0.0100	0.0001	2	1.00	0.017	0.018
1.00	64	1	64	0.0100	0.0001	3	1.00	0.017	0.019
1.00	64	1	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00	64	1	64 64	0.0001	1.0000 0.0100	3	0.00 1.00	0.025	0.076
1.00	64	1	64	0.0001	0.0100	3	1.00	0.017	0.018
1.00	64	1	64	0.0001	0.0001	2	1.00	0.017	0.024
1.00	64	1	64	0.0001	0.0001	3	1.00	0.015	0.023
1.00	64	1	256	1.0000	1.0000	2	0.00	0.001	0.010
1.00	64	1	256 256	1.0000	1.0000	3	0.00	0.121	0.199
1.00	64	1	256	1.0000	0.0100	3	0.00	0.001	0.001
1.00	64	1	256	1.0000	0.0001	2	0.33	0.001	0.051
1.00	64	1	256	1.0000	0.0001	3	0.83	0.049	0.448
1.00	64	1	256	0.0100	1.0000	2	0.00	0.001	0.026
1.00	64	1	256	0.0100	1.0000	3	0.00	0.254	0.889
1.00	64	1	256 256	0.0100	0.0100	3	0.67	0.001	0.077
1.00	64	1	256	0.0100	0.0001	2	1.00	0.068	0.098
1.00	64	1	256	0.0100	0.0001	3	1.00	0.070	0.098
1.00	64	1	256	0.0001	1.0000	2	0.00	0.001	0.041
1.00	64	1	256	0.0001	1.0000	3	0.00	0.345	1.052
1.00	64	1	256 256	0.0001	0.0100	3	1.00	0.060	0.098
1.00	64	1	256	0.0001	0.0001	2	1.00	0.033	0.038
1.00	64	1	256	0.0001	0.0001	3	1.00	0.075	0.121
1.00	64	4	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	4	1	1.0000	1.0000	3	0.00	0.002	0.002
1.00	64	4	1	1.0000	0.0100	3	0.00	0.001	0.001
1.00	64	4	1	1.0000	0.0001	2	0.00	0.002	0.002
1.00	64	4	1	1.0000	0.0001	3	0.00	0.002	0.002
1.00	64	4	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	4	1	0.0100	1.0000	3	0.00	0.002	0.021
1.00	64	4	1	0.0100	0.0100	3	0.00	0.001	0.001
1.00	64	4	1	0.0100	0.0001	2	0.00	0.002	0.001
1.00	64	4	1	0.0100	0.0001	3	0.00	0.002	0.005
1.00	64	4	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	64	4	1	0.0001	1.0000 0.0100	3	0.00	0.002	0.003
1.00	64	4	1	0.0001	0.0100	3	0.00	0.001	0.001
1.00	64	4	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	64	4	1	0.0001	0.0001	3	0.00	0.002	0.032
1.00	64	4	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	4	4	1.0000	1.0000 0.0100	3	0.00	0.002	0.007
1.00	64	4	4	1.0000	0.0100	3	0.00	0.001	0.001
1.00	64	4	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	64	4	4	1.0000	0.0001	3	0.00	0.002	0.013
1.00	64	4	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	4	4	0.0100	1.0000 0.0100	3	0.00	0.002	0.016
1.00	64	4	4	0.0100	0.0100	3	0.50	0.001	0.003
1.00	64	4	4	0.0100	0.0001	2	0.33	0.001	0.004
1.00	64	4	4	0.0100	0.0001	3	0.33	0.002	0.019
1.00	64	4	4	0.0001	1.0000	2	0.50	0.001	0.003
1.00	64	4	4	0.0001	1.0000	3	0.50	0.002	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	64	4	4	0.0001	0.0100	2	0.67	0.001	0.003
1.00	64	4	4	0.0001	0.0100	3	0.67	0.002	0.008
1.00	64	4	4	0.0001	0.0001	2	0.50	0.001	0.004
1.00	64	4	16	1.0000	1.0000	2	0.07	0.002	0.001
1.00	64	4	16	1.0000	1.0000	3	0.00	0.002	0.009
1.00	64	4	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	4	16	1.0000	0.0100	3	0.00	0.002	0.219
1.00	64	4	16	1.0000	0.0001	2	0.33	0.001	0.006
1.00	64	4	16 16	1.0000 0.0100	1.0000	2	0.67	0.006	0.023
1.00	64	4	16	0.0100	1.0000	3	0.00	0.001	0.001
1.00	64	4	16	0.0100	0.0100	2	0.67	0.001	0.006
1.00	64	4	16	0.0100	0.0100	3	1.00	0.006	0.014
1.00	64	4	16	0.0100	0.0001	2	0.33	0.001	0.006
1.00	64	4	16	0.0100	0.0001	3	1.00	0.006	0.023
1.00	64	4	16 16	0.0001	1.0000	2	0.33	0.001	0.006
1.00	64	4	16	0.0001	0.0100	2	1.00	0.002	0.007
1.00	64	4	16	0.0001	0.0100	3	1.00	0.006	0.007
1.00	64	4	16	0.0001	0.0001	2	0.83	0.001	0.007
1.00	64	4	16	0.0001	0.0001	3	1.00	0.005	0.006
1.00	64	4	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	4	64	1.0000	1.0000	3	0.00	0.012	0.028
1.00	64 64	4	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	4	64	1.0000	0.0001	2	0.50	0.002	0.042
1.00	64	4	64	1.0000	0.0001	3	0.83	0.010	0.054
1.00	64	4	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	4	64	0.0100	1.0000	3	0.00	0.009	0.049
1.00	64	4	64	0.0100	0.0100	2	0.83	0.001	0.015
1.00	64 64	4	64	0.0100	0.0100	3 2	1.00	0.010	0.016
1.00	64	4	64	0.0100	0.0001	3	1.00	0.012	0.018
1.00	64	4	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00	64	4	64	0.0001	1.0000	3	0.00	0.024	0.109
1.00	64	4	64	0.0001	0.0100	2	1.00	0.017	0.019
1.00	64	4	64	0.0001	0.0100	3	1.00	0.018	0.019
1.00	64	4	64	0.0001	0.0001	2	1.00	0.015	0.023
1.00	64 64	4	64 256	0.0001 1.0000	1.0000	3	1.00 0.00	0.019	0.023
1.00	64	4	256	1.0000	1.0000	3	0.00	0.001	0.003
1.00	64	4	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	4	256	1.0000	0.0100	3	0.00	0.002	0.849
1.00	64	4	256	1.0000	0.0001	2	0.83	0.001	0.075
1.00	64	4	256	1.0000	0.0001	3	1.00	0.052	0.104
1.00	64 64	4	256 256	0.0100	1.0000	2	0.00	0.001	0.026
1.00	64	4	256	0.0100	0.0100	2	0.00	0.230	0.427
1.00	64	4	256	0.0100	0.0100	3	1.00	0.049	0.079
1.00	64	4	256	0.0100	0.0001	2	1.00	0.068	0.098
1.00	64	4	256	0.0100	0.0001	3	1.00	0.083	0.098
1.00	64	4	256	0.0001	1.0000	2	0.00	0.001	0.040
1.00	64	4	256	0.0001	1.0000	3	0.00	0.335	0.636
1.00	64	4	256 256	0.0001	0.0100	3	1.00	0.067 0.068	0.096 0.095
1.00	64	4	256	0.0001	0.0100	2	1.00	0.088	0.093
1.00	64	4	256	0.0001	0.0001	3	1.00	0.076	0.129
1.00	64	16	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	16	1	1.0000	1.0000	3	0.00	0.002	0.002
1.00	64	16	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	16	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	64	16 16	1	1.0000	0.0001	3	0.00	0.001	0.001
1.00	64	16	1	0.0100	1.0000	2	0.00	0.002	0.001
1.00	64	16	1	0.0100	1.0000	3	0.00	0.002	0.032
1.00	64	16	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	64	16	1	0.0100	0.0100	3	0.00	0.002	0.038
1.00	64	16	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	64	16 16	1	0.0100	0.0001 1.0000	2	0.00	0.002	0.002
1.00	64	16	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	64	16	1	0.0001	0.0100	2	0.00	0.002	0.001
1.00	64	16	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00	64	16	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	64	16	1	0.0001	0.0001	3	0.00	0.002	0.002

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	64	16	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	16	4	1.0000	1.0000	3	0.00	0.002	0.030
1.00	64	16	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	16 16	4	1.0000	0.0100	3	0.00	0.002	0.031
1.00	64	16	4	1.0000	0.0001	3	0.00	0.001	0.001
1.00	64	16	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	16	4	0.0100	1.0000	3	0.17	0.002	0.016
1.00	64	16	4	0.0100	0.0100	2	0.50	0.001	0.004
1.00	64	16 16	4	0.0100	0.0100	3	0.50	0.002	0.013
1.00	64	16	4	0.0100	0.0001	3	0.00	0.001	0.001
1.00	64	16	4	0.0001	1.0000	2	0.17	0.001	0.004
1.00	64	16	4	0.0001	1.0000	3	0.33	0.002	0.004
1.00	64	16	4	0.0001	0.0100	2	1.00	0.004	0.004
1.00	64	16 16	4	0.0001	0.0100	3	1.00 0.50	0.004	0.004
1.00	64	16	4	0.0001	0.0001	3	0.50	0.001	0.004
1.00	64	16	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	16	16	1.0000	1.0000	3	0.00	0.002	0.102
1.00	64	16	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	16 16	16 16	1.0000	0.0100	3	0.00	0.002	0.021
1.00	64	16	16	1.0000	0.0001	3	0.33	0.001	0.001
1.00	64	16	16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	16	16	0.0100	1.0000	3	0.00	0.002	0.015
1.00	64	16 16	16 16	0.0100	0.0100	3	0.83 1.00	0.001	0.006
1.00	64	16	16	0.0100	0.0100	2	1.00	0.005	0.013
1.00	64	16	16	0.0100	0.0001	3	1.00	0.005	0.006
1.00	64	16	16	0.0001	1.0000	2	0.00	0.001	0.001
1.00	64	16	16	0.0001	1.0000 0.0100	3	0.00	0.002	0.030
1.00	64	16 16	16 16	0.0001	0.0100	3	1.00	0.006	0.007
1.00	64	16	16	0.0001	0.0001	2	1.00	0.006	0.007
1.00	64	16	16	0.0001	0.0001	3	1.00	0.006	0.007
1.00	64	16	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	16 16	64 64	1.0000	1.0000 0.0100	3	0.00	0.002	0.046
1.00	64	16	64	1.0000	0.0100	3	0.00	0.001	0.043
1.00	64	16	64	1.0000	0.0001	2	0.17	0.001	0.010
1.00	64	16	64	1.0000	0.0001	3	0.83	0.012	0.043
1.00	64	16 16	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	16	64	0.0100	0.0100	3	0.67	0.002	0.043
1.00	64	16	64	0.0100	0.0100	3	1.00	0.010	0.012
1.00	64	16	64	0.0100	0.0001	2	1.00	0.011	0.013
1.00	64	16	64	0.0100	0.0001	3	1.00	0.011	0.013
1.00	64	16 16	64 64	0.0001	1.0000	3	0.00	0.001	0.001
1.00	64	16	64	0.0001	0.0100	2	1.00	0.002	0.033
1.00	64	16	64	0.0001	0.0100	3	1.00	0.012	0.013
1.00	64	16	64	0.0001	0.0001	2	1.00	0.013	0.014
1.00	64	16	256	0.0001	0.0001	3	1.00	0.014	0.015
1.00	64	16 16	256 256	1.0000	1.0000	3	0.00	0.001	0.011
1.00	64	16	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	16	256	1.0000	0.0100	3	0.00	0.071	0.588
1.00	64	16	256	1.0000	0.0001	2	0.67	0.001	0.075
1.00	64	16 16	256 256	1.0000 0.0100	0.0001 1.0000	3	1.00 0.00	0.049	0.137 0.019
1.00	64	16	256	0.0100	1.0000	3	0.00	0.001	0.019
1.00	64	16	256	0.0100	0.0100	2	1.00	0.051	0.065
1.00	64	16	256	0.0100	0.0100	3	1.00	0.050	0.054
1.00	64	16	256	0.0100	0.0001	2	1.00	0.064	0.068
1.00	64	16 16	256 256	0.0100	0.0001 1.0000	3	1.00 0.00	0.065	0.068
1.00	64	16	256	0.0001	1.0000	3	0.00	0.001	1.181
1.00	64	16	256	0.0001	0.0100	2	1.00	0.078	0.100
1.00	64	16	256	0.0001	0.0100	3	1.00	0.096	0.100
1.00	64	16 16	256 256	0.0001	0.0001	3	1.00	0.075	0.126 0.126
1.00	64	64	230	1.0000	1.0000	2	0.00	0.077	0.120
1.00	64	64	1	1.0000	1.0000	3	0.00	0.002	0.324
1.00	64	64	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	64	1	1.0000	0.0100	3	0.00	0.002	0.003

1.00	0.001 0.002 0.001 0.079 0.001 0.003 0.001 0.002 0.001 0.002 0.001 0.002
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.001 0.079 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.072 0.001 0.016
1.00 64 64 1 0.0100 1.0000 3 0.00 0.002 1.00 64 64 1 0.0100 0.0100 2 0.00 0.001 1.00 64 64 1 0.0100 0.0100 3 0.00 0.002 1.00 64 64 1 0.0100 0.0001 2 0.00 0.001 1.00 64 64 1 0.0100 0.0001 2 0.00 0.001 1.00 64 64 1 0.0001 1.0000 2 0.00 0.001 1.00 64 64 1 0.0001 1.0000 2 0.00 0.001 1.00 64 64 1 0.0001 1.0000 3 0.00 0.002 1.00 64 64 1 0.0001 0.0100 3 0.00 0.001 1.00 64 64 1 0.0001 0.0001 <td>0.079 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.072 0.001 0.016</td>	0.079 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.072 0.001 0.016
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.072 0.001 0.016
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.002 0.001 0.003 0.001 0.002 0.001 0.072 0.001 0.016 0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.001 0.003 0.001 0.002 0.001 0.072 0.001 0.016 0.001
1.00 64 64 1 0.0100 0.0001 3 0.00 0.002 1.00 64 64 1 0.0001 1.0000 2 0.00 0.001 1.00 64 64 1 0.0001 1.0000 3 0.00 0.002 1.00 64 64 1 0.0001 0.0100 2 0.00 0.001 1.00 64 64 1 0.0001 0.0100 3 0.00 0.002 1.00 64 64 1 0.0001 0.0001 2 0.00 0.001 1.00 64 64 1 0.0001 0.0001 3 0.00 0.002 1.00 64 64 1 0.0001 0.0001 3 0.00 0.002 1.00 64 64 4 1.0000 1.0000 2 0.00 0.001 1.00 64 64 4 1.0000 1.0000 <td>0.003 0.001 0.002 0.001 0.072 0.001 0.016 0.001</td>	0.003 0.001 0.002 0.001 0.072 0.001 0.016 0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.001 0.002 0.001 0.072 0.001 0.016 0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.001 0.072 0.001 0.016 0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.072 0.001 0.016 0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.001 0.016 0.001
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.016 0.001
1.00 64 64 4 1.0000 1.0000 2 0.00 0.001 1.00 64 64 4 1.0000 1.0000 3 0.00 0.002 1.00 64 64 4 1.0000 0.0100 2 0.00 0.001 1.00 64 64 4 1.0000 0.0101 3 0.00 0.002 1.00 64 64 4 1.0000 0.0001 2 0.00 0.001 1.00 64 64 4 1.0000 0.0001 3 0.00 0.002 1.00 64 64 4 0.0100 1.0000 2 0.00 0.001 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 0.0100 <td>0.001</td>	0.001
1.00 64 64 4 1.0000 1.0000 3 0.00 0.002 1.00 64 64 4 1.0000 0.0100 2 0.00 0.001 1.00 64 64 4 1.0000 0.0100 3 0.00 0.002 1.00 64 64 4 1.0000 0.0001 2 0.00 0.001 1.00 64 64 4 1.0000 0.0001 3 0.00 0.002 1.00 64 64 4 0.0100 1.0000 2 0.00 0.001 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 0.0100 2 0.17 0.001	
1.00 64 64 4 1.0000 0.0100 2 0.00 0.001 1.00 64 64 4 1.0000 0.0100 3 0.00 0.002 1.00 64 64 4 1.0000 0.0001 2 0.00 0.001 1.00 64 64 4 1.0000 0.0001 3 0.00 0.002 1.00 64 64 4 0.0100 1.0000 2 0.00 0.001 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 0.0100 2 0.17 0.001	0.007
1.00 64 64 4 1.0000 0.0100 3 0.00 0.002 1.00 64 64 4 1.0000 0.0001 2 0.00 0.001 1.00 64 64 4 1.0000 0.0001 3 0.00 0.002 1.00 64 64 4 0.0100 1.0000 2 0.00 0.001 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 0.0100 2 0.17 0.001	0.007
1.00 64 64 4 1.0000 0.0001 2 0.00 0.001 1.00 64 64 4 1.0000 0.0001 3 0.00 0.002 1.00 64 64 4 0.0100 1.0000 2 0.00 0.001 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 0.0100 2 0.17 0.001	0.001
1.00 64 64 4 1.0000 0.0001 3 0.00 0.002 1.00 64 64 4 0.0100 1.0000 2 0.00 0.001 1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 0.0100 2 0.17 0.001	0.001
1.00 64 64 4 0.0100 1.0000 3 0.17 0.002 1.00 64 64 4 0.0100 0.0100 2 0.17 0.001	0.108
1.00 64 64 4 0.0100 0.0100 2 0.17 0.001	0.001
	0.004
1.00 64 64 4 0.0100 0.0100 3 0.33 0.002	0.004
	0.019
1.00 64 64 4 0.0100 0.0001 2 0.17 0.001	0.004
1.00 64 64 4 0.0100 0.0001 3 0.50 0.002	0.004
1.00 64 64 4 0.0001 1.0000 2 0.50 0.001 1.00 64 64 4 0.0001 1.0000 3 0.83 0.002	0.004
1.00 64 64 4 0.0001 1.0000 3 0.83 0.002 1.00 64 64 4 0.0001 0.0100 2 0.33 0.001	0.004
1.00 64 64 4 0.0001 0.0100 2 0.33 0.001 1.00 64 64 4 0.0001 0.0100 3 0.83 0.002	0.004
1.00 64 64 4 0.0001 0.0001 2 1.00 0.004	0.004
1.00 64 64 4 0.0001 0.0001 3 1.00 0.004	0.004
1.00 64 64 16 1.0000 1.0000 2 0.00 0.001	0.001
1.00 64 64 16 1.0000 1.0000 3 0.00 0.002	0.002
1.00 64 64 16 1.0000 0.0100 2 0.00 0.001	0.001
1.00 64 64 16 1.0000 0.0100 3 0.00 0.002	0.018
1.00 64 64 16 1.0000 0.0001 2 0.00 0.001	0.003
1.00 64 64 16 1.0000 0.0001 3 0.33 0.002	0.023
1.00 64 64 16 0.0100 1.0000 2 0.00 0.001	0.001
1.00 64 64 16 0.0100 1.0000 3 0.00 0.002	0.027
1.00 64 64 16 0.0100 0.0100 2 0.33 0.001 1.00 64 64 16 0.0100 0.0100 3 0.67 0.002	0.006
1.00 64 64 16 0.0100 0.0100 5 0.67 0.002 1.00 64 64 16 0.0100 0.0001 2 0.67 0.001	0.006
1.00 64 64 16 0.0100 0.0001 2 0.07 0.001 1.00 64 64 16 0.0100 0.0001 3 0.83 0.002	0.007
1.00 64 64 16 0.0001 1.0000 2 0.50 0.001	0.006
1.00 64 64 16 0.0001 1.0000 3 0.50 0.002	0.020
1.00 64 64 16 0.0001 0.0100 2 1.00 0.006	0.007
1.00 64 64 16 0.0001 0.0100 3 1.00 0.006	0.007
1.00 64 64 16 0.0001 0.0001 2 1.00 0.007	0.007
1.00 64 64 16 0.0001 0.0001 3 1.00 0.007	0.008
1.00 64 64 64 1.0000 1.0000 2 0.00 0.001	0.001
1.00 64 64 64 1.0000 1.0000 3 0.00 0.002	0.025
1.00 64 64 64 1.0000 0.0100 2 0.00 0.001	0.001
1.00 64 64 64 1.0000 0.0100 3 0.00 0.002 1.00 64 64 64 1.0000 0.0001 2 0.17 0.001	0.024
1.00 64 64 64 1.0000 0.0001 2 0.17 0.001 1.00 64 64 64 1.0000 0.0001 3 0.83 0.011	0.016
1.00 64 64 64 1.0000 0.0001 3 0.83 0.011 1.00 64 64 64 0.0100 1.0000 2 0.00 0.001	0.040
1.00 64 64 64 0.0100 1.0000 2 0.00 0.001	0.001
1.00 64 64 64 0.0100 0.0100 2 0.83 0.001	0.024
1.00 64 64 64 0.0100 0.0100 3 1.00 0.011	0.016
1.00 64 64 64 0.0100 0.0001 2 1.00 0.012	0.018
1.00 64 64 64 0.0100 0.0001 3 1.00 0.012	0.018
1.00 64 64 64 0.0001 1.0000 2 0.00 0.001	0.001
1.00 64 64 64 0.0001 1.0000 3 0.00 0.002	0.051
1.00 64 64 64 0.0001 0.0100 2 1.00 0.012	0.019
1.00 64 64 64 0.0001 0.0100 3 1.00 0.017	0.019
1.00 64 64 64 0.0001 0.0001 2 1.00 0.015	0.023
1.00 64 64 64 0.0001 0.0001 3 1.00 0.014	0.022
1.00 64 64 256 1.0000 1.0000 2 0.00 0.001 1.00 64 64 256 1.0000 1.0000 3 0.00 0.002	0.001
1.00 64 64 256 1.0000 1.0000 3 0.00 0.002 1.00 64 64 256 1.0000 0.0100 2 0.00 0.001	0.156
1.00 64 64 256 1.0000 0.0100 2 0.00 0.001 1.00 64 64 256 1.0000 0.0100 3 0.00 0.002	0.001
1.00 64 64 256 1.0000 0.0100 3 0.00 0.002 1.00 64 64 256 1.0000 0.0001 2 0.33 0.001	0.003
1.00 64 64 256 1.0000 0.0001 3 0.83 0.002	0.076
1.00 64 64 256 0.0100 1.0000 2 0.00 0.001	0.001
1.00 64 64 256 0.0100 1.0000 3 0.00 0.002	0.379

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	64	64	256	0.0100	0.0100	2	0.83	0.001	0.080
1.00	64	64	256	0.0100	0.0100	3	1.00	0.048	0.080
1.00	64	64	256	0.0100	0.0001	2	1.00	0.059	0.068
1.00	64	64	256 256	0.0100	0.0001 1.0000	3	1.00 0.00	0.060	0.092
1.00	64	64	256	0.0001	1.0000	3	0.00	0.001	0.385
1.00	64	64	256	0.0001	0.0100	2	1.00	0.065	0.068
1.00	64	64	256	0.0001	0.0100	3	1.00	0.065	0.070
1.00	64	64	256	0.0001	0.0001	2	1.00	0.076	0.123
1.00	64	64	256	0.0001	0.0001	3	1.00	0.077	0.125
1.00	64	256 256	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	256	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	256	1	1.0000	0.0100	3	0.00	0.002	0.002
1.00	64	256	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	64	256	1	1.0000	0.0001	3	0.00	0.002	0.003
1.00	64	256 256	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	256	1	0.0100	0.0100	2	0.00	0.002	0.020
1.00	64	256	1	0.0100	0.0100	3	0.00	0.002	0.040
1.00	64	256	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	64	256	1	0.0100	0.0001	3	0.00	0.002	0.002
1.00	64	256	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	64	256 256	1	0.0001	1.0000 0.0100	3	0.00	0.002	0.072
1.00	64	256	1	0.0001	0.0100	3	0.00	0.001	0.001
1.00	64	256	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	64	256	1	0.0001	0.0001	3	0.00	0.002	0.002
1.00	64	256	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	256	4	1.0000	1.0000	3	0.00	0.002	0.008
1.00	64	256 256	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	256	4	1.0000	0.0001	2	0.00	0.002	0.049
1.00	64	256	4	1.0000	0.0001	3	0.00	0.002	0.014
1.00	64	256	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	256	4	0.0100	1.0000	3	0.00	0.002	0.013
1.00	64	256	4	0.0100	0.0100	2	0.17	0.001	0.004
1.00	64	256 256	4	0.0100	0.0100	3	0.17	0.002	0.013
1.00	64	256	4	0.0100	0.0001	3	0.33	0.001	0.022
1.00	64	256	4	0.0001	1.0000	2	0.33	0.001	0.004
1.00	64	256	4	0.0001	1.0000	3	0.33	0.002	0.020
1.00	64	256	4	0.0001	0.0100	2	1.00	0.003	0.004
1.00	64	256 256	4	0.0001	0.0100	3	1.00 0.83	0.003	0.004
1.00	64	256	4	0.0001	0.0001	3	1.00	0.001	0.004
1.00	64	256	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	64	256	16	1.0000	1.0000	3	0.00	0.002	0.009
1.00	64	256	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	256	16	1.0000	0.0100	3	0.00	0.002	0.016
1.00	64	256 256	16 16	1.0000	0.0001	3	0.00	0.001	0.001
1.00	64	256	16	0.0100	1.0000	2	0.00	0.002	0.021
1.00	64	256	16	0.0100	1.0000	3	0.00	0.002	0.009
1.00	64	256	16	0.0100	0.0100	2	0.17	0.001	0.005
1.00	64	256	16	0.0100	0.0100	3	0.67	0.004	0.024
1.00	64	256 256	16 16	0.0100	0.0001	2	0.67	0.001	0.007
1.00	64	256	16	0.0100	1.0000	2	0.00	0.002	0.007
1.00	64	256	16	0.0001	1.0000	3	0.17	0.002	0.006
1.00	64	256	16	0.0001	0.0100	2	0.83	0.001	0.007
1.00	64	256	16	0.0001	0.0100	3	1.00	0.006	0.007
1.00	64 64	256 256	16 16	0.0001	0.0001	3	0.83 1.00	0.001 0.005	0.007
1.00	64	256	64	1.0000	1.00001	2	0.00	0.003	0.007
1.00	64	256	64	1.0000	1.0000	3	0.00	0.002	0.036
1.00	64	256	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	256	64	1.0000	0.0100	3	0.00	0.002	0.015
1.00	64	256	64	1.0000	0.0001	2	0.17	0.001	0.014
1.00	64	256 256	64	1.0000 0.0100	0.0001 1.0000	3	0.83	0.002	0.016
1.00	64	256	64	0.0100	1.0000	3	0.00	0.001	0.001
1.00	64	256	64	0.0100	0.0100	2	0.83	0.001	0.015
1.00	64	256	64	0.0100	0.0100	3	0.83	0.002	0.016
1.00	64	256	64	0.0100	0.0001	2	0.83	0.001	0.018
1.00	64	256	64	0.0100	0.0001	3	1.00	0.012	0.019

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	64	256	64	0.0001	1.0000	2	0.17	0.001	0.012
1.00	64	256	64	0.0001	1.0000	3	0.17	0.002	0.074
1.00	64	256	64	0.0001	0.0100	2	1.00	0.012	0.014
1.00	64	256 256	64	0.0001	0.0100	3	1.00	0.012	0.014
1.00	64	256	64	0.0001	0.0001	3	1.00	0.013	0.016
1.00	64	256	256	1.0000	1.0000	2	0.00	0.014	0.001
1.00	64	256	256	1.0000	1.0000	3	0.00	0.002	0.246
1.00	64	256	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	64	256	256	1.0000	0.0100	3	0.00	0.002	0.254
1.00	64	256	256	1.0000	0.0001	2	0.67	0.001	0.054
1.00	64	256	256	1.0000	0.0001	3	0.67	0.002	0.461
1.00	64	256 256	256 256	0.0100	1.0000	2	0.00	0.001	0.001
1.00	64	256	256	0.0100	1.0000 0.0100	3	0.00	0.002	0.349
1.00	64	256	256	0.0100	0.0100	3	1.00	0.049	0.080
1.00	64	256	256	0.0100	0.0001	2	1.00	0.058	0.093
1.00	64	256	256	0.0100	0.0001	3	1.00	0.058	0.094
1.00	64	256	256	0.0001	1.0000	2	0.00	0.001	0.001
1.00	64	256	256	0.0001	1.0000	3	0.00	0.002	1.896
1.00	64	256	256	0.0001	0.0100	2	1.00	0.076	0.101
1.00	64	256	256	0.0001	0.0100	2	1.00	0.093	0.102
1.00	64	256 256	256 256	0.0001	0.0001	3	1.00	0.084	0.128 0.128
1.00	256	230	230	1.0000	1.0000	2	0.00	0.082	0.128
1.00	256	1	1	1.0000	1.0000	3	0.00	0.002	0.001
1.00	256	1	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	1	1	1.0000	0.0100	3	0.00	0.002	0.006
1.00	256	1	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256	1	1	1.0000	0.0001	3	0.00	0.002	0.004
1.00	256 256	1	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	1	1	0.0100	1.0000 0.0100	2	0.00	0.002	0.005
1.00	256	1	1	0.0100	0.0100	3	0.00	0.001	0.007
1.00	256	1	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	256	1	1	0.0100	0.0001	3	0.00	0.002	0.031
1.00	256	1	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	256	1	1	0.0001	1.0000	3	0.00	0.002	0.039
1.00	256	1	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	256	1	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00	256 256	1	1	0.0001	0.0001	3	0.00	0.001	0.001
1.00	256	1	4	1.0000	1.0000	2	0.00	0.002	0.023
1.00	256	1	4	1.0000	1.0000	3	0.00	0.002	0.006
1.00	256	1	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	1	4	1.0000	0.0100	3	0.00	0.002	0.018
1.00	256	1	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256	1	4	1.0000	0.0001	3	0.00	0.002	0.015
1.00	256 256	1	4	0.0100	1.0000	3	0.00	0.001	0.001
1.00	256	1	4	0.0100	0.0100	2	0.00	0.002	0.008
1.00	256	1	4	0.0100	0.0100	3	0.33	0.001	0.010
1.00	256	1	4	0.0100	0.0001	2	0.17	0.001	0.003
1.00	256	1	4	0.0100	0.0001	3	0.17	0.002	0.011
1.00	256	1	4	0.0001	1.0000	2	0.00	0.001	0.001
1.00	256	1	4	0.0001	1.0000	3	0.17	0.002	0.053
1.00	256 256	1	4	0.0001	0.0100	3	0.83	0.001	0.004
1.00	256	1	4	0.0001	0.0001	2	0.83	0.002	0.003
1.00	256	1	4	0.0001	0.0001	3	0.67	0.001	0.004
1.00	256	1	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	1	16	1.0000	1.0000	3	0.00	0.002	0.020
1.00	256	1	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	1	16	1.0000	0.0100	3	0.00	0.002	0.035
1.00	256	1	16	1.0000	0.0001	2	0.17	0.001	0.007
1.00	256 256	1	16 16	1.0000 0.0100	0.0001 1.0000	3	0.33	0.005	0.137 0.001
1.00	256	1	16	0.0100	1.0000	3	0.00	0.001	0.001
1.00	256	1	16	0.0100	0.0100	2	0.83	0.002	0.005
1.00	256	1	16	0.0100	0.0100	3	1.00	0.004	0.005
1.00	256	1	16	0.0100	0.0001	2	0.50	0.001	0.005
1.00	256	1	16	0.0100	0.0001	3	0.83	0.005	0.009
1.00	256	1	16	0.0001	1.0000	2	0.50	0.001	0.006
1.00	256 256	1	16 16	0.0001	1.0000 0.0100	3	0.50 1.00	0.002	0.017
1.00	256	1	16	0.0001	0.0100	3	1.00	0.006	0.007
1.00	230	1	10	0.0001	0.0100		1.00	0.000	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	256	1	16	0.0001	0.0001	2	1.00	0.005	0.008
1.00	256	1	16	0.0001	0.0001	3	1.00	0.005	0.008
1.00	256	1	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	1	64	1.0000	1.0000	3	0.00	0.002	0.832
1.00	256	1	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	1	64	1.0000	0.0100	3	0.00	0.002	0.068
1.00	256	1	64	1.0000	0.0001	2	0.33	0.001	0.017
1.00	256	1	64	1.0000	0.0001	3	0.67	0.002	0.025
1.00	256	1	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256 256	1	64	0.0100	1.0000 0.0100	3	1.00	0.002	0.002
1.00	256	1	64	0.0100	0.0100	3	1.00	0.011	0.012
1.00	256	1	64	0.0100	0.0001	2	1.00	0.010	0.013
1.00	256	1	64	0.0100	0.0001	3	1.00	0.012	0.014
1.00	256	1	64	0.0001	1.0000	2	0.33	0.001	0.016
1.00	256	1	64	0.0001	1.0000	3	0.33	0.002	0.025
1.00	256	1	64	0.0001	0.0100	2	1.00	0.011	0.014
1.00	256	1	64	0.0001	0.0100	3	1.00	0.012	0.014
1.00	256	1	64	0.0001	0.0001	2	1.00	0.013	0.016
1.00	256	1	64	0.0001	0.0001	3	1.00	0.014	0.020
1.00	256	1	256	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	1	256	1.0000	1.0000	3	0.00	0.072	0.156
1.00	256	1	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	1	256	1.0000	0.0100	3	0.00	0.002	0.202
1.00	256	1	256	1.0000	0.0001	2	0.17	0.001	0.051
1.00	256	1	256	1.0000	0.0001	3	0.83	0.002	0.111
1.00	256	1	256	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	1	256	0.0100	1.0000	3	0.00	0.078	0.239
1.00	256 256	1	256 256	0.0100	0.0100	3	0.83 1.00	0.001	0.082
1.00	256	1	256	0.0100	0.0100	2	1.00	0.052	0.120
1.00	256	1	256	0.0100	0.0001	3	1.00	0.060	0.098
1.00	256	1	256	0.0100	1.0000	2	0.00	0.000	0.001
1.00	256	1	256	0.0001	1.0000	3	0.00	0.064	0.393
1.00	256	1	256	0.0001	0.0100	2	1.00	0.066	0.107
1.00	256	1	256	0.0001	0.0100	3	1.00	0.066	0.100
1.00	256	1	256	0.0001	0.0001	2	1.00	0.076	0.106
1.00	256	1	256	0.0001	0.0001	3	1.00	0.076	0.122
1.00	256	4	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	4	1	1.0000	1.0000	3	0.00	0.002	0.020
1.00	256	4	1	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	4	1	1.0000	0.0100	3	0.00	0.002	0.003
1.00	256	4	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256	4	1	1.0000	0.0001	3	0.00	0.002	0.002
1.00	256	4	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	4	1	0.0100	1.0000	3	0.00	0.002	0.007
1.00	256	4	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	256 256	4	1	0.0100	0.0100	3	0.00	0.002	0.039
1.00	256	4	1	0.0100	0.0001	3	0.00	0.001	0.001
1.00	256	4	1	0.0100	1.00001	2	0.00	0.002	0.538
1.00	256	4	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	256	4	1	0.0001	0.0100	2	0.00	0.002	0.003
1.00	256	4	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00	256	4	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	256	4	1	0.0001	0.0001	3	0.00	0.002	0.002
1.00	256	4	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	4	4	1.0000	1.0000	3	0.00	0.002	0.026
1.00	256	4	4	1.0000	0.0100	2	0.00	0.001	0.001
	256	4	4	1.0000	0.0100	3	0.00	0.002	0.044
1.00	256								
1.00	256	4	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00 1.00 1.00	256 256	4	4	1.0000	0.0001	3	0.00	0.002	0.021
1.00 1.00 1.00 1.00	256 256 256	4 4 4	4 4 4	1.0000 0.0100	0.0001 1.0000	3 2	0.00	0.002 0.001	0.021 0.001
1.00 1.00 1.00 1.00 1.00	256 256 256 256	4 4 4 4	4 4 4 4	1.0000 0.0100 0.0100	0.0001 1.0000 1.0000	3 2 3	0.00 0.00 0.00	0.002 0.001 0.002	0.021 0.001 0.026
1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256	4 4 4 4 4	4 4 4 4 4	1.0000 0.0100 0.0100 0.0100	0.0001 1.0000 1.0000 0.0100	3 2 3 2	0.00 0.00 0.00 0.00	0.002 0.001 0.002 0.001	0.021 0.001 0.026 0.001
1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256	4 4 4 4 4	4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100	0.0001 1.0000 1.0000 0.0100 0.0100	3 2 3 2 3	0.00 0.00 0.00 0.00 0.67	0.002 0.001 0.002 0.001 0.003	0.021 0.001 0.026 0.001 0.013
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256	4 4 4 4 4 4 4	4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100	0.0001 1.0000 1.0000 0.0100 0.0100 0.0001	3 2 3 2 3 2	0.00 0.00 0.00 0.00 0.67 0.50	0.002 0.001 0.002 0.001 0.003 0.001	0.021 0.001 0.026 0.001 0.013 0.004
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256 256	4 4 4 4 4 4 4	4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100 0.0100	0.0001 1.0000 1.0000 0.0100 0.0100 0.0001	3 2 3 2 3 2 3	0.00 0.00 0.00 0.00 0.67 0.50 0.67	0.002 0.001 0.002 0.001 0.003 0.001 0.002	0.021 0.001 0.026 0.001 0.013 0.004 0.047
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256 256 256	4 4 4 4 4 4 4 4	4 4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100 0.0100 0.0001	0.0001 1.0000 1.0000 0.0100 0.0100 0.0001 1.0000	3 2 3 2 3 2 3 2	0.00 0.00 0.00 0.00 0.67 0.50 0.67	0.002 0.001 0.002 0.001 0.003 0.001 0.002 0.001	0.021 0.001 0.026 0.001 0.013 0.004 0.047
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256 256 256	4 4 4 4 4 4 4 4 4	4 4 4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100 0.0100 0.0001	0.0001 1.0000 1.0000 0.0100 0.0100 0.0001 0.0001 1.0000	3 2 3 2 3 2 3 2 3 2	0.00 0.00 0.00 0.00 0.67 0.50 0.67 0.17	0.002 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.003	0.021 0.001 0.026 0.001 0.013 0.004 0.047 0.004 0.008
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256 256 256	4 4 4 4 4 4 4 4	4 4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100 0.0100 0.0001 0.0001	0.0001 1.0000 1.0000 0.0100 0.0100 0.0001 1.0000 1.0000 0.0100	3 2 3 2 3 2 3 2 3 2 3 2	0.00 0.00 0.00 0.00 0.67 0.50 0.67 0.17 0.17	0.002 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.003	0.021 0.001 0.026 0.001 0.013 0.004 0.047 0.004 0.008 0.004
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256 256 256	4 4 4 4 4 4 4 4 4 4	4 4 4 4 4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100 0.0100 0.0001 0.0001 0.0001	0.0001 1.0000 0.0100 0.0100 0.0001 0.0001 1.0000 1.0000 0.0100	3 2 3 2 3 2 3 2 3 2	0.00 0.00 0.00 0.00 0.67 0.50 0.67 0.17 0.67 0.67	0.002 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.003 0.001 0.003	0.021 0.001 0.026 0.001 0.013 0.004 0.047 0.004 0.008 0.004 0.014
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256 256 256	4 4 4 4 4 4 4 4 4 4 4 4 4	4 4 4 4 4 4 4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100 0.0100 0.0001 0.0001	0.0001 1.0000 1.0000 0.0100 0.0100 0.0001 1.0000 1.0000 0.0100	3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 3 2 3 3 2 3	0.00 0.00 0.00 0.00 0.67 0.50 0.67 0.17 0.17	0.002 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.003	0.021 0.001 0.026 0.001 0.013 0.004 0.047 0.004 0.008 0.004
1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	256 256 256 256 256 256 256 256 256 256	4 4 4 4 4 4 4 4 4 4 4 4 4 4	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1.0000 0.0100 0.0100 0.0100 0.0100 0.0100 0.0100 0.0001 0.0001 0.0001 0.0001	0.0001 1.0000 0.0100 0.0100 0.0001 0.0001 1.0000 1.0000 0.0100 0.0100 0.0001	3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 2 3 2 3 2 2 3 2 2 3 2 2 3 2 2 3 2 2 3 2 2 3 2 3 2 2 3 2 2 3 2 3 2 3 2 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 2 3 2 2 3 2 3 2 3 2 3 2 2 3 2 2 3 2 2 2 3 2 3 2 3 2 2 3 2 3 2 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 2 3 2 3 2 2 2 2 2 3 2 2 2 2 2 3 2	0.00 0.00 0.00 0.00 0.67 0.50 0.67 0.17 0.67 0.67 0.50	0.002 0.001 0.002 0.001 0.003 0.001 0.002 0.001 0.003 0.001 0.002 0.001	0.021 0.001 0.026 0.001 0.013 0.004 0.047 0.004 0.008 0.004 0.014 0.004

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	256	4	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	4	16	1.0000	0.0100	3	0.00	0.002	0.026
1.00	256	4	16	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256 256	4	16 16	1.0000 0.0100	1.0000	3	0.50	0.002	0.022
1.00	256	4	16	0.0100	1.0000	3	0.00	0.001	0.001
1.00	256	4	16	0.0100	0.0100	2	0.50	0.002	0.006
1.00	256	4	16	0.0100	0.0100	3	0.83	0.002	0.009
1.00	256	4	16	0.0100	0.0001	2	0.50	0.001	0.007
1.00	256	4	16	0.0100	0.0001	3	0.67	0.002	0.007
1.00	256	4	16	0.0001	1.0000	2	0.33	0.001	0.006
1.00	256	4	16	0.0001	1.0000	3	0.33	0.002	0.006
1.00	256	4	16	0.0001	0.0100	2	1.00	0.006	0.007
1.00	256 256	4	16	0.0001	0.0100	3	1.00	0.006	0.006
1.00	256	4	16 16	0.0001	0.0001	3	1.00	0.007	0.007
1.00	256	4	64	1.0000	1.0000	2	0.00	0.007	0.007
1.00	256	4	64	1.0000	1.0000	3	0.00	0.002	0.019
1.00	256	4	64	1.0000	0.0100	2	0.00	0.001	0.006
1.00	256	4	64	1.0000	0.0100	3	0.00	0.002	0.085
1.00	256	4	64	1.0000	0.0001	2	0.50	0.001	0.016
1.00	256	4	64	1.0000	0.0001	3	0.83	0.014	0.031
1.00	256	4	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	4	64	0.0100	1.0000	3	0.00	0.002	0.025
1.00	256 256	4	64 64	0.0100	0.0100	3	0.83 1.00	0.001	0.016 0.016
1.00	256	4	64	0.0100	0.0100	2	1.00	0.010	0.016
1.00	256	4	64	0.0100	0.0001	3	1.00	0.018	0.019
1.00	256	4	64	0.0001	1.0000	2	0.17	0.001	0.015
1.00	256	4	64	0.0001	1.0000	3	0.17	0.002	0.034
1.00	256	4	64	0.0001	0.0100	2	1.00	0.017	0.019
1.00	256	4	64	0.0001	0.0100	3	1.00	0.017	0.019
1.00	256	4	64	0.0001	0.0001	2	1.00	0.015	0.022
1.00	256	4	64	0.0001	0.0001	3	1.00	0.014	0.021
1.00	256 256	4	256 256	1.0000	1.0000	3	0.00	0.001	0.001
1.00	256	4	256	1.0000	0.0100	2	0.00	0.003	0.188
1.00	256	4	256	1.0000	0.0100	3	0.00	0.001	0.145
1.00	256	4	256	1.0000	0.0001	2	0.33	0.001	0.079
1.00	256	4	256	1.0000	0.0001	3	0.67	0.002	0.082
1.00	256	4	256	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	4	256	0.0100	1.0000	3	0.00	0.002	0.680
1.00	256	4	256	0.0100	0.0100	2	0.83	0.001	0.077
1.00	256	4	256	0.0100	0.0100	3	0.83	0.002	0.080
1.00	256	4	256	0.0100	0.0001	2	1.00	0.058	0.063
1.00	256 256	4	256 256	0.0100	1.0000	3	1.00 0.00	0.059	0.063
1.00	256	4	256	0.0001	1.0000	3	0.00	0.220	0.023
1.00	256	4	256	0.0001	0.0100	2	1.00	0.062	0.068
1.00	256	4	256	0.0001	0.0100	3	1.00	0.062	0.064
1.00	256	4	256	0.0001	0.0001	2	1.00	0.078	0.094
1.00	256	4	256	0.0001	0.0001	3	1.00	0.081	0.105
1.00	256	16	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	16	1	1.0000	1.0000	3	0.00	0.002	0.020
1.00	256 256	16 16	1	1.0000	0.0100	3	0.00	0.001	0.001
1.00	256	16	1	1.0000	0.0100	2	0.00	0.002	0.003
1.00	256	16	1	1.0000	0.0001	3	0.00	0.001	0.001
1.00	256	16	1	0.0100	1.0000	2	0.00	0.001	0.003
1.00	256	16	1	0.0100	1.0000	3	0.00	0.002	0.029
1.00	256	16	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	256	16	1	0.0100	0.0100	3	0.00	0.002	0.011
1.00	256	16	1	0.0100	0.0001	2	0.00	0.001	0.009
1.00	256	16	1	0.0100	0.0001	3	0.00	0.002	0.003
1.00	256	16	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	256 256	16 16	1	0.0001	1.0000 0.0100	3	0.00	0.002 0.001	0.032
1.00	256	16	1	0.0001	0.0100	3	0.00	0.001	0.001
1.00	256	16	1	0.0001	0.0100	2	0.00	0.002	0.037
1.00	256	16	1	0.0001	0.0001	3	0.00	0.001	0.001
1.00	256	16	4	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	16	4	1.0000	1.0000	3	0.00	0.002	0.011
1.00	256	16	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	16	4	1.0000	0.0100	3	0.00	0.002	0.023
1.00	256	16	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256	16	4	1.0000	0.0001	3	0.00	0.002	0.007

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	256	16	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	16	4	0.0100	1.0000	3	0.00	0.002	0.011
1.00	256	16	4	0.0100	0.0100	2	0.17	0.001	0.003
1.00	256	16	4	0.0100	0.0100	3	0.50	0.002	0.003
1.00	256	16	4	0.0100	0.0001	2	0.33	0.001	0.004
1.00	256 256	16 16	4	0.0100	0.0001 1.0000	3	0.50 0.17	0.002	0.016 0.004
1.00	256	16	4	0.0001	1.0000	3	0.17	0.001	0.004
1.00	256	16	4	0.0001	0.0100	2	0.67	0.001	0.003
1.00	256	16	4	0.0001	0.0100	3	0.67	0.002	0.008
1.00	256	16	4	0.0001	0.0001	2	0.67	0.001	0.004
1.00	256	16	4	0.0001	0.0001	3	0.83	0.003	0.017
1.00	256	16	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	16	16	1.0000	1.0000	3	0.00	0.002	0.015
1.00	256 256	16 16	16 16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	16	16	1.0000	0.0100	2	0.00	0.002	0.006
1.00	256	16	16	1.0000	0.0001	3	0.33	0.002	0.024
1.00	256	16	16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	16	16	0.0100	1.0000	3	0.00	0.002	0.016
1.00	256	16	16	0.0100	0.0100	2	0.33	0.001	0.005
1.00	256	16	16	0.0100	0.0100	3	0.83	0.002	0.006
1.00	256 256	16	16	0.0100	0.0001	3	0.83	0.001	0.006
1.00	256	16 16	16 16	0.0100	1.0000	2	0.83	0.005	0.019
1.00	256	16	16	0.0001	1.0000	3	0.83	0.001	0.004
1.00	256	16	16	0.0001	0.0100	2	1.00	0.004	0.006
1.00	256	16	16	0.0001	0.0100	3	1.00	0.004	0.005
1.00	256	16	16	0.0001	0.0001	2	1.00	0.005	0.007
1.00	256	16	16	0.0001	0.0001	3	1.00	0.005	0.007
1.00	256 256	16 16	64 64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	16	64	1.0000	0.0100	2	0.00	0.002	0.018
1.00	256	16	64	1.0000	0.0100	3	0.00	0.001	0.084
1.00	256	16	64	1.0000	0.0001	2	0.50	0.001	0.016
1.00	256	16	64	1.0000	0.0001	3	1.00	0.015	0.031
1.00	256	16	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256 256	16 16	64 64	0.0100	1.0000 0.0100	3	0.00	0.002	0.023
1.00	256	16	64	0.0100	0.0100	3	0.83	0.001	0.012
1.00	256	16	64	0.0100	0.0001	2	1.00	0.017	0.019
1.00	256	16	64	0.0100	0.0001	3	1.00	0.017	0.018
1.00	256	16	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00	256	16	64	0.0001	1.0000	3	0.00	0.002	0.091
1.00	256 256	16 16	64	0.0001	0.0100	3	1.00	0.018	0.023
1.00	256	16	64	0.0001	0.0100	2	1.00	0.018	0.020
1.00	256	16	64	0.0001	0.0001	3	1.00	0.014	0.020
1.00	256	16	256	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	16	256	1.0000	1.0000	3	0.00	0.002	0.162
1.00	256	16	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	16	256	1.0000	0.0100	3	0.00	0.002	0.157
1.00	256	16 16	256	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256 256	16	256 256	0.0100	1.00001	2	0.17	0.002	0.331
1.00	256	16	256	0.0100	1.0000	3	0.00	0.138	0.369
1.00	256	16	256	0.0100	0.0100	2	0.67	0.001	0.081
1.00	256	16	256	0.0100	0.0100	3	1.00	0.075	0.081
1.00	256	16	256	0.0100	0.0001	2	1.00	0.059	0.098
1.00	256	16	256	0.0100	0.0001	3	1.00	0.060	0.097
1.00	256 256	16 16	256 256	0.0001	1.0000	3	0.00	0.001	0.001
1.00	256	16	256	0.0001	0.0100	2	1.00	0.002	0.009
1.00	256	16	256	0.0001	0.0100	3	1.00	0.100	0.102
1.00	256	16	256	0.0001	0.0001	2	1.00	0.078	0.112
1.00	256	16	256	0.0001	0.0001	3	1.00	0.076	0.120
1.00	256	64	1	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256 256	64 64	1	1.0000	1.0000 0.0100	3 2	0.00	0.002 0.001	0.618
1.00	256	64	1	1.0000	0.0100	3	0.00	0.001	0.001
1.00	256	64	1	1.0000	0.0001	2	0.00	0.001	0.002
1.00	256	64	1	1.0000	0.0001	3	0.00	0.002	0.003
1.00	256	64	1	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	64	1	0.0100	1.0000	3	0.00	0.002	0.030
1.00	256 256	64 64	1	0.0100	0.0100	2	0.00	0.001	0.001
1.00	230	υ4	1	0.0100	0.0100	3	0.00	0.002	0.037

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	256	64	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	256	64	1	0.0100	0.0001	3	0.00	0.002	0.003
1.00	256	64	1	0.0001	1.0000	2	0.00	0.001	0.001
1.00	256	64	1	0.0001	1.0000	3	0.00	0.002	0.006
1.00	256	64	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	256	64	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00	256	64	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	256 256	64	1 4	0.0001 1.0000	0.0001 1.0000	3	0.00	0.002	0.002
1.00	256	64	4	1.0000	1.0000	3	0.00	0.001	0.001
1.00	256	64	4	1.0000	0.0100	2	0.00	0.002	0.001
1.00	256	64	4	1.0000	0.0100	3	0.00	0.002	0.038
1.00	256	64	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256	64	4	1.0000	0.0001	3	0.00	0.002	0.008
1.00	256	64	4	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	64	4	0.0100	1.0000	3	0.00	0.002	0.039
1.00	256	64	4	0.0100	0.0100	2	0.17	0.001	0.004
1.00	256 256	64	4	0.0100	0.0100	3	0.67	0.004	0.013
1.00	256	64	4	0.0100	0.0001	3	0.33	0.001	0.004
1.00	256	64	4	0.0001	1.0000	2	0.33	0.002	0.003
1.00	256	64	4	0.0001	1.0000	3	0.33	0.002	0.007
1.00	256	64	4	0.0001	0.0100	2	0.83	0.001	0.004
1.00	256	64	4	0.0001	0.0100	3	0.83	0.002	0.004
1.00	256	64	4	0.0001	0.0001	2	0.83	0.001	0.004
1.00	256	64	4	0.0001	0.0001	3	0.83	0.003	0.016
1.00	256	64	16	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	64	16	1.0000	1.0000	3	0.00	0.002	0.003
1.00	256 256	64	16 16	1.0000	0.0100	3	0.00	0.001	0.001
1.00	256	64	16	1.0000	0.0100	2	0.00	0.002	0.026
1.00	256	64	16	1.0000	0.0001	3	0.33	0.001	0.019
1.00	256	64	16	0.0100	1.0000	2	0.00	0.002	0.001
1.00	256	64	16	0.0100	1.0000	3	0.00	0.002	0.021
1.00	256	64	16	0.0100	0.0100	2	0.33	0.001	0.006
1.00	256	64	16	0.0100	0.0100	3	0.83	0.002	0.014
1.00	256	64	16	0.0100	0.0001	2	0.67	0.001	0.007
1.00	256	64	16	0.0100	0.0001	3	0.83	0.006	0.030
1.00	256	64	16	0.0001	1.0000	3	0.17	0.001	0.006
1.00	256 256	64 64	16 16	0.0001	1.0000 0.0100	2	0.50 1.00	0.002	0.006
1.00	256	64	16	0.0001	0.0100	3	1.00	0.005	0.006
1.00	256	64	16	0.0001	0.0001	2	1.00	0.005	0.007
1.00	256	64	16	0.0001	0.0001	3	1.00	0.005	0.007
1.00	256	64	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	64	64	1.0000	1.0000	3	0.00	0.002	0.027
1.00	256	64	64	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	64	64	1.0000	0.0100	3	0.00	0.002	0.124
1.00	256	64	64	1.0000	0.0001	2	0.33	0.001	0.013
1.00	256 256	64 64	64 64	1.0000 0.0100	0.0001 1.0000	3	0.50	0.002	0.024 0.001
1.00	256	64	64	0.0100	1.0000	3	0.00	0.001	0.001
1.00	256	64	64	0.0100	0.0100	2	0.83	0.002	0.043
1.00	256	64	64	0.0100	0.0100	3	1.00	0.010	0.011
1.00	256	64	64	0.0100	0.0001	2	1.00	0.011	0.013
1.00	256	64	64	0.0100	0.0001	3	1.00	0.012	0.013
1.00	256	64	64	0.0001	1.0000	2	0.00	0.001	0.001
1.00	256	64	64	0.0001	1.0000	3	0.00	0.002	0.079
1.00	256	64	64	0.0001	0.0100	2	1.00	0.012	0.013
1.00	256	64	64	0.0001	0.0100	3	1.00	0.012	0.015
1.00	256 256	64	64 64	0.0001	0.0001	3	1.00	0.013	0.021
1.00	256	64	256	1.0000	1.0000	2	0.00	0.013	0.021
1.00	256	64	256	1.0000	1.0000	3	0.00	0.002	0.147
1.00	256	64	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	64	256	1.0000	0.0100	3	0.00	0.002	0.105
1.00	256	64	256	1.0000	0.0001	2	0.33	0.001	0.080
1.00	256	64	256	1.0000	0.0001	3	0.83	0.053	0.116
1.00	256	64	256	0.0100	1.0000	2	0.00	0.001	0.017
1.00	256	64	256	0.0100	1.0000	3	0.00	0.002	0.299
1.00	256	64	256	0.0100	0.0100	3	0.17	0.001	0.054
1.00	256 256	64 64	256 256	0.0100	0.0100	2	0.83 1.00	0.002	0.056 0.080
1.00	256	64	256	0.0100	0.0001	3	1.00	0.059	0.080
1.00	256	64	256	0.0001	1.0000	2	0.00	0.000	0.001
1.00	256	64	256	0.0001	1.0000	3	0.00	0.002	0.374
	2. 0					-			

mul	m_1	m_2	$ \tau $	TR	DTR	alg	SR	mint	maxt
1.00	256	64	256	0.0001	0.0100	2	1.00	0.064	0.102
1.00	256	64	256	0.0001	0.0100	3	1.00	0.064	0.102
1.00	256	64	256	0.0001	0.0001	2	1.00	0.077	0.127
1.00	256	64	256	0.0001	0.0001	3	1.00	0.077	0.119
1.00	256 256	256 256	1	1.0000	1.0000	3	0.00	0.001	0.001
1.00	256	256	1	1.0000	0.0100	2	0.00	0.002	0.022
1.00	256	256	1	1.0000	0.0100	3	0.00	0.002	0.003
1.00	256	256	1	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256	256	1	1.0000	0.0001	3	0.00	0.002	0.003
1.00	256 256	256 256	1	0.0100	1.0000	3	0.00	0.001	0.001
1.00	256	256	1	0.0100	0.0100	2	0.00	0.002	0.001
1.00	256	256	1	0.0100	0.0100	3	0.00	0.002	0.018
1.00	256	256	1	0.0100	0.0001	2	0.00	0.001	0.001
1.00	256	256	1	0.0100	0.0001	3	0.00	0.002	0.002
1.00	256 256	256 256	1	0.0001	1.0000	3	0.00	0.001	0.001
1.00	256	256	1	0.0001	0.0100	2	0.00	0.001	0.001
1.00	256	256	1	0.0001	0.0100	3	0.00	0.002	0.002
1.00	256	256	1	0.0001	0.0001	2	0.00	0.001	0.001
1.00	256	256 256	1 4	0.0001 1.0000	0.0001 1.0000	3	0.00	0.002	0.002
1.00	256 256	256	4	1.0000	1.0000	3	0.00	0.001	0.001
1.00	256	256	4	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	256	4	1.0000	0.0100	3	0.00	0.002	0.007
1.00	256	256	4	1.0000	0.0001	2	0.00	0.001	0.001
1.00	256 256	256 256	4	1.0000 0.0100	0.0001 1.0000	3	0.00	0.002	0.028
1.00	256	256	4	0.0100	1.0000	3	0.33	0.001	0.004
1.00	256	256	4	0.0100	0.0100	2	0.50	0.001	0.004
1.00	256	256	4	0.0100	0.0100	3	0.83	0.003	0.009
1.00	256	256	4	0.0100	0.0001	2	0.17	0.001	0.003
1.00	256 256	256 256	4	0.0100	0.0001 1.0000	3	0.50 0.17	0.002	0.011
1.00	256	256	4	0.0001	1.0000	3	0.50	0.002	0.004
1.00	256	256	4	0.0001	0.0100	2	0.50	0.001	0.004
1.00	256	256	4	0.0001	0.0100	3	0.67	0.002	0.004
1.00	256 256	256 256	4	0.0001	0.0001	3	0.67	0.001	0.003
1.00	256	256	16	1.0000	1.0000	2	0.00	0.002	0.004
1.00	256	256	16	1.0000	1.0000	3	0.00	0.002	0.011
1.00	256	256	16	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	256	16	1.0000	0.0100	3	0.00	0.002	0.004
1.00	256 256	256 256	16 16	1.0000	0.0001	3	0.00	0.001	0.001
1.00	256	256	16	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	256	16	0.0100	1.0000	3	0.17	0.002	0.168
1.00	256	256	16	0.0100	0.0100	2	0.50	0.001	0.006
1.00	256 256	256 256	16 16	0.0100	0.0100	3	0.83	0.002	0.006
1.00	256	256	16	0.0100	0.0001	3	0.83	0.001	0.006
1.00	256	256	16	0.0001	1.0000	2	0.50	0.001	0.005
1.00	256	256	16	0.0001	1.0000	3	0.50	0.002	0.011
1.00	256 256	256 256	16 16	0.0001	0.0100	3	1.00	0.004	0.006
1.00	256	256	16	0.0001	0.0100	2	1.00	0.005	0.005
1.00	256	256	16	0.0001	0.0001	3	1.00	0.005	0.006
1.00	256	256	64	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	256	64	1.0000	1.0000	3	0.00	0.002	0.002
1.00	256 256	256 256	64	1.0000	0.0100	3	0.00	0.001	0.001
1.00	256	256	64	1.0000	0.0100	2	0.00	0.002	0.013
1.00	256	256	64	1.0000	0.0001	3	0.67	0.002	0.034
1.00	256	256	64	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256 256	256 256	64 64	0.0100	1.0000 0.0100	2	0.00	0.002 0.001	0.002
1.00	256	256	64	0.0100	0.0100	3	1.00	0.001	0.012
1.00	256	256	64	0.0100	0.0001	2	1.00	0.012	0.014
1.00	256	256	64	0.0100	0.0001	3	1.00	0.012	0.014
1.00	256	256	64	0.0001	1.0000	2	0.17	0.001	0.011
1.00	256 256	256 256	64 64	0.0001	1.0000 0.0100	3	0.33 1.00	0.002 0.012	0.048
1.00	256	256	64	0.0001	0.0100	3	1.00	0.012	0.016
1.00	256	256	64	0.0001	0.0001	2	1.00	0.014	0.023
1.00	256	256	64	0.0001	0.0001	3	1.00	0.016	0.023

mul	m_1	m_2	au	TR	DTR	alg	SR	mint	maxt
1.00	256	256	256	1.0000	1.0000	2	0.00	0.001	0.001
1.00	256	256	256	1.0000	1.0000	3	0.00	0.002	0.040
1.00	256	256	256	1.0000	0.0100	2	0.00	0.001	0.001
1.00	256	256	256	1.0000	0.0100	3	0.00	0.002	0.003
1.00	256	256	256	1.0000	0.0001	2	0.17	0.001	0.059
1.00	256	256	256	1.0000	0.0001	3	1.00	0.053	0.082
1.00	256	256	256	0.0100	1.0000	2	0.00	0.001	0.001
1.00	256	256	256	0.0100	1.0000	3	0.00	0.002	0.138
1.00	256	256	256	0.0100	0.0100	2	0.50	0.001	0.050
1.00	256	256	256	0.0100	0.0100	3	1.00	0.050	0.054
1.00	256	256	256	0.0100	0.0001	2	0.83	0.001	0.099
1.00	256	256	256	0.0100	0.0001	3	1.00	0.064	0.102
1.00	256	256	256	0.0001	1.0000	2	0.17	0.001	0.049
1.00	256	256	256	0.0001	1.0000	3	0.17	0.002	0.230
1.00	256	256	256	0.0001	0.0100	2	1.00	0.065	0.104
1.00	256	256	256	0.0001	0.0100	3	1.00	0.065	0.068
1.00	256	256	256	0.0001	0.0001	2	1.00	0.077	0.084
1.00	256	256	256	0.0001	0.0001	3	1.00	0.075	0.084